# A/C-HEATER SYSTEM TROUBLE SHOOTING - MANUAL

# 1990 Nissan 240SX

1990 Manual A/C-Heater Systems

240SX

NOTE: This article has been revised as specified in Technical Service Bulletin TS89-160 Dated Nov. 30,1989.

# MANUAL A/C-HEATER SYSTEM TROUBLESHOOTING

See MANUAL A/C-HEATER SYSTEM TROUBLESHOOTING CHART below and applicable figures.

#### MANUAL A/C-HEATER SYSTEM TROUBLESHOOTING CHART

Preliminary Check	Problem/Symptom	Comment
	<pre>Intake door is not set at FRESH in DEFROST or FOOT/DEFROST mode A/C Does Not Blow Cold Air</pre>	
3	Compressor (Magnet) Clutch Does Not Operate In DEFROST Mode	See Fig. 3
5	Air outlet does not change  Noise	
	For A/C System	See Fig. 6




Fig. 1: Preliminary Check 1 Courtesy of Nissan Motor Co., U.S.A.




Fig. 2: Preliminary Check 2 Courtesy of Nissan Motor Co., U.S.A.




Fig. 3: Preliminary Check 3 Courtesy of Nissan Motor Co., U.S.A.




Fig. 4: Preliminary Check 4
Courtesy of Nissan Motor Co., U.S.A.






Fig. 5: Preliminary Check 5 Courtesy of Nissan Motor Co., U.S.A.








Fig. 6: Preliminary Check 6 Courtesy of Nissan Motor Co., U.S.A.

#### PRELIMINARY CHECK 6 POWER SUPPLY CIRCUIT CHECK FOR A/C SYSTEM

Thermo Control Amplifier Check

- 1. Disconnect thermo control amplifier harness connector.
- 2. Turn ignition ON. Using voltmeter, ensure battery voltage exists at connector terminal No. 34.
- 3. Turn ignition OFF. Turn A/C and fan switch ON. Using harness connector terminal No. 13 and ground.

Push Control Unit Check

- 1. Disconnect push control unit harness connector.
- 2. Turn ignition switch to ACC position.
- 3. Using voltmeter, ensure battery voltage exists at terminal No. 14 of harness connector.
  - 4. Turn ignition switch to OFF position.
- 5. Using ohmmeter, ensure continuity exists between terminal No. 17 of harness connector and ground.

## DIAGNOSTIC PROCEDURE 1 - BLOWER MOTOR DOES NOT ROTATE

See Fig. 7 to 9.




Fig. 7: Diagnostic Procedure 1 (1 of 3) Courtesy of Nissan Motor Co., U.S.A.





Fig. 8: Diagnostic Procedure 1 (2 of 3) Courtesy of Nissan Motor Co., U.S.A.



91D04815
Fig. 9: Diagnostic Procedure 1 (3 of 3)
Courtesy of Nissan Motor Co., U.S.A.

## DIAGNOSTIC PROCEDURE 2 - AIR OUTLET DOES NOT CHANGE





Fig. 10: Diagnostic Procedure 2 (1 of 2) Courtesy of Nissan Motor Co., U.S.A.


 $\mbox{\sc Perform PRELIMINARY CHECK 4}$  and 6 before referring to the following flow chart.



Courtesy of Nissan Motor Co., U.S.A.

# DIAGNOSTIC PROCEDURE 3 - INTAKE DOOR DOES NOT CHANGE

Intake Door Does Not Change In VENT, BI-LEVEL or FOOT Mode. See Fig. 12.



90E05636
Fig. 12: Diagnostic Procedure 3
Courtesy of Nissan Motor Co., U.S.A.

 $\mbox{\sc Perform PRELIMINARY CHECK 1}$  and 6 before referring to the following flow chart.

Compressor (Magnet) clutch does not engage with A/C & Fan switch on. See Figs. 13 to 17.




Fig. 13: Diagnostic Procedure 4 (1 of 5) Courtesy of Nissan Motor Co., U.S.A.




Fig. 14: Diagnostic Procedure 4 (2 of 5) Courtesy of Nissan Motor Co., U.S.A.




Fig. 15: Diagnostic Procedure 4 (3 of 5) Courtesy of Nissan Motor Co., U.S.A.




Fig. 16: Diagnostic Procedure 4 (4 of 5) Courtesy of Nissan Motor Co., U.S.A.





Fig. 17: Diagnostic Procedure 4 (5 of 5) Courtesy of Nissan Motor Co., U.S.A.

# DIAGNOSTIC PROCEDURE 5 - PUSH CONTROL INDICATORS DO NOT

## on. See Figs. 18 to 21.



 Perform PRELIMINARY CHECK 6 before referring to the following flow chart.

Turn ignition switch and lighting switch ON.

## CHECK ILLUMINATION AND INDICATORS.


- Turn A/C, REC and fan switches ON.
- Push VENT, B/L, FOOT, F/D and DEF switches in order.
- Check for incidents and follow the repairing methods as shown:

	INCIDENTS								
ILL.	VENT	B/L	FOOT	F/D	DEF	REC	A/C	"How to repair"	
×	0	0	0	0	0	0		Go to DIAGNOSTIC PROCEDURE 5-1.	
	0	0	0	0	0	0	×	Go to DIAGNOSTIC PROCEDURE 5-2.	
0	x	×	х	x	×	×		Go to DIAGNOSTIC PROCEDURE 5-3.	
$\sum$	Δ							Replace control amp, built-in push control unit.	
0	×	×	х	х	х	×	0	Replace control amp, built-in push control nit.	
$\sum$	х	х	х	х	х	х.	0	Go to DIAGNOSTIC PROCEDURE 5-4.	

- O: Illumination or indicator comes on.
- X: Illumination or indicator does not come on.
- $\Delta$  : Some indicators for VENT, B/L, FOOT, F/D, DEF or REC come on.

Fig. 18: Diagnostic Procedure 5 (1 of 4) Courtesy of Nissan Motor Co., U.S.A.


 $\mbox{\sc Perform PRELIMINARY CHECK 6}$  before referring to the following flow chart.



NOTE: If the result is no good (NG) after checking circuit continuity, repair harness or connector.

91D04820
Fig. 19: Diagnostic Procedure 5 (2 of 4)
Courtesy of Nissan Motor Co., U.S.A.

#### **DIAGNOSTIC PROCEDURE 5**



## **DIAGNOSTIC PROCEDURE 5-2**




Fig. 20: Diagnostic Procedures 5 (3 of 4) Courtesy of Nissan Motor Co., U.S.A.




Fig. 21: Diagnostic Procedures 5 (4 of 4) Courtesy of Nissan Motor Co., U.S.A.