

**Lucent Technologies**  
Bell Labs Innovations



# **DEFINITY ONE<sup>TM</sup>**

## **Communications System**

Release 2.0  
Maintenance

555-233-111  
Comcode 108671405  
Issue 2  
June 2000

## Notice

Every effort was made to ensure that the information in this book was complete and accurate at the time of printing. However, information is subject to change.

## Preventing Toll Fraud

Toll Fraud is the unauthorized use of your telecommunications system by an unauthorized party (for example, a person who is not a corporate employee, agent, subcontractor, or working on your company's behalf). Be aware that there is a risk of toll fraud associated with your system and that, if toll fraud occurs, it can result in substantial additional charges for your telecommunications services.

## Lucent Technologies Fraud Intervention

If you *suspect that you are being victimized* by toll fraud and you need technical assistance or support, call the Technical Service Center's Toll Fraud Intervention Hotline at 1-800 643-2353.

## Providing Telecommunications Security

Telecommunications security (of voice, data, and/or video communications) is the prevention of any type of intrusion to (that is, either unauthorized or malicious access to or use of your company's telecommunications equipment) by some party.

Your company's "telecommunications equipment" includes both this Lucent product and any other voice/data/video equipment that could be accessed via this Lucent product (that is, "networked equipment").

An "outside party" is anyone who is not a corporate employee, agent, subcontractor, or working on your company's behalf. Whereas, a "malicious party" is anyone (including someone who may be otherwise authorized) who accesses your telecommunications equipment with either malicious or mischievous intent.

Such intrusions may be either to/through synchronous (time multiplexed and/or circuit-based) or asynchronous (character-, message-, or packet-based) equipment or interfaces for reasons of:

- Utilization (of capabilities special to the accessed equipment)
- Theft (such as, of intellectual property, financial assets, or toll -facility access)
- Eavesdropping (privacy invasions to humans)
- Mischief (troubling, but apparently innocuous, tampering)
- Harm such as harmful tampering, data loss or alteration, regardless of motive or intent.

Be aware that there may be a risk of unauthorized or malicious intrusions associated with your system and/or its networked equipment. Also realize that, if such an intrusion should occur, it could result in a variety of losses to your company (including but not limited to, human/data privacy, intellectual property, material assets, financial resources, labor costs, and/or legal costs).

## Your Responsibility for Your Company's Telecommunications Security

The final responsibility for securing both this system and its networked equipment rests with you - a Lucent customer's system administrator, your telecommunications peers, and your managers. Base the fulfillment of your responsibility on acquired knowledge and resources from a variety of sources including but not limited to:

- Installation documents
- System administration documents
- Security documents
- Hardware-/software-based security tools
- Shared information between you and your peers
- Telecommunications security experts

To prevent intrusions to your telecommunications equipment, you and your peers should carefully program and configure your:

- Lucent provided telecommunications system and their interfaces
- Lucent provided software applications, as well as their underlying hardware/software platforms and interfaces
- Any other equipment networked to your Lucent products

## Federal Communications Commission Statement

**Part 15: Class A Statement.** This equipment has been tested and found to comply with the limits for a Class A digital device, pursuant to Part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference when the equipment is operated in a commercial environment. This equipment generates, uses, and can radiate radio-frequency energy and, if not installed and used in accordance with the instructions, may cause harmful interference to radio communications. Operation of this equipment in a residential area is likely to cause harmful interference, in which case the user will be required to correct the interference at his own expense.

**Part 68: Network Registration Number.** This equipment is registered with the FCC in accordance with Part 68 of the FCC Rules. It is identified by FCC registration number AS593M-13283-MF-E. Refer to "Federal Communications Commission Statement" in "About This Book" for more information regarding Part 68.

## Canadian Department of Communications (DOC)

### Interference Information

This digital apparatus does not exceed the Class A limits for radio noise emissions set out in the radio interference regulations of the Canadian Department of Communications.

Le Présent Appareil Numérique n'émet pas de bruits radioélectriques dépassant les limites applicables aux appareils numériques de la class A prescrites dans le reglement sur le brouillage radioélectrique édicté par le ministère des Communications du Canada.

## Trademarks

See "About This Book."

## Ordering Information

**Call:** Lucent Technologies Publications Center  
Voice 1 800 457-1235 International Voice 317 361-5353  
Fax 1 800 457-1764 International Fax 317 361-5355

**Write:** Lucent Technologies Publications Center  
P.O. Box 4100  
Crawfordsville, IN 47933

**Order:** Document No. 555-233-111  
Comcode 108671405  
2, June 2000

For additional documents, refer to the section in "About This Book" entitled "Related Documents."

You can be placed on a standing order list for this and other documents you may need. Standing order will enable you to automatically receive updated versions of individual documents or document sets, billed to account information that you provide. For more information on standing orders, or to be put on a list to receive future issues of this document, contact the Lucent Technologies Publications Center.

## European Union Declaration of Conformity

The "CE" mark affixed to the DEFINITY ONE equipment described in this book indicates that the equipment conforms to the following European Union (EU) Directives:

- Electromagnetic Compatibility (89/336/EEC)
- Low Voltage (73/23/EEC)
- Telecommunications Terminal Equipment (TTE) i-CTR3 BRI and i-CTR4 PRI

For more information on standards compliance, contact your local distributor.

## Comments

To comment on this document, return the comment card at the end of the document.

# Contents

<a href="#">Contents</a>	<a href="#">iii</a>
<a href="#">About This Document</a>	<a href="#">xv</a>
<a href="#">Purpose</a>	<a href="#">xv</a>
<a href="#">Intended audience</a>	<a href="#">xv</a>
<a href="#">Organization</a>	<a href="#">xvi</a>
<a href="#">Conventions used in this book</a>	<a href="#">xvii</a>
<a href="#">Typographic conventions</a>	<a href="#">xviii</a>
<a href="#">Admonishments</a>	<a href="#">xix</a>
<a href="#">Safety precautions</a>	<a href="#">xix</a>
<a href="#">Security issues</a>	<a href="#">xx</a>
<a href="#">Standards compliance</a>	<a href="#">xxi</a>
<a href="#">Electromagnetic compatibility standards</a>	<a href="#">xxii</a>
<a href="#">Trademarks and service marks</a>	<a href="#">xxiii</a>
<a href="#">Related documents</a>	<a href="#">xxiv</a>
<a href="#">Federal Communications Commission statement</a>	<a href="#">xxv</a>
<a href="#">How to order documentation</a>	<a href="#">xxvii</a>
<a href="#">How to comment on this book</a>	<a href="#">xxvii</a>
<a href="#">Where to call for technical support</a>	<a href="#">xxviii</a>
<b>1</b> <a href="#">Maintenance Concepts for DEFINITY ONE</a>	<a href="#">1-1</a>
<a href="#">What's New in DEFINITY ONE Release 2.0</a>	<a href="#">1-1</a>
<a href="#">Circuit packs</a>	<a href="#">1-9</a>
<a href="#">Maintenance objects</a>	<a href="#">1-14</a>
<a href="#">Alarm and error reporting</a>	<a href="#">1-14</a>
<a href="#">Maintenance testing</a>	<a href="#">1-15</a>
<a href="#">DEFINITY LAN Gateway maintenance</a>	<a href="#">1-19</a>
<a href="#">Processor C-LAN maintenance</a>	<a href="#">1-23</a>
<a href="#">Media processor</a>	<a href="#">1-26</a>
<a href="#">Accessing DEFINITY ONE™ for maintenance</a>	<a href="#">1-26</a>
<a href="#">Initialization and recovery</a>	<a href="#">1-29</a>
<a href="#">System reset (system shutdown on demand from a bash session)</a>	<a href="#">1-33</a>
<a href="#">LED interpretation</a>	<a href="#">1-33</a>
<a href="#">Logins and passwords</a>	<a href="#">1-42</a>

- [Customer access](#) 1-42
- [Windows NT logins for the customer](#) 1-43
- [DEFINITY logins for the customer](#) 1-49
- [Comcodes for Release 2.0](#) 1-53

## **2 Maintenance Procedures for DEFINITY ONE Compact Modular Cabinets** 2-1

- [Preventive maintenance](#) 2-1
- [Recovery from fatal errors](#) 2-4
- [Resolving alarms](#) 2-5
- [Reseating/replacing circuit packs](#) 2-7
- [Replace the TN795 circuit pack](#) 2-8
- [Replace the hard disk](#) 2-9
- [Removing power](#) 2-11
- [Restoring power](#) 2-12
- [Setting neon voltage \(ring ping\)](#) 2-13
- [Troubleshooting features](#) 2-14
- [Install DS1 CPE loopback jack \(T1 only\)](#) 2-39
- [Multimedia call handling](#) 2-52
- [TN760D tie trunk option settings](#) 2-60
- [TN464E/F option settings](#) 2-62
- [Troubleshooting multimedia call handling \(MMCH\)](#) 2-63

## **3 Global Administration Subsystem Commands** 3-1

- [alarmorig](#) 3-5
- [alarmstat](#) 3-6
- [autobackup](#) 3-6
- [cleargamalarm](#) 3-7
- [backupparms](#) 3-8
- [backupsources](#) 3-9
- [d1backup](#) 3-11
- [d1restore](#) 3-13
- [d1stat](#) 3-14
- [downloadboot](#) 3-15
- [environment](#) 3-16

■ <a href="#">exit</a>	<a href="#">3-17</a>
■ <a href="#">fileversion</a>	<a href="#">3-17</a>
■ <a href="#">ftpserv</a>	<a href="#">3-17</a>
■ <a href="#">fwversion</a>	<a href="#">3-18</a>
■ <a href="#">gamalarmstat</a>	<a href="#">3-19</a>
■ <a href="#">identbackup</a>	<a href="#">3-20</a>
■ <a href="#">installconfig</a>	<a href="#">3-21</a>
■ <a href="#">lucent help</a>	<a href="#">3-21</a>
■ <a href="#">net user</a>	<a href="#">3-21</a>
■ <a href="#">oss</a>	<a href="#">3-22</a>
■ <a href="#">pcanywhere</a>	<a href="#">3-23</a>
■ <a href="#">post</a>	<a href="#">3-23</a>
■ <a href="#">productid</a>	<a href="#">3-24</a>
■ <a href="#">rasdrop</a>	<a href="#">3-24</a>
■ <a href="#">reboot</a>	<a href="#">3-25</a>
■ <a href="#">restartcause</a>	<a href="#">3-25</a>
■ <a href="#">schedbackup</a>	<a href="#">3-26</a>
■ <a href="#">serialnumber</a>	<a href="#">3-27</a>
■ <a href="#">setip</a>	<a href="#">3-28</a>
■ <a href="#">siteconfig</a>	<a href="#">3-30</a>
■ <a href="#">shutdown</a>	<a href="#">3-30</a>
■ <a href="#">start</a>	<a href="#">3-33</a>
■ <a href="#">swversion</a>	<a href="#">3-34</a>
■ <a href="#">terminate</a>	<a href="#">3-35</a>
■ <a href="#">versiondiff</a>	<a href="#">3-36</a>

<b><a href="#">4</a></b>	<b><a href="#">Maintenance Commands for DEFINITY ONE</a></b>	<b><a href="#">4-1</a></b>
■	<a href="#">System command structure</a>	<a href="#">4-1</a>
■	<a href="#">busyout access-endpoint</a>	<a href="#">4-2</a>
■	<a href="#">busyout adjunct-ip-link</a>	<a href="#">4-4</a>
■	<a href="#">busyout board</a>	<a href="#">4-6</a>
■	<a href="#">busyout cdr-link</a>	<a href="#">4-7</a>
■	<a href="#">busyout data-module</a>	<a href="#">4-8</a>
■	<a href="#">busyout link</a>	<a href="#">4-10</a>
■	<a href="#">busyout mis</a>	<a href="#">4-11</a>
■	<a href="#">busyout port</a>	<a href="#">4-12</a>

■ <a href="#">busyout pri-endpoint</a>	4-13
■ <a href="#">busyout station</a>	4-14
■ <a href="#">busyout tdm</a>	4-15
■ <a href="#">busyout tone-clock</a>	4-16
■ <a href="#">busyout trunk</a>	4-17
■ <a href="#">cancel hardware-group</a>	4-18
■ <a href="#">change circuit-packs</a>	4-19
■ <a href="#">change synchronization</a>	4-21
■ <a href="#">change system-parameters maintenance</a>	4-22
■ <a href="#">clear audits</a>	4-30
■ <a href="#">clear errors</a>	4-30
■ <a href="#">clear isdnpri-testcall</a>	4-31
■ <a href="#">clear mst</a>	4-31
■ <a href="#">clear pkt</a>	4-31
■ <a href="#">clear port</a>	4-31
■ <a href="#">disable administered-connection</a>	4-32
■ <a href="#">disable mst</a>	4-32
■ <a href="#">disable suspend-alm-orig</a>	4-32
■ <a href="#">disable synchronization-switch</a>	4-33
■ <a href="#">disable test-number</a>	4-33
■ <a href="#">display alarms</a>	4-33
■ <a href="#">display capacity</a>	4-38
■ <a href="#">display disabled-tests</a>	4-48
■ <a href="#">display errors</a>	4-49
■ <a href="#">display events</a>	4-55
■ <a href="#">display initcauses</a>	4-57
■ <a href="#">display port</a>	4-59
■ <a href="#">display synchronization</a>	4-60
■ <a href="#">display system-parameters maintenance</a>	4-61
■ <a href="#">display time</a>	4-69
■ <a href="#">enable administered-connection</a>	4-70
■ <a href="#">enable mst</a>	4-70
■ <a href="#">enable suspend-alm-orig</a>	4-70
■ <a href="#">enable synchronization-switch</a>	4-71

■ <a href="#">enable test-number</a>	<a href="#">4-72</a>
■ <a href="#">list configuration</a>	<a href="#">4-72</a>
■ <a href="#">list config software-version</a>	<a href="#">4-75</a>
■ <a href="#">list disabled-mos</a>	<a href="#">4-76</a>
■ <a href="#">list history</a>	<a href="#">4-77</a>
■ <a href="#">list isdn-testcall</a>	<a href="#">4-79</a>
■ <a href="#">list marked-ports</a>	<a href="#">4-80</a>
■ <a href="#">list measurements</a>	<a href="#">4-81</a>
■ <a href="#">list suspend-alm-orig</a>	<a href="#">4-84</a>
■ <a href="#">list sys-link</a>	<a href="#">4-85</a>
■ <a href="#">list testcalls</a>	<a href="#">4-86</a>
■ <a href="#">mark port</a>	<a href="#">4-90</a>
■ <a href="#">monitor bcms</a>	<a href="#">4-90</a>
■ <a href="#">monitor health</a>	<a href="#">4-95</a>
■ <a href="#">monitor security-violations</a>	<a href="#">4-98</a>
■ <a href="#">monitor system</a>	<a href="#">4-99</a>
■ <a href="#">monitor traffic</a>	<a href="#">4-105</a>
■ <a href="#">monitor trunk</a>	<a href="#">4-107</a>
■ <a href="#">recycle carrier</a>	<a href="#">4-108</a>
■ <a href="#">release access-endpoint</a>	<a href="#">4-109</a>
■ <a href="#">release adjunct-ip-link</a>	<a href="#">4-110</a>
■ <a href="#">release board</a>	<a href="#">4-112</a>
■ <a href="#">release cdr-link</a>	<a href="#">4-113</a>
■ <a href="#">release data-module</a>	<a href="#">4-114</a>
■ <a href="#">release mis</a>	<a href="#">4-115</a>
■ <a href="#">release modem-pool</a>	<a href="#">4-116</a>
■ <a href="#">release port</a>	<a href="#">4-117</a>
■ <a href="#">release pri-endpoint</a>	<a href="#">4-118</a>
■ <a href="#">release station</a>	<a href="#">4-119</a>
■ <a href="#">release tdm</a>	<a href="#">4-120</a>
■ <a href="#">release tone-clock</a>	<a href="#">4-121</a>
■ <a href="#">release trunk</a>	<a href="#">4-122</a>
■ <a href="#">reset board</a>	<a href="#">4-123</a>
■ <a href="#">reset packet-interface</a>	<a href="#">4-124</a>
■ <a href="#">reset switch-control</a>	<a href="#">4-125</a>

■ <a href="#">reset system</a>	<a href="#">4-125</a>
■ <a href="#">reset tone-clock</a>	<a href="#">4-126</a>
■ <a href="#">resume hardware-group</a>	<a href="#">4-128</a>
■ <a href="#">save translation</a>	<a href="#">4-129</a>
■ <a href="#">set options</a>	<a href="#">4-130</a>
■ <a href="#">set signaling-group</a>	<a href="#">4-135</a>
■ <a href="#">set synchronization</a>	<a href="#">4-135</a>
■ <a href="#">set tdm</a>	<a href="#">4-136</a>
■ <a href="#">set tone-clock</a>	<a href="#">4-136</a>
■ <a href="#">status access-endpoint</a>	<a href="#">4-137</a>
■ <a href="#">status administered-connection</a>	<a href="#">4-138</a>
■ <a href="#">status asai/adjunct tcp/ip link</a>	<a href="#">4-140</a>
■ <a href="#">status attendant</a>	<a href="#">4-142</a>
■ <a href="#">status audits</a>	<a href="#">4-143</a>
■ <a href="#">status bri-port</a>	<a href="#">4-151</a>
■ <a href="#">status cdr-link</a>	<a href="#">4-158</a>
■ <a href="#">status cleared-alarm-notif</a>	<a href="#">4-159</a>
■ <a href="#">status conference</a>	<a href="#">4-159</a>
■ <a href="#">status data-module</a>	<a href="#">4-195</a>
■ <a href="#">status hardware-group</a>	<a href="#">4-197</a>
■ <a href="#">status health</a>	<a href="#">4-199</a>
■ <a href="#">status isdn-testcall</a>	<a href="#">4-202</a>
■ <a href="#">status link</a>	<a href="#">4-204</a>
■ <a href="#">status packet-interface</a>	<a href="#">4-204</a>
■ <a href="#">status periodic-scheduled</a>	<a href="#">4-205</a>
■ <a href="#">status pri-endpoint</a>	<a href="#">4-206</a>
■ <a href="#">status processor-channel</a>	<a href="#">4-208</a>
■ <a href="#">status remote-access</a>	<a href="#">4-210</a>
■ <a href="#">status signaling-group</a>	<a href="#">4-211</a>
■ <a href="#">status station</a>	<a href="#">4-213</a>
■ <a href="#">status synchronization</a>	<a href="#">4-216</a>
■ <a href="#">status sys-link</a>	<a href="#">4-217</a>
■ <a href="#">status system</a>	<a href="#">4-219</a>
■ <a href="#">status trunk</a>	<a href="#">4-223</a>

■ <a href="#">status tsc-administered</a>	<a href="#">4-225</a>
■ <a href="#">status tti</a>	<a href="#">4-226</a>
■ <a href="#">test access-endpoint</a>	<a href="#">4-228</a>
■ <a href="#">test alarms</a>	<a href="#">4-230</a>
■ <a href="#">test analog-testcall</a>	<a href="#">4-235</a>
■ <a href="#">test board</a>	<a href="#">4-237</a>
■ <a href="#">test cdr-link</a>	<a href="#">4-240</a>
■ <a href="#">test customer-alarm</a>	<a href="#">4-241</a>
■ <a href="#">test data-module</a>	<a href="#">4-243</a>
■ <a href="#">test ds1-loop</a>	<a href="#">4-244</a>
■ <a href="#">test eda-external-device-alm</a>	<a href="#">4-247</a>
■ <a href="#">test environment</a>	<a href="#">4-249</a>
■ <a href="#">test hardware-group</a>	<a href="#">4-251</a>
■ <a href="#">test inads-link</a>	<a href="#">4-256</a>
■ <a href="#">test isdnpri-testcall</a>	<a href="#">4-258</a>
■ <a href="#">test led</a>	<a href="#">4-260</a>
■ <a href="#">test modem-pool</a>	<a href="#">4-260</a>
■ <a href="#">test packet-interface</a>	<a href="#">4-261</a>
■ <a href="#">test pkt</a>	<a href="#">4-262</a>
■ <a href="#">test port</a>	<a href="#">4-264</a>
■ <a href="#">test pri-endpoint</a>	<a href="#">4-266</a>
■ <a href="#">test pr-maintenance</a>	<a href="#">4-268</a>
■ <a href="#">test signaling-group</a>	<a href="#">4-269</a>
■ <a href="#">test station</a>	<a href="#">4-271</a>
■ <a href="#">test switch-control</a>	<a href="#">4-273</a>
■ <a href="#">test synchronization</a>	<a href="#">4-274</a>
■ <a href="#">test sys-link</a>	<a href="#">4-276</a>
■ <a href="#">test tdm</a>	<a href="#">4-278</a>
■ <a href="#">test tone-clock</a>	<a href="#">4-280</a>
■ <a href="#">test translation-store</a>	<a href="#">4-281</a>
■ <a href="#">test trunk</a>	<a href="#">4-283</a>
■ <a href="#">test tsc-administered</a>	<a href="#">4-285</a>

<b><u>5</u></b>	<b><u>Maintenance Objects for DEFINITY ONE</u></b>	<b><u>5-1</u></b>
■	<u>ABRI-PORT (ASAI ISDN-BRI Port)</u>	<u>5-2</u>
■	<u>ADJLK-IP (ASAI Adjunct IP Link)</u>	<u>5-2</u>
■	<u>ADM-CONN (administered connection)</u>	<u>5-13</u>
■	<u>ALARM-PT (ALARM port)</u>	<u>5-18</u>
■	<u>ANL-16-L (16-Port Neon Analog Line)</u>	<u>5-26</u>
■	<u>ANL-24-L (24-Port Analog Line)</u>	<u>5-44</u>
■	<u>ANL-BD (analog line circuit pack)</u>	<u>5-64</u>
■	<u>ANL-LINE (8-port analog line),</u> <u>ANL-NE-L (8-port neon analog line)</u>	<u>5-65</u>
■	<u>AN-LN-PT (Analog Line Port)</u>	<u>5-88</u>
■	<u>ANN-BD (announcement circuit pack)</u>	<u>5-112</u>
■	<u>ANN-PT (announcement port)</u>	<u>5-133</u>
■	<u>ANNOUNCE (announce)</u>	<u>5-144</u>
■	<u>ASAI-BD (Multi-Application Platform Board)</u>	<u>5-148</u>
■	<u>ASAI-EPT</u>	<u>5-150</u>
■	<u>ASAI-PT</u>	<u>5-158</u>
■	<u>ASAI-RES/E-DIG-RES (TN800 reserve slot)</u>	<u>5-168</u>
■	<u>ATM-BCH (ATM B-channel trunk)</u>	<u>5-169</u>
■	<u>ATM-DCH (ATM D-channel port)</u>	<u>5-184</u>
■	<u>ATM-EI (Expansion Interface Circuit Pack)</u>	<u>5-187</u>
■	<u>ATM-INTF (TN2305/6)</u>	<u>5-239</u>
■	<u>ATM-NTWK (ATM Network Error)</u>	<u>5-243</u>
■	<u>ATM-SGRP (ATM signaling group)</u>	<u>5-251</u>
■	<u>ATM-TRK (circuit emulation service</u> <u>circuit pack)</u>	<u>5-264</u>
■	<u>BRI-BD/LGATE-BD (ISDN-BRI Line Circuit Pack)</u>	<u>5-305</u>
■	<u>BRI-DAT (ISDN-BRI)</u>	<u>5-312</u>
■	<u>BRI-PORT (ISDN-BRI Port),</u> <u>ABRI-PORT (ASAI ISDN-BRI Port)</u>	<u>5-312</u>
■	<u>BRI-SET, ASAI-ADJ, BRI-DAT</u>	<u>5-334</u>
■	<u>CABINET (Cabinet Sensors)</u>	<u>5-363</u>
■	<u>CDR-LNK (CDR Link)</u>	<u>5-371</u>
■	<u>CLAN-BD (Control LAN Circuit Pack)</u>	<u>5-378</u>
■	<u>CLSFY-BD (Call Classifier Circuit Pack)</u>	<u>5-394</u>
■	<u>CLSFY-PT (Call Classifier Port)</u>	<u>5-395</u>

■ <a href="#">CO-BD (Central Office Trunk Circuit Pack)</a>	5-401
■ <a href="#">CO-DS1 (DS1 CO Trunk)</a>	5-402
■ <a href="#">CO-TRK (CO Trunk)</a>	5-419
■ <a href="#">CONFIG (System Configuration)</a>	5-445
■ <a href="#">CUST-ALM (Customer-Provided Alarming Device)</a>	5-446
■ <a href="#">DATA-CHL (Data Channel)</a>	5-449
■ <a href="#">DAT-LINE (Data Line)</a>	5-466
■ <a href="#">DETR-BD (International Version)</a>	5-474
■ <a href="#">DID-BD (Direct Inward Dial Trunk Circuit Pack)</a>	5-474
■ <a href="#">DID-DS1 (DS1 DID Trunk)</a>	5-475
■ <a href="#">DID-TRK (DID Trunk)</a>	5-486
■ <a href="#">DIG-BD (Digital Line Circuit Pack)</a>	5-501
■ <a href="#">DIG-LINE (Digital Line)</a>	5-502
■ <a href="#">DIOD-DS1 (DS1 DIOD Trunk)</a>	5-526
■ <a href="#">DIOD-TRK (DIOD Trunk), DIOD-BD (DIOD Circuit Pack)</a>	5-537
■ <a href="#">DIOD-TRK (DIOD Trunk)</a>	5-537
■ <a href="#">DLY-MTCE (MO-DAILY)</a>	5-548
■ <a href="#">DS1-BD (DS1 Interface Circuit Pack)</a>	5-548
■ <a href="#">DT-LN-BD (Data Line Circuit Pack)</a>	5-624
■ <a href="#">DTMR-PT [Dual Tone Multifrequency Port (TTR)]</a>	5-624
■ <a href="#">E-DIG-BD (Multi Application Platform Board)</a>	5-629
■ <a href="#">E-DIG-STA (Emulated Digital Line)</a>	5-631
■ <a href="#">EMG-XFER</a>	5-641
■ <a href="#">ERR-LOG (Error Log)</a>	5-644
■ <a href="#">ETH-PT (Control LAN Ethernet)</a>	5-645
■ <a href="#">ETR-PT (Enhanced Tone Receiver Port)</a>	5-655
■ <a href="#">EXT-DEV ADMIN? N (External Device Alarm)</a>	5-660
■ <a href="#">EXT-DEV ADMIN? Y (External Device Alarm)</a>	5-663
■ <a href="#">GPTD-PT [General Purpose Tone Detector Port (CPTR)]</a>	5-667
■ <a href="#">H323-SGRP (H.323 Signaling Group)</a>	5-668
■ <a href="#">HYB-BD (Hybrid Line Circuit Pack)</a>	5-673
■ <a href="#">HYB-LINE (Hybrid Line)</a>	5-674
■ <a href="#">INADS (INADS Link)</a>	5-696

■ <a href="#">ISDN-PLK (ISDN-PRI Signaling Link Port)</a>	<a href="#">5-699</a>
■ <a href="#">ISDN-SGR (ISDN-PRI Signaling Group)</a>	<a href="#">5-705</a>
■ <a href="#">ISDN-TRK (DS1 ISDN Trunk)</a>	<a href="#">5-722</a>
■ <a href="#">LGATE-AJ</a>	<a href="#">5-749</a>
■ <a href="#">LGATE-BD</a>	<a href="#">5-749</a>
■ <a href="#">LGATE-PT</a>	<a href="#">5-749</a>
■ <a href="#">LOG-SVN (Login Security Violation)</a>	<a href="#">5-749</a>
■ <a href="#">MAPD-BD (MAPD Interface Circuit Pack TN802)</a>	<a href="#">5-752</a>
■ <a href="#">MEDPROPT (TN802 MED PRO DSP PORT)</a>	<a href="#">5-782</a>
■ <a href="#">MEM-BD (Memory)</a>	<a href="#">5-788</a>
■ <a href="#">MEMORY</a>	<a href="#">5-794</a>
■ <a href="#">MET-BD (MET Line Circuit Pack)</a>	<a href="#">5-794</a>
■ <a href="#">MET-LINE (MET Line)</a>	<a href="#">5-795</a>
■ <a href="#">MIS (Management Information System)</a>	<a href="#">5-815</a>
■ <a href="#">MMI-BD</a>	<a href="#">5-818</a>
■ <a href="#">MMI-LEV (Multimedia Interface Resource Level)</a>	<a href="#">5-828</a>
■ <a href="#">MMI-PT</a>	<a href="#">5-831</a>
■ <a href="#">MMI-SYNC</a>	<a href="#">5-836</a>
■ <a href="#">MODEM-BD (Modem Pool Circuit Pack)</a>	<a href="#">5-838</a>
■ <a href="#">MODEM-PT (Modem Pool Port)</a>	<a href="#">5-838</a>
■ <a href="#">M/T-ANL (Maintenance/Test Analog Port)</a>	<a href="#">5-854</a>
■ <a href="#">M/T-BD (Maintenance/Test Circuit Pack)</a>	<a href="#">5-864</a>
■ <a href="#">M/T-DIG (Maintenance/Test Digital Port) [G3iV1-1.286, G3iV2-386]</a>	<a href="#">5-865</a>
■ <a href="#">M/T-PKT (Maintenance/Test Packet Bus Port)</a>	<a href="#">5-877</a>
■ <a href="#">OPS-LINE (DS1 OPS Line)</a>	<a href="#">5-882</a>
■ <a href="#">PDMODULE, TDMODULE (Data Module)</a>	<a href="#">5-894</a>
■ <a href="#">PE-BCHL (PRI Endpoint Port)</a>	<a href="#">5-913</a>
■ <a href="#">PI-LINK (Processor Interface Link)</a>	<a href="#">5-934</a>
■ <a href="#">PKT-BUS (Packet Bus)</a>	<a href="#">5-950</a>
■ <a href="#">PKT-INT (Packet Interface)</a>	<a href="#">5-958</a>
■ <a href="#">PMS-PRNT/JNL-PRNT (PMS Printer Link)</a>	<a href="#">5-974</a>
■ <a href="#">PPP-PT (Control LAN Packet/Port)</a>	<a href="#">5-980</a>
■ <a href="#">PR-ADX (Processor Board - AUDIX Port)</a>	<a href="#">5-993</a>

■ <a href="#">PR-AL-BD (Processor Alarm Board)</a>	<a href="#">5-997</a>
■ <a href="#">PR-MAINT (Maintenance Processor)</a>	<a href="#">5-1000</a>
■ <a href="#">PROCR (Processor Circuit Pack)</a>	<a href="#">5-1008</a>
■ <a href="#">PR-SSP (Processor Board - Scalable Speech Processor)</a>	<a href="#">5-1015</a>
■ <a href="#">PR-TN-BD (TN795 Processor/Tone-Clock)</a>	<a href="#">5-1023</a>
■ <a href="#">PROC-SAN (Process Sanity Audits)</a>	<a href="#">5-1035</a>
■ <a href="#">RING-GEN (Analog Ring Generator)</a>	<a href="#">5-1036</a>
■ <a href="#">S-SYN-BD (Speech Synthesis Circuit Pack)</a>	<a href="#">5-1040</a>
■ <a href="#">S-SYN-PT (Speech Synthesis Port)</a>	<a href="#">5-1041</a>
■ <a href="#">SW-CTL (Switch Control)</a>	<a href="#">5-1054</a>
■ <a href="#">SYNC (Synchronization)</a>	<a href="#">5-1063</a>
■ <a href="#">SYS-LINK (System Links)</a>	<a href="#">5-1070</a>
■ <a href="#">SYSTEM (System)</a>	<a href="#">5-1075</a>
■ <a href="#">TBRI-BD (TN2185 ISDN Trunk-Side BRI)</a>	<a href="#">5-1077</a>
■ <a href="#">TBRI-PT (TN2185 ISDN Trunk-Side BRI Port)</a>	<a href="#">5-1085</a>
■ <a href="#">TBRI-TRK (TN2185 ISDN Trunk-Side BRI)</a>	<a href="#">5-1105</a>
■ <a href="#">TDM-BUS (TDM Bus)</a>	<a href="#">5-1116</a>
■ <a href="#">TDM-CLK (TDM Bus Clock)</a>	<a href="#">5-1132</a>
■ <a href="#">TDMODULE (Trunk Data Module)</a>	<a href="#">5-1142</a>
■ <a href="#">TIE-BD (Tie Trunk Circuit Pack)</a>	<a href="#">5-1143</a>
■ <a href="#">TIE-DS1 (DS1 Tie Trunk)</a>	<a href="#">5-1144</a>
■ <a href="#">TIE-TRK (Tie Trunk)</a>	<a href="#">5-1161</a>
■ <a href="#">TONE-BD (Tone-Clock Circuit Pack)</a>	<a href="#">5-1184</a>
■ <a href="#">TONE-PT (Tone Generator)</a>	<a href="#">5-1204</a>
■ <a href="#">TRANS-STO (Translation Storage)</a>	<a href="#">5-1214</a>
■ <a href="#">TSC-ADM (Administered Temporary Signaling Connections)</a>	<a href="#">5-1217</a>
■ <a href="#">TTR-LEV (TTR Level)</a>	<a href="#">5-1223</a>
■ <a href="#">UDS1-BD (UDS1 Interface Circuit Pack)</a>	<a href="#">5-1227</a>
■ <a href="#">VC-BD</a>	<a href="#">5-1315</a>
■ <a href="#">VC-DSPPT</a>	<a href="#">5-1319</a>

- [VC-LEV \(Voice Conditioner DSP Port Level\)](#) [5-1328](#)
- [VC-SUMPT](#) [5-1331](#)
- [WAE-PORT \(Wideband Access Endpoint Port\)](#) [5-1336](#)
- [XXX-BD \(Common Port Circuit Pack\)](#) [5-1343](#)

**[6](#)** [DEFINITY ONE NT Log Events and Alarms](#) [6-1](#)

- [Introduction](#) [6-1](#)
- [Alarms for DEFINITY ONE Co-Resident Services](#) [6-3](#)

**[A](#)** [Summary of DEFINITY ONE Commands](#) [A-1](#)

- [LAC GAS Commands](#) [A-11](#)

**[B](#)** [Access Security Gateway](#) [B-1](#)

- [Using the ASG Mobile](#) [B-1](#)

**[IN](#)** [Index](#) [IN-1](#)

# About This Document

---

## Purpose

This book contains the information needed to monitor, test, and maintain DEFINITY ONE™ Communications System and covers many of the faults and troubles that can occur in the system. Most maintenance requirements are simple procedures due to the modular, self-testing nature of the system.

Simple, traditional troubleshooting methods are sometimes sufficient to locate and clear faults. The traditional methods include terminal substitution, visual inspections, continuity checks, and clarification of operating procedures with end users.

DEFINITY ONE is a high-functionality communications system for customers in the 25-40 line size or smaller with growth potential to 168 stations. This offer provides DEFINITY® software, INTUITY® AUDIX® messaging, and DEFINITY Site Administration (DSA) on a single hardware platform

## Intended audience

The information in this book is intended for use by:

- A maintenance technician dispatched to a DEFINITY ONE site in response to a trouble alarm or a user trouble report
- A maintenance technician located at a remote maintenance facility
- The customer's assigned maintenance technician. The technician is expected to have a knowledge of telecommunications fundamentals and of DEFINITY ONE to the extent that the procedures in this book can be performed, in most cases, without assistance.

Each DEFINITY ONE System has a user-designated System Manager who is responsible for system administration and with whom the maintenance technician should work closely.

This book is not intended to solve all levels of troubles. It is limited to troubles that can be solved by using the Alarm Log, Error Log, trouble-clearing procedures, maintenance tests, and traditional troubleshooting methods. If the trouble still has not been resolved, it is the responsibility of the maintenance technician to escalate the problem to a higher level of technical support. Escalation should conform to the procedures in the *Technical and Administration Escalation Plan*.

## Organization

---

### [Chapter 1, "Maintenance Concepts for DEFINITY ONE"](#)

Describes what's new in DEFINITY ONE, the system design and maintenance strategy, reset and reboot processes, LED sequences, allowable circuit packs, and component comcodes.

---

### [Chapter 2, "Maintenance Procedures for DEFINITY ONE Compact Modular Cabinets"](#)

Describes the various maintenance procedures: powering up and down, connecting to DEFINITY ONE, getting access to the system software, replacing components, routine maintenance, troubleshooting advice.

---

### [Chapter 3, "Global Administration Subsystem Commands"](#)

Describes the commands available via the command line interface.

---

### [Chapter 4, "Maintenance Commands for DEFINITY ONE"](#)

Explains how to use the maintenance commands including specific command syntax, typical forms, and display output.

---

### [Chapter 5, "Maintenance Objects for DEFINITY ONE"](#)

Contains specific troubleshooting and repair instructions for every maintenance component in the system. This chapter also contains repair procedures for system-alarmed and user-reported troubles. For each Maintenance Object (MO), a table lists the alarm level, hardware error associated with the MO, the associated test that caused the error, the test sequences and the specific command-line entry required to run the tests, and a brief description of each test. Explanations of error codes associated with each test are given along with specific maintenance procedures used to resolve each problem.

[Chapter 6, “DEFINITY ONE NT Log Events and Alarms”](#)

Describes alarms for each software subsystem, listed by alarm number. Advice for resolving alarms is also provided.

[Appendix A, “Summary of DEFINITY ONE Commands”](#)

Provides brief descriptions for the commands you encounter in using the DEFINITY ONE system.

[Chapter B, “Access Security Gateway”](#)

Provides information on how to administer Access Security Gateway (ASG).

## Conventions used in this book

Circuit pack codes (such as TN763D) are shown with the minimum acceptable alphabetic suffix (for example, the “D” in the code TN763D).

Generally, an alphabetic suffix greater than that shown is also acceptable. However, not every vintage of either the minimum suffix or a higher suffix code is necessarily acceptable.



**NOTE:**

Refer to *Technical Monthly: Reference Guide for Circuit Pack Vintages and Change Notices* for current information about usable vintages of specific circuit pack codes (including the suffix).

The following conventions describe the systems referred to in this document.

- *System* is a general term encompassing Release 2.0 and includes references to DEFINITY ONE.
- Information is applicable for Release 2.0 unless otherwise specified
- DEFINITY ONE Communications System is abbreviated as DEFINITY ONE.

Physical dimensions in this book are in inches followed by metric centimeters (cm) in parentheses. Wire gauge measurements are in American Wire Gauge (AWG) followed by the cross-sectional area in squared millimeters (mm<sup>2</sup>) in parentheses.

## Typographic conventions

---

This document uses the following typographic conventions:

- Information you type at the management terminal is shown in the following typeface: **list system-parameters maintenance**.
- Information displayed on the management terminal screen is shown in the following typeface: `login`.
- Keyboard keys are shown in the following typeface: `Enter`.

The following conventions describe the systems referred to in this document.

- Circuit pack codes (such as TN763D) are shown with the minimum acceptable alphabetic suffix (like the “D” in the code TN763D).
- An alphabetic suffix greater than that shown is also acceptable. However, not every vintage of either the minimum suffix or a higher suffix code is necessarily acceptable.



### NOTE:

Refer to *Technical Monthly: Reference Guide for Circuit Pack Vintages and Change Notices* for current information about usable vintages of specific circuit pack codes (including the suffix).

- The word *system* is a general term encompassing Release 2.0 and includes references to DEFINITY ONE.
- Information in this book is applicable for Release 2.0 unless otherwise specified
- DEFINITY ONE Communications System is abbreviated as DEFINITY ONE.
- Physical dimensions in this book are in inches followed by metric centimeters (cm) in parentheses. Wire gauge measurements are in AWG followed by the cross-sectional area in squared millimeters (mm<sup>2</sup>) in parentheses.
- The term “ASAI” is synonymous with the newer CallVisor ASAI.

## Admonishments

---

Admonishments used in this book have the following meanings:



**CAUTION:**

*This sign is used to indicate possible harm to software, possible loss of data, or possible service interruptions.*



**WARNING:**

*This sign is used where there is possible harm to hardware or equipment.*



**DANGER:**

*This sign is used to indicate possible harm or injury to people.*

## Safety precautions

---

When performing maintenance or translation procedures on the system, users must observe certain precautions. Observe all caution, warning, and danger admonishments to prevent loss of service, possible equipment damage, and possible personal injury. In addition, the following precautions regarding electromagnetic interference (EMI) and static electricity must be observed:

### Electromagnetic interference

---

This equipment generates, uses, and can radiate radio frequency energy. Electromagnetic fields radiating from the switch may cause noise in the customer's equipment. If the equipment is not installed and used in accordance with the instruction book, radio interference may result.



**WARNING:**

*To maintain the EMI integrity of the system, maintenance personnel must ensure that all cabinet panels, covers, and so forth, are firmly secured before leaving the customer's premises.*

## Static electricity

---

To prevent or reduce electrostatic discharge (ESD), maintenance personnel must always attach wrist grounding straps before working on switch components or handling circuit packs.

### CAUTION:

*Electrostatic discharge can damage or destroy circuit packs containing integrated circuits (ICs).*

The ESD wrist strap, cable assembly, and spare fuses are packed in a plastic bag and placed in the top of the system cabinet. Use the ESD wrist strap when troubleshooting, performing maintenance, or handling any circuit packs associated with the system.

## Security issues

---

To ensure the greatest security possible for customers, Lucent Technologies offers services that can reduce toll-fraud liabilities. Contact your Lucent Technologies representative for more security information.

Login security is an attribute of the DEFINITY ONE software. Existing passwords expire 24 hours after installation.

For Software Copy Protection information, see Chapter 10, "Security and Copy Protection" in the *DEFINITY ONE Communications System Release 2.0 Installation and Upgrades* (555-233-109).

### NOTE:

Login security is an attribute of the DEFINITY ONE Release 2.0 software.

## Standards compliance

---

The equipment presented in this document complies with the following (as appropriate):

- ITU-T (Formerly CCITT)
- ECMA
- ETSI
- IPNS
- DPNSS
- National ISDN-1
- National ISDN-2
- ISO-9000
- ANSI
- FCC Part 15 and Part 68
- EN55022
- EN50081
- EN50082
- CISPR22
- Australia AS3548 (AS/NZ3548)
- Australia AS3260
- IEC 825
- IEC950
- UL 1459
- UL1950
- CSA C222 Number 225
- TS001

## Electromagnetic compatibility standards

---

This product complies with and conforms to the following:

- Limits and Methods of Measurements of Radio Interference Characteristics of Information Technology Equipment, EN55022 (CISPR22), 1993
- EN50082-1, European Generic Immunity Standard
- FCC Parts 15 and 68
- Australia AS3548



**NOTE:**

The system conforms to Class A (industrial) equipment; voice terminals meet Class B requirements.

- Electrostatic Discharge (ESD) IEC 1000-4-2
- Radiated radio frequency field IEC 1000-4-3
- Electrical Fast Transient IEC 1000-4-4
- Lightning effects IEC 1000-4-5
- Conducted radio frequency IEC 1000-4-6
- Mains frequency magnetic field IEC 1000-4-8
- Low-frequency mains disturbance

The system conforms to the following:

- Electromagnetic compatibility General Immunity Standard, part 1; residential, commercial, light industry, EN50082-1, CENELEC, 1991
- Issue 1 (1984) and Issue 2 (1992), Electrostatic-discharge immunity requirements (EN55024, Part 2) IEC 1000-4-2
- Radiated radio-frequency field-immunity requirements IEC 1000-4-3
- Electrical fast-transient/burst immunity requirements IEC 1000-4-4

## European Union standards

---

Lucent Technologies Business Communications Systems declares that the DEFINITY equipment specified in this document bearing the “CE” mark conforms to the European Union Electromagnetic Compatibility Directives.

The “CE” (Conformité Européenne) mark indicates conformance to the:

- European Union Electromagnetic Compatibility Directive (89/336/EEC)
- Low Voltage Directive (73/23/EEC)
- Telecommunication Terminal Equipment (TTE) Directive (91/263/EEC)
- i-CTR3 Basic Rate Interface (BRI) and i-CTR4 Primary Rate Interface (PRI) as applicable.

The “CE” mark is applied to the following DEFINITY ONE product:

- AC-powered Compact Single-Carrier Cabinet (CSCC) with 25-Hz ring generator

## Trademarks and service marks

---

The following are trademarks or registered trademarks of Lucent Technologies:

- 5ESS™, 4ESS™
- Ascend® (A wholly owned subsidiary of Lucent Technologies)
- AUDIX®
- Callvisor®
- Callmaster®
- CentreVu™
- CONVERSANT®
- DEFINITY®
- DEFINITY ONE™
- DIMENSION®
- MERLIN®
- VOICE POWER®

The following are trademarks or registered trademarks of AT&T:

- ACCUNET®
- DATAPHONE®
- MEGACOM®
- MULTIQUEST®
- TELESEER®

The following are trademarks or registered trademarks of other companies:

- Audichron<sup>®</sup> (registered trademark of the Audichron Company)
- MS-DOS<sup>®</sup> (registered trademark of the Microsoft Corporation)
- MicroChannel<sup>®</sup> (registered trademark of IBM Systems)
- MULTIQUEST<sup>®</sup> (registered trademark of Telecommunications Service)
- PagePac<sup>®</sup> (trademark of the Dracon Division of the Harris Corporation)
- UNIX<sup>®</sup> (trademark of the Novell Corporation)
- Windows NT<sup>®</sup> (registered trademark of the Microsoft Corporation)
- Internet Explorer<sup>®</sup> is a registered trademark of Microsoft Corporation
- Netscape<sup>®</sup> is a registered trademark of Netscape Communications Corporation

## **Related documents**

---

- *BCS Products Security Handbook (555-025-600)*
- *DEFINITY Enterprise Communications Server Release 8.2 Installation for Adjuncts and Peripherals (555-230-125)*
- *DEFINITY Enterprise Communications Server Release 8.2 Administrator's Guide (555-230-506)*
- *DEFINITY Enterprise Communications System R 8.2 Administration for Network Connectivity (555-233-501)*
- *DEFINITY Enterprise Communications Server Release 8.2 System Description Pocket Reference (555-230-211)*
- *DEFINITY Communications System and System 75 and System 85 Terminals and Adjuncts (555-015-201)*
- *DEFINITY ONE Communications System Release 2.0 Overview (555-233-001)*
- *DEFINITY ONE Communications System Release 2.0 Installation and Upgrades (555-233-109)*

## Federal Communications Commission statement

---

### Part 68: statement

---

Part 68: Answer-Supervision Signaling. Allowing this equipment to be operated in a manner that does not provide proper answer-supervision signaling is in violation of Part 68 rules. This equipment returns answer-supervision signals to the public-switched network when:

- Answered by the called station
- Answered by an attendant
- Routed to a recorded announcement or music in queue that can be administered by the CPE user

This equipment returns answer-supervision signals on all DID calls forwarded back to the public-switched telephone network, with these exceptions:

- A call is unanswered
- A busy tone is received
- A reorder tone is received

This equipment is capable of providing users access to interstate providers of operator services through the use of access codes. Modification of this equipment by call aggregators to block access dialing codes is a violation of the Telephone Operator Consumers Act of 1990.

This equipment complies with Part 68 of the FCC Rules. On the rear of this equipment is a label that contains, among other information, the FCC registration number and ringer equivalence number (REN) for this equipment. If requested, this information must be provided to the telephone company. The REN is used to determine the number of devices connected to the telephone line. Excessive RENs on the telephone line may result in devices not ringing in response to an incoming call. In most, but not all areas, the sum of RENs should not exceed 5.0. To be certain of the number of devices that can be connected to a line, as determined by the total RENs, contact the local telephone company.

 **NOTE:**

REN is not required for some types of analog or digital facilities.

## Means of Connection (U.S.)

Connection of this equipment to the telephone network is shown in the following table.

Manufacturer's Port Identifier	FIC Code	SOC/REN/A.S. Code	Network Jacks
Off- /On-Premises Station	OL13C	9.0F	RJ2GX, RJ21X, RJ11C
DID Trunk	02RV2-T	0.0B	RJ2GX, RJ21X
CO Trunk (ground start)	02GS2	0.3A	RJ21X
CO Trunk (loop start)	02LS2	0.3A	RJ21X
Tie Trunk	TL31M	9.0F	RJ2GX
1.544 Digital Interface	04DU9-B, C	6.0P	RJ48C, RJ48M
1.544 Digital Interface	04DU9-BN, KN	6.0P	RJ48C, RJ48M
120A2 Channel Service Unit	04DU9-DN	6.0P	RJ48C

If the terminal equipment (DEFINITY system) causes harm to the telephone network, the telephone company may notify you in advance that temporary discontinuance of service is required. But if advance notice is not practical, the telephone company may notify the customer as soon as possible thereafter. Also, you will be advised of your right to file a complaint with the FCC if you believe it is necessary.

The telephone company may make changes in its facilities, equipment, operations, or procedures that could affect the operation of the equipment. If this happens, the telephone company will provide advance notice so you can make the necessary modifications to maintain uninterrupted service.

If trouble is experienced with this equipment or for repair or warranty information, please contact the Technical Service Center at 1-800-248-1234. If the equipment causes harm to the telephone network, the telephone company may request that you disconnect the equipment until the problem is resolved.

It is recommended that repairs be performed by Lucent Technologies-certified technicians.

The equipment cannot be used on public coin-phone service. Connection to party-line service is subject to state tariffs. Contact the state public utility commission, public service commission, or corporation commission for information.

This equipment is hearing aid compatible if a telephone receiver is used.

## **How to order documentation**

---

A complete list of DEFINITY ONE, DEFINITY, and AUDIX books is available in the *Business Communications System Publications Catalog*, 555-000-010.

You can order this document and any other documentation directly from the Lucent Technologies Business Communications System Publications Fulfillment Center at 1-317-322-6791 or toll free at 1-800-457-1235.

## **How to comment on this book**

---

Lucent Technologies welcomes your feedback. Please fill out the reader comment card at the end of this book and return it. Your comments are of great value and help us to improve our documentation.

If the reader comment card is missing, fax your comments to 1-303-538-1741 or to your Lucent Technologies representative, and mention this document's name and number, *DEFINITY ONE™ Communications System Maintenance Release 2.0*, (555-233-111).

## **Where to call for technical support**

	<b>Telephone number</b>
Streamlined Implementation (for missing equipment)	1-800-772-5409
USA/Canada Technical Service Center	1-800-248-1234
Technical Service Center (INADS Database Administration)	1-800-248-1111
Asia/Pacific Regional Support Center	65-872-8686
Western Europe/South Africa/Middle East	441-252-774-800
Business Communications Europe	441-252-391-789
Eastern/Central Europe	361-345-4334
ITAC	1-303-804-3777
Latin/Central America & Caribbean	1-303-804-3778
DEFINITY Helpline	1-800-225-7585
Lucent Technologies Toll Fraud Intervention	1-800-643-2353
Lucent Technologies Technical Care Center	1-800-242-2121
Lucent Technologies Corporate Security	1-800-822-9009
DEFINITY Site Administration (DSA) Domestic	1-800-242-2121
DEFINITY Site Administration (DSA) International	Call Local Dealer
INTUITY AUDIX Helpline	1-800-242-2121

# Maintenance Concepts for DEFINITY ONE

# 1

---

The maintenance subsystem is a part of the software that initializes and maintains the system. The software continuously monitors system health and keeps a record of errors detected in the system. The maintenance subsystem also provides a user interface for on-demand testing. This chapter provides a brief description of the Release 2.0 maintenance strategy and background information on the system's overall functions.

## What's New in DEFINITY ONE Release 2.0

---

- [“TN795 processor circuit pack”](#)
- [“Virtual boards and devices”](#)
- [“Windows NT platform”](#)
- [“pcAnywhere third-party software” on page 1-3](#)
- [“GUI operation”](#)
- [“New backup procedures”](#)
- [“DEFINITY ONE™ design”](#)
- “Connectivity and Access to DEFINITY ONE” see [“Accessing DEFINITY ONE™ for maintenance” on page 1-26](#)
- [“DEFINITY LAN Gateway maintenance” on page 1-19](#)
- [“DLG release-from-busyout results” on page 1-22](#)
- [“Accessing DEFINITY ONE™ for maintenance” on page 1-26](#)

## TN795 Processor circuit pack

The TN795 processor provides:

- An on-board Pentium processor chip that runs Windows NT
- A Motorola processor running application firmware
- An NT-to-firmware interface
- A tone clock
- 1A12 alarm board
- 1A11 and 1A13 virtual boards
- A “virtual” AUDIX board

See [“DEFINITY ONE™ design” on page 1-5](#) and the *DEFINITY ONE™ Communications System Release 2.0 Overview* (555-233-001), for more information regarding the TN795.

## Virtual boards and devices

The TN795 processor circuit pack includes functions, (such as the tone clock) that had previously resided on separate circuit packs. Commands, tests, and maintenance objects that were valid for the separate circuit packs are still available.

A virtual AUDIX board (PR-SSP) resides in slot 1A12. The hardware for this board is located on the TN795 but the AUDIX ports on the board are administered as if they were physical ports on the virtual board. Virtual boards, designated 1A11 and 1A13, reside in slots 11 and 13. The 1A11 board is used by DEFINITY to provide External Device Alarm contacts to indicate presence of any non-DEFINITY alarms. See [“PR-AL-BD \(Processor Alarm Board\)” on page 5-997](#). The 1A13 is a TN795 Processor Board.

## Windows NT platform

The TN795 Processor circuit pack runs Microsoft Windows NT 4.0. All DEFINITY ONE applications run in the Windows NT environment. The DEFINITY ONE system allows access using a laptop computer running Window 95, Windows 98, or Windows NT, and can be installed as part of a LAN.

The following applications are installed or available on the DEFINITY ONE system:

- DEFINITY Provides DEFINITY call processing features
- AUDIX Provides voice mail.
- pcAnywhere Must also be installed on the laptop or other network PC. Alternatively use the web based pcAnywhere Java client.
- DEFINITY Site Administration Available for download
- Message Manager Available for download

## pcAnywhere third-party software

If you have pcAnywhere application software installed on your laptop, on a PC, or the customer network, you can use it to access the DEFINITY ONE system just as if you had a monitor, keyboard, and mouse directly connected to the DEFINITY ONE cabinet location.

You can also get access to the DEFINITY ONE system using Telnet sessions. (See [“Recovery from fatal errors” on page 2-4](#) for more information.)

These connections can be over a PCMCIA Network Connection, a RAS Modem Connection, or a customer LAN Connection.

## GUI operation

DEFINITY ONE uses DEFINITY Site Administration (DSA) which has a graphical user interface (GUI) for all functions. See Chapter 2, “Connectivity and Access to DEFINITY ONE” in *DEFINITY ONE™ Communications System Release 2.0 Installation and Upgrades* (555-233-109).

## New backup procedures

Since the DEFINITY ONE system combines DEFINITY, AUDIX and Windows NT on one platform, there is a new procedure to back up user information and translations.

Backup is performed in one of two ways:

- Using the web browser
- Using the UNIX-like bash shell, accessed via a Telnet session
- DEFINITY ONE, with a series of global administration system (GAS) commands (see [Chapter 3, “Global Administration Subsystem Commands”](#) for a list of GAS commands).

### NOTE:

If a backup or restore operation is in progress, no other backup or restore command can be executed until the first one has finished.

## How backup works

The DEFINITY ONE system performs a backup by copying the files to be stored into a destination directory.

- All files currently in the directory are removed prior to backup.
- An identification file (ident file) is created for each backup, listing:
  - Version of backup program
  - Date and time the backup started
  - Date and time the backup completed
  - Code indicating successful completion or reason of failure
  - Indication of full or partial backup
- A global alarm is raised if an error occurs during a backup operation.
- Checksum verification is performed on all translation files.



### **WARNING:**

*Saving translations through the hard drive does not constitute a system backup. The data can still be lost.*

A save translation command from DEFINITY saves DEFINITY translations data on the hard drive of the TN795.

## Where to save translations and system user data

Once the data has been placed on the hard drive, it should also be saved on a backup drive. Data can be backed up to:

- PCMCIA Flash Disk The flash disk is a nonvolatile storage device installed in a PCMCIA slot on the TN795.

A system backup to flash card will save **only**

- Windows system registry
- DEFINITY translations
- AUDIX translations
- Header information for AUDIX messages

### **WARNING:**

*Messages should **not** be saved on the flash disk, because there is limited space. If you want to save messages, you must back up the files to another device on the customer network.*

- Network device You can back up all applications and messages to any network device that has enough storage, and is accessible across the network by DEFINITY ONE. Such devices include:
  - Network disk drives
  - Servers
  - Tape drives
  - Writable CDs

## DEFINITY ONE™ design

This section describes major design highlights for DEFINITY ONE. For further information, see the *DEFINITY ONE Communications System Release 2.0 Overview* (555-233-001).

Three slots are reserved (2 slots for the processor and one slot for the tone detector circuit pack).

## Compact modular cabinet

---

The DEFINITY ONE 10-slot Compact Modular Cabinet (CMC) includes:

- Slots for circuit packs
- Power supply

### Slots

- Two shelves of 5 slots each
- The slots are numbered 1-5 (lower shelf), and 6-10 (upper shelf).



#### NOTE:

The TN795 Processor circuit pack must be installed in slot 2 (due to width, slot 1 is unavailable).

- See [Figure1-1 on page1-8](#).

### AC power supply unit (650A)

- Multiple DC outputs:  $\pm 5.1$  VDC, -48 VDC, +8-14 VDC (fan speed control), and -150 to -115 VDC (Neon bus)
- Three switch-selectable AC ring outputs: 85 VAC @20 Hz (North America), 72 VAC @25 Hz (international), and two 28 VAC @50 Hz (France)
- For LED indicators and interpretation, see ["Power supply LEDs" on page 1-41](#).

### UPS

---

Use of an optional uninterruptable power supply (UPS) between the AC power source and the switch is recommended to maintain service without interruptions.

- There is no battery backup available for the DEFINITY ONE switch.
- If power is interrupted for more than 50 milliseconds, all calls are dropped and dynamic memory is lost.
- An external alarm is reserved for the UPS on the TN795 processor circuit pack.
  - If power is interrupted for more than one minute, a major alarm is raised.
  - The TN795 processor will attempt to shut the system down gracefully.

## TN795 processor circuit pack

The TN795 Processor circuit pack is the heart of DEFINITY ONE. It uses Microsoft Windows NT as its operating system, allowing for graphical user interaction, network connections, standard applications, and coresidency and multitasking of applications. It is always found in slot 2 of the carrier (See [Figure1-1 on page1-8](#)).

The TN795 features include:

- Dual processor complex consisting of an Intel Pentium and Motorola processors
- 16 Mbytes of FLASH PROM for software text
- 128 Mbytes of DRAM for translations and other data.
- RS232 port for the external modem

The DEFINITY ONE uses an external modem for alarm reporting to INADS and remote access. Approved modems include:

- U. S. Robotics Model 839 Sportster 33.6 Fax Modem (shipped with the DEFINITY ONE system)

This modem has a slightly different initialization string from other modems used with other DEFINITY products. Modem administration is accomplished using Windows NT.

- Connectors for local devices (keyboard, mouse, and monitor)
- An interface for LAN connections

## Features unique to the TN795 processor

- The following LEDs are not provided on the TN795:
  - WARNING LED (amber)

If there is a warning, consult the alarm log with the **display alarms** command. More details on the processor LEDs can be found in the [“TN795 processor circuit pack LEDs” on page 1-34](#).

- ACK LED (green)
- Processor and memory tests are no longer supported. Use the test board command to test the TN795. See [“test board” on page 4-237](#) for more information.

## Reliability options

The DEFINITY ONE system does not support either high- or critical-reliability duplication or expansion options.




Figure 1-1. Compact Modular Cabinet (CMC) slot configuration

## Circuit packs

All circuit pack slots in the Compact Modular Cabinet (CMC) are “universal slots.” That is, any slot can contain any type of circuit pack (port, control, or service), hence the absence of the purple and white slot coding found on other DEFINITY products. The only requirements for slot allocation are:

- Service circuit packs listed in [Table 1-1](#) are the only packs allowed in the CMC. These “universal” service packs can be located in any slot numbered 3-10.
- A TN744D Call Classifier/Tone Detector circuit pack is required in DEFINITY ONE Release 2.0. This circuit pack can be installed into any slot, although slot 3 is preferred.

**WARNING:**

The TN795 Processor circuit pack must be located slot 2. [Figure 1-1 on page 1-8](#) also shows the PCMCIA disk drive location

### Allowable and non-allowable circuit packs for CMC

[Table 1-1](#) lists the circuit packs allowable with DEFINITY ONE Release 2.0

**Table 1-1. Circuit packs and circuit modules**

Apparatus code	Name	Allowable
650A	AC Power Unit	Yes
982LS	Current Limiter	No
CFY1B	Current Limiter	No
CPP1	Memory Expansion	No
ED-1E546 (TN2208) (TN2170)	CallVisor Adjunct-Switch Application Interface (ASAI) over the DEFINITY (LAN) Gateway R1	No
J58890M-1 (TN801)	CallVisor ASAI/Call Visor PC/LAN over the DEFINITY LAN Gateway Release 2.0	No
NAA1	Fiber Optic Cable Adapter Circuit Pack	Yes
TN417	Auxiliary Trunk	Yes
TN419B	Tone-Clock	No
TN420B/C	Tone Detector	No

*Continued on next page*

1 Maintenance Concepts for DEFINITY ONE  
Circuit packs

1-10

Table 1-1. Circuit packs and circuit modules — *Continued*

Apparatus code	Name	Allowable
TN429/B/C/D	Analog Direct Inward/Outward Dialing (DIOD) Central Office Trunk	Yes
TN429C	Analog Central Office Trunk	Yes
TN429D	Analog DIOD Trunk - Analog Loop Start	Yes
TN433	Speech Synthesizer	Yes
TN436B	Direct Inward Dialing Trunk	Yes
TN437B	Tie Trunk Australia (future availability)	Yes
TN438B	Central Office Trunk	Yes
TN439	Tie Trunk	Yes
TN447	Central Office Trunk	Yes
TN457	Speech Synthesizer	Yes
TN459B	Direct Inward Dialing Trunk	Yes
TN464F	DS1 Interface - T1, 24 Channel - E1, 32 Channel	Yes
TN465B/C	Central Office Trunk	Yes
TN467	Analog Line	Yes
TN468B	Analog Line	Yes
TN479	Analog Line	Yes
TN553	Packet Data Line	Yes
TN556C/D	Integrated Services Digital Network -Basic Rate Interface 4-Wire S/T-NT Interface (ISDN-BRI)	Yes
TN568	DEFINITY AUDIX Slim	No
TN570B/C	Expansion Interface	No
TN572	Switch Node Clock	No
TN573B	Switch Node Interface	No
TN574	DS1 Converter - T1, 24 Channel	No
TN577	Packet Gateway	No
TN722B	DS1 Tie Trunk	Yes
TN725B	Speech Synthesizer	Yes
TN726B	Data Line	Yes

*Continued on next page*

Table 1-1. Circuit packs and circuit modules — *Continued*

Apparatus code	Name	Allowable
TN735	Multibutton Electronic Telephone (MET) Line	Yes
TN742	Analog Line	Yes
TN744B/C	Call Classifier	No
TN744D	Call Classifier - Detector	Yes
TN746B	Analog Line	Yes
TN747/B	Central Office Trunk	Yes
TN748B/C/D	Tone Detector	No
TN750B	Announcement	No
TN750C	Announcement	Yes
TN753/B	Direct Inward Dialing Trunk	Yes
TN754/B/C	Digital Line 4-Wire DCP	Yes
TN755/B	Neon Power Unit	No
TN756	Tone Detector/Generator	No
TN758	Pooled Modem	Yes
TN760B/C/D/E	Tie Trunk	Yes
TN762/B	Hybrid Line	Yes
TN763B/C/D	Auxiliary Trunk	Yes
TN765	Processor Interface	No
TN767B/C/D/E	DS1 Interface - T1, 24 Channel	Yes
TN768	Tone-Clock	No
TN769	Analog Line	Yes
TN771/D	Maintenance/Test	No
TN772	Duplication Interface	No
TN775/B/C	Maintenance	No
TN776	Expansion Interface	No
TN777B	Network Control	No
TN778	Packet Control	No
TN780	Tone-Clock	No

*Continued on next page*

1 Maintenance Concepts for DEFINITY ONE  
Circuit packs

1-12

Table 1-1. Circuit packs and circuit modules — *Continued*

Apparatus code	Name	Allowable
TN787F/G/H/J/K	Multimedia Interface	No
TN788B	Multimedia Voice Conditioner	No
TN789	Radio Controller	Yes
TN790B	Processor	No
TN791	Analog Line	Yes
TN792	Duplication Interface	No
TN793	Analog Line, 24-Port, 2-Wire	Yes
TN794	Network Control/Packet Interface (NetPkt)	No
TN795	Processor	Yes
TN798B	Processor	No
TN799/B	Control LAN (C-LAN)	Yes
TN801	LAN Gateway Interface	No
TN802/B	Internet Protocol (IP) Trunk	Yes
TN1648/B	System Access/Maintenance	No
TN1650B	Memory	No
TN1654	DS1 Converter - T1, 24 Channel/E1, 32 Channel	No
TN1655	Packet Interface	No
TN1656	Tape Drive	No
TN1657	Disk Drive	No
TN2135	Analog Line	Yes
TN2136	Digital Line 2-Wire DCP	Yes
TN2138	Central Office Trunk	Yes
TN2139	Direct Inward Dialing Trunk	Yes
TN2140B	Tie Trunk - Hungary, Italy	Yes
TN2144	Analog Line	Yes
TN2146	Direct Inward Dialing Trunk	Yes
TN2147C	Central Office Trunk	Yes
TN2149	Analog Line	Yes

*Continued on next page*

Table 1-1. Circuit packs and circuit modules — *Continued*

Apparatus code	Name	Allowable
TN2180	Analog Line	Yes
TN2181	Digital Line 2-Wire DCP	Yes
TN2182/B	Tone-Clock - Tone Detector and Call Classifier	No
TN2183	Analog Line	Yes
TN2184	DIOD Trunk	Yes
TN2185/B	ISDN-BRI 4-Wire S/T-TE Interface (Trunk Side)	Yes
TN2198	ISDN-BRI 2-Wire U Interface	No
TN2199	Central Office Trunk	Yes
TN2202	Ring Generator	No
TN2207	DS1 Interface - (T1) 24 Channel and (E1) 32 Channel	Yes
TN2210	Tone Generator	No
TN2214/B	Digital Line, 24-Port, 2-Wire DCP - Category B only	No
TN2215	Analog Line, 16-Port 2-Wire - Category B only	No
TN2224/B	Digital Line, 24-Port, 2-Wire DCP	Yes
TN2238	ATM Trunk Interface (Multi-Mode)	No
TN2242	TTC Japanese 2Mbit Trunk	Yes
TN2301	Survivable Remote Logic Switch	No
TN2305	Asynchronous Transfer Mode (ATM) Trunk	Yes
TN2306	ATM Interface (Single-Mode)	No
TN2308	Direct Inward Dialing Trunk	No
TN2464	DS1 Interface - T1, 24 Channel - E1, 32 Channel	Yes
TN2793/B	Analog Line 24-Port	Yes

## Maintenance objects

---

The maintenance subsystem is partitioned into separate entities called maintenance objects (MOs). A maintenance object can be:

- An individual circuit pack
- A hardware component that is part of a circuit pack
- An entire subsystem
- A set of monitors
- A process (or set of processes)
- A combination of processes and hardware

Each MO is referred to by an upper-case, mnemonic-like name that serves as an abbreviation and for the MO. For example, "CO-TRK" stands for "Central Office TRunk."

"Maintenance names" are recorded in the Error and Alarm logs. Individual copies of an MO are assigned an address that defines the MO's physical location in the system. These locations display as the `Port` field in the Alarm and Error logs and as output of various commands such as **test board**, **busy tdm-bus**, and so forth.

[Chapter 5, "Maintenance Objects for DEFINITY ONE"](#) includes the complete set of DEFINITY ONE MOs and maintenance strategies.

## Alarm and error reporting

---

During normal operations, software or firmware may detect error conditions pertaining to specific MOs. The system automatically attempts to either fix or circumvent these problems. Errors are detected in two ways:

- For "in-line" errors, firmware on the component detects the occurrence of an error during ongoing operations.
- For other types of errors, a "periodic test" or a "scheduled test" started by the software detects the error.

The technician can run periodic and scheduled tests on demand by using the maintenance commands described in [Chapter 4, "Maintenance Commands for DEFINITY ONE"](#), and the maintenance objects in [Chapter 5, "Maintenance Objects for DEFINITY ONE"](#).

When an error is detected, the maintenance software puts the error in the Error Log and increments the error counter for that error. When an error counter is "active" (greater than zero), there is a maintenance record for the MO. If a hardware component incurs too many errors, an alarm is raised.

## Alarm classifications

---

Alarms are classified depending on their effect on system operation:

- **MAJOR** alarms identify failures that cause a critical degradation of service. These alarms require immediate attention.
- **MINOR** alarms identify failures that cause some service degradation but that do not render a crucial portion of the system inoperable. **MINOR** alarms require attention. However, typically a **MINOR** alarm affects only a few trunks, stations, or a single feature.
- **WARNING** alarms identify failures that cause no significant degradation of service or equipment failures external to the switch. These failures are not reported to INADS or to the attendant console.
- **ON-BOARD** problems originate in the circuitry on the alarmed circuit pack.
- **OFF-BOARD** problems originate in a process or component that is external to the circuit pack.

[Chapter 6, “DEFINITY ONE NT Log Events and Alarms”](#) describes all alarms.

## Maintenance testing

---

Maintenance testing can reduce most troubles to the level of a field-replaceable component (usually a circuit pack). The affected circuits can be identified by:

- LEDs on the circuit packs
- Reports generated by the system software.

The background maintenance tests in the system are divided into three groups:

- **Periodic** tests:
  - Usually performed hourly by maintenance software
  - Nondestructive (not service-affecting)
  - Can be run during high-traffic periods without interfering with calls
- **Scheduled** tests:
  - Usually performed daily
  - More thorough than periodic testing
  - Destructive (service-affecting)
  - Run only during off-hours to avoid service disruptions

**■ Fixed-interval tests:**

- Performed at regular time intervals and cannot be administered
- Run concurrently with periodic maintenance
- The MOs that run fixed-interval testing are listed below:

Maintenance Object	Interval (min)
TDM-BUS	10
TONE-PT	10

Other kinds of maintenance testing are referred to as **Demand** tests:

- Include periodic tests plus other tests required only when trouble occurs
- Can be run by the system when it detects a need or by maintenance personnel in trouble-clearing activities
- Using the management terminal, maintenance personnel can “demand” the same tests that the system initiates in periodic or background testing.
- Some nonperiodic demand tests are destructive (service-disrupting) tests, and are identified in boldface type.

## Layers

---

The Open System Interconnect (OSI) model for data communications contains seven layers, each with a specific function. Communications to and through the system concern themselves only with layers 1 and 2 of the model.

### Layer 1

The *physical layer*, Layer 1, covers

- The physical interface between devices
- The rules by which bits are passed

Examples of physical layer protocols are RS-232, RS-449, X.21, DCP, and DS1.

## Layer 2

Layer 2, the *data-link layer*, refers to code created and interpreted by the DCE.

1. The originating equipment sends blocks of data appended with the necessary codes for:
  - Synchronization
  - Error control
  - Flow control
2. The destination equipment:
  - Checks the physical-link reliability
  - Corrects any transmission errors
  - Maintains the link
3. When a transmission reaches the destination equipment, it strips any layer-2 information the originating equipment may have inserted. The destination equipment only passes to the destination DTE equipment the information sent by the originating DTE equipment.

The originating DTE equipment can also add layer-2 code to be analyzed by the destination DTE equipment. The DCE equipment treats this layer as data and passes it along to the destination DTE equipment as it would any other binary bits. Refer to [Figure 1-2](#).

## Layers 3 to 7

Layers 3 to 7 (and the DTE-created layer 2) are embedded in the transmission stream and are meaningful only at the destination DTE equipment. Therefore, they are shown in [Figure 1-2](#) as “user-defined,” with no state changes until the transmission stream reaches its destination.

1 Maintenance Concepts for DEFINITY ONE  
Maintenance testing




Figure 1-2. Data transmission states

## DEFINITY LAN Gateway maintenance

The DEFINITY LAN Gateway (DLG) provides connectivity for ASAI to CentreVu CT without using the C-LAN board. Connectivity is provided between DEFINITY ONE and CentreVu CT using the interface on the TN795 Circuit Pack or (optionally) the C-LAN TN799 Circuit Pack.

A CLAN board is normally used only if a private LAN is required for security reasons. For this release of the DLG feature, only one of the interfaces (TN795 or C-LAN) can be used on the same system.

The *status asai/adjunct-ip-link* form is used to obtain a summary of the connections to the built-in DLG feature. See [“ADJLK-IP \(ASAI Adjunct IP Link\)” on page 5-2](#). See [Figure 1-3](#). The form is provided here for reference only.





Figure 1-3. DLG links status

When a service is administered on the *ip-services* form, the service type and link number are combined into a single keyword entry, for example, ADJLK1. However, on the above form the link number (1 in ADJLK1) is shown separately from the link or service type (ADJLK in ADJLK1). The *client's* link number is also shown for convenience. When using the TN801, this value is administered in DEFINITY as well as in the ASAI client. When using the DLG function, the client link number, assigned only in the client, is obtained by DEFINITY from the protocol and displayed on this form. It is not administered within DEFINITY.

## DLG test

---

A test of these links is supported. The test causes a TCP-Tunnel Heartbeat message to be sent from DEFINITY and a Heartbeat Reply message to be returned from the client. See [Figure 1-4](#). The form is provided here for reference only.



```
Telnet - albania
Connect Edit Terminal Help
test adjunct-ip-link 1

                                TEST RESULTS

Port      Maintenance Name  Alt. Name  Test No.  Result      Error Code
1         ADJLK-IP          1365      FAIL       5

Command successfully completed
Command:
F1=Cancel  F2=Nxt Page  F3=Submit  F4=Help  Esc p=Prv Page  Esc r=Refresh
```

Figure 1-4. DLG links test

## Busyout and release

---

Both busyout and release-from-busy commands are supported. The busyout command causes a message to be sent to the client to stop using the link. See [“busyout adjunct-ip-link” on page 4-4](#).

The Release commands cause a message to be sent to the client indicating that link can again be used. See [“busyout adjunct-ip-link” on page 4-4](#). These commands do NOT busy out the TCP/IP connection. See [Figure 1-5](#).




Figure 1-5. DL links busyout results




Figure 1-6. DLG release-from-busyout results

## Processor C-LAN maintenance

The Processor C-LAN provides TCP/IP connectivity to DEFINITY ONE using the Ethernet interface on the TN795 Processor Board. This is similar to the use of the C-LAN Board, except that the processor interface is specified. The Processor C-LAN connectivity is an option for specified applications, such as TCP/IP, DCS, EMS, and the DLG feature.

### Administration and maintenance


Before the LAN interface on the TN795 processor card can be used, it must be enabled on the customer options form. See [Figure 1-7](#). The form is provided here for reference only.

```
Telnet - albania
Connect Edit Terminal Help
change system-parameters customer-options Page 3 of 7
OPTIONAL FEATURES
  Hospitality (Basic)? y
  Hospitality (G3U3 Enhancements)? y
    H.323 Trunks? y      Processor and System MSP? y
    IP Stations? y      Private Networking? n
    ISDN Feature Plus? n Processor Ethernet? y
    ISDN-BRI Trunks? y Restrict Call Forward Off Net? y
    ISDN-PRI? y        Secondary Data Module? y
                        Station and Trunk MSP? y
  Malicious Call Trace? y
  Mode Code for Centralized Voice Mail? n
  Mode Code Interface? y      Tenant Partitioning? n
  Multifrequency Signaling? y Terminal Trans. Init. (TTI)? y
  Multimedia Appl. Server Interface (MASI)? n
  Multimedia Call Handling (Basic)? y Time of Day Routing? y
  Multimedia Call Handling (Enhanced)? y Uniform Dialing Plan? y
  Personal Station Access (PSA)? y Usage Allocation Enhancements? y
                        Wideband Switching? n
                        Wireless? y
(NOTE: You must logoff & login to effect the permission changes.)
F1=Cancel F2=Nxt Page F3=Submit F4=Help Esc p=Prv Page Esc r=Refresh
```

Figure 1-7. Processor ethernet customer option entry

The status, busy, and release-from-busy commands are available for the Processor Ethernet interface.

For the status command, see [“status asai/adjunct tcp/ip link” on page 4-140](#). See [Figure 1-8 on page 1-24](#). This form is provided here for reference only.



```
Telnet - albania
Connect Edit Terminal Help
status processor-ip-interface Page 1 of 2
PROCESSOR IP INTERFACE STATUS

      Status: connected
      Enabled: yes
Source IP Address: 135.9.142.95
      Subnet Mask: 255.255.255.0
Broadcast Address: 135.9.142.255
Maintenance Busy? no
      Active Channels: 0

F1=Cancel F2=Nxt Page F3=Submit F4=Help Esc p=Prv Page Esc r=Refresh
```

Figure 1-8. Processor interface status

For the busyout command, see [“busyout adjunct-ip-link” on page 4-4](#). See [Figure1-9 on page1-25](#). This form is provided here for reference only.

```

Telnet - albania
Connect Edit Terminal Help
busyout processor-ip-interface

                                COMMAND RESULTS

Port      Maintenance Name  Alt. Name  Result  Error Code
P         PEI-PT                PASS      0

Command successfully completed
Command:
F1=Cancel  F2=Nxt Page  F3=Submit  F4=Help  Esc p=Prv Page  Esc r=Refresh
    
```

Figure 1-9. Processor busyout command results

For the release-from-busy command, see [“busyout adjunct-ip-link” on page 4-4](#). See [Figure 1-10](#). This form is provided here for reference only.

COMMAND RESULTS			
Maintenance Name	Alt. Name	Result	Error Code
PEI-PT		PASS	0

Figure 1-10. Processor release from busyout command

## Media processor

---

The MedPro board is the TN802B version of the MAPD circuit pack, when operating as a media processor. See [“MEDPROPT \(TN802 MED PRO DSP PORT\)” on page 5-782](#).

## Accessing DEFINITY ONE™ for maintenance

---

There are several ways to connect to the DEFINITY ONE system.

- Web browser interface
- Telnet session
- pcAnywhere
- DEFINITY Site Administration

This section describes these types of interfaces and when it is appropriate to use them. For more information, see Chapter 2, “Connectivity and Access to DEFINITY ONE” in *DEFINITY ONE Communications System Release 2.0 Installation and Upgrades* (555-233-109).

### Web browser interface

---

You can perform basic maintenance and administration functions on the DEFINITY ONE from a standard web browser (such as Netscape Navigator).

- Backup
- Restore
- Restart
- Start pcAnywhere host and client applications.
- Download software
  - DEFINITY Site Administration (DSA)
  - DEFINITY Message Manager

To use the web browser interface, see “Via a Web browser session” in Chapter 2, “Connectivity and Access to DEFINITY ONE” in *DEFINITY ONE Communications System Release 2.0 Installation and Upgrades* (555-233-109).

## Telnet session

---

Opening a Telnet session to the DEFINITY ONE system allows you to:

- Open a command line interface
- Run the AUDIX administration application

The Telnet session provides access to all areas of DEFINITY ONE maintenance and administration.

You will need special permissions to open a Telnet session to the DEFINITY ONE. Access requires an encrypted response to a login challenge.

## Command line interface

The command line interface is available in the UNIX bash shell using the bash command. The bash shell accepts the Global Administration Subsystem (GAS) commands that are listed in [Chapter 3, "Global Administration Subsystem Commands"](#). Use this interface to:

- Reset system
- Shutdown system
- Install license file (see note below)
- Startup/shutdown system IP addresses
- Enable Individual application (or process)
- Verify system alarm status
- Display and clear global alarms
- Turn global alarm reporting of INADS on and off
- Verify software versions



### NOTE:

Refer to the DEFINITY ONE™ Communications System Release 2.0 Installation and Upgrades document, Chapter 3, System Initialization, Section, "Obtaining a License."

## DEFINITY SAT

The DEFINITY SAT screens are enabled from a Telnet session. This acts in the same manner as a SAT terminal connected to any other DEFINITY system.

## AUDIX application

For a laptop, you can run the command line AUDIX application, using the AUDIX command.

## pcAnywhere

pcAnywhere is required to set the time zone and to install software. It may be used for other windows-related functions, such as managing logins or mapping drives. The application allows a client PC to access a host computer using the standard Microsoft Windows NT interface and to access the following functions:

- Set date, time, time zone
- Map network drives
- Activate AUDIX logins and set appropriate passwords for the customer um/sa
- Upgrades

Activate and access pcAnywhere through the web browser, Telnet, LAN or modem connection.

## DEFINITY site administration

Opening a DSA session provides access to all areas of DEFINITY ONE maintenance and administration. DSA performs most of the switch administration activities (except for monitor commands). In DSA you can:

- Start the session as a normal application from Windows at the start button.
- Enable your browser.

The Lucent Services representative uses the logins Lucent1, Lucent2, or Lucent3 and the NT password/ASG challenge.

## Initialization and recovery

---

When the system is initially powered up, or when an existing system experiences a catastrophic fault that interrupts its basic functions, the system either initializes or reboots.

### LED boot sequence

---

See [“LED interpretation” on page 1-33](#) for a description of the LEDs in the DEFINITY ONE system.

### TN795 processor circuit pack

When power is first applied to DEFINITY ONE, or when the system reboots, the LEDs on the TN795 circuit pack will light according to this sequence:

1. All lights on the TN795 will rapidly blink in sequence, from bottom to top (also known as “racing lights”). All lights will then be off.
2. Within one minute, the second light from the top will blink green:
  - When the LED is more on than off indicates BIOS loading
  - More off than on indicates NT loading
3. The third LED from the top will blink amber to indicate application firmware loading.
4. When firmware is loaded, the LEDs will blink in sequence again (racing lights), then all LEDs will light and then go off.

The DEFINITY ONE system is now under normal operating conditions. When the system is operating normally you will see:

- The amber LED (third from the top) will blink quickly once every 10 seconds, indicating the firmware/NT watchdog processes are running.
- The CLOCK LED will blink once every four seconds.

Any other LEDs that are illuminated indicate an alarm or problem with DEFINITY ONE. For more information about alarms, see [Chapter 6, “DEFINITY ONE NT Log Events and Alarms”](#).




Figure 1-11. TN795 processor panel

### Other circuit packs

You may see some LEDs on power up on the other circuit packs. Under normal operation, you should not see LEDs lit on the circuit packs, with the following exception: A solid green LED on any circuit pack indicates that diagnostic tests are being executed on that circuit pack.

## DEFINITY initialization

---

Upon initialization, no forms (not even Customer Options) are available until the Offer Category is set. (The remote INADS channel is available.) To set the customer options, login as Lucent 1 and do the following:

1. Enter **change system-parameters offer-options** (Lucent 1, 2, and 3 logins only) and the following form displays:

```
change system-parameters offer-options                               Page 1 of 1
                                                                    OFFER OPTIONS
Offer Category: A
Activate Offer? y
```

### Field descriptions

Offer category	Only Type <b>A</b> is allowed.
Activate offer?	Type <b>y</b> if the entry for Offer category is correct and press Tab. Type <b>n</b> if there is an error in the Offer category field and press Tab. Re-enter the correct Offer Category.

2. After these two fields are filled and you press Enter, the system displays a message in the History window.
3. Select the Submit option to submit the form.
4. Use the **save translations** command to make the changes permanent.



#### **CAUTION:**

*To avoid potential loss of service, ensure that your system's translations are protected by saving them to the PCMCIA disk.*

### System reset

---

You can reset the DEFINITY ONE system from either the web browser interface or the UNIX bash shell from a Telnet session.

## DEFINITY reset (recovery)

---

There are several less severe resets available to the system that allow it to recover from disrupting errors. These resets can be user initiated with the **reset system n** command (where *n* is the reset level), and automatically initiated by system software in response to certain error conditions. These commands are used to manually restart the system at various levels, depending on the required test activity. The reset system commands are discussed below.

A system is reset due to a loss of power, or through:

- Reset commands at the administration terminal
- Maintenance software, from which the system can reset itself. (This process starts when certain software and hardware errors are detected by the software.)



### WARNING:

*When the system is rebooted or reset at level 2, 3, 4, or 5, all voice terminal and attendant console features are adversely affected. Users should be advised of services that are lost and that, as a result, must be reactivated. See ["Removing power" on page 2-11](#).*

The administration terminal display and circuit pack LEDs indicate the progress of the recovery process. See ["LED interpretation" on page 1-33](#) for more information.

## Reset system 1 (DEFINITY warm start)

---

- This recovery takes about 60 seconds.
- All software is reset.
- All stable phone calls remain up.
- In-progress calls are dropped.
- No new calls can be made during this time.

## Reset system 2 (DEFINITY cold start)

---

The following are reset:

- All software
- TDM Bus
- All Port circuit packs

All telephone sessions are dropped. Telephones begin to reconnect to the switch within 60 seconds. In a large system, reconnection of all telephones may take up to five minutes.

- 1 Maintenance Concepts for DEFINITY ONE  
System reset (system shutdown on demand from a bash session)

1-33

### **Reset system 3 (DEFINITY reboot)**

---

This is the same as Reset System 4 (see below). This command is retained for consistency with other DEFINITY products.

### **Reset system 4 (DEFINITY reboot)**

---

- Emergency Transfer is invoked in this reset.
- System processes are reloaded from flash disk into memory.
- All port circuit packs are reset.
- All telephone sessions are dropped.

Telephones begin to reconnect to the switch within 60 seconds. In a large system, reconnection of all telephones may take up to five minutes.

### **Reset system 5 (Extended DEFINITY reboot)**

---

This is the same as Reset System 4 (see above). This command is retained for consistency with other DEFINITY products.

## **System reset (system shutdown on demand from a bash session)**

---

- System Reboot `r(eboot nice)` — complete system shutdown followed by an automatic reboot. Use after updating the system or changing system parameters
- System Shutdown (`shutdown system`) — complete system shutdown without an automatic reboot. Typically used for planned shutdown. See Appendix D for shutdown and restart actions and Appendix G for bash commands in *DEFINITY ONE™ Communications System Release 2.0 Installation and Upgrades (555-233-109)*.

## **LED interpretation**

---

The LEDs indicate the status of various maintenance components in the system. LEDs are located on:

- The attendant console
- All circuit packs in the switch cabinets
- Customer-designated voice terminals (option)

The following LEDs are included in the system:

- [“TN795 processor circuit pack LEDs”](#)
- [“Attendant console LEDs”](#)
- [“Circuit pack status LEDs”](#)
- [“Power supply LEDs”](#)

## TN795 processor circuit pack LEDs

The front pane has two groups of LEDs. One group indicates the status of the pack, and the other group (which includes the Major, Minor, and Warning alarms described in the [“Alarm and error reporting”](#) section) reflects maintenance conditions in the entire system. See [Figure1-12 on page1-38](#).



**NOTE:**

Alarms on the SW-CTL, PKT-INT, PR-MAINT, TRAN-STO, PR-TN-BD, TONE-PT, TDM-CLK, PR-SSP and PR-ADX maintenance objects are indicated by the red LED on the Processor circuit pack.

**Table 1-2. TN795 Processor Circuit Pack LEDs**

Red (alarm)	Alarm--The system has detected a fault in tis circuit pack.
Green Test	Test--the system is running tests on this circuit pack.
Amber	Handshake--In an operating system, this LED indicates that the handshaking between the firmware and the NT operating system is occurring by flashing briefly once every 10 seconds
Amber	PCMCIA--The flash disk is in use
Red	Major Alarms
Red	Minor Alarms
Amber	Clock--Blinks every 4 seconds
Red	EX-MFR-- Indicates emergency transfer has been invoked.
Green	OK Remove--Indicates that it is OK to remove the TN795 processor circuit pack.



**NOTE:**

If the AC power cord is unplugged, the emergency transfer feature invokes, however the EMERGENCY TRANSFER LED (red) is not lit due to loss of AC power.



**WARNING:**

**DO NOT REMOVE** the TN795 circuit pack unless the **OK to REMOVE LED** is illuminated. Failure to heed this warning may result in loss of data and/or damage to equipment.



**WARNING:**

When the TN795 is replaced, a new license file must be downloaded to the system before the system will become operational. Refer to "Obtaining a License File" in Chapter 3 of *DEFINITY ONE™ Communications System Release 2.0 Installation and Upgrades (555-233-109)*.

The following table summarizes the TN795 circuit pack LED states.

Table 1-3. TN795 circuit pack states

		Boot Sequence = 3 min., 45 sec.							Shutdown Sequence 1-3min		Other		
LED name	LED color	Power-on reset	860 core test in progress	860 core test finished, RM initialized	PC BIOS boot	PC OS boot	Firmware download	Jump to application firmware	SPE up	Shutdown in progress	Shutdown complete	860 core test failed	Pentium BIOS update
TN795 CP A Alarm	red	on	on	Racing LEDs	on	on	on	Racing LEDs	sw	on	on	on	on
TN795 Test	green	off	on		flash 1	flash 3	off		sw	sw	off	on	flash 2
TN795 In Use	yellow	off	off		off	off	flash 2		flash 4	sw	off	on	flash 2
PCMCIA	yellow	on	on		sw	sw	sw		sw	sw	on	off	on
Major Alarm	red	off	off		off	off	off		sw	sw	off	off	off
Minor Alarm	red	off	off		off	off	off		sw	sw	off	off	off
Clock Status	yellow	off	off		off	off	off		clk	clk	off	off	off
ETR	red	on	on		on	on	on		sw	sw	on	on	on
OK to Remove	green	off	on		on	off	off		off	flash3	on	on	off
_____	_____	_____	(a) 40 sec.		(b) 40 sec.	(c) 80 sec.	(d) 30 sec.	(e)					

- flash1— 800ms ON, 200ms OFF
- flash2— 500ms ON, 500ms OFF
- flash3— 200ms ON, 800ms OFF
- flash4— 200ms OFF on every sanity heartbeat
- flash5— 1 sec ON, 1 sec OFF
- sw— Software Controlled
- clk— Similar to the TN2182 Tone/Clock LED



**NOTE:**

When system status is “up” you will go through stat 1-8. After 8, DEFINITY ONE will start up in 20 seconds and you should be able to dial. AUDIX continues to initialize for about 5 minutes.

## Legend

1. Power-on reset.
  2. 860 Core test in progress. Testing ROM, RAM, 860, etc. (usually lasts about 35 seconds).
  3. 860 Core test finished successfully. Remote maintenance initialized.
  4. Pentium released from reset. Waiting for Windows NT to start booting.
  5. Booting Windows NT. Waiting for application firmware download.
  7. Jump to application firmware. Remote maintenance initialized (this time in application firmware).
  8. SPE is up. The TN795 circuit pack In Use yellow LED turns off for 200ms every time (approximately every 10 seconds) firmware receives handshake from software. This is the heartbeat that software and firmware is alive and talking. DEFINITY ONE software starts up.
  9. Shutdown is in progress. It's OK to Remove green LED flashes. Don't remove the circuit pack yet.
  10. Shutdown is complete. It's safe to remove the circuit pack.
  11. 860 Core test failed. Try power cycling the circuit pack. Replace circuit pack if it keeps failing.
  12. Pentium BIOS update mode is activated.
  13. Entering factory diagnostic mode. Wait about 35 seconds for 860 Core test to finish.  
In factory diagnostic mode.
-




Figure 1-12. LED indicators on the TN795 processor circuit pack

## Attendant console LEDs

The console has two red LEDs, labeled ALM and ACK. The left LED lights steadily when there is a Major or Minor alarm at the switch cabinet. The right LED lights steadily if the alarm has been successfully reported to INADS. If the system is unable to report the alarm to INADS, the LED flashes; signaling the attendant to call INADS and report the alarm.

## Circuit pack status LEDs

---

Each circuit pack has three LEDs on the front panel visible at the front of the carrier. On all circuit packs, except the 650A Power Unit, the LEDs indicate:

1. Red (alarm) — If the circuit pack is communicating with the system, the system has detected a fault in this circuit pack. An on-board alarm for this circuit pack is displayed in the Alarm Log.

The circuit pack also lights this LED when either the circuit pack has not yet initialized communication with the system or when the circuit pack loses contact with the system and stops functioning (circuit pack is said to be “in reset”). In these cases, there may not be an alarm in the Alarm Log. To determine if the red LED is lit because the circuit pack is not in contact with the system, issue the **list configuration board PCSS** command, where PCSS refers to the slot containing this circuit pack. If the system does not detect the circuit pack, this command returns `Identifier not assigned` or `no board`.

If the circuit pack has just been inserted, the system may still be initializing the circuit pack. If, after 5 minutes, the circuit pack still has not initialized communications with the system, check the MO for any special instructions (for example, EPN Maintenance circuit pack can stop EXP-INTF circuit pack from initializing). If the MO does not provide the needed information, perform the following steps:

- Check the Error Log for TONE-BD and TDM-BUS errors. Enter **test tdm P** where P is the port network containing the relevant slot. Refer to [“Restarting Nonfunctioning Port Circuit Packs” on page 5-1119](#) in the general description of the [“TDM-BUS \(TDM Bus\)” on page 5-1116](#). Enter **test tone-clock PC**, where P is the network containing the relevant slot, and C is the carrier containing the relevant slot. Follow appropriate sections for any TONE-BD and TDM-BUS errors.
- Reseat the suspect circuit pack.



### WARNING:

*Reseating the TN795 may be very destructive.*



### WARNING:

*When the TN795 is replaced, a new license file must be downloaded to the system before the system will become operational. Refer to “Obtaining a License File” in Chapter 3 of DEFINITY ONE™ Communications System Release 2.0 Installation and Upgrades (555-233-109)*

Wait 5 minutes. Then issue the **list configuration board PCSS** command. If the result indicates that the system still has not registered the circuit pack, go to next step.

- Try to insert the circuit pack into a different slot and try to insert a different circuit pack into the suspect slot (provided the maintenance documentation for this circuit pack does not warn against either of these actions).
  - If the system seems to be functioning correctly, but the circuit pack does not start communicating with the system, replace the circuit pack.
2. Green (test) — the system is running tests on this circuit pack.
  3. Yellow (busy) — indicates that the circuit pack is in use.



**NOTE:**

A port circuit pack also lights its red LED when it performs initialization tests (for example, when the circuit pack is initially inserted into the system). If all initialization tests pass, the red LED is turned off. If any initialization tests fail, the red LED remains lighted and the circuit pack is not placed into service.

During the various states of operation (start-up testing, normal operation, circuit failure, and so forth) circuit pack status LED indications appear as shown in [Table 1-4](#).

**Table 1-4. Control and port circuit pack status LEDs**

Equipment type	LED	Description
Port Circuit Packs	Red	On briefly during power up, circuit pack reseating, resetting, and system reset. Steadily on if circuit pack fails start-up test or fails while in use. Off during normal operation.
	Green	Briefly on during circuit pack testing following power up, circuit pack reseating, and system reset. On during periodic, scheduled, and system technician demanded testing. Off during normal operation.
	Yellow	On when any port in the circuit pack is in use, otherwise, off.
Control Circuit Pack	Red	On briefly during power up and system reset. Steadily on if circuit pack fails start-up test or fails while in use. Off during normal operation.

**Table 1-4. Control and port circuit pack status LEDs — Continued**

Equipment type	LED	Description
	Green	On briefly during board testing following power up and system reset. Also on during periodic, scheduled, and system technician-demanded testing. Off during normal operation.
	Yellow	<p>Processor</p> <ul style="list-style-type: none"> <li>■ Lit during processor initialization.</li> <li>■ Lit during system initialization (stays lit until Emergency Transfer is turned off).</li> </ul> <p>Tone Detector/Generator</p> <ul style="list-style-type: none"> <li>■ Slow blinking when clock is in use; otherwise, off.</li> </ul>

## Power supply LEDs

[Table 1-5](#) shows the LED and alarm conditions for the 650A Power Supply. Ring voltage and neon bus output do not activate alarm status.

**Table 1-5. LED and alarm conditions**

Condition	LED status	Alarm state	Fan alarm
Normal	Red off; Yellow on	Open	Normal
No input power	Red off; Yellow off	Closed	No input power
DC output not present (except Neon)	Red on; Yellow off	Closed	DC output not present (except Neon)
Fan alarm	Red on; Yellow on	Closed	Fan alarm

## Logins and passwords

---

This section describes passwords and logins on the DEFINITY ONE system. Set Up and Use of Customer Logins

This chapter provides information about the setup and use of customer logins:

1. [“Customer access” on page 1-42](#)
2. [“Windows NT logins for the customer” on page 1-43](#)
  - [“NT login types for the customer” on page 1-43](#)
  - [“Enabling Windows NT customer logins” on page 1-48](#)
3. [“DEFINITY logins for the customer” on page 1-49](#)

## Customer access

---

In DEFINITY ONE Release 2.0, the Lucent Access Control (LAC) module allows access to a “shell” (=bash) using any valid Windows NT login. This enhancement allows a customer to use a login, such as NTADMIN, to access Windows NT via a “bash shell”. This feature is not intended to be used by Lucent Services personnel who continue to use the Lucent Services logins (lucent1, lucent2, lucent3).

In Release 1.0 the LAC module listened only on TCP port 23. A connection to this port produced different results depending on the login used. For example, a services login (lucent1, lucent2, lucent3) resulted in the “lac” prompt to select DEFINITY, Audix, or a Bash shell. An alias login, such as dinit, resulted in a DEFINITY SAT screen without a LAC prompt. This continues to be supported in Release 2.0, but is being deprecated in favor of the use of separate telnet ports for direct access to DEFINITY and AUDIX.

If the telnet session is established to TCP port 22, and the login has privileges to access DEFINITY, a connection is made directly to a DEFINITY SAT without a LAC prompt. If the caller logs off, the telnet session is terminated.

If the telnet session is established to TCP port 24, and the login has privileges to access AUDIX, a connection is made directly to an AUDIX Forms Controller administration screen without a LAC prompt. If the caller logs off, the telnet session is terminated.

The same logins are used with ports 22, and 24, as well as 23. The difference is that a direct connection is made to the appropriate application without a LAC prompt or having to use an alias login.

See Chapter 7 “DEFINITY Site Administration (DSA)”, in *DEFINITY ONE™ Communications System Release 2.0 Installation and Upgrades* (555-233-109).

## Windows NT logins for the customer

Several Windows NT login groups and associated logins are pre-installed for customer use from the factory. See [Table 1-6](#).

The login IDs in the last two columns of [Table 1-6](#) are for customer use. The following describes use and administration of these logins.

**Table 1-6. Windows NT logins**

Windows NT login group	Logins for customer use	
	User name	Default password
Administrators	NTadmin	NTadmin1
Guest - disabled	--	--
lucent	--	--
officeadmin	1	
officeuser	2	
Power Users	--	--
Users	browse vm sa	

1. To be administered
2. To be administered

### **WARNING:**

*The logins in the Lucent group of [Table 1-6](#) are for the exclusive use of Lucent Technologies Services personnel. These logins are established and updated automatically by Lucent software. DO NOT ALTER THESE LOGINS IN ANY MANNER. To do so may render the system unserviceable and may require a partial or complete reinstallation of the software by Lucent personnel.*

## NT login types for the customer

### Administrator login

- NTadmin

This is a standard Windows NT administrator account used to administer network parameters and similar functions.

## AUDIX logins

- browse

This login is used in the Voice Messaging application. See the INTUITY AUDIX documentation or [Table 1-7](#) for a list of commands accessible to the browse login. This login is disabled from the factory. It must be enabled and a password chosen before it can be used.

- vm

This login is used in the Voice Messaging application. See the INTUITY AUDIX documentation or [Table 1-7](#) for a list of commands accessible to the vm login. This login is disabled from the factory. It must be enabled and a password chosen before it can be used.

- sa

This login is used in the Voice Messaging application. It has full customer administration privileges. See the INTUITY AUDIX documentation or [Table 1-7](#) for a list of commands accessible to this login. This login is disabled from the factory. It must be enabled and a password chosen before it can be used.

 **NOTE:**

The stand-alone INTUITY AUDIX system login “sa” normally produces a menu. This feature is not supported on DEFINITY ONE. All logins result in a Forms Screen interface.

**Table 1-7. AUDIX commands versus logins for sa, vm, and browse**

Command	Login		
	sa	vm	browse
add	✓	✓	
audit	✓	✓	
change	✓	✓	
copy	✓		
display	✓	✓	✓
exit	✓	✓	✓
get	✓	✓	
help	✓	✓	✓
list	✓	✓	✓

*Continued on next page*

Table 1-7. AUDIX commands versus logins for sa, vm, and browse — *Continued*

Command	Login		
	sa	vm	browse
logoff	✓	✓	✓
print	✓	✓	✓
remove	✓	✓	
reset	✓		
test	✓	✓	✓
toggle	✓	✓	✓
trace	✓	✓	✓

## Customer Web access logins

The following login groups are used for web access:

- Officeadmin

Login IDs in this group are installed from the factory. This login group facilitates access via the DEFINITY ONE web interface. Group members select administrative privileges via the web interface. The NTadmin account is used to establish an account in this group. Generally, an account in the Officeadmin group is used to download DSA from the DEFINITY ONE Web page.

- Officeuser

Login IDs in this group are installed from the factory. This login facilitates download of client software, such as Message Manager. Group members have access for client download only. The NTadmin account is used to establish an account in this group. An Officeuser group account is generally used to download Message Manager from the DEFINITY ONE Web page.

- anonymous

The anonymous login is for very limited access via the web interface to load a software patch. See [Table 1-8 on page 1-46](#).

1 Maintenance Concepts for DEFINITY ONE  
Windows NT logins for the customer

1-46

Table 1-8. Web access rights for office admin. and office user access

Directory	Use	Login group	Permissions
c:\LucentWeb\Public	DEFINITY ONE Home Page	anonymous	read
		officeuser	read
		officeadmin	read
		administrators	full control
		lucent	full control
c:\LucentWeb\admin\audix\html	AUDIX networking HTML pages	anonymous	none
		officeuser	none
		officeadmin	read
		administrators	full control
		lucent	full control
c:\LucentWeb\admin\audix\cgi	AUDIX networking cgi scripts	anonymous	none
		officeuser	none
		officeadmin	execute
		administrators	full control
		lucent	full control
c:\LucentWeb\admin\user\html	Pages for non administrator users e.g. download	anonymous	none
		officeuser	read
		officeadmin	full control
		administrators	read
		lucent	full control
c:\LucentWeb\admin\user\cgi	cgi scripts for non administrator users. e.g. download	anonymous	none
		officeuser	execute
		officeadmin	execute
		administrators	full control
		lucent	full control
c:\LucentWeb\admin\html	Platform HTML pages	anonymous	none
		officeuser	none
		officeadmin	read
		administrators	read
		lucent	full control

Continued on next page

**Table 1-8. Web access rights for office admin. and office user access — Continued**

Directory	Use	Login group	Permissions
c:\LucentWeb\admin\cgi	platform cgi scripts	anonymous	none
		officeuser	none
		officeadmin	execute
		administrators	execute
		lucent	full control
c:\LucentWeb\AdminAll\html	Restricted html pages. e.g. activate pcAnywhere	anonymous	none
		officeuser	none
		officeadmin	none
		administrators	full control
		lucent	full control
c:\LucentWeb\AdminAll\cgi	Restricted html pages. e.g. activate pcAnywhere	anonymous	none
		officeuser	none
		officeadmin	none
		administrators	full control
		lucent	full control

## Enabling Windows NT customer logins

---

Only the Administrator can enable customer logins.

### Activate pcAnywhere

1. On a DEFINITY ONE LAN workstation enable a web browser and the DEFINITY ONE web page. Click **Administer System** on this web page and login as NTadmin using the default password. On the administration page click **Activate pcAnywhere**.

A pcAnywhere client must be installed on the workstation. This client may be purchased from a local supplier or Symantec Corporation. Alternately, a JAVA client may be downloaded from the DEFINITY ONE administration page, the same page the pcAnywhere host is activated in step 1.

2. Activate the pcAnywhere client on the workstation.
3. Login to the DEFINITY ONE system, using the NTadmin account.

### Setup login accounts

1. Start the NT user manager on the DEFINITY ONE desktop. Click (Start > Programs > Administrative Tools > User Manager)
2. Change the password for the NTadmin account.
3. Activate and set passwords for the browse, vm, and sa accounts. This also can be done via the command line tool net user. See "Lucent access controller bash commands" in *DEFINITY ONE Communications System Release 2.0 Installation and Upgrades (555-233-109)*
4. Create three Windows NT accounts in the Officeadmin group for three application administrators. These accounts are used to download DSA software. The account names can be chosen as desired. For this example they are called D1user1, D1user2, and D1user3.
5. Create one Windows NT account in the Officeuser group for download of the INTUITY Message Manager Software. The NTadmin account should be used for NT administration only. The account name can be chosen as desired. For this example it is called D1WEB.
6. Disconnect from pcAnywhere.



#### NOTE:

The NTadmin account can be used for download, but should be used for NT administration only.

## DEFINITY logins for the customer

In addition to the logins maintained in the Windows operating system, there are customer level logins within the DEFINITY application that do NOT appear as Windows logins. The default password should be changed by the customer during installation.

Table 1-9. DEFINITY customer logins

DEFINITY customer logins	Comments	Default password
defty1	This is the customer level "super user" login within the DEFINITY application. Its use should be restricted to the system administrator. This login can be used to create additional DEFINITY logins. See the DEFINITY command <b>add login</b> .	

Release 2.0 provides enhanced login/password security by adding a security feature that allows users to define their own DEFINITY logins/passwords and to specify a set of commands for each login.

- The system allows up to 14 simultaneous connections (logins) to DEFINITY ONE. (DEFINITY can have 5 connections, AUDIX can have 4 connections, and the rest of the connections are reserved for shell commands.)
- Each DEFINITY ONE login name can be customized
  - Logins must be 3 to 6 alphabetic/numeric characters, or a combination of both.
  - A password must be from 4 to 11 characters in length and contain at least 1 alphabetic and 1 numeric symbol.

Password aging is an optional feature that the super-user administering the logins can activate (see below).

### NOTE:

If several users are logging in and out at the same time, a user may see the message: `Transient command conflict detected; please try later`. After the "users" have completed logging in or out, the terminal is available for use.

## Forced password aging (DEFINITY-specific)

Forced password aging operates as follows:

- The password for each login can be aged starting with the date the password was created, or changed, and continuing for a specified number of days (1 to 99).
- 7 days before the password expiration date, the user is notified that the password is about to expire at the login prompt.
- When the password expires the user is required to enter a new password into the system before logging in.
- If a login is added or removed, the “Security Measurement” reports are not updated until the next hourly poll, or a **clear measurements security-violations** command is entered.
- Once a non-super-user has changed the password, the user must wait 24 hours to change the password again.

## Logoff notification (DEFINITY-specific)

Security is enhanced by providing a logoff notification screen to a system administrator at log off while either the facility test call or remote access features are still administered. The administrator can be required to acknowledge the notification before completing the logoff process. Logoff notification is administered on the Login Administration screen.

## Super\_User

Release 2.0 is delivered to the customer with one customer “super-user” login/password defined. The customer is required to administer additional login/passwords as needed. The super-user login has full customer permissions and can customize any login created.

Login permissions for a specified login can be set by the super-user to block any object that may compromise switch security. Up to 40 administration or Administer Trunks

- Additional Restrictions
- Administer Features
- Administer Permissions
- Maintenance Commands

### NOTE:

Enable MSP features using change system-parameters customer-options.

- Maintain Stations
- Maintain Trunks
- Maintain Systems
- Maintain Switch Circuit Packs

## Administer login command permissions

Users with super-user permissions can set the permissions of logins they create by performing a change permissions <login-name> command. This causes the Login Permissions form to display. The Login Permissions form allows the user to control access to various categories of commands for a given login. It also permits restricting access to objects (forms) on an individual basis for up to 40 objects. Restricting an object means that no commands may be performed on that object by that login (add, change, remove, etc.) The three main categories of commands are:

- Common Command
- Administration Commands
- Optional Maintenance Commands

Each category of commands has sub-categories that, when set to **y**, allow access to objects associated with that sub-category. If the category is set to **n**, the user is not be able to add, remove, or change commands on objects under that sub-category. If the display category is **y**, the login will list or display the object in most cases. If the super-user wants to restrict access to all commands associated with an individual object in a subcategory, the Additional Restrictions field is set to **y**. This causes 2 additional pages to be added to the permissions form. Scroll these pages and press **Help**. Individual objects will be displayed in alphabetical order. Enter the object that you want to restrict access to into the fields and submit the form. Up to 40 objects may be restricted. A restricted login cannot access any of the commands associated with that login. Note that permissions cannot be changed for the login and you cannot create Additional Restrictions without full super-user permissions.

## DEFINITY commands for user login

DEFINITY commands refer to the set of commands that execute under the DEFINITY application running on the DEFINITY ONE system platform and which can be accessed through the SAT session or the DEFINITY Site Administration application.

These commands are grouped into three command categories. Each of the three command categories has a group of command subcategories listed under them, and each command subcategory has a list of command objects that the commands acts on. A super-user can set a user's permissions to restrict or block access to any command in these categories. These categories are displayed on the Command Permissions Categories form. The three main categories are:

- Common Commands
  - Display Administrative and Maintenance Data
  - System Measurements

- Administration Commands
  - Administer Stations
  - Administer Trunks
  - Additional Restrictions
  - Administer Features
  - Administer Permissions
- Maintenance Commands
  - Maintain Stations
  - Maintain Trunks
  - Maintain Systems
  - Maintain Switch Circuit Packs
  - Maintain Process Circuit Packs

## Password expiration

If your password has expired, the following message displays:

```
Login: telmgr

Password:
Your Password has expired, enter a new one.

Reenter Current Password:

New Password:

Reenter New Password:
```

**Figure 1-13. Password expiration screen**

If your password is within 7 days of the expiration date, the following message displays:

```
WARNING: Your password will expire in X days
```

## **Comcodes for Release 2.0**

[Table 1-10](#) lists the comcodes for equipment used with Release 2.0 CMC.

**Table 1-10. Comcodes for Release 2.0**

<b>Comcode</b>	<b>Description</b>
847951662	Left Panel
847951670	Right Panel
601929763	Processor Interface Cable
407633999	U.S. Robotics Model 839 External Modem
105631527	TDM/LAN Bus Terminator (AHF110)
	Vertical TDM/LAN Bus Cable (WP-91716 List 8)
	Horizontal TDM/LAN Bus Cable (WP-91716 List 9)
407780501	Single-Point Ground Block
847987187	CMC 110 Cross-Connect Assembly (Main Distribution Frame)
J58890T1 L1	DEFINITY ONE Cabinet
103557484	TN795 Processor Circuit Pack
407961804	PCMCIA Hard Disk
601929920	Software CDs
2403-701	Lucent UPS PEC
407676691	120 VAC Power Distribution Unit (145D 6-AC)
847951605	Fan Assembly
407745009	Fan Air Filter
405362641	120 VAC Power Cable
106278062	Apparatus Blank (Circuit Pack Blank) (158P)
106606536	Integrated Channel Service Unit (ICSU) (120A2)
107988867	DS1 Loopback Jack (T1 Only) (700A)
107152969	75 Ohm DS1 Coaxial Adapter (888B)
403613003	157B Connecting Block
406948976	6SCP-110 Protector
107435091	507B Sneak Current Fuse Panel
407216316	220029 Sneak Current Fuse

*Continued on next page*

**Table 1-10. Comcodes for Release 2.0 — Continued**

<b>Comcode</b>	<b>Description</b>
403613003	157B Connecting Block
103970000	Main Distribution Frame Label (Code 220A)
847489895 or 847489903	6-pin mini DIN to RJ-11 jack to allow 715 BCS keyboard on 2900/715 Terminal
407536531	9-pin DTE to 25-pin DCE Adapter Cable for a 715 BCS-2 Terminal
104307327	C6C cable — 50-foot (15.2 m) shielded DS1 cable with 50-pin male to 15-pin male
104307376	C6D cable — 50-foot (15.2 m) shielded DS1 cable with 50-pin male on each end
104307434	C6E cable — 100-foot (30.5 m) shielded DS1 cable with a 50-pin male to 50-pin female
104307475	C6F cable — 50-foot (15.2 m) shielded DS1 cable with 50-pin male to 3 inch (7.62 cm) stub
102381779	3B1A Carbon Block
104410147	3B1E-W Wide Gap Gas Tube
105514756	3C1S Solid State
102904893	4B1C Carbon Block with Heat Coil
104401856	4B1E-W Wide Gap Gas Tube w/Heat Coil
104386545	4C1S Solid State with Heat Coil
406948976	SCP-110 Sneak Current Protector
407216316	220029 Fuse Sneak Current Protector
105581086	4C3S-75 Solid State with Heat Coil
406144907	ITW LINX Gas Tube, Avalanche Suppress
901007120	ITW LINX Ground Bar (used with above)
406304816	ITW LINX Replacement Fuse
103972758	Data Link Protector (1 circuit)
103972733	Data Link Protector (8 circuits)
407063478	Electrostatic Discharge (ESD) Wrist Strap
107731853	Single-Mode Fiber Optic Transceiver (300A)
106455348	Multi-Mode Fiber Optic Transceiver (9823A)

*Continued on next page*

Table 1-10. Comcodes for Release 2.0 — *Continued*

Comcode	Description
106455363	Multi-Mode Fiber Optic Transceiver (9823B)
407439975	Multi-mode Fiber Interconnect Cable (20 Feet (6.1 m))
407598325	Single-mode Fiber Interconnect Cable (20 Feet (6.1 m))
105357727	Single-mode Fiber Optic Patch Cord (2 Feet (0.6 m))
106060718	Single-mode 5dB Attenuator
106060734	Single-mode 10dB Attenuator
601939804	H600512G1 Octopus Cable

**1** Maintenance Concepts for DEFINITY ONE  
*Comcodes for Release 2.0*

1-56

# Maintenance Procedures for DEFINITY ONE Compact Modular Cabinets

# 2

---

This chapter provides commonly used maintenance procedures and troubleshooting information.

## **Preventive maintenance**

---

The following describes procedures for implementing and logging preventive maintenance at customer sites:

### **Preventive maintenance log**

---

The sample below shows the DEFINITY ONE Preventive Maintenance Log. When completing any of the preventive maintenance procedures described in this section, ensure that the requested information on the log form is filled out before leaving the customer's premises.

**DEFINITY ONE preventive maintenance log**

Date System Installed: \_\_\_\_\_

Component (Comcode)	Scheduled Date	Completed Date	Completed By	Scheduled Date	Completed Date	Completed By
Air Filter <sup>1</sup> (407745009)						

- 
1. Inspect annually; see [“Air filters”](#) below for cleaning/replacement details.
- 

**Air filters**

Air filters should be inspected annually. See [Table 2-1](#).

**Table 2-1. Inspecting air filters**

If	Then
Filter is dirty or clogged	Tap filter on the ground.
Tapping does not dislodge dirt or clog	Wash with warm water and mild detergent, or clean with a vacuum cleaner (if one is available)
No facility exists for washing or vacuuming	Replace air filter (Comcode 407745009). Refer to <a href="#">Figure 2-1</a> for more information on air filters and fans.

**Fan filter removal/replacement**

1. Remove the left door.
2. Remove the fan/filter access panel. See [Figure 2-1](#).




Figure 2-1. Fan/filter removal

### Fan assembly removal/replacement

1. Pull (unplug) the fan assembly from the chassis. The power for the fan automatically disconnects when the assembly is unplugged.
2. Plug in the new fan assembly. The power for the fan automatically connects when the fan assembly is plugged in.

Replace the fan/filter access panel and the left door.

### Fan filter removal/replacement

1. Remove the fan access panel from the left side of the cabinet.
2. Pull the fan filter from the chassis.
3. Clean (vacuum or wash with water) or replace the filter as needed and slide the filter back into the chassis.
4. Replace the fan access panel.

## Recovery from fatal errors

---

In the DEFINITY ONE system, there are two types of fatal software failure modes:

- Software failure, resulting in the failure of DEFINITY and AUDIX.
- Operating system failure, resulting in the failure of Windows NT.  
(SPE-Down Mode)

Hardware failures can also be a root cause of fatal software failures. Hardware failures may also be accompanied by an illuminated red LED on the failing circuit pack.

### Firmware failure

---

The firmware will automatically reboot the DEFINITY ONE system when the handshaking signal between the firmware and NT is not detected. If there are greater than 5 reboots in a 60-minute time period, the system is not self-repairing, and the firmware will stop attempting to reboot NT.

#### To view the handshaking signal

1. Observe the amber LED on the TN795 processor circuit pack.
2. If it flashes briefly once every 10 seconds, the handshaking signal is present.

#### If there is no handshaking signal

If the firmware has stopped, and NT is running, you can use Windows NT to provide information to higher-tier personnel for troubleshooting.

#### To access the NT interface

1. Start pcAnywhere from your laptop or a network PC to the DEFINITY ONE.
2. If the pcAnywhere server is not running on DEFINITY ONE, you must:
  - a. Telnet into the system.
  - b. Enter **bash** at the command line to open a bash shell.
  - c. Enter **pcanywhere** at the command line to start up the pcAnywhere server on DEFINITY ONE.
3. View the NT event log.
4. After pcAnywhere is used, it is required that pcAnywhere is turned off using **pcanywhere -c**.

## **SPE-down mode**

---

In the DEFINITY ONE system, SPE-Down mode refers to the condition in which:

- Windows NT has failed
- The system firmware is still running

The firmware will issue an INADS alarm call at 7 minute intervals. If the problem has not been corrected after the first three messages have been issued, the alarm call interval is increased to 45 minutes.

## **Recovery from fatal errors**

---

In general, if there is a fatal error, the system will not be operating at a level that can be investigated in the field.

If the DEFINITY ONE has a fatal error:

1. Reboot the system. If you cannot access the system using any of the software methods, you can reboot the system by pressing the reset button on the TN795 processor circuit pack. See [“Hardware shutdown” on page 2-12](#).
2. If the problem persists after reboot, you may have to replace the processor circuit pack.

## **Resolving alarms**

---

An alarm is generated when a non-fatal error is detected by the DEFINITY ONE system. This section describes methods to determine the source of alarms.

## **Recovery procedures**

---

The first step is to determine the location of the problem. It is possible for two or more circuit packs to have failed. It is also possible for a fatal problem with one circuit pack to affect another circuit pack, especially the Processor circuit pack. All three of the following methods should be employed to determine where the fatal fault lies.

## Use the bash shell in a telnet session

The bash shell opened during a telnet session is the most robust interface into the DEFINITY ONE system. Once this interface is established:

1. Use alarmstat command.  
alarmstat will display all active global, DEFINITY and AUDIX alarms. See [“alarmstat” on page 3-6](#).
2. If there are any global alarms, use gamalarmstat to see details of global alarms. See [“gamalarmstat” on page 3-19](#).
3. Use restartcause to obtain information about system restarts. See [“restartcause” on page 3-25](#).
4. Use the start command to restart firmware and applications. See [“start” on page 3-33](#).

## To see DEFINITY alarms

If you can get the DEFINITY application to run either from a telnet session (SAT window) or DSA, you can use the following DEFINITY commands to obtain more alarm information.

1. Use [display alarms](#) command:  
Issuing the **display alarms** command at the administration terminal shows where maintenance thinks the problem lies. The alarms are a good indication of why the system went down. They should be used along with the following two methods.
2. Observe red LEDs on the circuit pack to determine where software or processor firmware had a problem.
3. Use the **reset** command:

## To remove a system from the SPE-Down mode.

### NOTE:

**This is important!** If you cannot complete the first step or have problems with the maintenance interface, then the first step should be to replace the Processor circuit pack.

1. Determine which circuit pack is defective by displaying alarms and observing the red LEDs (as discussed previously).

The following general purpose maintenance procedures may be used with other repair strategies to clear system-alarmed and user-reported troubles.

## Reseating/replacing circuit packs

---

### **WARNING:**

*It is NOT recommended that you reseat circuit packs unless the documentation specifically instructs you to do so. If it is required to reseat a circuit pack, follow the instructions below which explain how to unseat, reseat, and replace circuit packs.*

The procedures for unseating, reseating, and replacing control circuit packs vary depending on the system configuration. Therefore, before performing these maintenance activities, refer to the appropriate procedure below.

### Control circuit packs

---

To unseat a control circuit pack:

1. Remove power from the PPN using the procedure provided in [“Removing power”](#).
2. Slide the latch pin upward to unlock the locking lever.
3. Pull down on the locking lever until the circuit pack disconnects from its socket.
4. Pull the circuit pack just enough to break contact with the backplane connector, but do not remove it from the cabinet.

To reseat a circuit pack:

1. Push the unseated circuit pack back into the backplane connector.
2. Lift the locking lever until the pin engages.
3. Restore power to the PPN using the procedure provided in [“Setting neon voltage \(ring ping\)”](#).

To replace Control circuit packs:

1. Remove power from the PPN using the procedure in [“Removing power”](#).
1. Unseat the circuit pack.
2. Slide the circuit pack out of the slot.
3. Replace the circuit pack as per the following procedure:

### **NOTE:**

If a new circuit pack does not correct the problem, install the original circuit pack.

To install a new circuit pack or return the original one to service:

1. Carefully insert the circuit pack and push it all the way into its mounting slot.
2. Lift the locking lever until the latch pin engages.
3. Restore power to the PPN using the procedure in [“Setting neon voltage \(ring ping\)”](#).
4. Verify that the circuit pack LED indications are correct.
5. Test the replaced control circuit pack by issuing the system technician commands after power has been restored.

## Replace the TN795 circuit pack

### **WARNING:**

*When the disk is replaced on the TN795, a new license file must be downloaded to the system before the system will become operational. Refer to “Obtaining a License File” in Chapter 3 of DEFINITY ONE™ Communications System Release 2.0 Installation and Upgrades (555-233-109).*

1. Shut down the system. Refer to the procedure, “Shut Down” in Appendix C, Miscellaneous Procedures of the *DEFINITY ONE™ Communications System Release 2.0 Installation and Upgrades (555-233-109)*.
2. Remove the TN795 circuit pack.
3. Remove the hard disk from the failed TN795 circuit pack.
4. Insert the hard disk onto the new TN795 circuit pack.  
See [Table 1-3 on page 1-36](#).
5. Plug in the TN795 board.
6. Boot the system.

### **NOTE:**

The system will boot but the DEFINITY ONE applications won't start running because the serial number on the disk doesn't match the serial number on the board.

Because the hard disk is reused, the system has the old password file that was on the system before the board failed. You must obtain the appropriate password from the TSO to log in.

7. Call INADS to obtain a new license file.
8. After the license file has been installed and the system has been rebooted, login into the system and run a demand test on the new board.  
Refer to “Obtaining a License File” in Chapter 3 of *DEFINITY ONE™ Communications System Release 2.0 Installation and Upgrades (555-233-109)*.

## Replace the hard disk

---

1. Shut down the system. (See the procedure, "Shut Down" in Appendix C, Miscellaneous Procedures of the *DEFINITY ONE™ Communications System Release 2.0 Installation and Upgrades* (555-233-109).
2. Remove the TN795 circuit pack.



### WARNING:

*When the disk is replaced on the TN795, a new license file must be downloaded to the system before the system will become operational. Refer to "Obtaining a License File" in Chapter 3 of *DEFINITY ONE™ Communications System Release 2.0 Installation and Upgrades* (555-233-109).*



### CAUTION:

*Replacing the TN795 processor board can cause the translation error message "TRANS ID INTERVAL EXPIRATION:xxdays to display when logging into the SAT window. If this occurs, immediately call a Lucent Technical Services Consultant (TSC) to remove the error message. While*

3. Remove the failed hard disk from the TN795 circuit pack
4. Insert the new hard disk onto the board, making sure to use the appropriate hard disk for the given circuit pack and software release.  
  
The disk comes pre-loaded with all the necessary DEFINITY ONE software; however, the DEFINITY ONE applications won't run until you install the new license file, see step [9](#).
5. Once the system has rebooted, connect the services laptop computer to DEFINITY ONE using the procedure in ["Connect the Laptop Computer to DEFINITY ONE" on page A-17](#).
6. Telnet to the LAC using the procedure, "Via a Telnet Session" in Chapter 2, "Connectivity and Access to DEFINITY ONE", in *DEFINITY ONE™ Communications System Release 2.0 Installation and Upgrades* (555-233-109).
7. Log in and run a bash session.
8. Execute [swversion](#) and verify that the load of software on the hard drive matches that on the customer's CD. If it is not, follow the procedure, Software Upgrade, in this chapter.

2 Maintenance Procedures for DEFINITY ONE Compact Modular Cabinets  
Replace the hard disk

2-10

9. Bring up NT Explorer or Netscape on the laptop and load the DEFINITY ONE Home Page. For information about how to start a web browser, see the procedure, "Via a Web Browser Session" in Chapter 2, "Connectivity and Access to DEFINITY ONE", in *DEFINITY ONE™ Communications System Release 2.0 Installation and Upgrades* (555-233-109). Navigate the browser to the backup and restore screens.

The browser will prompt for a login and password, because the new hard disk does not have a password file so the system reverts back to the factory default login of **lucent3**, with **lucent3** as the password.

10. Follow the steps for restoring the customers data, note the customer may have backed up to their local network or the PCMCIA flash disk
11. After restoring, follow the procedures to install a new license file, including running the [setip](#) command. For more details, see the procedure, "Obtaining the License File" in Chapter 3 of *DEFINITY ONE™ Communications System Release 2.0 Installation and Upgrades* (555-233-109).

After installing the license file, the system restarts and all applications load.

12. The logins and passwords will have been updated by the **installconfig** command.
13. Note that the NT logins of **vm**, **sa**, **browse**, and **Ntadmin** will be reset to their factory defaults. Tell the customer to reset these passwords and re-install any other NT accounts they may have created.

 NOTE:

The DEFINITY-specific customer logins should still work as they were restored with the restore done earlier.

14. If it is necessary, upgrade the software on the disk by following the steps in the procedure, Update Software, in Chapter 5 of *DEFINITY ONE Communications Release 2.0 Installation and Upgrades* (555-233-109). If an upgrade is necessary upgrade the software before installing the new license file.

## Removing power

---

When power is removed, *all* DEFINITY ONE features deactivate.



### NOTE:

There is no power switch on the DEFINITY ONE.

There are two types of shutdown:

- “Graceful” shutdown means that all processes are told to stop, and are given time to arrive in a known, recoverable, state.
- Immediate shutdown means that all processes stop immediately without necessarily storing information.

You can command a system shutdown from the software or the hardware.

## Software shutdown

---

Software shutdown is performed using GAS commands at the bash shell interface. ()

### Graceful shutdown

1. Use the shutdown system command.

This will close all processes, firmware, and Windows NT. This may take several minutes, depending on what processes are running. See [“shutdown” on page 3-30](#).

The system is ready for power off when the green “OK to Remove” LED is light on the TN795 processor circuit pack.

2. Unplug the power cord, or
3. Disengage the latch on the power supply and pull it from its slot so that the backplane pins are not connected.

### Immediate shutdown

1. Use the terminate system command.



### CAUTION:

*This command will kill all processes, firmware and NT. Software may have to be re-loaded to regain operation. Use the **shutdown** command whenever possible.*

The system is ready for power off when the green “OK to Remove” LED is light on the TN795 processor circuit pack. (This takes about 3 minutes)

2. Unplug the power cord, or
3. Disengage the latch on the power supply and pull it from its slot so that the backplane pins are not connected.

## Hardware shutdown

---

### Graceful shutdown

You will need a pen or small screwdriver for these procedures.

1. Press the recessed shutdown button until the “Complete” LED starts to flash on the TN795 processor circuit pack using a small tool.

The system will perform a graceful shutdown.

The system is ready for power off or removing the TN795 circuit pack after the “Complete” LED goes to a steady green.

2. Unplug the power cord, or
3. Disengage the latch on the power supply and pull it from its slot so that the backplane pins are not connected.

The procedure for an immediate hardware shutdown (i.e. unplugging the system) is not recommended.

## Replacing the power supply

---



### WARNING:

*Ensure that the power is OFF before proceeding.*

1. Pull on the latch for the 650A Power Supply.
2. Replace the power supply and secure the latch.



### NOTE:

You will have to adjust the neon voltage after replacing the power supply. See [“Setting neon voltage \(ring ping\)” on page 2-13](#) for more information.

## Restoring power

---

The procedures you need to restore power depend on the system configuration. Before performing these activities, refer to the appropriate procedure. Restore power as follows:

1. Plug in power cords in port cabinets first.
2. The system now goes through the rebooting process. This process takes about 3 minutes. LEDs will go through their power-up sequence. See [“LED boot sequence” on page 1-29](#).
3. The system has finished booting when the EM XFER (emergency transfer) LED goes off.

## Setting neon voltage (ring ping)

---

This procedure must be performed at installation and after replacement of the power supply.



**NOTE:**

The frequency (20, 25 or 50 Hz) is set by a switch on the power supply. Check the setting on this switch to ensure it is properly set.

### Set neon voltage to OFF

---

Neon voltage should be set to OFF under these conditions:

- Ringing option is set to 50 Hz. Neon voltage is not available.
- LED message lamps are used on telephones.
- No *neon* message waiting lamps on telephones.

To turn the neon voltage OFF

1. Turn the neon voltage control to OFF (see [Figure 2-2.](#))

### Adjust neon voltage

---

The neon voltage must be adjusted under these conditions:


- Ringing option is set to 25 Hz. Maximum neon voltage is 120 Volts.
- Neon message waiting lamps are present on telephones.

Use the following procedure to adjust the neon voltage:

1. Call a telephone with a neon message indicator and leave a message.
2. Check for “ring ping” (single ring pulse) each time the lamp flashes (approximately every 3 seconds).
3. Adjust the neon voltage control clockwise in small increments until the ring ping stops. See [Figure 2-2 on page 2-14.](#)

Ensure that the message lamp still lights when the adjustment is finished.

4. Enter **logoff** and press **Enter** to logoff the system and to prevent unauthorized changes to data.
5. Set the left and right doors onto the hinge pins and close the doors. The doors must be closed to prevent EMI emissions. Tighten the door screws.
6. Set the cover panel onto the right panel and secure.



didmt1 KLC 053097

Figure 2-2. Setting the neon voltage

## Troubleshooting features

In addition to the various maintenance and test commands that are available, the following system features may also be useful in troubleshooting certain system resources:

- [“Automatic Circuit Assurance”](#)
- [“Busy Verification of Terminals and Trunks”](#)
- [“Trunk Group Busy/Warning Indicators to attendant”](#)
- [“Trunk Identification by attendant”](#)
- [“Facility test calls”](#)
- [“Analog tie trunk back-to-back testing”](#)
- [“Terminating trunk transmission testing”](#)
- [“Troubleshooting ISDN-PRI problems”](#)
- [“Troubleshooting PRI endpoint problems”](#)
- [“Troubleshooting ISDN-PRI test call problems”](#)

## **Automatic Circuit Assurance**

---

A display-equipped voice terminal (may be nondisplay type if the Voice Message Retrieval feature is provided) or an attendant console is required. An “ACA activate/deactivate” button (one per system) is required on the voice terminal or attendant console.

Automatic Circuit Assurance (ACA) assists users in identifying possible trunk malfunctions. The system maintains a record of the performance of individual trunks relative to short and long holding time calls. The system automatically initiates a referral call to an attendant console or display-equipped voice terminal when a possible failure is detected.

Holding time is the elapsed time from when a trunk is accessed to the time a trunk is released. When ACA is enabled through administration, the system measures the holding time of each call.

A short holding time limit and a long holding time limit are preset by the System Manager for each trunk group. The short holding time limit can be from 0 to 160 seconds. The long holding time limit can be from 0 to 10 hours. The measured holding time for each call is compared to the preset limits for the trunk group being used.

Measurements are not made on personal CO lines, out-of-service trunks, or trunks undergoing maintenance testing.

## **Busy Verification of Terminals and Trunks**

---

A multi-appearance voice terminal or attendant console equipped with a “verify” button is required.

Busy Verification of Terminals and Trunks allows a user at a voice terminal or attendant console to make test calls to trunks, voice terminals, and hunt groups (DDC/UCD). These test calls check the status of an apparently busy resource. This provides an easy method to distinguish between a voice terminal or resource that is truly busy and one that only appears busy because of a trouble condition.

## Trunk Group Busy/Warning Indicators to attendant

An attendant console is required.

Trunk Group Busy/Warning Indicators to Attendant provides the console user with a visual indication of the trunk group status for each trunk group associated with the 12 Trunk Group Select buttons located on the console. Trunk groups with busy indications during nonbusy periods should be checked to ensure that the trunks are busy and not out-of-service. Use the Busy Verification of Terminals and Trunks feature to test the suspected faulty trunks.

## Trunk Identification by attendant

A display-equipped voice terminal or an attendant console equipped with a "trunk id" button is required.

Trunk Identification by Attendant allows a voice terminal or attendant console user to identify a specific trunk being used on a call. This is useful when a user experiences noise or poor transmission on a trunk call. The trunk identification (access code and group number) is displayed when the "trunk id" button is pressed while on a trunk call. Use of this feature is denied if there are more than two trunks on a call. If the call is trunk-to-trunk, the identification displayed is of the last trunk added to the call.

## Facility test calls

The Facility Test Calls feature provides a voice terminal user the capability of placing test calls to access specific trunks, touch-tone (DTMF) receivers, time slots, and system tones. The test call can be made by a local voice terminal user by dialing an access code.

### NOTE:

For the ISDN-PRI Test Call feature, see ["Troubleshooting the outgoing isdn-testcall command" on page 2-38.](#)

The following Facility Test Calls are described below:

- ["Trunk test call"](#)
- ["Touch-tone \(DTMF\) receiver test call"](#)
- ["Time slot test call"](#)
- ["System tone test call"](#)

## Trunk test call

The trunk test call accesses specific Tie or CO trunks. DID trunks cannot be accessed.

To place a call:

1. Dial the Facility Test Call Feature Access Code (for example, 197, see Note), and listen for dial tone.



### NOTE:

The Facility Test Call Access Code (FAC) is administered on the Feature Access Codes Form. The 197 FAC code used here is an example.

2. Dial the 6-digit port number **PCSSpp**

- P = Port network number (1)
- C = Carrier number (A=1, B=2, C=3)
- SS = Slot number (01-10)
- pp = Port number

The channels on a DS1 trunk are addressed by using the channel number for the port number.

3. Listen for one of the following tones:
  - Dial Tone or Silence — trunk is connected. Go to Step [4](#). If you hear a dial tone, it is coming from the far end. If the far end has been disabled, you do not hear dial tone. However, depending on far-end administration, you may still be able to dial digits. All digits dialed after the port number are transmitted using end-to-end DTMF signaling; therefore, if the trunk being tested is a rotary trunk, it is not possible to break dial tone.
  - Reorder Tone — trunk is busy or maintenance busy.
  - Intercept Tone — a trunk or touch-tone (DTMF) receiver has not been accessed.

4. Place a call. Even if you do not hear a dial tone, you may still be able to dial digits, depending on the administration of the far-end switch.

All digits dialed after the port number are transmitted using end-to-end DTMF signaling; therefore, if the trunk being tested is a rotary trunk, it is not possible to break dial tone.

If the call does not go through (that is, no ringing), determine if the trunk circuit pack has been removed.

**CAUTION:**

*To leave the Facility Test Call administered after you logoff poses a significant security risk that unauthorized individuals may connect to the telecommunications network through the use of test call features.*

To remove the Facility Test Calls Access Code, do the following:

- a. Enter **change feature-access-codes** to display the Feature Access Code screen.
- b. Leave the Facility Test Calls Access Code field **blank**.

## Touch-tone (DTMF) receiver test call

The touch-tone (DTMF) receiver call accesses and tests the four touch-tone (DTMF) receivers located on the TN744D Tone Detector circuit pack. To place the call:

1. Dial the Facility Test Call Feature Access Code (for example, 197, see Note), and listen for dial tone.

**NOTE:**

The Feature Access Code (FAC) is administered on the Feature Access Codes Form. The 197 FAC code used here is an example.

2. Dial the 6-digit port number **PCSSpp**:

P = Port network number (1)

C = Carrier number (A=1, B=2, C=3)

SS = Slot number (01-10)

pp = Touch-tone (DTMF) Receiver Port number (01, 02, 05, or 06)

3. Listen for one of the following tones:

- Confirmation Tone — touch-tone (DTMF) receiver is connected. Go to Step 4.
- Reorder Tone — touch-tone (DTMF) receiver is busy.
- Intercept Tone — a touch-tone (DTMF) receiver or trunk has not been accessed.

4. Dial **1234567890\*#** and listen for Confirmation tone (test passed) or intercept tone (test failed). The test fails if the touch-tone (DTMF) receiver does not recognize all the touch-tone (DTMF) signals.
5. To test another touch-tone (DTMF) receiver, repeat Steps [2](#) through [4](#).
6. To terminate the test call, hang up the station set used for testing.

## Time slot test call

The time slot test call connects the voice terminal user to a specific time slot located on the TDM Buses (A or B) or out-of-service time slots. Specific Time Slots To place the call:

1. Dial the Facility Test Call Feature Access Code (for example, 197, see Note), and listen for dial tone.



### NOTE:

The Feature Access Code (FAC) is administered on the Feature Access Codes Form. The 197 FAC code used here is an example.

2. Dial port network number (1), then press # and the 3-digit time slot number "sixty," where:

xxx = Time slot number (000 through 255 on Bus A and 256 through 511 on Bus B)

3. Listen for one of the following tones:
  - Confirmation Tone — time slot is idle or maintenance busy
  - Reorder Tone — time slot is busy
  - Dedicated Tone — one of the following tones is heard (see [Table 2-2](#))

**Table 2-2. TDM bus time slot numbers**

TDM Bus A time slot	TDM Bus B time slot	Tone heard
000	256	Reorder
001	257	Reorder
002	258	Reorder
003	259	Reorder
004	260	Reorder
005	261	Touch Tone 1 - 697Hz

*Continued on next page*

**Table 2-2. TDM bus time slot numbers — Continued**

TDM Bus A time slot	TDM Bus B time slot	Tone heard
006	262	Touch Tone 2 - 770 Hz
007	263	Touch Tone 3 - 852Hz
008	264	Touch Tone 4 - 941 Hz
009	265	Touch Tone 5 - 1209 Hz
010	266	Touch Tone 6 - 1336Hz
011	267	Touch Tone 7 - 1447 Hz
012	268	Touch Tone 8 - 1633 Hz
013	269	Dial Tone
014	270	Reorder Tone
015	271	Alert Tone
016	272	Busy Tone
017	273	Ringback Tone
018	274	Special Ringback Tone
019	275	2225 Hz Tone
020	276	Music
021	277	Tone on Hold
022-253	278-509	Confirmation (used for calls)
254	510	Reorder
255	511	Confirmation

Out-of-Service Time Slots to place the call:

1. Dial the Facility Test Call Feature Access Code (for instance, 197, see Note), and listen for dial tone.



**NOTE:**

The Feature Access Code (FAC) is administered on the Feature Access Codes Form. The 197 FAC code used here is an example.

2. Dial port network number (1), then dial \*\* and listen for the following tones:
  - Confirmation Tone — Connection is made. Go to Step 3.
  - Reorder Tone — No time slots are out-of-service.
3. Repeat from Step 1 to alternate between out-of-service time slots on TDM Bus A and B.

## System tone test call

The system tone test call connects the voice terminal user to a specific system tone. To place the call:

1. Dial the Facility Test Call Feature Access Code (for instance, 197, see Note), and listen for dial tone.

**NOTE:**

The Facility Test Call Access Code (FAC) is administered on the Feature Access Codes Form. The 197 FAC code used here is an example.

2. Dial port network number (1), then dial \*, followed by the two-digit tone identification number listed in [Table 2-3](#).

**NOTE:**

For a definition of Call Progress Tones see *DEFINITY Enterprise Communications Server Release 8.2 Administration and Feature Description*.

**Table 2-3. System Tone Identification Numbers**

Number	Description
00	Null tone
01	Dial tone
02	Reorder tone
03	Alert tone
04	Busy tone
05	Recall dial tone
06	Confirmation tone
07	Internal call waiting tone
08	Ringback tone
09	Special ringback tone

*Continued on next page*

Table 2-3. System Tone Identification Numbers — Continued

Number	Description
10	Dedicated ringback tone
11	Dedicated special ringback tone
12	Touch tone 1
13	Touch tone 2
14	Touch tone 3
15	Touch tone 4
16	Touch tone 5
17	Touch tone 6
18	Touch tone 7
19	Touch tone 8
20	Chime
21	350 Hz
22	440 Hz
23	480 Hz
24	620 Hz
25	2025 Hz
26	2225 Hz
27	Counter
28	External call waiting
29	Priority call waiting
30	Busy verification
31	Executive override/intrusion tone
32	Incoming call identification
33	Dial zero
34	Attendant transfer
35	Test calls
36	Recall on don't answer
37	Audible ring
38	Camp-on recall

---

*Continued on next page*

Table 2-3. System Tone Identification Numbers — *Continued*

Number	Description
39	Camp-on confirmation
40	Hold recall
41	Hold confirmation
42	Zip tone
43	2804 Hz
44	1004 Hz (-16dB)
45	1004 Hz (0 dB)
46	404 Hz
47	Transmission test sequence 105
48	Redirect tone
49	Voice signaling tone
50	Digital milliwatt
51	440 Hz + 480 Hz
52	Music
53	Transmission test sequence 100
54	Transmission test sequence 102
55	Laboratory test tone 1
56	Laboratory test tone 2
57	Disable echo supervision dial tone
58	7 seconds of answer tone
59	4 seconds of answer tone
60	Restore music (or silence)
61	Warning tone
62	Forced music tone
63	Zip tone (first of 2 sent)
64	Incoming call ID (first of 2 sent)
65	Tone on hold
66	CO dial tone

---

*Continued on next page*

Table 2-3. System Tone Identification Numbers — Continued

Number	Description
67	Repetitive confirmation tone
68	Conference/bridging tone

## Analog tie trunk back-to-back testing

The TN760B circuit pack can be configured for back-to-back testing (also known as connectivity testing) by making translation and cross-connect changes. This testing configuration allows for the connection of Tie Trunks back-to-back in the same switch to verify the operation of Tie Trunk ports. The tests can be performed in either the E & M or simplex modes.

### E & M mode test procedure

The procedures to perform the Analog Tie Trunk port test in the E & M mode are as follows:

1. At the administration terminal, enter **list configuration trunks** command to determine which ports are assigned on the Tie Trunk circuit pack.
2. Enter **display dialplan** command to determine the Trunk Access Code (TAC) format.
3. Enter **display port xx** command for all ports defined in Step 1. This action displays the trunk groups to which the ports belong (that is, of which the ports are members).

#### NOTE:

See [“Control circuit packs” on page 2-7](#) for details on how to remove and replace port circuit packs.

4. Insert the circuit pack back into the slot.
5. Enter **display trunk xx p** command for each trunk group identified in Step 3. This command displays the specified trunk group on the administration terminal screen and prints a hard copy on the printer. Save this data for later use.
6. Remove all members defined by these ports from the trunk group(s) using the **ch trunk xx** command.
7. Remove the Tie Trunk circuit pack from the carrier slot.
8. Set the dip (option) switches for each of the two ports to be tested on the Tie Trunk circuit pack to “E & M mode” and “unprotected.”

9. Enter **add trunk n** command to add a new (test) trunk group. Then enter the following information:

- Group Type — tie
- TAC — (use trunk access code obtained from dial plan)
- Trunk Type (in/out) — wink/wink
- Port — assign two of the ports from the tie trunk
- Mode — E & M
- Type — specify one port as t1 standard and other port as t1 compatible

Examples of the Trunk Group forms are shown in [Figure 2-3](#) and [Figure 2-4 on page 2-26](#).

```

display trunk-group 10                                     Page 1 of 5

                                TRUNK GROUP

Group Number: 10                Group Type: tie          CDR Reports? y
Group Name: tr 10                COR: 1              TAC: 110
Direction: two-way              Outgoing Display? n  Data Restriction? n
MIS Measured? n
Dial Access? y                  Busy Threshold: 60   Night Service:
Queue Length: 0                  Internal Alert? n    Incoming Destination:
Comm Type: voice                  Auth Code? n

TRUNK PARAMETERS

Trunk Type (in/out): wink/wink      Incoming Rotary Timeout(sec): 5
Outgoing Dial Type: tone              Incoming Dial Type: tone
                                       Disconnect Timing(msec): 500
                                       Digits:
Digit Treatment:
Used for DCS? n
ACA Assignment? n

Baud Rate: 1200                    Synchronization: async Duplex: full
Incoming Dial Tone? y                Maintenance Tests? y
Answer Supervision Timeout:           Suppress # Outpulsing? n
    
```

Figure 2-3. Trunk Group form

Page 2 of 5

TRUNK GROUP

GROUP MEMBER ASSIGNMENTS

Port	Name	Mode	Type	Answer Delay
1: B1901		E & M	t1 stan	
2: B1902		E & M	t1 comp	
3:				
4:				
5:				
6:				
7:				
8:				
9:				
10:				
11:				
12:				
13:				
14:				
15:				

Figure 2-4. Trunk Group form — E & M mode (Page 2 of 2)

- Locate the Tie Trunk port terminal connections at the cross-connect field. See [Table 2-4](#).

**Table 2-4. Carrier lead appearances at 110 cross-connect field**

110 connecting block terminals	CO trunk TN747B	Tie trunk TN760B
1	T1	T1
2	R1	R1
3		T11
4		R11
5		E1
6		M1
7	T2	T2
8	R2	R2
9		T12

*Continued on next page*

**Table 2-4. Carrier lead appearances at  
110 cross-connect field — *Continued***

110 connecting block terminals	CO trunk TN747B	Tie trunk TN760B
10		R12
11		E2
12		M2
13	T3	T3
14	R3	R3
15		T13
16		R13
17		E3
18		M3
19	T4	T4
20	R4	R4
21		T14
22		R14
23		E4
24		M4
25	T5	
26	R5	
27		
28		
29		
30		
31	T6	
32	R6	
32		
33		
34		
36		


*Continued on next page*

**Table 2-4. Carrier lead appearances at  
110 cross-connect field — *Continued***

110 connecting block terminals	CO trunk TN747B	Tie trunk TN760B
37	T7	
38	R7	
39		
40		
41		
42		
43	T8	
44	R8	
45		
46		
47		
48		
49		
50		

11. At the cross-connect field, disconnect outside trunk facilities from the Tie Trunk ports and mark the disconnected wires for later reconnecting the Tie Trunk ports back to normal operation. The D Impact Tool (AT-8762) is required to perform this step.

12. Use jumper wires (DT 24M-Y/BL/R/G and DT 24P-W/BRN) and the D Impact Tool to connect wiring between the two ports assigned in Step 9 at the cross-connect field. For example, if the two ports on the Analog Tie Trunk circuit pack are port 1 and 2, connect the wirings as shown below:



13. Check all wiring to verify good connections between the two test ports.
14. Place a call from one voice terminal to another voice terminal using the Tie Trunk ports assigned. Dial TAC and extension. For example, if TAC of Tie Trunk group is 110 and station number is 5012, then dial 110 5012. If the call cannot be made, either one of these ports could be defective. There are four ports on TN760B (port 1, 2, 3, and 4), try different combinations to determine defective ports.
15. If there is a defective port on the circuit pack, try to switch to an unused port. However, if all ports are normally used, then replace the circuit pack.
16. Disconnect the jumpers between two ports. Then use administration terminal and trunk printouts to restore all trunk group changes to normal values.

### Analog tie trunk port test procedure

The procedures to perform the Analog Tie Trunk Port Test in the simplex mode are as follows:

1. Repeat Steps 1 through 7 of the E & M Mode Test Procedure.
2. Set the dip (option) switches for each of the two ports to be tested on the Tie Trunk circuit pack to simplex mode.
3. Enter **add trunk n** command to add a new (test) trunk group. Then enter the following information:
  - Group Type — tie
  - TAC — (use trunk access code obtained from dial plan)
  - Trunk Type (in/out) — wink/wink
  - Port — assign two of the ports from the tie trunk
  - Mode — simplex
  - Type — type 5

An example of the Trunk Group Form Page 2 is shown in [Figure 2-5](#).

Page 2 of 5


TRUNK GROUP

GROUP MEMBER ASSIGNMENTS

Port	Name	Mode	Type	Answer Delay
1: B1901		simplex	type 5	
2: B1902		simplex	type 5	
3:				
4:				
5:				
6:				
7:				
8:				
9:				
10:				
11:				
12:				
13:				
14:				
15:				

Figure 2-5. Trunk group form — simplex mode (page 2 of 5)

4. Locate the Tie Trunk port terminal connections at the cross-connect field. See [Table 2-4 on page 2-26](#).
5. At the cross-connect field, disconnect outside trunk facilities from the Analog Tie Trunk ports and mark the disconnected wires for later when the Tie Trunk ports are placed back into normal operation. The D Impact Tool (AT-8762) is required to perform this step.
6. Use jumper wires (DT 24M-Y/BL/R/G) and the D Impact Tool to connect wiring between the two ports assigned in Step 4 at the cross-connect field. For example, if the two ports on the Analog Tie Trunk circuit pack are ports 1 and 2, connect the wirings as shown below:



7. Repeat Steps 13 through 16 of the E & M Mode Test Procedure.

## Terminating trunk transmission testing

The Terminating Trunk Transmission (TTT) (noninteractive) feature provides for extension number access to three tone sequences that can be used for trunk transmission testing from the far end of the trunks.

The three test types should have extension numbers assigned on the Maintenance-Related System Parameters Form.

Test Type 100:\_\_\_\_\_ Test Type 102:\_\_\_\_\_ Test Type 105:\_\_\_\_\_

Test Type 100 provides:

1. 5.5 seconds of 1004 Hz tone at 0dB
2. Quiet until disconnect; disconnect is forced after one minute

Test Type 102 provides:


1. 9 seconds of 1004 Hz tone at 0dB
2. 1 second of quiet
3. This cycle is repeated until disconnect; disconnect is forced after 24 hours.

Test Type 105 provides:

1. Nine seconds of 1004 Hz at -16dB
2. One second of quiet
3. Nine seconds of 404 Hz at -16dB
4. One second of quiet
5. Nine seconds of 2804 Hz at -16dB
6. 30 seconds of quiet
7. One half second of Test Progress Tone (2225 Hz)
8. Approximately five seconds of quiet
9. Forced disconnect

**Troubleshooting ISDN-PRI problems**

The following flowchart, [Figure 2-6](#) and [Figure 2-7 on page 2-33](#), defines a layered approach when troubleshooting ISDN-PRI problems. Since a problem at a lower layer affects upper layers, layers are investigated from low to high. In the flowchart, the DS1 facility is layer 1, the TN765 Processor Interface is layer 2, and the ISDN trunks are layer 3. Transient problems are diagnosed on Page 2 of the flowchart, [Figure 2-7 on page 2-33](#).



**Figure 2-6. Processing of ISDN-PRI problems (page 1 of 2)**




Figure 2-7. Processing of ISDN-PRI problems (page 2 of 2)

### Troubleshooting PRI endpoint problems

The following flowchart, [Figure 2-8 on page 2-34](#) and [Figure 2-9 on page 2-35](#), defines a layered approach when troubleshooting PRI endpoint problems. Since a problem at a lower layer affects upper layers, layers are investigated from low to high. In the flowchart, the DS1 facility is layer 1, the TN765 Processor Interface is layer 2, and the ISDN trunks are layer 3.

The troubleshooting procedure described here diagnoses faults between the switch and the line-side PRI terminal adapter/ISDN-PRI endpoint equipment. Problems encountered on the network-side of a wideband connection or problems with end-to-end equipment compatibility are outside the scope of this manual.




Figure 2-8. Processing of PRI endpoint problems (page 1 of 2)




Figure 2-9. Processing of PRI endpoint problems (page 2 of 2)

### Troubleshooting ISDN-PRI test call problems

An ISDN-PRI test call is a diagnostic call placed across an ISDN-PRI user-network interface to a previously-designated number. An ISDN-PRI test call is also a maintenance procedure concerned with the identification and verification ISDN-PRI user-network interface problems. The ISDN-PRI test call can access ISDN-PRI trunks only.

## Placing an outgoing ISDN-PRI test call



### NOTE:

An ISDN-PRI test call can be placed only if the circuit translates to an ISDN-PRI trunk.

An ISDN-PRI test call can be originated via either the *synchronous* or the *asynchronous* method. Each method is described below.

### Synchronous method

One command is used in this method to start, stop and query an ISDN-PRI test call. In the synchronous method, an outgoing ISDN-PRI test call may be part of a system technician-demanded long test sequence to test a circuit pack, port, or trunk. Therefore, the command line entry can be any of the following:

[test trunk](#) <grp>/<mbr> long [repeat #]

[test port](#) PCSSpp long [repeat #]

[test board](#) PCSS long [repeat #]

The "long" qualifier must be entered in the above commands in order for the ISDN test call to run. The repeat number (#) can be any number from 1 through 99 (default = 1).

The following information is displayed in response to the above commands:

- **Port:** The port address (PCSSpp) of the maintenance object under test.
- **Maintenance Name:** The type of maintenance object tested.
- **Test Number:** The actual test that was run.
- **Test Results:** Indicates whether the test passes, fails, or aborts.
- **Error Code:** Additional information about the results of the test. (See the ISDN Trunk Maintenance documentation for details.)

### Asynchronous method



### NOTE:

The asynchronous method requires a Maintenance/Test circuit pack to be physically present in the system.

In this method, four commands are used to start, stop, query, and list an outgoing ISDN-PRI test call. These commands are as follows:

[clear isdn-testcall](#) <grp>/<mbr> (stop)

[list isdn-testcall](#) (list)

[status isdn-testcall](#) <grp>/<mbr> (query)

[test isdn-testcall](#) <grp>/<mbr> [minutes] (start)

**⇒ NOTE:**

Before placing an outgoing ISDN-PRI test call, verify that the FAC on the System Features Form has been administered as well as the Far End Test Line No and TestCall Bearer Capability Class (BCC) on the Trunk Group Administration Form. Furthermore, if the ISDN-PRI trunk is of the "cbc" (call by call) service type, then the `Testcall Service` field on Trunk Group Administration Form must have been administered also.

To initiate an outgoing ISDN-PRI test call in the asynchronous method, issue the following command:

```
test isdn-testcall <grp>/<mbr> [minutes]
```

This command enables you to specify a specific the trunk on which to originate the ISDN-PRI test call.

**⇒ NOTE:**

The optional qualifier can also be used that specifies in minutes the duration of the test call. If no duration is specified, the default duration is used which is 8.4 or 9.6 seconds. The qualifier "minutes" accepts the numeric values one through 120 (that is, two hours = 120 minutes).

[Figure 2-10](#) shows a typical response to the **test isdn-testcall** command:

```
test isdn-testcall

Port      Maintenance Name  Test Number  Test Result  Error Code
1B1501    ISDN-TRK         258         PASS
```

**Figure 2-10. Typical response to test isdn-testcall command**

## Field descriptions

Port	Port address: <b>PCSSpp</b> (cabinet-carrier-slot-circuit)
Maintenance Name	Name of maintenance object
Test Number	The actual test that was run.
Test Result	Test result: Pass, Fail, Abort
Error Code	Numeric code explaining why the release failed or aborted. Refer to the detailed list of the codes by test number for each MO or see <a href="#">"ISDN-TRK (DS1 ISDN Trunk)" on page 5-722</a> .

The functions of the **clear**, **list**, and **status** commands associated with the ISDN Testcall are summarized in the following list. For more detailed information, refer to the appropriate sections as directed.

- **Clear isdn-testcall <grp>/<mbr>** enables you to cancel an in-progress ISDN-PRI test call and allow another test call to start. For details on this command, refer to the [“clear isdnpri-testcall”](#) command in [Chapter 4, “Maintenance Commands for DEFINITY ONE”](#).
- **List isdn-testcall <grp>/<mbr>** enables you to list all the ISDN-PRI trunks in use for an ISDN-PRI test call in the system. For details on this command, refer to the [“list testcalls”](#) command in [Chapter 4, “Maintenance Commands for DEFINITY ONE”](#).
- **Status isdn-testcall <grp>/<mbr no> [minutes]** enables you to check on the progress of an outgoing test call. When an outgoing ISDN-PRI test call completes in a specific port network, another ISDN-PRI trunk from the same port network is available for testing (regardless of whether the **status** information has been displayed). For details on this command, refer to the [“status isdn-testcall”](#) command description in [Chapter 4, “Maintenance Commands for DEFINITY ONE”](#).

## Troubleshooting the outgoing isdn-testcall command

---

If the TestCall BCC field appears on the Trunk Group Administration Form, make sure the TestCall BCC field indicates the correct BCC for the service provisioned on the ISDN-PRI trunk. The TestCall BCC values are defined as follows:

- 0 — Voice
- 1 — Digital Communications Protocol Mode 1
- 2 — Mode 2 Asynchronous
- 3 — Mode 3 Circuit
- 4 — Digital Communications Protocol Mode 0 (usually the default).

### ⇒ NOTE:

If the ISDN-PRI trunk is of type “cbc,” make sure the TestCall Service field on the Trunk Group Administration Form indicates the correct service so that a network facility message can be sent across the ISDN-PRI network

If the outgoing ISDN-PRI test call keeps aborting, please make sure that the far-end device can handle DCP Mode 0 or DCP Mode 1.

### ⇒ NOTE:

Before attempting to make an ISDN-PRI test call to the public network (that is, the network is the far-end), make sure that test call service is provisioned by the network. The user must subscribe to Test Type 108 service and have the correct far-end test call number administered on the trunk group form for the call to be allowed.

## Install DS1 CPE loopback jack (T1 only)

---

Using the DS1 CPE Loopback Jack (apparatus code 700A, comcode 107988867), a technician can test the DS1 span between the system and the network interface point. The 700A can quickly isolate DS1 problems to either the customer premises or to the external DS1 span.

The 700A loopback jack is required when DC power appears at the interface to the ICSU. *The loopback jack isolates the ICSU from the DC power and properly loops the DC span power.* The 700A is also used when no smart jack is installed by the local phone company.



### NOTE:

The loopback jack operates with any vintage of TN767E (or later) or TN464F (or later) DS1 circuit packs. The loopback jack operates with the 120A2 (or later) Integrated Channel Service Unit (ICSU) only; *not* the 31xx series of CSUs, other external CSUs, or earlier ICSUs.

## Loopback jack installation

---

### Configurations using a Smart Jack

The preferred location of the loopback jack is at the interface to the Smart Jack. This provides maximum coverage of CPE wiring when remote tests are run using the loopback jack. If the Smart Jack is not accessible, install the loopback jack at the extended demarcation point.

1. If there is no extended demarcation point, install the loopback jack directly at the network interface point as shown in [Figure 2-11 on page 2-45](#).
2. If there is an extended demarcation point and the Smart Jack is not accessible, install the loopback jack as shown in [Figure 2-12 on page 2-46](#).
3. If there is an extended demarcation point, but the Smart Jack is accessible, install the loopback jack as shown in [Figure 2-13 on page 2-47](#).

### Configurations without a Smart Jack

1. Install the loopback jack at the point where the cabling from the ICSU plugs into the “dumb” block. If there is more than one “dumb” block, choose the one that is closest to the Interface Termination feed or the fiber MUX. This provides maximum coverage for loopback jack tests. Refer to [Figure 2-14 on page 2-48](#) and [Figure 2-15 on page 2-49](#).

## Installation

1. To install the loopback jack, simply disconnect the RJ-48 (8-wide) connector (typically an H600-383 cable) at the appropriate interface point and connect the loopback jack in series with the DS1 span. See [Figure 2-11 on page 2-45](#) through [Figure 2-15 on page 2-49](#).
2. Plug the H600-383 cable from the ICSU into the female connector on the loopback jack.
3. Plug the male connector on the loopback jack cable into the network interface point.

**NOTE:**

Do not remove the loopback jack after installation. This is not a test tool and should always be available to remotely test a DS1 span.

## Administration

---

1. At the management terminal, enter **change ds1 <location>**. The “location” is the DS1 interface circuit pack for which the loopback jack was installed.
2. Be sure the “near-end CSU type” is set to `integrated`.
3. On page 2 of the form, change the supply CPE loopback jack power field to `y`.

**NOTE:**

Setting this field to `y` informs the technician that a loopback jack is present on the facility. This allows a technician to determine that the facility is available for remote testing.

4. Enter [save translation](#) to save the new information.

## DS1 span test

---

This test should only be performed after the DS1 circuit pack and the 120A2 (or later) ICSU have been successfully tested using appropriate maintenance procedures. The DS1 span test consists of 2 sequential parts. Each part provides a result indicating if there is a problem in the CPE wiring. CPE wiring may be considered problem-free only if the results of both parts are successful.

The first part of the span test powers-up the loopback jack and attempts to send a simple code from the DS1 board, through the wiring and loopback jack, and back to the DS1 board. Maintenance software waits about 10 seconds for the loopback jack to loop, sends the indication of the test results to the management terminal, and proceeds to the second part of the test.

The second part of the test sends the standard DS1 3-in-24 stress testing pattern from the DS1 board, through the loopback jack, and back to a bit error detector and counter on the DS1 board. The bit error rate counter may be examined at will via the management terminal, and provides the results of the second part of the test. The test remains in this state until it is terminated so that the CPE wiring may be bit error rate tested for as long as desired.

1. Busy out the DS1 circuit pack by entering **busyout board UCCSS** (where UCCSS is the cabinet, carrier, and slot number of the DS1 board).
2. At the management terminal, enter **change ds1 <location>** and verify the near-end csu type is set to integrated.
3. Change to page 2 of the DS1 administration form and confirm that the TX LBO field is 0dB. If not, record the current value and change it to 0dB for testing. Press Enter to implement the changes or press Cancel to change nothing.
4. Enter **test ds1-loop <location> cpe-loopback-jack**. This turns on simplex power to the loopback jack and waits about 20 seconds for any active DS1 facility alarms to clear. A "PASS" or "FAIL" displays on the terminal. This is the first of the 2 results. A "FAIL" indicates a fault is present in the wiring between the ICSU and the loopback jack. The loopback jack may also be faulty. A "PASS" only indicates that the loopback jack looped successfully, not that the test data contains no errors. If a "PASS" is obtained, continue with the following steps.

**⇒ NOTE:**

The loss of signal (LOS) alarm (demand test #138) is not processed during this test while the 3-in-24 pattern is active.

5. Enter **clear meas ds1 loop <location>** to clear the bit error count.
6. Enter **clear meas ds1 log <location>** to clear the performance measurement counts.
7. Enter **clear meas ds1 esf <location>** to clear the ESF error count.
8. Enter **list meas ds1 sum <location>** to display the bit error count. Refer to [Table 2-5 on page 2-42](#) for troubleshooting information.

Table 2-5. DS1 span troubleshooting

Displayed Field	Function	Indication
Test: cpe-loopback-jack	Pattern 3-in-24	The loopback jack test is active.
Synchronized	Y or N	If “y” displays, the DS1 circuit pack has synchronized to the looped 3-in-24 pattern and is accumulating a count of the bit errors detected in the pattern until the test has ended. If n displays, retry the test 5 times by ending the test per Step 11 and re-starting the test per Step 4. If the circuit pack never synchronizes, substantial bit errors in the 3-in-24 pattern are likely. This could be intermittent connections or a broken wire in a receive or transmit pair in the CPE wiring.
Bit Error Count	Cumulative count of detected errors	<p>If there are no wiring problems, the counter remains at 0.</p> <p>A count that pegs at 65535 or continues to increment by several hundred to several thousand on each <b>list meas</b> command execution indicates intermittent or corroded connections, severe crosstalk, or impedance imbalances between the two conductors of the receive pair or the transmit pair. Wiring may need replacement.</p> <p>Note that “ESF error events” counter and the ESF performance counter summaries (“errored seconds”, “bursty errored seconds”, and so forth) will also increment. These counters are not used with the loopback jack tests. However, they will increment if errors are occurring. Counters should be cleared following the test.</p>

- Repeat Steps 5 through 8 as desired to observe bit error rate characteristics. Also, wait 1 to 10 minutes between Steps 5 through 7. One minute without errors translates to better than a 1 in 10 to the eighth error rate. Ten minutes without errors translates to better than a 1 in 10 to the ninth error rate.

10. If the test runs for 1 minute with an error count of 0, confirm that the 3-in-24 pattern error detector is operating properly by entering **test ds1-loop <location> inject-single-bit-error**. This causes the 3-in-24 pattern generator on the DS1 circuit pack to inject a single-bit error into the transmit pattern. A subsequent **list meas ds1 summary <location>** command displays the bit error count. If a count greater than 1 is displayed, replace the ICSU and retest. If the problem continues, replace the DS1 circuit pack.
11. Terminate the test by entering **test ds1-loop <location> end cpe-loopback-jack-test**. Wait about 30 seconds for the DS1 to re-frame on the incoming signal and clear DS1 facility alarms.

Loopback termination fails under the following conditions:

- a. The span is still looped somewhere. This could be at the loopback jack, at the ICSU, or somewhere in the network. This state is indicated by a fail code of 1313. If the red LED on the loopback jack is on, replace the ICSU. Re-run the test and verify that the loopback test terminates properly. If not, replace the DS1 circuit pack and repeat the test.
  - b. The DS1 cannot frame on the incoming span's signal after the loopback jack is powered down. This means that there is something wrong with the receive signal into the loopback jack from the "dumb" block or the Smart Jack. If the service provider successfully looped and tested the span, up to the Smart Jack, this condition isolates the problem to the wiring between the loopback jack and the Smart Jack. Refer to "[Loopback Jack Fault Isolation Procedures](#)" for information on how to proceed in this case. The test cannot be successfully terminated until a good signal is received. To properly terminate the test before a good receive signal is available, enter **reset board <location>**.
12. Restore the TX LBO field to the original value recorded in Step [2](#).
  13. Release the DS1 circuit pack using the **release board PCSSpp** command.
  14. Leave the loopback jack connected to the DS1 span.

## Loopback Jack Fault Isolation Procedures

This section describes the possible DS1 configurations in which the loopback jack may be used. These configurations are: when the DS1 provider includes a Smart Jack, when no Smart Jack is provided at all, and when sites use fiber multiplexers.

## Configurations Using a Smart Jack


The addition of the loopback jack and the presence of a Smart Jack divides the DS1 span into 3 separate sections for fault isolation. These sections are shown in [Figure 2-11 on page 2-45](#) through [Figure 2-13 on page 2-47](#) for the different span configurations. They are:

- Section 1: Between the 120A2 (or later) ICSU and the loopback jack.
- Section 2: Between the loopback jack and the Smart Jack (network interface point).
- Section 3: From the Smart Jack to the CO. It is necessary to contact the DS1 provider to run this test.

A problem can exist in 1 or more of the 3 sections. The field technician is responsible for finding and correcting problems in the first 2 sections. The DS1 service provider is responsible for finding and correcting problems in the third section. Testing is divided into 3 steps.

- Test customer premises wiring (section 1 in the following 3 figures) from the ICSU to the loopback jack as described in “DS1 Span Test.”
- Test the CO-to-network interface wiring (section 3 in [Figure 2-11 on page 2-45](#)) using the Smart Jack loopback (CO responsibility). Coordinate this test with the DS1 provider.
- Test the short length of customer premises wiring (section 2 in the following 3 figures) between the loopback jack and the Smart Jack. This can be done using a loopback that “overlaps” section 2 of the cable. Any of the following loopbacks can do this:
  - a. The local ICSUs line loopback, which is typically activated, tested, and then deactivated by the DS1 service provider at the CO end.
  - b. The local DS1 interface’s payload loopback, activated and tested by the DS1 service provider at the CO end.
  - c. The far-end ICSU’s line loopback. This test is activated at the management terminal by entering **test ds1-loop <location> far-csu-loopback-test-begin**. The test is terminated by entering **test ds1-loop <location> end-loopback/span-test**. Bit error counts are examined as described in “DS1 Span Test.” This test method is the least preferable because it covers wiring that is not in the local portion of the span. This test only isolates problems to section 2 wiring if there are no problems in the wiring between the far-end CO and the far-end ICSU. Coordinate this test with the DS1 service provider.

If any of the above tests (a, b, or c) fail, a problem is indicated in section 2 as long as the tests for section 1 and section 3 pass. Since section 2 includes the network interface point, it is necessary to work with the service provider to isolate the fault to the loopback jack cable, the “dumb” block, or the Smart Jack.




prdfcs7 KLC 012797

**Figure notes:**

- |  |   |
|--|---|
| 1. Span Section 1  | 5. RJ-48 to Network Interface (Up to 1000 Feet) (305 m) |
| 2. Span Section 2  | 6. Loopback Jack  |
| 3. Span Section 3  | 7. Network Interface Smart Jack                         |
| 4. 120A2 (or later) Integrated Channel Service Unit (ICSU) | 8. Interface Termination or Fiber MUX                   |
|  | 9. Central Office                                       |

**Figure 2-11. Network interface at Smart Jack**

2 Maintenance Procedures for DEFINITY ONE Compact Modular Cabinets  
Install DS1 CPE loopback jack (T1 only)




pdfcs4 KLC 012797

**Figure notes:**

- 1. Span Section 1
- 2. Span Section 2
- 3. Span Section 3
- 4. 120A2 (or later) Integrated Channel Service Unit (ICSU)
- 5. RJ-48 to Network Interface (Up to 1000 Feet) (305 m)
- 6. Loopback Jack
- 7. "Dumb" Block (Extended Demarcation)
- 8. Network Interface Smart Jack
- 9. Interface Termination or Fiber MUX
- 10. Central Office

**Figure 2-12. Network interface at extended demarcation point (Smart Jack inaccessible)**



prdfcs5 KLC 012797

**Figure Notes:**


- |  |  |
|--|--|
| 1. Span Section 1  | 6. "Dumb" Block (Extended Demarcation) |
| 2. Span Section 2  | 7. Loopback Jack                       |
| 3. Span Section 3  | 8. Network Interface Smart Jack        |
| 4. 120A2 (or later) Integrated Channel Service Unit (ICSU) | 9. Interface Termination or Fiber MUX  |
| 5. RJ-48 to Network Interface (Up to 1000 Feet) (305 m)    | 10. Central Office                     |
|  | 11. "Dumb" Block to Smart Jack RJ-48   |

**Figure 2-13. Network interface at extended demarcation point (Smart Jack accessible)**

**Configurations without a Smart Jack**

When the loopback jack is added to a span that does not contain a Smart Jack, the span is divided into 2 sections. See [Figure 2-14](#) and [Figure 2-15 on page 2-49](#).

1. ICSU to the loopback jack.
2. Loopback jack to the Central Office (CO).




prdfcs8 KLC 012497

**Figure notes:**

- |  |                                       |
|--|---------------------------------------|
| 1. Span Section 1  | 5. Loopback Jack                      |
| 2. Span Section 2  | 6. "Dumb" Block (Demarcation Point)   |
| 3. 120A2 (or later) Integrated Channel Service Unit (ICSU) | 7. Interface Termination or Fiber MUX |
| 4. RJ-48 to Network Interface (Up to 1000 Feet) (305 m)    | 8. Central Office                     |

**Figure 2-14. Network interface at "dumb" block**



prdfcs6 KLC 012497

**Figure notes:**

- |  |                                     |
|--|-------------------------------------|
| 1. Span Section 1  | 5. Loopback Jack                    |
| 2. Span Section 2  | 6. "Dumb" Block (Demarcation Point) |
| 3. 120A2 (or later) Integrated Channel Service Unit (ICSU) | 7. Repeater                         |
| 4. RJ-48 to Network Interface (Up to 1000 Feet) (305 m)    | 8. Fiber MUX                        |
|  | 9. Central Office                   |

**Figure 2-15. Network interface at "dumb" block with repeater line to fiber MUX**

Section 2 includes the short cable from the loopback jack to the "dumb" block demarcation point (part of the loopback jack). This is the only portion of section 2 that is part of customer premises wiring but is not covered in the loopback jack's loopback path.

A problem can exist in 1 or both of the 2 sections. The field technician is responsible for finding and correcting problems in section 1 and the loopback cable portion of section 2. The DS1 service provider is responsible for finding and correcting problems in the majority of section 2. Testing is divided into 2 steps.

1. Test customer premises wiring (section 1 in [Figure 2-14](#)) from the ICSU to the loopback jack as described in the “DS1 Span Test” section.
2. Test the loopback jack-to-”dumb” block and ”dumb” block-to-CO wiring (section 2 in [Figure 2-14](#)). This can be done using a loopback that ”overlaps” the section of the span. Any of the following loopbacks can do this:
  - a. The local ICSUs line loopback, which is typically activated, tested, and then deactivated by the DS1 service provider at the CO end.
  - b. The local DS1 interface’s payload loopback, activated and tested by the DS1 service provider at the CO end.
  - c. The far-end ICSU’s line loopback. This test is activated at the management terminal by entering **test ds1-loop <location> far-csu-loopback-test-begin**. The test is terminated by entering **test ds1-loop <location> end-loopback/span-test**. Bit error counts are examined as described in the “DS1 Span Test” section. This test only isolates problems to section 2 wiring if there are no problems in the wiring between the far-end CO and the far-end ICSU. Coordinate this test with the DS1 service provider.

If any of the above tests (a, b, or c) fail, a problem is indicated in section 2. This could mean bad loopback jack -to-”dumb” block cabling, but is more likely to indicate a problem somewhere between the ”dumb” block and the CO. This is the responsibility of the DS1 service provider. If the DS1 Span Test confirms that there are no problems in section 1, the technician should proceed as follows to avoid unnecessary dispatch.

- Identify and contact the DS1 service provider
- Inform the DS1 provider that loopback tests of the CPE wiring to the ”dumb” block (section 1) showed no problems
- If the far-end ICSU line loopback test failed, inform the DS1 provider
- Request that the DS1 provider perform a loopback test of their portion of the section 2 wiring by sending someone out to loop section 2 back to the CO at the ”dumb” block.

If this test fails, the problem is in the service provider’s wiring.

If the test passes, the problem is in the cable between the loopback jack and the ”dumb” block. Replace the loopback jack.

## Configurations using fiber multiplexers

---

Use the loopback jack when customer premises DS1 wiring connects to an on-site fiber multiplexer (MUX) and allows wiring to the network interface point on the MUX to be remotely tested. This requires that ICSUs be used on DS1 wiring to the MUX.

Fiber MUXes can take the place of Interface termination feeds as shown in [Figure 2-11](#), [Figure 2-12](#), [Figure 2-13](#), and [Figure 2-14](#). Test these spans using the same procedures as metallic spans. Note the following points:

1. Fiber MUXes may have loopback capabilities that can be activated by the service provider from the CO end. These may loop the signal back to the CO or back to the DS1 board. If the MUX provides the equivalent of a line loopback on the “problem” DS1 facility, this may be activated following a successful loopback jack test and used to isolate problems to the wiring between the loopback jack and the MUX.
2. Be aware that there are installations that use repeatered metallic lines between the MUX and the “dumb” block. These lines require DC power for the repeaters and this DC power is present at the “dumb” block interface to the CPE equipment. *A loopback jack is required in this configuration to properly isolate and terminate the DC power.*

To check for the presence of DC, make the following 4 measurements at the network interface jack:

1. From Transmit Tip (T, Pin 5) to Receive Tip (T1, Pin 2)
2. From Transmit Ring (R, Pin 4) to Receive Ring (R1, Pin 4)
3. From Transmit Tip (T, Pin 5) to Transmit Ring (R, Pin 4)
4. From Receive Tip (T1, Pin 2) to Receive Ring (R1, Pin 4)

All measurements should read 0 (zero) volts DC. For pin numbers and pin designations, refer to *Integrated Channel Service Unit (ICSU) Installation and Operation*, (555-230-193).

## Multimedia call handling

---


- [“Expansion Services Module”](#)
- [“Troubleshooting MMCH”](#)

### Expansion Services Module

---

The Expansion Services Module (ESM) shown in [Figure 2-16](#) provides T.120 data sharing capability on a MMCH multipoint H.320 video conference. Each conference participant must have endpoints administered and a personal computer with the H.320 video application installed. The DEFINITY ECS must have the expansion service module installed.

---



#### Figure Notes

1. Port B Y-cable connector to a TN787 Multimedia Interface (MMI) circuit pack
2. Port A Y-cable connector to a TN2207 PRI circuit pack
3. 25-pair Y-cable
4. 356A adapter
5. D8W cord connected to 356A adapter port 1
6. Expansion Service Module (ESM)
7. Port B on compatible primary rate interface (PRI) card

---

Figure 2-16. Typical ESM connections

#### CAUTION:

*The TN2207 circuit pack is the only pack allowing connection of an ESM to the DEFINITY ECS switch.*

## Troubleshooting MMCH

---

- ["64 Kbps calls terminate but far end receives 56 Kbps indication"](#)
- ["Calls terminate with no audio"](#)
- ["Some parties cannot be heard by others \(audio subsetting\)"](#)
- ["Calls terminate with no video"](#)
- ["Calls terminate correctly but are unstable"](#)
- ["Synchronization"](#)
- ["Voice-activated switching problems"](#)
- ["No switching, full motion video"](#)
- ["Video never switches to a particular party"](#)
- ["Audio echo"](#)
- ["Endpoint or I-MUX in loopback mode"](#)

Before troubleshooting any problems associated with the DEFINITY MMCH, always be sure that the endpoint is operating correctly (audio, video, and data) by making point-to-point test calls. If possible, make the test calls over the network to test the connectivity and routing of network calls from the endpoint. This eliminates problems such as disconnected audio or video cables and network troubles.

### 64 Kbps calls terminate but far end receives 56 Kbps indication

#### Description

Some 2x64 Kbps conferences on the DEFINITY MMCH do not establish because of framing, audio, or video problems.

For calls that are routed in the network through a Lucent Technologies/LEC interface, the originating equipment may launch a 64 Kbps call attempt, and the far end receives either a 56 Kbps or 64 Kbps indication. If the far end receives a 64 Kbps indication, the call may have used 56 Kbps facilities. If so, the call may exhibit any of the following conditions:

- No handshaking in one direction or both (call disconnects after timeouts)
- Call connects, but audio or video is corrupted (audio noise or no video)
- Call succeeds without disruption (this is the least likely since one endpoint must be aware that the call is really 56 Kbps to connect)

If any of the above conditions occur, then 64 Kbps calls from the site are blocked.

#### Solution

Administer the conference for connection at 56 Kbps.

## Calls terminate with no audio

### Description

To support endpoints that do not support Multipoint Command Conference (MCC), the DEFINITY MMCH changes its capability set and initiates a capability set exchange with the endpoint when the Selected Communications Mode (SCM) changes. If the endpoint does not follow the SCM audio mode, the MCU may include the endpoint as a secondary (audio only) endpoint. If the endpoint sends an unknown or unsupported audio mode, then the TN788B decoder port mutes the endpoint from the conference. The user may hear the conference but may not be heard by other parties in the conference.

### Solution

1. Use the Status Conference x form and check the Audio Mode field for the current operating mode of the conference.
2. Another indication of the audio modes is in the "Incoming Mode Commands from Endpoint and Outgoing Commands from MMI" on page 3 of the Status Conference x Endpoint y form. Check the `Audio` fields under the Mode Commands/Communication Modes section of the form.

## Some parties cannot be heard by others (audio subsetting)

### Description

Problems where varying subsets of the conference hear different things may have problems with the various summing resources/groups that are in use. Traditionally these faults are caused by the SPE not cleaning up the connections properly. Isolation and diagnosis should focus on the VC resources in use by that conference.

### Solution

1. Use the **status conference** command to list the VC resources in use by this conference. Try a hot replacement of any VC boards in use, which refreshes the VC translations and move all of the audio connections to different VC ports.
2. If the problem still exists, try dropping the conference and then bringing the conference back up again. Not only does this refresh VC translations, but uses different timeslots as well.
3. If the problem still exists, suspect a hardware problem. If practical, wait for the DEFINITY MMCH to be idle (no active conferences), and then check the circuit packs for active (yellow) LEDs. If any of these are unexpected, such as on a VC board, try replacing the board and then bringing the conference up again.

## Calls terminate with no video

### Description

Generally, loss of video can be divided into 2 types. The first occurs when the DEFINITY MMCH switches to the endpoint, but nobody sees them. The receivers see either "black" video or a frozen image of the previous speaker depending on the codec of the manufacturer. The type occurs when the DEFINITY MMCH does not switch to an endpoint.

### Solution

In the first type described above, wiring problems, power to the camera, or video encoder circuit pack problems in the codec are typical causes.

In the second type, no video from an endpoint typically occurs because it is not a valid video source. This can be checked by looking at page 1 of the Status Conference x Endpoint y Vid form under the Capability section. In this section, a "y" or "c" suggests that the endpoint has video. An "e" means ept has not declared any video capability in cap set, "n" is audio only, and "blank" means audio add-on.

Also check page 1 of the Status Conference x Endpoint y Vs form for indication of the video state for the endpoint values.

## Calls terminate correctly but are unstable

### Description

A number of conditions will lead to some or all endpoints having stability problems during the course of a conference. A lack of stability from an endpoint is noticeable by a lack of a video switching while the party is the only talker or excessive disconnects from that endpoint.

## Synchronization

Generally, the most common problem is a mismatch in synchronization sources between the endpoint and the DEFINITY MMCH. This typically causes low-level (Px64) handshake problems that can trigger the endpoint/MMCH to disconnect the call. The MCCH's timers are set to sufficiently high values so that, normally, the endpoint will timeout and disconnect first. If installed in a customer network, it is a good idea to perform an audit of the path synchronization is being supplied. If there are different clock sources between endpoints and the DEFINITY MMCH, some problems are sure to occur. The severity of these problems can range from a handshake failure every few seconds to one per day. Depending on the type of endpoint, this can cause the endpoint to disconnect or just freeze video until the main problem is resolved.

Specifically, PictureTel System 4000 endpoints seem to be the most sensitive to instability. The Lucent Technologies Vistium also disconnects fairly infrequently. Last, the CLI Rembrandt II VP freezes video and waits for framing to be recovered.

## Network configuration concerns with synchronization

When auditing a network for synchronization, avoid unnecessary hops. Thus, a switch providing star-configuration synchronization is preferred over a daisy-chain configuration. Additionally, if there are DEFINITY PBXs that have EPNs, synchronization should be provided to sub nodes from the same port network through which the PBX receives its synchronization. Passing synchronization through the PBX Expansion Interface adds an unnecessary hop to the path and creates another potential point of failure.

## Expansion Interface duplication

If a customer's network uses PBX EPNs with duplicated Expansion Interfaces, scheduled switching of the Expansion Interface links should be disabled on the PBX via **change system-parameters maintenance**. When scheduled maintenance runs and switches the links, there is a brief corruption of the data path. If endpoints have active calls when the switch occurs, this corruption of the data path causes Px64 handshake problems, which lead to the endpoints losing video source status, and sometimes disconnecting as described above. Disabling the EI switching is in the customer's best interest to prevent the disruption of the Px64 data stream. The customer will get the same level of alarm indications and maintenance on the EI links, regardless of the status of scheduled switching.

## PRI D-channel backup

A somewhat unlikely source of call stability problems occur where the translations for PRI D-channel Backup between two non-MCU switches were incorrect. As an example, on switch A, DS1 1A10 was designated as the primary source, and on switch B, the corresponding DS1 was designated as the secondary source. When scheduled maintenance was run on the switch that had an active standby D-channel, an audit disconnected some calls using the link. The problem was corrected when the D-channel primary/secondary assignments matched.

## Processor duplication on the PBX

Do not enable the PI link switch on scheduled maintenance. This can cause link stability problems on the Accunet Bandwidth Controller (ABC).

## Voice-activated switching problems

Voice-activated switching on the DEFINITY MMCH does not follow the loudest talker. The MMCH queues all speaking parties and selects a new video broadcaster (the second-oldest speaking party) when the oldest speaking party has stopped talking. The new broadcaster will see the last speaker as its video. The system can also "learn" about the noise coming from an endpoint to help prevent false switches, adapting both to noise level and repetitive sounds such as a fan. This adaptation occurs over approximately 10 seconds.

## No switching, full motion video

If a room is excessively noisy, the DEFINITY MMCH may receive sufficient audio signal to conclude that there is a speaker present. Use the Status Conference X form to determine if the MMCH thinks an endpoint is talking. The MMCH sets the `Ts` field to `t` for each endpoint if there is voice energy detected. This endpoint may have to mute when nobody at the site is speaking to allow the conference to proceed normally. Remind the customer that it may be necessary to mute if a side conversation is going on in the background, just as one would do in an audio conference. If the system does not switch broadcasters even after the current broadcaster has muted, check the conference administration using the **display conference X** command to ensure that the conference is in voice-activated mode. Also verify that parties who were speaking are valid video sources as described in the "[Calls terminate with no video](#)" section above.

The See-Me feature (MCV) can also cause VAS to "lock-up." An endpoint can activate MCV to force their site to become the broadcaster. If they do not disable the feature when finished, the system remains in this mode indefinitely. Beginning with Release 3.0, the **status conference X** command shows that MCV is in effect by displaying `av` in the Video Status (Vs) column. Page 3 of the Status Conference X Endpoint Y form also has a `Broadcaster` field that indicates MCV is in effect with (SEE-ME) as the broadcaster. The same scenario can occur in a CHAIR or UCC-controlled conference with a designated broadcaster. In this situation the CHAIR/UCC has not released the designated broadcaster and returned to VAS mode. If there is a UCC-designated broadcaster, **status conference X** indicates a Video Status of `u`. Also, for UCC rollcall the return video may appear to be stuck. Check the Video Status for an "R," indicating rollcall.

If none of the examples above appears to be the cause, and if the room was quiet, all speakers are valid video sources, the conference is voice-activated, and the speaker can be heard, then escalate the problem.

## Video never switches to a particular party

### Description

Verify that the endpoint is a valid video source as described in the "[Calls terminate with no video](#)" section above. If it is, then the audio from the endpoint may not have sufficient voice signal for the hardware to determine the parties at the endpoint are speaking. Check the `Talk` field on page three of the Status Conference X Endpoint Y form to see if the `talking` bit is `y`. Next, check the audio by standing adjacent to the microphone and speaking at a normal level.

## Solution

If the audio is not muffled:

1. Use the **status conference** command to determine which port on the TN788B (VC board) is connected to this endpoint.
2. Check the VC (TN788B) board using the **test board xxyy long** command.
3. Drop the call.
4. Find another available port, then:
  - a. Busyout the port to which the endpoint was connected.
  - b. Make another call to the same conference. If the problem corrects itself, then the previous port may be bad. If there are other VC boards with sufficient available ports to replace calls on the current VC, then pull the board that has the bad endpoint on it (the **status conference** command displays the encoder port associated with the call). The system will automatically reestablish the VC connections without dropping the call. If this fixes the problem, then replace the board, as it has at least one bad port. Reseating the board may temporarily fix the problem due to the hard reset done to the board.

## Audio echo

Echo in conference calls, particularly those with large delay characteristics, is totally disruptive. When Voice Activated Switching is taken into account, the effects are disastrous. Various arrangements of the microphone(s) and room speaker(s) may be needed.

For some Lucent Technologies Vistium endpoints, if an external speaker is attached or was attached when the system was last rebooted, this endpoint will cause audio echo throughout the conference. First, isolate the offending endpoint by asking each endpoint to mute, one at a time, until the echo disappears.

If the input from an endpoint is located too close to the speakers of an endpoint, then acoustic echo is created. The microphone must be moved away from the speakers.

Normally, if any microphone in the room is moved relative to the speakers, that site will cause echo until the echo canceller in the codec retrains itself, some will require a manual reset. If a PictureTel keypad is configured with external microphones connected to the keypad, then the internal microphone and external microphone(s) "sing" to each other if the "ext mic" bat switch is set to "int mic" on the back of the keypad. In this configuration, VAS locked on that site, and the acoustic "singing" was inaudible.

## Rate adaptation

Because of a lack of a clear explanation in standards, sometimes endpoints do not work well with each other and the DEFINITY MMCH. The MMCH will only allow a conference to downgrade from 64kbps to 56 kbps operation on conferences that have the `Rate Adaptation` flag set to `y`.

When a downgrade does occur, information on the Status Conference form indicates the success or failure of the 64kbps-endpoints that are participants to properly rate adapt to 56kbps. As a general indication that the conference has rate adapted, the `Conference Transfer Rate` and `Effective Transfer Rate` fields show initial and current transfer rates, respectively. For each 64-kbps endpoint the column that indicates `Rate Adapt` shows an `n` if the endpoint did not follow the procedures as specified by the H.221. If an endpoint shows `y`, it did successfully rate adapt. If an endpoint shows `c`, it joined the conference at 56kbps.

Once the conference rate adapts, the endpoints that do not properly follow suit, will become audio-only endpoints. A conference will not rate adapt from 56 kbps back to 64 kbps until all endpoints disconnect from the conference and it idles.

The PictureTel 1000 Release 1.1C, PictureTel 6.01 software, and the Vistium 2.0 software successfully rate adapt with the MCU. External rate adaptation techniques used by VTEL and CLI are known to cause problems with the endpoint when used with this feature.

## Endpoint or I-MUX in loopback mode

Some endpoints have a loopback enable feature. This makes DEFINITY MMCH data loopback at the MMCH when a connection is in progress. The loopback can be enabled prior to or during a connection.

The MMCH does not detect the loop and continues to VAS. In most scenarios, the switch occurs, but within a few seconds, the broadcaster's return video becomes its own image. Once the broadcaster stops speaking, the system "false" switches to an apparently random port that was not speaking.

## TN760D tie trunk option settings

The TN760D Tie Trunk circuit pack interfaces between 4 tie trunks and the TDM bus. Two tip and ring pairs form a 4-wire analog transmission line. An E and M pair are DC signaling leads used for call setup. The E-lead receives signals from the tie trunk and the M-lead transmits signals to the tie trunk.

To choose the preferred signaling format ([Table 2-6](#) and [Table 2-7](#)), set the switches on the TN760D and administer the port using [Figure 2-17 on page 2-61](#) and [Table 2-8 on page 2-61](#).


**Table 2-6. Signaling Formats for TN760D**

Mode	Type
E & M	Type I Standard (unprotected)
E & M	Type I Compatible (unprotected)
Protected	Type I Compatible, Type I Standard
Simplex	Type V
E & M	Type V
E & M	Type V Revised

**Table 2-7. Signaling type summary**

Signaling Type	Transmit (M-Lead)		Receive (E-Lead)	
	On-Hook	Off-Hook	On-Hook	Off-Hook
Type I Standard	ground	battery	open <sup>1</sup> /battery	ground
Type I Compatible	open <sup>1</sup> /battery	ground	ground	open <sup>1</sup> /battery
Type V	open <sup>1</sup> /battery	ground	open	ground
Type V Reversed	ground	open	ground	open

1. An open circuit is preferred instead of battery voltage.



r758183 RBP 050896

Figure 2-17. TN760D tie trunk circuit pack (component side)

Table 2-8. TN760D option switch settings and administration

Installation situation		Preferred format	signaling	E&M/SMP LX switch	Prot/Unprot switch	Administered port
Circumstance	To	System	Far-End			
Co-Located	DEFINITY	E&M Type 1 Compatible	E&M Type 1 Standard	E&M	Unprotected	Type 1 Compatible
Inter-Building	DEFINITY	Protected Type 1 Compatible	Protected Type 1 Standard Plus Protection Unit	E&M	Protected	Type 1 Compatible
Co-Located	Net Integrated	E&M Type 1 Standard	Any PBX	E&M	Unprotected	Type 1


## TN464E/F option settings

The TN464E/F DS1/E1 Interface - T1/E1 circuit pack interfaces between a 24- or 32-channel Central Office/ISDN or tie trunk and the TDM bus.

Set the switches on the circuit pack to select bit rate and impedance match. See [Table 2-9](#) and [Figure 2-18](#).

**Table 2-9. Option switch settings on TN464E/F**

120 Ohms	Twisted pair
75 Ohms	Coaxial requiring 888B adapter
32 Channel	2.048 Mbps
24 Channel	1.544 Mbps



### Figure notes

- |                           |                                |
|---------------------------|--------------------------------|
| 1. Backplane Connectors   | 6. 120 Ohm (shown selected)    |
| 2. 24/32 Channel Selector | 7. 24 Channel (shown selected) |
| 3. 75/120 Ohm Selector    | 8. 75 Ohm                      |
| 4. Faceplate              | 9. Connector                   |
| 5. 32 Channel             | 10. TN464E/F                   |

**Figure 2-18. TN464E/F option settings**

## **Troubleshooting multimedia call handling (MMCH)**

---

Before troubleshooting any problems associated with the DEFINITY MMCH, always be sure that the endpoint is operating correctly (audio, video, and data) by making point-to-point test calls. If possible, make the test calls over the network to test the connectivity and routing of network calls from the endpoint. This eliminates problems such as disconnected audio or video cables and network troubles.

### **64 Kbps calls terminate but far end receives 56 Kbps indication**

---

#### **Description**

Some 2x64 Kbps conferences on the DEFINITY MMCH do not establish because of framing, audio, or video problems.

For calls that are routed in the network through a Lucent Technologies/LEC interface, the originating equipment may launch a 64 Kbps call attempt, and the far end receives either a 56 Kbps or 64 Kbps indication. If the far end receives a 64 Kbps indication, the call may have used 56 Kbps facilities. If so, the call may exhibit any of the following conditions:

- No handshaking in one direction or both (call disconnects after timeouts)
- Call connects, but audio or video is corrupted (audio noise or no video)
- Call succeeds without disruption (this is the least likely since one endpoint must be aware that the call is really 56 Kbps to connect)

If any of the above conditions occur, then 64 Kbps calls from the site are blocked.

#### **Solution**

Administer the conference for connection at 56 Kbps.

### **Calls terminate with no audio**

---

#### **Description**

To support endpoints that do not support Multipoint Command Conference (MCC), the DEFINITY MMCH changes its capability set and initiates a capability set exchange with the endpoint when the Selected Communications Mode (SCM) changes. If the endpoint does not follow the SCM audio mode, the MCU may include the endpoint as a secondary (audio only) endpoint. If the endpoint sends an unknown or unsupported audio mode, then the TN788B decoder port mutes the endpoint from the conference. The user may hear the conference but may not be heard by other parties in the conference.

## Solution

1. Use the Status Conference x form and check the Audio Mode field for the current operating mode of the conference.
2. Another indication of the audio modes is in the "Incoming Mode Commands from Endpoint and Outgoing Commands from MMI" on page 3 of the Status Conference x Endpoint y form. Check the `Audio` fields under the Mode Commands/Communication Modes section of the form.

## Some parties cannot be heard by others (audio subsetting)

### Description

Problems where varying subsets of the conference hear different things may have problems with the various summing resources/groups that are in use. Traditionally these faults are caused by the SPE not cleaning up the connections properly. Isolation and diagnosis should focus on the VC resources in use by that conference.

### Solution

1. Use the **status conference** command to list the VC resources in use by this conference. Try a hot replacement of any VC boards in use, which refreshes the VC translations and move all of the audio connections to different VC ports.
2. If the problem still exists, try dropping the conference and then bringing the conference back up again. Not only does this refresh VC translations, but uses different timeslots as well.
3. If the problem still exists, suspect a hardware problem. If practical, wait for the DEFINITY MMCH to be idle (no active conferences), and then check the circuit packs for active (yellow) LEDs. If any of these are unexpected, such as on a VC board, try replacing the board and then bringing the conference up again.

## Calls terminate with no video

### Description

Generally, loss of video can be divided into 2 types. The first occurs when the DEFINITY MMCH switches to the endpoint, but nobody sees them. The receivers see either "black" video or a frozen image of the previous speaker depending on the codec of the manufacturer. The type occurs when the DEFINITY MMCH does not switch to an endpoint.

## Solution

In the first type described above, wiring problems, power to the camera, or video encoder circuit pack problems in the codec are typical causes.

In the second type, no video from an endpoint typically occurs because it is not a valid video source. This can be checked by looking at page 1 of the Status Conference x Endpoint y Vid form under the Capability section. In this section, a "y" or "c" suggests that the endpoint has video. An "e" means ept has not declared any video capability in cap set, "n" is audio only, and "blank" means audio add-on.

Also check page 1 of the Status Conference x Endpoint y Vs form for indication of the video state for the endpoint values.

## Calls terminate correctly but are unstable

### Description

A number of conditions will lead to some or all endpoints having stability problems during the course of a conference. A lack of stability from an endpoint is noticeable by a lack of a video switching while the party is the only talker or excessive disconnects from that endpoint.

### Synchronization

Generally, the most common problem is a mismatch in synchronization sources between the endpoint and the DEFINITY MMCH. This typically causes low-level (Px64) handshake problems that can trigger the endpoint/MMCH to disconnect the call. The MCCH's timers are set to sufficiently high values so that, normally, the endpoint will timeout and disconnect first. If installed in a customer network, it is a good idea to perform an audit of the path synchronization is being supplied. If there are different clock sources between endpoints and the DEFINITY MMCH, some problems are sure to occur. The severity of these problems can range from a handshake failure every few seconds to one per day. Depending on the type of endpoint, this can cause the endpoint to disconnect or just freeze video until the main problem is resolved.

Specifically, PictureTel System 4000 endpoints seem to be the most sensitive to instability. The Lucent Technologies Vistium also disconnects fairly infrequently. Last, the CLI Rembrandt II VP freezes video and waits for framing to be recovered.

## Network configuration concerns with synchronization

When auditing a network for synchronization, avoid unnecessary hops. Thus, a switch providing star-configuration synchronization is preferred over a daisy-chain configuration. Additionally, if there are DEFINITY PBXs that have EPNs, synchronization should be provided to sub nodes from the same port network through which the PBX receives its synchronization. Passing synchronization through the PBX Expansion Interface adds an unnecessary hop to the path and creates another potential point of failure.

## PRI D-channel backup

A somewhat unlikely source of call stability problems occur where the translations for PRI D-channel Backup between two non-MCU switches were incorrect. As an example, on switch A, DS1 1A10 was designated as the primary source, and on switch B, the corresponding DS1 was designated as the secondary source. When scheduled maintenance was run on the switch that had an active standby D-channel, an audit disconnected some calls using the link. The problem was corrected when the D-channel primary/secondary assignments matched.

## Voice-activated switching problems

---

Voice-activated switching on the DEFINITY MMCH does not follow the loudest talker. The MMCH queues all speaking parties and selects a new video broadcaster (the second-oldest speaking party) when the oldest speaking party has stopped talking. The new broadcaster will see the last speaker as its video. The system can also “learn” about the noise coming from an endpoint to help prevent false switches, adapting both to noise level and repetitive sounds such as a fan. This adaptation occurs over approximately 10 seconds.

## No switching, full motion video

---

If a room is excessively noisy, the DEFINITY MMCH may receive sufficient audio signal to conclude that there is a speaker present. Use the Status Conference x form to determine if the MMCH thinks an endpoint is talking. The MMCH sets the  $T_s$  field to  $t$  for each endpoint if there is voice energy detected. This endpoint may have to mute when nobody at the site is speaking to allow the conference to proceed normally. Remind the customer that it may be necessary to mute if a side conversation is going on in the background, just as one would do in an audio conference. If the system does not switch broadcasters even after the current broadcaster has muted, check the conference administration using the **display conference X** command to ensure that the conference is in voice-activated mode. Also verify that parties who were speaking are valid video sources as described in the [“Calls terminate with no video”](#) section above.

The See-Me feature (MCV) can also cause VAS to “lock-up.” An endpoint can activate MCV to force their site to become the broadcaster. If they do not disable the feature when finished, the system remains in this mode indefinitely. Beginning with Release 3.0, the **status conference X** command shows that MCV is in effect by displaying `av` in the Video Status (Vs) column. Page 3 of the Status Conference X Endpoint Y form also has a `Broadcaster` field that indicates MCV is in effect with (SEE-ME) as the broadcaster. The same scenario can occur in a CHAIR or UCC-controlled conference with a designated broadcaster. In this situation the CHAIR/UCC has not released the designated broadcaster and returned to VAS mode. If there is a UCC-designated broadcaster, **status conference X** indicates a Video Status of `u`. Also, for UCC rollcall the return video may appear to be stuck. Check the Video Status for an “R,” indicating rollcall.

If none of the examples above appears to be the cause, and if the room was quiet, all speakers are valid video sources, the conference is voice-activated, and the speaker can be heard, then escalate the problem.

## Video never switches to a particular party

### Description

Verify that the endpoint is a valid video source as described in the “[Calls terminate with no video](#)” section above. If it is, then the audio from the endpoint may not have sufficient voice signal for the hardware to determine the parties at the endpoint are speaking. Check the `Talk` field on page three of the Status Conference X Endpoint Y form to see if the `talking bit` is `y`. Next, check the audio by standing adjacent to the microphone and speaking at a normal level.

### Solution

If the audio is not muffled:

1. Use the **status conference** command to determine which port on the TN788B (VC board) is connected to this endpoint.
2. Check the VC (TN788B) board using the **test board xxyy long** command.
3. Drop the call.
4. Find another available port, then:
  - a. Busyout the port to which the endpoint was connected.
  - b. Make another call to the same conference. If the problem corrects itself, then the previous port may be bad. If there are other VC boards with sufficient available ports to replace calls on the current VC, then pull the board that has the bad endpoint on it (the **status conference** command displays the encoder port associated with the call). The system will automatically reestablish the VC connections without dropping the call. If this fixes the problem, then replace the board, as it has at least one bad port. Reseating the board may temporarily fix the problem due to the hard reset done to the board.

## Audio echo

---

Echo in conference calls, particularly those with large delay characteristics, is totally disruptive. When Voice Activated Switching is taken into account, the effects are disastrous. Various arrangements of the microphone(s) and room speaker(s) may be needed.

For some Lucent Technologies Vistium endpoints, if an external speaker is attached or was attached when the system was last rebooted, this endpoint will cause audio echo throughout the conference. First, isolate the offending endpoint by asking each endpoint to mute, one at a time, until the echo disappears.

If the input from an endpoint is located too close to the speakers of an endpoint, then acoustic echo is created. The microphone must be moved away from the speakers.

Normally, if any microphone in the room is moved relative to the speakers, that site will cause echo until the echo canceller in the codec retrains itself, some will require a manual reset. If a PictureTel keypad is configured with external microphones connected to the keypad, then the internal microphone and external microphone(s) "sing" to each other if the "ext mic" bat switch is set to "int mic" on the back of the keypad. In this configuration, VAS locked on that site, and the acoustic "singing" was inaudible.

## Rate adaptation

---

Because of a lack of a clear explanation in standards, sometimes endpoints do not work well with each other and the DEFINITY MMCH. The MMCH will only allow a conference to downgrade from 64kbps to 56 kbps operation on conferences that have the `Rate Adaptation` flag set to `y`.

When a downgrade does occur, information on the Status Conference form indicates the success or failure of the 64kbps-endpoints that are participants to properly rate adapt to 56kbps. As a general indication that the conference has rate adapted, the `Conference Transfer Rate` and `Effective Transfer Rate` fields show initial and current transfer rates, respectively. For each 64-kbps endpoint the column that indicates `Rate Adapt` shows an `n` if the endpoint did not follow the procedures as specified by the H.221. If an endpoint shows `y`, it did successfully rate adapt. If an endpoint shows `c`, it joined the conference at 56kbps.

Once the conference rate adapts, the endpoints that do not properly follow suit, will become audio-only endpoints. A conference will not rate adapt from 56 kbps back to 64 kbps until all endpoints disconnect from the conference and it idles.

The PictureTel 1000 Release 1.1C, PictureTel 6.01 software, and the Vistium 2.0 software successfully rate adapt with the MCU. External rate adaptation techniques used by VTEL and CLI are known to cause problems with the endpoint when used with this feature.

## Endpoint or I-MUX in loopback mode

Some endpoints have a loopback enable feature. This makes DEFINITY MMCH data loopback at the MMCH when a connection is in progress. The loopback can be enabled prior to or during a connection.

The MMCH does not detect the loop and continues to VAS. In most scenarios, the switch occurs, but within a few seconds, the broadcaster's return video becomes its own image. Once the broadcaster stops speaking, the system "false" switches to an apparently random port that was not speaking.

**2** Maintenance Procedures for DEFINITY ONE Compact Modular Cabinets  
*Troubleshooting multimedia call handling (MMCH)*

*2-70*

# Global Administration Subsystem Commands

# 3

---

The global administration subsystem (GAS) provides a command line interface for administration and maintenance functions for functions in the DEFINITY ONE system that are not supported in other applications.

The GAS commands are executed from the command line of a telnet session to the DEFINITY ONE system.

To obtain a list of commands at the command line, type ["lucent help"](#) plus Enter. To expand options for a command, type the commands after lucent help.

## Command structure

GAS commands are special words and phrases instructing the system to perform a specific function. The commands are arranged in a hierarchy of keywords; that is, enter 1 command to go to a different level. The commands contain these parts:

- COMMAND NAME
- PARAMETERS
- OPTIONS

## Command name

The command name is typed in first at the telnet prompt. Commands will be displayed in this type face. Examples of GAS commands are lucent help, alarmstat, and backup.

## Parameters

---

A command may require additional information to complete its function. If this is the case, you must type in the appropriate parameter after the command. Parameters will be displayed inside of straight brackets [in this typeface], and listed in a table following the command with descriptions of what will occur with each parameter.

## Options

---

Options refers to characters that may be appended to the command line. Options may be prefaced with either a dash (-) or a slash (/).



NOTE:

*Options are printed in this typeface*, and are enclosed in curly brackets *{-h}*.

## bash commands

---

The following commands are useful for administration and installation tasks. These commands are allowed for the lucent1 login. After choosing the bash shell, type the name of the command.

**Table 3-1. Common bash commands for lucent1 login**

Command	Description
alarmorig (see page <a href="#">3-5</a> )	Turns on alarm origination from the GAM (INADS)
alarmstat (see page <a href="#">3-6</a> )	Gives global alarm status (major, minor, or none) for the GAM, DEFINITY, and AUDIX
autobackup (see page <a href="#">3-6</a> )	Enables and disables backup commands
backupparams (see page <a href="#">3-8</a> )	Enables day and time destination
backupsources (see page <a href="#">3-9</a> )	Selects the data to be backedup
cleargamalarm (see page <a href="#">3-7</a> )	Clears alarms after analysis
d1backup (see page <a href="#">3-11</a> )	No help

*Continued on next page*

Table 3-1. Common bash commands for lucent1 login — *Continued*

Command	Description
d1restore (see page <a href="#">3-13</a> )	No help
d1stat (see page <a href="#">3-14</a> )	Displays the status of all the applications groups running on the system.  Lists all the processes associated with an application that is only partially up and the status of each process (+ => up and - => down).  Lists all the processes associated with an application regardless of its state.
downloadboot (see page <a href="#">3-15</a> )	Enables download of boot image to firmware
environment (see page <a href="#">3-16</a> )	Determines if a circuit pack is too hot.
ftpserv (see page <a href="#">3-17</a> )	Installs patches and license files (INADS)
fileversion (see page <a href="#">3-17</a> )	Queries Windows NT for executable file
fwversion (see page <a href="#">3-18</a> )	Displays command version number
identbackup (see page <a href="#">3-20</a> )	No help
installbackup	No help
installconfig (see page <a href="#">3-21</a> )	Installs license file (INADS)
gamalarmstat (see page <a href="#">3-19</a> )	Displays GAM alarm information formatted as follows:  mm/dd/yyyy = month/day/year  NT Event Log Name= System   Security   Application  Alarm Source= NT   GAM   LAC   GSK   VFM   GAS  NT Event Type = Error   Warn   Info  Alarm Type = Major   Minor  Event ID= Event field in NT Event Log  ACKed= ACKed, NACKED, FAILURE, NO_OSS_RESPONSE

*Continued on next page*

Table 3-1. Common bash commands for lucent1 login — *Continued*

Command	Description
lucent help (see page <a href="#">3-21</a> )	Lists all commands
oss (see page <a href="#">3-22</a> )	Sets telephone numbers for outgoing INADS calls
pcAnywhere (see page <a href="#">3-23</a> )	If no argument is given, pcAnywhere will start. If ? is typed, help is displayed, if v is typed, the version of the command is displayed, and if c is typed, pcAnywhere is stopped.
post (see page <a href="#">3-23</a> )	If no argument is given, postcodes are sent to the 860 firmware with the results sent to standard output.
product id (see page <a href="#">3-24</a> )	If no argument is given, the command displays product-id information for GAM and AUDIX.
rasdrop (see page <a href="#">3-24</a> )	If no argument is given, rasdrop schedules the RAS service to stop and restart in 2 minutes from when it was run.
reboot (see page <a href="#">3-25</a> )	Reboots system as follows:  <b>nice:</b> Shuts down applications and Windows NT in a graceful manner  <b>immediate:</b> reboots the system without waiting for the applications to shut down, causing possible loss of voice messages that are being recorded and all calls drop
restartcause (see page <a href="#">3-25</a> )	Displays the restart causes for system (for technician/TSC)
serialnumber (see page <a href="#">3-27</a> )	Reads and displays the serial number of the circuit pack
setip (see page <a href="#">3-28</a> )	Sets the IP address, subnet mask, and default gateway of the LAN interface to the customer's LAN (out the splitter cable). Turns on RAS. Reboot is required for this to take effect.

*Continued on next page*

Table 3-1. Common bash commands for lucent1 login — *Continued*

Command	Description
shutdown (see page <a href="#">3-30</a> )	Shuts down: <b>all</b> : Lucent DEFINITY ONE applications <b>system</b> : all Lucent DEFINITY ONE applications and Windows NT <b>appName</b> : the name of the application to be shut down <b>camp-on</b> : (AUDIX feature) notifies users that a system shutdown will happen and waits for users to end their sessions before shutting down.
siteconfig (see page <a href="#">3-30</a> )	Prompts the user with a warning message and request confirmation
start (see page <a href="#">3-33</a> )	Called from a bash shell on Contry to start an application through Watchdog.
swversion (see page <a href="#">3-34</a> )	
terminate (see page <a href="#">3-35</a> )	Called from a bash shell on Contry to terminate applications
versiondiff (see page <a href="#">3-36</a> )	Compares NT executables against version entered at the command line
vilog	Merges and displays the various log files in the system

## alarmorig

This command will enable, disable or display the status of alarm origination to the OSS.

Command name	Parameter	Parameter description	Permissions	Defaults	Feature interactions
alarmorig	<i>none</i>	Displays current status (either "on" or "off").	lucent1 lucent2 lucent3 (display only)	none	none
	<i>on</i>	Enable OSS alarm reporting			
	<i>off</i>	Disable OSS alarm reporting			

### Format

```
alarmorig {on | off}
```

## alarmstat

This command displays alarms for all applications (Global, DEFINITY, AUDIX) running on DEFINITY ONE.

- You must view individual DEFINITY and AUDIX alarms in the appropriate applications. See [Chapter 6, “DEFINITY ONE NT Log Events and Alarms”](#) for procedures about how to view the alarm logs in the DEFINITY and AUDIX applications.
- Use the command [“gamalarmstat”](#) to view more details about global alarms.

Command name	Parameter	Parameter description	Permissions	Defaults	Feature interactions
<b>alarmstat</b>	<i>none</i>	<b>View active alarms</b>	lucent1 lucent2 lucent3	none	none

## Output

System Alarm Status:

Global: { major | minor | none }

Definity: { major | minor | none }

AUDIX: { major | minor | none }

Both major and minor alarms can appear on the output for each application if both types of alarms are present.

## autobackup

This command enables or disables automatic periodic backup of translation data. The backup time and selection of data are set with the “Schedbackup” command.

Command name	Parameter	Parameter description	Permissions	Defaults	Feature interactions
<b>autobackup</b>	<i>-y or /y</i>	<b>Enable automatic backup</b>	lucent1 lucent2 lucent3	none	Command will fail if backup parameters have not been administered
	<i>-e or /e</i>	<b>Enable automatic backup</b>			
	<i>-n or /n</i>	<b>Disable automatic backup</b>			
	<i>-d or /d</i>	<b>Disable automatic backup</b>			
	<i>-v or /v</i>	<b>Display version number</b>			

## Format

autobackup { -y | -n | -e | -d } <developers: should -v be included?>

## cleargamalarm

---

This command clears all global alarms.

Command name	Parameter	Parameter description	Permissions	Defaults
<b>cleargamalarm</b>	<b><i>all</i></b>	<b>Clear all GAM alarms.</b>	lucent1 lucent2 lucent3	none
	<b><i>nnn</i></b>	Clear the alarm with the alarm ID numbers specified by nnn		
	<b><i>nnn,mmm,...,xxx</i></b>	Clear the list of alarms specified by the alarm ID numbers in the comma separated list.		
	<b><i>nnn-xxx</i></b>	Clear all the alarms whose IDs are between nnn and xxx, inclusive.		

### Format

---

```
cleargamalarm {all | nnn | nnn,mmm,...,xxx | nnn-xxx }
```

### Example

---

To clear all alarms, enter:

```
cleargamalarm all
```

To clear alarms 1099 and 3422, enter

```
cleargamalarm 1099,3422
```

To clear all alarms between 500 and 889, enter

```
cleargamalarm 500-889
```

## backupparms

This command is used to administer or display the time and destination of the backup service.

### ⇒ NOTE:

If a network destination is entered for the destination parameter, DEFINITY ONE will attempt to access the location. If the location is not accessible, the destination parameter is saved, and a warning message is displayed.

Command Name	Parameter	Parameter Description	Permissions	Feature Interactions
<b>backupparms</b>	<i>none</i>	<b>Displays the current days, time and destination settings</b>	lucent1 lucent2 lucent3	
	<i>days</i>	Enter a number for the desired day(s) of the week, in the format 1234567, where 1 = Sunday 2 = Monday 3 = Tuesday 4 = Wednesday 5 = Thursday 6 = Friday 7 = Saturday		
	<i>time</i>	Enter the time of day in 24-hour format (HH:MM)		
	<i>dest</i>	Enter the destination for the backup: pcmcia = backup to the PCMCIA disk. Network directory path in the format \xxxx\yyyy		The directory is E:/backup  The network backup drive is fixed as drive F:

### Format

`backupparms days time dest`

### Example

To set backups for every Monday, Thursday and Saturday at 11:30 PM on the PCMCIA disk, enter:

```
backupparms 257 23:30 pcmcia
```

To set backups for Sunday at 4 AM to the network path F:\definityone\backups, enter:

```
backupparms 1 04:00 \definityone\backups
```

## backupsource

---

This command is used to select or view what data is backed up during an autobackup.

Command Name	Parameter	Parameter Description	Permissions	Defaults
<b>backupsource</b>	<i>none</i>	Displays the list of data sets administered for backup.	lucent1 lucent2 lucent3	
	<i>all</i>	All data sets with a ♦ in the “defaults” column are backed up with this command parameter.		Yes
	<i>deftran</i>	Backup DEFINITY translations		♦
	<i>registry</i>	Backup Windows NT system registry		♦
	<i>vmannounce</i>	Backup voice announcements		
	<i>vmmsgtran</i>	Backup voice messages and translations		
	<i>vmnammsgtran</i>	Backup voice names, messages, and translations		♦
	<i>vmnamtran</i>	Backup voice names and translations		
	<i>vmtran</i>	Backup voice mail translations		

### Format

---

*backupsource list\_of\_parameters*

*backupsource*

## Example

---

To back up all datasets, enter

```
backupparms all security vmannounce vmtran
```

To see what is scheduled for backup, enter:

```
backupparms
```

The following displays:

Automatic Backup Administration:

```
Enabled          yes | no
Data Sets        all
                  security
                  vmannounce
                  vmtran
Schedule         MM/DD - HH:MM (see NOTE, below)
Destination      pcmcia | \xxxx\yyyy (see NOTE, below)
Last             MM/DD - HH:MM
```

Where “last” is the date and time of the last automatic backup.



### NOTE:

The day and time, and destination is administered with the [“schedbackup”](#) command.

## d1backup

Start an immediate backup of selected data, or cancel a backup that is in progress.

Use this command for manual backups.

You can use the dataset administered in a previous `backsource` command, and the destination administered in a previous `schedbackup` command.

Command name	Parameter	Parameter description	Permissions	Defaults
<b>backup</b>	<i>none</i>	Displays backup settings	lucent1 lucent2 lucent3	
	<i>all</i>	All data sets with a ♦ in the “defaults” column are backed up with this command parameter.		Yes
	<i>-c</i>	Cancel the currently running backup operation (initiated either manually or automatically)		
	<i>dest</i>	Enter the destination for the backup:  pcmcia = backup to the PCMCIA disk. The directory is E:\contrybackup  Network directory path in the format \xxx\yyy The network backup drive is fixed as drive F:\{xxx\yyy}\contrybackup		
	<i>deftran*</i>	Backup DEFINITY translations		♦
	<i>registry*</i>	Backup Windows NT system registry		♦
	<i>vmannounce*</i>	Backup voice announcements		
	<i>vmmsgtran*</i>	Backup voice messages and translations		
	<i>vmnammsgtran*</i>	Backup voice names, messages, and translations		♦
	<i>vmnamtran*</i>	Backup voice names and translations		
	<i>vmtran*</i>	Backup voice mail translations		

\* These are identified as dataset parameters any or all of which may be separated by blank spaces

### Format

```
backup {dataset dest | -c}
```

## Example

---

To cancel a backup, enter

```
d1backup -c
```

To backup DEFINITY translation and AUDIX translation, enter

```
d1backup deftran vmtran pcmcia
```

To display the current backup settings, enter

```
d1backup
```

The following displays:

Backup Administration:

```
Enabled      yes | no
Data Sets    all
              security
              vmannounce
              vmtran
Schedule     MM/DD - HH:MM
Destination  pcmcia | \xxxx\yyyy
Last        MM/DD - HH:MM
```

## d1restore

This command restores or cancels a restore of data from a backup set.

Command name	Parameter	Parameter description	Permissions	Valid values
restore	<b>-c</b>	<b>Cancel a restore that is currently occurring. NOTE: The system may be in an unknown state after this operation.</b>	lucent1 lucent2 lucent3 agent1	
	<b>source</b>	Where the backup is located:		pcmcia for pcmcia disk \\xxx\yyyy for the pathname of the network disk
	<b>data-set</b>	the list of keywords indicating what data is to be restored. See below.		

Table 3-2. Data-set Keywords

Keyword	Definition	Notes
<b>all</b>	A combination of datasets are to be restored.	This will only work if the restore was done with the <i>all</i> keyword. If all the datasets are not present, the restore will fail. If this happens, you must specify the list of datasets.
<b>deftran</b>	Restore DEFINITY translations	
<b>registry</b>	Restore Windows NT system registry	
<b>vmannounce</b>	Restore voice announcements	
<b>vmmsgtran</b>	Restore voice messages and translations	
<b>vmnammsgtran</b>	Restore voice names, messages, and translations	
<b>vmnamtran</b>	Restore voice names and translations	
<b>vmtran</b>	Restore voice mail translations	

## Format

```
d1restore source data-set
d1restore -c
d1restore pcmcia deftran vmtran
```



### CAUTION:

*Canceling a restore may leave the DEFINITY ONE system in an unknown state. If translations are corrupted, the system may be inoperable.*

## d1stat

Displays the status of all the applications groups running on the system. By default all the groups and their status are listed. If a particular application group's name or a set of names are specified, then the output is restricted to the set of groups.

Possible applications groups:

NT	Windows NT basic services
*NTras	Remote Access server
NTweb	Web server
*pcAnywhere	pcAnywhere server
NTconsole	A user logged in to the monitor/keyboard/mouse
NTplatform	Third party software
CoResServ	Co Resident services
DEFINTIY	Phone call processing/PBX
CornerStone	Voice processing platform
AUDIX	Voice Mail
AUDIXNet	Mail interchange with other servers
MISC	other

\* = not required to be "up" for fully functional system

Command name	Parameter	Parameter description	Permissions	Defaults
<b>d1stat</b>	<i>none</i>	Displays the status of all the applications groups running on the system.	lucent1 lucent2 lucent3	
	<i>-l</i>	List all the processes associated with an application which is only PARTIALLY UP and the status of each process (+ => and - => down)		
	<i>-lv</i>	List all the process associated with an application regardless of its state.		

## Format

d1stat

## Example

---

The following displays:

```
estonia-lucent1>dlstat
NT          11/11 UP
NTTras     2/ 2 UP
NTweb      1/ 1 UP
pcAnywhere 0/ 1 DOWN
NTconsole  2/ 2 UP
NTplatform 6/ 6 UP
CoResServ  5/ 5 UP
DEFINITY   51/51 UP
CornerStone 4/ 4 UP
AUDIX      33/33 UP
AUDIXNet   0/ 5 DOWN
MISC       24/ 0 UP
nero-lucent1>
```

## downloadboot

---

This command downloads a new version of boot firmware.

Command name	Parameter	Parameter description	Permissions	Defaults
<b>downloadboot</b>	<b><i>source</i></b>	<b>Filename of the source file. This location must be accessible by the DEFINITY ONE system.</b>	lucent1 lucent2 lucent3	none

## Format

---

```
downloadboot source
```

## environment

This command displays environmental parameters on the TN795 processor circuit pack.

Command name	Parameter	Parameter description	Permissions	Defaults
environment	none	Displays current operating environment of the TN795 board.	lucent1 lucent2 lucent3	none

## Format

```
environment
```

## Output

```
temperature:
temp1: 85.29 deg F (29.60 deg C)
temp2: 81.38 deg F (27.43 deg C)

current minor alarm state:      OFF
current UPS alarm state:       OFF
current cabinet power/fan state: ON
current alarm output state:    OFF

Voltages:
actual      min          max
48V         -47.99V     -52.80V     -43.20V
VCC         -5.12V      -5.50V      -4.50V
+VCC        +5.07V      +4.50V      +5.50V
+VEE        +12.04V     +10.80V     +13.20V
3.3V        +3.33V      +2.97V      +3.63V

DEFINITY Red LED: OFF
DEFINITY Green LED: OFFMajor Alarm LED: OFF
```

## exit

This command ends the LAC session.

**NOTE:**

This command will not terminate a remote access session (RAS). If multiple LAC sessions are active, only the session where the logoff command was entered will be terminated.

Command name	Parameter	Parameter description	Permissions	Defaults
<b>exit</b>	<i>none</i>	<b>Terminates the LAC session. Telnet is still active.</b>	lucent1 lucent2 lucent3	none

## fileversion

This command displays the version of the specified file.

Command name	Parameter	Parameter description	Permissions	Defaults	Feature interactions
<b>fileversion</b>	<i>filename</i>	<b>Displays the version number of the file <i>filename</i>.</b>	lucent1 lucent2 lucent3	none	Version information must be stored in the same manner as an ".exe" file.

## Format

```
fileversion filename
```

## ftpserv

The **ftpserv** command is executed from a bash shell and is used to turn on and off the file transfer protocol on the DEFINITY ONE. If you attempt to ftp into the DEFINITY ONE and you get a "connection refused" message then ftp is not running.

Command name	Parameter	Parameter description	Permissions	Defaults
<b>ftpserv</b>		<b>Starts ftpserv</b>	lucent1 lucent2 lucent3	none
	<b>-c</b>	<b>Stops (closes) the service</b>		

## Format

```
ftpserv
```

```
ftpserv -c
```

## fwversion

---

This command displays the version of the firmware executing on the TN795 processor circuit pack.

Command name	Parameter	Parameter Description	Permissions	Defaults	Feature interactions
<b>fwversion</b>	<i>none</i>	<b>Displays the firmware version on the TN795 board</b>	lucent1 lucent2 lucent3	none	none

### Format

---

```
fwversion
```

### Output

---

```
TN795 application firmware version = nnnnnn
```

## gamalarmstat

This command displays all the global alarms that are not cleared.

Command name	Parameter	Parameter description	Permissions	Defaults
gamalarmstat	none	displays the global alarms that are not cleared	lucent1 lucent2 lucent3	none

## Output

Alarms are displayed in the following format:

```
refnum: mm/dd/yyyy hh:mm:ss nt-event-log-name source event-type severity event-ID ACKed
```

where

Alarm parameter	Description	Valid values
refnum	Alarm ID. Use this number to clear the alarm with the <a href="#">"cleargamalarm"</a> command	Any alphanumeric sequence
mm/dd/yyyy	Date when the alarm was generated (Month, day, year format)	Any valid date
hh:mm:ss	Time when the alarm was generated (hour:minute:second format)	Any valid time
nt-event-log-name	Indicates in which NT event log this alarm can be found.	application security system
source	Indicates which application is the source of the alarm. Use this information in conjunction with the alarm tables in <a href="#">Chapter 6, "DEFINITY ONE NT Log Events and Alarms"</a> for troubleshooting.	NT NT operating system GAM global alarm manager LAC Lucent access control GSK global sanity keeper VFM virtual fabric manager GAS global administration system
event-type	The type of event, as defined by Windows NT	Error Warning info
severity	The alarm severity	Major Minor
event-ID	An identification number given to the event by the NT operating system	Any valid alphanumeric
ACKed	Indicates that the alarm has been acknowledged. This field will be blank if the alarm has not been acknowledged.	ACK {blank}

## identbackup

This command displays the identification information from an existing backup set.

Command name	Parameter	Parameter description	Permissions	Defaults
<b>identbackup</b>	<b><i>dest</i></b>	<b>Destination of backup file:</b> pcmcia, or \xxx\yyy for a network drive directory	lucent1 lucent2 lucent3	none

### Format

```
identbackup { pcmcia / \xxx\yyy }
```

### Output

The following displays (example):

```
Backup Set Identification:
```

```

Version      1.01
Time         06/21 - 21:45
Data Sets    all
              security
              vmannounce
              vmtran
```

where

Parameter	Definition
Version	DEFINITY ONE version
Time	Date and time the backup was made in month/day - hour:minute format, using a 24-hour time.
Data Sets	The data included in the backup. See " <a href="#">d1backup</a> " for meaning of the data set keywords.

## installconfig

---

This command installs the login and license server data bases from a file received from the TSC/COE, and reboots the system.

**NOTE:**

This file must be present in order to run AUDIX, Cornerstone, or DEFINITY applications.

Command name	Parameter	Parameter description	Permissions	Defaults	Feature interactions
<b>installconfig</b>	<b><i>filename</i></b>	<b>Installs the file <i>filename</i> on the DEFINITY ONE system.</b>	lucent1 lucent2 lucent3	none	Required to run DEFINITY, Cornerstone and AUDIX applications.

### Format

---

```
installconfig filename
```

## lucent help

---

This command displays the list of commands supported by GAS.

**NOTE:**

To get help for an individual command, type *-?* (or */?*) after the command.

## net user

---

This command is used to add NT level logins, change NT level passwords, and enable/disable current NT accounts.

Command name	Parameter	Parameter description	Permissions	Defaults
<b>net user</b>	<b><i>login PW</i></b> <b><i>/active</i></b> <b><i>login PW</i></b>	<b>Adds NT level login</b> <b>activates a currently disabled login</b> <b>change existing PW</b>	lucent1 lucent2 lucent3	none

### Format

---

```
net user login password - adds new login
```

```
net user login /active - enables login
```

```
net user login new password - sets new password
```

## OSS

---

This command administers or displays parameters to control alarm call-out to the OSS system.

The parameters are stored in the Windows NT registry.

Command name	Parameter	Parameter description	Permissions	Valid values
oss	<i>none</i>	<b>Displays current settings of the oss parameters</b>	lucent1 lucent2 lucent3 agent1	
	<i>telephone-number</i>	The telephone number of the OSS to call for alarms.		Any number with 1 to 30 digits. Use commas to insert pauses in the dial string.
	<i>retries</i>	How many retries will be attempted if an alarm call fails.		0 - 10, and 99 - indicates continuous retries.
	<i>period</i>	The time between retries in minutes.		1 - 1440

## Format

---

*oss telephone-number retries period*

## Output

---

TTTT...TTTT, NN, PPPP

Parameter	Definition
TTTT...TTTT	telephone number
NN	retries
PPPP	period

## pcanywhere

This command launches the pcAnywhere server on DEFINITY ONE. Use this, in conjunction with the pcAnywhere client on a laptop, or other workstation, to access the Windows NT desktop of the DEFINITY ONE system on the laptop or workstation.

**NOTE:**

All of the Windows NT functions can be performed using the command line interface. Therefore the pcAnywhere application is not required.

Command name	Parameter	Parameter description	Permissions	Defaults
<b>pcanywhere</b>		<b>Starts the pcAnywhere server.</b>	lucent1	none
	<b>-c</b>	<b>Stops (closes) pcAnywhere</b>	lucent2 lucent3	

### Format

`pcanywhere`

## post

This command displays the last set of POST codes that resulted from the current boot of NT. This is to diagnose BIOS problems, and will not likely be useful in the field.

Command name	Parameter	Parameter description	Permissions	Defaults	Feature interactions
<b>post</b>	<i>none</i>	<b>Display the set of hexadecimal codes produced at the last NT boot.</b>	lucent1 lucent2 lucent3	none	

## productid

This command sets or displays the OSS product IDs for the DEFINITY ONE software.

Command name	Parameter	Parameter description	Permissions	Defaults
<b>productid</b>	<i>none</i>	<b>Displays the 10-digit numeric product ID.</b>	lucent1 lucent2 lucent3	none
	<b>AUDIX-product-id</b>	Displays product ID for AUDIX alarms		
	<b>GAM-product-id</b>	Displays product ID for GAM alarms		

### Format

To set the product ID:

```
productid system-id
```

To view the product ID:

```
productid
```

### Output

```
Product ID: System=xxxxxxxxxxx
```

## rasdrop

The rasdrop command is executed from a bash shell, it causes the Remote Access Server (RAS) service to be stopped and started again, there is a two minute delay from the time the command is executed till the service is toggled.

Command name	Parameter	Parameter description	Permissions	Defaults
<b>rasdrop</b>		<b>stops and starts ras service after a two minute delay</b>	lucent1 lucent2 lucent3	none

### Format

```
rasdrop
```

## reboot

---

This command causes DEFINITY ONE system to reboot.

Command name	Parameter	Parameter description	Permissions	Defaults
reboot	<i>nice</i>	<b>Shuts down all applications and NT in a graceful manner before rebooting.</b>	lucent1 lucent2 lucent3	
	<i>immediate</i>	Reboots the system without shutting any software or processes down.		

## Feature Interactions

---

```
reboot { nice | immediate }
```

### CAUTION:

Using the command **reboot** will cause all calls to be dropped. Any messages currently being recorded will likewise be lost.

## restartcause

---

This command displays the causes for system restart.

restartcause will search the NT event log from the most recent entry, and display any restart event with a time stamp at or after the time entered in the command line.

### NOTE:

DEFINITY and AUDIX restarts are not displayed.

Command name	Parameter	Parameter description	Permissions	Defaults
restartcause	<i>none</i>	<b>Display all restart entries in the NT event log.</b>	lucent1 lucent2 lucent3	
	<i>mm/dd/yyyy hh:mm</i>	Display all restart entries at or after the date and time specified in month/day/year hour:second format.		

## **schedbackup**

This command is used to administer or display the time and destination of the backup service.



**NOTE:**

If a network destination is entered for the destination parameter, DEFINITY ONE will attempt to access the location. If the location is not accessible, the destination parameter is saved, and a warning message is displayed.



**CAUTION:**

*When entering a parameter description, do not enter the brackets. This will cause...*

Command name	Parameter	Parameter description	Permissions	Feature interactions
<b>schedbackup</b>	<b>list</b>	<b>list=[dataset]</b>	lucent1 lucent2 lucent3	
	<b>dest</b>	dest=[destination] dest=//machineName/share name or pcmcia		
<b>schedbackup</b>	<b>days</b>	days=[Su,M,T,W,Th,F,S]		
<b>schedbackup</b>	<b>time</b>	time=[hh:mm]		The directory is E:/backup  The network backup drive is fixed as drive F:
	<b>none</b>	Displays the list of data sets administered for backup.	lucent1 lucent2 lucent3	
	<b>all</b>	All data sets with a in the "defaults" column are backed up with this command parameter.		Yes
	<b>defann</b>	Definity Announcements		
	<b>deftran</b>	Backup DEFINITY translations		
	<b>registry</b>	Backup Windows NT system registry		
	<b>sam</b>	NT passwords and permissions		
	<b>security</b>	Lucent LAC and license files		
	<b>vmannounce</b>	Backup voice announcements		

*Continued on next page*

3 Global Administration Subsystem Commands  
*serialnumber*

3-27

Command name	Parameter	Parameter description	Permissions	Feature interactions
	<b><i>vmmsgtran</i></b>	Backup voice messages and translations		
	<b><i>vmnammsgtran</i></b>	Backup voice names, messages, and translations		
	<b><i>vmnamtran</i></b>	Backup voice names and translations		
	<b><i>vmtran</i></b>	Backup voice mail translations		

## serialnumber

This command displays the serial number of the TN795 processor circuit pack.

Command name	Parameter	Parameter description	Permissions	Defaults
<b>serialnumber</b>	<b><i>none</i></b>	<b>Display serial number of TN795</b>	lucent1 lucent2 lucent3	none

## Format

`serialnumber`

## Output

```
croatia-lucent1> serialnumber Ryon serial number:
99DR01263695
TNcode:
TN795
```

## setip

The setip command is used to set system parameters including:

- LAN IP Address
- LAN subnet mask
- LAN Default Gateway
- RAS IP Address
- System Name

Options for setting system network options. IP addresses are all dotted decimal, e.g. 10.0.0.1. The GUI graphical equivalent (through a normal Windows NT logon via the monitor or pcAnywhere) are also given.

Command name	Parameter	Parameter description	Permissions	Defaults
<b>setip</b>	<i>none</i>		lucent1 lucent2 lucent3	
	<b>-s</b>	Be silent. Don't print before/after settings		
	<b>-v</b>	Print out the version of the command		
	<b>-z</b>	Debug. Show commands that will execute, but don't execute them.		
	<b>-?</b>	Help. Print this help string		
	<b>name=systemname</b>	Set the windows Networking name of the system. The name will be converted to uppercase. Reboot needed for this to take effect. GUI: NetworkNeighborhood->Properties->Identification->Computer Name:		
	<b>cust=ip-addr, netmask [gateway]</b>			
	<b>cust=DHCP</b>	Set the IP address, subnet mask, and default gateway of the LAN interface to the customer's LAN (out the splitter cable). Reboot required for this to take effect. DHCP will be enabled if that is the address specified. GUI: Network Neighborhood->Properties-> IP Address->Adaper: [1]		

3 Global Administration Subsystem Commands  
*setip*

3-29

Command name	Parameter	Parameter description	Permissions	Defaults
	<b><i>dns=[name, domain, primary-ns-ip-addr[,secondary-ns-ip-addr]...]</i></b>	Set the DNS host name, domain name, and a list of name server IP addresses. DNS will be turned off if no arguments are given. GUI: NetworkNeighborhood->Properties->Protocols->DNS		
	<b><i>wins=[ip-addr-primary [,ip-addr-backup]]</i></b>	Set the IP address of the primary and secondary Window NetBios on the TCP name server. Reboot required for this to take effect. WINS will be turned off if no address is given.  GUI: NetworkNeighborhood-.Properties-.Protocols->WINS-.  Adapter: [1]		
	<b><i>ras=[ip-addr]</i></b>	Set the modem RAS/PPP interface IP address. This also causes RAS to be automatically started and programs default IP routes for Lucent Services Access. Reboot required for this to take effect. RAS will be turned off if no address is given.  GUI: NetworkNeighborhood->Properties->Services-.Remote Access-. Properties->COM1-.Network->TCP/IP Configure->Begin:		

**Example**

`setip cust- 155.9.162.121, 255.255.255.252, 155.9.162.2`

`setip ras-10.21.011`

The following displays:

```
estonia-lucent1> setip
name=BRONCO
cust=135.9.142.101,255.255.255.0,135.9.142.254
dns=estonia,dr.lucent.com,135.9.1.29,135.9.1.30,135.9.1.39
wins=135.9.140.1,135.9.140.4
ras=10.0.0.1
Command succeeded: No changes made
```

## siteconfig

---

This command installs the login and license server data bases from a file received from the TSC/COE. This command is only available to the lucent1 login group.

**NOTE:**

This command can only be executed on a previously installed system.

Command Name	Parameter	Parameter Description	Permissions	Defaults	Feature Interactions
<b>siteconfig</b>	<i>filename</i>	<b>Installs the encrypted system security file <i>filename</i> on the DEFINITY ONE system.</b>	lucent1 only	none	This command is logged in the event log, and can only be executed on a previously installed system.

### Format

---

```
siteconfig filename
```

### Feature Interactions

---

**NOTE:**

When `siteconfig` is executed, an event is logged, and may optionally send an alarm to the OSS.

**NOTE:**

Login and license server data must be present in order to run AUDIX, Cornerstone, or DEFINITY applications.

## shutdown

---

This command instructs the named target process(es) to perform an orderly shutdown. If the shutdown is not completed in 60 seconds, an automatic terminate (see ["terminate"](#)) will be sent to the process(es).

One parameter must be selected from the list of processes. The parameter `campon` is optional.

3 Global Administration Subsystem Commands  
*shutdown*

3-31

Command name	Parameter	Parameter description	Permissions	Notes
<b>shutdown</b>	<b>all</b>	Shut down all DEFINITY ONE applications.  NOTE: <i>shutdown all</i> does <u>not</u> shut down Windows NT or the TN795 firmware.  NOTE: Commands should be executed from a bash window through a pcAnywhere session. Otherwise the bash may disappear.	lucent1 lucent2 lucent3 agent1	When all applications are selected for shut down, they will close in the following order:  1. AUDIX 2. AUDIX Networking 3. CornerStone 4. DEFINITY 5. VFM 6. GMM 7. License Server 8. Backup Restore 9. LACr 10. LucentLogger 11. watchdog  The " <a href="#">campon</a> " option is valid for this command parameter
	<b>AUDIX</b>	Shut down the AUDIX application.		The " <a href="#">campon</a> " option is valid for this command parameter
	<b>AUDIXNetw</b>	Shut down the AUDIX Networking application		
	<b>BackupRestore</b>	Shut down the backup/restore process.		
	<b>campon</b>	AUDIX option only. Using this option causes AUDIX to notify users that the system is shutting down, and then wait for all users to end their sessions.		There is no shutdown wait time limit for this option. AUDIX will wait indefinitely until all users have ended their sessions, or a shutdown is commanded without the campon option.
	<b>CornerStone</b>	Shut down the Cornerstone application. If you shut it down, it will shut down AUDIX as well.		
	<b>DEFINITY</b>	Shut down the DEFINITY application.		
	<b>GMM</b>	Shut down the GMM application		Alarming will not occur until GMM is restarted
	<b>LAC</b>	Shut down the LAC application		
	<b>LicenseServer</b>	Shut down the licence server application.		You will not be able to run any applications until the license server has been restarted.
	<b>LucentLogger</b>	Shut down the Lucent logger process.		

*Continued on next page*

### 3 Global Administration Subsystem Commands

*shutdown*

3-32

Command name	Parameter	Parameter description	Permissions	Notes
	<b>system</b>	Shut down all DEFINITY ONE processes, Windows NT and the TN795 firmware.		When multiple processes are selected for shut down, they will close in the following order: <ol style="list-style-type: none"><li>1. AUDIX</li><li>2. CornerStone</li><li>3. DEFINITY</li><li>4. VFM</li><li>5. GMM</li><li>6. License Server</li><li>7. Backup Restore</li><li>8. LAC</li><li>9. LucentLogger</li><li>10. watchdog</li></ol> The <a href="#">"campon"</a> option is valid for this command parameter
	<b>VFM</b>	Shut down the VFM process.		

#### Format

---

```
shutdown target {campon}
```

#### Feature interactions

---

If the [campon](#) option is used with the target all or system, shutdown will wait for AUDIX to terminate before continuing to close the other processes. AUDIX will wait for all users to end their sessions, with no time limit. When AUDIX is waiting indefinitely, a shutdown of AUDIX may be required.

If a target is not running, an error message is displayed.

The ["start"](#) command is used to start a target previously shut down or terminated.

## start

This command restarts selected processes previously stopped by a [“shutdown”](#) or a [“terminate”](#) command.



**NOTE:**

You cannot restart Windows NT or the TN795 firmware with the start command.

Command name	Parameter	Parameter description	Permissions	Notes
<b>start</b>	<b><i>all</i></b>	Restart all DEFINITY ONE processes.  NOTE: <i>start all</i> does <u>not</u> restart Windows NT or the TN795 firmware.	lucent1 lucent2 lucent3	The processes that are restarted are (not in order):  AUDIX AUDIX Networking Backup/Restore CornerStone CornerStone Logger DEFINITY GMM LAC License Server LucentLogger VFM
	<b><i>AUDIX</i></b>	Restart the AUDIX application.		
	<b><i>AUDIXNetw</i></b>	Restart the AUDIX Networking application		
	<b><i>BackupRestore</i></b>	Restart the backup/restore process.		
	<b><i>CornerStone</i></b>	Restart the Cornerstone application.		
	<b><i>DEFINITY</i></b>	Restart the DEFINITY application.		
	<b><i>GMM</i></b>	Restart the GMM application		
	<b><i>LAC</i></b>	Restart the LAC application		
	<b><i>LicenseServer</i></b>	Restart the licence server application.		You will not be able to run any applications until the license server has been restarted.
	<b><i>LucentLogger</i></b>	Restart the Lucent logger process.		
	<b><i>VFM</i></b>	Restart the VFM process.		

## Format

*start process-name*

## Feature interactions

---

Issuing the start command on a process already running will generate an error message.

## swversion

---

This command displays the software version and load number of all DEFINITY ONE software components.

Command name	Parameter	Parameter description	Permissions
<b>swversion</b>	<i>none</i>	<b>Display the software version and load number for all installed applications.</b>	lucent1 lucent2 lucent3

## Output

---

```
Software Versions and Loads:
  Release=DefinityOne.02.0.009.0
  NT=4.0 1381 Service Pack 5
  CYGNUS=CYGWIN_NT-4.0
  GAM=G3V8c.00.0.510.0
  LAC=G3V8c.00.0.510.0
  Watchdog=G3V8c.00.0.510.0
  Definity=G3V8c.00.0.510.0
  AUDIX=N5.0
  CornerStone=1.0.0
  DSA=not installed
```

**NOTE:**

If a particular component is not installed, the version number will be replaced with the text “not installed”.

## terminate

---

This command kills the named target process(es). The target process will not be notified, and is not expected to wait for I/O or user activity to cease.

Use the "[shutdown](#)" command to stop a process in an orderly way. The shutdown command is the preferred method of stopping processes. Use terminate only as a last resort.

Command name	Parameter	Parameter description	Permissions	Notes
<b>terminate</b>	<b><i>all</i></b>	Terminate all DEFINITY ONE processes.  NOTE: <i>terminate all</i> does <u>not</u> terminate Windows NT or the TN795 firmware.	lucent1 lucent2 lucent3	When multiple processes are selected for termination, they will stop in the following order:  1. AUDIX 2. CornerStone 3. DEFINITY 4. VFM 5. GMM 6. License Server 7. Backup Restore 8. LAC 9. LucentLogger 10. watchdog
	<b><i>AUDIX</i></b>	Terminate the AUDIX application.		
	<b><i>BackupRestore</i></b>	Terminate the backup/restore process.		
	<b><i>CornerStone</i></b>	Terminate the Cornerstone application and AUDIX.		
	<b><i>DEFINITY</i></b>	Terminate the DEFINITY application.		
	<b><i>GMM</i></b>	Terminate the GMM application		Alarming can not occur until the GMM is restarted.
	<b><i>LAC</i></b>	Terminate the LAC application		
	<b><i>LicenseServer</i></b>	Terminate the licence server application.		You will not be able to run any applications until the license server has been restarted.
	<b><i>LucentLogger</i></b>	Terminate the Lucent logger process.		
	<b><i>system</i></b>	Terminate all DEFINITY ONE processes, Windows NT and the TN795 firmware.		
<b><i>VFM</i></b>	Terminate the VFM process.			

## Format

---

`terminate process-name`

## Feature interactions

---

If a target is not running, an error message is displayed.

The [“start”](#) command is used to start a previously terminated target.

## versiondiff

---

This command lists all files in the specified directory that have different NT version numbers than the one specified in the command.

Use versiondiff to locate patch files on a particular DEFINITY ONE system.

Command name	Parameter	Parameter description	Permissions	Defaults
versiondiff	<i>version</i>	<b>A Windows NT version number. All files which do not have the specified version number will be displayed.</b>  Only files with version information in the header in “.dll” format will be checked. Others will be ignored.	lucent1 lucent2 lucent3	none
	<i>directory</i>	<b>The directory, including sub-directories, to search for files</b>		

## Format

---

```
versiondiff version directory
```

# Maintenance Commands for DEFINITY ONE

# 4

---

This chapter provides additional trouble-clearing information for resolving both system-alarmed and user-reported troubles. This chapter supplements the information found in [Chapter 5, "Maintenance Objects for DEFINITY ONE"](#). The maintenance commands are used to control, test, and obtain information associated with maintenance objects (MOs). The commands require the use of the administration terminal or remote Initialization and Administration System (INADS) interface and a valid login and password.

For Maintenance Objects and Maintenance Commands for the DEFINITY Wireless Business System (DWBS), refer to the appropriate maintenance documentation that accompanies the DWBS.

## System command structure

---

System commands are standard words and phrases instructing the system to perform a specific function. The commands are arranged in a hierarchy of keywords; that is, enter 1 command to go to a different level. The commands contain 3 parts:

- ACTION
- OBJECT
- QUALIFIER

## Action

---

ACTION is the first part of the command. When `command:` appears on the screen. The ACTION specifies the operation desired. Examples include **add**, **duplicate**, **change**, **remove**, **display**, **list**, and **save**.

## Object

---

OBJECT is the second part of the command and specifies the particular object to be administered. Some typical entries are **hunt-group**, **coverage path**, and **station**.

## Qualifier

---

QUALIFIER is the last part of the command. It is 1 or more words or digits used to further identify or complete the OBJECT. For example, **hunt group 15** or **station 3600**, where **15** and **3600** are qualifiers.

 **NOTE:**  
*Qualifiers are printed in this typeface.*

## Example

---

The command to add a station with extension number *1234* is:

**add station 1234**

In this example, **add** is the ACTION, **station** is the OBJECT, and **1234** is the QUALIFIER. In the command line, spaces are required between the ACTION, OBJECT, and QUALIFIER.

## Abbreviations

---

To save time, enter enough letters for each part of the command to make it unique. For example, if you want to enter the command **change system-parameters country-options**, typing **cha sys coun** is sufficient.

 **NOTE:**  
The craft login may not be allowed to perform some of the steps needed to initialize the system. If access is denied to some of these procedures, contact your Lucent Technologies representative for assistance.

## **busyout access-endpoint**

---

**This command is destructive.** This command is used to busyout a specified access endpoint.

4 Maintenance Commands for DEFINITY ONE

*busyout access-endpoint*

4-3

Action/ Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>busyout access-endpoint</b>	<b>extension</b>	Extension number of access endpoint (per dial-plan)  Examples: <b>busyout access-endpoint 25012</b> <b>busyout access-endpoint 77868</b>	init inads craft nms	none	See below

**Feature interactions**

- If there is an active call on the specified access endpoint, the call to drop.

**Output**

The following example shows the output for the **busyout access-endpoint 22502** command and assumes that access endpoint ports for extension 22502 are in cabinet 1, carrier C, slot 11, circuit 1 to 6. The responses display on a test-by-test basis with one line of data for each test result.

```

busyout access-endpoint 22502                                SPE A

                                COMMAND RESULTS

Port      Maintenance Name  Alt. Name  Result  Error Code
01C1101   WAE-PORT           22502     PASS
01C1102   WAE-PORT           22502     PASS
01C1103   WAE-PORT           22502     PASS
01C1104   WAE-PORT           22502     PASS
01C1105   WAE-PORT           22502     PASS
01C1106   WAE-PORT           22502     PASS

Command Successfully Completed
    
```

**Field descriptions**

- Port** Port address (cabinet-carrier-slot-circuit)
- Maintenance Name** Name of maintenance object (WAE-PORT = wideband access endpoint; TIE-DS1 = single port access endpoint)
- Alt. Name** The alternate way of identifying the maintenance object, in this case, the extension number of the access endpoint.
- Result** Test result: Pass, Fail, Abort
- Error Code** Numeric code explaining why the release failed or aborted. Refer to the detailed list of the codes by test number for each MO.

## busyout adjunct-ip-link

The busyout adjunct-ip-link command is used to busy out a specified ASAI adjunct IP link that is administered on the ip-services form. An ASAI adjunct link provides connectivity to CentreVu-CT which is connected to an Ethernet LAN. On DEFINITY ONE, the LAN interface is provided by the TN795 Ethernet interface or by the CLAN (Control LAN) TN799 circuit pack. A CLAN board is used only if a private LAN is required for security reasons.

When the link is busied out, a Link Status message with the cause code set to "link down" and the reason code set to "Virtual BRI port busied out or not administered" is sent to the client. Background heart beat handshake ceases from this point on.

Action/object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>busyout adjunct</b>	<b><i>ip-link</i></b>	Link identifier (1 - 8) Example: <b>busyout adjunct-ip-link 1</b>	init inads craft or any customer type login		See <a href="#">Feature interactions</a>

### Feature interactions

1. All ASAI service is disabled.
2. A Warning alarm is generated even if more severe ADJLK-IP alarms are present.
3. Periodic and scheduled tests continue to run. No alarms more severe than a Warning are generated until the adjunct-ip-link is released from busyout.
4. The release of the adjunct-ip-link from busyout retires all alarms.
5. If a problem still exists, background maintenance generates new alarms within a few minutes.

## Output

---

The following display shows a typical result when busyout adjunct-ip-link is entered.

```
busyout adjunct-ip-link 1
                                COMMAND RESULTS
Port      Maintenance Name  Alt. Name      Result      Error Code
1         ADJLK-IP              PASS
Command successfully completed
```

## Field Descriptions

Port	The link number (1-8) as administered on the ip-services form
Maintenance Name	The name of the maintenance object as it appears in the Error and Alarm Logs
Alternate Name	An alternate means of identifying the maintenance object. This is not used for the ASAI adjunct-ip link
Result	Whether or not the object was successfully busied out
Error code	A number indicating the reason for an abort or failure of the command. See Busyout and Release Error Codes at the beginning of this chapter for details of common abort and failure codes.

## busyout board

This command puts all the ports associated with the specified access endpoint in a maintenance busy (craft busy) state. No periodic or scheduled tests are performed on the busied out access endpoint ports until they are released. When the access endpoint ports are maintenance busy, the access endpoint is removed from active service on the switch, meaning that no call processing activity can include the busied objects because terminals on the administered ports do not receive dial-tone. Warning alarms are generated on each busied out port in the access endpoint. The **release access-endpoint** command returns all the ports associated with the specified access endpoint to operation.



### WARNING:

*This command is service disrupting and may cause extraneous alarms.*

Action/object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
busyout board	location	Board address (PCSSpp) Examples: <b>busyout board 01c11</b> <b>busyout board 02c15</b>	init inads craft	none	None

## Output

The following example shows the output from the **busyout board 1c07** command, and assumes that board in cabinet 1, carrier c, slot 7 is an analog board with three administered ports. The responses display on a test-by-test basis with one line of data for each test result.

```

busyout board 01c07                               SPE A

                                COMMAND RESULTS

Port      Maintenance Name  Alt. Name  Result  Error Code
01c07     ANL-BD              51001     PASS
01c0702   ANL-LINE
01c0701   ANL-LINE
01c0703   ANL-LINE
Command successfully completed
    
```







## busyout link

This places maintenance objects associated with a specified link in a maintenance busy state. No periodic or scheduled tests are performed on the busied out maintenance objects until they are released. The link is marked out of service and is inaccessible to call processing. Warning alarms (error type 18) are generated on each busied out maintenance object, so that INADS can determine the state of the objects. The **release link** command reactivates the objects.

Action/Object	Qualifier	Qualifier Description	Permissions	Defaults	Feature Interactions
<b>busyout link</b>	<b><i>link-id</i></b>	Processor Interface circuit pack 1a1 or 1b1 = 1 – 4  Processor Interface circuit pack 1a2 or 1b2 = 5 – 8  Examples <b>busyout link 1</b>	init inads craft	none	none

## Output

The following example shows the output from the **busyout link 1** command. The responses display on a test-by-test basis with one line of data for each test result.

```

busyout link 1                                SPE A

                                COMMAND RESULTS

Port      Maintenance Name  Alt. Name  Result      Error Code
01C0301   PI-LINK              Not Applicable  PASS

Command successfully completed

```

## Field descriptions

Port	Port address/link-id
Maintenance Name	The name of the busied out maintenance object
Alt. Name	Not applicable
Result	Test result: Pass, Abort, Fail
Error Code	Numeric code explaining why the release failed or aborted. Refer to the detailed list of the codes by test number for each MO.

## busyout mis

This command places a management information system in the maintenance busy state. No periodic or scheduled maintenance is performed on the busied out mis until it is released. When the object is busied out no call processing activity may be performed over the link. A warning alarm (error type 18) is generated on the busied out mis, so that INADS can determine its state. The command, **release mis**, reactivates the busied out mis.

Action/Object	Qualifier	Qualifier Description	Permissions	Defaults	Feature Interactions
<b>busyout mis</b>		Example: <b>busyout mis</b>	init inads craft cust rcust	None	None

## Output

The following example shows the output from the **busyout mis** command. The responses display on a test-by-test basis with one line of data for each test result.

```

busyout mis                               SPE A
                                     COMMAND RESULTS
Port      Maintenance Name  Alt. Name  Result      Error Code
MIS
Command Successfully Completed
    
```

## Field descriptions

Port	Not applicable
Maintenance Name	Name of busied out maintenance object: MIS
Alt. Name	Not applicable
Result	Test result: Pass, Abort, Fail
Error Code	Numeric code explaining why the release failed or aborted. Refer to the detailed list of the codes by test number for each MO.

## busyout port

This command places the specified port on a circuit pack in a maintenance busy state. No periodic or scheduled tests are performed on the busied out port until it is released. When the object is maintenance busy, it is deactivated (no call processing activity may include the busied object). Warning alarms (error type 18) are generated on each busied out maintenance object, so that INADS can determine the state of the objects. The command, **release port**, reactivates the administered port on a circuit pack at a specified location.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>busyout port</b>	<b>location</b>	Port address: <b>PCSS</b> marked port: <b>PPSSpp</b>  Examples: <b>busyout port 01c1101</b> <b>busyout port 02c1501</b>	init inads craft	none	see below

## Output

The following example is a display of the **busyout port** command.

```

busyout port 01C0701                               SPE A

                                COMMAND RESULTS

Port      Maintenance Name  Alt. Name  Result      Error Code
01C0701   ANL-LINE                PASS

Command successfully completed
    
```

## Field descriptions

Port	Port address (cabinet-carrier-slot-circuit)
Alt. Name	Alternate way to identify maintenance objects.
<b>If the Object is</b>	<b>The field contains</b>
station	extension
trunk	xxx/yyy (where xxx = trunk group number and yyy = member number)
	private CO lineP/xxx (where xxx = private CO line group number)
Maintenance Name	Type of busied out maintenance object.
Result	Test result: Pass, Abort, Fail
Error Code	Numeric code explaining why the release failed or aborted. Refer to the detailed list of the codes by test number for each MO.

## busyout pri-endpoint

This command places all PRI endpoint ports (B-channels) associated with the specified PRI endpoint in a maintenance busy (system technician busy) state. No periodic or scheduled tests are performed on the busied out PRI endpoint ports until they are released. When the PRI endpoint port is maintenance busy it is deactivated (no call processing activity may include the busied object). Warning alarms (error type???) are generated on each busied out port. The command, **release pri-endpoint**, reactivates all ports (B-channels) associated with the specified PRI endpoint extension and the switch attempts to negotiate with the far-end PRI terminal adapter to reactivate each PRI endpoint port (B-channel).

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>busyout pri-endpoint</b>	<b><i>extension</i></b>	PRI endpoint extension number  Examples: <b>busyout pri-endpoint 25012</b> <b>busyout pri-endpoint 77868</b>	init inads craft nms	none	If active calls resides on specified PRI endpoints, the busyout command drops the call.  Once the PRI endpoint is maintenance-busy, call attempts from far-end PRI terminal adapters are denied with a cause value 17.

## Output

```

busyout pri-endpoint 22501                               SPE A

                                COMMAND RESULTS

Port      Maintenance Name  Alt. Name  Result      Error Code
01B2001   PE-BCHL              22501     PASS
01B2002   PE-BCHL              22501     PASS
01B2003   PE-BCHL              22501     PASS
01B2004   PE-BCHL              22501     PASS
01B2005   PE-BCHL              22501     PASS
01B2006   PE-BCHL              22501     PASS

Command Successfully Completed
    
```

## Field descriptions

Port	Port address (cabinet-carrier-slot-circuit)
Maintenance Name	Type of busied out maintenance object: PE-BCHL
Alt. Name	Extension number of PRI endpoint
Result	Test result: Pass, Fail, Abort
Error Code	Numeric code explaining why the release failed or aborted. Refer to the detailed list of the codes by test number for each MO.

## busyout station

This command places the installed and uninstalled administered voice terminal extension (station) in a maintenance busy state. No periodic or scheduled tests are performed on the busied out station until it is released. When the object is maintenance busy it is deactivated (no call processing activity may include the busied object). Warning alarms (error type 18) are generated on each busied out maintenance object, so that INADS can determine the state of the objects. The command, **release station**, reactivates the specified voice terminal extension.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>busyout station</b>	<b>extension</b>	Extension number (per dial-plan) Examples: <b>busyout station 10020</b> <b>busyout station 32770</b>	init inads craft	none	none

## Output

The following example is a display of the **busyout station** command.

```

busyout station 1002                               SPE A

                                COMMAND RESULTS

Port      Maintenance Name  Alt. Name  Result      Error Code
01C1102   DIG-LINE              PASS

Command successfully completed

```

## Field descriptions

Port	Port address (cabinet-carrier-slot-circuit)
Maintenance Name	Type of busied out maintenance object
Alt. Name	Alternate means to identify maintenance object: extension number
Result	Test result: Pass, Fail, Abort
Error Code	Numeric code explaining why the release failed or aborted. Refer to the detailed list of the codes by test number for each MO.

## busyout tdm

The **busyout tdm** command places the specified tdm bus in a maintenance busy state. No periodic or scheduled tests are performed on the busied out bus until it is released. When the object is maintenance busy it is deactivated (no call processing activity may include the busied object). Warning alarms (error type 18) are generated on each busied out tdm bus, so that INADS can determine the state of the objects. The command, **release tdm**, reactivates the specified tdm bus.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>busyout tdm</b>	<b>pn</b> <i>number</i>	pn number = TDM bus Port Network number to be busied out.	init inads craft	none	If a bus is busied out, no calls are torn down. and no new calls are set up.  Dedicated tone time slots must be moved to another bus (the other half of the duplicated bus) before a busyout of a particular bus is allowed.
	<b>bus</b>	bus = <b>a</b> (default control bus) or <b>b</b> (default tone bus) specifies desired half of TDM bus. Each 512 time slot TDM bus configures as two duplicate 256 time slot buses. This division allows duplication of control channels and dedicated tone time slots.  Examples: <b>busyout tdm 1a</b>			

## Output

The following example is a display of the **busyout tdm** command.

```

busyout tdm port-network 1 bus a                               SPE A

                                COMMAND RESULTS

Port      Maintenance Name  Alt. Name  Result      Error Code
PN 01A    TDM-BUS                PASS

Command successfully completed
    
```

## Field descriptions

Port	Port address and associated TDM number and bus (PNA or PNB)
Alt. Name	Not applicable
Maintenance Name	Type of busied out maintenance object: TDM-BUS
Result	Test result: Pass, Abort, Fail
Error Code	Numeric code explaining why the release failed or aborted. Refer to the detailed list of the codes by test number for each MO.

## busyout tone-clock

The **busyout tone-clock** command places the specified tone/clock in a maintenance busy state. No periodic or scheduled tests are performed on the busied out object until it is released. When the object is maintenance busy it is deactivated (no call processing activity may include the busied object). Warning alarms (error type 18) are generated on each tone clock circuit pack busied out, so that INADS can determine the state of the objects. The command, **release tone-clock**, reactivates the specified tone/clock.



**NOTE:**

There is no tone clock board on DEFINITY ONE systems.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>busyout tone-clock</b>	<b>location</b>	Physical location ( <b>PCC</b> ) Examples: <b>busyout tone-clock 01c</b> <b>busyout tone-clock 03d</b>	init inads craft	1 (one)	none

## Output

The following example is a display of the **busyout tone-clock** command.

```

busyout tone-clock 1a                               SPE A

                                COMMAND RESULTS

Port      Maintenance Name  Alt. Name  Result      Error Code
01A      TONE-PT                PASS
01A      TDM-CLK                PASS
01A      TONE-BD                PASS

Command successfully completed
    
```

## Field descriptions

Port	Tone/clock board address (cabinet-carrier)
Maintenance Name	Circuit pack name: TONE-PT, TDM-CLK, TONE-BD
Alt. name	Not applicable
Result	Test result: Pass, Abort, Fail
Error Code	Numeric code explaining why the release failed or aborted. Refer to the detailed list of the codes by test number for each MO.

## busyout trunk

The **busyout trunk** command places the specified installed or uninstalled trunk group or trunk group member in a maintenance busy state. No periodic or scheduled tests are performed on the busied out trunk groups or trunk group members until they are released. When the object is maintenance busy it is deactivated (no call processing activity may include the busied object). A single group member can be busied out by specifying the group and member number. All members in a trunk group can be busied out by specifying the trunk group number. Warning alarms (error type 18) are generated on each busied out maintenance object, so that INADS can access the state of the objects. The **release trunk** command reactivates the specified trunk group or group member.

### ⇒ NOTE:

If the user enters **busyout trunk <group number>/**, the lowest port-location in the group is busied out. **This s NOT recommended.**

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>busyout trunk</b>	<b>group</b>	Trunk group number (1–99)	init inads craft	none	none
	<b>member</b>	Number of a particular trunk within a trunk group (1 – 99)  Examples: <b>busyout trunk 78</b> <b>busyout trunk 78/1</b>			

## Output

The following example is a display of the **busyout trunk** command.

```

busyout trunk 78/1                               SPE A

                                COMMAND RESULTS

Port      Maintenance Name  Alt. Name  Result  Error Code
01C1505   CO-TRK                78/01     PASS

Command successfully completed
    
```



## change circuit-packs

This command allows users to administer circuit packs that are inserted into the system port, expansion control, and switch node carriers. It is used to configure the system when circuit packs are not physically inserted.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>change circuit-packs</b>	<b>cabinet number</b>	Cabinet number of circuit packs to change  Examples: <b>change circuit-packs 1</b> <b>change circuit-packs 2</b>	init inads craft cust nms	1 (one)	none

## Output

The following example is a display of page 1 of the **change circuit-packs 1** command when DEFINITY AUDIX is Administered by entering **TN566** in slot 8.

```
change circuit-packs                                Page 1 of 5
                CIRCUIT PACKS

Cabinet: 1                                         Carrier: A
                                                Carrier Type: processor

Slot Code  Sf Mode  Name                               Slot Code  Sf Mode  Name
01: TN795                RESERVED-PROCESSOR
02: TN795                PROCESSOR-TONE/CLK  13:
03:                                14:
04: TN556  C            BRI LINE                    15:
05: TN464  E            # DS1 INTERFACE              16:
06: TN744  D            CALL CLASSIFIER
07:
08: TN2224                DIGITAL LINE
09: TN464  F            DS1 INTERFACE
10: TN746  B            ANALOG LINE
'#' indicates circuit pack conflict.
```

If **TN566** is entered for slot 8 and any of the 2 slots before it or 1 slot after it are occupied, the following error message displays:

```
Remove installed equipment from reserved 2 previous and 1
next slots
```

4 Maintenance Commands for DEFINITY ONE  
*change circuit-packs*

4-20

The following is an example of page 1 of the change circuit-packs form when MAPD is administered by entering **TN800**, **TN801**, or **TN802** in slot 7.

```
change circuit-packs                                Page 1 of 5
                                           CIRCUIT PACKS

      Cabinet: 1                                Carrier: A
                                           Carrier Type: processor

Slot Code  Sf Mode  Name                      Slot Code  Sf Mode  Name
01: TN795                                RESERVED-PROCESSOR
02: TN795                                PROCESSOR-TONE/CLK  13:
03:                                         14:
04: TN556  C        BRI LINE                    15:
05: TN464  E        # DS1 INTERFACE              16:
06: TN744  D        CALL CLASSIFIER
07:
08: TN2224                                DIGITAL LINE
09: TN464  F        DS1 INTERFACE
10: TN746  B        ANALOG LINE
11: VIRALM VIRTUAL ALARM BD
12: CWY1 VIRTUAL PR-SSP BD
```

## Field descriptions

Cabinet	Administered cabinet number
Cabinet Layout	Type of cabinet (single-carrier)
Carrier	In-use cabinet carrier
Carrier Type	Carrier function (port, processor, or expansion control)
Slot	Slot numbers (0 - 21).
Code	Circuit pack code (TN number) to identify the circuit pack type
Sfx	Lists the suffix, if applicable
Name	Alphanumeric circuit pack name

## change synchronization

Each system contains a hierarchy of sources used for timing synchronization. DS1 inputs to the external stratum 3 clock affect stratum 3 synchronization hierarchy. Primary and secondary fields reflect Stratum 4 synchronization. If all fields are blank, the tone clock board within each PN provides timing for that PN.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
change synchronization		Examples: change synchronization change synch	init inads craft cust rcust bcms	none	DS1 interface, BRI trunk, or UDS1 board selected as either a primary or secondary synch source cannot be removed on the DS1 circuit pack administration form or the regular circuit pack administration form.

## Output/Input

The following example shows the output for the **change synchronization** command. "4" was entered in the stratum field.

```
change synchronization                               Page 1 of 1

      SYNCHRONIZATION PLAN

SYNCHRONIZATION SOURCE (circuit pack location)
  Stratum: 4
  Primary: _____ Secondary: _____
Location Name Slip      Location Name Slip

NOTE: DS1 and BRI trunk sources will result in stratum 4, type II
synchronization
```

The following example shows the output for the **change synchronization** command. "3" was entered in the stratum field.

```
change synchronization                               Page 1 of 1

      SYNCHRONIZATION PLAN

SYNCHRONIZATION SOURCE (DS1 circuit pack location)
  Stratum: 3
  Port Network: 1
```

#### 4 Maintenance Commands for DEFINITY ONE

*change system-parameters maintenance*

4-22

### Field descriptions

Stratum:	Current synchronization stratum (3, 4)
Primary:	First choice system synchronization source (blank entry = no synchronization); field valid only if stratum 4 synchronization is specified.
Secondary:	Second choice system synchronization source (blank = no synchronization); valid if stratum 4 synchronization selected
Location:	Circuit pack location of all administered DS1 circuit packs (port network, carrier and board slot)
Name:	User-defined name for the DS1 circuit pack (blank = no user-defined name assigned)
Slip:	If DS1 circuit pack has slip alarm, y; if not, n.
Port Network:	Display-only field specifying the port network that supplies synchronization through the tone clock circuit pack (valid for stratum 3 synchronization)

## **change system-parameters maintenance**

---

The **change system-parameters maintenance** command specifies and displays scheduled maintenance operations and maintenance support functions. It also activates and deactivates INADS alarm origination during repairs. To deactivate alarm origination:

1. Make a note of the current entries in the Alarm Origination and CPE Alarm fields so you can restore them later.
2. Change the Alarm Origination to OSS Numbers field to **neither**.
3. Change the CPE Alarm Activation Level field to **none**.
4. If daily scheduled maintenance must remain idle during a maintenance procedure, set the Start Time field to a time after the session ends. If daily Scheduled Maintenance is running and needs to be deactivated, set the Stop Time field to one minute after the current time.

4 Maintenance Commands for DEFINITY ONE  
*change system-parameters maintenance*

4-23

- Press Enter and verify that the screen displays the message:

Command successfully completed



**NOTE:**

For earlier releases of system software, disable Cleared Alarm Notification and Restart Notification before submitting the form.



**NOTE:**

When finished working on the switch be sure to return all fields to their original settings.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>change system-parameters maintenance</b>		Examples: <b>change system-parameters maintenance</b>	init inads craft cust rcust	none	none

## Output

The following output example shows a display of the **change system-parameters maintenance** command

```

change system-parameters maintenance                               Page 1 of 3
      MAINTENANCE-RELATED SYSTEM PARAMETERS

OPERATIONS SUPPORT PARAMETERS
  Product Identification: 1000000000
  First OSS Telephone Number: 5551212      Abbrev Alarm Report? y
  Second OSS Telephone Number: 5551212     Abbrev Alarm Report? n
  Alarm Origination to OSS Numbers: both
  Cleared Alarm Notification? y             Suspension Threshold: 5
  Restart Notification? y
  Test Remote Access Port? n
  CPE Alarm Activation Level: none
  Customer Access to INADS Port? n
  Repeat Dial Interval (mins): 7

SCHEDULED MAINTENANCE
  Start Time: 22: 00                               Stop Time: 04: 00
  Daily Maintenance: daily                         Save Translation: daily
  Control Channel Interchange: no                  System Clocks Interchange: no
    
```

4 Maintenance Commands for DEFINITY ONE  
change system-parameters maintenance

4-24

```
change system-parameters maintenance                               Page  2 of  3
      MAINTENANCE-RELATED SYSTEM PARAMETERS

MINIMUM MAINTENANCE THRESHOLDS ( Before Notification )
      TTRs: 4           CPTRs: 1           Call Classifier Ports: 0
      MMIs: 0           VCs: 0

TERMINATING TRUNK TRANSMISSION TEST ( Extension )
      Test Type 100:           Test Type 102:           Test Type 105:

ISDN MAINTENANCE
      ISDN-PRI Test Call Extension:           ISDN-BRI Service SPID:

DS1 MAINTENANCE
      DS0 Loop-Around Test Call Extension:

LOSS PLAN ( Leave Blank if no Extra Loss is Required )
      Minimum Number of Parties in a Conference Before Adding Extra Loss:

SPE OPTIONAL BOARDS
      Packet Intf1? y           Packet Intf2? y
```

```
change system-parameters maintenance                               Page 3 of 3
      MAINTENANCE-RELATED SYSTEM PARAMETERS

      Modem Connection: external
```

## Field descriptions

### Operations support parameters

Product Identification	Identifies switch to an Operations Support System (OSS): 10-digit number starting with 1.
First OSS Telephone Number	Switch reports alarms first to the First OSS telephone number (for example, INADS or Trouble Tracker). The number must be obtained from the National Customer Support Center (NCSC) or the TSC. (# and * are not allowed in the telephone number.)
Abbrev Alarm Report	Enables the Abbreviated Alarm Report feature for the first OSS. (yes)
Second OSS Telephone Number	The switch reports alarms secondly to the second OSS telephone number. For example, INADS or DEFINITY SNMP. The number must be obtained from the National Customer Support Center (NCSC) or the TSC. (# and * are not allowed in the telephone number.)

4 Maintenance Commands for DEFINITY ONE  
*change system-parameters maintenance*

4-25

Abbrev Alarm Report	Enables the Abbreviated Alarm Report feature for the second OSS. (no)
Alarm Origination to OSS Numbers	<p>Indicates one of four options for alarm origination (neither):</p> <p><code>both</code> = Major and Minor alarms result in an automatic call to both administered OSS telephone numbers.</p> <p><code>first-only</code> = Major and Minor alarms result in an automatic call to the first administered OSS number.</p> <p><code>neither</code> = alarm origination does not occur; reports are not sent to either number.</p> <p><code>second no-backup</code> = Major and Minor alarms result in an automatic call to the first administered OSS telephone number. If calling the first OSS telephone number fails four times, the switch calls the second administered OSS telephone number until calling the first OSS telephone number is successful.</p> <p><b>⇒ NOTE:</b> Before Release 1.0, the name of this field is Alarm Origination Activated.</p> <p>If Alarm Origination is deactivated, Cleared Alarm Notification and Restart Notification deactivate, even though they may still be activated in the administration.</p>
Cleared Alarm Notification	The switch originates calls to the OSS and sends an alarm resolution message once all previously-reported Major and Minor alarms are resolved. Activate Alarm Origination to enable Cleared Alarm Notification. (no)
Restart Notification	Enables the switch to originate calls to the OSS and report any system restarts caused by switch problems. Activate Alarm Origination to enable Restart Notification.
Suspension Threshold	Some problems cause alarms to be generated and resolved repeatedly. To detect these problems, the switch suspends Cleared Alarm Notification when it has reported the specified number of Cleared Alarm notifications in a 24 hour period. A suspended Cleared Alarm Notification reactivates with a successfully-completed "logoff" command, a system reset, or when the threshold is changed. This field is irrelevant if Cleared Alarm Notification or Alarm Origination are disabled. (1-15)

## 4 Maintenance Commands for DEFINITY ONE

### *change system-parameters maintenance*

4-26

Test Remote  
Access Port

Indicates if remote access testing on the SYSAM circuit pack is active. This field should be set to **yes** when an INADS line is connected to the switch and a maintenance contract is in effect to maintain alarm origination capability.

If no equipment is connected to the remote access port, or if a trunk for remote access and alarm origination is not provided, running tests on the remote access port on the SYSAM results in test failures. This causes unnecessary maintenance alarms and allows potentially destructive tests to be run. To prevent this set this field to **no**.

CPE Alarm  
Activation  
Level

Indicates the minimum level (Major, Minor or Warning) to activate Customer-Provided Equipment (CPE) alarm. If the level is **none**, the CPE does not activate for any alarm. (none)

#### NOTE:

When the switch goes into Emergency Transfer, the CPE alarm activates regardless of the CPE Alarm Activation Level setting.

Customer Access  
to INADS Port

To prevent customer login ID access to system administration and maintenance interface control, set this field to **no**. Lucent Technologies services has sole access to this field. (no)

Repeat Dial  
Interval (MMS)

Number of minutes that the system must wait before attempting another call origination to an OSS. Lack of a far-end acknowledgment triggers the timer.

## Scheduled maintenance

An automated series of maintenance tests and operations runs daily according to the schedule and settings specified in the following fields

Start Time

Hour and minute (24-hour notation) when daily scheduled maintenance starts

Stop Time

Hour and minute when scheduled daily maintenance ceases. If any daily maintenance operations are not completed by this time, the system notes its stopped sequence location and includes those operations during the next scheduled daily maintenance.

Daily  
Maintenance

This display-only field lists the standard test series run by maintenance software during daily maintenance.

Save  
Translation

Indicates days that translation data in memory automatically saves to the Mass Storage System disk and/or tape devices during scheduled maintenance. The operation saves to disk, then completes a backup to tape. (daily, days of the week, or no) "No" prevents automatic saves.

Control  
Channel  
Interchange

Each port network has a pair of TDM busses called A and B. Each has a set of time slots dedicated to the control channel. One bus (at a time) carries the control channel in each PN. (daily, days of the week, or no) "No" prevents interchanges. (no)

#### 4 Maintenance Commands for DEFINITY ONE

*change system-parameters maintenance*

4-27

System Clocks Interchange	This field indicates the days that interchanges occur. (daily, days of the week, or no). "No" prevents interchanges. (no)
SPE Interchange	This field indicates the days SPE interchanges execute during scheduled maintenance, for duplicated SPE systems. (daily, days of the week, or no). "No" prevents scheduled interchanges. (no)
EXP-LINK Interchange	This field indicates if expansion links between port-networks interchange as part of scheduled maintenance. The value "no" means that EXP-LINK interchanges do not automatically occur as part of scheduled maintenance. (no)
Minimum Threshold for TTRs	When the number of touch tone receivers (TTRs) in service falls below this number (4 to 200), a WARNING alarm is raised against TTR-LEV. These are also known as dual-tone multifrequency receivers (DTMRs). There are 8 TTRs on the TN795. To alarm the first occurrence of a TTR being taken out of service, set this field to the total number of TTRs in the switch.
Minimum Threshold for CPTRs	When the number of call progress tone receivers in service falls below this number (2 to 100), a WARNING alarm is raised against TTR-LEV. These are also known as general purpose tone detectors (GPTDs). There are 8 CPTRs on the TN795. To alarm the first occurrence of a CPTR being taken out of service, set this field to the total number of CPTRs in the switch.
Minimum Threshold for Call Classifier Ports	When the number of call classifier ports (CLSFY-PTs) in service falls below this number, a WARNING alarm is raised against TTR-LEV. Valid entries are 1 to 200. There are 8 ports on the TN795 circuit pack. To alarm the first occurrence of a CLSFY-PT being taken out of service, set this field to the total number of CLSFY-PTs.

#### 4 Maintenance Commands for DEFINITY ONE

*change system-parameters maintenance*

4-28

Test Type  
100, Test  
Type 102,  
Test Type 105

This field specifies extensions assigned to receive tie-trunk calls from other switches that have test line origination capability. The system responds by sending a sequence of test tones. Test Type 100 tests far end to near end loss and C-message by sending:

- 5.5 seconds of 1004 Hz tone at 0dB
- Quiet until disconnect; disconnect is forced after one minute

Test Type 102 tests far end to near end loss by sending:

- 9 seconds of 1004 Hz tone at 0dB
- 1 second of quiet
- This cycle is repeated until disconnect; disconnect is forced after 24 hours.

Test Type 105 tests 2-way loss, gain slope, and C-message and C-notch noise by sending:

- Nine seconds of 1004 Hz at -16dB
- One second of quiet
- Nine seconds of 404 Hz at -16dB
- One second of quiet
- Nine seconds of 2804 Hz at -16dB
- 30 seconds of quiet
- One half second of Test Progress Tone (2225 Hz)
- Approximately five seconds of quiet
- Forced disconnect

ISDN-PRI Test  
Call  
Extension

This field indicates the extension used by far-end ISDN nodes to place calls to the system, for testing ISDN-PRI trunks between the far-end and the system.

ISDN-BRI  
Service SPID

This field shows if the link associates with the Service SPID. If the link is associated with the Service SPID. This number is the test spid (0 – 99999) (see ["BRI-SET, ASAI-ADJ, BRI-DAT" on page 5-334](#)). Otherwise, this field is blank. Service SPID is a feature used by the system technician to check building wiring between the switch and the BRI endpoint.

**4 Maintenance Commands for DEFINITY ONE**  
*change system-parameters maintenance*

DSO  
 Loop-Around  
 Test Call  
 Extension

The extension used to set up a DSO loop around connection for testing non-ISDN DS1 trunks

The DSO Loop-Around Test Call feature is used primarily for testing DSO channels associated with non ISDN-PRI trunks. The loop-around is activated by dialing the test extension number. Multiple DSO Loop-Around connections can be established by placing multiple calls to the loop-around extension.

For more information see [“Facility test calls”](#) in [Chapter 2, “Maintenance Procedures for DEFINITY ONE Compact Modular Cabinets”](#).

Loss Plan

Leave this field blank if no extra loss is required. If extra loss is required, enter digits as shown below. Use this field if additional loss is required to maintain transmission quality for conference calls by entering the digits shown below.

No. of parties to be conferenced	Enter digit
3	2
4	3
5	4
6	5
7	6

SPE Optional Boards:

These fields indicate if a Disk circuit pack is present, and identifies administered Packet Interface slots. If a Packet Interface circuit pack is present, the corresponding Packet Interface field is set to y when the system boots. No change to that field is allowed. If a Packet Interface circuit pack is not present, the value for the Packet Interface field is read from translation data, and stored on disk or tape. If the field is set to **n**, a Packet Interface circuit pack may be administered by changing the corresponding Packet Interface field to **y**.

## clear audits

---

The **clear audits** command clears cumulative and/or peak hour's data collected for each data relation audit. This command clears old data to display data collected since the last **clear audits** command when the **status audits** command is invoked. Refer to ["status audits" on page 4-143](#) for more information).

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>clear audits</b>	<b><i>cumulative</i></b>	Clears data collected about the peak hour since the last reboot or <b>clear audits cumulative</b> command	init inads	none	See below
	<b><i>peak-hour</i></b>	Clears peak hour data  Examples: <b>clear audits cumulative</b> <b>clear audits peak-hour</b>			

### Feature interactions

---

**Status audits** displays data cleared by the **clear audits** command. After **clear audits** executes successfully, the **display audits cumulative** and/or **display audits peak-hour** commands display information collected since the last **clear audits** command. The start date displays on the status audits screen reflecting the time that **clear audits** executed.

## clear errors

---

The **clear errors** command moves errors and resolved alarms to cleared-error lists, making room for new incoming error messages. This command does not clear active alarms from the alarm log. This command must be used with care to prevent overwriting cleared entries. When additional entries are needed to log new errors, the system clears error entries first. Use the **display errors** command to list the cleared errors.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>clear errors</b>		Examples: <b>clear errors</b>	init inads craft	none	none

## clear isdnpri-testcall

The **clear isdnpri-testcall** command cancels in-progress ISDN-PRI test calls. Once a running test call is cleared, another can begin.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>clear isdnpri-testcall</b>	<b>group number</b> <b>member number</b>	Trunk group number.  Member within the trunk group.  Examples: <b>clear isdnpri-testcall 80/1</b> <b>clear isdnpri-testcall 78/2</b>	init inads craft	none	none

## clear mst

The **clear mst** command precedes a trace. If this command is active during a trace, it clears unwanted data.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>clear mst</b>		Examples: <b>clear mst</b>	init inads	none	none

## clear pkt

The **clear pkt** command resolves packet bus problems and sends a forced packet bus **clear stimuli** command over the packet bus.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>clear pkt</b>	<b>port network location</b>	Physical position of the packet bus (1 - 3)  Examples: <b>clear pkt port-network 1</b>	init inads craft	none	none

## clear port

The **clear port** works with the **mark port** command. This command removes marks from ports frees them for service.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>clear port</b>	<b>location</b>	Port location ( <b>PCSSpp</b> )  Examples: <b>clear port 01c1102</b>	init inads cust nms	none	none

## **disable administered-connection**

The **disable administered connection** command stops both scheduled and periodic testing and stops processing of in-line errors for all or selected administered connections.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>disable administered-connection</b>	<b>ac</b>	Number of the administered connection	init inads craft cust rcust mis	none	none
	<b>number</b>				
	<b>all</b>	Selects all administered connections  Examples: <b>disable administered-connection all</b> <b>disable administered-connection 1</b> <b>disable administered-connection 128</b>			

## **disable mst**

The **disable mst** command stops the message trace facility. If the trace was not already disabled, the command inserts a GAP marker into the trace. The user should execute the **disable mst** command when the trace is complete. If left enabled, the trace continues to use CPU time until the time limit expires. Entering **disable mst** command has no effect on the system if the trace is already disabled. To view the results of the trace, enter the **list mst** command.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>disable mst</b>		Example: <b>disable mat</b>	init inads	none	none

## **disable suspend-alm-orig**

The **disable suspend-alm-orig** command stops entries from the active Suspend Alarm Origination table. This command disables all board entries that match a specific physical board location.

**NOTE:**

This command does *not* disable port entries.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>disable suspend-alm-orig</b>	<b>board location</b>	Physical location of the replaced or corrected board (does not support port location)  Examples: <b>disable suspend-alm-orig 1C03</b> <b>disable suspend-alm-orig 1E07</b>	init inads craft cust rcust	none	none

## **disable synchronization-switch**

This command stops the automatic clock switching capability of the maintenance subsystem. The clock refers to the oscillator on a tone/ clock or DS1 interface. The synchronization subsystem (TDM bus clock, DS1 trunk board, and maintenance and administration software) provides error-free digital communication between the switch and other PBXs, COs, or customer equipment.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>disable synchronization-switch</b>			init inads craft	none	none

## **disable test-number**

The **disable test-number** command prohibits selected maintenance tests from running. To run a disabled test number, enter the **enable test-number** command.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>disable test-number</b>	<i>number</i>	Maintenance test number	init inads	none	none

## **display alarms**

The **display alarms** command creates an Alarm Report. The user completes an option screen to select the parameters for the report.

The system creates the reports from the logs of the maintenance subsystem. The subsystem monitors the system hardware and logs problems as errors or alarms. The type of alarm indicates the impact of the problem, as defined below:

**Warning alarm**—A minor interference which does not noticeably impair service.

**Minor alarm**—A problem which could disable a local area of the system and noticeably impair service.

**Major alarm**—A problem which widely degrades the system and seriously impairs service. The system automatically calls INADS to report major alarms.

**Resolved alarm**—A problem which has been corrected, and the system is correctly functioning. The system stamps resolved alarms with the date and time the problem was corrected. The system handles any errors associated with the alarms as “resolved.”

## System Reboots and the Alarm Logs

The system saves the Alarm and Error logs to the memory card if any of the following events occur:

- The **save translation** command is executed.
- Translations are saved as part of scheduled maintenance.
- A reboot takes place.
- The PPN is about to lose all power after having been on battery backup.

The attempt to save the alarm and error logs may be unsuccessful if the MSS is not available.

Whenever the system reboots, the logs are restored from the SPE disk that becomes active with the reboot. Since the logs are saved to the disk on the SPE that was active *before* the reboot, the versions restored at reboot time may not be current. This condition occurs if:

- The attempt to save at reboot did not succeed.
- The SPE disk that is rebooted is not the same disk to which the logs were last saved.

In such a case, the logs will not contain the most recent errors and alarms. To determine if the restored logs are complete, look for indications that would have preceded the reboot.

System resets, that are less severe than a reboot, rarely affect the error and alarm logs.



**NOTE:**

If the error and alarm logs contain SYSTEM errors, then use the **display initcauses** command to search for information that system could *not* log during reset operation.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
display alarms			init inads craft cust rcust bcms browse	all alarms displayed	See below

## Feature interactions

- If the user disables the alarm origination with the **change system-parameters maintenance** command, then the Ack? (Acknowledged) field on the Alarm Report is blank regardless of the true acknowledged state of the alarm.

## Options screen

When you enter the **display alarms** command, the system first displays the options screen. Select the options you want to view on the report. The figure below is an example of the options screen for Alarm Reports.

```

display alarms                                     Page 1 of 1

                                ALARM REPORTS

The following options control which alarms will be displayed.
ALARM TYPES
    Active? y_      Resolved? n_
    Major? y_      Minor? y_      Warning? y_
REPORT PERIOD
    Interval: m_    From: __/__/__:__ To: __/__/__:__
EQUIPMENT TYPE ( Choose only one, if any, of the following )
    Cabinet: _____
    Port Network:  __
    Board Number:  _____
    Port:          _____
    Category:     _____
    Extension:    _____
Trunk ( group/member ): __/___

```

## Field descriptions

ALARM TYPES	Enter <b>y</b> (yes) or <b>n</b> (no) in any of the 5 alarm type fields
Interval	Enter <b>one</b> of the codes below: <b>m</b> = last month <b>h</b> = last hour <b>d</b> = last day <b>w</b> = last week <b>a</b> = all (default)
From	Month/day/year (example: 01/01/97); if the From date is blank, the report contains all the active alarms for the month <i>prior</i> to the current date.
To	Month/day/year (example: 01/15/97); if the To date is not entered, the report contains all the active alarms starting with the From date to the current date.
Cabinet	Administered cabinet number (1-3)

**4 Maintenance Commands for DEFINITY ONE**  
*display alarms*

4-36

Port Network	1-3
Board Number :	Board address ( <b>PCSS</b> ); example: 01A20
Port	Port address ( <b>PCSSpp</b> ); example: 01A2031
Category	Object code for the equipment category. Press <b>HELP</b> in this field to view a list of the object codes.
Extension	Extension number (per dial-plan)
Trunk	Enter a group number or a group and member number: <ul style="list-style-type: none"> <li>■ Enter <i>only</i> the <b>group</b> number (01-99) to display <i>all</i> members in the group. Example: 01/___</li> <li>■ Enter <i>both</i> the <b>group</b> number (01-99) and <b>member</b> number (01-99) to display a <i>specific</i> member in a group. Example: 01/99</li> </ul>

**Output**

After you complete the options screen, the system displays a 1- or 2-page Alarm Report. To toggle between the pages and to exit the report, use the keys described below:

- or 513 and 715 terminals, use **F8** for NEXT PAGE and PREV PAGE commands
- For all other terminals, use **F7** for NEXT PAGE and PREV PAGE commands
- Use **Esc** for the CANCEL command.

The screen below shows an example of an Alarm Report.

```
display alarms
```

## ALARM REPORT

Port	Maintenance Name	On Brd?	Alt Name	Alarm Type	Svc State	Ack? 1 2	Date Alarmed	Date Resolved
01C07	ANL-BD	y		MINOR		n n	05/22/20:26	00/00/00:00
01C0702	ANL-LINE	n	311	WARNING	IN		05/22/20:26	00/00/00:00
01C0701	ANL-LINE	n	1051	WARNING	IN		05/22/20:26	00/00/00:00
01C0703	ANL-LINE	n	1053	WARNING	IN		05/22/20:26	00/00/00:00
01C1505	CO-TRK	n	78/01	WARNING	OUT		05/22/20:26	00/00/00:00
01C1505	CO-TRK	n	78/01	WARNING	OUT		05/22/20:26	00/00/00:00
PN 02B	TDM-BUS	n		WARNING			05/23/14:53	00/00/00:00

```
Command successfully completed
```

## Field descriptions

Port	Lists the location codes for the alarmed object, as follows: <ul style="list-style-type: none"><li>■ Circuit packs locations display as: cabinet-carrier-[slot]-[circuit]. Example: <b>01C0702</b>.</li></ul>
Maintenance Name	Lists the logical name of the maintenance object with the alarm.
On Brd	A <b>y</b> (yes) indicates the fault was found on the associated circuit pack. A <b>n</b> (no) indicates the fault is <b>not</b> connected to the circuit pack.
Alt Name	Identifies the location of maintenance object, as follows: <ul style="list-style-type: none"><li>■ Station = extension number</li><li>■ Trunk = Group number (78/__) or group and member numbers (78/01)</li><li>■ Private CO Line = private CO line (P) and group number. (P/xxx)</li></ul>
Alarm Type	Alarm level: MAJOR, MINOR, or WARNING
Service State	Service state of the station and trunk ports: <ul style="list-style-type: none"><li>■ RDY = ready for service</li><li>■ OUT = out of service</li><li>■ IN = in service</li><li>■ [Blank] = No associated service state</li></ul>
Ack?	Headings 1 and 2 identify the first and second OSS telephone numbers, respectively. The entries below indicate the acknowledged alarm state: <ul style="list-style-type: none"><li>■ <b>y</b> (yes) = alarm has been acknowledged</li><li>■ <b>n</b> (no) = alarm has <b>not</b> been acknowledged</li><li>■ <b>c</b> (cleared) = alarm was first acknowledged, then resolved and cleared</li></ul> <p>[Blank] = no attempt was made to report the alarm</p> <p><b>⇒ NOTE:</b> If the user disables the alarm origination with the <b>change system-parameters maintenance</b> command, then the <b>Ack?</b> field will be blank regardless of the true acknowledged state of the alarm.</p>
Date Alarmed	Month, day, hour, and minute of the alarm.
Date Resolved	Month, day, hour, and minute of the resolution (active alarms = zeros)

## display capacity

This form describes how you have administered your system and provides a "snapshot" status of the switch resources.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
display capacity			init inads craft cust rcust	none	none

The screen below shows the output from the **display capacity** command.



**NOTE:**

The capacities listed may not coincide with your system. The figures that follow are included to help explain the command and the field values, not to provide capacity information.

```

display capacity                                     Page 1 of 9

                SYSTEM CAPACITY

Current System Memory Configuration: G3cfsV6

                Used   Available   System
                -----
AAR/ARS
    AAR/ARS Patterns:           17       623       640
    Inserted Digit Strings:      6      2994      3000

ABBREVIATED DIALING (AD)
    AD Entries Per System:      10     99990    100000
    AD Personal Lists Per System: 1      4999      5000

ADJUNCT SWITCH APPLICATION INTERFACE (ASAI)
    Active Controlling Associations: 0       6000      6000
    Notification Requests:         0      10000     10000
Simultaneous Active Adjunct Controlled Calls: 0       3000      3000
    
```

### Field descriptions (page 1)

#### AAR/ARS

AAR/ARS  
Patterns

The number of route patterns. For further information, see *DEFINITY Enterprise Communications Server Administration and Feature Description*.

Inserted Digit Strings      Number of 12-character inserted-digit strings available for AAR/ARS preferences. For further information, see *DEFINITY Enterprise Communications Server Administration and Feature Description*.

**Abbreviated Dialing (AD)**

AD Entries Per System      The number of abbreviated dialing entries (for both group and personal lists).

AD Personal Lists Per System      The number of abbreviated dialing personal lists. For further information, see *DEFINITY Enterprise Communications Sever Administration and Feature Description*.

**Adjunct Switch Application Interface (ASAI)**

Active Controlling Associations      The number of station domain controls that ASAI adjuncts can request.

Notification Requests      The number of requests ASAI can make to monitor call activity at a split or VDN.

Simultaneous Active Adjunct Controlled Calls      The number of calls that can be controlled by ASAI adjuncts.

SYSTEM CAPACITY		Page 2 of 9		
	Used	Available	System Limit	
	-----	-----	-----	
ATTENDANT SERVICE				
Attendant Positions:	2	26	28	
Queue Length:	0	300	300	
Authorization Codes:	0	90000	90000	
BASIC CALL MANAGEMENT SYSTEM (BCMS)				
Measured Agents Per System:	0	2000	2000	
Measured Splits/Skills:	0	600	600	
VDNs:	0	512	512	

Figure 4-1. System Capacity form (page 2 of 9)

Field descriptions (page 2)

**Attendant Service**

Attendant Positions	The number of administered attendants.
Queue Length	A <i>real-time</i> snapshot of the number of calls waiting for all attendants.
Authorization Codes	The number of authorization codes used for security purposes. For further information, see <i>DEFINITY Enterprise Communications Server Administration and Feature Description</i> .

**Basic Call Management System (BCMS)**

Measured Agents Per System	The number of agents the Basic Call Management System (BCMS) is measuring.
Measured Splits/Skills	The number of hunt groups BCMS is measuring.
VDNs	The number of vector directory numbers BCMS is measuring.

			Page 3 of 9
	SYSTEM CAPACITY		
		Used	Available System Limit
		-----	-----
	CALL COVERAGE		
	Coverage Answer Groups:	0	750 750
	Coverage Paths:	7	9992 9999
	Call Pickup Groups:	0	5000 5000
	Call Records:	-	- 7712
	CALL VECTORING/CALL PROMPTING		
	Vector Directory Numbers:	2	19998 20000
	Vectors Per System:	3	509 512
	BSR Application-Location Pairs Per System:	0	1000 1000

Figure 4-2. System Capacity form (page 3 of 9)

**Field descriptions (page 3)****Call Coverage**

Coverage Answer Groups	The number of Coverage Answer Groups. For further information, see <i>DEFINITY Enterprise Communications Server Administration and Feature Description</i> .
Coverage Paths	Coverage Paths — The number of coverage paths which is a path taken when a call goes to coverage. For further information, see <i>DEFINITY Enterprise Communications Server Administration and Feature Description</i> .
Call Pickup Groups	The number of call pickup groups have been administered. For further information, see <i>DEFINITY Enterprise Communications Server Administration and Feature Description</i> .
Call Records	The maximum number of active calls at a given time. This field does not display real-time data, just the system limit and is not administrable.

**Call Vectoring/Call Prompting**

Vector Directory Numbers	The number of system VDNs. For further information, see <i>DEFINITY Call Vectoring/Expert Agent Selection</i> .
Vectors Per System	The number of vectors per system. For further information, see <i>DEFINITY Call Vectoring/Expert Agent Selection</i> .
BSR Application - Location Pairs Per System	The number of mappings administered in a multisite network. The maximum number of application-location pairs per system is 1000. For example, for a network of 10 locations, you can assign 100 applications; with 50 locations, you can assign 20 applications. For further information, see <i>DEFINITY Call Vectoring/Expert Agent Selection</i> .

Page 4 of 9

SYSTEM CAPACITY

	Used	Available	System Limit
	-----	-----	-----
DATA PARAMETERS			
Administered Connections:	5	123	128
Alphanumeric Dialing Entries:	0	1250	1250
DIAL PLAN			
Extensions:	104	35961	36065
Miscellaneous Extensions:	25	20292	20317
UDP Extension Records:	15	49985	50000
Digital Data Endpoints:	50	7450	7500
Expansion Port Networks:	2	41	43
Facility Busy Indicators:	10	9990	10000

Figure 4-3. System Capacity form (page 4 of 9)

### Field descriptions (page 4)

#### Data Parameters

**Administered Connections** The number of connections between two access or data endpoints. For further information, see *DEFINITY Enterprise Communications Server Administration and Feature Description*.

**Alphanumeric Dialing Entries** For further information, see *DEFINITY Enterprise Communications Server Administration and Feature Description*.

#### Dial Plan

**Extensions** This includes stations, data endpoints, hunt groups, announcements, TEGs, VDNs, common shared extensions, and code calling IDs.

**Miscellaneous Extensions** Anything that is not a station, trunk, data module, or attendant. This includes, but is not limited to, PCOL groups, common shared extensions, access endpoints, administered TSCs, code calling IDs, VDNs, LDNs, hunt groups, announcements, and TEGs.

**UDP Extension Records** The number of 4- or 5-digit extension numbers that allow a user to call from one PBX to another using that number.

**Digital Data Endpoints** The number of digital serial communication devices that permit the asynchronous transfer of data. This also includes the number of analog adjuncts.

4 Maintenance Commands for DEFINITY ONE  
display capacity

4-43

Expansion Port Networks The number of port networks connected to the TDM bus and packet bus of a process port network.

Facility Busy Indicators The number of visual indicators of the busy/idle status of any particular trunk group, hunt group member, or station user. For further information, see *DEFINITY Enterprise Communications Server Administration and Feature Description*.

Page 5 of 9

SYSTEM CAPACITY

	Used	Available	System Limit
	-----	-----	-----
HUNT GROUPS, SPLITS, OR SKILLS			
Groups/Splits/Skills:	9	591	600
Logged-In ACD Agents:	0	5200	5200
Group Members Per System:	17	9983	10000
CMS Measured ACD Members:	0	10000	10000
Queue Slots Per System:	2	14998	15000
Queue Status Buttons:	0	2000	2000
Intercom Groups Per System:	0	256	256
Modem Pool Groups Per System:	0	63	63
Personal CO Line (PCOL) Trunk Groups:	0	200	200

Figure 4-4. System Capacity form (page 5 of 9)

Field descriptions (page 5)

Hunt groups, splits, or skills

Groups/Splits/Skills The number of ACD hunt groups.

Logged-In ACD Agents A *real-time* field displaying the number of agents actually logged in. For example, if an agent is logged into 4 skills (and there are no other agents), then the Logged-In ACD Agents field is 1 and the Group Members Per System field is 4.

Group Members Per System The number of agent/group pairs.

CMS Measured ACD Members The number of agent pairs being measured by CMS.

Queue Slots Per System The number of hunt group queue positions.

4 Maintenance Commands for DEFINITY ONE  
display capacity

4-44

- Queue Status Buttons      The number of hunt group queue status buttons administered on stations. There are four types of queue status buttons; attendants use the last two queue status buttons:
  - q-calls (Queue Calls)
  - q-time (Queue Time)
  - atd-qcalls (ATD - Queue Calls)
  - atd-qtime (ATD - Queue Time)
  
- Intercom Groups Per System      The number of intercom groups set up within your organization.
  
- Modem Pool Groups Per System      The number of modem pool groups. For further information, see *DEFINITY Enterprise Communications Server Administration and Feature Description*.
  
- Personal CO Line (PCOL) Trunk Groups      The number of PCOL trunk groups. For further information, see *DEFINITY Enterprise Communications Server Administration and Feature Description*.

Page 6 of 9

SYSTEM CAPACITY	Used	Available	System Limit
	-----	-----	-----
Recorded Announcement Analog Queue Slots:	0	1256	1256
TEMPORARY SIGNALING CONNECTIONS (TSC)			
Administered TSCs:	0	128	128
NCA-TSC Calls:	0	256	256
TRUNKS			
DS1 Circuit Packs:	9	157	166
ICHT For ISDN Trunks:	0	576	576
ISDN CBC Service Selection Trunks:	1	199	200
Trunks Groups:	29	637	666
Trunks Ports:	86	3914	4000

Figure 4-5. System Capacity form (page 6 of 9)

Field descriptions (page 6)

Recorded Announcement Analog Queue Slots The number of calls in queue for the system's analog announcements.

Temporary Signaling Connections (TSC)

Administered TSCs The number of allowed Temporary Signaling Connections (TSCs).  
NCA-TSC Calls The number of allowed Non-Call Associated TSCs.

Trunks

DS1 Circuit Packs The number of allowed DS1 circuit packs.  
ICHT For ISDN Trunks The number of Incoming Call Handling Table (ICHT) entries administered for trunk groups.  
ISDN CBC Service Selection Trunks The number of call-by-call trunk groups.  
Trunk Groups The number of trunk groups administered.  
Trunk Ports The number of trunk ports administered.

Page 7 of 9

SYSTEM CAPACITY			
	Used	Available	System Limit
	-----		
VOICE TERMINALS			
Station Button Memory (units):	0 %	100 %	5260000
Station Records:	35	24965	25000
Stations:	29	-	-
Stations With Port:	29	-	-
Stations Without Port:	0	-	-
Other Stations:	6	-	-
TTI Ports:	0	-	-
TOTAL SUBSCRIBED PORTS			
ISDN BRI Ports:	3	6997	7000
Station and Trunk Ports:	119	13881	14000

Figure 4-6. System Capacity form (page 7 of 9)

Field descriptions (page 7)

**Voice Terminals**

Station Button Memory (units)	The percentage of memory being consumed by all administered buttons.
Station Records	The number of resources being used by regular stations, announcements, and music on hold.
Stations	The number of voice terminals.
Stations With Port	The number of connected voice terminals (stations with specific administered ports).
Stations Without Port	The number of voice terminals not having an administered port, such as AWOH.
Other Stations	The number of ports used as conversion resources, agent login ID, MASI, and analog announcements.
TTI Ports	The number of ports assigned by TTI features.

**Total Subscribed Ports**

ISDN BRI Ports	The number of ISDN-BRI ports.
Station and Trunk Ports	The number of stations with ports and assigned trunk ports.




Figure 4-7. System Capacity form (page 8 of 9)

## Field descriptions (page 8)

### Current System Information

Software Load	The current software load on which the system is running.
Memory Configuration	The system platform.
Offer Category	The system's offer category.

### Last Translation Loaded Information

Software Load	The software load translations saved before upgrade or reboot.
Memory Configuration	The platform on which the translations were saved. Can also be <code>unknown</code> if no flash card is present or translations made on old load. This is important because platforms are not always compatible.
Offer Category	The offer category that was set when the last save translation was done before upgrade or reboot. Can also be <code>unknown</code> if no flash card is present or translations made on old load.

```

display capacity                                     Page 9 of 9
SYSTEM CAPACITY

CURRENT SYSTEM INFORMATION

Software Load: G3V8c.00.0.509.0
Memory Configuration: G3cfsV8
Offer Category: A

LAST TRANSLATION LOADED INFORMATION

Software Load: G3V8c.00.0.509.0
Memory Configuration: G3cfs(compact co-res)
Offer Category: A
    
```

Figure 4-8. System Capacity form (page 9 of 9)

## Field descriptions (page 9)

### Total Subscribed Ports

Radio Controllers	The number of subscribed radio controller circuit packs.
Wireless Terminals	The number of subscribed wireless terminals.

## **display disabled-tests**

---

This command lists the numbers for all maintenance tests that have been disabled by INADS. These tests will not be available for background or demand testing.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>display disabled-tests</b>			init inads craft cust rcust	none	none

## **Output**

---

The following examples shows the output from the **display disabled-tests** command.

```
display disabled-tests                               SPE A

                DISABLED TEST INFORMATION

    Test Number
    710

Command successfully completed
```

## display errors

---

The **display errors** command creates an Alarm Report. The user completes an option screen to select the parameters for the report.

The system creates the reports from the logs of the maintenance subsystem. The subsystem monitors the system hardware and logs problems as errors or alarms.

Errors can result from in-line firmware errors, periodic tests, failures detected while executing a test command, software inconsistency, or a data audit discrepancy.

### System reboots and the error logs

The system saves the alarm and error logs to the memory card if any of the following events occur:

- The **save translation** command is executed.
- Translations are saved as part of scheduled maintenance.
- A reboot takes place.
- The PPN is about to lose all power after having been on battery backup.

The attempt to save the alarm and error logs may be unsuccessful if the MSS is not available.

Whenever the system reboots, the logs are restored from the SPE disk that becomes active with the reboot. Since the logs are saved to the disk on the SPE that was active *before* the reboot, the versions restored at reboot time may not be current. This condition occurs if:

- The attempt to save at reboot did not succeed.
- The SPE disk that is rebooted is not the same disk to which the logs were last saved.

In such a case, the logs do not contain the most recent errors and alarms. To determine if the restored logs are complete, look for indications that would have preceded the reboot.

System resets, less severe than a reboot, rarely affect the error and alarm logs.

#### NOTE:

If the error and alarm logs contain SYSTEM errors, then use the **display initcauses** command to search for information that system could *not* log during reset operation.

4 Maintenance Commands for DEFINITY ONE  
*display errors*

4-50

Action/ Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>display errors</b>	<b>high resolution</b>	Highlights the time stamps on the Error Report for the first and last occurrences of the error.	init inads craft cust nms browse	all errors displayed	none

## Input form

When you enter the **display errors** command, the system first displays the options screen. You select the options you want to view on the report. The figure below is an example of the options screen for an Error Report.

```

display errors                                     Page 1 of 1
                                     ERROR REPORT
The following options control which errors will be displayed.
ERROR TYPES
  Error Type: _____ Error List: active-alarms
REPORT PERIOD
  Interval: _           From: __/__/__:__ To: __/__/__:__
EQUIPMENT TYPE ( Choose only one, if any, of the following )
  Cabinet: _____
  Port Network: _____
  Board Number: _____
  Port: _____
  Category: _____
  Extension: _____
Trunk ( group/member ): __/___
    
```

## Field descriptions

**Error Type** Enter a specific error type. If the field is blank, the system displays all errors. Press HELP in this field to view a list of codes.

**Error List** Enter **one** of the error lists below:

active-alarms (default)  
errors  
cleared-errors

The title for the Hardware Error Report will include the name of the selected error list.

**Interval** Enter **one** of the codes below:

**m** = last month  
**h** = last hour  
**d** = last day (default)  
**w** = last week  
**a** = all

#### 4 Maintenance Commands for DEFINITY ONE

*display errors*

4-51

From	Enter 2-digit numbers for the month/day/year (Example: 01/01/97). The default is the earliest time of the existing error records in the log.
To	Enter 2-digit numbers for the month/day/year (Example: 01/01/97). The default is the current date.
Cabinet	Enter 1
Port Network	Enter 1
Board Number :	Board address: <b>PCSS</b>
Port	Port location: <b>PCSSpp</b>
Category	Enter the object code for the equipment category. Press HELP in this field to view a list of the object codes
Extension	Enter the extension number
Trunk	Enter a group number or a group and member number: <ul style="list-style-type: none"><li>■ Enter <i>only</i> the <b>group</b> number (01-99) to display <i>all</i> members in the group. Example: 01/___</li><li>■ Enter <i>both</i> the <b>group</b> number (01-99) and <b>member</b> number (01-99) to display a <i>specific</i> member in a group. Example: 01/99.</li></ul>

### Form output

After completing the options screen, the system displays a 1- or 2-page Hardware Error Report. To toggle between the pages and to exit the report, use the keys described below:

- For 513 and 715 terminals, use **F8** for NEXT PAGE and PREV PAGE commands
- For all other terminals, use **F7** for NEXT PAGE and PREV PAGE commands
- Use **Esc** for the CANCEL command

The screen below is an example of an Hardware Error Report -- Active Alarms, **without** the high-resolution qualifier in the command line.

4 Maintenance Commands for DEFINITY ONE  
display errors

4-52

display errors Page 1 SPE A

HARDWARE ERROR REPORT - ACTIVE ALARMS

Port	Mtce Name	Alt Name	Err Type	Aux Data	First Occur	Last Occur	Err Cnt	Err Rt	Rt/ Hr	Al St	Ac
01C0702	ANL-LINE	311	257		01/31/09:20	01/31/20:26	255	256	255	a	y
01C0701	ANL-LINE	1051	257		01/31/20:26	01/31/20:26	4	0	4	a	y
01C0703	ANL-LINE	1053	257		01/31/20:26	01/31/20:26	4	0	4	a	y
01A	TDM-CLK		0	0	01/31/20:34	01/31/20:34	1	0	1	a	n
01C1505	CO-TRK	078/001	3329	57408	01/31/20:26	01/31/20:27	5	300	5	a	y
01C1505	CO-TRK	078/001	1537		01/31/20:26	01/31/20:28	5	150	5	a	y

Command successfully completed

## Field descriptions

- Port** Lists the location codes for the alarmed object, as follows:
- Circuit packs locations display as: cabinet-carrier-[slot]-[circuit]. Example: 01C702.
  - Port network locations display as: port network number-bus. Example: **PN 01B**. PN 01 = Port Network (PN) number and A or B = bus.
- Maintenance Name** Lists the logical name of the maintenance object with an error logged against it.
- Alt Name** Identifies the location of maintenance object, as follows:
- Station = extension number
  - Trunk = Group number (78/\_\_) or group and member numbers (78/01)
  - Private CO Line = private CO line (P) and group number (P/xxx)
- Error Type** Lists the error number for the type of problem encountered for this maintenance object. The technician must use this error number in conjunction with the logical name information to determine the exact nature of the error.
- Aux Data** Lists additional information concerning the maintenance object error condition. Like the error type, this data will be specific to the maintenance object type. However, unlike the error code, only the most recent value of the auxiliary data will be retained for each error record.
- First Occur** Displays the month, day, hour, and minute (and second if the high-resolution command line option is used) that the error was first recorded.

**4** Maintenance Commands for DEFINITY ONE  
*display errors*

4-53

Seq Cnt	Sequence Count - This number indicates the order of errors logged within a second for the time stamps associated with the first occurrence and last occurrence of an error. This information is displayed only if the <b>high-resolution</b> command line option is entered. There may be gaps for the sequence numbers within a given second since the last occurrence of an error may replace an existing entry that had been assigned the missing sequence number. Gaps may also appear in the numbers since sequence counts are also used with software event information not shown in the hardware error log.
Last Occur	Displays the month, day, hour, and minute (and second if the high-resolution command line option is used) of the most recent error. Note: if the system is unable to retrieve the time of day when the error occurred, a 'dummy' date will be stamped in the log and appears as: <b>00/00/01:07</b> .
Err Cnt	Error Count - The total number of times that the error type has occurred for this maintenance object. If the number of errors exceeds 3 digits, the system enters the number <b>256</b> , which indicates that a larger number of errors occurred, but could not be displayed correctly.
Err Rt	Error Rate - The average rate at which the errors have occurred from the first occurrence to the present. If the number of errors exceeds 3 digits, the system enters the number <b>256</b> , which indicates that a larger number of errors occurred, but could not be displayed correctly.
Rt/Hr	Rate per Hour - An approximation of the rate that this error occurred in the last hour. If the number of errors exceeds 3 digits, the system enters the number <b>256</b> , which indicates that a larger number of errors occurred, but could not be displayed correctly.
Al St	Alarm Status - A character indicating the status of this MO in the error and alarm logs. The allowed values are:  <b>a</b> = Active alarm entry  <b>r</b> = Resolved alarm entry  <b>c</b> = Resolved alarm entry as a result of the long "clear" option of the test command  <b>s</b> = Resolved alarm entry as a result of a software requested (non-demand) system restart  <b>t</b> = Resolved alarm entry as a result of a technician requested system restart  <b>n</b> = Not alarmed.
Ac	Active? - A <b>y</b> (yes) entry indicates the maintenance object is still active. A <b>n</b> (no) entry indicates the object is no longer a problem.

The screen below is an example of an Hardware Error Report -- Active Alarms, **with** the high-resolution qualifier in the command line.

When you enter the command **display errors high-resolution**, the system adds the Seq Cnt (sequence count) column. The number in the column indicates the order of errors logged within a second for the time stamps associated with the first occurrence and the last occurrence of an error. Refer to the field description above for more details.

```
display errors high-resolution Page 1 SPE A
```

HIGH RESOLUTION HARDWARE ERROR REPORT - ACTIVE ALARMS

Port	Mtce Name	Alt Name	Err Type	Aux Data	First Occur	Seq Cnt	Last Occur	Seq Cnt	Err Cnt	Al St
01C0702	ANL-LINE	311	257		01/31/09:20:21	1	01/31/20:26:05	1	255	a
01C0701	ANL-LINE	1051	257		01/31/20:26:18	1	01/31/20:26:18	7	4	a
01C0703	ANL-LINE	1053	257		01/31/20:26:18	2	01/31/20:26:18	8	4	a
01A	TDM-CLK		0	0	01/31/20:34:35	1	01/31/20:34:35	1	1	a
01C1505	CO-TRK	078/001	3329	57408	01/31/20:26:07	1	01/31/20:27:28	1	5	a
01C1505	CO-TRK	078/001	1537		01/31/20:26:52	1	01/31/20:28:41	1	5	a

Command successfully completed



## Field descriptions

Category	Vector specifies the type of event report to display and is the only valid entry.
Report Period	The fields in this section allow you to view only those vector events that occurred within a specific time period. If these are left blank, all vector events recorded are displayed.
Interval:	This field specifies a display of all events within the last time period of the type Enter the first letter of one of the following selections: all, month, day, hour, minute.
Start/Stop Time	The starting and ending times of the interval to be reported in 24-hour notation.
Vector Number	The number of the vector (1-256) for which events will be reported. If this field is left blank, events for all vectors are reported.
Event Type	Specific types of vector events are associated with numbers from 50000 to 50999. Entering one of these numbers limits the report to events of this type. If this field is left blank, events for all types of vectors are reported.

## Output

See *DEFINITY Communications System Generic 3 Call Vectoring and Expert Agent Selection (EAS) Guide*, 555-230-520, for more information on how to interpret this report. In particular, the `Event Data 2` field is associated with possible causes and repair strategies for the event.

The following example shows a typical vector event report.

```

display events                                     Page 1   SPE B

                                EVENTS REPORT

Event Event          Event  Event  First   Last   Evnt
Type  Description     Data 1  Data 2  Occur   Occur   Cnt
-----
50020 Call not queued    256/5   B   09/28/13:43 09/28/13:43 1
50541 Not a messaging split Split 89 4C 09/28/13:43 09/28/13:43 1
    
```

## Field descriptions

Event Type	A number from 50000 to 50999 that identifies what type of vector event occurred.
Event Description	A text string describing the event.
Event Data 1	If in the format <i>number/number</i> such as "200/10", this indicates the vector number and step number associated with the event. If in the format "Split <i>number</i> " such as "Split 2", this indicates the split number.
Event Data 2	Additional data concerning the event encoded as a hex number.
First Occur	The date and time when the vector event first occurred.
Last Occur	The date and time when the vector event last occurred.
Evnt Cnt	The total number of times, up to 255, that vector events of this type have occurred.

## display initcauses

The **display initcauses** command displays a history of recovery steps taken by the system. Each time the system performs some type of recovery (due to user request or a hardware or software problem), the recovery information is stored. The software error log also contains information pertaining to restarts. If a reset 4 (reboot) occurs, the software error log is also be stored. Information in the software error log should be used in conjunction with information in the *initcauses* log.

The history of the last 16 restarts performed by the system will be recorded to the *initcauses* buffer in chronological order. This buffer fills an entire screen with information if it is completely full. Power failures in the processor complex wipe out the entire *initcauses* buffer.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>display initcauses</b>			init inads craft nms	none	none

## Output

The following example shows the output from the **display initcauses** command.

```
display initcauses
```

### INITIALIZATION CAUSES

Cause	Action	Escalated	Carrier	Time
System Technician Request	4	no	1A	08/05 9:15
Upgrade Software	2	no	1A	08/05 9:29
Software Request	1	no	1A	08/09 2:34

```
Command successfully completed
```

## Field descriptions

Cause	<ul style="list-style-type: none"><li>■ <b>Bad Memory</b>: A defective memory circuit pack generating too many errors caused a restart.</li><li>■ <b>System Technician Request</b>: The restart was performed because of system technician demand. A system technician-requested <b>reset system 4</b> command entry should always precede an <b>upgrade software</b> command entry.</li><li>■ <b>Initialized</b>: This is always the first entry in the history and is present until more than 15 restarts have been performed.</li><li>■ <b>Maintenance Reset</b>: This refers to resets of the SPE by maintenance in SPE Down mode in which maintenance periodically tries to awaken the SPE.</li><li>■ <b>Software Request</b>: Software requested the system restart.</li><li>■ <b>Unknown</b>: A restart that could not be classified. The Software Error Log may contain more information about the restart.</li></ul>
Action	The level of recovery performed by the system. The recovery levels follow: <ul style="list-style-type: none"><li>Reset system 1 (Warm)</li><li>Reset system 2 (Cold-2)</li><li>Reset system 4 (Reboot)</li></ul>
Escalated	Whether the restart was escalated to a higher level to clear the problem. There is a software escalation strategy that can cause a higher level restart than the one previously performed to be executed if the need arises.
Carrier	Indicates the carrier on which the recovery was performed ( <b>1A</b> ).
Time	The date (month and day) and time of the restart.

## display port

This command displays the port location, the equipment connected to the port, and the means by which the port can be identified (for example, an extension number, the trunk group and member, and so on).

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
display port	<i>location</i>	Port address ( <b>PCSSpp</b> )	init inads craft cust browse	none	none

## Output

The following example shows the output for the **display port 1c0801** command.

```
display port 1c0801                               SPE A

          PORT INFORMATION

          Port: 01C0801
          Equipment Type: Station
          Identification: 1021
```

## Field descriptions

Port:	Port address (cabinet-carrier-slot-circuit)
Equipment Type:	Hardware that is physically connected to the specified port.
Identification:	Depends on the hardware that is physically connected to the port:
	<b>If hardware is      The field contains</b>
	station                      station extension
	trunk                        trunk group and member number)
	modem pool                modem pool group number

## display synchronization

This command calls up the synchronization form where the administered synchronization stratum and reference sources are displayed. (No changes can be made to the system synchronization with this command.)

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>display synchronization</b>			init inads craft cust rcust bcms browse	none	See below

### Feature interactions

- A DS1 interface or a UDS1 board that has been selected as either a primary or secondary synchronization source cannot be removed on the DS1 circuit pack administration form or the regular circuit pack administration form.

### Output

The following example shows the output for the **display synchronization** command.

```

display synchronization                               Page 1 of 2

SYNCHRONIZATION SOURCE (Synchronization Plan circuit pack location)

Stratum: 4
Primary:      Secondary:

                DS1 CIRCUIT PACKS

Location      Name      Slip      Location      Name      Slip
01C10 D92D1 ds1 lc10   n
01C11 D92D1 ds1 lc11   n

NOTE: DS1 and BRI Trunk sources result in stratum 4, type II synchronization
    
```

## Field descriptions

Stratum:	Synchronization stratum that is used (3 or 4)
Primary:	First choice system synchronization source (blank = no synchronization); valid only if stratum 4 synchronization specified
Secondary:	Second choice system synchronization source (blank = no synchronization); valid only if stratum 4 synchronization specified
Location:	Circuit pack location (cabinet-carrier-slot) of all administered DS1 circuit packs are listed here.
Name:	User-defined name administered for the DS1 circuit pack. Blank means no user-defined name administered.
Slip:	If the DS1 circuit pack has slip alarm, field shows <i>y</i> ; otherwise, <i>n</i> .

## **display system-parameters maintenance**

---

This command displays the translation data for maintenance-related system parameters.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>display system-parameters maintenance</b>			init inads craft super-user Maintain Switch Circuit Packs permissions	none	none

**4 Maintenance Commands for DEFINITY ONE**  
*display system-parameters maintenance*

4-62

**Output**

The following display shows a typical result when **display system-parameters maintenance** is entered.

```
display system-parameters maintenance                Page 1 of 3
                MAINTENANCE-RELATED SYSTEM PARAMETERS

OPERATIONS SUPPORT PARAMETERS
    Product Identification: 1000000000
    First OSS Telephone Number: 5551212             Abbrev Alarm Report? y
    Second OSS Telephone Number: 5551212           Abbrev Alarm Report? n
    Alarm Origination to OSS Numbers: both
    Cleared Alarm Notification? y                  Suspension Threshold: 5
    Restart Notification? y
    Test Remote Access Port? n
    CPE Alarm Activation Level: none
    Customer Access to INADS Port? n
    Repeat Dial Interval (mins): 7

SCHEDULED MAINTENANCE
    Start Time: 22: 00                               Stop Time: 04: 00
    Daily Maintenance: daily                         Save Translation: daily
    Control Channel Interchange: no                  System Clocks Interchange: no
```

```
display system-parameters maintenance                Page 2 of 3
                MAINTENANCE-RELATED SYSTEM PARAMETERS

MINIMUM MAINTENANCE THRESHOLDS ( Before Notification )
    TTRs: 4          CPTRs: 1          Call Classifier Ports: 0
    MMIs: 0          VCs: 0

TERMINATING TRUNK TRANSMISSION TEST ( Extension )
    Test Type 100:          Test Type 102:          Test Type 105:

ISDN MAINTENANCE
    ISDN-PRI Test Call Extension:          ISDN-BRI Service SPID:

DS1 MAINTENANCE
    DS0 Loop-Around Test Call Extension:

LOSS PLAN ( Leave Blank if no Extra Loss is Required )
    Minimum Number of Parties in a Conference Before Adding Extra Loss:

SPE OPTIONAL BOARDS
    Packet Intf1? y          Packet Intf2? y
```

```
display system-parameters maintenance
      MAINTENANCE-RELATED SYSTEM PARAMETERS
```

Page 3 of 3

```
Modem Connection: external
```

## Field descriptions

Defaults for data entry fields are listed in parentheses.

Product Identification	10-digit number (starting with 1) that identifies the switch to an Operations Support System (OSS), for example, INADS.
First OSS Telephone Number	First telephone number that the switch dials to report alarms; must be obtained from the National Customer Support Center (NCSC) or the TSC. (# and * are not allowed in the telephone number.)
Abbrev Alarm Report	Enables the Abbreviated Alarm Report feature for the first OSS. (yes)
Second OSS Telephone Number	Second telephone number that the switch dials to report alarms; must be obtained from the National Customer Support Center (NCSC) or the TSC. (# and * are not allowed in the telephone number.)
Abbrev Alarm Report	Enables the Abbreviated Alarm Report feature for the second OSS. (no)

4 Maintenance Commands for DEFINITY ONE  
*display system-parameters maintenance*

4-64

Alarm Origination to  
OSS Numbers

One of four options for alarm origination (neither):

- If *both*, all Major and Minor alarms result in an automatic call to both OSS telephone numbers. Both OSS telephone numbers must be administered.
- If *first-only*, all Major and Minor alarms result in an automatic call to the first OSS number only. The switch does not call the second OSS telephone number even if the number is administered. The first OSS telephone number must be administered
- If *neither*, alarm origination does not take place. Warning alarms are not reported to either numbers.
- If *second-as-backup*, all Major and Minor alarms result in an automatic call to the first OSS telephone number. If calling the first OSS telephone number fails four attempts, the switch starts to call the second OSS telephone number as a backup until calling the first OSS telephone number becomes successful. Both OSS telephone numbers must be administered.

Before Release 1.0, the name of this field is *Alarm Origination Activated*. If Alarm Origination is deactivated, both Cleared Alarm Notification and Restart Notification are disabled, even though they may still be activated in the administration.

Cleared Alarm  
Notification

Enables the switch to originate a call to the OSS and send an alarm resolution message whenever all previously-reported Major and Minor alarms are resolved. Alarm Origination must be activated in order for Cleared Alarm Notification to work. (no)

Restart Notification

Enables the switch to originate a call to the OSS and report any system restarts caused by problems with the switch.

Suspension Threshold

The threshold for suspending Cleared Alarm Notification (1-15). Some problems may cause alarms to be generated and then resolved repeatedly. To detect these problems (by not sending additional Cleared Alarm notifications to indicate a problem-free system), the switch suspends Cleared Alarm Notification when it has reported this administrable number of Cleared Alarm notifications in a 24-hour period. A suspended Cleared Alarm Notification is only enabled again with a successfully completed "logoff" command, a system reset, or when the threshold is changed. This field is irrelevant if Cleared Alarm Notification or Alarm Origination is disabled.

Test Remote Access  
Port

Specifies whether testing of the remote access port on the SYSAM circuit pack is enabled. This field should read *yes* whenever there is an INADS line connected to the switch and there is a maintenance contract in effect so that alarm origination capability is maintained.

#### 4 Maintenance Commands for DEFINITY ONE

*display system-parameters maintenance*

4-65

**CPE Alarm Activation Level** Indicates the minimum level (Major, Minor or Warning) at which the Customer-Provided Equipment (CPE) alarm is activated. If the level is *none*, the CPE does is not activated for any alarm. (*none*)

**NOTE:**

The CPE alarm is always activated when the switch goes into Emergency Transfer, regardless of the CPE Alarm Activation Level setting.

**Customer Access to INADS Port** Provides the capability to prohibit access to system administration and maintenance interface, via the INADS port when using customer login ID's. This field can only be activated by Lucent services through system-parameters maintenance administration. (*no*)

**Repeat Dial Interval (MMS)** Indicates the number of minutes that the system must wait before attempting another call origination to an OSS. This timer is triggered by the lack of a far-end acknowledgment. (*7*)

### Scheduled maintenance

A series of maintenance tests and operations runs automatically every day according to the schedule and settings specified in the following fields.

**Start Time** The hour and minute (24-hour notation) at which daily scheduled maintenance begins. (*22:00*)

**Stop Time** Time (hour and minute) when scheduled daily maintenance stops. If any daily maintenance operations are not completed by this time, the system notes where in the sequence it stopped and perform those operations during the next scheduled daily maintenance.

**Daily Maintenance** This display-only field simply represents the series of tests that are always run by maintenance software as part of daily maintenance.

**Save Translation** This field indicates on which days translation data in memory will automatically be saved to the Mass Storage System disk and/or tape devices during scheduled maintenance. The save operation is first made to disk, followed by a disk backup to tape. On systems with duplicated SPEs, translation data is saved on both SPEs. Valid entries are **daily**, days of the week, or **no**. "No" specifies that no automatic saves are to be executed. (*daily*)

**Control Channel Interchange** Each port network has a pair of TDM busses called A and B, each of which has a set of time slots dedicated to use by the control channel. At any one time, the control channel in each PN is carried on only one of the two busses. This field indicates on which days the control channel in each port network will be switched from one of the paired TDM busses to the other. Valid entries are **daily**, days of the week, or **no**. "No" specifies that no interchange be executed. (*no*)

#### 4 Maintenance Commands for DEFINITY ONE

*display system-parameters maintenance*

4-66

EXP-LINK Interchange	This field indicates whether or not the expansion links between port-networks are interchanged as part of scheduled maintenance. The value "daily" means that EXP-LINK interchange occurs automatically everyday. The value "no" means that EXP-LINK interchange is not done automatically as part of scheduled maintenance. Values represented by the days of the week mean that EXP-LINK interchange occurs automatically on the specified day only. Since EXP-LINK interchange only applies to duplicated systems, simplex systems do not display this field. (no)
Minimum Threshold for TTRs	When the number of touch tone receivers (TTRs) in service falls below this number (4 to 200), a WARNING alarm is raised against TTR-LEV. These are also known as dual-tone multifrequency receivers (DTMRs). There are 8 TTRs on the TN795. To alarm the first occurrence of a TTR being taken out of service, set this field to the total number of TTRs in the switch.
Minimum Threshold for CPTRs	When the number of call progress tone receivers in service falls below this number (2 to 100), a WARNING alarm is raised against TTR-LEV. These are also known as general purpose tone detectors (GPTDs). There are 8 CPTRs on the TN795. To alarm the first occurrence of a CPTR being taken out of service, set this field to the total number of CPTRs in the switch.
Minimum Threshold for Call Classifier Ports	When the number of call classifier ports (CLSFY-PTs) in service falls below this number, a WARNING alarm is raised against TTR-LEV. Valid entries are 1 to 200. There are 8 ports on the TN795 circuit pack. To alarm the first occurrence of a CLSFY-PT being taken out of service, set this field to the total number of CLSFY-PTs.
Test Type 100, Test Type 102, Test Type 105	An extension assigned to receive tie-trunk calls from other switches with test line origination capability. The system responds by sending a sequence of test tones. Test Type 100 tests far-end to near-end loss and C-message by sending: <ul style="list-style-type: none"><li>■ 5.5 seconds of 1004 Hz tone at 0dB</li><li>■ Quiet until disconnect; disconnect is forced after one minute</li></ul>
ISDN-PRI Test Call Extension	The extension used by a far-end ISDN node to place a call to the system to test the ISDN-PRI trunks between the far-end and the system.
ISDN-BRI Service SPID	This field shows whether or not the link is associated with the Service SPID. If the link is associated with the Service SPID, this field contains a "yes" and the extension field is blank; otherwise, this field is blank. Service SPID is a feature used by the system technician to check building wiring between the switch and the BRI endpoint.

4 Maintenance Commands for DEFINITY ONE  
*display system-parameters maintenance*

4-67

DSO Loop-Around  
Test Call  
Extension

Extension number for the test call. This test extension number is used to establish a loop-around connection on the selected trunk.

The DSO Loop-Around Test Call feature is used primarily for testing DSO channels associated with non-ISDN-PRI trunks. The loop-around is activated by dialing the test extension number. Multiple DSO Loop-Around connections can be set up by placing multiple calls to the loop-around extension.

The DSO Loop Around feature provides a loop around connection for incoming non-ISDN DS1 trunk data calls. This feature is similar to the far-end loop around connection provided for the ISDN Test Call feature. This DSO loop around is provided primarily to allow a network service provider to perform facility testing at the DSO level before video teleconferencing terminals are installed at the PBX.

The feature is activated on a call-by-call basis by dialing a test call extension specified on the second page of the System Parameters Maintenance form. No special hardware is required. When the test call extension is received by the PBX, a non-inverting, 64 kbps connection is set up on the PBX's Time Division Multiplexed bus. More than one loop around call can be active at the same time.

For calls routed over the public network using the ACCUNET Switched Digital Service (SDS) or Software Defined Data Network (SDDN), the data transmission rate is 56 Kbps, since robbed bit signaling is used. For calls established over a private network using common channel signaling, the full 64 kbps data rate is available.

When the incoming trunk group is used only for data calls (SDS), the Communications Type on the associated Trunk Group form should be set to "data." When the incoming trunk group is used for robbed bit alternate voice and/or data (SDN/SDDN), the Communications Type on the Trunk Group form should be set to **rbavd** (robbed bit alternate voice data). For private network trunks using common channel signaling, the Communications Type on the associated Trunk Group form can be set to "avd."

**4** Maintenance Commands for DEFINITY ONE  
*display system-parameters maintenance*

4-68

## Loss Plan

Use only when extra loss is required to maintain quality of transmission on conference calls. Leave this field blank if no extra loss is required. If extra loss is required, enter digits as shown below.

No. of parties to be conferenced	Enter digit
3	2
4	3
5	4
6	5
7	6

SPE Optional  
Boards:

These fields indicate whether a Disk circuit pack is present in the system, and which Packet Interface slots are administered. If a Packet Interface circuit pack is physically present, the corresponding Packet Interface field is set to **y** when the system boots, and no change to that field is allowed. If the system is equipped with duplicated SPEs, a Packet Interface field is set to **y** when either SPE carrier contains a Packet Interface circuit pack in the corresponding position. If a Packet Interface circuit pack is not present, then the value for the Packet Interface field is read from translation data stored on disk or tape. If the field is set to **n**, a Packet Interface circuit pack may be administered by changing the corresponding Packet Interface field to **y**.

## display time

---

This command displays the system time but does not allow for any changes to the system time.

## Output

---

The following example shows the output for the **display time** command.

```
display time
DATE AND TIME
DATE
          Day of the Week: Tuesday      Month: October
          Day of the Month: 19          Year: 1999

TIME
Hour: 8   Minute: 5   Second: 51

WARNING: Changing the date or time will impact BCMS, CDR and MEASUREMENTS

list configuration ds1
SYSTEM CONFIGURATION - DS1 Circuit Packs
Location  Code   Vintage   Signaling      Name                CSU MOD
01A05    TN767E  conflict  isdn-pri       albania-a05        none
```

## Field descriptions

Day of the Week	The day of the week that the system has stored.
Day of the Month	The numerical day of the month.
Month	The month of the year stored by the system.
Year	The current year stored by the system.
Hour	The hour of the current day.
Minute	The number of minutes into the hour.
Second	The number of seconds into the minute stored by the system.

## **enable administered-connection**

This command restarts scheduled and periodic maintenance for a single or all administered connections and can be used to track the maintenance processing of administered connections without interference from other maintenance processing. This command also restarts the processing of in-line errors for all or the selected administered connection.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>enable administered-connection</b>	<i>ac number</i>	The number of the administered connection	init inads	none	none
	<i>all</i>	All administered connections are enabled.  Examples: <b>enable administered-connection 128</b> <b>enable administered-connection all</b>	craft cust rcust mis		

## **enable mst**

Enables the message trace that is controlled according to the parameters created with the **change mst** command. If executed while the trace is enabled, the command has no effect and returns a screen message indicating that the command was successful.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>enable mst</b>			init inads	none	none

## **enable suspend-alm-orig**

This command enables Suspend Alarm Origination for a board (including all ports and endpoints on the board) or for a port (including all endpoints on the port) for both on- and off-board alarms or for off-board alarms only. Many control circuit packs do not have a board location, so this command cannot support all circuit packs. Each enable command becomes a new entry or replaces an existing entry in the Suspend Alarm Origination table. A new entry that matches both the physical location and off-only, on-, and off-board specifications of an active entry replaces the active entry in the Suspend Alarm Origination table.

On the command line, specify a time-out duration of 1 - 72 hours. The **off-board-only** is optional; if the keyword is not specified, the entry suspends Alarm Origination for both on-and off-board alarms.

4 Maintenance Commands for DEFINITY ONE  
*enable synchronization-switch*

4-71

This command may be particularly useful for:

- Improved control over customer requests. For example, to suspend off-board DS1 alarms temporarily for customers that periodically disconnect DS1 trunks for testing or other business-related purposes.
- Improved control over external (non-Lucent) problems such as suspending off-board DS1 alarms before a customer resolves facility problems (for example, a T1 trunk that has developed an off-board condition).
- Improved control over internal (Lucent) problems that cannot be resolved immediately. For example, the command can be used to suspend Alarm Origination for a bad circuit pack detected late Friday night and dispatch personnel cannot respond until Monday.



**NOTE:**

Also see other Suspend Alarm Origination related commands, including **disable suspend-alm-orig** and **list suspend-alm-orig**.

Action/ Object	Qualifiers	Qualifier description	Permissions	Defaults	Feature interactions
<b>enable suspend-alm-orig</b>	<b>board/port location</b>  <b>off-board-only</b>  <b>expires-in-hrs</b>	Physical location of the hardware optional; if not specified, both on-and off-board alarms suspended  No. of hours (1-72)  Examples: <b>enable suspend-alm-orig 1B03 expires-in-hrs 3</b> <b>enable suspend-alm-orig 1B0701 expires-in-hrs 72</b> <b>enable suspend-alm-orig 1B07 off-board-only expires-in-hrs 24</b>	init inads craft cust rcust	Both on- and off-board alarms if the <b>off-board-only</b> keyword is not specified	none

## enable synchronization-switch

This command re-enables automatic clock switching or returns the maintenance subsystem back to the normal state. The synchronization subsystem consists of the TDM bus clock, DS1 trunk board, and SPE-resident maintenance and administration software and provides error free digital communication between the switch and other PBXs, COs, or customer-premise equipment (CPE).

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
enable synchronization-switch			init inads craft	none	none

## **enable test-number**

This command enables a previously disabled test number. At the next request by maintenance or the technician, this test number will run.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>enable test-number</b>	<b>number</b>	The specific test number to re-enable  Example: <b>enable test-number 102</b>	init inads craft	none	The <b>display disabled-tests</b> command gives a list of all disabled tests.

## **list configuration**

This command generates a report listing the group specified, the type, code, suffix, and vintage of the requested circuit packs as installed in the switch, and all ports assigned to the circuit pack.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>list configuration</b>	<b>hardware-group</b>	See Hardware Groups below.  Examples: <b>list configuration carrier 1a</b> <b>list configuration port-network 1</b>	init inads craft cust rcust	none	none



**NOTE:**

The **list configuration software-version** command is discussed separately under its own heading.

### **Hardware groups**

Enter one of the following hardware groups:

- all** Displays all circuit packs administered and/or physically inserted in all cabinets.
- board PCSS** Displays all assigned ports on the circuit pack specified by cabinet, carrier, and slot.
- carrier *n*** Displays all circuit packs and assigned ports on the carrier specified by *n*, where *n* is either A or B.
- control** Displays the control complex.
- ds1** Displays all the DS1 (TN722, TN767, and TN464) port circuit packs administered and/or physically inserted.

**port-network pn#** Displays all circuit packs located in a specified port network. (**List cabinet** gives the port network number(s) associated with a particular cabinet.) Circuit packs on switch node carriers are not displayed when the port-network qualifier is entered. To display switch node circuit packs, use the **all**, **carrier** or **board** qualifiers.



**NOTE:**

DEFINITY ONE has only one port network.

**stations** Displays all circuit packs that can be assigned stations, including DS1 circuit packs for remote stations.

**trunks** Displays all circuit packs that can be used for administering trunks.

## Output

The following display shows the output from the **list configuration all** command.

```

list configuration all                                     Page 1
SYSTEM CONFIGURATION
Board
Number  Board Type          Code  Vintage  Assigned Ports
u=unassigned t=tti p=psa
01A01  RESERVED-PROCESSOR      TN795  000003
01A02  PROCESSOR-TONE/CLK      TN795  000003  x x x x x x x x
mj u
01A04  BRI LINE                TN556C 000002  01 u 02 u 03 u 04 u
05 u 06 u 07 u 08 u
09 u 10 u 11 u 12 u
01A05  DS1 INTERFACE          TN767E conflict  01 02 03 04 05 06 07 08
                                09 10 11 12 13 14 15 16
                                17 18 19 20 21 22 23 24
                                u u u u u u u u
01A06  CALL CLASSIFIER        TN744D 000001  01 02 03 04 05 06 07 08
01A08  DIGITAL LINE           TN2224 000005  01 02 03 u u u u u
                                u u u u u u u u
                                u u u u u u u u

press CANCEL to quit -- press NEXT PAGE to continue

```

## Field descriptions

Port	The port number of the circuit pack
Board Type	The functional name of the circuit pack
Code	The TN or UN code and suffix of the circuit packs
Suffix	
Vintage	The vintage number of the circuit pack
01 through 32	Assigned port numbers

The following display shows output from the **list configuration ds1** command.

```
list configuration ds1

                SYSTEM CONFIGURATION - DS1 Circuit Packs

Location   Code   Vintage   Signaling   Name           CSU MOD
-----
01A05     TN464F  000002   isdn-pri   120A1
01A06     TN464D  000002   isdn-pri   n/a
```

## Field descriptions

Signaling	This field is displayed only when <b>list configuration ds1</b> is entered. The contents of the field are the same as the signaling mode administered for the ds1 circuit pack or <i>none</i> if the circuit pack is not administered.
Name	This field is displayed only when <b>list configuration ds1</b> is entered. The contents of the field are the same as the signaling mode administered for the ds1 circuit pack or <i>none</i> if the circuit pack is not administered.
CSU MOD	This field is displayed only when <b>list configuration ds1</b> option is selected. The field contains the identification number of the Integrated CSU module present on the DS1 circuit pack (TN767E or later / TN464F or later) or <i>none</i> . If the circuit pack is a TN464E or TN767D, <i>unknown</i> displays. If the circuit pack is a TN464D or TN767C or earlier suffix DS1 board, then <i>n/a</i> displays.

## list config software-version

This command displays

- Software version numbers and compatibility indexes of the software load modules stored in system memory (RAM) and on the Mass Storage System devices (tape).
- The dates and times when translation and announcement data were last saved to the MSS.
- Information about any software update files that have been applied to the system. See “Software Upgrade” in [Chapter 2, “Maintenance Procedures for DEFINITY ONE Compact Modular Cabinets”](#) for an explanation of software versions and compatibility indexes.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
list configuration software-version	<i>memory-resident</i>	Data for the active SPE, RAM-resident files only.	init inads craft	none	none

## Output

If the memory card contains a core dump file, fields for tape or memory card data display `coredump`. When a core dump is present, all other files on the device are marked invalid.

If the memory card cannot be read at the time the command is entered, the relevant fields display `no tape` or `memory card`. (This does not indicate that the system does not recognize the presence of the device.)

The following display shows the output from the **list configuration software-version** command.

```
list configuration software-version

                SOFTWARE VERSIONS
                SPE_A                SEP_B

SOFTWARE VERSION
Memory Resident: G3V7c.00.0.432.0

TRANSLATION DATE
Memory Resident: 1:01 pm TUE JUN 1, 1999
Disk Resident: 1:01 pm TUE JUN 1, 1999
```

## Field descriptions

<b>Software version</b>	Displays information related to the current software-load module stored in memory and in the MSS.
Memory Resident	Version number of the RAM-resident load module.
PKT-CTRL FW VERSION	displays version number of the Packet Control firmware.
<b>Translation date</b>	Displays information related to the translation files as stored in memory and the MSS.
Memory Resident	Date and time when translation data was last read from the MSS into memory. This is stored in SPE memory and is not modified by changes to translation data. A <b>save translation</b> command updates this date. If <code>Date invalid</code> is displayed, the timestamp does not contain the expected information.

## list disabled-mos

This command displays all the MOs that have been maintenance disabled in the system.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>list disabled-mos</b>			init inads	none	none

## Output

The following example shows the output from the **list disabled-MOs** command.

```
list disabled-MOs

      DISABLED MAINTENANCE OBJECT INFORMATION

Maintenance Name  Location      Status
ALL              Enabled
DIG-LINE         01A1203     Disabled

Command successfully completed
```

## Field descriptions

Maintenance Name	The type of maintenance object (or group of maintenance objects) that have been disabled. All is also valid.
Location	The physical location of the disabled maintenance object that has been disabled. This field displays blanks if all maintenance objects have been disabled ( <b>disable all</b> ) or all MOs of a specific type have been disabled ( <b>disable MO-all</b> ).
Status	Whether the maintenance object or group of maintenance objects is Enabled or Disabled.

## list history

---

This command generates a log listing of the most recently completed “data affecting” administration and maintenance commands. Data commands are those administration and maintenance commands that change the data state associated with any object and qualifier in the system. Administration data commands affect translation data, while maintenance data commands affect state information. For example, **change station** is a data command, whereas **display station** is not.

All information in the transaction log is saved as translation data when the **save translation** command is performed (LIFO order).

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>list history</b>			init inads craft cust browse nms	none	See below

## Feature interactions

---

The translation log is written to the hard disk as translation data when the **save translation** command is executed. The translation data is time stamped when saved. This time stamp is noted when translation is loaded from the memory card and included in all recent change history reports.

When a user requests a recent change history report, there could be other users concurrently issuing data commands and altering the contents of the transaction log. Therefore, if the user pages the entire way through the report, the oldest entries in the transaction log (maximum 250 commands) may have been overwritten by data commands issued by these other users. Should this occur, the final entries of the report show the data commands issued by the other users since the recent change history report was originally requested.

## Output

```
list history Page 7

HISTORY
Date of Loaded Translation: 10:34am Fri Oct 15, 1999
  Date  Time Port      Login  Actn  Object      Qualifier

10/13 15:52 MGR1      init   logn
10/13 15:19 NET        init   logn
10/12 16:15 NET        init   cha   abbreviated- group 1
10/12 16:10 NET        init   logn
10/06 10:14 NET        init   cha   station     40001
10/06 10:13 NET        init   add   abbreviated- group next
10/06 10:12 NET        init   logn
 9/10 15:33 MGR1      init   cha   coverage    path 1
 9/10 15:32 MGR1      init   logn
 9/10  7:09 NET        init   enab  test-number 1357
 9/10  7:08 NET        init   test  board       1a12
 9/10  7:06 NET        init   logn
```

## Field descriptions

**Date** The date the command was issued in (mm/dd format)

**Time** The time the command was issued (in hh:mm format)

**Port** The port type to which the user was connected when the command was issued. For release 1 of DEFINITY ONE, this entry is not used. This field may show MGR1, NET, or INADS but those port types are incorrect. This will be fixed in a future release.

Port number	Board	List history display
0 - 30	EPN Maintenance Board Port	MAINT
31 - 40	System Access Port	SYS-PORT
41	Maintenance Board Port	SYSAM-LCL
42	Remote Maintenance Board Port	SYSAM-RMT

**Login** User login

**Actn** The first word (verb) of the command, specifying the operation to be performed. This field is truncated after four characters to allow enough space for objects and qualifiers. Four characters is enough to uniquely identify each action.

**Object** The qualifier, or second phrase of the command, specifying the particular thing being acted upon by the command. Twelve characters is enough to uniquely identify each object.



**NOTE:**

Where the object is multiple words in length, only the first word will be displayed in the object field. All succeeding words will be treated as qualifiers. This field is truncated after twelve characters to allow enough space for qualifiers.

**Qualifier** One or more qualifiers describing the characteristics of the action/object pair. This field is truncated after 31 characters to keep information for a command on a single line.

## list isdn-testcall

This command displays the ISDN-PRI trunks in use for ISDN-PRI test calls. This command is useful to determine which trunk is in use for an outgoing ISDN-PRI test call.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>list isdn-testcall</b>		Report sent to printer.	init inads craft	none	none

## Output

```
list isdnpri-testcall

                ISDN-PRI TESTCALLS
B-Channel  Start Time   Duration  M/T Port
078/001    25/12:36      120      1B1102
```

Command successfully completed

## Field descriptions

- B-Channel** Trunk in use for the ISDN-PRI test call (trunk group number/ member number).
- Start Time** Time the test call started (dd/hh:mm format).
- Duration** Expected duration of the test call.
- M/T Port** The Maintenance/Test circuit pack's digital port address (in cabinet/carrier/slot/circuit format) in use for the outgoing asynchronous ISDN-PRI test call.

## list marked-ports

This command lists all the ports that have been marked unusable with the **mark port** command (maximum of fifteen marked ports per page).

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>list marked-ports</b>			init inads craft cust rcust bcms browse	none	none

## Output

```
list marked-ports

          MARKED-PORT INFORMATION
Port      Board-Type
1C0101    DIG-BD
1C0601
1C0702    DIG-BD

Command successfully completed
```

## Field descriptions

- Port** The port address (cabinet-carrier-slot-circuit) of the marked port.
- Board-Type** The type of circuit pack containing the marked port. If this circuit pack information is no longer available because the circuit pack was removed after the port was marked, the **Board-Type** field is blank.

## list measurements

This command lists performance measurements of a DS-1 link indicating the quality of the DS-1 physical interface between the system and a far end system. The **ds1 summary** option provides a summary report while the **ds1 log** option provides a detailed report.



**NOTE:**

The **list measurements** command has many more options than documented here. Only those options dealing with DS1 board are documented below.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>list measurements</b>	<b>log</b>	Detailed report generated	init	none	none
	<b>summary</b>	Summary report generated	inads craft cust rcust browse nms bcms		
	<b>ds1_location</b>	The physical location of a DS1 circuit pack entered as cabinet-carrier-slot.  Examples: <b>list measurements ds1 log 2a18</b> <b>list measurements ds1 summary</b>			

## Output

```
list measurements ds1 summary 2a19                               SPE A
Switch Name:                               Date: 1:25 pm THU APR 16, 1992

    DS-1 Link Performance Measurements Summary Report

Counted Since: 1:20 pm THU APR 16, 1992
Number of Seconds Elapsed Into Current 15-min Interval: 323
Total of Valid 15-min Intervals in Past 24-hr Period: 0
Total of Current
Worst_15-Min_Interval 24-hr 15-Min Interval
Category      Date  Time  Count  Count  Count
Errored Seconds 4/16 13:20 0      0      4
Bursty Err Secs 4/16 13:20 0      0      4
Severely Err Secs 4/16 13:20 0      0      0
Failed Seconds  4/16 13:20 0      0      0

Command successfully completed
```

**Field descriptions (list measurements  
ds1-summary)**

Counted Since:	The start time and date when the associated measurement counters were cleared or the DS1 circuit pack was administered.
Number of Seconds Elapsed Into Current 15-min Interval:	The number of seconds from the beginning of the current 15-minute interval (0 - 900).
Total of Valid 15-min Intervals in Past 24-hr Period:	The total number of 15-minute intervals in the past 24-hour period that contain valid data (0 - 96).
Category	The four categories correspond to four measurement error counters: <ul style="list-style-type: none"><li>■ <b>Errored Seconds:</b> the value of the errored seconds counter for the specified 15-minute interval (0 - 900 or N/A if data for the 15-minute interval is invalid).</li><li>■ <b>Bursty Err Secs:</b> the value of the bursty errored seconds counter for the specified 15-minute interval (0 - 900 or N/A if data for the 15-minute interval is invalid).</li><li>■ <b>Severely Err Secs:</b> the value of the severely errored seconds counter for the specified 15-minute interval(0 - 900 or N/A if data for the 15-minute interval is invalid).</li><li>■ <b>Failed Seconds:</b> the value of the failed seconds counter for the specified 15-minute interval (0 - 900 or N/A if data for the 15-minute interval is invalid).</li></ul>
Worst_15-Min_ Interval	The date(Date), end time(Time), and error count (Count; from 0 to 900 in increments of four) of the 15-minute interval in the previous 24-hour period that contains the maximum value for each of the four error categories.
Total of 24-Hour Count	The sum of all valid 15-minute counts for the previous 24-hour period for each of the four error categories (0 - 65535).
Current 15-Minute Interval	The error count for the current (incomplete) 15-minute interval for each of the four error categories (0 - 900 or N/A if data for the 15-minute interval is invalid).

```
list measurements ds1 log 2a19                               SPE A

Switch Name:                               Date: 1:26 pm  THU APR 16, 1992

      DS-1 Link Performance Measurements Detailed Log Report
Counted Since: 1:20 pm  THU APR 16, 1992
      ERRORED BURSTY      SEVERELY      FAILED      VALID
DATE  TIME  SECOND  ERR SECS  ERR SECS  SECONDS  INTERVAL
4/16  13:05   0     0      0         0         Y
4/16  13:20   0     0      0         0         Y

Command successfully completed
```

### Field descriptions (list measurements ds1 log)

**Counted Since:** The start time and date when the associated measurement counters were cleared or the DS1 circuit pack was administered.

**DATE** The date of the 15-minute interval.

**TIME** The time of the 15-minute interval.

**ERRORED SECONDS** The value of the errored seconds counter for the specified 15-minute interval (0 - 900 or N/A if data for the 15-minute interval is invalid).

**BURSTY ERR SECS** The value of the bursty errored seconds counter for the specified 15-minute interval (0 - 900 or N/A if data for the 15-minute interval is invalid).

**SEVERELY ERR SECS** The value of the severely errored seconds counter for the specified 15-minute interval (0 - 900 or N/A if data for the 15-minute interval is invalid).

**FAILED SECONDS** The value of the failed seconds counter for the specified 15-minute interval (0 - 900 or N/A if data for the 15-minute interval is invalid).

**VALID INTERVAL** This field indicates whether the data for the specified 15-minute interval is valid. Data is considered valid when a count for that 15-minute interval. If the field has a value of **y**, the data for the four error categories is valid; otherwise, the data is invalid.

Data is considered valid when a count for that 15-minute interval is retrieved and none of the following invalid conditions occur:

- If a system warm start or a system cold start occurred during the interval
- If the DS1 circuit pack was not inserted during the interval
- If the system time was changed during the interval
- If the system was too busy to respond to a poll request for the interval

## **list suspend-alm-orig**

This command lists active entries in the Suspend Alarm Origination table. Even though this command only lists active entries, an entry that expires during the list process still appears in the output. If the Suspend Alarm Origination table is empty, the output contain only the title and field headings.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>list suspend-alm-orig</b>			init inads craft	none	none

## **Output**

```
list suspend-alm-orig
```

```
          Suspend Alarm Origination Entries
```

```
Physical   Board      Expires At
01C03      off-only    06/11/15:06
01E0407    on-and-off  06/11/17:26
01E0406    on-and-off  06/12/45:34
```

## list sys-link

This command displays all of the system links, including the location, link type and channel number, link state, current path status, faulted path status, and last recorded fault, if any. See [“SYS-LINK \(System Links\)” on page 5-1070](#) for details.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>list sys-link</b>			init inads craft	none	none

## Output

The following examples shows the output from the **list sys-link** command.

```
list sys-link                                     Page 1  SPE A
                                         SYSTEM LINKS INFORMATION
Location  Link Type/  State  Current  Faulted  Last Fault
          Channel   Path   Path     Path     Recorded
01A0516  PRI           up     present  present  12/30/1996 14:18
press CANCEL to quit -- press NEXT PAGE to continue
```

## Field descriptions

- Location** Physical location of the port associated with the system link (cabinet-carrier-slot-circuit)
- Link Type/Channel** Type of system-link and the processor channel number of the link (if there is one): for TN795, link type is PRI (PRI).
- State** System link state: up or down
- Current Path** Status of the current path: none if the link is down; present if the current path is valid
- Faulted Path** Specifies the faulted path status: present if the link has been faulted at least once, none if the link has never gone down, and default if the default faulted path is being used
- Last Fault Recorded** Date and time of the most recent fault

## list testcalls

This command generates an Automatic Transmission Measurement System (ATMS) report. The ATMS allows the voice and data trunk facilities to be measured for satisfactory transmission performance. The performance of the trunks is evaluated according to measurements produced by a series of analog tests and are compared against user-defined threshold values. The purpose of the report is to provide measurement data to help determine the quality of trunk lines. The measurement report contains data on trunk signal loss, noise, singing return loss, and echo return loss.

The measurements are produced by a set of analog trunk tests. The tests are initiated by a maintenance demand test or by a set of scheduled tests. The largest portion of these measurements are generated through scheduled testing during system quiet hours (hours where the traffic volume is low). Each trunk test performed by the system stores the results in a database. The trunk measurements in this database reflect the state of each trunk at the time of its last test.

Action/Object	Qualifiers/Options	Qualifier/Option description
list testcalls	<i>detail</i>	Detailed measurement report displayed
	<i>summary</i>	Summary measurement report displayed
	grp group number	Measurements for a specific trunk group displayed. When used with the <i>to-grp</i> option, this option is the starting trunk group in a range of user-specified trunk groups.
	to-grp group number	Measurements for all trunk groups from 1 to the specified "to-grp" trunk group are displayed. When used with the <i>grp</i> option, this option is the ending trunk group in a range of user-specified trunk groups.
	mem member number	Measurements for a specific trunk group member displayed. When used with the <i>to-mem</i> option, this option is the starting trunk group member in a range of user-specified trunk group members.
	to-mem member number	Measurements for all trunk group members from 1 to the specified "to-mem" trunk group member displayed. When used with the <i>mem</i> option, this option is the ending trunk group member in a range of user-specified trunk group members.
	port location	Measurements for a specific trunk circuit (port) displayed
	result result identifier	This option is used to filter out all measurement results that do not match the user-specified result, that is, only measurement results that match the user specified result are displayed. Examples of results are pass, marg, fail, etc.
	not-result result identifier	This option is used to filter out all measurement results that do match the user-specified result, that is, only measurement results that do not match the user specified result are displayed. Examples of results are pass, marg, fail, etc.
	count count number	This option is used to specify (limit) the number of records displayed.

## Examples

```
list testcalls detail
list testcalls detail grp 78
list testcalls detail grp 78 to-grp 80
list testcalls detail grp 78 to-grp 80 mem 1 not-result pass
list testcalls detail grp 78 to-grp 80 mem 1 to-mem 5
list testcalls detail grp 78 to-grp 80 mem 1 to-mem 5 count 3 result pass
list testcalls detail mem 1 count 3 result pass
list testcalls detail to-grp 78 to-mem 4 count 3 result pass
list testcalls detail to-mem 3 result pass
list testcalls detail port 1c1504t
list testcalls summary
list testcalls summary grp 78
list testcalls summary grp 78 count 5
list testcalls summary grp 78 to-grp 80
list testcalls summary grp 78 to-grp 80 count 3
list testcalls summary to-grp 78
```

## Output

The following example is of the output for the **list testcalls detail grp 80** command.

```
list testcalls detail grp 80                               Page 1   SPE A

                ATMS MEASUREMENT REPORT

Group: 80   Type: co   Vendor:                               TTL Type: 105-w-r1

THRESHOLD VALUES                Loss dev at

                1004Hz-loss   404Hz 2804Hz C-msg C-ntch SRL SRL
                Min   Max   -   +   -   +   Noise Noise LO HI ERL
Marginal      -2   21   9   9   9   9   55   74   0   0   0
Unacceptable  -2   21   9   9   9   9   55   74   0   0   0

Trk Test  Test  Test -16dBm 0dBm
Mem Date  Time  Rslt  NE FE NE FE  NE FE NE FE  NE FE NE FE  NE FE NE FE
1
2
3
4
5
6
7
8
9

press CANCEL to quit -- press NEXT PAGE to continue
```

## Detail report field descriptions

Group	The trunk group number selected.
Type	The trunk group type.
Vendor	The vendor of this trunk group.
TTL Type	The kind of test line for this trunk group.
Threshold Values	The list of marginal and unacceptable threshold values defined on the trunk group form.  The following fields appear on the lower section of the form. Many of the column headings contain the abbreviations "FE" for far end and "NE" for near end. These abbreviations define which end took the measurements.
Trk Mem	The trunk member within the trunk group.
Test Date	The month and day this trunk was tested.
Test Time	The time of day this trunk was tested.
Tst Rslt	This field describes the results of the trunk transmission test.
1004Hz-loss Min	Far-to-near and near-to-far measurements of 1004-Hz loss from low-level tone.
1004Hz-loss Max	Far-to-near and near-to-far measurements of 1004-Hz loss at 0 dBm.
Loss dev at 404Hz	Transmission tests at low frequency. These tests measure a maximum positive and negative deviation of +9 and -9 dB from the 1004-Hz loss measurements.
Loss dev at 2804Hz	Transmission tests at high frequency. These tests measure a maximum positive and negative deviation of +9 and -9 dB from the 1004-Hz loss measurements.
C-msg Noise	Maximum noise interference (in dB <sub>BrnC</sub> : decibels above reference noise, which is B(EQ)10 sup -12E(EQ) watts) terminating on a voice terminal within the voice-band frequency range (500 to 2500 Hz) between 15 and 55 dB <sub>BrnC</sub> .
C-ntch Noise	Maximum signal-dependent noise interference on a line between 34 and 74 dB <sub>BrnC</sub> .
SRL-LO	Singing return loss from 0 to 40 dB between the sum of the circuit (repeater) gains and the sum of the circuit losses. SRL-LO occurs most often in the frequency range of 200 to 500 Hz.
SRL-HI	Singing return loss from 0 to 40 dB between the sum of the circuit (repeater) gains on a circuit and the sum of the circuit losses. SRL-HI occurs most often in the frequency range of 2500 to 3200 Hz.
ERL	Echo return loss from 0 to 40 dB between the level of signal strength transmitted and the level of signal strength reflected. ERL occurs most often in the frequency range of 500 to 2500 Hz.

The following example is the output from the **list testcalls summary grp 80** command.

```
list testcalls summary grp 80                                SPE A
                                     ATMS MEASUREMENT SUMMARY REPORT

Trk  Num   Last   Last   Trunks  Trunks  Trunks
Grp  Of    Test   Test   Passed  Failed  Failed
Num  Trks  Date   Time  Transm  Marginal Unaccept
     Trks  Date   Time  Test   Threshld Threshld
     Use  Test   Trunks

80   19                0       0       0       0    19    19

Command successfully completed
```

## Summary report field descriptions

Trk Grp Num	The trunk group number which is being summarized. Only outgoing or two-way analog trunks will be listed.
Num Of Trks	The total number of members per trunk group.
Last Test Date	The date of the oldest measurement in the trunk group.
Last Test Time	The time of the oldest measurement in the trunk group.
Trunks Passed Transm Test	The number of trunks that have passed the trunk transmission tests.
Trunks Failed Marginal Threshld	The number of trunks that failed a marginal threshold, but not an unacceptable threshold according to the threshold values defined on the trunk group form.
Trunks Failed Unaccept Threshld	This is taken from the unacceptable threshold administered on the Trunk group form.
Trks In-Use	The number of trunks that were in-use at the time of testing.
Trks Not Test	The number of trunks that were not tested due to error conditions.
Busied Out Trunks	The number of trunks that were busied out at the time. This could be due to hardware problems, incorrect threshold values, etc.

## **mark port**

This command marks faulty ports as defective to prevent their use in other administrative operations (for example, adding a data-module or station). Ports on any type of circuit pack may be marked except for installed circuit packs that are administered automatically (for example, Tone Detector, Tone Generator, Announcement, Speech Synthesizer, Call Classifier and Maintenance/Test circuit packs). If the port can be administered manually, and it is unassigned, the port is marked as faulty. The **clear port** command reactivates the port. The **list marked-ports command** displays marked ports in list format. All marked port information is saved as part of translations.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>mark port</b>	<b><i>location</i></b>	Location of the port to be marked: <b>PCSSpp</b> Examples: <b>mark port 1c0208</b> <b>mark port 2a1001</b>	init inads craft	none	none

## **monitor bcms**

This command displays output for agents and splits and summarizes the bcms condition. This on-line status report automatically updates every 30 seconds (or by pressing the UPDATE key) until the command is canceled by pressing the CANCEL key. Three display options are available: skill, split, and system.



**NOTE:**

This command is not available in DSA.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>monitor bcms</b>	<b><i>split</i></b> <b><i>split number</i></b> <b><i>system</i></b> <b><i>system number</i></b> <b><i>skill</i></b> <b><i>skill number</i></b>		init inads craft cust rcust bcms browse	none	none

## Qualifier description

split	Specifies that the command display status information for a specified split number (an ACD hunt group).
split number	The split's identity to the switch and BCMS; an ACD hunt group number (split number). This parameter is entered only when the "split" parameter is entered.
system	This specifies that the command display split queue status as well as cumulative split information for all the BCMS measured splits.
system number	ACD hunt group numbers (split numbers) separated by spaces and/or split number ranges separated by a hyphen (-).
skill	This specifies that the command display status information for a specified skill number.
skill number	The skill's identity to the switch and BCMS; an ACD hunt group number (skill number). This parameter is entered only when the "skill" parameter is entered.

## Output

The following examples shows the output from the **monitor bcms system** command.

```

monitor bcms system                               Page 1 of 1

                BCMS SYSTEM STATUS

                Date: 14:02 THU OCT 17 1991

                AVG                AVG                AVG
                CALLS  OLDEST  ANSW  AVAIL  #  ABAND  #  AVG  AFTER
SPLIT  WAIT  CALL  SPEED  AGENT  ABAND  TIME  ACD  TALK  CALL
Service  3  1:03  :45  0    3    :30  20  2:30  1:25
Sales    5  :33   :15  0   11   :45  36  1:32  :35
    
```

## Field descriptions

Date:	The current date and time which is updated every 30 seconds or when the UPDATE key is pressed.
SPLIT	The name of the split being reported, if no name is administered then the split extension is displayed in the form "EXTxxxxx". Splits are displayed in split number order. This field is translation data.

4 Maintenance Commands for DEFINITY ONE  
*monitor bcms*

4-92

CALLS WAIT	The number of calls currently waiting in this split's queue. If any of these calls are Direct Agent Calls, the field will be preceded by an asterisk. This field is real-time status data.
OLDEST CALL	The amount of time that the oldest call has waited in queue. This field is real-time status data.
AVG ANSW SPEED	The average speed of answer for this split during the current period. This includes time in queue and time ringing at the agent's voice terminal. Calls that intraflow (calls that overflow from one ACD split to another split) will not have queue time from previous splits included in the average. The calculation is Total Answer Time/Total Automatic Call Distribution (ACD) Calls. This field is measurement data and includes only those calls that have completed (terminated).
AVAIL AGENT	The number of agents in this split currently available to receive an Automatic Call Distribution (ACD) call from this split. This field is real-time status data.
# ABAND	The number of calls that have abandoned during the current period. This field is measurement data.
AVG ABAND TIME	The average time abandoned calls waited in queue before abandoning during the current period. The calculation is Total Abandon Time/Total Calls Abandoned. This field is measurement data and includes only those calls that have completed (terminated).
# ACD	The number of Automatic Call Distribution (ACD) calls handled by this split during the current period. This includes calls that intraflow into the split. This field is measurement data.
AVG TALK	The average talk time for Automatic Call Distribution (ACD) calls handled by this split during the current period. This does not include ring time at the agents' voice terminal. The calculation is Total ACD Talk Time/Number of ACD Calls. This field is measurement data and includes only those calls that have completed (terminated).
AVG AFTER CALL	The average After Call Work (ACW) time for Automatic Call Distribution (ACD) calls handled by this split during the current period. ACD calls with no ACW time are included in the average. Time spent on direct incoming or outgoing calls while in ACW will not be included in the average. The calculation is (Total ACW Time - Total ACW Incoming Time - Total ACW Outgoing Time)/Total ACD Calls. This field is measurement data and includes only those calls that have completed (terminated).

The following example shows the output from the **monitor bcms split 1** command.

```
monitor bcms split 1                               Page 1 of 1   SPE A

          BCMS SPLIT (AGENT) STATUS

Split: 1
Split Name: hunt group 1           Date: 9:02 TUE OCT 22 1991
Calls Waiting: 0
Oldest Call: 0:00
0=Staffed  0=Avail  0=ACD  0=ACW  0=AUX  0=Extn  0=OtherSplit
AGENT      EXT     STATE  TIME   ACD  EXTN IN  EXTN OUT
          CALLS  CALLS  CALLS
```

## Field descriptions

Split:	The number of the split requested. This field is translation data.
Split Name:	The name of the split requested. If no name exists the split extension is displayed in the form "EXT xxxxx". This field is translation data.
Date:	The current date and time which is updated every 30 seconds or when the UPDATE key is pressed.
Calls Waiting:	The number of calls currently waiting in this split's queue. If any of these calls are Direct Agent Calls, the field will be preceded by an asterisk. This field is real-time status data.
Oldest Call:	The time in minutes:seconds that the current oldest call has waited in this split's queue. This field is real-time status data.
Staffed	The number of agents currently logged into this split. This field is real-time status data.
Avail	The number of agents currently available to receive an Automatic Call Distribution (ACD) call in this split. Agents are in either the Auto-in or Manual-in work modes and are not currently on a call. If the agent is on another split's call or in After Call Work (ACW) for another split, this agent is not considered available and will not be recorded here. This field is real-time status data.
ACD	The number of agents in this split currently on an Automatic Call Distribution (ACD) call for this split. This includes ACD calls that are being handled by this split that arrive as coverage from another split. This field also includes outbound calls (Outgoing Call Manager) that are distributed through the ACD. Note that if an agent puts an ACD call on hold, but does not enter another state (for example, the agent does not enter the AVAIL state), the agent will still be seen as in the ACD state. This field is real-time status data.

4 Maintenance Commands for DEFINITY ONE  
*monitor bcms*

4-94

ACW	The number of agents in this split currently in After Call Work (ACW) for this split. This field is real-time status data.
AUX	The number of agents in this split currently in AUX work for this split. If an agent is on another split's call or in After Call Work (ACW) for another split, this agent is not considered in AUX work and will not be recorded here. This field is real-time status data.
Extn	The number of agents in this split currently on non-ACD (Automatic Call Distribution) calls, either incoming or outgoing directly to or from their extensions. If the agents are also in After Call Work (ACW) or AUX they will be recorded as Extn rather than ACW or AUX. This field is real-time status data.
Other Split	The number of agents in this split on another split's call or in After Call Work (ACW) for another split. Only used if agents belong to multiple splits. This field is real-time status data.
AGENT	The name of the agent associated with the extension. If no name exists this field will be left blank. This field is translation data.
EXT	The extension of the agent. This field is translation data.
STATE	The current state of the agent for this split. This possible states are Avail, ACD, ACW, AUX, Extn In, Extn Out, OtherSplit, and Unstaff. If an agent is staffed, the agent must also be in one of the above states. This field is real-time status data.
TIME	The clock time that the agent entered the current state in hours:minutes. This field is real-time status data.
ACD CALLS	The number of Automatic Call Distribution (ACD) calls (inbound and outbound), that the agent has completed for this split during the current period (half hour or hour). The maximum number of calls is 255, and if this maximum is exceeded, 255 is displayed. This field is measurement data.
EXTN IN CALLS	The number of non-ACD (Automatic Call Distribution) calls that the agent has received (incoming) and completed during the current period. The maximum number of calls is 255, and if this maximum is exceeded, 255 is displayed. This field is measurement data.
EXTN OUT CALLS	The number of non-ACD (Automatic Call Distribution) calls that the agent has made (outgoing) and completed during the current period. The maximum number of calls is 255, and if this maximum is exceeded, 255 is displayed. This field is measurement data.

## monitor health

This command displays the current system alarm summary, maintenance busy summary, user summary, critical system status, and cabinet status, that are updated every minute.



**NOTE:**

This command is not available in DSA.

After this command is terminates, users are logged off.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
monitor health			init inads craft cust nms browse	none	If standby SPE Emergency Transfer Select Switches change and handshakes are down, the displayed Emerg Trans field is incorrect until handshake reinitializes.  When the <b>monitor health</b> command terminates, users are logged off of the system.

## Output

The following example is a display of the **monitor system health** command.

```
monitor health

ALARM SUMMARY                                CABINET STATUS
  Major:    0
  Minor:    2
Warning:    0
                                Emerg Alarms
                                Cab Trans Mj Mn Wn PNC
                                1 auto-  0| 2|  2 up
                                2 n.a.   0| 0|  0 dn
                                3 n.a.   0| 0|  0 dn

BUSY-OUT SUMMARY
  Trunks:   0
  Stations: 0
  Others:   0

CRITICAL SYSTEM STATUS
Active SPE: A/auto
Duplicated? SPE:n
Time Source: primary
# Logins: 3

                                9:33 WED APR 28 1998
```

## Field descriptions

Major	The number of logged major alarms (0 – 200).
Minor	The number of logged minor alarms (0 – 200).
Warning	Number of warnings logged in the alarm file (0 – 200).
Trunks	Number of busied out maintenance trunks.
Stations	Number of busied out maintenance stations.
Others	Combined number of busied out maintenance objects excluding trunks and stations.
Static	Proportion of the CPU currently dedicated to high priority items. This percentage is rounded to the nearest integer, therefore 0 percent means that the occupancy is less than one half of a percent.
SM	Proportion of the CPU currently dedicated to system management or periodic and scheduled maintenance. If large amounts of periodic or scheduled maintenance testing performs, this occupancy percentage can be high without affecting service. This percentage is rounded to the nearest integer, therefore 0 percent means that the occupancy is less than one half of a percent.
CP	Proportion of the CPU currently dedicated to call processing. This occupancy has priority over SM and IDLE occupancy categories and takes processor time away from these occupancy categories, if needed. This percentage is rounded to the nearest integer, therefore 0 percent means that the occupancy is less than one half of a percent.
Idle	Proportion of the CPU currently available. This percentage is rounded to the nearest integer, therefore 0 percent means that the occupancy is less than one half of a percent.
Active SPE	Currently-active processor complex. When the active processor complex is locked on-line with lock switching on DUPINT, the “lock” option displays; otherwise, “auto” displays.
Duplicated?	Duplication status of the SPE (n).
SPE Power	Current power source for the processor complex. The normal state is “commercial”. When commercial power is unavailable, in-use battery backup is indicated with “backup”.

**4 Maintenance Commands for DEFINITY ONE**  
*monitor health*

4-97

Time Source	<p>Current timing source is displayed. The display values for this field vary according to timing sources selected. If the site administers the optional Stratum-3 hardware, "external" displays and "internal" displays when an internal source, such as a tone clock, is used. Primary and secondary timing sources must be administered when using the Stratum-4 option.</p> <p>"primary" = primary administered source is in use "secondary" = secondary administered source is in use.</p> <p>"local" = neither the primary or secondary sources are in use.</p>
# Logins	Number of current users.
Cab	Assigned cabinet number, ranging from 1 to the highest cabinet number in the system.
Emerg Trans	<p>Current setting of the emergency transfer switch for each cabinet. Five options are available: auto-on ("auto+" or "a+"), auto-off ("auto-" or "a-*", "on", "off", and "n.a."). If "auto+" or "auto-" option are enabled, emergency transfers automatically activate when cabinets fail ("+" indicates that emergency transfer is activated, while "-" indicates that emergency transfer is inactive). When "on" is displayed, emergency transfer automatically activates. The "off" option shows that cabinets cannot activate emergency transfers. In duplicated SPE systems, switch settings for both processors of the PPN (cabinet 1) display. In this case, "auto+" is abbreviated "a+", "auto-" is d "a-", and "off" is "of". "on" does not changed. If "n.a." displays, emergency transfer switch settings are not available.</p>
Mj	Number of major alarms associated with the cabinet. An asterisk fills the field when the number exceeds 99.
Mn	Number of minor alarms associated with the cabinet. An asterisk fills the field when the number exceeds 99.
Wn	Number of Wn associated with the cabinet. An asterisk fills the field when the number exceeds 99.
PNC	<p>Displays current Port Network Connectivity (PNC) status for each port network within a cabinet. When multiple port networks exist within a cabinet, a slash separates Carriers A, B, and C (listed first) from Carriers D and E (up/up). Availability of the Expansion Archangel Link (EAL) determines the PNC status of a port network. "Up" denotes EAL availability. When the EAL is not available, then "dn" (down) displays.</p>
Time of Day	Displays current time of day acquired from the system.

## monitor security-violations

This command displays information about failed attempts to access the system, including the time of the violation, the login entered, and the port accessed during the failed login attempt. The system logs trunk group numbers, members, and extensions for remote access violations. The system logs remote and local invalid access attempts with a total of 16 entries maintained for each access type. This online status report automatically updates every 30 seconds until the command is canceled by pressing the CANCEL key.



**NOTE:**

This command is not available in DSA.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>monitor security-violations</b>	<i>print</i>	Reports print to SAT-linked printers.	init inads craft cust rcust bcms browse	none	none

## Output

The following example shows the output from the **monitor security-violations** command.

```

monitor security-violations                               SPE A

                SECURITY VIOLATIONS STATUS

                Date:   9:12 MON DEC 30 1991

SYSTEM MANAGEMENT VIOLATIONS          REMOTE ACCESS VIOLATIONS

Date  Time  Login  Port  Ext  Date  Time  TG No.  Mbr  Ext
12/30 09:12 init  MGR1  Ext  12/30 12:42 80      1    1111
12/30 09:12 init  MGR1
12/30 09:12 init  MGR1
    
```

## Field descriptions

Date:	Current date and time.
Date	Date of the logged security violation shown as MM/DD (where MM = month and DD = day).
Time	Time of the logged security violation shown as HH:MM (where HH = the hour and MM = minute of the invalid access attempt).
Login	Login ID entered for the login violation attempt.
Port	Type of port used when login violation occurred. The following is a table of valid port types:
MGR1	MGR1 represents a connection to a system SAT port. Connections are either hardwired or dialed-up.
Ext	Extension assigned to the data module that failed during "logging in" session. If a data module is not used, this field is blank.
Date	Date of the logged security violation shown as MM/DD (where MM = month and DD = day).
Time	The time of the logged security violation shown as HH:MM (where HH = the hour and MM = the minute).
TG No.	The trunk group number associated with the trunk from the failed remote access attempt (remote access violations only).
Mbr	The trunk group member number associated with the trunk from the failed remote access attempt (remote access violations only).
Ext	Extension that interfaces with remote access features (remote access violations only).

## monitor system

This command summarize the system's condition. This on-line status report automatically updates every minute (or by pressing the UPDATE key) until the command is canceled by pressing the CANCEL key. For security reasons, the cancel command automatically logs off technicians.

Overall system status is available with either view option. "View1" displays attendant, maintenance, and traffic status. Attendant and maintenance status update every minute and traffic status updates hourly. "View2" displays all "View1" items, except hunt group measurements that are omitted from traffic status portions. These screens contain simplified high-level information about the system's health. The **monitor system conn** command displays connection's status in the connection manager process. Data is collected frequently in the connection manager for key information items used to create this report.

### NOTE:

This command is not available in DSA.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>monitor system</b>	<b>view 1</b> <b>view 2</b> <b>conn</b> <b>pnn ###</b> <b>pnn ###</b> <b>pnn ###</b>	see below	init inads craft cust nms browse	none	none

## Qualifier description

- view1** This screen displays attendant status, maintenance status, last hour's measurement of trunk groups, hunt groups, attendant groups, and the time of day.
- view2** This screen displays a subset of view1 form entries. It includes view1 forms except the last hour's hunt group measurements.
- conn** This option displays the connection monitor output for key information.
- entering no options** Omitting "pnn # # #" arguments on the command line displays the default configuration of Pnn's 1, 2 and 3.
- pnn # # #** Entering "pnn # # #" (where a pnn number from 1 to 3 replaces "#", and displays data for specified pnn's.
- entering no options** Omitting the "pnn # # #" argument on the command line displays default configurations of Pnn's 1, 2 and 3.
- pnn # # #** Entering "pnn # # #", where "#" is replaced by a pnn number from 1 to 3, displays data for specified pnn's.

## Output

Below are displays of **monitor system view 1** and **monitor system view 2**.

```

monitor system view1
      ATTENDANT STATUS                               MAINTENANCE STATUS
      Console no.                                     # of alarms for trunks: 4
Activated: 1 2 3 4 5 6                               # of alarms for stations: 2
      Deactivated: 7 8                               # of alarms for other res: 1
                                                    First OSS number has been informed? n

      TRAFFIC STATUS
      Measurement Hour: 1800
      Trunk Group Measurement                         Hunt groups Measurement
(4 grps with highest %time ATB)                     (4 grps with highest # of qued calls)
      Grp no: 78                                     Grp no: 16
      Grp dir:                                       Calls qued: 2
Calls qued: 1                                       Calls aban: 1
      %Out blkg:                                     Attendant Group Measurement
      %Time ATB:                                     Calls qued: 1      Calls aban: 0

                                                    16:06 WED MAR 6 1996

      - press CANCEL to quit -
    
```

```

monitor system view2
      ATTENDANT STATUS                               MAINTENANCE STATUS
      Console no.                                     # of alarms for trunks: 4
Activated: 1 2 3 4 5 6                               # of alarms for stations: 2
      Deactivated: 7 8                               # of alarms for other res: 1
                                                    First OSS number has been informed? n

      TRAFFIC STATUS Measurement Hour: 1800
      Trunk Group Measurement
(4 grps with highest %time ATB)
      Grp no: 78
      Grp dir:
Calls qued: 1
      %Out blkg:
      %Time ATB:
      Attendant Group Measurement
Calls qued: 1      Calls aban: 0

                                                    16:08 WED MAR 6 1996

      - press CANCEL to quit -
    
```

## Field descriptions

Console #	A list of console numbers that are activated or deactivated.
Activated:	The attendant console is active. An attendant console activated if: <ul style="list-style-type: none"> <li>■ Its handset/headset is plugged in</li> <li>■ It is not busied out, and the system is in day service and the console is a day or day/night or principle console, or the system is in night service and the console is a night or day/night console.</li> </ul>
Deactivated:	The attendant console is inactive. The attendant console deactivated if it does not meet activated conditions.
# of alarms for trunks	The number of existing minor and major trunk port alarms.
# of alarms for other resources	The number of existing minor and major alarms on all maintainable objects in the system, except trunks and stations.
First OSS number has been informed?	Questions if the first OSS telephone number reports and acknowledges alarms. If "Alarm Origination" is disabled or there are no active alarm, the field is "n".
Measurement Hour	The starting time for taking measurements. For example, if the measurement hour is shown as 1800, traffic status data display is the time period from 6 PM to 7 PM (The measurement is taken hourly).
Grp no	A number between 1 and the maximum trunk or hunt group number.
Grp dir	Group direction: incoming, outgoing or two way.
Calls qued	Total calls that arrive and are placed in the trunk group queue.
Calls aban	Total abandoned calls by the caller.
%Out blkg:	The ratio of outgoing calls that are not carried (due to overload conditions) on a trunk group to outgoing calls offered.
% Time ATB:	The percentage of time within polling intervals that all trunks in the trunk group are unavailable for use.
Time of day	The current time of day acquired from the system.

The following example is a display of the **monitor system conn** command.

```

Time Slot Status
Pnn      Bus   State  *Idle Count      Bus Status
10       0   Maint    0                10  0  Avail
10       1   Normal  233              10  1  Avail
10       0   Maint    0                22  0  Avail
10       1   Normal  233              22  1  Avail
22       0   Maint    0                1  0  Avail
22       1   Normal  233              1  1  Avail
22       0   Maint    0
22       1   Normal  233      *Callrate:  20
1        0   Maint    0      *Interval:  60
1        1   Normal  233      *Max_callrate:45
1        0   Maint    0      *Next_hour:  70
1        1   Normal  233
tot_ts_req :0F24 0000 3CE2 ts_count :0010 0920 0200 Requests-TN748 TTRs :0014
ts_denied  :0E46 3CE2 0000 ts_total :0000 0090 0028 Requests-TN748 CPTRs:0041
tot_fts_req:0000 53D2 2231 fts_count:02E0 0910 0784 Requests-TN744 CPTRs:0082
                fts_total:0320 0192 7048 Requests-TN744 TTRs :0082
                Requests-TN744 MFCs :0082

```

Note: \* Denotes Base 10, All Other Figures are in Base 16

## Field descriptions

- Time Slot Status** 4 numbers are associated with time slot status for each specified pnn; the two buses (0 and 1) have a maintenance and a normal state, and a number of idle counts. These fields represent real-time status data.
- Bus Status** Two numbers are associated with the two buses for each pnn. Shown are the pnn number; the associated bus (0 or 1); and the bus's state (avail or unavail). These fields represent real-time status data.
- Callrate** The callrate field represents call rates currently executing on the switch. This is a counter that is bumped for each call attempt. This field represents real-time status data.
- Interval** This field represents the interval applied to the call rate. It is normally a 36 second time period. This field represents constant status data.
- Max\_callrate** This field represents the maximum call rate achieved since the last hour. If, at 20 minutes past 12:00, the system executes this command, the maximum call rate obtained during the past 20 minutes displays. This field represents real-time status data.
- Next\_hour** This field contains a value of 0 or 1 depending related to measurements taken this hour or the next. This hour reflects maximum call rates. When this flag is set, statistics accumulate for the next hour and shortly thereafter.

**4** Maintenance Commands for DEFINITY ONE  
*monitor system*

4-104

<code>tot_ts_req</code>	This field holds the total time slots in use during the time period elapsed since the top of the last hour. Data is internally collected every 100 seconds. When the timer fires and the data collection occurs, a check is made as to how many time slots are currently in use. That's where the total comes from. There are three numbers displayed for this field on the form; one for each of the pnn's requested. This field represents real-time status data.
<code>ts_denied</code>	This field records total time slots requests denied since the beginning of the last hour. Data is collected internally every 100 seconds. Three numbers display for this field; one for each requested pnn. This field represents real-time status data.
<code>tot_fts_req</code>	This field represents the total number of requested fiber time slots. This field increments each time a fiber time slots is allocated since the last top of the hour measurement polling. Three values display; one for each requested pnn. This field represents real-time status data.
<code>ts_count</code>	The value in this field represents the requests for time slots during the last 100 second interim. An internal timer initiates polling every 100 seconds. Three numbers display for this field on the form; one for each requested pnn. This field represents real-time status data.
<code>ts_total</code>	This field represents the total number of time slots requested since the top of the last hour. This field represents real-time status data.
<code>fts_count</code>	The value in this field represents the requests for fiber time slots during the last 100 second interim. An internal timer initiates polling every 100 seconds. Three numbers display for this field; one for each requested pnn. This field represents real-time status data.
<code>fts_total</code>	This field indicates the total number of fiber time slots during the last 100 second interim. This field represents real-time status data.
<code>Requests-TN748 TTRs</code>	This field reflects the total number of requested touch tone receivers that are currently-active. It decrements when tone receivers are freed and increments when they are requested. This field applies strictly to the TN748 board. This field represents real-time status data.
<code>Requests-TN748 CPTRs</code>	This field reflects the total number of requested call progress tone receivers that are currently active. It decrements when call progress tone receivers are freed and increments when they are requested. This field applies strictly to the TN748 board. This field represents real-time status data.
<code>Requests-TN744 CPTRs</code>	This field reflects the total number of requested call progress tone receivers that are currently active. It decrements when call progress tone receivers are freed and increments when they are requested. This field applies strictly to the TN744 board. This field represents real-time status data.

4 Maintenance Commands for DEFINITY ONE  
*monitor traffic*

4-105

Requests-TN744  
TTRs

This field reflects the total number of requested touch tone receivers that are currently active. It decrements when tone receivers are freed and increments when they are requested. This field applies strictly to the TN744 board. This field represents real-time status data.

Requests-TN744  
MFC

This field reflects the total number of requested multi-frequency receivers that are currently active. It decrements when multi-frequency receivers are freed and increments when they are requested. Note that this field applies strictly to the TN744 board. This field represents real-time status data.

## **monitor traffic**

This command provides information on the number of trunk group and hunt group calls waiting to be serviced, and the time the oldest call in the group has been waiting for service.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>monitor traffic</b>	<i>trunk-groups</i> <i>hunt-groups</i>	see below	init inads craft cust rcust bcms browse	none	none

### **Qualifier description**

***trunk-groups*** The number of trunk group calls waiting to be serviced, members in the group, and number of members that are active on calls in the group. This field displays up to 60 administered trunk groups. Technicians specify the starting trunk group. If technicians enter 5, the displayed trunks start at 5. Numbers 1-4 do not appear.

***hunt-groups*** This field displays the waiting time for oldest call in each hunt group. Screen data updates every minute; only changed fields refresh. Unadministered hunt groups have blank values.

## Output

The following output example is a display of the **monitor traffic hunt-groups** command.

```
monitor traffic hunt-groups

          HUNT GROUP STATUS      22:49 SAT DEC 31 1988
#   S   A   Q   W   LCIQ      #   S   A   Q   W   LCIQ
1   15  10  10  0   20      17
2                                     18
3                                     19
4                                     20
5                                     21
6                                     22
7                                     23
8                                     24  10  5  0  0  10
9                                     25
10                                    26
11                                    27
12                                    28
13                                    29
14                                    30
15                                    31
16                                    32

( #: Group; S: Grp Size; A: Active Members; Q: Q Length; W: Calls Waiting)
(LCIQ: Longest Call In Queue in seconds)
```

## Field descriptions

- # Group number for trunk group or hunt group.
- S Number of members administered for each trunk or hunt group.
- A Number of group members that are active on a call. This does not include busied out members.
- Q The length of queues administered for groups.
- W Number of calls waiting in group queues to be serviced.
- LCIQ The longest call in queue (LCIQ) indicates the time in seconds the oldest call in the hunt group queue has been waiting to be serviced.

The following output example is a display of the **monitor traffic trunk-groups** command.

```
monitor traffic trunk-groups

                                TRUNK GROUP STATUS    22:49 SAT DEC 311988
#  S  A  Q  W  #  S  A  Q  W  #  S  A  Q  W  #  S  A  Q  W
1  15 10 0  0
2  22 21 10 10
9  31 12 20  0
65 5  5 10  8
99 12 0  0  0

(#: Group;  S: Grp Size;  A: Active Members;  Q: Q Length;  W: Calls Waiting)
```

## monitor trunk

This command displays internal software status information. This command helps to locate facilities to which the trunk is communicating. If a trunk group number is entered without a member number, and with or without “/”, it is member 1. If a trunk group and member number are both entered, status for specified members displays.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
monitor trunk	<b>group</b>	1 – 99. If a group number is entered without a member number, the member number defaults to 1.	init inads craft cust rcus bcms browse	1 (one)	none
	<b>member</b>	1 – 99. If a member number is entered, the member status displays.			

## Output

The following example shows the output from the **monitor trunk 78/1** command.

```
monitor trunk 78/1

                                TRUNK STATUS

Trunk Group/Member: 078/001          Service State: in-service/idle
Port: 01C1505                       Maintenance Busy? no
Signaling Group ID:                  CA-TSC State:
Connected Ports:
```

## Field descriptions

Trunk Group/Member	Trunk group and group member number. (1-99/1-99).
Port	The port location (cabinet-carrier-slot-circuit) for trunks.
Signaling Group ID	If the trunk is ISDN, this field contains the number of the ISDN Signaling Group. Otherwise, this field is blank. ( )
Connected Ports	Port locations (cabinet-carrier-slot-circuit) connected to the trunk.
Service State	In-service/active, in-service/idle, out-of-service, out-of-service-NE (Near End), out-of-service-FE (Far End), maint-NE/active, maint-FE/active, maint-NE/idle, maint-FE/idle, pending-in-service, pending-maint, or disconnected. NE (Near End) and FE (Far End) refer to the "end" of the trunk that has placed the facility in its current state.
Maintenance Busy	This field identifies maintenance testing that occurs on the trunk.
CA-TSC State	The state of temporary signaling connections. (connection set up to pass call information over PRI signaling links).

## recycle carrier

This command recycles power for specified carriers. When power units are replaced in carriers, this command recycles that carrier's power. **No Compact Modular Cabinet (CMC) can be recycled.**

## release access-endpoint

This command removes all ports associated with the specified access endpoint from a maintenance busy state. Periodic and scheduled tests subsequently resume on the released ports. Maintenance completes background initialization testing on the released ports. For details of the test sequence, refer to [3].

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>release access-endpoint</b>	<b>extension</b>	number associated with desired access endpoint.	init inads craft nms	none	none

## Output

The following example shows the output from the **release access-endpoint 22502** command and assume that the access endpoint ports for extension 22502 are in cabinet 1, carrier C, slot 11, circuit 1 to 6.

```
release access-endpoint 22502           page 1 of 1

                COMMAND RESULTS

Port Maintenance Name Alt. Name Result  Error Code
01C1101 WAE-PORT  22502   PASS
01C1102 WAE-PORT  22502   PASS
01C1103 WAE-PORT  22502   PASS
01C1104 WAE-PORT  22502   PASS
01C1105 WAE-PORT  22502   PASS
01C1106 WAE-PORT  22502   PASS

Command Successfully Completed
```

## Field descriptions

Port	Port address (cabinet-carrier-slot-circuit) of released maintenance.
Maintenance Name	The type of released maintenance object. (wideband access point = WAE-PORT, single port access endpoint = TIE-DS1).
Alt. Name	Alternate way to identify maintenance objects. This field contains the extension number of the access endpoint.
Result	Success status of a busied out object (PASS, ABORT, FAIL)
Error Code	System-generated description of a command failure.

## release adjunct-ip-link

---

### Description

---

The `release adjunct-ip-link` command is used to release a busied out ASAI adjunct IP link that is administered on the `ip-services` form. An ASAI adjunct link provides connectivity to CentreVu-CT which is connected to an Ethernet LAN. On DEFINITY ONE, the LAN interface is provided by the TN795 Ethernet interface or by the CLAN (Control LAN) TN799 circuit pack. A CLAN board is used only if a private LAN is required for security reasons.

When the link is released, a Link Status message with the cause code set to "link up" is sent to the client. The client responds with a restart message and the switch precedes to bring the link up.

### Parameters

`Link-id` - A number from 1 to 8 assigned to the link on the `ip-services` form as the suffix on the `adjlk` services type. For the first release of the feature, only 1 link will be supported.

### Examples

```
release adjunct-ip-link 1
```

### Output

---

Port	The link number (1-8) as administered on the <code>ip-services</code> form
Maintenance Name	The name of the maintenance object as it appears in the Error and Alarm Logs
Alternate Name	An alternate means of identifying the maintenance object. This is not used for the ASAI adjunct-ip link
Result	Whether or not the object was successfully released.
Error code	A number indicating the reason for an abort or failure of the command. See <code>Busyout</code> and <code>Release Error Codes</code> at the beginning of this chapter for details of common abort and failure codes.

4 Maintenance Commands for DEFINITY ONE  
*release adjunct-ip-link*

4-111

The following display shows a typical result when busyout adjunct-ip-link is entered

```
release adjunct-ip-link 1
                                COMMAND RESULTS

  Port      Maintenance Name  Alt. Name    Result      Error Code
  1         ADJLK-IP                PASS

Command successfully completed
```

## release board

This command activates administered maintenance objects on the circuit pack at specified locations.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
release board	<i>location</i>	Board location: <b>PCSS</b>	init inads craft nms	none	none

## Output

The following output example is a display of the **release board 1c07** command and assumes that the board in cabinet 1, carrier c, slot 7 is an analog board with three administered ports.

```
release board 01C07

                        COMMAND RESULTS

Port   Maintenance Name  Alt. Name  Result  Error Code
01C07  ANL-BD              PASS
01C0702 ANL-LINE              PASS
01C0701 ANL-LINE              51001    PASS
01C0703 ANL-LINE              PASS

Command successfully completed
```

## Field descriptions

Port	Port address (cabinet-carrier-slot) of released maintenance object.
Maintenance Name	The type of maintenance object that is being released.
Alt. Name	Alternate way to identify maintenance objects.
	<b>If the Object is    The field contains</b>
	station                    extension
	trunk                    xxx/yyy (where xxx = trunk group number and yyy = member number)
	private CO line    P/xxx (where xxx = private CO line group number)
Result	Success status of a busied out object (PASS, ABORT, FAIL)
Error Code	System-generated description of a command failure.

## release cdr-link

This command removes maintenance objects associated with specified call detail recording (cdr)-links from a maintenance busy state. These links provide asynchronous data connections from switches to peripherals; they are composed of a:

- Manager that initiates and maintains the link embedded on the TN795
- Controller/protocol that services the link

For information on what a CDR link is and does, see the description of the [“status cdr-link”](#) command.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>release cdr-link</b>			init inads craft	none	none

## Output

The following example shows the output from the **release cdr-link primary** command.

```
release cdr-link

                                COMMAND RESULTS

Port  Maintenance Name  Alt. Name  Result  Error Code
      PRI-CDR                PASS

Command successfully completed
```

## Field descriptions

Port	Not applicable. ( )
Maintenance Name	Type of released maintenance object. (primary cdr-link = PRI-CDR, secondary cdr-link = SEC-CDR)
Alt. Name	Not applicable. ( )
Result	Success status of a busied out object (PASS, ABORT, FAIL)
Error Code	System-generated description of a command failure.



## release mis

---

This command activates management information systems. Hardware tests are executed to verify that equipment is functioning properly.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>release mis</b>			init inads craft cust rcust	none	none

## Output

---

The following example shows the output from the **release mis** command.

```
release mis
```

```
COMMAND RESULTS
```

```
Port      Maintenance Name  Alt. Name  Result  Error Code
          MIS
          PASS
```

```
Command Successfully Completed
```

## Field descriptions

Port	Not applicable.
Maintenance Name	MIS
Alt. Name	Not applicable.
Result	Success status of a busied out object (PASS, ABORT, FAIL)
Error Code	System-generated description of a command failure.

## release modem-pool

This command deactivates specified modem pool groups or group members. Specifying group numbers, member numbers releases single group members. Specifying modem pool group numbers releases members in a modem pool group.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>release modem-pool</b>	<b>group</b>	1-5.	init inads craft	none	none
	<b>member</b>	pair of analog and digital line ports (or two pair for the Integrated modem-pool case). 1-32.			

## Output

The following example shows the output from the **release modem-pool 1** command.

```
release modem-pool 1          SPE B
                               COMMAND RESULTS
Port      Maintenance Name  Alt. Name  Result  Error Code
01C0701   MODEM-PT                PASS
01C0703   MODEM-PT                PASS
Command successfully completed
```

## Field descriptions

Port	Port address (cabinet-carrier-slot-circuit) of busied out maintenance object.
Maintenance Name	MODEM-PT.
Alt. Name	This field is not applicable to this command.
Result	Success status of a busied out object (PASS, ABORT, FAIL)
Error Code	System-generated description of a command failure.



## release pri-endpoint

This command removes PRI endpoint ports (B-channels) associated with specified PRI endpoint from maintenance busy states. Periodic and scheduled tests resume on released ports. The switch attempts to negotiate with the far-end PRI terminal adapter activating PRI endpoint port (B-channel). Maintenance does background initialization testing on released ports. For details of the test sequence, refer to [3].

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>release pri-endpoint</b>	<b>extension</b>	extension number associated with desired PRI endpoint.	init inads craft nms	none	none

## Output

The following example shows the output from the **release pri-endpoint 22501** command and assumes that the PRI endpoint ports for extension 22501 are in cabinet 1, carrier B, slot 20, circuit 1 to 6.

```
release pri-endpoint 22501           page 1 of 1
                                     COMMAND RESULTS

Port      Maintenance Name Alt. Name  Result  Error Code
01B2001   PE-BCHL           22501   PASS
01B2002   PE-BCHL           22501   PASS
01B2003   PE-BCHL           22501   PASS
01B2004   PE-BCHL           22501   PASS
01B2005   PE-BCHL           22501   PASS
01B2006   PE-BCHL           22501   PASS

Command Successfully Completed
```

## Field descriptions

Port	Port address (cabinet-carrier-slot-circuit) of released maintenance object.
Maintenance Name	PE-BCHL.
Alt. Name	Alternate way to identify maintenance objects. (PRI endpoint extension)
Result	Success status of a busied out object (PASS, ABORT, FAIL)
Error Code	System-generated description of a command failure.

## release station

This command removes specified administered voice terminal extensions from a maintenance busy state.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
release station	<i>extension</i>	Extension number (see dial-plan)	init inads craft cust	none	none

## Output

The following example shows the output from the **release station 1002** command.

```
release station 1002

                                COMMAND RESULTS

Port      Maintenance Name  Alt. Name  Result  Error Code
01C1102   DIG-LINE           PASS

Command successfully completed
```

## Field descriptions

Port	Port address (cabinet-carrier-slot-circuit) of the released maintenance object.
Maintenance Name	Type of released maintenance object.
Alt. Name	Alternate way to identify maintenance objects. This field contains an extension when the object is a station.
Result	Success status of a busied out object (PASS, ABORT, FAIL)
Error Code	System-generated description of a command failure.

## release tdm

This command removes specified tdm buses from a maintenance busy state.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>release tdm</b>	<b>port-net work pn number</b>	Port network number of the TDM bus	init inads craft	none	see below
	<b>bus bus</b>	("a" or "b") specifies desired half of the TDM bus. Each 512 time slot TDM bus is configured as two duplicate 256 time slot buses. This division allows for duplication of control channels and dedicated tone time slots. The default control bus (carrying the control channel) is the "a" bus, while the default tone bus (carrying dedicated tones) is the "b" bus. (1 - 3)			

### Feature interactions

- The system tears down busied out buses. No new calls can be administered on busied out buses.
- To prevent busyouts of particular buses, technicians should move dedicated tone time slots to another bus (the other half of the duplicated bus).

### Output

The following example shows the output from the **release tdm port-network 1 bus a** command.

```
release tdm port-network 1 bus a
```

COMMAND RESULTS

Port	Maintenance Name	Alt. Name	Result	Error Code
PN 01A	TDM-BUS		PASS	

```
Command successfully completed
```

4 Maintenance Commands for DEFINITY ONE  
*release tone-clock*

4-121

### Field descriptions

Port	Port network number (preceded by "PN") and bus ("A" or "B") associated with the TDM bus.
Maintenance Name	TDM-BUS
Alt. Name	Not applicable
Result	Success status of a busied out object (PASS, ABORT, FAIL)
Error Code	System-generated description of a command failure.

### release tone-clock

This command removes specified tone/clocks from maintenance busy states.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>release tone-clock</b>	<b>location</b>	Physical location of the tone/clock: <b>PC</b>	init inads craft	1 (one)	none

### Output

The following example shows the output from the **release tone-clock 1a** command.

```
release tone-clock 1a

                                COMMAND RESULTS

Port   Maintenance Name  Alt. Name  Result  Error Code
01A    TONE-PT             PASS
01A    TDM-CLK             PASS
01A    TONE-BD             PASS

Command successfully completed
```

### Field descriptions

Port	The tone clock circuit pack maintenance object displays the cabinet and carrier of the specified tone/clock board.
Maintenance Name	TONE-PT, TDM-CLK and TONE-BD
Alt. Name	Not applicable.
Result	Success status of a busied out object (PASS, ABORT, FAIL)
Error Code	System-generated description of a command failure.

## release trunk

This command removes specified trunk groups or trunk group members from a maintenance busy state. Specifying the group number releases a single group member and the member number; specifying the trunk group number releases members in a trunk group.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
release trunk	<i>group</i>	1–99.	init inads craft	none	none
	<i>member</i>	1–99			

## Output

The following example shows the output from the **release trunk 78/1** command.

```
release trunk 78/1
```

### COMMAND RESULTS

Port	Maintenance Name	Alt. Name	Result	Error Code
01C1505	CO_TRK	78/01	PASS	

```
Command successfully completed
```

## Field descriptions

Port	Port address (cabinet-carrier-slot-circuit) of the released maintenance object.
Maintenance Name	The type of maintenance object that is being released.
Alt. Name	Alternate way to identify maintenance objects.
	<b>If the Object is</b> <b>The field contains</b>
	station                    extension
	trunk                    xxx/yyy (where xxx = trunk group number and yyy = member number)
	private CO line        P/xxx (where xxx = private CO line group number)
Result	Success status of a busied out object (PASS, ABORT, FAIL)
Error Code	System-generated description of a command failure.

## reset board

This command performs a soft reset of every specified, administered port on the port circuit pack. Ports must be busied out before the port circuit pack resets.



### WARNING:

*This command is service disrupting and may cause extraneous alarms.*

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
reset board	<b>location</b>	Physical location of board: <b>PCSS</b>	init inads craft nms	carrier = 1	none
	<b>repeat number</b>	Number of times command repeats (1–99)		repeat number = 1	

## Output

The following example shows the output from the **reset board 1c07** command and assumes that the board in port network 1, carrier c, slot 7 is an analog board with three administered ports.

```

reset board 1c07

                                TEST RESULTS

Port      Maintenance Name  Alt. Name  Test No.  Result  Error Code
01C07     ANL-BD              53        PASS

Command Successfully Completed
    
```

## Field descriptions

Port	Port address (cabinet-carrier-slot) of the reset maintenance object.
Maintenance Name	Type of reset maintenance object.
Alt. Name	Alternate way to identify maintenance objects.
	<b>If the Object is    The field contains</b>
	station                    extension
	trunk                    xxx/yyy (where xxx = trunk group number and yyy = member number)
	private CO line    P/xxx (where xxx = private CO line group number)
Result	Success status of a busied out object (PASS, ABORT, FAIL)
Error Code	System-generated description of a command failure.

## reset packet-interface

---

### reset packet-interface C [S] ['restart]

#### CAUTION:

*Resetting a packet interface is disruptive under the following conditions:*

- On all standard reliability systems (simplex SPE)
- When handshake is down, and the packet interface is reset.

#### CAUTION:

*In the above cases, call service throughout the system is disrupted, the terminal is logged off. A minor alarm is logged against the circuit pack to be reset.*

This command resets or restarts and initializes the packet interface circuit pack hardware and firmware on the TN795 processor circuit pack. If this command is executed without the 'restart' argument and failed, re-execute this command with the restart option. The restart option can be executed only if the packet-interface is out of service; use the status packet-interface command to determine the state of the packet-interface.

When an active packet interface is reset, its links are dropped and reassigned to the remaining in-service packet interface circuit packs. These links are not migrated back to the packet interface after the reset. A level 2 (Cold-2) or greater system restart is required to redistribute the links equally among all active packet interfaces, including the one that was reset.

For DEFINITY ONE, the specified packet interface circuit pack is simply reset. Failure of the reset can lead to the circuit pack being placed in the out-of-service state. When a packet interface is out of service, scheduled, periodic, error and demand testing of the circuit pack is prevented and it is not used for links. The circuit pack returns to the in-service state upon passing the reset. A level 2 (Cold-2) or greater system restart is then performed to distribute the links equally among the available packet interface circuit packs.

## Parameters

---

**C, CS** The cabinet is always 1 and need not be specified. The slot number (1-2) designates one of the dedicated PKT-INTFC on the TN795 circuit pack, and defaults to the lowest-numbered slot with a packet interface installed in it.

**restart** If the reset command fails and the packet interface is out of service, this option allows a technician to recover the packet interface.

## reset switch-control

This command resets and initializes the switch control hardware and firmware.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>reset switch-control</b>	none	none	init		none
	restart	restart archangel firmware on the TN795	inads craft nms		

## reset system

This command resets the system beginning with the corresponding vector bit set, a core dump is written to memory card, only if the memory card is the special core dump card), the vector is cleared, and the requested restart is performed.

**NOTE:**

All successful reset system commands log users off.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>reset system</b>	<i>level</i>	1 = Warm Restart 2 = Cold 2 3 = Reboot 4 = Reboot 5 = Reboot	init inads craft	none	see below

## Feature interactions

- The **reset command** invokes system initialization like low-level maintenance. Software never escalates requested reset levels; technicians determine the levels.
- Two hardware switches are associated with active SPEs. These hardware switches override demand maintenance activities requested by system technicians.

## reset tone-clock

This command resets the tone clock component TN795 Processor circuit.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>reset</b> <b>tone-clock</b> <b>location</b> <b>repeat number</b>		reset command performs a soft (i.e. software) reset on the TN795 board.	init inads nms	The carrier and repeat number default to 1.	none



### WARNING:

*This command is service disrupting and may cause extraneous alarms.*

## Help Messages

**location** A "location" represents the physical position of the tone-clock component on the TN795 circuit pack to be reset and is entered as "UUc" where "UU" represents the cabinet number (1 - 3), "c" represents the carrier

**number** The "number" specifies how many times each board reset is to be repeated. "Number" may be any integer between 1 and 100.

If the system technician presses HELP after entering "reset board," the following message will be displayed:

```
Enter [cabinet(1-0)];[carrier (A)], ['repeat' (1-100)]
```

## Error Messages

If the format of the tone-clock location is incorrect, the following error message will be displayed:

```
Board invalid
```

If a tone-clock is not inserted in the specified location, then the following message will be displayed:

```
Board not assigned
```

If a reset is attempted on an invalid board in the service slot, the following message is displayed:

```
Board invalid
```

If the command entered is in conflict with another currently executing command, then a message will be displayed showing the login id of the conflicting user and the conflicting command. The message is as follows:

```
'login id': 'command' has a command conflict
```

If during the execution of a command a resource problem occurs that requires the user to restart the command, then the following message will be displayed:

```
Command resources busy;
Press CANCEL to clear, and then resubmit
```

If all of the available maintenance resources are currently in use, then the following message will be displayed:

```
All maintenance resources busy; try again later
```

## Output

---

Port	The port address (cabinet-carrier-slot) of the maintenance object that is being reset.
Maintenance Name	The type of maintenance object being reset.
Alt. Name	The alternate means of identifying the maintenance object. This field contains the extension when the object is a station, and it contains xxx/yyy when the object is a trunk, where xxx is the trunk group number and yyy is the member number. It contains P/xxx when the object is a private CO line, where xxx is the private CO line group number.
Result	The result of the reset -"PASS," "ABORT," "FAIL."
Error Code	A system-generated number that tells why the reset failed or aborted. A detailed list of the codes can be in the "Reset Commands" section of this chapter.

For the following output example, assume that the board in port network 1, carrier A, slot 2 is an analog board with three ports administered. The command that was entered is "reset board 1A02."

```
reset tone-clock 1A
```

### TEST RESULTS

Port	Maintenance Name	Alt. Name	Test No.	Result	Error Code
1A02	PR-TN-BD		53	PASS	

```
Command Successfully Completed
```

## Feature interactions

---

None.

## **resume hardware-group**

---

This command resumes the previous **test hardware-group** command its canceled position. Entering another **test hardware-group** disables the **resume hardware-group** command.

A canceled **test hardware-group** command appears as *canceled* on the **status hardware-group** screen. A resumed **test hardware-group** command appears as *active* on the **status hardware-group** screen.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>resume hardware-group</b>		none	init inads	none	none

### **Feature interactions**

---

- Cancelling a test hardware-group command deactivates the test command. The status hardware-group screen displays the state as *canceled*.
- When the **resume hardware-group** command is entered to resume a previously-canceled **test hardware-group** command, the state of the test command will be changed to *active* on the **status hardware-group** screen.

## save translation

All translation data is kept on the hard drive during system operation. This command allows users to save the hard drive translation data to the hard drive. This command runs as part of scheduled maintenance and/or on demand by the technician.



**NOTE:**

Translations are volatile only when changes are administered, but not yet saved.



**NOTE:**

Translations are stored on the hard drive, not the removable drive.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
save translations	spe-active	Translations saved to the hard drive.	dinit dinads dcraft cust	none	If translation data changes due to administrative commands, <b>save translation</b> cannot be performed.

## Output

The following example shows the output from the **save translation** command. Error Codes are as follows:

- 0 - save successful
- 1 - could not write to the active device

```

save translation

                                SAVE TRANSLATION

Processor  Command Completion Status      Error Code
SPE-A     Success                          0

Command Successfully Completed
    
```

## Field descriptions

**Processor** Identifies the processor carrier where translation data is saved. (SPE-A)

**Command Completion Status** Displays a variety of messages, identifying the success or failure of the command.

## set options

This command enables a remote user with INADS permission to select which types of maintenance categories report alarms automatically and which types require customer call-in. Judicious use of this command can reduce the number of ineffective alarms to the TSC. For effective results, technicians should use the **set options** command default settings specified in this section. Technicians should not change these settings. Special circumstances (for example, special studies) may require temporary changes under the guidance of Tiers 3 and 4.



**NOTE:**

Alarms do not upgrade.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
set options		none	init inads	see below	none

## Form Input

The following example is a display of the **set options** command.

```
set options
```

Page 1 of 8

ALARM REPORTING OPTIONS

```

                                Major  Minor
On-board Station Alarms:    w      w
Off-board Station Alarms:   w      w
On-board Trunk Alarms (Alarm Group 1): y      y
Off-board Trunk Alarms (Alarm Group 1): w      w
On-board Trunk Alarms (Alarm Group 2): w      w
Off-board Trunk Alarms (Alarm Group 2): w      w
On-board Trunk Alarms (Alarm Group 3): w      w
Off-board Trunk Alarms (Alarm Group 3): w      w
On-board Trunk Alarms (Alarm Group 4): w      w
Off-board Trunk Alarms (Alarm Group 4): w      w
On-board Adjunct Link Alarms: w      w
Off-board Adjunct Link Alarms: w      w
Off-board MASI Link Alarms:  w      w
Off-board DS1 Alarms:        w      w
Off-board TCP/IP Link Alarms: w      w
Off-board Alarms (Other):    w      w
    
```

```
set options                                     Page 2 of 8

                                TRUNK GROUP ALARM OPTIONS
                                (Alarm Group)

01: 1  11: 1  21: 1  31: 1  41: 1  51: 1  61: 1  71: 1  81: 1  91: 1
02: 1  12: 1  22: 1  32: 1  42: 1  52: 1  62: 1  72: 1  82: 1  92: 1
03: 1  13: 1  23: 1  33: 1  43: 1  53: 1  63: 1  73: 1  83: 1  93: 1
04: 1  14: 1  24: 1  34: 1  44: 1  54: 1  64: 1  74: 1  84: 1  94: 1
05: 1  15: 1  25: 1  35: 1  45: 1  55: 1  65: 1  75: 1  85: 1  95: 1
06: 1  16: 1  26: 1  36: 1  46: 1  56: 1  66: 1  76: 1  86: 1  96: 1
07: 1  17: 1  27: 1  37: 1  47: 1  57: 1  67: 1  77: 1  87: 1  97: 1
08: 1  18: 1  28: 1  38: 1  48: 1  58: 1  68: 1  78: 1  88: 1  98: 1
09: 1  19: 1  29: 1  39: 1  49: 1  59: 1  69: 1  79: 1  89: 1  99: 1
10: 1  20: 1  30: 1  40: 1  50: 1  60: 1  70: 1  80: 1
90: 1
```

**⇒ NOTE:**

Remaining Trunk Group information displays on pages 3-8, and is not documented in this Manual.

The first page of the Alarm Reporting Options Form, provides the following alarm options: the four trunk alarm severity groups, the adjunct alarms, off-board DS1 alarms, and PI-LINK alarms, memory card translation capacity alarms, and other off-board alarms. The second page, known as the Alarm Reporting Options Form, provides alarm severity groups to each trunk group.

The following alarm options are available:

- **Minor:** Maintenance testing discovers raised alarms, downgrades them to minor alarms, and deactivates alarmed resources. LEDs on the port board and maintenance board follow standard minor alarm LED protocol and call receiving OSSs.
- **Warning:** Maintenance testing discovers raised alarms, downgrades them to warnings and deactivates alarmed resources. The Alarm Log pinpoints customer-reported trunk or station problems. Alarm LEDs light on the port circuit pack and Maintenance circuit pack as before, but no attendant LEDs or stations reporting alarms are affected. No call is placed to INADS.
- **Report:** The report option treats alarms the same as warnings with one exception: alarms report to INADS with a special WARNING category. When this type of alarm is received, INADS logs the occurrence and creates a trouble ticket or closes it immediately. Retry strategy for this type of call is similar to normal Major or Minor alarm reports. However, the acknowledgment LED on the attendant console or alarm reporting station does not reflect the status of the call.
- **Yes:** Alarms raise normally without filtering alarm data.

- No: Alarms that raise on trunks, stations, or adjuncts in this category drop. Error information displays as before, but alarm is evident. LED is inactive and calls are not sent to INADS. Because resources are deactivated without any record, this option is recommended only when other options do not provide desired results.

Technicians can administer alarm options on a system-wide basis for the following categories:

- Major on-board station alarms
- Minor on-board station alarms
- Major off-board station alarms
- Minor off-board station alarms

Trunk alarms have four alarm severity groups with administrable alarm options in the categories listed below. For G1, technicians can administer alarm options on a system-wide basis for the following categories:

- Major on-board trunk alarms
- Minor on-board trunk alarms
- Major off-board trunk alarms
- Minor off-board trunk alarms

Technicians assign alarm severity options to the following Adjunct categories:

- Major on-board adjunct alarms
- Major off-board adjunct alarms
- Minor on-board adjunct alarms
- Minor of-board adjunct alarms

Technicians can administer options for Minor off-board DS1 Interface circuit pack alarms and Minor off-board Memory Card Capacity Alarms on a system-wide basis.

The system inspects alarm reporting options information in the Alarm Reporting Options Form as translation data and preserves it through all restart levels.

This command affects the MO alarming listed below. Neither the trunk nor the station category applies to alarms raised on the common portion of the circuit pack.

If the option associated with the alarm type is set to "n," the system drops the alarm report. Alarm error information remains intact, but no records of alarms and no LEDs light on the port circuit pack, the Maintenance circuit pack, the attendant console, or alarm reporting station to indicate a problem.

If technicians set the option “warning” or “report,” port circuit pack LEDs and LEDs on the Maintenance circuit pack are affected the same as warning alarms.

Default parameters are:

- The system downgrades all station, trunk (except on-board trunk alarms), and Minor DS1-BD alarms to warning alarms.
- On-board Major and Minor trunk alarms, and the Memory Card Capacity alarm continue to raise alarms and report to INADS.

### Station MOs affected by this command



#### NOTE:

Although alarms on some MOs appear as warnings, they should be investigated with user-reported problems.

- Analog Lines (ANL-LINE, ANL-NE-L, ANL-16-L)
- Digital Lines (DIG-LINE)
- Hybrid Lines (HYB-LINE)
- MET Lines (MET-LINE)
- ISDN-BRI Lines (BRI-PORT, BRI-SET)

If more than 75% of the members of the trunk group alarm, minor arms escalate to major alarms. If the trunk category option is set to “warning,” “minor,” “report,” or “no,” this no longer happens. Maintenance reactivates individual trunk members according to Major and Minor alarm criteria.

### Trunk MOs affected by this command



#### NOTE:

Although alarms on these MOs may appear as warnings, the alarms should be investigated with user-reported problems.

- Auxiliary Trunks (AUX-TRK)
- Central Office Trunks (CO-TRK)
- Direct Inward Dialing Trunks (DID-TRK)
- Direct Inward and Outward Dial Trunks (DIOD-TRK)
- DS1 Central Office Trunks (CO-DS1)
- DS1 Direct Inward Dialing Trunks (DID-DS1)
- DS1 Tie Trunks (TIE-DS1)
- ISDN Trunks (ISDN-TRK)
- Tie Trunks (TIE-TRK)

## Circuit pack MOs affected by this command

**NOTE:**

Although alarms on some MOs appear as warnings, the alarms should be investigated with user-reported problems.

**NOTE:**

The alarm severity of group one downgrades trunks that are not members of Trunk Groups, (for example, PCOLs).

- DS1 Interface Circuit Pack (DS1-BD)

## Adjunct-related MOs affected by this command

**NOTE:**

Although alarms on some MOs appear as warnings, the alarms should be investigated with user-reported problems.

- ASAI Adjunct (ASAI-ADJ)
- Lucent Adjunct Port (ATT-PORT)
- Ethernet ASAI Port (LGATE-PT)
- Ethernet ASAI Adjunct (LGATE-AJ)
- Ethernet Lucent Port (ATTE-PT)
- Ethernet Lucent Adjunct (ATTE\_AJ)
- ISDN-BRI Ports connected to Adjuncts (ABRI-PORT)

Adjuncts are administered as stations; however, the administration of alarm severity for the station alarm group does not affect alarm severity levels for adjuncts. Similarly, the administration of alarm severity for the adjunct alarm group does not affect the alarm severity levels for other stations.

## Other MOs affected by this command

**NOTE:**

Although alarms on some MOs appear as warnings, the alarms should be investigated with user-related problems.

- EPN Maintenance Circuit Pack (MAINT)
- ISDN-PRI Signaling Group (ISN-SGR)
- CDR Link (CDR)
- SPE Select Switches (SPE-SELEC)
- Synchronization (SYNC)
- System Communication Interface (PI-SCI)
- TDM Clock (TDM-CLK)
- Tone Generator Circuit Pack (TONE-BD)

## set signaling-group

This command upgrades secondary D-channel in specified signaling groups to primary D-channels. Current primary D-channel then revert to secondary D-channels. A signaling group is a collection of B-channels that designate single D-channels or a set of D-channels signals over an ISDN-PRI.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>set signaling-group</b>	<b>group identifier</b>	administered number associated with each signaling group.	init inads craft	none	none

## set synchronization

This command sets DS1 trunks or active tone/clock circuit packs that supply references for synchronization. The **set synchronization** command works after the **disable synchronization** command disables synchronization. Technicians may administer DS1 trunks or active tone/clocks with the **set synchronization** command. DS1 or tone/clocks remain synchronization references until the **set synchronization** command runs with another board or until the **enable synchronization** command runs.

After the **enable synchronization** command runs, administered primary or secondary synchronization sources become synchronization references. If no primary or secondary source is administered, synchronization uses active tone/clock boards as synchronization references after synchronization is enabled.

The synchronization subsystem provides error-free digital communication between the switch and other PBXs, COs, or customer premise equipment. System components involved in synchronization include: TDM bus clock, DS1 trunk board, and maintenance and administration software resident in the SPE.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>set synchronization</b>	<b>location</b>	Physical position of the DS1 trunk or active tone/clock: <b>PCSS</b>	init inads craft	none	none

## set tdm

The **set tdm** command establishes the TDM bus on a port network that houses control channels and dedicated tones.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>set tdm</b>	<b>port network</b>	Port network number of the TDM bus	init inads craft	none	See below
	<b>pn number bus</b>	("a" or "b") specifies desired half of the TDM bus. Configure each 512 time slot TDM bus as two duplicate 256 time slot buses, allowing duplication of control channels and dedicated tone time slots. A port network number (1 - 3)			
	<b>bus override</b>	Forces the setting of a deactivated bus or a bus whose dedicated tone time slots are active			

### Feature interactions

New calls go to time slots reserved for tones on the bus that have not other time slots when:

- Time slots on a specified bus are in use
- Dedicated tone time slots are on the other half of the bus

A **set** command to buses that have calls on dedicated tone time slots drops these calls.

## set tone-clock

This command sets the active tone/clock for a PN that has a duplicated tone/clock circuit pack. Technicians should reset the default active tone clock in each PN after using the **set tone-clock** command. If it is not in use, a single failure can cause an unnecessary service outage. The schedule maintenance tone-clock switch option does not reset the tone-clock to the default active if it was not active at the beginning of the test.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>set tone-clock</b>	<b>location</b>	Tone/clock location: <b>PC</b>	init inads craft	1 (one)	none
	<b>override</b>	Forces the set command into effect regardless of the tone/clock circuit pack's health.			

## status access-endpoint

This command displays the status of an access endpoint and can be helpful in locating facilities with which access endpoints communicate.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>status access-endpoint</b>	<b>extension</b>	Extension number of the access endpoint	init inads craft cust nms browse	none	none

## Output

The following example shows the output for the **status access-endpoint 22502** command. The command assumes that access endpoint ports for extension 22502 are in cabinet 1, carrier C, slot 11, circuit 1 to 6 — that access endpoints are connected on an active call to ports 7 to 12 of the board in location 1B19 (cabinet 1, carrier B, slot 19). This means that port 01C1101 connects to 01B1907, port 01C1102 connects to 01B1908, and port 01C1103 connects to 01B1909.

```
status access-endpoint 22502                page 1 of 1

ACCESS-ENDPOINT STATUS

      Extension: 22502
(Starting) Port: 01C1101
Communication Type: wideband
              Width: 6

      Service State: in-service/active

      Connected Ports: 01B1907 01B1908 01B1909
                      01B1910 01B1911 01B1912

Command Successfully Completed
```

## Field descriptions

Extension	Extension of the access endpoint
(Starting) Port	Port locations of the access endpoint. For wideband access endpoint, the location shown is that of the starting port.
Communication Type	The valid voice and data communication type that the access endpoint is administered. The options are: 56k-data, 64k-data, voice-grade-data, and wideband.
Width	For 56k-data, 64k-data, and voice-grade data, the width value is 1. For wideband, this field displays the number of DS0s that make up the access endpoint.
Service State	<i>in-service/active</i> , <i>in-service/idle</i> , and <i>out-of-service</i>
Connected Ports	Port location connected to the access endpoint for an active call. For wideband, all ports connected to the wideband access endpoint are listed.

## **status administered-connection**

This command provides automatic end-to-end connections between two access/data endpoints.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>status administered-connection</b>	<b><i>ac number</i></b>	Administered connection number	init inads craft cust rcust bcms browse	none	none

## Output

---

The following example shows the output from the **status administered-connection 3** command.

```
status administered-connection 3                page 1 of 1
                                               ADMINISTERED-CONNECTION STATUS
Connection Number:
  Enabled?
  Originator:
  Destination:
  Connection State:
  Failure Cause:
  Number of Retries:
  Auto Restorable?
```

## Field descriptions

Connection Number:	Number assigned to the administered connection.
Enabled?	Is administered connection enabled? (y or n).
Originator:	Extension of originating access/data endpoint.
Destination:	Destination address used to route administered connections.
Connection State:	Current status of the administered connection. (connected, restored, failed, waiting to retry, attempting to restore, attempting to connect, not scheduled, and disabled).
Failure Cause:	Reason that the administered connection is attempting to connect, to restore, or failed to restore. If the administered connection was scheduled to be active but is disconnected, this field shows the most recent failure reason.
Number of Retries:	Number of consecutive failed establishment attempts.
Auto Restorable?	When an administered connection is connected, this field indicates if auto restoration attempts when a failure occurs.

## status asai/adjunct tcp/ip link

The status asai/adjunct-ip-link command displays the status of all adjlk (asai proprietary adjunct) tcp/ip links administered on the ip-services form. These links provide connectivity to CentreVu-CT which is connected to an Ethernet LAN. On DEFINITY ONE, the LAN interface is provided by the TN795 Ethernet interface or by the CLAN (Control LAN) TN799 circuit pack. A CLAN board is used only if a private LAN is required for security reasons.

The status of the TCP/IP Tunnel Connection and ASAI Adjunct link are displayed along with the number of ASAI messages sent and received during a specified collection period.

Action/Object	Qualifier	Qualifier Description	Permissions	Defaults	Feature Interactions
status asai/adjunct-ip-link	None	None	init inads craft cust	None	None

## Output

The following display shows a typical result when the status asai/adjunct-ip-link command is entered.

ASAI/ADJUNCT TCP/IP LINK STATUS

ASAI Link	Client Link	Service Type	Maint Busyout	Connection State	Service State	Msgs Sent	Msgs Rcvd	Msg Col Period
1	1	adjlk	yes	established	established	1	10	

#### 4 Maintenance Commands for DEFINITY ONE

*status asai/adjunct tcp/ip link*

4-141

### Field Descriptions

ASAI Link	The DEFINITY ASAI link number (1 through 8) as administered as the suffix number of the service type on the <i>ip-services</i> form
Client Link	The Client Link number selected by the CentreVu-CT software at the far end.
Service Type	The service type, <i>asai</i> or <i>adjlk</i> , as administered on the <i>ip-services</i> form
Maintenance Busy State	The link has been busied out using the <i>busyout adjunct-ip-link 1</i> command. It may be released by using the <i>release adjunct-ip-link 1</i> command.
Connection State	The connection state of the TCP/IP Tunnel connection <ul style="list-style-type: none"><li>■ Disabled: This usually means that <i>asai</i> link is not enabled on the <i>ip-services</i> form. The TCP Tunnel connection will deny any connection request from the far end.</li><li>■ Listening: The TCP/IP socket is up and the TCP Tunnel connection is waiting for a connection request message from the client.</li><li>■ Established: The TCP Tunnel connection has been established. This is the steady state when the client is connected.</li><li>■ Intfce dwn: The Processor IP interface has been busied out.</li></ul>
Service State	The service state of the ASAI link <ul style="list-style-type: none"><li>■ Down: The ASAI link is down.</li><li>■ Restarting: The switch sends a Restart message to the client but has not received a Restart Acknowledgment message from the client.</li><li>■ Restarted: After receiving a Restart Acknowledgement message, the switch sends a Heartbeat message to the client and awaits a response.</li><li>■ Established: Normal State for the ASAI client.</li><li>■ Hyperactive: The link has sent too many messages per unit time. Stop accepting new associations from the client.</li></ul>
Messages Sent	The number of ASAI messages sent during the Collection Period
Messages Received	The number of ASAI messages received during the Collection Period
Message Collection Period	The collection period in seconds

## status attendant

This command diagnoses internal software. This command help to locate facilities to which the attendant console communicates.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>status attendant</b>	<b>console number</b>	Assigned attendant number (1 –16).	init inads craft cust rcust bcms browse	none	none

## Output

The following example shows the output from the **status attendant 1** command.

```
status attendant 1

ATTENDANT STATUS

Console Number: 1           Service State: in-service/night service
Port: 01C1106             Download Status: no
Connected Ports:

Command successfully completed
```

## Field descriptions

Console Number	Number assigned to the attendant (1-16).
Port	Port location of the attendant (cabinet-carrier-slot-circuit).
Service State	In-service/idle, in-service/active, out of service, or disconnected.
Usage State	Idle or active.
Maintenance Busy State	Is maintenance testing the object? (y or n)
Connected Ports	Port locations to which the attendant is communicating (cabinet-carrier-slot-circuit).

## status audits

---

This command displays results of Data Relation Audits that are built into the switch. Data Relation Audits check for inconsistencies between selected data items in the switch, and report inconsistencies. Data Relation Audits are useful during development and testing phases of projects to uncover software errors. In the field they help the switch to recover from data corruption before service is interrupted.

This command displays the date and time that the requested interval begins, the number of times that the full sequence of audits executes (audit cycles), and status information about each audit that detected a problem or aborted during the interval. The status information contains:

- The name of the audit
- The number of times that an audit ran and corrected an error
- The number of times that an audit ran and detected an irreparable error
- The number of times that an audit ran and aborted
- The date and time that the audit first detected a problem (only for cumulative)
- The time of the most recent error detected by the audit (only for cumulative)

Audit data information cumulates from the last reboot or the last **clear audits cumulative** command, and for peak hours since the last reboot or the last **clear audits peak-hour** or **clear audits cumulative** commands.

### NOTE:

Single process restarts, warm starts, cold 2 restarts, cold 1 restarts, or processor interchanges do not clear this data.

Audits can execute directly using the **test MO** command. For example, **test MO I 8192 p 512 t 0** executes the Station Connections Audits, audit Inames and numbers (pnames) included in the Table Of Audits. When the "test MO" command executes an audit, report results display on the screen. In general, errors discovered from a demand tests are not logged in the error logs. To be consistent with other error logging, and to avoid confusion, errors that are discovered from a demand test that executes an audit are not displayed.

The screen does not automatically update, but reflects the system at the time of the request.

4 Maintenance Commands for DEFINITY ONE  
*status audits*

4-144

Action/ Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>status audits</b>	<b>peak-hour</b>	data collected since the last reboot or since the last execution of the <b>clear audits cumulative</b> command.	init inads	none	see below
	<b>cumulative</b>	Data for the peak hour since the last reboot or since the last execution of the <b>clear audits cumulative</b> or <b>clear audits peak-hour</b> command.			

## Output

The following example shows the output from the **status audits** command.

```
status audits cumulative
```

AUDIT STATUS INFORMATION

Start Date: 13:00 MON MAR 19 1997 # of Audit Cycles Completed: 67532

Audit Name	# Cycles Fixed Data	# Cycles Could Not Fix Data	# Cycles Audit Aborted	First Error	Most Recent Error
HTLK	0	*****	0	03/22/10:14	06/24/16:03
CR-AUDIT	135	0	0	03/22/10:12	06/10/19:17
HU-CALLS	2	0	0	03/22/10:12	03/22/10:20
SE-CALLS	1	0	1	03/22/10:13	03/22/19:14
TTR-SID	1	0	0	05/01/02:17	05/01/02:17
CO-CALLS	1	0	0	05/01/02:16	05/01/02:16
DE-CALLS	1	0	0	03/22/10:12	03/22/10:12
TR-QUE	1	0	0	04/05/13:05	04/05/13:05
CTRK	0	1	0	03/22/10:12	03/22/10:12
AT-ADM	1	0	0	03/22/10:12	03/22/10:12
CO-ADM	1	0	0	03/22/10:13	03/22/10:13
PC-ADM	1	0	0	04/05/15:05	04/05/15:05
PRI-USR (SCH)	1	0	0	03/22/10:14	03/22/10:14

Command successfully completed

4 Maintenance Commands for DEFINITY ONE  
status audits

4-145

```
status audits peak-hour
```

AUDIT STATUS INFORMATION

```
Start Date: 10:00 MON MAR 22 1997 # of Audit Cycles Completed: 25
```

Audit Name	# Cycles Fixed Data	# Cycles Could Not Fix Data	# Cycles Audit Aborted
HTLK	0	25	0
HU-CALLS	2	0	0
CR-AUDIT	1	0	0
DE-CALLS	1	0	0
CTRK	0	1	0
AT-ADM	1	0	0
CO-ADM	1	0	0
SE-CALLS	0	0	1
PRI-USR (SCH)	1	0	0

```
Command successfully completed
```

Audit information displays with one line of data displayed audit that has detected an error or aborted. Audits that did not detect any errors or aborted do not display. The output sorts in descending order, based on the sum of the values in the # Cycles Fixed Data, # Cycles Could Not Fix Data, and # Cycles Audit Aborted fields.

## Field descriptions

Start Date

Date and time that interval begins. "cumulative" = date and time of the last reboot or execution of the "clear audits cumulative" command.

"peak-hour" = date and time of the beginning of the peak hour since the last reboot or execution of a "clear audits cumulative" or "clear audits peak-hour" command.

# of Audit Cycles Completed

Number of audit cycles completed in the specified interval (0 – 999999). Asterisks indicate numbers that exceed 999999. The switch executes audits in a set order. After all audits execute, the switch restarts the sequence.

### ➡ NOTE:

Since this field shows the number of completed audit cycles, it is possible that individual audit values, can be larger than the values described below (if the switch is partially through another audit cycle). Audit Cycles numbers do not apply to these audits that execute as part of scheduled maintenance.

Audit Name

Audit's name that detected an error or aborted. A few audits do not run in the normal audit sequence. Instead, they execute as part of scheduled maintenance and are marked with "(SCH)" following the audit name.

#### 4 Maintenance Commands for DEFINITY ONE

*status audits*

4-146

# Cycles Fixed Data	Number of times that the audit ran, in the specified interval, and found a fixable problem. (0–65534) Asterisks are used for numbers that exceed 65534.
# Cycles Could Not Fix Data	Number of times that the audit ran, in the specified interval, and found an unfixable problem. The audited switch data is inconsistent when this happens. (0–65534) Asterisks are used for numbers that exceed 65534.
# Cycles Audit Aborted	Number of times that the audit ran, in the specified interval, and aborted due to an internal error. (0–65534) Asterisks are for numbers that exceed 65534.
First Error	Date and time that the audit first detected fixed data, could not fix data or audit aborted problems since the last <b>clear audits cumulative</b> command. Example: 03/27/14:31 for 2:31 pm, March 27th. This field appears with the <b>status audits cumulative</b> display.
Most Recent Error	Date and time that the audit last detected fixed data, could not fix data or audit aborted problems since the last "clear audits cumulative" command. Example: 03/27/14:31 for 2:31 pm, March 27th. This field appears with the <b>status audits cumulative</b> display.

### Feature interactions

---

The **clear audits** command affects the data displayed by **status audits cumulative** and **status audits peak-hour**. The **clear audits cumulative** command clears data collected to date, resets the start time kept for that data, and clears peak hour data. The **clear audits peak-hour** command clears data kept for the peak hour so that a new peak hour can be established.

When the **schedule** option is specified, a scheduling form is displayed allowing the technician to schedule command execution.

to the Report Scheduler and System Printer feature specification [3] for details about the scheduling form.

### Table of audits

---

The following table shows the names of the audits that are run as part of time available maintenance, the audit number (pname) and a short description of each audit. These audits execute using Iname MO\_DR\_AUDIT (8192). These audits may execute using the *test MO* command with Iname 8192, pname "audit number," and test number 0 (for example, *test MO 1 8192 p 607 t 0* executes the AC state audit).

4 Maintenance Commands for DEFINITY ONE  
*status audits*

4-147

<b>Audit name</b>	<b>Audit number</b>	<b>Description</b>
AC-ISG	607	AC state audit
ADJUSR	595	Adjunct user record audit
ADMTRM	559	Administration terminal audit
ANUR-A	589	Announcement user record audit
AN-ADM	574	Announcement group administration audit
AN-CALLS	572	Announcement group calls audit
AN-QUE	577	Announcement group queue audit
AQSA	545	ACB queue slot allocation audit
ASLINK	606	ASAI link status audit
ASYLED	605	ASAI yellow LED audit
ATACT	558	Attendant active audit
ATAV	557	Attendant availability audit
ATDRCNT	576	Attendant resource count audit
AT-ADM	529	Attendant group administration audit
AT-CALLS	515	Attendant group calls audit
AT-QUE	523	Attendant group queue audit
AUR-A	540	Attendant user record audit
AU-CIDP	596	Announcement user cid/port audit
AWOH-UR	614	Admin Without Hardware Split User Record Audit
B2B-TAB	617	Board-to-Board Link Audit
BR-CALLS	629	Bridged extensions audit
BUTLK	560	Button lock audit
CALK	569	Coverage answer member lock audit
CATT	527	Attendant connections audit
CCTRTAB	624	Call Classifier Tone Receiver Table Audit
CCTR-SID	600	Call classifier tone receiver audit
CDM	528	Data module connections audit
CO-ADM	530	Coverage group administration audit
CO-CALLS	516	Coverage group calls audit
CPROC	585	Call process/call record audit
CPTRTAB	623	Call Progress Tone Receiver Table Audit
CPTR-SID	601	Call progress tone receiver audit
CPWAKEUP	586	Wake up call process audit

*Continued on next page*

4 Maintenance Commands for DEFINITY ONE  
*status audits*

4-148

Audit name	Audit number	Description
CR-AUDIT	513	Call processing data audit
CSR-A	544	Connection service record audit
CSTAT	512	Station connections audit
CTRK	526	Trunk connections audit
DA-CALLS	583	DAP call record audit
DA-MSG	584	DAP message buffer audit
DE-ADM	531	Data extension group administration audit
DE-CALLS	517	Data extension group calls audit
DMLK	563	Data module lock audit
DUR-A	543	Data user record audit
DXLK	567	Data extension member lock audit
FHT	554	Facility status hundreds table audit
FTED	553	Facility status tracked user audit
FTING	552	Facility tracking user audit
FTSRA	593	Fiber time-slot record allocation audit
GIP-TIMER	609	GIP Timer Audit
HTLK	568	Hunt member lock audit
HU-ADM	532	Hunt group administration audit
HU-CALLS	518	Hunt group calls audit
HU-QUE	524	Hunt group queue audit
IAP-CALLS	590	IAP call record audit
IAP-URB	591	IAP user record audit
IM-HMM	579	HMM image table audit
INST-LNK	604	Instigator/down-link user link audit
ISGR-A	594	ISG call record audit
LOG-A	570	MDM error/alarm log audit
MAP-HMM	580	HMM map status table audit
MCT-ADM	561	Malicious call trace administration audit
MIS-FAC	587	MIS facility state audit
MP-ADM	575	Modem pool group administration audit
MP-CALLS	573	Modem pool group calls audit
MSGQ-HMM	582	HMM map request queue audit
MS-CALLS	588	MISAP call record audit

*Continued on next page*

4 Maintenance Commands for DEFINITY ONE  
*status audits*

4-149

Audit name	Audit number	Description
MUV	555	Message user verification audit
MWIA	550	Message waiting indicator audit
MWL-NOAP	599	Message waiting lamp no AP audit
PA-ADM	533	Paging group administration audit
PA-CALLS	519	Paging group calls audit
PCLK	566	PCOL member lock audit
PC-ADM	535	Personal CO line group administration audit
PC-CALLS	521	Personal CO line group calls audit
PINC-TAB	612	Packet Inter-Port Network Connection Sub-Table audit
PI-ADM	534	Pickup group administration audit
PLIP-LNK	602	LIP link audit
PN-HMM	578	HMM pname table audit
PRI-CR	598	PRI call record audit
PRI-TBUF	592	TSCUUI buffer audit
PUR-A	541	Phantom user record audit
SDSBUF	581	Service dispatcher stim buffer audit
SDSID	571	Service dispatcher SID audit
SE-ADM	538	Terminating extension group administration audit
SE-CALLS	537	Terminating extension group calls audit
STNLK	562	Station lock audit
SUR-A	539	Station user record audit
S-INC-TAB	611	Service Inter-Port Network Connection Sub-Table audit
S-PT-TAB	610	Service-Port Connection Sub-Table audit
S-TAB	620	Service Table Audit
TEGLK	565	TEG member lock audit
TKLK	564	Trunk lock audit
TONE-TS	608	Tone Time Slot Subtable Audit
TR-ADM	536	Trunk group administration audit
TR-CALLS	522	Trunk group calls audit
TR-QUE	525	Trunk group queue audit
TSC-PRI	520	ISDN-PRI TSC resource audit
TSRA	547	Time slot record allocation audit
TTI-STATE	618	TTI State Audit

*Continued on next page*

4 Maintenance Commands for DEFINITY ONE  
*status audits*

4-150

<b>Audit name</b>	<b>Audit number</b>	<b>Description</b>
TTI-TRANS	619	TTI Translation Audit
TTR-SID	514	Touch tone receiver audit
TTR-TAB	622	Touch Tone Receiver Table Audit
TUR-A	542	Trunk user record audit
T-TS-TAB	613	Tone Time Slot Connection Sub-Table Audit
UGMA	551	User group membership audit
UPUSR-LNK	603	Up-link user link record audit
URMB	548	User record maintenance busy audit
X25-CHAN	615	X.25 Channel Status Audit
X25-LINK	616	X.25 Link Status Audit

The following table shows the names of audits that run as part of scheduled maintenance, the audit number (pname) and a short description of each audit. These audits execute using lname MO\_SCH\_AUDIT (8193). These audits may execute using the *test MO* command with lname 8193, pname "audit number," and test number 0 (for example, *test MO / 8193 p 556 t 0* executes the Message Waiting Lamp Audit audit).

<b>Audit name</b>	<b>Audit number</b>	<b>Description</b>
MWL	556	Message Waiting Lamp Audit
PRI-USR	597	PRI user record audit
SUR-FREE	625	Station User Record Free List Audit

## status bri-port

This command displays the service state, maintenance state and layer 1 state of an ISDN-BRI port. This form also displays information about point-to-point signaling links that transport over the port.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>status bri-port</b>	<b>location</b>	Port location: <b>PCSSpp</b>	init inads craft cust nms browse	none	none

## Output

For the following example shows the output from the **status bri-port 1c1701** command.

```

status bri-port 1c1701                               Page 1 of 1  SPE A
                                                    STATUS BRI-PORT
                Port: 01c1701
        Service State: in-service
Maintenance Busy?: no
        Layer 1 State: activated

    TEI Value  Layer2 State  Endpt Extension  Endpt SPID  Service SPID?
Link1    64      13-established    1010          1010
Link2
Link3

```

## Field descriptions

Port:	ISDN-BRI port address.
Service State:	ISDN-BRI port is "in-service" or "out-of-service."
Maintenance Busy?:	specifies if maintenance testing is executing on the ISDN-BRI port ("yes" or "no").

Layer 1 State:	<p>BRI Layer 1 (physical) state on the port. Valid states are “activated,” “pend-activation,” and “deactivated.”</p> <ul style="list-style-type: none"><li>■ “activated” state = layer 1 frames are passing between the port and BRI endpoints.</li><li>■ “pend-activation” state = the port is in-service, the layer 1 interface device is on, layer 1 frames are sending to the BRI endpoints connected to this port, but BRI endpoints are not responding.</li><li>■ “deactivated” state = the layer 1 interface device on the BRI is off, because the port goes out-of-service.</li></ul>
TEI Value	<p>Layer 2 addressing parameter used by the switch to exchange information over point-to-point signaling links between BRI endpoints. Each point-to-point signaling link has an associated TEI. This field displays the addressing parameter value. (0–127)</p>
Layer2 State:	<p>Point-to-point signaling link layer 2 state. Valid states are “un-assigned,” “assigned,” “established,” “I3-established” or “hyperactive.”</p> <ul style="list-style-type: none"><li>■ “un-assigned” = the link is in TEI-UNASSIGN state at Layer 2.</li><li>■ “assigned” state = the link is in the AWAIT_EST (Await Establish) state at layer 2. (If BRI endpoints support TEI allocation procedures, they successfully execute and a TEI is assigned to the endpoint by the switch.</li><li>■ “established” = the link is in the MF_EST_NORM (Multi-Frame Established Normal) state at layer 2. The switch successfully initiates the link can now exchange layer 3 frames with the endpoint. If the endpoint does not support SPID initialization procedures, the endpoint extension associated with the link also displays. This is the normal state for the link in the point-to-point wiring configuration.</li><li>■ “I3-established” = link is in the MF_EST_NORM state at layer 2 and SPID initialization procedures successfully complete. The endpoint extension associated with the link also displays. This is the normal state for the link in the multi-point wiring configuration.</li><li>■ “hyperactive” = traffic on this link goes over threshold. The link suspends and is deemed hyperactive.</li></ul>
Endpt Extension	<p>Voice/data endpoint extension associated with the link if the link is in the “established” (point-to-point configuration) or “I3-established” (multipoint configuration) layer 2 state. Otherwise, this field is blank.</p>

**Endpt SPID** This field displays the SPID administered on the voice/data endpoint associated with the link. Note that this information is displayed only if the link is in either the “established” (point-to-point configuration) or the “13-established” (multipoint configuration) layer 2 state. Otherwise this field is blank.

**Service SPID** Indicates if the link is associated with the Service SPID. If the link is associated with Service Spuds, the field contains a “yes” and the endpoint extension field is blank; otherwise, this field is blank. Service SPID checks building wiring between the switch and the BRI endpoint.

### Status bri-port interpretation

[Table 4-1](#) provides information on the status bri-port form.

**Table 4-1. Status BRI-port command interpretation**

Endpoint types	TEI range	Layer 2 state	Voice extension	Service SPID	Description / Recommendation
ASAI, BRI	0-126	Assigned	blank	blank	<p>Transitory state for BRI endpoints and ASAI adjuncts. The switch attempts link establishment.</p> <ol style="list-style-type: none"> <li>1. Check endpoints and wiring by following SPID Facility Test Procedures described in the BRI-SET (ISDN-BRI Set/ASAI Adjunct) Maintenance documentation.</li> <li>2. Verify repairs with <b>status bri-port PCSSpp</b>. Determine that L2 state of the signaling link is “L3-Established” for ASAI adjuncts and BRI endpoints supporting MIM (management information messages) initialization and “Established” for fixed TEIBRI endpoints and automatic TEIBRI endpoints not supporting MIM initialization.</li> </ol> <p> <b>NOTE:</b> A MIM is a level-3 message that conveys management and maintenance information between communications systems and BRI terminals.</p>

Table 4-1. Status BRI-port command interpretation — *Continued*

Endpoint types	TEI range	Layer 2 state	Voice extension	Service SPID	Description / Recommendation
ASAI	0-63	Established	blank	blank	<p>Transitory state for ASAI adjuncts. ASAI signaling is connects at Layer 2. Layer 3 Restart procedure does not complete between switch and adjunct.</p> <ol style="list-style-type: none"> <li>1. Check the adjunct by following the manufacturer's recommended repair procedures.</li> <li>2. Verify repairs by executing the <b>status bri-port PCSSpp</b> command. Determine that the L2 state of the signaling link is L3-Established.</li> </ol>
BRI	0-126	Established	ext	blank	Normal state for non-MIM initializing, fixed and automatic TEIBRI endpoints.
BRI, ASAI	64-126	Established	blank	blank	<p>Transitory state for automatic TEIBRI endpoints which support MIM initialization.</p> <ol style="list-style-type: none"> <li>1. Verify that SPID administration on the switch and endpoint are consistent. Verify the repair by executing the <b>status bri-port PCSSpp</b> command. Determine that the L2 state of the signaling link is L3-Established. Otherwise, proceed to Step 2.</li> <li>2. Try to replace the endpoint. Verify the repair by executing the <b>status bri-port PCSSpp</b> command. Determine that the L2 state of the signaling link is L3-Established.</li> </ol>
BRI	64-126	L3-Established	ext	blank	Normal state for automatic TEIBRI endpoints supporting MIM initialization.

*Continued on next page*

Table 4-1. Status BRI-port command interpretation — *Continued*

Endpoint types	TEI range	Layer 2 state	Voice extension	Service SPID	Description / Recommendation
BRI, ASAI	64-126	L3-Established	blank	yes	Technicians conduct SPID facilitation tests on the port. Links are not associated with BRI port endpoints. See description of SPID Facility Test Procedures in the <a href="#">“BRI-SET, ASAI-ADJ, BRI-DAT”</a> maintenance documentation.
BRI	64-126	L3-Established	ext	yes	Technicians conduct SPID facilitation tests on the port. Links are associated with port endpoints. See description of SPID Facility Test Procedures in the <a href="#">“BRI-SET, ASAI-ADJ, BRI-DAT”</a> maintenance documentation.
BRI	0-126	L3-Established	blank	blank	Invalid SPID assigned to link.  1. Change the SPID value in the BRI endpoint to match the SPID administered to the BRI endpoint on the port. Verify the repair by executing the <b>status bri-port PCSSpp</b> command. Determine that the L2 state of the BRI endpoint is L3-Established.

*Continued on next page*

Table 4-1. Status BRI-port command interpretation — *Continued*

Endpoint types	TEI range	Layer 2 state	Voice extension	Service SPID	Description / Recommendation
BRI	0-126	L3-Assigned	ext	blank	<p>Transitory state for BRI endpoints which support MIM initialization.</p> <ol style="list-style-type: none"> <li>2. Wait for five seconds and repeat the command. If the state has not changed, continue with Step 2.</li> <li>3. Make sure SPID administration on the switch and endpoint are consistent. Verify the repair by executing the <b>status bri-port PCSSpp</b> command. Determine that the L2 state of the signaling link is L3-Established. Otherwise, go to Step 3.</li> <li>4. Try to replace the endpoint. Verify the repair by executing the <b>status bri-port PCSSpp</b> command. Determine that the L2 state of the signaling link is L3-Established.</li> </ol>
BRI	0-126	L3-Assigned	ext	yes	<p>Transitory state for BRI endpoints which support MIM initialization when SPID Facility Test initializes the station.</p> <ol style="list-style-type: none"> <li>5. Wait for five seconds and repeat the command. If the state has not changed, continue with Step 2.</li> <li>6. Make sure SPID administration on the switch and endpoints are consistent. Verify the repair by executing the <b>status bri-port PCSSpp</b> command. Determine that the L2 state of the signaling link is L3-Established. Otherwise, go to Step 3.</li> <li>7. Try to replace the endpoint. Verify the repair by executing the <b>status bri-port PCSSpp</b> command. Determine that the L2 state of the signaling link is L3-Established.</li> </ol>

*Continued on next page*

Table 4-1. Status BRI-port command interpretation — *Continued*

Endpoint types	TEI range	Layer 2 state	Voice extension	Service SPID	Description / Recommendation
ASAI	0-126	Hyperactive	ignore	ignore	Link has sent too many messages per unit time.
BRI					Signaling suspends. System timeouts in 60 seconds and attempts reactivate the link. If links remain in this state while no activity occurs at BRI endpoints: <ol style="list-style-type: none"><li>1. Ensure that SPID switch administration and endpoints are consistent. Verify repairs by executing the <b>status bri-port PCSSpp</b> command. Determine that the L2 state of the signaling link is L3-Established.</li><li>2. Replace the endpoint. Verify repairs by executing the <b>status bri-port PCSSpp</b> command. Determine that the L2 state of the signaling link is L3-Established.</li></ol>
ASAI	0-126	L3-Restarting	ext		The switch sends a Restart message to the adjunct but has not received a Restart Acknowledgment message from the adjunct.
ASAI	0-126	L3-Restarted	ext		After receiving a Restart Acknowledgment message, the switch sends a Heartbeat message to the adjunct and awaits a response.
ASAI	0-126	L3-Established	ext		Normal state for ASAI adjunct.

## status cdr-link

This command displays the status of call detail recording (CDR) links. Link up or down status displays. If a link is down, the system displays the number of times the switch attempts link setup.

Call detail recording (CDR) links physically link SPEs to a recording device (for example, printer) for sending CDR call records. CDR link are composed of a data channel on the NETCON board or EIA port on the processor circuit pack, a digital port and a data module. Two CDR links can exist in the system.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>status cdr-link</b>			init inads craft cust rcust nms bcms browse	none	none

## Output

The following example shows the output from the **status cdr-link** command.

```
status cdr-link
                                CDR LINK STATUS

Link State: down
Number of Retries: 0
Maintenance Busy? yes
```

## Field descriptions

Link State	up = link is up and available to the application. (normal state) down = link is physically down. Extension not administered = administer <b>system cdr feature</b> form.
Number of Retries	The number of times the switch tried to initialize the link.
Maintenance Busy	yes = maintenance object is busied out; no = not busied out.

## **status cleared-alarm-notif**

Expert Systems use this command to detect chronic alarming conditions. If this command displays *Feature is suspended*, Expert Systems can identify open trouble tickets as chronic problems for special consideration.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>cleared-alarm-notif</b>	<b>1</b>	First OSS telephone number status of Cleared Alarm Notification.	init inads craft	First OSS telephone number for the Cleared Alarm Notification status.	none
	<b>2</b>	Second OSS telephone number status of Cleared Alarm Notification.	cust rcust		

## **status conference**

Use this command to solve the following multimedia problems:

1. A user cannot join or remain connected to a conference.
2. Automatic algorithms — audio AUTO mode and the Px64 video picture specifications downgrade the conference, causing poor video quality.
3. A user does not receive full service.
4. An audio add-on user cannot join or remain connected to a conference.
5. A conferee is not seen by other users due to interworking problems.
6. Users cannot participate in Multipoint Communications Service conferences.
7. Continuous conferences do not move endpoints in or out of quadrants.

Action/Object	Qualifier	Qualifier Description	Permissions	Defaults	Feature Interactions
<b>status conference</b>	<b>status conference</b>	Stored conference data.	init inads craft	Conference-ID = <b>all</b> (all stored data).	none
	<b>status conference 2 print</b>	Conference 2 data (current or last completed). Sends report to printer.			

Output

```

status 50                                     Page 1 of 2
                STATUS OF CONFERENCE: 50 Status: in-use
Conference Name: MCH DYNAMIC                 Conference Mode: voice-activated
Password Scope:
Password:                                     Cascade Mode:
Class: dedicated                             Audio Mode: G.728
Start Time/Date: 09:08 OCT 28                Data Mode: none      MLP Rate:
Stop Time/Date: 00:00 000 00   Admin Bandwidth: 64k      No of Channels: 2
Chair:                                       Conf Bandwidth: 64k  Rate Adaptation? y
Format (in/out): CIF                       FPS: 7.5 QFPS: 7.5  Lo/Hi Interworking? n

      Type Ext Meet-Me Number      Dial In ---Capability--- Rate Bond
      Type Use Chl And Vid Mlp Gz Adpt Mode Ts Va
1: P54      in  o  y  y  o      s
2: AUD      out y      y
3:
4:
5:
6:

```

admin MLC status

Screen 4-1. status conference: page 1 of 2

It is possible for several records to display. Active conferences display first (in order of conference-ID), followed by completed conferences (most recently completed first). Conferences that have not begun have no data or information.

Conference data displays in 2 parts: the first screen describes the status of the conference and indicates the modes and levels of the conference. It also identifies in-use endpoints that cause conference operating modes to change. This screen is similar to the administration screens. The remainder of the screens display endpoint level data (up to 8 endpoints per screen), revealing ports and drop reasons.

[Screen 4-1](#) shows page 1 of a typical administration screen. The first screen appears when **status conference** is entered and at least 1 valid conference is found.

**Field descriptions (status conference, page 1)**

---

status	Current status of the conference (active, in-use, complete)
conference name	(MMCH DYNAMIC)
conference mode	(Voice-activated)
password	Not Applicable
password scope	Not Applicable
cascade mode	Conference cascade mode (blank)
audio mode	Current operating audio mode (G.711-A, G.711-mu, G.728, G.722)
class	Conference type (dedicated)
data mode	Conference data mode capability (none, any-mlp, ww-pcs)
MLP rate	Conference MLP Data Rate (blank).
start time/date	Conference start time in 24-hour notation with month and day.
stop time/date	End of conference in 24-hour notation with month and day. It is the actual end time if Status is complete; otherwise, it is blank.
admin bandwidth	Channel bandwidth administered on the Conference Record form. (64k)
no of channels	Number of channels required for each Px64 endpoint (2)
Chair	Current chair token holder. ( )
conf bandwidth	Current operating channel conference bandwidth. Different from the administered bandwidth because of Rate Adaptation.
Rate adaptation	Does this conference support Rate Adaptation? (n, y)

4 Maintenance Commands for DEFINITY ONE  
status conference

4-162

Format (in/out)	<p>The video format for single-screen conferences: CIF, QCIF, QCIF/CIF, H.CTS, H.CTX+, and SG4.</p> <p>non-H.261 conferences = input and output formats are always symmetric and the mode is the same for input and output. (H.CTX, H.CTX+, and SG4).</p> <p>H.261 mode non-continuous presence conferences = symmetric format (CIF and QCIF).</p> <p>Non-presentation, continuous presence conference in single-screen = symmetric format (CIF and QCIF).</p> <p>Presentation mode H.261 single screen continuous presence capable conferences = symmetric input and output formats QCIF/CIF (displayed as CIF) or asymmetric QCIF/CIF, if the administered format is upgradable.</p> <p>For quad-screen conferences = the format is QCIF/CIF to reflect the QCIF input from all participants and output of CIF to all participants.</p> <p>For presentation mode quad-screen conference = the format is QCIF/CIF to reflect the input/output of all participants except the presenter. In quad-screen mode, presenter input is always CIF.</p>
FPS	<p>The CIF frame rate (frames per second) - ' - ', 30, 15, 10, 7.5. FPS indicates the rate that endpoints can receive frames. The MCU cannot detect maximum transmit frame rates or current frame rates. Frame rates change due to the amount of motion in the input image.</p>
QFPS	<p>The ACIF frame rate (frames per second) (' - ', 30, 15, 10, 7.5). The rate that an endpoint can generate/receive frames.</p> <p>Quad-screen VAS conferences = QFPS reflects the highest common QCIF frame rate of all endpoints and the video mixer board rate, that is lower than the rest of the participants. QCIF calculation accounts for the highest common CIF frame rate declared by all conference participants, since the QCIF rate cannot be greater than that of the highest common CIF rate.</p> <p>Quad-screen presentation conferences = QFPS reflects the highest common QCIF frame rate of all participants and the video mixer board rate. QFPS cannot be greater than the CIF frame rate that is announced by the presenter.</p> <p>QFPS field is blank for proprietary modes.</p>
lo/hi interworking	<p>Does this conference support Low Speed/High Speed Interworking? This field defaults to n.</p>
Type	<p>The type of conferee — Audio/Video (P64), Audio Add-on (AUD), Cascade Link (CAS), BONDing Call (BOND), BONDing Cascade Link (BCAS), UCC Controller (UCC), or Dedicated Access (DA). BONDing calls use up to 12 channels to form a single multimedia pipe.</p>
Ext	<p>Administered endpoint extension. ( ).</p>

4 Maintenance Commands for DEFINITY ONE  
*status conference*

4-163

Meet-me number	The Meet-Me Number administered for the Meet-Me Extension. ( )
Dial Type	“in” = dial-in to join endpoint to conference. “out” = dial-out to join endpoint to conference.
In Use	“y” = the endpoint is in use and is fully-connected on all media in an active conference.  “c” = the endpoint is in use and is fully-connected; however, the endpoint has changed conference audio or video capability or conference rate due to rate adaptation. This condition requires analysis of this endpoint’s capabilities and mode fields to identify reduced capability.  “e” = the endpoint is in use but has capability problems. The endpoint lacks one of the required capabilities (Vid, Bhl, MLP) to fully participate. For MLP capabilities, see the “T120” field. This condition requires analysis of this endpoint’s capabilities and mode field to identify the missing capability.  “f” = the endpoint is in use but not connected to all media. The endpoint declared all required capabilities (channel/video/audio/data) but is not fully connected to all conference media. This endpoint may be connecting, failed to connect, or is not a valid video source. This condition requires analysis of this endpoint’s capabilities and mode fields to identify the problem.  “n” = the endpoint disconnected during a conference or unsuccessfully attempted to connect to a conference.  “blank” = the field is blank until the first call from or to the endpoint.
Ch1	“y” = the endpoint has the required number of channels.  “e” = the endpoint does not declare support for the correct number of channels and cannot participate fully in the conference.  “n” = the endpoint declares the correct number of channels, but not all join the conference, due to a network or endpoint problem.  “blank” = Audio add-on endpoints set the Ch1 field to blank.

4 Maintenance Commands for DEFINITY ONE  
*status conference*

4-164

Aud	“y” = the endpoint has the required audio capability. Audio add-on endpoints always set the Aud field to y when the endpoint joins the conference.  “c” = the endpoint is PCM only and it changes the conference video quality by changing the operating audio from G.728 to G.711. If administered audio modes are auto and the administered bandwidth is 112 kbps (56 k/channel) or 128 kbps (64 k/channel), the system initiates with the highest common audio, G.728. When the administered bandwidth is greater than 128 kbps, the system initiates with the highest common bandwidth, 7 kHz.  “e” = A PCM-only endpoint that could not support the administered audio mode, G.728 (such as a data conference), or G. 278/G.711 endpoint that could not support the administered audio mode, 7 kHz. Such endpoints operate with PCM audio and interwork with current operating audio modes.  blank = blank until the first call from or to the endpoint.
Vid	“y” = the endpoint has the required video capability and should be receiving video if the Chl, Aud, and Dat fields are y.  “c” = downgraded conference video quality from changing CIF to ACIF or by decreasing the frame rate. The conference video mode defaults to CIF. If QCIF-only endpoints join the conference, the entire conference operates in QCIF, with downgraded video clarity. The conference frame rate is initially set to the highest frame rate that can be reduced by any endpoint. If the conference video mode is not administered with upgrade capability, the video parameters for a conference are “downgraded.” They are not “upgraded” until all endpoints disconnect from the conference.  “e” = the endpoint does not declare video capability in its cap-set.  “n” = audio only, not receiving video, due to audio or data problems.  “blank” = Audio add-on endpoint defaults the Vid field to blank.
MLP	Control Link to the ESM (T.120 stack terminator) status, the endpoint MLP data capability, and the state of the data connection in the T.120 stack. This field defaults to blank, indicating that the Data Mode for the conference is none.
Gx	“y” = This endpoint has Still Frame Graphics capability.  e = This endpoint does not have Still Frame Graphics capability. The conference retains still frame graphics capability when non-compliant endpoints join the conference.  blank = This endpoint never joined the conference.

4 Maintenance Commands for DEFINITY ONE  
status conference

4-165

Rate Adpt	<p>Rate adaptation/Interworking indicator ( 5, 6, y, c, e, n, blank). 5 and "6" apply to Low Speed/High Speed Interworking. All other values apply to Rate Adaptation.</p> <p>"5" = 56-kbps (Low Speed) endpoint joins a High Speed (128 kbps or above) conference. This endpoint connects with audio only capability but is not a valid video source and destination.</p> <p>"6" = 64-kbps (Low Speed) endpoint joins a High Speed (128 kbps or above) conference. This endpoint connects with audio only capability but is not a valid video source and destination.</p> <p>"y" = Endpoint joins the conference at 64 kbps, but because rate adaptation to 56 kbps is triggered by another endpoint, this endpoint rate adapts to 56 kbps.</p> <p>"c " = The administered conference bandwidth is 64 kbps. This endpoint joins the conference at 56 kbps. The first 56 kbps endpoint that joins 64 kbps rate adaptable conferences triggers rate adaptation (see <code>Join Time</code> below).</p> <p>"n" = Another endpoint triggers a 64-kbps conference to rate adapt to 56 kbps. This endpoint joins the conference at 64 kbps, but encounters problems in rate adapting to 56 kbps. This endpoint may have audio and may be receiving video, but is not a valid video source.</p> <p>"blank" Rate adaptation was not triggered by any endpoint. If this endpoint is in use and connected, it joins the conference at the administered bandwidth.</p>
Bond Mode	BONDing Mode = blank for calls that are unrelated to bonding.
Ts	<p>"t" = The endpoint detects voice energy (talking).</p> <p>"m" = The endpoint indicates to the MCU that it is muted. It is possible for an endpoint to mute, but not send any indication to the MCU. In this situation the MCU does not display a mute indication.</p> <p>"M" = UDD/CRCS Agent interface mutes the endpoint's audio. Both the endpoint and the UCC/CRCS Agent must mute the endpoint audio.</p> <p>"S" = The solo-audio state set by UCC/CRCS Agents mutes the endpoint's audio. While in solo-audio state, new endpoints that join the conference automatically mute.</p> <p>"blank" = Voice energy (talking) is not detected from the endpoint.</p>

Vs

MCU endpoint video state (a, b, B, c, i, r, R, s, S, u, U, v, blank).

Quad-screen conferences = an \* appears before the Vs value indicating that an endpoint belongs to the mixed image. # appears before Vs values indicating that an endpoint is set to be in the mixed image (via administration or UCC/CRCS Agent), but instead, Fill video displays in its place. This occurs when videos of an endpoint that are set in a quadrant cannot be used as a video sources, because the endpoint is not joined to the conference, suppresses its video, or has invalid video for its video source. Up to four endpoints may have an \* or # before the Vs field value.

Quad-screen conferences in VAS mode = Mixed images broadcast to all endpoints.

Quad-screen conferences in presentation mode = Mixed images are return videos to the presenter.

Vs  
(cont'd.)

a = Applies to quad-screen conferences. \*a indicates that an endpoint belongs to the mixed image and is administered to one of the quadrants, but is not currently connected (Fill image displays).

b = Applies to full-screen conferences. This endpoint's video broadcasts to other sites. This conference is in VAS, broadcast, or presentation mode. Quad-screen VAS conferences are prefix with an \* indicating that this endpoint's video belongs to the mixed image. Quad-screen presentation conferences, (b without an asterisk) identify the presenter as the broadcaster.

B = The UCC roll call feature causes the endpoint's video to broadcast to other sites. The UCC roll call feature performs in full-screen mode.

"c" = This endpoint's video broadcasts to other sites. The conference is in chair mode and the chair designates the broadcaster. Chair features perform in full-screen mode.

"i" = The endpoint is not a valid video source. #i represents continuous presence conferences with endpoints that are set in particular quadrants.

"r" = For full-screen conferences, the endpoint's video is the return video to the broadcaster. For continuous presence conference in presentation mode, \*r represents a VAS quadrant that belongs to the mixed image.

"R" = The UCC browse feature causes the endpoint's video to return video to the broadcaster. UCC Browse feature perform in full-screen mode.

"s" = The endpoint suppresses this endpoint's video. For continuous presence conference with fixed quadrant participants, #s represents endpoints that are fixed in a particular quadrant.

Vs  
 (cont'd)

“S” = UCC/CRCS Agent interface suppresses this endpoint’s video. For continuous presence conference with fixed quadrant participants, #S represents endpoints that are fixed in a particular quadrant S displays when both the endpoint and the UCC/CRCS Agent suppress the endpoint video.

“u” = For full-screen conferences, this endpoint’s video broadcasts to other sites. The conference is in VAS mode and the UCC/CRCS Agent interface designates the broadcaster. For quad-screen conferences, UCC/CRCS Agents designate this endpoint as set in a quadrant. An \*u represents endpoints that belong to the quad image, and #U represents disconnected endpoints.

“U” = For quad-screen conferences UCC/CRCS Agents designate quadrants as VAS. \*U indicates that this endpoint belongs to the quad image.

“v” This endpoint’s video broadcasts to other sites. The conference is in VAS mode but the endpoint asks to be a broadcaster with the “See-Me” request and is granted a MCV (Multipoint Command Visualize) token. The See-Me feature performs in full-screen mode.

“blank” = The endpoint’s video is not broadcast, return, video, or part of the mixed-image, but it is a valid video source.

status conference

page 2 of 2

STATUS OF CONFERENCE:

Sum Grp: Group1 Group2 Group3 Group 4  
 L1:  
 L2:

Ext	Join Time	Drop Time	Drop Reason	AC Num	-----Ports-----	Sum	Software
				Trunk	Video	Aud/Esm Grp	
1:							
2:							
3:							
4:							
5:							
6:							

Screen 4-2. status conference: page 2 of 2

**Field descriptions (status conference, page 2)**

Sum Grp	The VD audio Level 1 (L1) and Level 2 (L2) summer group parts for each assigned group (1-4). Summer parts are assigned only for conferences with over 6 participants. When a conference operates at an audio mode of 7 kHz (administered audio mode is 7 kHz, or auto with the bandwidth greater than 128 kbps), the system allocates "primary" and "secondary" L1 and L2 summer parts. Primary and secondary parts are allocated as adjacent port slots on the same board. Status conferences display primary summer ports. Secondary summer ports are one slot higher than displayed primary summer ports.
Join Time	Time (in 24-hour notation) when the channel joins the conference.
Drop Time	Time (in 24-hour notation) when the channel disconnects. If the first channel has a drop time, the endpoint is inactive. If a drop time exists without a join time, the call disconnects without joining the conference.
Drop Reason	Channel's disconnect because:  "2-pri" = Administration errors cause mismatches in primary-secondary designation for cascade linking. This mismatch indicates that both MCUs are administered as primaries (see "Cascading" for a description of primary-secondary compatibility).  "2-sec" = Administration errors cause mismatches in primary-secondary designation for a cascade link. This mismatch indicates that both MCUs are administered as secondaries (see "Cascading" for a description of primary-secondary compatibility).  "Agent" = The reservation agent causes the call to disconnect.  "Bandwidth" = A mismatch occurs between a call and the conference it attempts to join.  "BondHshake" = Information channel parameters are unsupported or invalid, parameter negotiations terminate out of sequence, timers expire because secondary channels do not establish, or BONDing framing is undetected for one of the other channels.  "Busy" = MCU detects that the conferee's terminal equipment is busy. This drop reason is detected by ISDN cause values (for example h0). See "Dial-out" for a description of CPTR usage.  "Chair" = Chair Command Disconnect (CCD) or Chair Command Kill (CCK) signals disconnects the endpoint.  "Conf End" = The conference ends when it reaches the stop time for a reserved conference or an active conference converts to file.

Drop Reason  
(*cont'd*)

Endpoint Clearing received from DS1. The endpoint causes the disconnect. The endpoint notifies the MCU that it intends to disconnect.

Far-end Clearing received from DS1. The network or endpoint cause the disconnect.

“Handshake” = Framing is not located or is lost for over 40 seconds and the endpoint disconnects. (The endpoint cannot complete initialization due to problems with finding Frame Alignment Signal (FAS), Multi Frame Alignment (MFA) and getting a corrected coded cap-set.)

“IDtimeout” = The H.320 sends three unsuccessful responses to the MCU regarding the UIN/password Query. Timeout periods exist for each period.

“Internal” = MCU cannot allocate the necessary trunk resources to route the dial-out call for the specified dial-numbers. This problem can be associated with routing patterns or trunk associated translations, or it can indicate insufficient trunk resources.

“Network” = Clearing received from DS1. The network causes the disconnect. The endpoint with disconnect notification capability disconnects without notifying the MCU.

“Not-MCU” = The dial-out destination number(s) of the “CAS” extension terminates to a number that is not a dial-in cascade MCU extension.

“No-ring” = Calls are up for 30 seconds without ringing.

“Reorder” = The MCU CPTR resources detects that no network trunks are available to place the call. See “Dial-out” for a description of CPTR usage.

4 Maintenance Commands for DEFINITY ONE  
*status conference*

4-170

Drop Reason (cont'd)	<p>“Pre-AnsDrop” = The call disconnects before an endpoint answers. The network, an endpoint, or a terminal adapter may cause the disconnect. This drop reason differs from ‘No-answer,’ which indicates that a 60-second timeout occurs during alerting. In this case, the call drops before the 60-second timer expires. Some busy endpoints connected through terminal adapters display this behavior.</p> <p>“Resource” = MCU cannot provide resources (VC or MMI) when the call arrives or loses the resources during the call. This can occur when they are Out of Service, busied out by craft, or in use by system maintenance. This drop reason can also occur if the DS1/MMI cable disconnects. If a resource problem exists when the call arrives, it gets a reorder (fast busy) and the MCU does not disconnect it.</p> <p>“Password” = The user entered a wrong password or the audio add-on user did not enter it within the specified time period. The audio add-on user has one attempt to enter a correct password and has about 10 seconds between digits (inter-digit timing).</p> <p>“System” = MCU restarts (level 2) disconnect all calls.</p> <p>“UIN-Inv” The user enters an invalid User Identification Number.</p> <p>“Unknown” = The system cannot determine the disconnect cause.</p> <p>“Wrong Num” The MCPTR resources SDN cause value detects an incorrectly-dialed destination number. See “Dial-out” for details.</p> <p>“UCC” = The controller intentionally disconnects the endpoint.</p>
AC Num	Administered Connection Number. (1–128) AC numbers further diagnose problems by combining status conference information with the <b>status administered connection</b> command, and data stored in error and alarm logs.
Ports Trunk	The data endpoint used by the channel.
Ports Video	The MMI port for the channel.
Ports Aud	If the endpoint type is not “UCC,” the VC audio encoder port (which is always paired to a decoder port) for the channel (only the first channel). appears together with the ESM data port in the endpoint’s channel 1 port slot position of the <code>Port Aud/ESM</code> column. For “UCC” endpoints, channel 1 port slot positions display allocated Call Classifier resources.
Ports ESM	Expansion Service Module MMI data port. This field defaults to blank.
Sum Grp	Endpoint’s assigned summer group number. The summer group port assignments are on screen 1.
software	For Lucent Technologies use only.



In Use	<p>Is the endpoint participating in the conference or connecting to the conference? - y, c, e, f, n, blank.</p> <p>“y” = The endpoint is in use and fully-connected on all media in an active conference.</p> <p>“c” = The endpoint is in use and fully-connected; however, the endpoint changes the conference audio or video capability, or the rate of the conference due to rate adaptation. This condition requires analysis of this endpoint’s capabilities and mode fields to identify the reduced capability.</p> <p>“e” = The endpoint active, but has capability problems. The endpoint lacks one of the required capabilities (Vid, Bhl, MLP) to be a full participant. For MLP capabilities, see the “T120” field. This condition requires analysis of this endpoint’s capabilities and mode field to identify the missing capability.</p> <p>“f” = The endpoint is active, but is not connected to all media. The endpoint declared all required capabilities (channel/video/audio/data) but is not fully-connected to all conference media. This endpoint may be connecting, failed to connect, or is not a valid video source. This condition requires analysis of this endpoint’s capabilities and mode fields to identify the problem.</p> <p>“n” = The endpoint connects then disconnects in a conference, or unsuccessfully attempts to connect to a conference.</p> <p>“blank” = Blank until the first call is made from or to the endpoint.</p>
Enh BAS	<p>Enhanced Basic Service Flag - n, y</p> <p>“y” = The endpoint supports the enhanced BAS commands/caps; “n” = The endpoint supports the basic BAS commands/caps.</p>
Ch1	<p>Data on the quantify and quality of channels (transfer rate)? - y, e, n, blank</p> <p>“y” = The endpoint has the required number of channels.</p> <p>“e” = The endpoint does not declare support for the correct number of channels and cannot participate fully in the conference.</p> <p>“n” = The endpoint declares the correct number of channels, but not all channels join the conference, due to network or endpoint problems.</p> <p>“blank” = Audio add-on endpoints set the Ch1 field to blank.</p>

Aud	<p>Does it have the required audio capability? - <i>y</i>, <i>c</i>, <i>e</i>, <i>blank</i></p> <p>“<i>y</i>” = The endpoint has the required audio capability. Audio add-on endpoints set the Aud field <i>y</i> when the endpoint joins the conference.</p> <p>“<i>c</i>” = This PCM-only endpoint changes conference video quality by changing the operating audio from G.728 to G.711. If the administered audio mode is auto and the administered bandwidth is 112 kbps (56 k/channel) or 128 kbps (64 k/channel), the system begins with the highest common audio, G.728. When the administered bandwidth is greater than 128 kbps, the system begins with the highest common bandwidth, 7 kHz.</p> <p>“<i>e</i>” = A PCM-only endpoint that could not support the administered audio mode, G.728 (such as a data conference), or G. 278/G.711 endpoint that could not support the administered audio mode, 7 kHz. Such endpoints operate with PCM audio and interwork with operating audio modes.</p> <p>“<i>blank</i>” = Blank until the first call is made from or to the endpoint.</p>
Vid	<p>Does it have required video capability and is it receiving video? - <i>y</i>, <i>c</i>, <i>e</i>, <i>n</i>, <i>blank</i></p> <p>“<i>y</i>” = The endpoint has the required video capability and receives video if the Chl, Aud, and Dat fields are <i>y</i>.</p> <p>“<i>c</i>” = The endpoint downgrades the conference’s video quality from CIF to ACIF, or by decreasing the frame rate. The conference video mode defaults to CIF, and if a QCIF-only endpoint joins the conference, the entire conference operates in QCIF, with downgraded video clarity. The conference frame rate is initially set to the highest frame rate that can be reduced by any endpoint. If the conference video mode is not administered with upgrade capability, the video parameters for a conference downgrade. They do not upgraded until all endpoints disconnect from the conference.</p> <p>“<i>e</i>” = The endpoint does not declare video capability in its cap-set.</p> <p>“<i>n</i>” = Audio only, not receiving video, due to an audio or data problem.</p> <p>“<i>blank</i>” = Audio add-on endpoints set the Vid field to <i>blank</i>.</p>
MLP	<p>The relationship between the Control Link and the ESM (T.120 stack terminator), the endpoint MLP data capability, and the state of the data connection in the T.120 stack. This field defaults to <i>blank</i>, indicating that the Data Mode for the conference is <i>none</i>.</p>
Gx	<p>“<i>y</i>” This endpoint has Still Frame Graphics capability.</p> <p>“<i>e</i>” = This endpoint did not have Still Frame Graphics capability. The conference retains still frame graphics capability when a non-compliant endpoint joins the conference.</p> <p>“<i>blank</i>” = This endpoint never joins the conference.</p>

4 Maintenance Commands for DEFINITY ONE  
*status conference*

4-174

Rate Adpt	<p>Rate adaptation/Interworking indicator = 5, 6, y, c, e, n, blank. 5 and 6 apply to Low Speed/High Speed Interworking. All other values apply to Rate Adaptation.</p> <p>“5” = 56-kbps (Low Speed) endpoints join High Speed (128 kbps or above) conferences. This endpoint connects with audio only capability, but is not a valid video source and destination.</p> <p>“6” = 64-kbps (Low Speed) endpoints join High Speed (128 kbps or above) conferences. This endpoint connects with audio only capability, but is not a valid video source and destination.</p> <p>“y” = This endpoint joins the conference at 64 kbps, but because another endpoint triggers rate adaptation to 56 kbps, this endpoint rate adapts to 56 kbps.</p> <p>“c” = 64 kbps endpoints join the conference at 56 kbps. The first 56 kbps endpoint that joins 64 kbps rate adaptable conferences triggers rate adaptation (see <i>Join Time</i> below).</p> <p>“n” = Another endpoint triggers a 64-kbps conferences to rate adapt to 56 kbps. This endpoint joins the conference at 64 kbps, but encounters problems with rate adapting to 56 kbps. This endpoint may have audio and may be receiving video, but is not a valid video source.</p> <p>“blank” = No endpoint triggers rate adaptation. If this endpoint is active, it joins the conference at the administered bandwidth.</p>
Bond Mode	<p>BONDing Mode - blank. This field is blank for calls that are not related to bonding.</p>
Ts	<p>The talking state of the endpoint - t, m, M, S, blank.</p> <p>“t” = The endpoint detects voice energy (talking).</p> <p>“m” = The endpoint indicates that it is muted to the MCU. Endpoints may mute, but not send an indication to the MCU.</p> <p>“M” = UDD/CRCS Agent interface mutes the endpoint’s audio. M displays when both the endpoint and the UCC/CRCS Agent mute the endpoint audio.</p> <p>“S” = the solo-audio state set by UCC/CRCS Agent mutes the endpoint’s audio. While in solo-audio state, new endpoints joining the conference automatically mute.</p> <p>“blank” = The endpoint does not detect voice energy (talking).</p>

Vs

The MCU video state for this endpoint. a, b, B, c, i, r, R, s, S, u, U, v, blank.

Quad-screen conferences = \* appears before V values indicating that an endpoint belongs to the mixed image. A # appears before the V values indicating that an endpoint belongs to the mixed image (by administration or UCC/CRCS Agent). Instead, a `Fill` video displays in its place. This occurs when an endpoint's video that is set in a quadrant cannot be used as a video source because the endpoint is not connected to the conference, suppresses its video, or has invalid video for its video source. Up to four endpoints have an \* or # before the Vs field value.

Quad-screen conference in VAS mode = The mixed image broadcasts to all endpoints. For quad-screen conference in presentation mode, the mixed image is return video to the presenter.

"a" = This value applies to quad-screen conferences. \*a indicates that an endpoint belongs to the current mixed image and is administered to one of the quadrants. \*<sub>a</sub> indicates that the endpoint is fixed in a quadrant, but is not currently connected (Fill image displays).

"b" = For full-screen conferences, this endpoint's video broadcasts to other sites. This conference is in VAS, broadcast, or presentation mode. For quad-screen VAS conference are prefixed an asterisk indicating that this endpoint's video is part of the mixed image because of VAS. For quad-screen presentation conferences, b identifies the presenter as the broadcaster.

"B" = The UCC roll call feature causes the endpoint's video to broadcast to other sites. The UCC roll call feature performs in full-screen mode.

"c" = This endpoint's video broadcasts to other sites. The conference was in chair mode and the chair designates the broadcaster. Chair features perform in full-screen mode.

Vs  
(cont'd.)

“i” = The endpoint is not a valid video source. For continuous presence conference, #i represents endpoints that are fixed in a particular quadrant.

“r” For full-screen conferences, the endpoint’s video is the return video to the broadcaster. For continuous presence conferences in presentation mode, \*r represents a VAS quadrant that is part of the mixed image.

“R” = The UCC browse feature causes the endpoint’s video to be the return video to the broadcaster. UCC Browse feature performs in full-screen mode.

“s” = The endpoint suppresses its video. For continuous presence conferences with fixed quadrant participants, #s represents an endpoint that is fixed in a particular quadrant.

“S” = UCC/CRCS Agent interface suppresses the endpoint’s video. For continuous presence conference with fixed quadrant participants, #s represents an endpoint that is fixed in a particular quadrant. s displays when both the endpoint and the UCC/CRCS Agent suppress the endpoint video.

“u” = For full-screen conferences, this endpoint’s video broadcasts to other sites. The conference is in VAS mode and the UCC/CRCS Agent interface designates the broadcaster. For quad-screen conferences, the UCC/CRCS Agent designates this endpoint as fixed in a quadrant. \*u represents an endpoint that is part of the quad image, and #u represents a disconnected endpoint.

“U” = For quad-screen conferences, UCC/CRCS Agents designate a quadrant as VAS. \*U indicates that this endpoint is part of the current quad image.

“v” = This endpoint’s video broadcasts to other sites. The conference was in VAS mode, but the endpoint asks to be a broadcaster with the “See-Me” request and is granted a MCV (Multipoint Command Visualize) token. The See-Me feature performs in full-screen mode.

“blank” = The endpoint’s video is not broadcast, return, video, or part of the mixed-image, but it is a valid video source.

## Page 2 - Endpoint Channel Information

This section describes fields specific to endpoint-level command output.

```

status conference endpoint                                     page 2 of 6

                                ENDPOINT CHANNEL INFORMATION

Chan. Join  Drop  ----Drop----  AC  -----Ports-----  Fr
No.   Time  Time  Reason  Code  Num Trunk  Video  Aud/ESM  BONDng  Err  Software
1:    _____  _____  _____  _____  _____  _____  _____  _____  _____  _____  _____
2:    _____  _____  _____  _____  _____  _____  _____  _____  _____  _____  _____
3:    _____  _____  _____  _____  _____  _____  _____  _____  _____  _____  _____
4:    _____  _____  _____  _____  _____  _____  _____  _____  _____  _____  _____
5:    _____  _____  _____  _____  _____  _____  _____  _____  _____  _____  _____
6:    _____  _____  _____  _____  _____  _____  _____  _____  _____  _____  _____
7:    _____  _____  _____  _____  _____  _____  _____  _____  _____  _____  _____
8:    _____  _____  _____  _____  _____  _____  _____  _____  _____  _____  _____
9:    _____  _____  _____  _____  _____  _____  _____  _____  _____  _____  _____
10:   _____  _____  _____  _____  _____  _____  _____  _____  _____  _____  _____
11:   _____  _____  _____  _____  _____  _____  _____  _____  _____  _____  _____
12:   _____  _____  _____  _____  _____  _____  _____  _____  _____  _____  _____

Help line
enter command:
    
```

Screen 4-4. Page 2 of 6: status conference x endpoint y

### Field descriptions

- Join Time            Time (in 24-hour notation) when the channel joins the conference.
- Drop Time            Time (in 24-hour notation) when the channel disconnects. If the first channel has a drop time, the endpoint is inactive. If a drop time occurs without a join time, the call disconnects without joining the conference.

Drop Reason

Channels disconnect because:

“2-pri” = Administration errors cause mismatches in primary-secondary designations for cascade links. This mismatch indicates that both MCUs are administered as primaries (see “Cascading” for a description of primary-secondary compatibility).

“2-sec” = Administration errors cause mismatches in primary-secondary designations for cascade links. This mismatch shows that both MCUs are administered as secondaries (see “Cascading” for a description of primary-secondary compatibility).

“Agent” = Reservation agents cause calls to disconnect (for example, agents change connected dial-out destination numbers).

“Bandwidth” = Mismatches occur when bandwidths of calls and the conferences they attempt to join are inconsistent.

“BondHshake” = Unsupported Information channel parameters or invalid, parameter negotiations that terminate out of sequence, timers that expire because secondary channels do not establish, or BONDing framing that goes undetected for another channels.

“Busy” = The MCU detects that the conferee’s terminal equipment is busy. An ISDN cause value detects this drop reason (for example h0). See “Dial-out” for a description of CPTR usage.

“Chair” = Chair Command Disconnect (CCD) or Chair Command Kill (CCK) signals disconnect the endpoint.

“Conf End” = The conference ends when the stop time is reached for a reserved conference or an active conference converts to file.

Drop Reason  
(cont'd)

“Endpoint” = Clearing received from DS1. The endpoint initiates the disconnect. The endpoint notifies the MCU that it intends to disconnect.

“Far-end” = Clearing received from DS1. The network or endpoint initiate the disconnect.

“Handshake” = Framing is never found or is lost for over 40 seconds and the endpoint is disconnected. (the endpoint could not complete initialization due to problems with finding Frame Alignment Signal (FAS), Multi Frame Alignment (MFA) and corrected coded cap-sets)

“IDtimeout” = The H3.20 user unsuccessfully (three times) sends MCU responses regarding the UIN/password Query. Each timeout period is administered.

“Internal” = MCU has a problem allocating the necessary trunk resources to route dial-out calls for specified dial-numbers. This problem is associated with routing patterns or trunk-associated translation (for example, TAC specified in the dial-out number or routing pattern points to a trunk group without members), or indicates a lack of trunk resources (for example, all trunk members are maintenance busy or all in-service members are busy on a call).

“Network” = Clearing received from DS1. The disconnects the endpoint. The endpoint with the disconnect notification capability disconnects without notifying the MCU.

“Not-MCU” = The dial-out destination numbers of the “CAS” extensions terminate to numbers that are not dial-in cascade MCU extensions.

“No-ring” = The is up for 30 seconds and no ringing is detected.

“Reorder” The MCU CPTR resources detect that no network trunks are available to place the call. See “Dial-out” for a description of CPTR usage.

Drop Reason <i>(cont'd)</i>	<p>“Pre-AnsDrop” = The call disconnects an endpoint answers. The network, an endpoint, or a terminal adapter may cause the disconnect. This drop reason differs from ‘No-answer,’ which indicates that a 60-second timeout occurs during alerting. In this case, the call drops before the 60-second timer expires. Some busy endpoints that are connected through terminal adapters display this behavior.</p> <p>“Resource” = MCU cannot provide resources (VC or MMI) when calls arrive or lose their resources during the call. Calls can lose resources when they are Out of Service, busied out by craft, or in use by system maintenance. If the DS1/MMI cable is disconnected, this drop reason can also occur. If a resource problem exists when the call arrives, it gets reorder (fast busy) and is not disconnected by the MCU.</p> <p>“Password” = The user enters a wrong password or the audio add-on user does not enter it within the specified time period. The audio add-on user gets one attempt to enter a correct password and has about 10 seconds between digits (inter-digit timing).</p> <p>“System” = MCU restarts (level 2) disconnect all calls.</p> <p>“UIN-Inv” = Users enter invalid User Identification Numbers.</p> <p>“Unknown” = The system cannot determine the disconnect cause.</p> <p>“Wrong-num” = The MCU CPTR resources SDN cause values detect an incorrectly-dialed destination number. See “Dial-out” for details.</p> <p>“UCC” = The controller intentionally disconnects the endpoint.</p>
Drop Code	A detail code complementing the Drop Reason. Additional bonding-related information is available from the supplementary BONDing Drop Codes described above.
AC Num	Administered Connection Numbers. (1–128) AC numbers can further diagnose problems by combining status conference information with the <b>status administered connection</b> command, and data stored in the error and alarm logs.
Ports Trunk	The data endpoint that the channel is using.
Ports Video	The MMI port for the channel.
Ports Aud	If the endpoint type is not “UCC,” the VC audio encoder port (which is always paired to a decoder port) for the channel (only the first channel). appears together with the ESM data port in the endpoint’s channel 1 port slot position of the Port Aud/ESM column. For “UCC” endpoints, the channel 1 port slot position displays allocated Call Classifier resources.
Ports ESM	Expansion Service Module MMI data port. This field is always blank.
Ports BONDng	The MMI port used for channel BONDing.
Fr Err	Frame error counter. A circular hex counter (0-FF) to indicates framing error occurrences.

### Page 3 - Conference Information

This section describes fields that are specific to endpoint-level command output.

```

status conference endpoint                                     page 3 of 6

CONFERENCE INFO:  Broadcaster: xx (See-Me)
                   Return Vid: xx

----- MODE COMMANDS/COMMUNICATION MODES -----
  CMD  STAT   CONF          EPT-IN      EPT-OUT      EPT MISC      FAW  --
                   |                   |                   |----- I O   | CH1 CH2
                   |                   |                   |----- y n   | -----
XRATE: y   384          384          384          VIS y n       A-OUT: y n
AUDIO: n   G728        neutral        G728          MIS: n n      A-IN: y n
56/64: y   derestrict  derestrict  derestrict    MCV: n n      M-FRM: y n
VIDEO: n   H.261        H.261        H.261          |-----|      MFA: y n
MLP: y     MLP-off     MLP-off     MLP-off        TALK: y 05    MFN: y n
H-MLP: y   H-MLP-off   H-MLP-off   H-MLP-off     VFCV: y 01    FAS: y n
LSD: y     LSD-off     LSD-off     LSD-off        BCTK: n 02    MCFAL: 00 00
HSD: y     HSD-off     HSD-off     HSD-off        RTTK: y 01    FEFAL: 00 00
CRYPT: y   encrypt-off  encrypt-off  encrypt-off    BCLS: n
S/M: y     N-comp-6B-H0  N-comp-6B-H0  N-comp-6B-H0  RTLS: n
                                           HYPR: n 00
                                           DMUTE: n 00
                                           H.261: n 00
                                           VFMT: n 00

Help line
enter command:
    
```

Screen 4-5. Page 3 of 6: status conference x endpoint y

**Conference Info.** This information primarily applies to full-screen conferences. The Broadcaster field applies to quad-screen presentation mode conferences.

### Field descriptions

- Broadcaster** The current broadcaster endpoint number. The following keywords qualify the broadcaster:
- “Broadcast” = A broadcast mode broadcaster.
  - “Chair” = The chair designates the broadcaster.
  - “See-Me” = The endpoint initiates a MCV broadcaster request.
  - “Presenter” = A presentation mode broadcaster.
  - “Rollcall” = The UCC designates the broadcaster by the Rollcall feature.
  - “UCC” = The UCC designates the broadcaster.
  - “VAS” = A Voice Activated Switching broadcaster.

#### 4 Maintenance Commands for DEFINITY ONE

*status conference*

4-182

Next Broadcaster	The endpoint number that is selected to be the next broadcaster.
Return Vid	The endpoint number that is the current return video. The return video is qualified with the following keywords:  “blank” = VAS, Chair action, UCC action, or endpoint MCV requests force the previous broadcaster to be the return video. The broadcaster qualifier identifies the action that forced this endpoint to become return video.  “Autoscan” = Auto scan return video, when conference mode broadcasts with auto scan.  “Browse” = The UCC designates the return video with the Browse feature.  “VAS” = A Voice Activated Switching return video.
Next Return Vid	Indicates the endpoint number selected to be the next return video.

**Mode Commands/Communication Modes.** This is a collection of incoming and outgoing bandwidth allocations for the multiplex. The Incoming data is the rate at which the MCU thinks the endpoint is communicating based on the Bit-rate Allocation Signal (BAS) codes received from the endpoint/codec and the capabilities the MCU has declared. The Outgoing data is the rate from the MCU toward the endpoint. The following are column definitions for this section of page 3.

### Field descriptions

CONF	The desired conference operating mode. This may differ from the endpoint in (EPT-IN) or endpoint out (EPT-OUT) modes.
CMD	Labels for the various types of mode commands
STAT	Conference and incoming mode compatibility. “y” = mode compatibility “n” = modes incompatibility.
EPT-IN	defines the communication modes coming in from an endpoint.
EPT-OUT	Defines the communication modes sent to an endpoint based on the number of connected channels and the endpoint’s capabilities.

The following are field definitions for the Mode Commands/Communication Modes section of Page 3.

XRATE One of the supported rates in [Table 4-2](#):

**Table 4-2. Supported Transfer Rates s**

XRATE	Bandwidth of the Call
2x64	2B (2x56 or 2x64)
128	112kbps or 128kbps
196	168kbps or 196kbps
256	224kbps or 256kbps
320	280kbps or 320kbps
384	336kbps or 384kbps
512	512kbps
768	768kbps
1472	1472kbps
1536	1536kbps'
1920	1920kbps

XRATE XRATE may be 64 when the endpoint dials in, or in the event that problems occur. It implies that only one B channel is in use.

AUDIO Conference and endpoint Audio rates (kbps bandwidth) must be the same. Their modes are not necessarily the same. When the audio rate of the conference and the endpoint differ, the endpoint's audio interworks, but the endpoint's video is invalid. MCU may or may not send video to such an endpoint.

[Table 4-3](#) summarizes expected endpoint audio modes with different transfer rate configurations, facility bandwidths, and conference modes. It includes endpoints that support the highest common audio mode (HC audio) when the administered mode is `auto`. The highest common conference mode depends on the administered bandwidth. A '-' in the table indicates 'does not apply.'

Table 4-3. Audio Mode Configurations

Admin Mode (HC Audio)	All Support HC Audio	Xfer Rate	Facility BW	Conf Mode	Expected Endpoint Mode
auto (G.728)	yes	<=128k	-	G.728	G.728
auto (G.728)	no	<=128k	64k	G.711-A-56k	G.711-A-56k B.711-Mu-56k
auto (G.728)	no	<=128k	56k	G.711-A-48k	G.711-A-48k G.711-MU-48k
auto (G.722)	-	>128k	64k	G.722-56k	G.722-56k G.711-A-56k G.711-Mu-56k
auto (G.722)	-	>128k	56k	G.722-48k	G.722-48k G.711-A-48k G.711-Mu-48k
G.728	-	-		G.728	G.728
G.711	-	-	64k	G.711-A-56k	G.711-A-56k G.711-Mu-56k
G.711	-	-	56k	G.711-A-48k	G.711-A-48k G.711-Mu-48k
G.722	-	-	64k	G.722-56k	G.722-56k G.711-A-56k G.711-mu-56k
G.722	-	-	56k	G.722-48k	G.722-48k G.711-A-48k G.711-Mu-48k

AUDIO  
(cont'd.)

Other possible AUDIO mode values include `neutral` (neutralized I-channel), `Au-off`, and `Frm` (no audio signal) which never match conference modes and are unsupported by MCU.

## 56/64

The `56/64` field derestricts when operating at 64kbps, 128kbps, 192kbps, 256kbps, 320kbps, 384kbps, 512kbps, 768 kbps, 1472kbps, 1536kbps, or 1920kbps per channel speeds; it `restricts` when operating at 56kbps, 112kbps, 168kbps, 224kbps, 280kbps, 336kbps, 448kbps, and 672kbps per channel speeds.

If technicians configure the conference for Nx56kbs operations, endpoint may signal by capabilities or modes that operate at the proper rate. In such a case, when technicians receive `derestrict` commands while they are in the `restrict` mode, that do not match conference communication modes, (MISC capability has `restrict` displayed on Page 4) the `STAT 56/64` is `y` indicating 56/64 compatibility between the conference and the endpoint.

## VIDEO

The Video mode: `H.261` (recommended), `H.CTX` (proprietary), `H.CTX+` (proprietary), or `SG4` (proprietary) indicate that video is on in the direction indicated; and `video-off` when the video is off.

#### 4 Maintenance Commands for DEFINITY ONE

*status conference*

4-185

MLP	<p>Multi Layer Protocol data mode. When technicians administer Data Modes as <code>any-mlp</code> or <code>ww-pcs</code>, MLP modes should be <code>var-MLP</code>. Other values affect video status.</p> <p>MLP modes should be <code>MLP-off</code> when technicians administer Data Modes as <code>none</code>. Other values in this mode affect video status.</p>
H_MLP	<p>The High Speed MLP mode. The HMLP mode should be <code>H-MLP-off</code>. Other values in this mode will affect video status.</p>
LSD	<p>Low Speed Data mode. The LSD mode should be <code>LSD-off</code>. Other values in this mode affect video status.</p>
HSD	<p>High Speed Data mode. The HSD mode should be <code>HSD-off</code>. Other values in this mode affect video status.</p>
CRYPT	<p>Encryption mode. The CRYPT mode should be <code>encrypt-off</code>. Other values in this mode affect video status.</p>
S/M	<p>Single/Multi channel interoperability mode. <code>6B-H0-comp</code> indicates that the sender is interoperating multiple channels and a single channel (for example, 6B and H0). <code>Not-comp-6B-H0</code> indicates that the sender is not interoperating between 6B and H0. Normally this value is <code>Not-comp-6B-H0</code>. Other values in this mode affect video status.</p>

**Endpoint Miscellaneous (EPT MISC) Information.** EPT MISC contains miscellaneous states and counters for an endpoint. Flags can `y` or `n`. Counters start with 0x00, increment to 0xff, and wrap around to 0x01. `AIM` and `VIS` are BAS commands that can be sent as input to MCU from an endpoint or as output from MCU to an endpoint

### Field descriptions

AIM	<p>Audio Indicate Mutes.</p> <p>“y” = For input, this endpoint mutes its audio. MCU does not VAS to an endpoint displaying mute. For output, all other endpoints in the conference mute their audio (have sent AIM to MCU). MCU in turn tells this endpoint (by sending it AIM) that there is no audio output from MCU.</p> <p>“n” = For input, this endpoint does not mute (only if endpoint audio mode is turned on). For output, an audio path opens across the bridge.</p>
VIS	<p>Video Indicate Suppressed.</p> <p>“y” = For input, this endpoint suppresses its video (video is muted). For output, the MCU is not sending video to this endpoint because there is no video broadcaster (broadcaster does not join or broadcaster’s video is invalid).</p>

4 Maintenance Commands for DEFINITY ONE  
*status conference*

4-186

MIS	<p>Multipoint Indicate Secondary-status.</p> <p>“n” = For output, the endpoint is a valid source (not necessarily at this moment). n is the correct state for the video.</p> <p>“y” = MIS was sent to an endpoint considered to be a secondary endpoint. The endpoint is included in the audio, but not video portion of the conference. Video is not sent.</p>
MCV	<p>Multipoint Command Visualize.</p> <p>“y” = For input, an endpoint requests to become a broadcaster. This is used during Still Frame Graphics and to force “presentation” mode.</p>
TALK	<p>“y” = The VC board detects voice energy from the endpoint. The TALK counter indicates the number of starts or stops.</p>
VRCV	<p>“y” = The endpoint is receiving video (MCU is sending video to the endpoint). The VRCV counter counts the number of times video sends or does not send to this endpoint.</p>
BCTK	<p>Single screen and quad-screen presentation mode conferences.</p> <p>“y” = The endpoint is the video broadcast source. The BCTK counter tallies the number of times this endpoint is the video broadcast source.</p>
RTTK	<p>Single screen conferences.</p> <p>“y” = The endpoint is the return video source. The RTTK counter tallies the number of times this endpoint is the return video source.</p>
BCLS	<p>Single and quad-screen presentation mode conferences.</p> <p>“y” = The endpoint is watching the video of the broadcast source.</p>
RTLS	<p>Single screen conferences.</p> <p>“y” = The endpoint is watching the video of the return source.</p>
HYPR	<p>“y” = Endpoint hyperactivity (MCU isolates endpoints from the MMCH conference due to “thrashing” behavior) affects the endpoint’s status as a video source (for 5 seconds of hyperactivity timer). The HYPR counter tallies the number of times this endpoint is hyperactive.</p>
DMUTE	<p>“y” = The VC board or the software in the MCU mute the decoder. VC boards mutes the decoder when it loses MMI or endpoint framing, when it receives invalid audio code words, and when endpoints are hyperactive. MCU software mutes the endpoint decoder of all endpoints besides the broadcaster. (when a mode of a conference is “broadcastw/scan”, broadcast with auto scan) The DMUTE counter tallies the number of times the VC board mutes this endpoint’s decoder.</p>
VFMT	<p>Quad-screen conferences. This field always defaults to n, indicating QCIF format.</p>
H.261	<p>“y” = Video framing loss. The H.261 counter tallies the number of times framing is lost.</p>

**Frame Alignment Word (FAW) Information.** The FAW section of page 3 provides channel Frame Alignment Word information for the communication paths labeled CHL 1 and 2. For 2B calls, both CHL 1 and 2 are used. For 1-channel calls (112, kbps, 128 kbps, 168 kbps, 196 kbps, 224 kbps, 256 kbps, 280 kbps, 320 kbps, 336 kbps, 384 kbps, 768 kbps, 1472 kbps, 1536 kbps, and 1920 kbps) only CHL 1 is used. A-OUT, A-IN, M-FRM, MFA, and MFN are flags with *y* or *n*.

## Field descriptions

A-OUT	MCU has endpoint framing.
A-IN	Endpoint has MCU framing
M-FRM	Multichannel frame alignment of both channels in 2B is present.
MFA	Multiframe alignment word is present (required in 2B call).
MFN	Multiframe numbering is present (required in 2B call).
FAS	Frame Alignment Signal (FAS) channel number (1 or 2). This number should match the column header.
MCUFAL	MCU Frame Alignment Loss (MCUFAL). Counts the number of times the MCU reports lost endpoint FAW or multichannel synchronization (M-FRM) to the endpoint. The MCU a-bit toggles when the MCU gains or loses endpoint multichannel synchronization. This counter starts with 0x00, increments to 0xff, then wraps around to 0x01. The MCUFAL count also displays in the <code>Fr Err</code> field on Page 2
FEFAL	Far End Frame Alignment Loss (FEFAL). Counts of the number of changes the MCU detects in the endpoint's a-bit (A-OUT). The endpoint a-bit toggles when an endpoint gains or loses MCU framing. This counter starts with 0x00, increments to 0xff, then wraps around to 0x01.

### Page 4 - Endpoint Capability Information

This section describes fields specific to endpoint-level command output.

```

status conference endpoint                                     page 4 of 6
                                ENDPOINT CAPABILITY INFORMATION
-----
VID | vfmt: QCIF   cmpi: 30      H.CTX   SG4   imp
    | da_sfg      qmpi: 7.5    H.CTX+  SG4_sfg
-----
MISC | derestrict  S/M  mbe  dcomp   cic
-----
XR  | 64 64x2 64x3 64x4 64x5 64x6      384 384x2 384x3 384x4 384x5
    | 128 192 256 320 512 768 1152 1472 1536 1920
-----
AUD | ntrl      711m 711a g728 g722_64 g722_48
-----
LSD | var 300 1200 4800 6400 8000 9600 14.4k 16k 24k 32k 40k 48k 56k 62.4k 64k
-----
HSD | var 64k 128k 192k 256k 320k 348k 512k 768k 1152k 1536k
-----
MLP | var 4k 6.4k 14.4k 16k 22.4k 24k 30.4k 32k 38.4k 40k 46.4k 62.4k
-----
HMLP | var 62.4k 68k 128k 192k 256k 320k 384k
-----

```

Screen 4-6. Page 4 of 6: status conference x endpoint y

**Endpoint Capability Information.** Fields on this page display if an endpoint declares specific capability. For example, if an endpoint does not declare VID H.CTX capability, the H.CTX field does not display.

## Field descriptions

VID	<p>Video and frame rate types that the endpoint supports.</p> <p>“vfmt” = Does not display if the endpoint has no video capability. All values are blank if an active call or audio-only endpoint exists. Otherwise, values for this field include:</p> <ul style="list-style-type: none"><li>■ FCIF for full CIF</li><li>■ QCIF for quarter CIF. CIF support implies QCIF support. For larger screens, CIF typically displays sharper resolution video, ZCIF is blocked, but may run at higher frame rates with less clarity. Differences are less observable on very small displays.</li><li>■ cfps and qfps are maximum frame rates (frames/second) that the endpoint can receive video for CIF and QCIF operating modes. CIF frame rate values are 30fps, 15fps, 10fps, and 7.4fps. If the endpoint does not support CIF (that is, the vfmt field is QCIF), the cfps value should be blank.</li><li>■ da_sfg indicates support for H.261 Still Frame Graphics transfers.</li><li>■ H. CTX, H. CTX+ and SG4 are proprietary video format capabilities.</li><li>■ SG4_sfg indicates support for SG4 Still Frame Graphics</li></ul>
MISC	<p>The restrict field and the 56/64 command mode with a restrict value indicate that endpoints operate at 56 kbps per channel. Endpoints on 56 kbps conferences must send one or both 2 indications that they are operating at 56 kbps before they become a video source in a 56 kbps conference. If they signal that they are operating at 56 kbps in a 64 kbps or 384 kbps conference, they become an audio-only source, but the MCU continues to send Selected Communication Mode (SCM) toward them when possible.</p> <p>A MISC capability of derestrict and a 56/64 command of derestrict together indicate that an endpoint operates at 64 kbps. If either is restrict, the conference operates at 56 kbps. Other field values include:</p> <ul style="list-style-type: none"><li>■ dcomp indicates support for WorldWorx PCS data compliance.</li><li>■ mbe indicates support for Multi Byte Extension. MBE exchanges passwords, terminal names, and other special capabilities, such as, WorldWorx PCS specific features support.</li><li>■ cic (Chair Indicate Capability) indicates chair control capability.</li></ul>

XR	<p>Transfer rate capabilities. Endpoint speeds over current connections and Px64 Multiplexes.</p> <p>For 384 kbps (H0) calls, endpoints indicate 384 kbps support, that displays as 384. On 336 kbps calls, endpoints must signal 384 kbps support. If an endpoint does not indicate support for 384 kbps on a 384/336 kbps conference, the MCU provides Audio Only Communications Mode (ACOM). For a 2B conference, the MCU sets the rate to 2x64, expecting the endpoints to do likewise (64x2 displays; if this is not displayed, no 64x2 capability exists). Endpoints may remove 2x64 (or the current channel rate: 384, 768, 1472, 1536) from their capability. This is Mode 0 forcing and is a normal procedure. The MCU provides AOCM if the endpoint does not signal support that matches the conference configuration.</p>
AUD	<p>Audio. Audio protocols that the endpoint supports. 711m and 711a are PCM (G.711) and support Mu and A-law, respectively. Endpoints require at least one. The g728 field indicates if G.728 is supported (LB_CELP). This value depends upon the endpoint type and configuration. The g722_48 field indicates endpoint support for G.722 (7 kHz) at both 48 kbps and 56 kbps. The g722_64 field indicates endpoint support for G.722 at 64 kbps in an unframed (unsupported by the MCU) mode.</p>
LSD	<p>Low Speed Data conferencing capabilities.</p>
HSD	<p>High speed Data conferencing capabilities.</p>
MLP	<p>Multi Layer Protocol Data capabilities.</p>
HMLP	<p>High Speed MLP data conferencing capabilities.</p>

### Page 5 - Endpoint Call Status Information

This page summarizes call-related status for per-channel join counts, join/drop times, drop reasons, drop codes, and auxiliary bonding drop codes. In addition, it contains drop codes and software fields from the previous call. The data on the page is retained. The Endpoint Call Status Information section groups all call-related fields. The only new field in this section is Join Count; all other fields are described in [Screen 4-3](#) and [Screen 4-4](#).

```

status conference endpoint                                     page 5 of 6

                                ENDPOINT CALL STATUS INFORMATION

Chan  Join   Join   Drop   ----- Drop   -----   --- Previous  -----
      Count  Time   Time   Reason          Code     BondCode   DropCode   Software
1:    ___    ___    ___    _____    ___    ___    ___    _____
2:    ___    ___    ___    _____    ___    ___    ___    _____
3:    ___    ___    ___    _____    ___    ___    ___    _____
4:    ___    ___    ___    _____    ___    ___    ___    _____
5:    ___    ___    ___    _____    ___    ___    ___    _____
6:    ___    ___    ___    _____    ___    ___    ___    _____
7:    ___    ___    ___    _____    ___    ___    ___    _____
8:    ___    ___    ___    _____    ___    ___    ___    _____
9:    ___    ___    ___    _____    ___    ___    ___    _____
10:   ___    ___    ___    _____    ___    ___    ___    _____
11:   ___    ___    ___    _____    ___    ___    ___    _____
12:   ___    ___    ___    _____    ___    ___    ___    _____
    
```

Screen 4-7. Page 5 of 6: status conference x endpoint y

### Field descriptions

**Join Count** Tallies the number of times this endpoint joins this conference during this session. This counter starts with 0, increments to 64, and wraps around back to 1.

### Page 6 - Administered Connections

This page summarizes information for administered connections associated with this endpoint. This data can be viewed while the conference is active.

status conference endpoint				page 6 of 6	
ADMINISTERED CONNECTIONS INFORMATION					
AC				Retry	Failure
Chan Num	Dial-out Number	Connection State		Count	Cause
1:	_____	_____		__	__
2:	_____	_____		__	__
3:	_____	_____		__	__
4:	_____	_____		__	__
5:	_____	_____		__	__
6:	_____	_____		__	__
7:	_____	_____		__	__
8:	_____	_____		__	__
9:	_____	_____		__	__
10:	_____	_____		__	__
11:	_____	_____		__	__
12:	_____	_____		__	__

Screen 4-8. Page 6 of 6: status conference x endpoint y

### Field descriptions

**Dial-out number** Numbers that are dialed out by administered connections for each channel in the call. The dial Out #1 and #2 on page 1 of the forms display the DCP endpoint number. This is particularly useful with bonding dial-out calls.

Connection  
State

The call state of the AC. The following are connection states associated with dial-out ACs:

“enabled” = Transient in nature indicating that an AC is about to enter the “attempting to connect” state.

“disabled” = one of three options:

- The AC reaches an administered retry threshold, and all retries are stopped. To verify this, check the Error Log to see if an error type of 9 is logged against the AC.
- The AC is in a connected state with the far end disconnected.
- The initial channel call is not connected. No dial out call attempt is made for the additional channels until the initial channel has reaches a connected state.

“not scheduled” = Transient in nature, indicating that an AC is about to enter the “attempting to connect” state.

“waiting to retry” = The AC is inactive, waiting for the retry timer to expire. Once the timer expires, the AC sends a dial out call and enters the “attempting to connect” state. In this state, dial out calls fail at least once.

“attempting to connect” = The AC is active, but has not connected.

“connected” = The call associated with the AC is answered and joins cut-thru to the conference.

Retry Count

Tallies the attempted retries for this AC during join attempts and does not clear when the AC connects. However, it clears when the Redial feature attempts a new join. This differs from the `Join Count` which counts the number of times the channel joins the conference during this conference session.

Failure Cause

An ISDN or CPTR cause value (values lower than 0x7f) records when the last dial out call drops. Values above 0x7f are generated internally. [Table 4-4](#) lists all possible failure cause values displayed by this field and its associated description. The `Failure Cause` value logs in the Error Log and displays with the **display errors** command. (`Err Type` is normally displayed as a decimal.)

**Table 4-4. Status AC - Failure Cause Values**

Failure Cause (hexadecimal)	Description
0x00 (0t0)	N/A
0x01 (0t1)	Incorrect destination address
0x02 (0t2)	Reason unknown

*Continued on next page*

Table 4-4. Status AC - Failure Cause Values — *Continued*

Failure Cause (hexadecimal)	Description
0x06 (0t6)	Reason unknown
0x10 (0t16)	Normal call clearing
0x11 (0t17)	Endpoint not available
0x12 (0t18)	ISDN timer expired
0x15 (0t21)	Reason unknown
0x12 (0t22)	Destination address changed
0x1C (0t28)	Bad destination or access denied
0x1D (0t29)	Access denied
0x1F (0t31)	Reason unknown
0x22 (0t34)	Trunks unavailable
0x26 (0t38)	Temporary or facility failure
0x29 (0t41)	Temporary or facility failure
0x2A (0t42)	Resources unavailable
0x2C (0t44)	Resources unavailable
0x32 (0t50)	Access denied
0x34 (0t52)	Access denied
0x36 (0t54)	Access denied
0x3A (0t58)	Resources unavailable
0x41 (0t65)	Required capability not implemented
0x42 (0t66)	Required capability not implemented
0x45 (0t69)	Required capability not implemented
0x51 (0t81)	ISDN protocol error
0x52 (0t82)	Required capability not implemented
0x58 (0t88)	Incorrect destination number
0x60 (0t96)	ISDN protocol error
0x61 (0t97)	ISDN protocol error
0x62 (0t98)	ISDN protocol error
0x64 (0t100)	ISDN protocol error
0x66 (0t102)	ISDN timer expired
0x7f (0t127)	Reason unknown

*Continued on next page*

Table 4-4. Status AC - Failure Cause Values — *Continued*

Failure Cause (hexadecimal)	Description
0xC2 (0t194)	Ring no answer
0xC8 (0t200)	Hi and dry - no feedback detected
0xC9 (0t201)	Cascade link administered wrong
0xCA (0t202)	CPTR not available to detect failure

## status data-module

This command displays internal software state information that can help locate facilities to which the data module is communicating.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>busyout mis</b>	<b><i>extension</i></b>	Data module extension	init inads craft cust rcust bcms browse	none	none

## Output

The following example shows the output from the **status data-module 301** command.

```
status data-module 301
```

```
DATA-MODULE STATUS
```

```
Data Ext/Stn Ext for Stn DM: 301      Service State: out-of-service
Port/Channel Number: 01C1103      Maintenance Busy? no
CF Destination Ext:
Connected Ports:
```

## Field descriptions

Data Ext/Sta Ext for Stn DM	The data module extension number. The DTDM is an exception: the connected station extension is shown.
Port/Channel Number	The port location of the data module (cabinet-carrier-slot-circuit). If the data module specified is a data channel, the channel number will be shown instead.
Service State	This entry displays the status of the data module; valid states are: <ul style="list-style-type: none"><li>— In-service/idle</li><li>— The data module is present but not in use.</li><li>— In-service/active</li><li>— The data module is present and is in use.</li><li>— Out-of-service</li><li>— The data module has been removed from service</li><li>— Disconnected</li><li>— The data module no longer appears to be present</li></ul>
CF Destination Ext	This entry displays the call forwarding destination, if any, of the station.
Maintenance Busy?	Whether maintenance is testing the object, "yes" or "no".
Connected Ports	Port locations to which the data module is connected (cabinet-carrier-slot-circuit).

## **status hardware-group**

This command displays summary information for the active or last hardware group test. This display includes the number and percentage of tested maintenance objects, the percentage of tests passed, failed, and aborted, the time elapsed since initiating the hardware group test, the specific hardware group test command (see [“test hardware-group”](#) command) initiated, and the state (active/canceled/complete) of the hardware-group test.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>status hardware-group</b>			init inads craft cust rcust bcms browse	none	none

## **Output**

The following example shows the output from the **status hardware-group** command.

```

status hardware-group                                page 1 of 1

                HARDWARE GROUP STATUS

Hardware Group Command State:  active
Number of MOs Tested:         11070
Total Number of MOs to be Tested: 12300
    Percent Complete:          90%
Elapsed Test Time (hr:min:sec): 0:15:30
    Repetition Number:         1
    Percentage of Tests Passed: 82%
    Percentage of Tests Failed: 11%
    Percentage of Tests Aborted: 7%

                ENTERED HARDWARE GROUP COMMAND

Command: test hardware-group system
Test sequence: short
Test repetition: repeat 3
Output Options: failures
Hardware Options: SPE-interchange
    
```

## Field descriptions

Hardware Group Command State:	“active” = testing in progress, “canceled” = testing canceled, “complete” = command completed; no testing occurring.
Number of MOs Tested:	Number of MOs in the specified group (refer to <a href="#">“test hardware-group” on page 4-251</a> ) that the <b>hardware-group</b> command tests, including MOs that were tested or aborted due to resource contention.
Total Number of MOs to be Tested:	Number of MOs in the group specified in the <b>test hardware-group</b> command.
Percent Complete:	Ratio of the completed MOs to the MOs to test in the command.
Elapsed Test Time:	Tracks completion time for the <b>hardware-group</b> command. If a test cancels and then restarts, the time for the cancel period is excluded. (HH:MM:SS)
Repetition Number	Number of completed iterations that correspond to the 'repeat' or 'continuously' option.
Percentage of Tests Passed:	Percentage of tests that passed.
Percentage of Tests Failed:	Percentage of tests that failed.
Percentage of Tests Aborted:	Percentage of aborted tests
Command:	Hardware-group action objects and qualifiers.
Test sequence:	Short or long.
Test repetition:	Displays continuously or the keyword repeats with the entered repeat value.
Output options:	Selections that were chosen on the input form: auto-page, background, or failures.
Hardware options:	Selections that were chosen on the input form: all-ports, or SPE-interchange.

## status health

This command displays the current system alarm summary, maintenance busy summary, user summary, critical system status, and cabinet status. This same page displays with the **monitor health** command, except that the **status health** output page does not update periodically.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
status health			init inads craft cust nms browse	none	none.

## Output

The following example shows the output from the **status health** command.

```
status health
```

### ALARM SUMMARY

```
Major: 0
Minor: 2
Warning: 0
```

### BUSY-OUT SUMMARY

```
Trunks: 0
Stations: 0
Others: 0
```

### CRITICAL SYSTEM STATUS

```
Active SPE: A/auto
Duplicated? SPE:n
Time Source: primary
# Logins: 3
```

### CABINET STATUS

#### Emerg Alarms

```
Cab Trans Mj Mn Wn PNC
1 auto- 0 | 2 | 2 up
2 n.a. 0 | 0 | 0 dn
3 n.a. 0 | 0 | 0 dn
```

```
9:33 WED APR 28 1998
```

## Field descriptions

- Major Number of logged major alarms. (0–200)
- Minor Number of logged minor alarms. (0–200)
- Warning Number of warnings logged in the alarm file. (0–200)
- Trunks Number of maintenance busied out trunks.

**4** Maintenance Commands for DEFINITY ONE  
*status health*

4-200

Stations	Number of maintenance busied out stations.
Others	Combined number of maintenance busied out objects excluding trunks and stations.
Static	Proportion of the CPU that is dedicated to high priority items (for example, the operating system). This percentage is rounded to the nearest integer, therefore a percentage of 0 means that the occupancy is less than one half of a percent.
SM	Proportion of the CPU that is dedicated to system management or periodic and scheduled maintenance. If many periodic or scheduled maintenance tests perform, this occupancy percentage can be high without affecting service. This percentage rounds to the nearest integer; therefore, a percentage of 0=the occupancy is less than one half of a percent (for example, an 89.6% occupancy displays as 90%).
CP	Proportion of the CPU that is dedicated to call processing. This occupancy has priority over SM and IDLE occupancy categories, and if needed, takes processor time from these occupancy categories. This percentage is rounded to the nearest integer.
Idle	Available proportion of the CPU. This percentage is rounded to the nearest integer.
Active SPE	A or B indicate the active processor complex. When the active processor complex is locked on-line with lock switching on DUPINT, the "lock" option displays; otherwise, "auto" displays.
Duplicated?	Duplication status of the SPE component. "y" = duplication; "n" = no duplication.
SPE Power	Power source for the processor complex. (commercial) When commercial power is unavailable, battery backup is in use and is indicated with "backup".
Time Source	The current timing source. Display values for this field vary according to timing sources selected. "external" = For Stratum-3 hardware, "internal" = an internal source, such as a tone clock. Primary and secondary timing sources must be administered for the Stratum-4 option. "primary"= the primary administered source is in use, "secondary" = the administered secondary source is in use. "local" = neither the primary or secondary sources are in use.
# Logins	Number of current users.
Cab	Assigned cabinet number (1 to the highest system cabinet number).

**4 Maintenance Commands for DEFINITY ONE**  
*status health*

4-201

Emerg Trans	Settings for emergency transfer switches on the maintenance board for each cabinet. Available options are: auto-on (“auto+” or “a+”), auto-off (“auto-” or “a-”), “on”, “off”, and “n.a.”. The system defaults to “auto+” or “auto-”. In this state, emergency transfer activate automatically if the cabinet fails (“+”=emergency transfer is activate, “-” = emergency transfer is inactive). “on” = emergency transfer automatically activates. “off”=the cabinet cannot activate emergency transfers. Duplicated SPEs systems = switch settings for both processors of the PPN (cabinet 1) display. In this case, “auto+” is abbreviated “a+”, “auto-” is abbreviated “a-”, and “off” is abbreviated “of”. “on” does not change. “n.a.” = the emergency transfer switch setting is unavailable.
Mj	Number of major alarms associated with the cabinet. Asterisks are used to fill fields when numbers exceed 99.
Mn	Number of minor alarms associated with the cabinet. Asterisks are used to fill fields when numbers exceed 99.
Wn	Number of warnings associated with the cabinet. Asterisks are used to fill fields when numbers exceed 99.
PNC	Port Network Connectivity (PNC) status for each port networks within a cabinet. When multiple port networks exist, Carriers A, B, and C are listed first and separated from Carriers D and E by a slash (for example, up/up).
Time of Day	Current time of day acquired from the system.

## status isdn-testcall

This command displays the progress of an outgoing ISDN-PRI test call. The status form displays the tested ISDN-PRI B-channel port number, bit error rate, number of bits transmitted, block error rate, number of blocks transmitted, start time, duration specified, duration of test call and reason of termination.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>status isdn-testcall</b>	<b>group number</b>	Administered trunk group number	init inads craft	none	see below
	<b>group member number</b>	Administered group number (trunk within a trunk group)			

### Feature interactions

If the bit error rate or block error rate is greater than zero, the ISDN-PRI trunk may be in trouble. The statistical information displayed on the terminal may deactivate the ISDN trunk. This is subjective because the ISDN trunk may be used for data or voice. If the trunk is used for data and the rates are high, the trunk should be deactivated. If the trunk is used for voice, the trunk may not be deactivated. Also, high rates be at risk for some type of power hit.

### Output

The following example shows the output from the **status isdn-testcall 80/1** command.

```

status isdn-testcall 80/1                               Page 1 of 1   SPE A

                ISDN TESTCALL STATUS

      Bit   Number Block Number      Duration      Reason
      Error Of Error Of   Start   Duration Of   Of
      Rate  Bits  Rate  Blocks Time   Specified Test Termination
-----
1B1401  0EE0  4EE7   0EE0  6EE2   25/12:36 120      100    in progress

```

## Field descriptions

Port	(cabinet/carrier/slot/circuit) of the ISDN-PRI B-channel.
Bit Error Rate	The measured bit error count based on the comparison between sent and received bit patterns. (Number displays in scientific notation)
Number of Bits	Number of bits generated. (Number displays in scientific notation)
Block error Rate	The measured block error count based on the comparison between sent and received bit patterns. (Number displays in scientific notation).
Number of Blocks	Number of blocks generated. (Number displays in scientific notation)
Start Time	Test call start time. (dd/hh:mm).
Duration Specified	Specified run time for the test call. (1-120 minutes, or blank = default of 10 seconds).
Duration of Test	Run time for the test call, listed in minutes. "blank" = a default time.
Reason of Termination	Reason that the test call terminates: "finished," "canceled," "overflow," "no bits," "transmission," "internal fail," "data corrupt," "call dropped," "call rejected," and "in progress." "finished" = the test finishes in the specified time. "canceled" = the test call cancels with the <b>clear isdn-testcall</b> command. "overflow" = the transmitted bits overflow buffer allocation. "no bits" = no bits are received because the ISDN-PRI test call circuit connection is bad. "transmission" = a data transmission interrupts, probably from a power hit. "call dropped" = the call drops due to an abnormal termination, or inability to cut-through to the other side. "call rejected" = the originating call is not set up properly. "internal fail" = an internal error on the Maintenance/Test circuit pack. "in progress" = the test is still running; "data corrupt" = any other error condition.

## status link

This command displays the operational status associated with a specified processor interface link. Since no links are administered in a TN795 processor system, this command does not apply.

## status packet-interface

This command displays the status of the packet-interface portion of the TN795 processor circuit pack along with link information. Link status information including total, active, and failed links also display. When the packet-interface is out-of-service or uninstalled, it is not used to establish and maintain links; when it returns to in-service status, new links are again assigned to it.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>status packet-interface</b>			init inads craft	none	none

## Output

The following example shows the output from the **status packet-interface** command.

```
status packet-interface
```

```
PACKET INTERFACE STATUS
```

```

Location:          01A
Service State:    in-service

Total Links:      32
Active Links:     32
Failed Links:     0

```

## Field descriptions

Location	Location: (cabinet-carrier-circuit pack)
Service State	standby is used in place of <i>in-service</i> for the standby packet-interface.
Total links	Total number of links
Active links	Number of links in use
Failed links	Number of failed links (equals # of total links - # of active links)

## status periodic-scheduled

This command displays the current status of the periodic and scheduled maintenance objects.

### Output

```

status periodic-scheduled
      MO
      Type          Current   Current   Previous Cycle   Rate of
                   Type      Cycle %   Cycle     Duration         Completed
                   Complete Active?    (hr:min:sec)    Cycles
PERIODIC   System Critical  100%     n         00:00:07         1.0/hr
MAINTENANCE Shared Resource  100%     n         00:01:13         1.0/hr
           Single User   100%     n         00:02:42         1.0/hr
           Total         00:04:02
Start Time of Current or Previous Cycle: 10/19/07:06:54
Pre - SCHEDULED MAINTENANCE              n         00:00:00
SCHEDULED System Critical  100%     n         00:00:31         1.0/day
MAINTENANCE Shared Resource  100%     n         00:02:19         1.0/day
           Single User   100%     n         00:00:50         1.0/day
           Total         00:03:40
Start Time of Current or Previous Cycle: 10/19/01:00:09
    
```

### Field descriptions

MO Type	Type of Maintenance Objects executed.
Current Cycle % Complete	Percentage of tests complete in the current testing cycle.
Current Cycle Active?	<b>y</b> indicates testing cycle is active. <b>n</b> indicates testing cycle is inactive.
Previous Cycle Duration (hr:min:sec)	Time in hours, minutes, and seconds (hh:mm:ss format) it took to complete the previous test cycle.
Rates of Completed Cycles	Frequency of test cycles (cycles per unit time).
PERIODIC MAINTENANCE	Tests scheduled for Periodic Maintenance. See <a href="#">"Maintenance testing" on page 1-15</a> .
Start Time of Current or Previous Cycle:	Time that the last maintenance cycle occurred.
Pre - SCHEDULED MAINTENANCE	Tests assigned to pre-scheduled maintenance.
SCHEDULED MAINTENANCE	Tests schedule for Periodic maintenance. See <a href="#">"Maintenance testing" on page 1-15</a>

## **status pri-endpoint**

This command displays internal software state information for diagnosis and can help locate facilities with which a PRI endpoint is communicating. Status information for each of the B-channels making up the PRI endpoint display in addition to some overall PRI endpoint information.

Action/ Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>status pri-endpoint</b>	<b><i>extension</i></b>	PRI endpoint extension to be displayed (see dial-plan).  Examples: <b>status pri-endpoint 25012</b> <b>status pri-endpoint 77868</b>	init inads craft nms browse	none	none

## **Output**

The following example shows the output for the `status pri-endpoint 22501` command and assumes the following:

- PRI endpoint ports for extension 22501 are in cabinet 1, carrier B, slot 20, circuit 1 to 6.
- The ports 1 to 3 of the specified PRI endpoint are connected on an active call to ports 13 to 15 of board in location 1B19 (cabinet 1, carrier B, slot 19).
- Ports 4 and 5 of the specified PRI endpoint are idle.
- Port 6 of the specified PRI endpoint is out of service, and background maintenance testing is being performed on the port.

**NOTE:**

A PRI endpoint can initiate and receive a call on any one or more of the B-channels making up the PRI endpoint.

4 Maintenance Commands for DEFINITY ONE  
status pri-endpoint

4-207

status pri-endpoint 22501 page 1 of 1

PRI-ENDPOINT STATUS

Extension: 22501 Width: 6  
 Signaling Group ID: 3 B-Channels Active: 3  
 Originating Auto Restoration? n B-Channels Idle: 2

Port	Service State	Test In Progress	Connected Port
01B2001	in-service/active	n	01B1913
01B2002	in-service/active	n	01B1914
01B2003	in-service/active	n	01B1915
01B2004	in-service/idle	n	
01B2005	in-service/idle	n	
01B2006	out-of-service-NE	y	

Command Successfully Completed

Note that the line listing of each B-channel's status may continue onto the next page. The user is prompted to press the `NxtPg` key to continue the display.

## Field descriptions

Extension	PRI endpoint extension
Width	Administered number of B-channels associated with the specified PRI endpoint
Signaling Group ID	ID number of the signaling group that handles the signaling for the ports in the specified PRI endpoint
Originating Auto Restoration	Administered option for the auto restore feature (restores calls originated from this PRI endpoint in the case of network failure): y = restoration option enabled n = restoration option disabled
B-Channels Active	The number of B-channels active on a call
B-Channels Idle	The number of B-channels in the in-service/idle state
Port	Port locations (cabinet-carrier-slot-circuit) for each of the B-channels making up the PRI endpoint.

- Service State** Service state of the B-channels:  
in-service/active, in-service/idle, out-of-service-NE,  
out-of-service-FE, maint-NE/active, maint-FE/active, maint-NE/idle,  
and maint-FE/idle.
- NE (Near End) and FE (Far End) refer to which “end” of the B-channel has placed the facility in the current state. NE refers to the switch and FE refers to the PRI terminal adapter (or any device that terminates the D-channel signaling on the facility).
- Test In Progress** Whether or not there is any current maintenance testing on the port.
- Connected Port** Connected port location (cabinet-carrier-slot-circuit) for each of the B-channels active on a call.

## **status processor-channel**

This command displays the status of the specified processor channel and the values of its various counters. A processor channel is 1 of 64 logical channels associated with an SCI link. Each processor channel terminates in the switch processing element with a session.

Action/ Object	Qualifier	Qualifier Description	Permissions	Defaults	Feature Interactions
<b>status processor-channel</b>	<b><i>channel number</i></b> <b><i>print</i></b>	Processor channel number (1-64).  Report sent to printer  Examples: <b>status processor-channel 1</b> <b>status processor-channel 10</b> <b>status processor-channel 64</b> <b>status processor-channel 64 print</b>	init inads craft cust rcust bcms browse	none	none

## Output

---

The following example shows the output from the **status processor-channels 1** command.

```
status processor-channels 1

                                PROCESSOR CHANNEL STATUS

Channel Number: 1
Channel Status: 6: In data transfer state
Reset Count: 3
Message Buffer Number: 1
Link Number: 4
Retransmission Count: 5
```

## Field descriptions

Channel Number	The processor channel number 1-64.
Channel Status	State the channel is in: <ol style="list-style-type: none"><li>1. Channel is not administered.</li><li>2. Channel is administered but not used.</li><li>3. Channel is in a state entering "wait session accept" (WSA).</li><li>4. Channel is in a state waiting for a "session accept" message from the far end.</li><li>5. Channel is waiting for action.</li><li>6. Channel is in data transfer state (channel up and running).</li><li>7. Channel is in resynchronization state.</li><li>8. Channel is waiting for acknowledge of disconnect message.</li><li>9. ISDN-PRI Channel is currently down.</li><li>10. ISDN-PRI Channel is in the data transfer state (that is, channel is up and running).</li></ol>
Reset Count	Number of times reset has been issued for this channel
Message Buffer Number	Number of message buffers currently used for communication on this channel.
Link Number	Physical SCI link (1-8) associated with the channel
Retransmission Count	Number of times that message retransmission has occurred

## status remote-access

This command displays information about remote access calls.

## Output

```

status remote-access
REMOTE ACCESS STATUS
Remote Access Status: not-administered
                        Date/Time Modified:  /  /  :

Barrier Code   Date Modified   Expiration Date   No. of Calls   Status   Date/Time Expired   Cause
                Modified   Date             Calls   Used

1:              /  /             /  /             /  /             /  /       :
2:              /  /             /  /             /  /             /  /       :
3:              /  /             /  /             /  /             /  /       :
4:              /  /             /  /             /  /             /  /       :
5:              /  /             /  /             /  /             /  /       :
6:              /  /             /  /             /  /             /  /       :
7:              /  /             /  /             /  /             /  /       :
8:              /  /             /  /             /  /             /  /       :
9:              /  /             /  /             /  /             /  /       :
10:             /  /             /  /             /  /             /  /       :
    
```

## Field descriptions

Remote Access Status            Indicates if the feature is enabled or not.

Barrier Code

Date Modified

Expiration Date

No. of Calls

Calls Used

Status

Date/Time Expired

Cause                            Reason for the expiration

## **status signaling-group**

This command displays the state, type, port location, and state of the Primary and Secondary D-channels within the group. A signaling group is a collection of B-channels signaled for by a designated single D-channel or set of D-channels over an ISDN-PRI.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>status signaling-group</b>	<b>group identifier</b>	Administered group identifier number (1-8)	init inads craft cust browse	none	none

## **Output**

The following output example shows the output from the **status signaling-group 1** command.

```
status signaling-group 1                               Page 1 of 1   SPE A

                STATUS SIGNALING-GROUP

Group ID: 1
  Type: facility associated signaling
Group State: in-service

                Primary D-Channel

Link: 1      Port: 01C1924  Level 3 State: in-service

                Secondary D-Channel

Link:      Port:      Level 3 State:
```

## Field descriptions

Group ID:	Numerical ID of the signaling group (1-8)
Type:	<p>facility associated signaling: all members are on a single DS-1 facility. Facility associated signaling groups support only the simplex D-channel configuration.</p> <p>non-facility associated signaling: members can be carried by multiple DS-1 facilities.</p> <p>The DS-1 facility is identified across the ISDN-PRI using an explicit facility identifier. In a simplex configuration one D-channel is used to signal for B-channel members.</p>
Group State:	<p>in-service: one of the D-channels signaling for the group is in service</p> <p>out-of-service: neither D-channel in the group is in service</p> <p> <b>NOTE:</b> If there is no D-channel backup and the primary D-channel is out-of-service, then the signaling group is in an out-of-service state.</p>
Link:	Link transporting the D-channel
Port:	Address of the port transporting either the primary or secondary D-channel

Level 3  
State:

State of the primary or secondary D-channels:

*in-service*: a D-channel is “in-service” when it is in the multiple-frame-established state at layer 2 carrying normal call-control signaling at layer 3.

*standby*: a D-channel is “standby” when it is in the multiple-frame-established state at layer 2, and not carrying any layer 3 call-control messages on logical link 0,0.

*wait*: a D-channel is in a “wait” state when an attempt has been made by one side of the interface to establish layer 3 peer communications as part of the process of going to the “in-service” state, which is transitional in nature. Only when the ISDN SERVICE message is sent over the interface, and the far end of the interface responds with a SERVICE ACKnowledge message is the D-channel placed in the “in-service” state.

*maintenance-busy*: a D-channel is “maintenance-busy” when it is not in the multiple-frame-established state at layer 2. This state is entered automatically when an active D-channel is declared failed. A D-channel that has been placed in the “maintenance-busy” state may be placed in the “out-of-service” state without system technician intervention.

*manual-out-of-service*: a D-channel is “manual-out-of-service” when system technician intervention has caused it to be placed in the TEI-assigned state at layer 2. System Technician intervention is required to retrieve a D-channel from this state.

*out-of-service*: a D-channel is “out-of-service” when it is in the TEI-assigned state at layer 2, but is periodically requested by layer 3 to attempt to establish the link.

*no-link*: no link is administered for the D-channel

## status station

This command displays the internal software state information for diagnosis and to help locate the facilities to which the station is communicating.

Action/ Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>status station</b>	<b><i>extension</i></b>	Station extension (per dial-plan) Examples: <b>status station 10020</b> <b>status station 83277</b>	init inads craft cust browse	none	none

## Output

The following example shows the output for the **status station 1002** command.

```
status station 1002

                                GENERAL STATUS

                Type: 7405D           Service State: in-service/on-hook
            Extension: 1002           Download Status: not-applicable
                Port: 01C0702        SAC Activated? no
            Call Parked? no           User Cntrl Restr: none
            Ring Cut Off Act? no      Group Cntrl Restr: none
Active Coverage Option: 1           CF Destination Ext:

Message Waiting:
Connected Ports:

ACD STATUS                HOSPITALITY STATUS

Grp/Mod Grp/Mod Grp/Mod Grp/Mod Grp/Mod  AWU Call At:
 /      /      /      /      /          User DND: not activated
 /      /      /      /      /          Group DND: not activated
 /      /      /      /      /          Room Status: non-guest room
 /      /      /      /      /

On ACD Call? no

Command:
```

## Field descriptions

Type	Administered station type
Extension	Station or attendant extension
Port	Port location: cabinet-carrier-slot-circuit
Call Park	Whether the station has a call parked (yes or no)
Ring Cut Off Activated	Whether ring cut off is activated (yes or no)
CF Destination Ext	Call forwarding destination extension, if any.
Message Waiting	Whether there is a message waiting for the station. "AP-SPE", "AUDIX", or blank if no messages are waiting.
Connected Ports	Port locations of the facilities to which the station is connected: cabinet-carrier-slot-circuit
Agent Logged In	Displays (underneath) the hunt groups (up to 3) that the agent is logged into
On ACD Call?	Whether the agent is on an ACD call currently (yes or no).

4 Maintenance Commands for DEFINITY ONE  
status station

4-215

Work Mode	Work mode of each hunt group that an agent is logged into
Service State	In service/on-hook, in service/off-hook, in-service/in-tsa (Terminal Self Administration), out of service, or disconnected.
Maintenance Busy State	Whether maintenance is testing the object (yes or no)
SAC Activated	Whether send all calls is activated (yes or no)
User Cntrl Restr	One or two of the following: none, total, stat-stat, outward or terminate.
Group Cntrl Restr	One or two of the following: none, total, stat-stat, outward or terminate.
AWU Call at	Time that Automatic Wakeup Call is scheduled
User DND	Status of the do not disturb feature.
Group DND	Status of the group do not disturb feature.
Room Status	Whether a room is occupied or not (non-guest room, vacant, or occupied).

## status synchronization

This command displays the location of the DS1 or tone-clock circuit pack that is used for an on-line synchronization reference. The synchronization subsystem provides error free digital communication between the switch and other PBXs, COs, or customer premise equipment. The subsystem is made up of: TDM bus clock, DS1 trunk board, maintenance and administration software resident in the SPE.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>status synchronization</b>			init inads craft cust browse	none	none

## Output

The following example shows the output for the **status synchronization** command.

```
status synchronization
```

```

                                SYNCHRONIZATION STATUS

```

```

                Stratum Level:4
    Maintenance Name: TONE-BD   Physical Location: 01A
    Switching Capability: Enabled
    Excessive Reference Switching: No

```

## Field descriptions

Stratum Level	Synchronization stratum level (3 or 4)
Maintenance Name :	Either TONE-BD, DS1-BD, or STRAT-3.
Physical Location	Board location of the selected DS1 or tone-clock circuit pack (cabinet-carrier-slot for a DS1; cabinet-carrier for a tone-clock)
Switching Capability	Whether the on-line reference for synchronization can be switched (Enabled or Disabled)
Excessive Reference Switching	High-level description of how many times the synchronization reference has been switched. If excessive reference switching is taking place (sync error 1793 is at threshold), this field displays Yes; otherwise No displays.

## status sys-link

This command displays status data for a specified system link. The report includes the type and operational state of the link, the associated processor channel (if any), active alarms and path status, and a list of all hardware components making up the link's path.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
status sys-link	location	Port location: <b>PCSSpp</b> Example: <b>status sys-link 1b0201</b>	init inads craft	none	none

## Output

The following example shows the output from the **status sys-link 01a0516** command.

```

status sys-link 01a0516                               Page 1 of 2
  Location: 01a0516      Type/Chan: PRI      Alarms: none
  Current Path: present  Faulted Path: present  Last Fault: 04/30/1997 14:18
  State: up

                        Current Hardware Path

Location      Maintenance      Maintenance
Name          Alarms          Location      Name          Alarms
-----
01A          PKT-INT      major
PN 01       TDM-BUS      none
    
```

If a faulted path exists in addition to the current path, the components making up the faulted path display on page 2 of the report:

```

status sys-link 01a0516                               Page 2 of 2
  Location: 01a0516      Type/Chan: PRI      Alarms: none
  Current Path: present  Faulted Path: present  Last Fault: 04/30/1997 14:18
  State: up

                        Faulted Hardware Path

Location      Maintenance      Maintenance
Name          Alarms          Location      Name          Alarms
-----
    
```

## Field descriptions

Location	Port location (cabinet-carrier-slot-circuit)
Type/Chan	Type of system-link: PRI (ISDN-PRI signaling link)
Alarms	Highest alarm level currently logged against the components making up the link.
Current Path	Operational status of the current path: none: link is down. present: current path displayed is valid.
Faulted Path	The status of the faulted path, if any: present: path of the link has been faulted at least once. none: no record of the link having gone down default: default faulted path is being used
Last Fault	Date and time at which the most recent fault occurred
State	Whether the system link is up or down
Current Hardware Path	Location, maintenance name, and alarm information for each hardware component making up the current path of the link. The path begins at the Packet Interface in the SPE and terminates at the circuit path terminating the other end of the link.
Faulted Hardware Path	If the link encounters a fault, the system reroutes it (if possible) over an alternate route. If this has taken place, the faulted path is displayed on page 2 of the report. The location, maintenance name, and alarm information for each hardware component making up the most recent faulted path is shown.

## status system

This command displays the status, mode, and operational attributes of the SPE(s), TDM and Packet busses, tone-clock circuit pack(s), and emergency transfer switch of single or all cabinets in the system.

### CAUTION:

*The purpose of this command is to provide general information about the cabinet status. This information may not display correctly when the cabinet is in a transient period. In this case, wait for 1 minute and enter the command again.*

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
status system	<b>cabinet</b>	<b>1st-cabinet.</b> PPN Examples: <b>status system 1st-cabinet</b> <b>status system all-cabinets</b>	init inads craft cust rcust bcms browse	none	none

## Output

The following example shows the output from the **status system all-cabinets** command.

```

status system all-cabinets                               Page 1 of 3   SPE B

                                SYSTEM STATUS CABINET 1

SPE MODE                                SELECT  SPE ALARMS  TONE/  SERVICE  SYSTEM  SYSTEM
1A  active                               SWITCH  MAJOR MINOR  CLOCK  STATE   CLOCK  TONE
                                           0      2      1A    in     active active

      SERVICE  CONTROL  DEDICATED                SERVICE  BUS ALARMS  BUS  OPEN BUS
TDM  STATE   CHANNEL  TONES   PKT  STATE  MAJOR  MINOR  FAULTS  LEADS
1A   in     y      n     1    in    n     n
1B   in     n      y

EMERGENCY  SELECT                SERVICE  CABINET
TRANSFER   SWITCH  EXP-LINK  STATE  MODE  TYPE
1A         auto-off  -        -      -    CMC
1B
    
```

## Field descriptions

SPE	Switch Process Element (SPE) identifier (1A or 1B)
MODE	SPE modes are different for simplex systems than for duplicated systems. See SPE Modes section that follows.
SELECT SWITCH	SPE select switch position: <ul style="list-style-type: none"><li>■ <code>auto</code>: the switch is in the middle position and automatically switches SPE depending upon conditions</li><li>■ <code>&lt;blank&gt;</code> always appears for the 1A SPE in a simplex system.</li></ul>
PE ALARMS - MAJOR	Number of Major alarms associated with the SPE complex that affect the fault severity level of this SPE.
SPE ALARMS - MINOR	Number of Minor alarms associated with the SPE complex that affect the fault severity level of this SPE.
TONE/CLOCK	Location of the tone-clock circuit pack (1A and 1B).
SERVICE STATE	<ul style="list-style-type: none"><li>■ <code>in</code>: Tone-Clock is installed and is in-service</li><li>■ <code>out</code>: Tone-Clock failed certain maintenance tests and has been removed from service</li><li>■ <code>&lt;blank&gt;</code> In simplex systems there is no B-carrier Tone-Clock, and this field displays blank.</li></ul>
SYSTEM CLOCK	Shows which Tone-Clock supplies the system clock for the cabinet displayed: <ul style="list-style-type: none"><li>■ <code>active</code>: Tone-Clock active and supplying system clock</li><li>■ <code>down</code>: Tone-Clock failed some maintenance activity and cannot supply the system clock for this cabinet.</li><li>■ <code>&lt;blank&gt;</code> If simplex, then the 1B Tone-Clock for the PPN displays blank; if no EPN, then both the 1A and 1B Tone-Clock for this EPN display blank.</li></ul>
SYSTEM TONE	Shows which Tone-Clock circuit pack supplies the system tones for the cabinet being displayed. <ul style="list-style-type: none"><li>■ <code>active</code>: Tone-Clock active and supplying system tones</li><li>■ <code>down</code>: Tone-Clock failed some maintenance activity and cannot supply the system tones for this cabinet.</li><li>■ <code>&lt;blank&gt;</code> If simplex, then the 1B Tone-Clock for the PPN displays blank. If the system does not have an EPN, then both the 1A and 1B Tone-Clock for this EPN display blank.</li></ul>
TDM	The TDM Bus identifier (1A and 1B)

4 Maintenance Commands for DEFINITY ONE  
*status system*

4-221

SERVICE STATE	Operational state of the TDM Bus circuit pack: <ul style="list-style-type: none"><li>■ <i>in</i>: TDM Bus installed and is in-service</li><li>■ <i>out</i>: TDM Bus failed certain maintenance tests and has been removed from service</li></ul>
CONTROL CHANNEL	Whether the control channel is on this TDM Bus ( <i>y</i> or <i>n</i> )
DEDICATED TONES	Whether the dedicated tones are on this TDM Bus ( <i>y</i> or <i>n</i> )
PKT	Packet Bus identifier (1). Refer to Packet Bus Maintenance descriptions for more information.
SERVICE STATE	The operational state of the Packet Buses: <ul style="list-style-type: none"><li>■ <i>in</i>: Packet Bus in-service and operating normally.</li><li>■ <i>out</i>: Packet Bus failed certain maintenance tests and has been removed from service.</li><li>■ &lt;blank&gt; System does not have the Packet Bus feature.</li></ul>
BUS ALARMS-MAJOR	Whether Major alarms exist for packet bus components ( <i>y</i> or <i>n</i> )
BUS ALARMS-MINOR	Whether Minor alarms exist for packet bus components ( <i>y</i> or <i>n</i> )
BUS FAULTS	Number of faulty bus leads (defined as shorted to another lead, stuck at some value, or an open lead: 0 - 24). This field may take on any integer between 0 and 24. This field displays blank if: <ul style="list-style-type: none"><li>■ Maintenance/Test circuit pack not present</li><li>■ Packet Bus port of the Maintenance/Test circuit pack has been taken out-of-service</li><li>■ System does not have the Packet Bus feature</li></ul>
OPEN BUS LEADS	Number of open bus leads between the Maintenance/Test circuit pack and bus terminator (0 - 24). This could mean physical damage to the backplane or its connectors or a missing bus terminator. This field displays blank if: <ul style="list-style-type: none"><li>■ Maintenance/Test circuit pack is not present</li><li>■ System does not have the Packet Bus feature.</li></ul>
EMERGENCY TRANSFER	Location of the Processor or EPN Maintenance circuit pack containing the Emergency Transfer Select Switch (1A and 1B)

**4** Maintenance Commands for DEFINITY ONE  
*status system*

4-222

- SELECT SWITCH** Emergency Transfer Switch position on the Processor(s) or the EPN maintenance circuit pack and the state of Emergency Transfer in the cabinet display:
- **on**: Designated analog phones in this cabinet are cut through to CO trunk lines only in an emergency situation.
  - **off**: Emergency Transfer is off and cannot be invoked. The switch should only be in this state when a service technician is on site.
  - **auto-on**: The switch is in the or auto position, however, because of a serious system fault, system software has invoked Emergency Transfer.
  - **auto-off**: Switch in the auto position; because system has no serious faults, system software has not invoked Emergency Transfer
  - **<blank>** If the system is Simplex, then the 1B Emergency Transfer indication for the PPN will display a blank. If the system does not have an EPN, then both the 1A and 1B Emergency Transfer indications for the EPN will display a blank.
- EXP-LINK** The Expansion Link does not exist in the system; a dash (-) displays.
- SERVICE STATE** ■ **<blank>** Expansion Interface Link does not exist
- MODE** ■ **<blank>** Expansion Interface Link does not exist
- CABINET TYPE** ■ **CMC** (Compact Modular Cabinet)
- SPE Modes** ■ **active**: 1A SPE in a simplex system is always the active SPE

## status trunk

This command displays internal software state information for diagnosis and can help locate facilities to which the trunk is communicating. If a trunk group number is entered without a member number, a list showing the status for each member in the specified group displays. If a both the trunk group and member numbers are entered, the status for only the specified member displays.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
status trunk	<b>group</b>	Administered group number (1 - 99). If group number entered without a member number, a list showing the status of each member in the group displays.	init inads craft cust rcust	none	none
	<b>member</b>	Administered member number within a trunk group (1 - 99)  Examples: <b>status trunk 78</b> <b>status trunk 80</b> <b>status trunk 78/1</b> <b>status trunk 80/2</b>	bcms browse		

## Output

The following example shows the output for the **status trunk 78/1** (trunk group/member) command.

```
status trunk 78/1

                                TRUNK STATUS

Trunk Group/Member: 078/001      Service State: in-service/idle
Port: 01C1505                    Maintenance Busy? no
Signaling Group ID:              CA-TSC State:
Connected Ports:
```

## Field descriptions (group/member)

Trunk	Trunk group number/group member number (1-99/1-99)
Group/Member	
Port	Port location (cabinet-carrier-slot-circuit)
Signaling Group ID	If trunk is ISDN, then this field displays the number of the ISDN Signaling Group to which this group belongs; otherwise, the field is blank.

4 Maintenance Commands for DEFINITY ONE  
status trunk

4-224

Connected Ports	Port locations (cabinet-carrier-slot-circuit) connected to the trunk
Service State	Trunk service state: in-service/active, in-service/idle, out-of-service-NE, out-of-service-FE, maint-NE/active, maint-FE/active, maint-NE/idle, and maint-FE/idle.  NE (Near End; switch) and FE (Far End; PRI terminal adapter or any device that terminates the D-channel signaling) refer to which “end” of the B-channel has placed the facility in the current state.
Maintenance Busy	Whether any maintenance testing is being performed
CA-TSC State	State of the temporary signaling connection (used to pass call information over PRI signaling links)

Group only

The following example shows the output from the **status trunk 78** (trunk group only) command.

```
status trunk 78

                TRUNK GROUP STATUS

Member   Port      Service State   Mtce Connected Ports
          01C1505 in-service/idle no
          01C1506 in-service/idle no
```

Field descriptions

Member	Trunk group number/group member number (1-99/1-99).
Port	Port location (cabinet-carrier-slot-circuit)
Service State	Trunk service state: in-service/active, in-service/idle, out-of-service-NE, out-of-service-FE, maint-NE/active, maint-FE/active, maint-NE/idle, and maint-FE/idle.  NE (Near End; switch) and FE (Far End; PRI terminal adapter or any device that terminates the D-channel signaling) refer to which “end” of the B-channel has placed the facility in the current state.
Mtce Busy	Whether any maintenance testing is being performed
Connected Ports	Port locations (cabinet-carrier-slot-circuit) connected to the trunk

## status tsc-administered

The status tsc-administered command displays the operational status of TSC's administered for an administered signaling group. The status represents the state of the TSC according to switched services.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
status tsc-administered	<i>signaling group</i>  <i>#/tsc index</i>	Administered signaling group number  Number associated with each TSC in a signaling group  Examples: <b>status tsc-administered 1</b> <b>status tsc-administered 1/1</b>	init inads craft	none	none

## Output

The following example shows the output for the **status tsc-administered 1/1** command.

```
status tsc-administered 1/1

          ADMINISTERED NON-CALL-ASSOCIATED TSC STATUS

TSC      TSC
Index    State      Establish  Enabled  Congested
1        inactive    as-needed  yes      no
```

## Field descriptions

TSC Index      The administered TSC index (1-64).

TSC State      State of the administered TSC:

- **inactive**: the administered TSC is not functioning (for example, D-channel out-of-service, or disabled)
- **active**: indicates that the administered TSC is up and user information can be exchanged end-to-end.
- **pending-inactive**: shows that the TSC is being released.
- **pending-active**: the TSC is about to come up

- Establish            The switch responsible for the origination of the administered TSC:
  - as-needed: TSC is established on an as needed basis
  - permanent: TSC is permanently established
- Enabled            Indicates if the administered TSC's have been enabled ("yes" or "no").
- Congested        Administered TSC congestion history (whether or not the network can handle the receipt of USER INFORMATION messages for the administered TSC):
  - yes: TSC is congested
  - no: TSC is not congested
  - clear: TSC congestion was cleared during its active period

## status tti

This command displays the status (active/not active) of the tti background maintenance task, and, if it is active, it displays whether tti ports are being generated or removed, the number of tti-supported boards that have processed, and the number of tti-supported boards that have not yet been processed. The display also includes the elapsed time since the background maintenance task started.

Action/ Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
status tti			init inads craft cust nms browse	none	TTI background maintenance task is activated by enabling the TTI system parameter on the System-parameters Features form.

## Output

The following example shows the output for the **status tti** command.

```

status tti                                     Page 1 of 1

                                     TTI STATUS

TTI Background Task State:  generating tti ports
                             TTI State:  voice
# of Boards Completed:      30
# of Boards Left to Process: 120
                             Percent Complete: 25
Elapsed Time since Task Started: 0:15
    
```

## Field descriptions

TTI Background Task State:	State of the tti background maintenance task: <ul style="list-style-type: none"><li>■ generating tti ports:</li><li>■ removing tti ports:</li><li>■ suspended:</li><li>■ not active:</li><li>■ completed - all ports translated: the last execution of the background task completed normally</li><li>■ completed - some ports not translated: the task completed due to resource exhaustion with some ports left untranslated</li></ul>
TTI State:	The tti state: displays <code>off</code> (TTI feature not enabled for the system), or if enabled, then the field displays what kind of tti ports are being generated or removed ( <code>voice, data</code> ).
# of Boards Completed:	Number of TTI-supported boards that have been processed by the background maintenance task: <ul style="list-style-type: none"><li>■ <code>completed</code>: board has either had all its unadministered ports translated as TTI ports or its TTI ports have been removed and are now unadministered ports. This depends on whether the TTI background task is generating or removing tti ports.</li></ul>
# of Boards Left to Process:	Number of TTI-supported boards that have not yet been processed by the background maintenance task.
Percent Complete:	Ratio of the of number of boards completed compared to the number of boards left to process.
Elapsed Time since Task Started:	Elapsed time since the TTI background task was started. If the task is "not active", then this field is blank. If the task is "completed" it will indicate the length of time ( <code>hh:mm</code> format) it took to complete the task. If the task is "suspended", then it will display the elapsed time at the point the task was suspended.

## test access-endpoint

This command performs hardware diagnostic tests on all port circuits that are associated with the specified access endpoint extension.

Action/ Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>test access-endpoint</b>	<b><i>extension</i></b>	Access endpoint extension (# of digits determined by dial-plan)	init inads craft nms	Test sequence = short; repeat = 1	none
	<b><i>short</i></b>	Option for a brief series of nondestructive diagnostic tests.			
	<b><i>long</i></b>	Option for a longer, more comprehensive test series (includes a destructive test)			
	<b><i>repeat number</i></b>	How many times each test in the sequence is repeated (1-100)			
	<b><i>clear</i></b>	This option causes the test sequence (short or long) to repeat until the alarm (if any) is cleared or a single test in the sequence fails. <sup>1</sup>  Examples: <b>test access-endpoint 25012</b> <b>test access-endpoint 45002 sh</b> <b>test access-endpoint 45892 l</b> <b>test access-endpoint 24389 sh r 4</b> <b>test access-endpoint 34899 l r 6</b> <b>test access-endpoint 93483 r 2</b> <b>test access-endpoint 10022 c</b>			

1. If no alarms are registered against the maintenance object then the test sequence is run only once. The ***long clear*** option forces a clear of all alarms if no errors are encountered during testing. The ***short clear*** option only clears alarms pertinent to tests in the short sequence.

## Output

The following example shows the output for the **test access-endpoint 22502** command, and assumes the access endpoint ports for extension 22502 are in cabinet 1, carrier C, slot 11, circuit 1 to 6. The responses are displayed on a port-by-port and test-by-test basis with one line of data for each test result.

```
test access-endpoint 22502 short                page 1 of 1

                                TEST RESULTS

Port      Maintenance Name  Alt. Name  Test No.  Result      Error Code
01C1101   WAE-PORT             22502     36        PASS
01C1102   WAE-PORT             22502     36        PASS
01C1103   WAE-PORT             22502     36        PASS
01C1104   WAE-PORT             22502     36        PASS
01C1105   WAE-PORT             22502     36        PASS
01C1106   WAE-PORT             22502     36        PASS

Command Successfully Completed
```

## Field descriptions

Port	Port address (cabinet-carrier-slot-circuit)
Maintenance Name	The name of maintenance object (wideband access endpoint = WAE-PORT; single port access endpoint = TIE-DS1)
Alt. Name	The extension number of the access endpoint
Test No	The test being executed
Result	Test result: Pass, Abort, Fail, No Board, Disabled
Error Code	Numeric code explaining why the release failed or aborted. Refer to the detailed list of the codes by test number for each MO.

## test alarms

This command allows automatic testing all of the hardware associated with the active alarms in the alarm log. This command provides an initial query form to help the user narrow the selection of alarmed objects. After submitting the query form, the system tests the hardware associated with the selected alarm log entries. The results display in standard test output and status information display on the message line as the command progresses.

Several alarms may be logged against a single maintenance object, each alarm representing a different problem. Even if there are multiple entries in the alarm log for a single object, the **test alarms** command only tests each physical object once.

Action/ Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
test alarms	<b>auto-page</b>	New screen displays when current screen fills <sup>1</sup>	init inads craft nms	Test sequence = short; repeat = 1	See below
	<b>failures</b>	Only the failures (hardware, aborts, conflicts, EPN-down) display			
	<b>step</b>	Allows "stepping" to the next or previous alarm (current alarm not tested) <sup>2</sup>			
	<b>short</b>	Option for a brief series of nondestructive diagnostic tests.			
	<b>long</b>	Option for a longer, more comprehensive test series (includes a destructive test)			
	<b>repeat number</b>	How many times each test in the sequence is repeated (1-100)			
	<b>clear</b>	This option causes the test sequence (short or long) to repeat until the alarm (if any) is cleared or a single test in the sequence fails. <sup>3</sup>  Examples: <b>test alarms</b> <b>test alarms step failures</b> <b>test alarms long clear auto-page</b> <b>test alarms long failures</b>			

1. If **auto-page** option is not specified, the screen does not refresh once filled, and testing stops until the user presses PAGE (continue) or CANCEL (halts testing).
2. Press CANCEL to abort the command, ENTER to test the currently displayed alarm, NEXT ALARM (function key) to move to the next alarm, and PREV ALARM (function key) to move to the previous alarm without testing the currently displayed alarm. If this option is entered, then the NEXT ALARM (function key) or PREV ALARM (function key) can be pressed at any time during the command, even during test results. If NEXT ALARM or PREV ALARM is pressed during a test, the test is aborted, testing of the current alarm stops, and the next or previous alarm displays. If the first alarm is displayed and PREV ALARM is pressed, then the last alarm is displayed. If the last alarm is currently displayed and the NEXT ALARM is requested, then the first alarm displays. The only way to terminate this command is to press CANCEL.

#### 4 Maintenance Commands for DEFINITY ONE

##### *test alarms*

4-231

3. If no alarms are registered against the maintenance object then the test sequence is run only once. The **long clear** option forces a clear of all alarms if no errors are encountered during testing. The **short clear** option only clears alarms pertinent to tests in the short sequence. SEE WARNINGS BELOW.

### WARNING:

*Executing a clear with short option may not clear all alarms, even if all tests pass.*

### WARNING:

*Since the "clear long" options clear all counters if tests pass, it is possible for firmware counters to be cleared even when a problem exists. In some cases customer service might degrade since calls may be routed over defective equipment.*

## Feature interactions

---

With the enhancement of multiple maintenance users, there may be a possibility of two users attempting to test the same physical hardware (for example, one using the **test alarms** command and another using the **test board** command). If this command attempts to test a board that is currently being tested by another user, a error message displays.

## Options form

---

After entering the **test alarms** command, you are presented with an options form for alarm selection.

```
test alarms repeat 1
```

```
HARDWARE TEST ALARM QUERY
```

```
The following options control which alarms will be tested.
```

```
ALARM TYPES
```

```
Major? y_      Minor? y_      Warning? y_
```

```
REPORT PERIOD
```

```
Interval: m_  From: __/__/__:__  To: __/__/__:__
```

```
EQUIPMENT TYPE ( Choose only one, if any, of the following )
```

```
    Cabinet:  __
```

```
    Port Network:  __
```

```
    Board Number:  ____
```

```
    Port:  _____
```

```
    Category:  _____
```

```
    Extension:  ____
```

```
    Trunk ( group/member ):  __/__
```

## Field descriptions (Hardware Test Alarm Query)

Alarm Types	The type of alarm to be tested: put <b>y</b> or <b>n</b> in the field(s) to selects one or a combination of alarms.
Interval	Tests alarms for the last hour ( <b>h</b> ), last day ( <b>d</b> ), last week ( <b>w</b> ) or all ( <b>a</b> ) [default].
From	Test alarm from the specified time specified ( <i>mm/dd/hh/mm</i> ). If no <code>from</code> date is entered, then no checking is done and the alarms active since a month prior to the current time are reported.
To	Test alarms associated with records to the specified time specified ( <i>mm/dd/hh/mm</i> ). If no <code>to</code> date is entered, any alarm active after the <code>from</code> date is selected.
Equipment Type	<p>The technician can choose from five different equipment types. If there is no input to any of these fields, the system defaults to all the equipment. The user can select one of the following fields:</p> <ul style="list-style-type: none"><li>■ <b>Cabinet</b>: tests alarms associated with a particular cabinet (1-3).</li><li>■ <b>Port Network</b>: tests all alarms associated with a particular port network (1-3).</li><li>■ <b>Board Number</b>: tests all alarms associated with a particular circuit pack (<b>PCSS</b>, default cabinet = 1).</li><li>■ <b>Port</b>: tests all alarms associated with a particular port on a circuit pack (<b>PCSSpp</b>, default cabinet = 1).</li><li>■ <b>Category</b>: Alarms for a particular equipment category</li><li>■ <b>Extension</b>: Alarms associated with an extension number</li><li>■ <b>Trunk (group/member)</b>: tests all alarms associated with a particular trunk group or trunk group member, <i>XXYY</i>, where the group identifier tests all alarms associated with a trunk group (<i>XX_</i>), and the group identifier <i>and</i> member identifier are both entered to test all alarms associated with a specific trunk group member (<i>XXYY</i>).</li></ul>

## Output

The following example shows the output from the **test alarms** command (query form left empty by pressing ENTER). The responses display on a test-by-test basis with one line of data for each test result.

```

test alarms                                     Page 1

```

ALARM ENTRY								
Port	Maintenance Name	On Brd?	Alt Name	Alarm Type	Svc State	Ack? 1 2	Date Alarmed	Alarm Count
01C03	UDS1-BD	n		WARNING			03/06/16:48	1/4

TEST RESULTS						
Port	Maintenance Name	Alt. Name	Test No.	Result	Error Code	
01C03	UDS1-BD		138	NO BOARD		
01C03	UDS1-BD		139	NO BOARD		
01C03	UDS1-BD		140	NO BOARD		
01C03	UDS1-BD		141	NO BOARD		
01C03	UDS1-BD		142	NO BOARD		
01C03	UDS1-BD		143	NO BOARD		
01C03	UDS1-BD		144	NO BOARD		
01C03	UDS1-BD		145	NO BOARD		
01C03	UDS1-BD		146	NO BOARD		

Testing completed for this object.

press CANCEL to quit -- press NEXT PAGE to continue

## Field descriptions

When encountering errors in preparing a particular object to be tested (not inserted, contention, etc.), an error message display in the TEST RESULTS section of the output form.

### ALARM ENTRY section

Port	Port location of alarmed object (cabinet-carrier-slot-circuit); same identifier as alarm log
Maintenance Name	The name of the maintenance object
On Board	Fault detected is on the associated circuit pack (y) or off board (o).
Alt Name	Terminal extension numbers or trunk group numbers
Alarm Type	Major, Minor, or Warning
Service State	Current service state of the station and trunk ports: RDY (ready for service), OUT (out of service), or IN (in service).
Ack	Whether alarm has been acknowledged by the first and second OSS telephone numbers, respectively.



## test analog-testcall

This command performs facility diagnostic tests on an entire trunk group, an individual trunk group member, an individual trunk port, or on all trunks on a board, depending on the options entered. The type of test call, the far-end test line number, and the various other parameters must be administered on the trunk group form before executing the command. Normally, the user should only invoke the full or supervision test. The other options are provided primarily for testing when setting up an ATMS schedule.

Action/ Object	Qualifier	Qualifier Description	Permissions	Defaults	Feature Interactions
<b>test analog- testcall</b>	<b>full</b>	Executes the most comprehensive test call available using the administered test set type.	init inads craft cust	Test sequence = long; repeat = 1	See below
	<b>no super- vision</b>	Executes a supervision-only test call (approx. 10 sec.) and confirms the presence of the test set at the far end.			
	<b>no-selftest</b>	Executes the "full" test (skips any self-test sequences), saving about 20 seconds on the type 105 transmission test and has no effect on type 100 or 102 transmission tests.			
	<b>no-return- loss</b>	Executes the "full" test (skips any return loss sequences), saving about 20 seconds on the type 105 transmission test and does not have any effect on type 100 or 102 transmission tests.			
	<b>no-st-or-rl</b>	Executes the "full" test (skips all self test and return loss sequences), saving about 40 seconds on the type 105 transmission test and does not have any effect on type 100 or 102 transmission tests.			
	<b>repeat number</b>	How many times each test in the sequence is repeated (1-100)			
	<b>schedule</b>	Command is validated and then a scheduling form displays to schedule execution of the command. The command is then placed in the command queue and is executed at the specified time. The information displayed by the command is sent to the system printer instead of the screen.			

4 Maintenance Commands for DEFINITY ONE  
*test analog-testcall*

4-236

Action/ Object	Qualifier	Qualifier Description	Permissions	Defaults	Feature Interactions
		Examples: test analog-testcall trunk 78 f test analog-testcall trunk 78 f schedule test analog-testcall trunk 80/1 s r 2 test analog-testcall trunk 80/1 s r 2 schedule test analog-testcall trunk 78/2 no-selftest r 10 test analog-testcall trunk 78/2 no-selftest r 10 schedule test analog-testcall trunk 78 r 4 test analog-testcall trunk 78 r 4 schedule test analog-testcall port 2a1505 no-st-or-rl r 4 test analog-testcall port 2a1505 no-st-or-rl r 4 schedule test analog-testcall board 2a15 test analog-testcall board 2a15 schedule test analog-testcall port 2a1505 no-return-loss test analog-testcall port 2a1505 no-return-loss schedule te an t 80 te an t 80 schedule			

### Feature Interactions

- Additional data is available after running a test. See the [“list measurements” on page 4-81](#) command with the **test-call** option for details on how to access the additional data.
- If the trunk is in use by call processing, the test aborts.
- If the trunk is in use by maintenance, the test queues and runs when the current maintenance activity finishes.

### Output

The following example shows the output for the **test analog-testcall trunk 78** command. The responses display on a test-by-test basis with one line of data for each test result.

```
test analog-testcall trunk 78
```

TEST RESULTS

Port	Maintenance Name	Alt. Name	Test No.	Result	Error Code
01C1505	CO-TRK	78/1	845	PASS	
01C1507	CO-TRK	78/2	845	PASS	

Command Successfully Completed



4 Maintenance Commands for DEFINITY ONE  
test board

4-238

Action/ Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
test board	<b>location</b>	Physical location of the board <b>PCSS</b>	init inads craft nms	Test sequence = short; repeat = 1	none
	<b>short</b>	Option for a brief series of nondestructive diagnostic tests.			
	<b>long</b>	Option for a longer, more comprehensive test series (includes a destructive test)			
	<b>repeat number</b>	How many times each test in the sequence is repeated (1-100)			
	<b>clear</b>	This option causes the test sequence (short or long) to repeat until the alarm (if any) is cleared or a single test in the sequence fails. <sup>1</sup>  Examples: <b>test board 01a01</b> <b>test board 01a02</b> <b>test board 01a03</b> <b>test board 01a05</b> <b>test board 01a10</b>			

1. If no alarms are registered against the maintenance object then the test sequence is run only once. The **long clear** option forces a clear of all alarms if no errors are encountered during testing. The **short clear** option only clears alarms pertinent to tests in the short sequence. SEE WARNING BELOW.



**WARNING:**

*Since the "clear long" options clear all counters if tests pass, it is possible for firmware counters to be cleared even when a problem exists. In some cases customer service might degrade since calls may be routed over defective equipment.*

**Feature interactions**

Destructive long tests on a Switch Node Interface (SNI) board are not allowed unless the board has first been busied out.



## test cdr-link

This command first validates that the Call Detail Recording (CDR) link has been administered and exists in the switch. Then individual diagnostic tests run on the link and return results of the test along with any possible error codes. For more information on the CDR link, see the description for [“status cdr-link” on page 4-158](#).

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>test cdr-link</b>	<b>short</b>	Option for a brief series of nondestructive diagnostic tests.	init inads craft	Test sequence = short; repeat = 1	none
	<b>long</b>	Option for a longer, more comprehensive test series (includes a destructive test)			
	<b>repeat number</b>	How many times each test in the sequence is repeated (1-100)			
	<b>clear</b>	This option causes the test sequence (short or long) to repeat until the alarm (if any) is cleared or a single test in the sequence fails. <sup>1</sup>			

1. If no alarms are registered against the maintenance object then the test sequence is run only once. The **long clear** option forces a clear of all alarms if no errors are encountered during testing. The **short clear** option only clears alarms pertinent to tests in the short sequence.

## Output

The following example shows the output for the **test cdr-link** command. The responses display on a test-by-test basis with one line of data for each test result.

```
test cdr-link long
```

```
TEST RESULTS
```

Port	Maintenance Name	Alt. Name	Test No.	Result	Error Code
	CDR-LINK		213	PASS	
	CDR-LINK		215	PASS	

## Field descriptions

Port	Not applicable (always blank)
Maintenance Name	The type of MO being tested: cdr-link
Alt. Name	Not applicable (always blank)
Test No	The test being executed
Result	Test result: Pass, Abort, Fail, Disabled
Error Code	Numeric code explaining why the release failed or aborted. Refer to the detailed list of the codes by test number for each MO.

## test customer-alarm

This command performs hardware diagnostic tests on the leads of the Processor and EPN maintenance circuit packs, used for customer-provided alarms by closing the appropriate relay for 1 minute. Failure is verified by checking the customer alarm attached to the specified circuit pack.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>test customer-alarm</b>	<b>location</b>	Extension of the data module or data channel to be tested (per dial-plan)	init inads craft	See below	none
	<b>short</b>	Runs test number 115			
	<b>long</b>	Runs test number 115 (same as short test option)			
	<b>repeat number</b>	How many times each test in the sequence is repeated (1-100)			
	<b>clear</b>	This option causes the test sequence (short or long) to repeat until the alarm (if any) is cleared or a single test in the sequence fails. <sup>1</sup>  Examples: <b>test customer-alarm</b> <b>test customer-alarm 02 r 2</b> <b>test customer-alarm 01b r 25</b> <b>test customer-alarm 2a</b> <b>test customer-alarm 2a sh</b> <b>test customer-alarm 3 c</b>			

1. If no alarms are registered against the maintenance object then the test sequence is run only once. The **long clear** option forces a clear of all alarms if no errors are encountered during testing. The **short clear** option only clears alarms pertinent to tests in the short sequence.

## Defaults

The default cabinet is cabinet 1, and the default carrier is "a." The default for the remaining parameter is a repeat of 1.

## Output

---

The following example shows the output from the **test customer-alarm 02a** command.

```
test customer-alarm 02A
```

```
TEST RESULTS
```

Port	Maintenance Name	Alt. Name	Test No.	Result	Error Code
02A	CUST-ALM		115	PASS	

```
Command Successfully Completed
```

## Field definitions

Port	The port address (cabinet-carrier-slot)
Maintenance Name	The maintenance name (always CUST-ALM)
Alt. Name	Not applicable
Test No.	The test number (always 115)
Result	Test result: Pass, Abort, or Fail
Error Code	Numeric code explaining why the release failed or aborted. Refer to the detailed list of the codes by test number for each MO.

## test data-module

This command performs hardware diagnostic tests on a data module or data channel. Test results are determined by the interface to the digital switch-data line port, digital line port, or network control data channel.

Action/ Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>test data-module</b>	<b>extension</b>	Extension of the data module or data channel to be tested (per dial-plan)	init inads craft cust nms	Test sequence = short; repeat = 1	none
	<b>short</b>	Option for a brief series of nondestructive diagnostic tests.			
	<b>long</b>	Option for a longer, more comprehensive test series (includes a destructive test)			
	<b>repeat number</b>	How many times each test in the sequence is repeated (1-100)			
	<b>clear</b>	This option causes the test sequence (short or long) to repeat until the alarm (if any) is cleared or a single test in the sequence fails. <sup>1</sup>  Examples: <b>test data-module 30000 l</b> <b>test data-module 30000</b> <b>test data-module 32000 sh r 2</b> <b>test data-module 33000 l r 25</b> <b>test data-module 30000 c</b>			

1. If no alarms are registered against the maintenance object then the test sequence is run only once. The **long clear** option forces a clear of all alarms if no errors are encountered during testing. The **short clear** option only clears alarms pertinent to tests in the short sequence. SEE WARNING BELOW.

### WARNING:

*Since the "clear long" options clear all counters if tests pass, it is possible for firmware counters to be cleared even when a problem exists. In some cases customer service might degrade since calls may be routed over defective equipment.*



4 Maintenance Commands for DEFINITY ONE  
*test ds1-loop*

4-245

Action/ Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>test ds1-loop</b>	<b><i>location</i></b>	Physical location of board (PCSS)	init inads craft super-user other <sup>3</sup>	ds1/csu- loopbac k-tests	See below
	<b><i>cpe-loopback- jack-test-begin</i></b>	Long-duration loopback test setup through the Customer Premises Equipment (CPE) Loopback Jack. Allows user to specify a loop-up code for the CPE loopback jack if it differs from the default (0x47F). The loop-up code is entered by specifying the number of bits in the loop-up code as well as the actual hexadecimal bit-pattern. <sup>1</sup>			
	<b><i>far-csu-loopback- test-begin</i></b>	Long-duration loopback test setup through the far-end Channel Service Unit (CSU)			
	<b><i>one-way-span- test-begin</i></b>	Long-duration one-way span test			
	<b><i>end-loopback/ span-test</i></b>	Terminates long-duration one-way span and loopback testing			
	<b><i>inject-single-bit- error</i></b>	Single bit error sent within an active framed 3-in-24 test pattern used in long-duration loopback and span testing			
	<b><i>ds1/csu- loopback-tests</i></b>	Sequentially executes the following loopback tests: DS1 Board LoopBack, CSU Module Equipment LoopBack, and CSU Module Repeater LoopBack. <sup>2</sup>  Examples: <b>test ds1-loop 01c08</b> <b>test ds1-loop 1-3c03</b> <b>cpe-loopback-jack</b> <b>test ds1-loop 1-3c03 cpe</b> <b>test ds1-loop 10c03 end</b> <b>test ds1-loop 02d12 fa</b> <b>test ds1-loop 02d12 inj</b>			

1. For TN464F or TN767E or later suffix DS1 boards only. The test aborts if the board has not been taken out of service with the **busyout** command.
2. For TN464F or TN767E or later suffix DS1 boards
3. Logins with `Maintain Switch Circuit Packs` permissions enabled.

## Feature interactions

- Loopback or span tests are not allowed on DS1 boards unless the board has been busied out.
- Only one of the CPE Loopback Jack, far-end CSU, one-way span, or DS1/CSU loopback tests may be active at any given time on a DS1 span.

## Output

The following example shows the output for the **test ds1-loop 1c07** command, and assumes that the board in cabinet 1, carrier c, slot 7 is a TN767E DS1 board. The responses display on a test-by-test basis with one line of data for each test result.

```
test ds1-loop 01C07 dsl/csu-loopback-tests
```

### TEST RESULTS

Port	Maintenance Name	Alt. Name	Test No.	Result	Error Code
01C07	DS1-BD		1209	PASS	
01C07	DS1-BD		1210	PASS	
01C07	DS1-BD		1211	PASS	

```
Command Successfully Completed
```

## Field descriptions

Port	Port address (cabinet-carrier-slot-circuit)
Maintenance Name	The name of maintenance object
Alt. Name	The alternate means of identifying the maintenance object.
Test No	The test being executed
Result	Test result: Pass, Abort, Fail, No Board, Disabled, or Extra Bd
Error Code	Numeric code explaining why the release failed or aborted. Refer to the detailed list of the codes by test number for each MO.

## test eda-external-device-alm

This command performs a hardware diagnostic test on all or specific port's administered external device alarms. The test **PASSES** if the external device *is not* reporting an external device alarm and **FAILS** if the external device *is* reporting an external device alarm. If you are entering a specific port, it must already be administered as an external device alarm port on a maintenance or an analog line port carrier board.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>test eda-external-device-alm</b>	<b>physical location</b>	In addition to the word <b>physical</b> , you must enter the physical location ( <b>PCSSpp</b> for an administered external device alarm analog line port). <sup>1</sup>	init inads craft	Repeat = 1	none
	<b>all</b>	Tests all administered external device alarm ports on analog line and maintenance boards.			
	<b>repeat</b>	How many times each test in the sequence is repeated (1-100)			
	<b>clear</b>	This option causes the test sequence (short or long) to repeat until the alarm (if any) is cleared or a single test in the sequence fails. <sup>2</sup>  Examples: <b>test eda-external-device-alm all</b> <b>test eda-external-device-alm physical 1major r 10</b> <b>test eda-external-device-alm physical 2c1101 c</b>			

1. Since the "maintenance board" alarm connections connect to control carrier boards that are in unnumbered slots, the standard port format cannot be used to designate these alarm connections. The special ports **Pmajor** and **Pminor** are used designate the major or minor maintenance board alarm connection for cabinet **P**. The major/minor designation specifies the pair of wires, *not* the alarm level associated with the connection (the "major" port can be administered as a major, minor or warning alarm and the "minor" port can be administered as a major, minor or warning alarm).
2. If no alarms are registered against the maintenance object then the test sequence is run only once. The **long clear** option forces a clear of all alarms if no errors are encountered during testing. The **short clear** option only clears alarms pertinent to tests in the short sequence.

## Output

---

The following example shows the output for the **test external-device-alarm all** command. The responses display on a test-by-test basis with one line of data for each test result.

```
test eda-external-device-alarm all

                                TEST RESULTS

Port      Maintenance Name  Alt. Name  Test No.  Result      Error Code

01major   EXT-DEV                UPS1       120       PASS
01minor   EXT-DEV                UPS1       120       PASS
01c1201   EXT-DEV                UPS1       120       PASS
01c1202   EXT-DEV                AUDIX1     120       PASS

Command successfully completed
```

## Field definitions

Port	Port address (cabinet-carrier-slot-circuit)
Maintenance Name	The name of the maintenance object
Alt. Name	The alternate means of identifying the maintenance object, in this case, the administered (descriptive) name of the external device alarm.
Test No	The test being executed
Result	Test result: Pass, Abort, Fail, No Board, Disabled, or Extra Bd.
Error Code	Numeric code explaining why the release failed or aborted. Refer to the detailed list of the codes by test number for each MO.

## test environment

This command performs hardware diagnostic tests of the environment monitoring and control, and emergency transfer functions of the Processor Port Network (PPN) cabinet. Circuit packs involved are the Processor (PPN simplex systems) and the Duplication Interface circuit packs. The tone/clock circuit pack is involved in tests of the ring generator.

There are 8 Maintenance Objects involved in this testing:

1. CABINET tests air flow and temperature
2. EMG-XFER tests emergency transfer status
3. EXT-DEV tests external
4. RING\_GEN tests ringing voltage are tested in MCC cabinets only.



### NOTE:

The processor carrier is not be recycled. All port carriers are recycled, and service is interrupted for each port carrier. If a carrier containing an active tone-clock board is recycled, all ports in the cabinet or port network will have service disrupted.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
test environment	<i>location</i>	Cabinet 1 = PPN	init inads craft	Cabinet = 1; test sequence = short; repeat = 1	See below
	<i>short</i>	Option for a brief series of nondestructive diagnostic tests.			
	<i>long</i>	Option for a longer, more comprehensive series of both destructive and nondestructive diagnostic tests.			
	<i>repeat number</i>	How many times each test in the sequence is repeated (1-100)			
	<i>clear</i>	This option causes the test sequence (short or long) to repeat until the alarm (if any) is cleared or a single test in the sequence fails. <sup>1</sup>  Examples: <b>test environment</b> <b>test environment 1 sh</b> <b>test environment 1   r 25</b> <b>test environment 01   r 25</b> <b>test environment 2   c</b> <b>test environment 3 c</b>			

1. If no alarms are registered against the maintenance object then the test sequence is run only once. The **long clear** option forces a clear of all alarms if no errors are encountered during testing. The **short clear** option only clears alarms pertinent to tests in the short sequence.

## Feature interactions

---

- The long test recycles power in some specified cabinet on non-SPE and maintenance board carriers and is destructive. Specifically, the 'a' carrier of PPNs does not have power recycled.
- All port carriers are recycled, and service is interrupted for each port carrier.
- If a carrier containing an active tone-clock board is recycled, all ports in the cabinet or port network will have service disrupted.

## Output

---

The following example shows the output for the **test environment 1** command to test a PPN cabinet. The responses display on a test-by-test basis with one line of data for each test result.

```
test environment 1
```

```
TEST RESULTS
```

Port	Maintenance Name	Alt. Name	Test No.	Result	Error Code
01	CABINET		122	PASS	
01	EMG-XFER		124	PASS	
01	EXT-DEV		120	PASS	
01	EXT-DEV		120	PASS	
01	RING-GEN		117	PASS	
01	RING-GEN		118	PASS	

```
Command Successfully Completed
```

## Field descriptions

Port	Port address (cabinet-carrier)
Maintenance Name	The name of maintenance object
Alt. Name	Not applicable
Test No.	The test being executed.
Result	Test result: Pass, Abort, Fail, Disabled
Error Code	Numeric code explaining why the release failed or aborted. Refer to the detailed list of the codes by test number for each MO.

## test hardware-group

This command allows a user to perform a set of hardware diagnostic tests on the whole system, a carrier, cabinet, spe, or board. The tests vary according to the configuration of the system and the specified command options. Each test exercises diagnostics on all the hardware in the specified hardware group and reports results of the test along with any possible error codes. Concurrent testing is done to enhance performance, therefore, test results display on the SAT in the order they are received. Consequently, test results of one maintenance object may be intermixed with test results of other maintenance objects.

Because the tests for this command are not destructive, the tests performed on a particular maintenance object with either the **short** or the long **option** may not be the same as the corresponding demand tests.

A hardware-group command executing in the foreground may be cancelled by either pressing the CANCEL key or by entering the **cancel hardware-group** command at a different SAT. However, if the technician wants to cancel a **test hardware-group** command running in the background, the **cancel hardware-group** command can be entered on any SAT. A canceled **test hardware-group** command can be resumed at the point it left off by entering the **resume hardware-group** command. Restarts are not allowed for **test hardware-group** commands entered with either the **all-ports** option or the **spe-interchange** option.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>test hardware-group</b>	<b>system</b>	System-wide test of all hardware-groups	init inads	Test sequence = short; repeat = 1	See below
	<b>carrier location</b>	Carrier address: cabinet (1), carrier (A) <sup>1</sup>			
	<b>cabinet location</b>	Cabinet address (1) <sup>2</sup>			
	<b>board location</b>	Board location: PCSS <sup>3</sup>			
		Examples: <b>test hardware-group system</b> <b>test hardware-group carrier 1a</b> <b>test hardware-group board 01c07</b> <b>test hardware-group spe</b>			

1. The type of carrier may be port, or processor. In the case of a port carrier, all universal port and tone-clock boards (see note 4) and its affiliated MOs residing in the specified carrier are tested. For a processor carrier, all SPE complex and tone-clock boards and affiliated MOs are tested.
2. All PN and PNC related MOs plus cabinet specific MOs, including maintenance boards and environment (ring generator, battery, power, emergency transfer, external alarms, fans, and temperature) are tested if they reside in the specified cabinet location.
3. All MOs on the specified 'board location' including ports are tested.

## Feature interactions

---

test hardware-group	Only one <b>test hardware-group</b> command can be active at any given time.
TTI	If the <b>test hardware-group</b> command is issued with the <b>all-ports</b> option when the TTI background task is active, some unadministered ports may not be tested. In addition, active alarms on line ports may be cleared by this task. The <b>status tti</b> command can be used to determine the state of the TTI background task.
Add Station	If a <b>add station</b> command is entered for an untranslated port at the same time as it is being tested as part of the <b>test hardware-group</b> command with the <b>all-ports</b> option, the error message, <code>Object in use; please try later</code> displays, and the request fails.
Trunk administration	If an attempt is made to add an unadministered trunk port to a trunk group at the same time as it is being tested as part of the <b>test hardware-group</b> with the <b>all-ports</b> option, the error message, <code>Object in use; please try later</code> displays, and the request fails.
Save translation	If the <b>test hardware-group</b> with the <b>all-ports</b> option while a <b>translation save</b> operation is active, some unadministered ports may not be tested. All other hardware will be tested normally.
Hardware alarms	When a hardware error is detected by the <b>test hardware-group</b> command, the hardware goes through the standard escalation strategy. Alarms are raised on hardware that manifest 'hard' errors. This alarming strategy is the same, regardless of whether the ports are translated or not.
System interaction	The performance of <b>test hardware-group</b> is affected by call processing traffic, administration activity, choice of the <b>short</b> or <b>long</b> option, whether the <b>all-ports</b> option is chosen, whether the <b>spe-interchange</b> option is chosen, and other demand maintenance activity.
Scheduled and periodic maintenance	While executing the <b>test hardware-group</b> command, all scheduled background maintenance, periodic background maintenance, and data audits activity is suspended until the command completes. When the <b>test hardware-group</b> command is canceled or completes, all suspended periodic, scheduled, and data audits background maintenance activity will be restarted where it left off.

## Setting the Test Parameters

Once the user has entered the desired action (**test hardware-group**) and the object (board, carrier, etc.), then an options form displays.

```
test hardware-group system                               Page 1 of 1
```

### TEST HARDWARE-GROUP SELECTIONS

Select the desired options for the specified test.

Test sequence: short

Test repetition: repeat\_\_\_\_\_ count: 1

#### Output OPTIONS:

Auto-page? n

Background? n

Failures? n

#### HARDWARE OPTIONS:

All-ports? n

SPE-interchange? n

## Field descriptions

Test sequence	<b>Short</b> (nondestructive) or <b>long</b> (more comprehensive, still nondestructive) test sequence
Test Repetition	<b>repeat</b> - (1-99) each test is executed the number of times specified on each physical object.  <b>continuously</b> -all tests on all the specified hardware run until cancelled by either pressing the CANCEL key or by executing the <b>cancel hardware-group</b> command.
count :	Repeat test sequence value (1-99). If the Test sequence field is set to <b>continuously</b> , then this field disappears from the screen; if this field is set to <b>repeat</b> , then the field appears.
Auto-page?	Provides a new screen every time the SAT screen fills with test results. ( <b>n / y</b> ). The screen does not scroll to accommodate new results; instead a new screen is provided after the current screen fills up.  If the <b>auto-page</b> option is not selected, the SAT screen does not refresh once it is filled, and testing stops until the user enters the PAGE key to continue or the CANCEL key to cancel the testing.  This option is not allowed if the <b>background</b> option is selected.

4 Maintenance Commands for DEFINITY ONE  
test hardware-group

4-254

Background? Run the command in the background, thus freeing the SAT (*n / y*). The error results are tabulated in the error log, but no results display on the terminal.

This option cannot be used if either the **continuously** or the **auto-page** options are selected.

Failures? Only failing test results display (*n / y*). Test results that pass or abort are not displayed. The **failures** option has no effect if entered with the **background** option.

All-ports? Tests all customer translated line and trunk ports as well as a set of untranslated line and trunk ports for boards listed in [Table 4-5](#) (*n / y*).

Table 4-5. Test of 'all ports' option for the following boards:

Board number	Description	Board number	Description
TN413	Digital Line	TN746	16 port Analog Line
TN417	Auxiliary Trunk	TN747B	Central Office Trunk
TN429	Direct Inward/ Outward Dialing Trunk	TN753	Direct-Inward-Dial Trunk
TN436	Direct Inward Dialing Trunk	TN754	Digital Line
TN437	Tie Trunk	TN760C	Tie Trunk
TN438	Central Office Trunk	TN762B	Hybrid Line
TN439	Tie Trunk	TN763C	Auxiliary Trunk
TN447	Central Office Trunk	TN767	DS1 Interface
TN458	Tie Trunk	TN769	Analog Line with Message Waiting
TN459	Direct Inward Dialing Trunk	TN784	Digital Line
TN464C	Universal DS1	TN785	16 port Analog Line
TN465	Central Office Trunk	TN2135	Italian 16 Port Analog Line
TN467	8 port Analog line	TN2136	Digital Line
TN468	16 port Analog line	TN2138	International Central Office Trunk
TN479	16 port Analog line	TN2139	Direct Inward Dialing Trunk
TN497	Tie Trunk	TN2140	Tie Trunk
TN556	ISDNBRI Line	TN2144	Analog Line
TN722B	DS1 Tie Trunk	TN2146	Direct Inward Dialing Trunk
TN726B	Data Line	TN2147	Central Office Trunk

Continued on next page

Table 4-5. Test of 'all ports' option for the following boards: — *Continued*

Board number	Description	Board number	Description
TN735	MET Line	TN2149	Analog Line
TN742	8 port Analog Line	TN2180	16 port Analog line

SPE-interchange? Allow for planned interchange of duplicated SPEs and subsequent testing of both the active and standby SPEs.

## Output

The following example shows the output for the **test hardware-group system** command and assumes that the board in port network 1, carrier c, slot 7 is an analog board with three administered ports and test sequence repeat = 3. Responses to this command running in the foreground display on a test-by-test basis with one line of data for each test result.

```
test hardware-group system
```

### TEST RESULTS

Port	Maintenance Name	Alt. Name	Test No.	Result	Error Code
01C07	ANL-BD		51	PASS	
01C07	ANL-BD		52	PASS	
01C0703	ANL-LINE		35	PASS	
01C0702	ANL-LINE		35	PASS	
01C0703	ANL-LINE		48	PASS	
01C0701	ANL-LINE		35	PASS	
01C0702	ANL-LINE		48	PASS	
01C0703	ANL-LINE		36	PASS	
01C0702	ANL-LINE		36	PASS	
01C0701	ANL-LINE		48	PASS	
01C0701	ANL-LINE		36	PASS	

```
Testing system, 11070 of 12300 (90%) MOs tested for repetition 1
```



Once the call is answered by INADS, the system sends a message with a test alarm type. INADS acknowledges receipt of the message and creates a trouble ticket. The trouble ticket is closed immediately and has a "INADS LINK TEST" message entered in the description field. If an alarm is raised while the test call is up, the system does not send an alarm message over the existing link. The normal retry mechanism is followed, which means an attempt to make a call to INADS to report the error takes place 7 minutes later. An INADS trouble ticket is created only if the connection is successfully established and a message is sent to the system acknowledging that INADS received the system message.

The `Maintain Process Circuit Packs` field must be set to **yes** on the inads and technician permission forms. This will provide permissions to execute the **test inads-link** command. This field can be changed by executing a **change permission login** command.

No alarms are raised on the system and attendant alarm and acknowledgment lamp states are not changed as a result of the **test inads-link** command. The test does not run during periodic or scheduled maintenance.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
test inads-link	1	First OSS telephone number	init inads craft nms	1st OSS number	none
	2	Second OSS telephone number  Examples: <b>test inads-link</b> <b>test inads-link 1</b> <b>test inads-link 2</b>			

## Output

Command successfully completed      Test passed

Command failed      Link was up, there was an active alarm that the switch needs to report, or there was a problem with the call.

 **NOTE:**  
An entry is made in the error log describing why the inads-link test failed.

## test isdnpri-testcall

This command starts an outgoing, asynchronous ISDN-PRI test call in the asynchronous method from a specified trunk. If the test results are PASS, the test call is started. A test result of ABORT means that a resource wasn't available, for example, B-channel or a Maintenance/Test circuit pack. A test result of FAIL denotes that the outgoing ISDN-PRI test call was not established.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>test isdnpri-testcall</b>	<b>group number</b>	The administered group number associated with each trunk group	init inads craft	duration = 8.4 or 9.6 sec	See below
	<b>member number</b>	The administered member number identifying a particular trunk within a trunk group.			
	<b>minute number</b>	Duration of the test call in minutes (1-120)  Examples: <b>test isdnpri-testcall 80/1</b> <b>test isdnpri-testcall 78/2 minutes 10</b> <b>test isdnpri-testcall 78/3 minutes 100 schedule</b>			

### Feature interactions

- Use the **status isdnpri-testcall** command for details on how to access the additional data available after running the test.
- Only one ISDN trunk can be tested per port network at a time. Once testing is completed, another ISDN trunk can be tested in that port network.
- The maximum number of asynchronous outgoing test calls running depends upon the number of Maintenance/Test circuit packs in the system.

## Output

---

The following example shows the output for the test **isdnpri-testcall 80/1** command. The responses display on a test-by-test basis with one line of data for each test result.

```
test isdn-testcall 77/1                               SPE A

                                TEST RESULTS

Port      Maintenance Name  Alt. Name  Test No.  Result      Error Code
01B1501   ISDN-TRK              077/001   258       PASS

Command Successfully Completed
```

## Field descriptions

Port	Port address: cabinet-carrier-slot-circuit
Maintenance Name	The name of the maintenance object being tested.
Alt. Name	Alternate means of identifying the maintenance object: trunk object <i>xxx/yyy</i> , where <i>xxx</i> = trunk group number, <i>yyy</i> = member number
Test No	The test being executed
Result	Test result: Pass, Abort, Fail, No Board, Disabled, or Extra Bd.
Error Code	Numeric code explaining why the release failed or aborted. Refer to the detailed list of the codes by test number for each MO.

## **test led**

This command performs a test on all the LEDs in a specified cabinet. Once the cabinet is validated and the range of circuit packs determined, the **test led** command turns on all LEDs on the circuit packs contained in each carrier until all affected carriers are lit. Once all the LEDs are on, there is a 2-second pause, and then all the LEDs are turned off in the same order. Once all of the repeat cycles are completed, all affected LEDs are restored to the current status.

The following LEDs are NOT lighted by the **test led** command:

- Power Unit LEDs
- OK to remove LED

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>test led</b>	<i>all</i>	All LEDs in all carriers are tested	init inads craft	all; repeat = 1; test sequence = short in a duplex system	none
	<i>cabinet number</i>	Cabinet number (each carrier tested sequentially)			
	<i>short</i>	Simplex: short and long option are identical and turn on and off all leds in the specified port network.			
	<i>long</i>	Short and long option are identical and turn on and off all leds in the specified port network.			
	<i>repeat number</i>	Number of times each test in the sequence is repeated (1-100)  Examples: <b>test led</b> <b>test led all r 2</b> <b>test led cabinet 1</b> <b>test led c 1</b> <b>test led 1 long</b>			

## **test modem-pool**

This section will be added at a later date.

## test packet-interface

---

This command performs hardware diagnostic tests on the packet interface circuit packs in a specified carrier. Tests performed include local memory checksum tests and checks of failure counters.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>test pkt-interface</b>	<b>location</b>	The packet interface to be tested: <i>nn</i> (cabinet 1-3 + carrier letter)	init inads craft	test sequence = short; repeat number = 1	see below
	<b>short</b>	Option for a brief series of nondestructive diagnostic tests.			
	<b>long</b>	Option for a longer, more comprehensive series of both destructive and nondestructive diagnostic tests.			
	<b>repeat number</b>	How many times each test in the sequence is repeated (1-100)			
	<b>clear</b>	This option causes the test sequence (short or long) to repeat until the alarm (if any) is cleared or a single test in the sequence fails. <sup>1</sup>  Examples: <b>test packet-interface 01a</b>			

1. If no alarms are registered against the maintenance object then the test sequence is run only once. The **long clear** option forces a clear of all alarms if no errors are encountered during testing. The **short clear** option only clears alarms pertinent to tests in the short sequence.

## Feature interactions

---

If the packet-interface circuit pack is in the “out-of-service” or “uninstalled” states, no demand, scheduled, periodic, or error tests can run. See also [“reset packet-interface” on page 4-124](#) and [“status packet-interface” on page 4-204](#).

## Output

The following example is the output for the **test packet-interface 1a1** command. The responses display on a test-by-test basis with one line of data for each test result.

```
test packet-interface 1a1

                                TEST RESULTS

Port      Maintenance Name  Alt. Name Test No. Result      Error Code
01A1      PKT_INT                887      PASS

Command Successfully Completed
```

## test pkt

The test pkt runs a series of tests on the Packet bus of the specified PPN.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>test pkt</b> <b>port-network</b>	<b>pn</b> <b>number</b>	The Packet bus to be tested: <i>nn</i> (1)	init inads craft	Test Sequence = short; Repeat = 1	none
	<b>short</b>	Option for a brief series of nondestructive diagnostic tests.			
	<b>long</b>	Option for a longer, more comprehensive series of both destructive and nondestructive diagnostic tests.			
	<b>repeat</b> <b>number</b>	How many times each test in the sequence is repeated (1-100)			
	<b>clear</b>	This option causes the test sequence (short or long) to repeat until the alarm (if any) is cleared or a single test in the sequence fails. <sup>1</sup>  Examples: <b>test pkt port-network 1 l</b> <b>test pkt port-network 1 sh r 2</b> <b>test pkt port-network 1 l r 25</b> <b>test pkt port-network 1</b> <b>test pkt port-network 1 c</b>			

1. If no alarms are registered against the maintenance object then the test sequence is run only once. The **long clear** option forces a clear of all alarms if no errors are encountered during testing. The **short clear** option only clears alarms pertinent to tests in the short sequence. SEE WARNING BELOW.

**WARNING:**

Since the "clear long" options clear all counters if tests pass, it is possible for firmware counters to be cleared even when a problem exists. In some cases customer service might degrade since calls may be routed over defective equipment.

## Output

---

The following example is the output for the **test pkt port-network 1** command. The responses display on a test-by-test basis with one line of data for each test result.

```
test pkt port-network 1
```

```
TEST RESULTS
```

Port	Maintenance Name	Alt. Name	Test No.	Result	Error Code
PN 01	PKT-BUS		571	PASS	
PN 01	PKT-BUS		572	PASS	
PN 01	PKT-BUS		573	PASS	

```
Command successfully completed
```

## Field descriptions

Port	Port network number (1)
Maintenance Name	The name of maintenance object being tested.
Alt. Name	Not applicable.
Test No	The test being executed
Result	Test result: Pass, Abort, Fail, No Board, Disabled, Extra Bd.
Error Code	Numeric code explaining why the release failed or aborted. Refer to the detailed list of the codes by test number for each MO.

## test port

This command performs hardware diagnostic tests on an individual port circuit. In most cases, tests are performed on hardware connected to the port.

Action/ Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>test port</b>	<b>location</b>	<b>PCSSpp</b>	init inads craft	Test Sequence = short; Repeat = 1	none
	<b>short</b>	Option for a brief series of nondestructive diagnostic tests.			
	<b>long</b>	Option for a longer, more comprehensive series of both destructive and nondestructive diagnostic tests.			
	<b>repeat number</b>	How many times each test in the sequence is repeated (1-100)			
	<b>clear</b>	This option causes the test sequence (short or long) to repeat until the alarm (if any) is cleared or a single test in the sequence fails. <sup>1</sup>  Examples: <b>test port 01c1101 l</b> <b>test port 02e1502 sh r 2</b> <b>test port 02d1201 r 4</b> <b>test port 01c1101 c</b>			

1. If no alarms are registered against the maintenance object then the test sequence is run only once. The **long clear** option forces a clear of all alarms if no errors are encountered during testing. The **short clear** option only clears alarms pertinent to tests in the short sequence. SEE WARNING BELOW.



### WARNING:

*Since the "clear long" options clear all counters if tests pass, it is possible for firmware counters to be cleared even when a problem exists. In some cases customer service might degrade since calls may be routed over defective equipment.*

## Output

The following example is the output for the **test port** command and assumes that the port in cabinet 1, carrier c, slot 7, circuit 1 is an analog port. The responses display on a test-by-test basis with one line of data for each test result.

```
test port 01c0701 short
```

### TEST RESULTS

Port	Maintenance Name	Alt. Name	Test No.	Result	Error Code
01C0701	ANL-LINE		35	PASS	
01C0701	ANL-LINE		48	PASS	
01C0701	ANL-LINE		36	PASS	

```
Command Successfully Completed
```

## Field descriptions

Port	Port address (cabinet-carrier-slot-circuit)
Maintenance Name	The name of maintenance object.
Alt. Name	The alternate means of identifying the maintenance object.
	<b>If the Object is a    The field contains</b>
	station                    extension
	trunk                      xxx/yyy (xxx = trunk group number and yyy = member number)
	private CO line        P/xxx (xxx = private CO line group number)
Test No	Test being executed.
Result	Test result: Pass, Abort, Fail, No Board, Disabled, Extra Bd.
Error Code	Numeric code explaining why the release failed or aborted. Refer to the detailed list of the codes by test number for each MO.

## test pri-endpoint

This command performs hardware diagnostic tests on all port circuits (B-channels) that are associated with the specified PRI endpoint.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>test pri-endpoint</b>	<b><i>extension</i></b>	PRI endpoint extension to be tested (must conform to dial-plan)	init inads craft nms	Test Sequence = short; Repeat = 1	none
	<b><i>short</i></b>	Option for a brief series of nondestructive diagnostic tests.			
	<b><i>long</i></b>	Option for a longer, more comprehensive series of both destructive and nondestructive diagnostic tests.			
	<b><i>repeat number</i></b>	How many times each test in the sequence is repeated (1-100)			
	<b><i>clear</i></b>	This option causes the test sequence (short or long) to repeat until the alarm (if any) is cleared or a single test in the sequence fails. <sup>1</sup>  Examples: <b>test pri-endpoint 25012</b> <b>test pri-endpoint 45002 sh</b> <b>test pri-endpoint 45892 l</b> <b>test pri-endpoint 24389 sh r 4</b> <b>test pri-endpoint 34899 l r 6</b> <b>test pri-endpoint 34912 l r 5</b> <b>schedule</b> <b>test pri-endpoint 93483 r 2</b> <b>test pri-endpoint 10022 c</b>			

1. If no alarms are registered against the maintenance object then the test sequence is run only once. The ***long clear*** option forces a clear of all alarms if no errors are encountered during testing. The ***short clear*** option only clears alarms pertinent to tests in the short sequence.

## Output

The following output example is for the **test pri-endpoint 22501** command and assumes that the PRI endpoint ports for extension 22501 are in cabinet 1, carrier B, slot 20, circuits 1 to 3. The responses display on a port-by-port and test-by-test basis with one line of data for each test result.

```
test pri-endpoint 22501 short                page 1 of 1

                                TEST RESULTS

Port      Maintenance Name  Alt. Name  Test No.  Result    Error Code
01B2001   PE-BCHL            22501     36        PASS
01B2001   PE-BCHL            22501     255       PASS
01B2001   PE-BCHL            22501     256       PASS
01B2001   PE-BCHL            22501     257       PASS
01B2002   PE-BCHL            22501     36        PASS
01B2002   PE-BCHL            22501     255       PASS
01B2002   PE-BCHL            22501     256       PASS
01B2002   PE-BCHL            22501     257       PASS
01B2003   PE-BCHL            22501     36        PASS
01B2003   PE-BCHL            22501     255       PASS
01B2003   PE-BCHL            22501     256       PASS
01B2003   PE-BCHL            22501     257       PASS
```

Command Successfully Completed

## Field descriptions

Port	The port address (cabinet-carrier-slot-circuit)
Maintenance Name	The maintenance object name (PE-BCHL)
Alt. Name	The specified extension number of the PRI endpoint.
Test No	The actual test being executed
Result	Test result: Pass, Abort, Fail, No Board, Disabled, Extra Bd.
Error Code	Numeric code explaining why the release failed or aborted. Refer to the detailed list of the codes by test number for each MO.

## test pr-maintenance

The test pr-maintenance command tests the maintenance functions associated with the TN795. This is a new command for CONTRY.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>test pr-maintenance</b>	<b>short</b>	Option for a brief series of nondestructive diagnostic tests.	init inads craft super-user	Test Sequence = short; Repeat = 1	none
	<b>long</b>	Option for a longer, more comprehensive series of both destructive and nondestructive diagnostic tests.	any customer type login with Maintain Processor Circuit Packs permissions enabled		
	<b>repeat number</b>	How many times each test in the sequence is repeated (1-100)			
	<b>clear</b>	This option causes the test sequence (short or long) to repeat until the alarm (if any) is cleared or a single test in the sequence fails. <sup>1</sup>			

1. If no alarms are registered against the maintenance object then the test sequence is run only once. The **long clear** option forces a clear of all alarms if no errors are encountered during testing. The **short clear** option only clears alarms pertinent to tests in the short sequence.

## Output

The following output example is for the **test pr-maintenance** command. The responses display on a test-by-test basis with one line of data for each test result.

```

test pr-maint                                     page 1
                                     TEST RESULTS
Port      Maintenance Name  Alt. Name  Test No.  Result  Error
Code
01A      PR-MAINT             102        PASS
01A      PR-MAINT             106        PASS
    
```

## Field descriptions

Port	Port address (cabinet carrier) of the maintenance object being tested
Maintenance Name	Name of the MO being tested
Alt. Name	Not applicable for this maintenance object
Test No.	The actual test that is being executed
Result	Test result: Pass, Abort, Fail, No Board
Error Code	Numeric code explaining why the release failed or aborted. Refer to the detailed list of the codes by test number for each MO.

## test signaling-group

This command validates that the specified signaling group is administered and runs a series of diagnostic tests that return results of the test along with possible error codes. A signaling group is a collection of B-channels signaled for by a designated single D-channel or set of D-channels over an ISDN-PRI.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>test signaling-group</b>	<b>group identifier</b>	The station extension (must conform to dial-plan)	init inads craft	Test Sequence = short; Repeat = 1	See below
	<b>short</b>	Option for a brief series of nondestructive diagnostic tests.			
	<b>long</b>	Option for a longer, more comprehensive series of both destructive and nondestructive diagnostic tests.			
	<b>repeat number</b>	How many times each test in the sequence is repeated (1-100)			
	<b>clear</b>	This option causes the test sequence (short or long) to repeat until the alarm (if any) is cleared or a single test in the sequence fails. <sup>1</sup>  Examples: <b>test signaling-group 1</b> <b>test signaling-group 1 repeat 10</b> <b>test signaling-group 2 short</b> <b>test signaling-group 4 long</b> <b>test signaling-group 4 long clear</b>			

1. If no alarms are registered against the maintenance object then the test sequence is run only once. The **long clear** option forces a clear of all alarms if no errors are encountered during testing. The **short clear** option only clears alarms pertinent to tests in the short sequence. SEE WARNING BELOW.

**WARNING:**

Since the "clear long" options clear all counters if tests pass, it is possible for firmware counters to be cleared even when a problem exists. In some cases customer service might degrade since calls may be routed over defective equipment.

## Feature interactions

---

Additional data is available after running a test. See the **status signaling-group** command for how to access the additional data.

## Output

---

The following output example is for the **test signaling-group 1** command. The responses display on a test-by-test basis with one line of data for each test result.

```
test signaling-group 1                               SPE A

                                     TEST RESULTS

Port      Maintenance Name  Alt. Name  Test No.  Result      Error Code
1         ISDN-SGR             636       PASS
1         ISDN-SGR             639       PASS
1         ISDN-SGR             637       PASS

Command Successfully Completed
```

## Field descriptions

Port	The signaling group number (1-8) of the signaling group that is being tested.
Maintenance Name	The type of maintenance object that is being tested.
Alt. Name	Not Applicable.
Test No	Test being executed
Result	Test result: Pass, Abort, Fail, No Board, Disabled, Extra Bd.
Error Code	Numeric code explaining why the release failed or aborted. Refer to the detailed list of the codes by test number for each MO.

## test station

This command performs hardware diagnostic tests on an individual port circuit assigned to that extension. The technician must specify the extension and a translation is automatically done to the physical port location.

Action/ Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
test station	<b>extension</b>	The station extension (must conform to dial-plan)	init inads craft cust nms	Test Sequence = short; Repeat = 1	none
	<b>short</b>	Option for a brief series of nondestructive diagnostic tests.			
	<b>long</b>	Option for a longer, more comprehensive series of both destructive and nondestructive diagnostic tests.			
	<b>repeat number</b>	How many times each test in the sequence is repeated (1-100)			
	<b>clear</b>	This option causes the test sequence (short or long) to repeat until the alarm (if any) is cleared or a single test in the sequence fails. <sup>1</sup>  Examples: <b>test station 81709 l</b> <b>test station 85136 s r 2</b> <b>test station 85036 l r 25</b> <b>test station 84297 r 4</b> <b>test station 81709 c</b>			

1. If no alarms are registered against the maintenance object then the test sequence is run only once. The **long clear** option forces a clear of all alarms if no errors are encountered during testing. The **short clear** option only clears alarms pertinent to tests in the short sequence. SEE WARNING BELOW.

### WARNING:

*Since the "clear long" options clear all counters if tests pass, it is possible for firmware counters to be cleared even when a problem exists. In some cases customer service might degrade since calls may be routed over defective equipment.*

## Output

---

The following screen is an example of the output from the **test station 81902 short** command with the assumptions that port in cabinet 1, carrier c, slot 7, circuit 1 is an analog port and extension 81902 is connected to that port. The responses display on a test-by-test basis with one line of data for each test result.

```
test station 81902 short
```

```
TEST RESULTS
```

Port	Maintenance Name	Alt. Name	Test No.	Result	Error Code
01C0701	ANL-LINE		35	PASS	
01C0701	ANL-LINE		48	PASS	
01C0701	ANL-LINE		36	PASS	

```
Command Successfully Completed
```

## Field descriptions

Port	The port address: cabinet-carrier-slot-circuit
Maintenance Name	The type of maintenance object that is being tested.
Alt. Name	Alternate means of identifying the maintenance object. This field contains the extension when the object is a station.
Test No	Test being executed
Result	Test result: Pass, Abort, Fail, No Board, Disabled, Extra Bd.
Error Code	Numeric code explaining why the release failed or aborted. Refer to the detailed list of the codes by test number for each MO.

## test switch-control

This is an existing command that tests the archangel. It will be modified for DEFINITY on CONTRY to test the archangel firmware on the MPC860.

Action/ Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>test switch-control</b>	<b>short</b>	Option for a brief series of nondestructive diagnostic tests.	init	Test	none
	<b>long</b>	Option for a longer, more comprehensive series of both destructive and nondestructive diagnostic tests.	inads craft cust super-user	Sequence = short; Repeat = 1	
	<b>repeat number</b>	How many times each test in the sequence is repeated (1-100)			
	<b>clear</b>	This option causes the test sequence (short or long) to repeat until the alarm (if any) is cleared or a single test in the sequence fails. <sup>1</sup>			

1. If no alarms are registered against the maintenance object then the test sequence is run only once. The **long clear** option forces a clear of all alarms if no errors are encountered during testing. The **short clear** option only clears alarms pertinent to tests in the short sequence. SEE WARNING BELOW.

## Output

The following output example is for the **test switch-control** command. The responses display on a test-by-test basis with one line of data for each test result.

```

test switch-control                                page 1
                                     TEST RESULTS
Port      Maintenance Name  Alt. Name  Test No.  Result  Error Code
01A       SW-CTL                92         PASS
01A       SW-CTL                94         PASS
    
```

## Field descriptions

Port	Port address (cabinet carrier) of the maintenance object being tested
Maintenance Name	Name of the MO tested
Alt. Name	Not applicable for this maintenance object
Test No.	The actual test that is being executed
Result	Test result: Pass, Abort, Fail, No Board
Error Code	Numeric code explaining why the release failed or aborted. Refer to the detailed list of the codes by test number for each MO.

## test synchronization

This command updates all the boards with the correct synchronization source and parameters. The system sends a downlink message to the tone clock and DS1 boards to place them in the correct synchronization configuration, providing error-free digital communication between the switch and other PBXs, COs, or customer premise equipment.

Action/ Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
test synch	<b>short</b>	Option for a brief series of nondestructive diagnostic tests.	init inads craft	Test Sequence = short; Repeat = 1	none
	<b>long</b>	Option for a longer, more comprehensive series of both destructive and nondestructive diagnostic tests.			
	<b>repeat number</b>	How many times each test in the sequence is repeated (1-100)			
	<b>clear</b>	This option causes the test sequence (short or long) to repeat until the alarm (if any) is cleared or a single test in the sequence fails. <sup>1</sup>  Examples: <b>test synchronization r 3</b> <b>test synchronization sh r 1</b> <b>test synchronization l</b>			

1. If no alarms are registered against the maintenance object then the test sequence is run only once. The **long clear** option forces a clear of all alarms if no errors are encountered during testing. The **short clear** option only clears alarms pertinent to tests in the short sequence.

## Output

---

The following screen is an example of the output for the **test synchronization short** command. The responses are displayed on a test-by-test basis with one line of data for each test result.

```
test synchronization short
```

```
TEST RESULTS
```

Port	Maintenance Name	Alt. Name	Test No.	Result	Error Code
	SYNC		417	PASS	

```
Command Successfully Completed
```

## Field descriptions

Port	Not applicable
Maintenance Name	Maintenance object name
Alt. Name	Not applicable
Test No.	Test being executed
Result	Test result: Pass, Abort, Fail, No Board, Disabled, Extra Bd.
Error Code	Numeric code explaining why the release failed or aborted. Refer to the detailed list of the codes by test number for each MO.

## test sys-link

This command validates the specified link and runs diagnostic tests on the hardware objects that comprises the system link. If the **current** or **faulted** options are specified, tests are run on all hardware objects that comprise the specified link. If **current** or **faulted** is not specified, only the end-to-end sys-link connection is tested.

The hardware path that comprises a system link consists of up to 21 hardware components that affect the behavior of the link. The number of components of a given system link hardware path depends on the system configuration and type of system link.

Action/ Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>test sys-link</b>	<b>location</b>	Port location associated with the system link.	init inads craft		none
	<b>current</b>	Current hardware path tested			
	<b>faulted</b>	Tests the hardware path of the system link as it was constituted when a fault last caused the link to go down.			
	<b>short</b>	Option for a brief series of nondestructive diagnostic tests.			
	<b>long</b>	Option for a longer, more comprehensive series of both destructive and nondestructive diagnostic tests.			
	<b>repeat number</b>	How many times each test in the sequence is repeated (1-100)			
	<b>clear</b>	This option causes the test sequence (short or long) to repeat until the alarm (if any) is cleared or a single test in the sequence fails. <sup>1</sup>  Examples: <b>test sys-link 2e0201 current</b> <b>test sys-link 2e0201 faulted r 10</b>			

1. If no alarms are registered against the maintenance object then the test sequence is run only once. The **long clear** option forces a clear of all alarms if no errors are encountered during testing. The **short clear** option only clears alarms pertinent to tests in the short sequence.

#### 4 Maintenance Commands for DEFINITY ONE

*test sys-link*

4-277

## Output

The following example shows the output from the **test sys-link 01A0516 current** command.

```
test sys-link 01A0516 current                               Page 1  SPE A
                                                           TEST RESULTS
Port      Maintenance Name  Alt. Name  Test No.  Result      Error Code
01A0516   SYS-LINK                PRI        985       PASS
01A       PKT-INT                  886       PASS
01A       PKT-INT                  887       PASS
PN 01A    TDM-BUS                  294       PASS
PN 01A    TDM-BUS                  296       PASS

press CANCEL to quit -- press NEXT PAGE to continue
```

## Field descriptions

Port	Port address
Maintenance Name	Maintenance object name
Alt. Name	Alternate means of identifying the link
Test No.	Test being executed
Result	Test result: Pass, Abort, Fail, No Board, Disabled, Extra Bd.
Error Code	Numeric code explaining why the release failed or aborted. Refer to the detailed list of the codes by test number for each MO.

## test tdm

This command tests all the time slots on a bus associated with a PPN or an EPN.

Action/ Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
test tdm	<i>pn number</i>	<i>nn</i> = number of the port network to have its TDM bus tested. Both halves ("a" and "b") of the TDM bus are tested.	init inads craft	Test Sequence = short; Repeat = 1	none
	<i>short</i>	Option for a brief series of nondestructive diagnostic tests.			
	<i>long</i>	Option for a longer, more comprehensive series of both destructive and nondestructive diagnostic tests.			
	<i>repeat number</i>	How many times each test in the sequence is repeated (1-100)			
	<i>clear</i>	This option causes the test sequence (short or long) to repeat until the alarm (if any) is cleared or a single test in the sequence fails. <sup>1</sup>  Examples: <b>test tdm port-network 1 l</b> <b>test tdm port-network 2 sh r 2</b> <b>test tdm port-network 1 l r 25</b> <b>test tdm port-network 2</b> <b>test tdm port-network 1 c</b>			

1. If no alarms are registered against the maintenance object then the test sequence is run only once. The **long clear** option forces a clear of all alarms if no errors are encountered during testing. The **short clear** option only clears alarms pertinent to tests in the short sequence.

## Output

---

The following example shows the output for the **test tdm port-network 1** command. The responses display on a test-by-test basis with one line of data for each test result.

```
test tdm port-network 1
```

### TEST RESULTS

Port	Maintenance Name	Alt. Name	Test No.	Result	Error Code
PN 01A	TDM-BUS		294	PASS	
PN 01A	TDM-BUS		296	PASS	
PN 01A	TDM-BUS		297	PASS	
PN 01B	TDM-BUS		294	PASS	
PN 01B	TDM-BUS		296	PASS	
PN 01B	TDM-BUS		297	PASS	

```
Command Successfully Completed
```

## Field descriptions

Port	For TDM-BUS maintenance object the port network number and the bus (A or B) is displayed.
Maintenance Name	Maintenance object name
Alt. Name	Not applicable.
Test No	Test being executed
Result	Test result: Pass, Abort, Fail, No Board, Disabled, Extra Bd.
Error Code	Numeric code explaining why the release failed or aborted. Refer to the detailed list of the codes by test number for each MO.

## test tone-clock

The test tone/clock command performs hardware diagnostic tests on a specified tone or clock circuit pack.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>test tone-clock</b>	<b>location</b>	PCSS	init inads craft	Test Sequence = short; Repeat = 1	none
	<b>short</b>	Option for a brief series of nondestructive diagnostic tests.			
	<b>long</b>	Option for a longer, more comprehensive series of both destructive and nondestructive diagnostic tests.			
	<b>repeat number</b>	How many times each test in the sequence is repeated (1-100)			
	<b>clear</b>	This option causes the test sequence (short or long) to repeat until the alarm (if any) is cleared or a single test in the sequence fails. <sup>1</sup>  Examples: <b>test tone-clock 01a l</b>			

1. If no alarms are registered against the maintenance object then the test sequence is run only once. The **long clear** option forces a clear of all alarms if no errors are encountered during testing. The **short clear** option only clears alarms pertinent to tests in the short sequence.

## Output

The following is the output for the **test tone-clock 1a** command. The responses display on a test-by-test basis with one line of data for each test result.

```
test tone-clock 1a
```

TEST RESULTS

Port	Maintenance Name	Alt. Name	Test No.	Result	Error Code
01A	TONE-BD		46	PASS	
01A	TONE-BD		52	PASS	
01A	TONE-PT		40	PASS	
01A	TONE-PT		41	PASS	
01A	TDM-CLK		148	PASS	
01A	TDM-CLK		149	PASS	
01A	TDM-CLK		150	PASS	
01A	TDM-CLK		151	PASS	
01A	TDM-CLK		574	PASS	

Command Successfully Completed

## Field descriptions

Port	The port address: cabinet-carrier-slot-circuit
Maintenance Name	Maintenance object name: TONE-BD, TONE-PT, and TDM-CLK.
Alt. Name	Not applicable.
Test No	Test being executed
Result	Test result: Pass, Abort, Fail, No Board, Disabled, or Extra Bd.
Error Code	Numeric code explaining why the release failed or aborted. Refer to the detailed list of the codes by test number for each MO.

## test translation-store

This is a new command that tests the DEFINITY translation data stored on the hard disk.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>test translation-store</b>	<b>short</b>	Option for a brief series of nondestructive diagnostic tests.	init inads craft	Test Sequence = short; Repeat = 1	none
	<b>long</b>	Option for a longer, more comprehensive series of both destructive and nondestructive diagnostic tests.	cust		
	<b>repeat number</b>	How many times each test in the sequence is repeated (1-100)			
	<b>clear</b>	This option causes the test sequence (short or long) to repeat until the alarm (if any) is cleared or a single test in the sequence fails. <sup>1</sup>			

1. If no alarms are registered against the maintenance object then the test sequence is run only once. The **long clear** option forces a clear of all alarms if no errors are encountered during testing. The **short clear** option only clears alarms pertinent to tests in the short sequence.

## Output

---

The following output example is for the **test translation-store** command. The responses display on a test-by-test basis with one line of data for each test result.

```
test translation-store
```

```
TEST RESULTS
```

Port	Maintenance Name	Alt. Name	Test No.	Result
01A	TRAN-STO		694	PASS

## Field descriptions

Port	The port address: cabinet-carrier
Maintenance Name	Maintenance object name being tested
Alt. Name	Not applicable.
Test No	Test being executed
Result	Test result: Pass, Abort, Fail
Error Code	A system-generated number indicating the reason that the test for the named MO failed or aborted.

## test trunk

---

This command performs hardware diagnostic tests on an entire trunk group or an individual trunk group member, depending on the options entered.

Action/ Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>test trunk</b>	<b>group number</b>	Administered group number (1-99)	init inads craft cust	Test Seq. = short; Repeat = 1	none
	<b>member number</b>	Administered number identifying a particular trunk within a trunk group (1-99).			
	<b>short</b>	Command executes a series of nondestructive diagnostic tests.			
	<b>long</b>	Command executes a more comprehensive and longer version of the both destructive and nondestructive diagnostic tests.			
	<b>repeat number</b>	How many times each test in the sequence is repeated (1-100)			
	<b>clear</b>	This option causes the test sequence (short or long) to repeat until the alarm (if any) is cleared or a single test in the sequence fails. <sup>1</sup>  Examples: <b>test trunk 78 l</b> <b>test trunk 80/1 sh r 2</b> <b>test trunk 78/2 l r 25</b> <b>test trunk 80</b> <b>test trunk 78 r 4</b> <b>test trunk 78 c</b>			

1. If no alarms are registered against the maintenance object then the test sequence will be exercised only once. The **long clear** option forces a clear of all alarms if no errors are encountered during testing. The **short clear** option only clears alarms pertinent to tests in the short sequence.

## Output

---

The following screen is an example of the output for the **test trunk 78** command. The responses display on a test-by-test basis with one line of data for each test result.

```
test trunk 78
```

```
TEST RESULTS
```

Port	Maintenance Name	Alt. Name	Test No.	Result	Error Code
01C1505	CO-TRK	078/001	3	PASS	
01C1505	CO-TRK	078/001	36	PASS	

```
Command Successfully Completed
```

## Field descriptions

Port	The port address: cabinet-carrier-slot-circuit
Maintenance Name	The name of maintenance object being tested.
Alt. Name	The alternate means of identifying the maintenance object. If the object is a trunk, the field contains xxx/yyy (where xxx = trunk group number, yyy = member number). If the object is a private CO line, the field contains P/xxx (where xxx = private CO line group number).
Test No	The test number being executed
Result	The result of the individual test: PASS, ABORT, FAIL, NO BOARD, DISABLED, and EXTRA BD.
Error Code	A system-generated number indicating the reason that the test for the named MO failed or aborted.

## test tsc-administered

This command submits a switched services request to run the Temporary Signaling Connection's heartbeat test for all administered TSCs on a signaling group.

Action/Object	Qualifier	Qualifier description	Permissions	Defaults	Feature interactions
<b>test tsc-administered</b>	<b><i>signaling group number/</i></b> <b><i>tsc index</i></b>  <b><i>repeat number</i></b>	Signaling group number (1–8)  The number associated with each TSC in a signaling group.  The number of times each test in sequence is repeated.	init inads craft	repeat = 1	Additional data available after running the test. See <b>status tsc-administered</b> for how to access additional data.

## Output

The following is an example of the output from the **test tsc-administered 1/1** command. The responses display on a test-by-test basis with one line of data for each test result.

```
test tsc-administered 1/1
```

```
TEST RESULTS
```

```
Port      Maintenance Name  Alt. Name  Test No.  Result      Error Code
1/1      TSC-ADM          604       PASS
```

```
Command Successfully Completed
```

4 Maintenance Commands for DEFINITY ONE  
*test tsc-administered*

4-286

## Field descriptions

Port	Port address of the administered temporary signaling connection (format = <i>signaling group no./tsc index</i> )
Maintenance Name	The name of the maintenance object
Alt. Name	Not applicable
Test No.	The test number being executed
Result	Test result: Pass, Abort, Fail, No Board, Disabled, or Extra Bd.
Error Code	A system-generated number indicating the reason that the test for the named MO failed or aborted.

# Maintenance Objects for DEFINITY ONE

# 5

---



**NOTE:**

This document is not intended to solve all troubles. When the limits of these procedures are reached and the problem is not resolved, escalate the problem to a higher level of technical support. Escalation must conform to the procedures in the *Technical and Administration Plan*.

## ABRI-PORT (ASAI ISDN-BRI Port)

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run <sup>1</sup>	Full Name of MO
ABRI-PORT <sup>2</sup>	MAJOR(b)	test port PCSSpp l	ASAI ISDN-BRI Port
ABRI-PORT	MINOR	test port PCSSpp l	ASAI ISDN-BRI Port

- Where P is the port network number (1 for PPN and 2 or 3 for EPN); C is the carrier designation (A, B, C, D, or E); and SS is the address of the slot in the carrier where the circuit pack is located (01, 02, ..., and so forth); and pp is the 2-digit port number (for example, 01).
- The alarm level for ABRI ports may be administered using the **set options** command. The alarm level can be set independently for Off-Board and On-Board alarms to MAJOR for all ABRI ports in the system.

**NOTE:**

Refer to [“BRI-PORT \(ISDN-BRI Port\), ABRI-PORT \(ASAI ISDN-BRI Port\)” on page 5-312](#) for repair procedures.


## ADJLK-IP (ASAI Adjunct IP Link)

### Error log entries and test to clear values

MO name (in alarm log)	Alarm level	Initial command to run	Full name of MO
ADJLK-IP	MAJOR <sup>1</sup>	test adjunct-ip-link 1 <sup>2</sup>	ASAI Adjunct IP link

- The alarm level may be downgraded using the off-board Adjunct Link entry on the Set Options form
- Only one link is supported for the first release of this feature so “1” is the only link number allowed.

The Adjunct IP link is the Adjunct Switch Application Interface (ASAI) proprietary link between DEFINITY ONE and CentreVu-CT. CentreVu-CT is connected to an Ethernet LAN. On DEFINITY ONE, the LAN interface is provided by the Ethernet interface on the TN795 circuit pack or by the C-LAN (Control LAN) TN799 circuit pack. A C-LAN board is normally used only if a private LAN is required for security reasons. For the first release of this connectivity feature, only one of the interfaces (TN795 or C-LAN) can be used on the same system.



\* Only one of these connectivity arrangements can be used

Figure 5-1. Hardware configuration for the ADJLK-IP link

## Error log entries and test to clear values

Table 5-1. ALARM-PT error log entries

Error type	Aux data	Associated test	Alarm level	On/Off board	Test to clear value
0 <sup>1</sup>		Any	Any	Any	test adjunct-ip-link 1
2 (a)	2-102	ASAI Link Status Test (#1365)	None		test adjunct-ip-link 1
18 (b)	0	None	WARNING	OFF	release adjunct-ip-link 1
257 (c)		ASAI Link Status Test (#1365)	MAJOR <sup>2</sup>	OFF	test adjunct-ip-link 1
513 (d)		ASAI Link Status Test (#1365)	WARNING	OFF	test adjunct-ip-link 1
769 (e)		ASAI Heartbeat Test (#1366)	MAJOR	OFF	test adjunct-ip-link 1 long
1025 (f)		ASAI Link Status Test (#1365)	MAJOR	OFF	test adjunct-ip-link 1
2561-2568 (g)		None	None		
3329 (h)		ASAI Link Status Test (#1365)	MAJOR	OFF	test adjunct-ip-link 1
3584-3839 (i)		None	None		
3840 - 4095 (j)		None	None		

1. Run the Short Test sequence first. If all tests pass, run the Long Test Sequence. Refer to the appropriate test description and follow the recommended procedures.
2. The alarm level for ASAI adjuncts may be administered using the set options command for Off-board Adjunct Link Alarms. The alarm level can be set to MAJOR, MINOR, or WARNING for all ASAI adjuncts in the system.

## Notes:

- a. Errors of this type indicate violations of the ISDN-BRI signaling protocol. Timers associated with certain Layer 3 messages have expired before a required response was received. In the following table, the aux data column indicates which timer has just expired. For more information, refer to the Lucent ISDN-BRI Specification.

Aux data	Timer type
2	First T303 (SETUP timer)
3	Second T303 (SETUP timer)
4	T305 (DISConnect timer)
5	First T308 (RELease timer)
6	Second T308 (RELease timer)
10	T316 (REStart timer)
12	T309 (Layer 2 Failure timer)
16	TM100 (Management Information Message timer 1)
17	TM200 (Management Information Message timer 2)
102	TASAI (ASAI Routing Timer)

- b. Error Type: 18 - The adjunct-ip-link has been busied out.
- c. Error Type: 257 - The ASAI link is not in an "established" state.
- d. Error Type: 513 - The ASAI link is hyperactive.
- e. Error Type 769 - No response from the far end to a heartbeat request.
- f. Error Type: 1025: TCP Tunnel Protocol Connection Failure
- g. Error Type: 2561-2568: ASAI Application Message Discard.
- h. Error Type: 3329 - The TCP tunnel connection is not in an "established" state.
- i. Error Types: 3584 -3839. Certain ASAI protocol-specific cause codes are logged by switch software. The cause code can be determined for the following formula:

If the error type is greater than 3712, then the ASAI cause code is equal to the error type minus 3712. This code was sent to the adjunct by the switch.

If the error type is less than 3712, then the ASAI cause code is equal to the error type minus 3584. This code was sent to the switch by the adjunct.

A description of the various ASAI cause values is contained in the "ASAI Cause Values" table that follows. The table shows the actual error log value (3584-3839), rather than the ASAI cause code value. This table also contains recommended craft actions associated with the cause value. Further information can also be found in the AT&T ASAI Specification (AT&T PUB 288-500-03). In addition, the Aux Data field of the Error Log entry contains additional diagnostic information.

j. Error Types: 3840 - 4095. Certain ISDN cause codes are logged by switch software. The cause code can be determined for the following formula:

If the error type is greater than 3968, then the ISDN cause code is equal to the error type minus 3968. This code was sent to the switch by the adjunct.

If the error type is less than 3968, then the ISDN cause code is equal to the error type minus 3840. This code was sent to the adjunct by the switch.

A description of the various ISDN cause values is contained in the "ISDN Cause Values" table that follows. This table also contains recommended craft actions associated with the cause value.

Table 5-2. ASAI cause values

Error log entry	ASAI code	Explanation	Recommendation
3584, 3712	0	(Service or Option Not Available)  Unrecognized ASAI protocol operation	The requested ASAI protocol operation is not implemented by the switch or adjuncts. The Aux Data Field or Error Log entry contains the protocol identifier for the unrecognized operation.  1. Consult switch and adjunct documentation to determine which set of operations is supported by the switch and the adjunct. Adjunct administration turning off operations not implemented by the switch may resolve the problem.  2. If step 1 does not resolve the problem, escalate to the next tier. There are no available internal resources to service switch or adjunct request. System transaction capacity for the adjunct or switch is exceeded.
3624, 3752	40	(Service or Option Not Available)  Resources not available	1. See Recommendation above for Code 0.  2. Re engineering of adjunct services may be required. If the problem persists, escalate the problem to the next tier.

*Continued on next page*

Table 5-2. ASAI cause values — *Continued*

Error log entry	ASAI code	Explanation	Recommendation
3647, 3775	63	(Service or Option Not Available)	<p>The Requested ASAI capability or resource is not available on the switch or adjunct. More than one adjunct may be contending for the same switch resources. There is a potential administration mismatch between the resource domains administered on the switch and those administered on the adjunct.</p> <ol style="list-style-type: none"><li>1. Verify that no overlapping administration of switch resources (e.g., requesting notification on a single domain by multiple adjuncts or multiple adjuncts attempting to control a single call) exists across all adjuncts connected to the switch. If overlaps exists, then readminister the adjuncts to guarantee that each adjunct is associated with a unique set of switch resources.</li><li>2. If Step 1 does not resolve the problem, escalate to the next tier.</li></ol>
3663, 3791	79	(Service or Option Not Implemented)	<p>A requested service or option (or combination of selected options) is not supported (implemented) in the switch or the adjuncts.</p> <ol style="list-style-type: none"><li>1. Consult the switch and adjuncts documentation to determine ASAI service options supported by both the switch and the adjuncts. Readministration of the switch-administered capabilities (see Customer Option Feature Form) or those of the adjunct may be necessary to correct the problem.</li><li>2. If Step 1 does not provide the set of desired services due to deficient implementation, escalate the problem to the next tier.</li></ol>

*Continued on next page*

Table 5-2. ASAI cause values — *Continued*

Error log entry	ASAI code	Explanation	Recommendation
3671, 3799	87	(Switch Error Conditions)  Internal switch audit	There is an inconsistency in switch data records.  1. No action is needed since the switch has corrected the data inconsistency.  2. If a number of these errors continue to occur, then escalate to the next tier.

Table 5-3. ISDN Cause values

ISDN Cause codes			
Error log entry	ISDN code	Explanation	Recommendation
3874, 4002	34	Switch resources not available  No circuit or channel available	There are no available trunks for outgoing call requests:  <ol style="list-style-type: none"><li>1. Verify that the adjunct is administered to support the trunk capabilities of the switch.</li><li>2. Investigate trunk group status by issuing status trunk commands from the SAT or by requesting a trunk group query or queries from the adjunct.</li><li>3. Perform trunk diagnostic procedures outline in this manual.</li></ol>
3890, 4018	50	Requested facility not subscribed	Requested facility is implemented, but not administered. Potential administration problem with endpoint or adjunct.  <ol style="list-style-type: none"><li>1. Display the Customer Optional Features From on the switch to determine which ASAI or Adjunct link capabilities are turned on in the switch</li><li>2. Verify that the adjunct is administered to support the identical capabilities as the switch. If there is a mismatch in the administration capabilities, then readminister the switch and/or the adjunct to match.</li></ol>
3921, 4049	81	Adjunct switch error conditions  Invalid CRV	An invalid CRV was sent by the adjunct.  <ol style="list-style-type: none"><li>1. This may indicate a CRV inconsistency between the switch and the adjunct. See the CallVisor protocol reference manual.</li></ol>

## System technician-demanded tests: descriptions and error codes

Always investigate tests in the order presented in the table below. By clearing error codes associated with the *ASAI Link Status test* for example, you may also clear errors generated from other tests in the testing sequence.

Order of investigation	Short test sequence	Long test sequence	D/ND <sup>1</sup>
ASAI Link Status test (#1365)	X	X	ND
TCP Tunnel Connection Heartbeat test (#1366)		X	ND

1. D = Destructive; ND = Nondestructive

### ASAI Link Status Test (#1365)

#### This test is nondestructive

This test queries the Call Processing software for the state of the TCP Tunnel Connection. If the Tunnel Connection is in the “established” state and if the ASAI link is in the “established” state, the test returns with a PASS. Otherwise, the test fails.

Table 5-4. TEST #1365 ASAI Link Status Test

Error Code	Test Result	Description/ Recommendation
1189	ABORT	The asai adjunct service is not enabled. <ol style="list-style-type: none"> <li>1. Enable the asai service administered for this link on the <i>ip-services</i> form.</li> <li>2. If the test continues to abort, escalate the problem.</li> </ol>
2500	ABORT	Internal System Error <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 3 times.</li> <li>2. If the test continues to abort, escalate the problem.</li> </ol>

*Continued on next page*

Table 5-4. TEST #1365 ASAI Link Status Test — *Continued*

Error Code	Test Result	Description/ Recommendation
1	FAIL	<p>The test failed because the ASAI Adjunct link is not up. The state of the link is represented by the error code as presented in <a href="#">Table 5-5</a>.</p> <ol style="list-style-type: none"> <li>1. Check the link status by entering the status asai/adjunct-ip-link command.</li> <li>2. If the TCP Tunnel Connection is not established:               <ol style="list-style-type: none"> <li>a. Check the entry for the local node on the ip-services form. If the entry is clanX, where X is the board number, refer to the maintenance information for the C-LAN board ("<a href="#">CLAN-BD (Control LAN Circuit Pack)</a>" on page 5-378) to clear the problem. If the entry is procr, refer to the maintenance information for the Processor LAN interface to clear the problem.</li> <li>b. If the test continues to fail, escalate the problem.</li> </ol> </li> <li>3. If the ASAI link is not established but the Connection is established:               <ol style="list-style-type: none"> <li>a. Use the ping command with the IP address for the remote node. This IP address is the IP-Address specified on the Node Names form for the Remote Node specified on the ip-services form. If no response is received, follow the repair procedures above for TCP Tunnel Connection Not Established.</li> <li>b. Use the administration information for the <i>G3 PBX Configuration</i> screen on CentreVu-CT to verify that the ASAI service is administered correctly</li> </ol> </li> </ol>
	PASS	<p>The ASAI link is up. That is, the Tunnel Connection is "established" and the ASAI Link state is "established".</p>

1. Refer to [Table 5-5](#)

Table 5-5. Error Codes for Link Status Test Failures

Error Code	Link Status		
	Connection State Not Established?	Link Hyperactive?	ASAI Link Not Established?
0			
1			X
2		X	
3		X	X
4	X		
5	X		X
6	X	X	
7	X	X	X

### TCP Tunnel Connection Heartbeat Test (#1366)

**This test is nondestructive.**

This test requests that a TCP Tunnel protocol heartbeat message be sent to the far end. It then checks for a response every 2 seconds for a maximum of 20 seconds. The test fails if a response has not been received within 20 seconds.

Table 5-6. TEST #1399 TCP Tunnel Connection Heartbeat Test

Error Code	Test Result	Description/ Recommendation
1189	ABORT	The asai adjunct service is not enabled. <ol style="list-style-type: none"> <li>1. Enable the asai service administered for this link on the <i>ip-services</i> form.</li> <li>2. If the test continues to abort, escalate the problem.</li> </ol>
1190	ABORT	The asai adjunct service has not established the TCP Tunnel. <ol style="list-style-type: none"> <li>1. Check the status of the asai adjunct service using this link.</li> <li>2. If the test continues to abort, escalate the problem.</li> </ol>
2500	ABORT	Internal System Error <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 3 times.</li> <li>2. If the test continues to abort, escalate the problem</li> </ol>

*Continued on next page*

Table 5-6. TEST #1399 TCP Tunnel Connection Heartbeat Test — *Continued*

Error Code	Test Result	Description/ Recommendation
	FAIL	The test failed since a response to the heartbeat message was not received within 20 seconds  1. Check the link status by entering the status asai/adjunct-ip-link command.  a. Follow the repair procedures described for the failure of Test 1400 - ASAI Link Status
	PASS	A response to the heartbeat message was received.

## ADM-CONN (administered connection)

MO name (in alarm log)	Alarm level	Initial command to run <sup>1</sup>	Full name of MO
ADM-CONN	MAJOR	status administered-connection N	Administered Connection
ADM-CONN	MINOR	status administered-connection N	Administered Connection
ADM-CONN	WARNING	status administered-connection N	Administered Connection

1. Where N is an appropriate Administered Connection number determined via the PORT field from the Alarm or Error Log.

An Administered Connection provides an end-to-end connection between two access endpoints or data modules. This connection is automatically established when the administered connection is administered and is due to be active. An error is logged when an administered connection cannot be established or when an established administered connection fails. An alarm is logged when a connection cannot initially be established or fails and cannot be reestablished. An alarming strategy is supported on a per administered connection basis. An alarm is raised for a connection when either the number of consecutive failed attempts to establish the connection reaches the alarm threshold or it can be determined that a failed attempt to establish was due to an administered error. The alarm raised ("major," "minor," "warning," or "none") is specified in the "Alarm Type" field of the Administered Connection Administration Form.

**Error log entries and test to clear values**

**Table 5-7. Administered connection error log entries**

<b>Error type</b>	<b>Aux data</b>	<b>Associated test</b>	<b>Alarm level</b>	<b>On/Off board</b>	<b>Test to clear value</b>
0 (a)(b)(c)(k)	Any	None	Any	OFF	None
1 (a)(b)(c)(d)(e)	Any	None	Any	OFF	None
2 (a)(b)(c)(f)	Any	None	Any	OFF	None
6 (a)(b)(c)(g)	Any	None	Any	OFF	None
16 (a)(b)(c)(k)	Any	None	Any	OFF	None
17 (a)(c)(h)	Any	None	Any	OFF	None
18 (a)(b)(c)(i)	Any	None	Any	OFF	None
21 (a)(b)(c)(g)	Any	None	Any	OFF	None
22 (a)(b)(c)(d)(j)	Any	None	Any	OFF	None
28 (a)(b)(c)(d)(e)	Any	None	Any	OFF	None
29 (a)(b)(c)(k)	Any	None	Any	OFF	None
31 (a)(b)(c)(g)	Any	None	Any	OFF	None
34 (a)(b)(c)(l)	Any	None	Any	OFF	None
38 (a)(b)(c)(m)	Any	None	Any	OFF	None
40 (a)(b)(c)(l)	Any	None	Any	OFF	None
41 (a)(b)(c)(m)	Any	None	Any	OFF	None
42 (a)(b)(c)(l)	Any	None	Any	OFF	None
43 (a)(b)(c)(q)	Any	None	Any	OFF	None
44 (a)(b)(c)(l)	Any	None	Any	OFF	None
50 (a)(b)(c)(d)(n)	Any	None	Any	OFF	None
52 (a)(b)(c)(d)(o)	Any	None	Any	OFF	None
54 (a)(b)(c)(o)	Any	None	Any	OFF	None
58 (a)(b)(c)(l)	Any	None	Any	OFF	None
65 (a)(b)(c)(d)(p)	Any	None	Any	OFF	None
66 (a)(b)(c)(d)(p)	Any	None	Any	OFF	None
69 (a)(b)(c)(d)(p)	Any	None	Any	OFF	None

*Continued on next page*

Table 5-7. Administered connection error log entries — *Continued*

Error type	Aux data	Associated test	Alarm level	On/Off board	Test to clear value
81 (a)(b)(c)(q)	Any	None	Any	OFF	None
82 (a)(b)(c)(r)	Any	None	Any	OFF	None
88 (a)(b)(c)(d)(s)	Any	None	Any	OFF	None
91 (a)(b)(c)(q)	Any	None	Any	OFF	None
95 (a)(b)(c)(q)	Any	None	Any	OFF	None
96 (a)(b)(c)(q)	Any	None	Any	OFF	None
97 (a)(b)(c)(q)	Any	None	Any	OFF	None
98 (a)(b)(c)(q)	Any	None	Any	OFF	None
99 (a)(b)(c)(q)	Any	None	Any	OFF	None
100 (a)(b)(c)(q)	Any	None	Any	OFF	None
102 (a)(b)(c)(i)	Any	None	Any	OFF	None
111 (a)(b)(c)(q)	Any	None	Any	OFF	None
127 (a)(b)(c)(g)	Any	None	Any	OFF	None

## Notes:

- a. These errors have no specific associated test. Refer to Notes [b](#) through [p](#) for an explanation and appropriate action.
- b. These errors are valid only for an administered connection established over ISDN facilities. Only error 127 is valid for an administered connection established over non-ISDN facilities (or between two endpoints on the same switch). The errors are as follows:
  - Aux Data 1 — Administered connection establishment failed
  - Aux Data 2 — Active administered connection failed; attempting reestablishment via auto restoration
  - Aux Data 3 — Auto restoration failed
  - Aux Data 4 — Active administered connection failed; attempting reestablishment via fast retry
  - Aux Data 5 — Fast retry failed

5 Maintenance Objects for DEFINITY ONE  
ADM-CONN (administered connection)

5-16

- c. These errors are typically associated with administrative problems and are not expected to be of a temporary nature. Therefore, the administered connection is not retried and the failure is alarmed immediately (the alarm threshold specified by the customer is ignored).
- d. The address of the destination endpoint is: an unassigned number (1); has an invalid number format (28); or is restricted from terminating calls ("Access Denied") [due to COR (Class of Restriction)]. Verify that the destination address is correct and that the destination endpoint is administered. The destination endpoint is not administered on the switch where this error is logged.
- e. A request has been made to use a transit network or common carrier that cannot be accessed. Check the routing pattern used by this Administered Connection and verify that the inter-exchange carrier specified is correct.
- f. The exact failure cause is unknown or has been mapped to one of these values. If this is not a temporary condition, try reversing the direction of the Administered Connection (that is, originate the Administered Connection from the destination switch). This may yield another failure cause.
- g. The destination endpoint is not available. Check the status of the destination endpoint (using **status access-endpoint** or **status data-module**) and verify that the endpoint is not busy or otherwise unavailable (for example, out-of-service). The status for the destination endpoint is not available on the switch where this error is logged.
- h. This switch sent an ISDN message to another switch, which either did not respond (18) or did not respond within the allotted time (102). This could be due to link failure or congestion or outage at the other switch.
- i. The address of the destination endpoint has changed. Verify that the new address is correct and change the Administered Connection accordingly. The destination endpoint is not administered on the switch logging this error.
- j. Indicate that a resource (for example, a circuit or bearer capability) required by the administered connection is not presently available.
- k. A network failure (38) or temporary failure (41) has occurred. Error Log entries for other maintenance objects (for example, DS1-BD or ISDN-LNK) may indicate a local problem.
- l. A request to use a network service has been denied because the service has not been purchased. Check the routing pattern used by this Administered Connection and verify that the service type is correct. If the service type appears correct, check with the customer or network provider or both to determine what services have been purchased by the customer.

5 Maintenance Objects for DEFINITY ONE  
ADM-CONN (administered connection)

5-17

- m. Indicate that outgoing calls may be barred on the originating switch (52) or that incoming calls may be barred on the destination switch (54). To restore an administered connection failure, issue the **status administered connection** command for current administered connection state (observe the retry count). If the administered connection state is "failed," then verify and correct the Administered Connection Administration Form.
- n. The requested bearer capability (65), channel type (66), or facility (69) is not implemented or is unknown to the network. Check the address of the destination endpoint and the routing pattern used by this Administered Connection, and verify that they are correct and available.
- o. These errors indicate that an ISDN protocol error has occurred.
- p. The destination endpoint (or some intermediate facility) is not compatible with the originating endpoint. Check the BCC fields of the routing pattern used by this Administered Connection. Also, check if the originating and destination endpoints are compatible (for example, the originating access endpoint is voice-grade data, and the destination access endpoint is 64k data).

## ALARM-PT (ALARM port)

---

MO name (in alarm log)	Alarm level	Initial command to run	Full name of MO
ALARM-PT	MAJOR <sup>1</sup>		Alarm Port
ALARM-PT	MINOR	test port long	Alarm Port
ALARM-PT	WARNING	test port sh	Alarm Port

- 
1. The "MAJOR" alarm occurs only at power-up time or on a Reset System 3, 4, or 5 when the switch cannot load all translations from the memory card.
- 

The Alarm Port Maintenance Object provides on-board maintenance for an analog line port that is administered as an external device alarm port.

Tests are provided to verify the analog line port's ability to detect an external device alarm. The external device alarm (EXT-DEV) MO is used for the off-board external device alarm.

For DEFINITY ONE, the analog line port that is administered for an external alarm may be a port on a virtual alarm board located in slot 1A11. The virtual board provides ports for External Device Alarm contacts to indicate to non-DEFINITY alarms or a PC (global) alarm. There is no hardware associated with the virtual alarm board. The MO name for this board is PR-AL-BD and the external name displayed by the list configuration command is VIRTUAL ALARM BOARD. By default, this board is located in slot 1A11.

If the Alarm Port Maintenance Object is located on the virtual alarm board, the maintenance tests described below will always pass and there should never be an alarm or hardware error log entry for that MO.

## Error log entries and test to clear values

---

Table 5-8. ALARM-PT error log entries

Error type	Aux data	Associated test	Alarm level	On/Off board	Test to clear value
0 <sup>1</sup>	0	Any	Any	Any	test port
769(a)	Any	Battery Feed Test (#35)	MINOR	OFF	test port long

1. Run the Short Test sequence first. If all tests pass, run the Long Test Sequence. Refer to the appropriate test description and follow the recommended procedures.

### Notes:

- a. Error Type: 769 - This test (Test #35) always passes for DEFINITY ONE.

## System technician-demanded tests: descriptions and error codes

---

Always investigate tests in the order presented in the table below. By clearing error codes associated with the *Battery Feed Test* for example, you may also clear errors generated from other tests in the testing sequence.

Order of investigation	Short test sequence	Long test sequence	D/ND <sup>1</sup>
Battery Feed Test (#35)		X	ND
Port Updates Test (#36)		X	ND

1. D = Destructive; ND = Nondestructive

**Battery feed test (#35)**

This test checks a port's battery feed circuitry. The battery feed circuitry is tested for proper battery voltage by testing the switchhook state. In response to the test message, the on-board firmware terminates the line and checks for switch-hook presence. The termination is then removed, and a check is made for no switch-hook presence. The MET set must be on-hook for the test to execute.

**NOTE:**

For DEFINITY ONE this test always passes.

Table 5-9. TEST #35 port diagnostic test

Error code	Test result	Description/ Recommendation
	ABORT	Internal system error.  1. Retry the command at 1-minute intervals a maximum of 5 times.
1000	ABORT	System resources required to run this test are not available. The port may be busy with a valid call. Use the <b>display port PCSSpp</b> command to determine the station extension, attendant number, or trunk group/member number of the port. Use the <b>status station, status attendant, or status trunk</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. You must wait until the port is idle before retesting. Attendants are always in use (off-hook) if the handset is plugged in and the port is not busied out.  1. If the port status is idle, then retry the command at 1-minute intervals a maximum of 5 times.

*Continued on next page*

Table 5-9. TEST #35 port diagnostic test — *Continued*

Error code	Test result	Description/ Recommendation
1004	ABORT	<p>The port was seized by a valid call during the test. The test has been aborted. Use the <b>display port PCSSpp</b> command to determine the station extension of the port. Use the <b>status station</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. You must wait until the port is idle before retesting.</p> <p><b>⇒ NOTE:</b> The battery feed circuitry is tested for proper battery voltage by testing the switchhook state. In response to the test message, the on-board firmware terminates the line and checks for switch-hook presence. The termination is then removed, and a check is made for no switch-hook presence. The MET set must be on-hook for the test to execute.</p> <p>1. If the port status is idle, then retry the command at 1-minute intervals a maximum of 5 times.</p>
1018	ABORT	Test disabled via software patch.
2000	ABORT	<p>This port may have been busied out by system technician.</p> <ol style="list-style-type: none"> <li>1. Look in the Error Log for Error Type 18 (port busied out) for this port. If this error type is present, then release the port via the <b>release station &lt;extension&gt;</b> command and run the test again.</li> <li>2. Make sure that the terminal is connected.</li> <li>3. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
2100	ABORT	<p>Could not allocate the necessary system resources to run this test. This could be due to a failure to seize the port.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>

*Continued on next page*

Table 5-9. TEST #35 port diagnostic test — *Continued*

Error code	Test result	Description/ Recommendation
	FAIL	Battery Feed Test failed. This port is out-of-service. <ol style="list-style-type: none"><li>1. Other ports on this circuit pack are not affected. Place user on a different port, if available, until a replacement circuit pack can be obtained.</li><li>2. Replace circuit pack when available.</li></ol>
	PASS	Battery Feed Test passed. Current flow is properly detected for this port. <ol style="list-style-type: none"><li>1. If users are reporting problems, examine connections to the port.</li></ol>
0	NO BOARD	The test could not relate the internal ID to the port (no board). This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted. <ol style="list-style-type: none"><li>1. Check to ensure that the board translations are correct. Use the <b>list config</b> command, and resolve any problems that are found.</li><li>2. If the board was found to be correctly inserted in step 1, issue the <b>busyout board</b> command.</li><li>3. Issue the <b>reset board</b> command.</li><li>4. Issue the <b>release busy board</b> command.</li><li>5. Issue the <b>test board long</b> command. This should re-establish the linkage between the internal ID and the port. If this is not the case, check to ensure that there is a valid board inserted.</li></ol>

**Port updates test (#36)**

This test sends port level translation data from switch processor to the circuit pack to assure that the translation is correct. The port audit operation verifies the consistency of the current state of the port in the switch software.

**TEST #36 audit and update test**

<b>Error code</b>	<b>Test result</b>	<b>Description/ Recommendation</b>
	ABORT	Internal System Error.  1. Retry the command at 1-minute intervals a maximum of 5 times.
1000	ABORT	The test was aborted because system resources required to run this test were not available. The port may be busy with a valid call. Use the <b>display port PCSSpp</b> command to determine the station extension of the port. Use the <b>status station</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. You must wait until the port is idle before retesting.  1. If the port is idle, retry the command at 1-minute intervals a maximum of 5 times.
1006	ABORT	The test was aborted because the station is out of service. This condition may be accompanied by an error type 18 entry in the error log. You may want to determine why the station was taken out of service. (When stations are taken out of service by maintenance software, the problems that preceded that point must be cleared.)  1. Use the <b>status station</b> command to check the service state of the port. If the port is indeed out of service, enter the <b>release station</b> command to bring the station back into service.  2. Retry the command at 1-minute intervals a maximum of 5 times.  3. If the test continues to abort, and the service state indicates that the station is in service and idle, escalate the problem.

---

*Continued on next page*

TEST #36 audit and update test — *Continued*

Error code	Test result	Description/ Recommendation
2000	ABORT	<p>The test was aborted because response to the test was not received within the allowable time period.</p> <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals for a maximum of 5 times.</li><li>2. If the test aborts with error code 2000 again, run short test sequence on the associated DS1-BD or UDS1-BD. If tests 138 through 145 on the associated DS1-BD or UDS1-BD are also aborting with error code 2000, hyperactivity on the board or facility is indicated. In this case, the hyperactivity problem should be dealt with first.</li></ol>
2100	ABORT	<p>System resources required for this test are not available.</p> <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
7 or 8	FAIL	<p>Test failed due to internal system error. Do not replace port board.</p> <ul style="list-style-type: none"><li>■ Error code 7: the failure occurred during station translation download (to DS1 Interface circuit pack).</li><li>■ Error code 8: the failure occurred during station ringer update.</li></ul> <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>

---

*Continued on next page*

TEST #36 audit and update test — *Continued*

Error code	Test result	Description/ Recommendation
	PASS	Trunk translation has been updated successfully. The current trunk states kept in the DS1 Interface circuit pack and switch software are consistent.
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board). This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"><li>1. Check to ensure that the board translations are correct. Use the <b>list config</b> command, and resolve any problems that are found.</li><li>2. If the board was found to be correctly inserted in step 1, issue the <b>busyout board</b> command.</li><li>3. Issue the <b>reset board</b> command.</li><li>4. Issue the <b>release busy board</b> command.</li><li>5. Issue the <b>test board long</b> command. This should re-establish the linkage between the internal ID and the port. If this is not the case, dispatch to check to ensure that there is a valid board inserted.</li></ol>

---

## ANL-16-L (16-Port Neon Analog Line)

MO name (in alarm log)	Alarm level	Initial command to run <sup>1</sup>	Full name of MO
ANL-16-L	MIN	test port PCSSpp l	16-Port Neon Analog Line
ANL-16-L	WRN	test port PCSSpp sh release station <ext>	16-Port Neon Analog Line

- Where P is the port network number (1 for PPN and 2 or 3 for EPN); C is the carrier designation (for example, A, B, C, D, or E); SS is the address of the slot in the carrier where the circuit pack is located (for example, 01, 02, ..., etc.); and pp is the 2-digit port number (for example, 01).

The following are 16-Port Analog Line circuit packs:

TN746	TN746B
TN468 [G3iV2-386]	TN749 [G3iV2-386]
TN468B [G3iV2-386]	TN2135 [G3iV2-386]
TN2144 [G3iV2-386]	TN2149 [G3iV2-386]

These circuit packs provide 16 ports for analog voice terminals. The TN746, TN468, and TN749 support only single-line, on-premises/in-building, analog voice terminals, and not off-premises stations, since these circuit packs are not equipped with lightning protection. The TN746B, TN2144, TN2149, and TN468B support both on-premises and off-premises (that is, out-of-building) analog voice terminals. The TN468, TN468B, TN479, TN2135, TN2144, and TN2149 do NOT support the neon message waiting feature.

Test #48 may cause some terminal equipment to ring briefly during daily maintenance. If this ringing is disturbing the customer or the terminal equipment, it should be disabled via the **change station <extension>** command. However, on some releases of the software, this action disables Tests #6, #7, #161, and #35 as well as Test #48.

No maintenance of the terminal connected to the 16-Port Neon Analog Line circuit pack is performed, except to determine whether or not the terminal is connected. Failures of the neon message waiting lamp power and the common ringing application circuitry are reported as part of the Common Port Circuit Pack errors (see errors 1281 and 1793 in [“XXX-BD \(Common Port Circuit Pack\)” on page 5-1343](#)).

## Hardware error log entries and test to clear values

Table 5-10. 16-Port Neon Analog Line Error Log Entries

Error type	Aux data	Associated test	Alarm level	On/Off board	Test to clear value
0 <sup>1</sup>	0	Any	Any	Any	test port PCSSpp sh r 1
1 (a)	40960 40977	none			
15 (b)	Any	Audits and Updates Test (#36)			
18	0	busyout station <extension>	WRN	ON	release station <extension>
130 (c)		None	WRN	ON	test port PCSSpp sh
257 (d)	40973	none			
513 (e)		Station Present Test (#48)	WRN	OFF	test port PCSSpp sh r 2
769		Battery Feed Test (#35)	MIN/WRN <sup>2</sup>	ON	test port PCSSpp sh r 2
1025		Loop Around Test (#161)	MIN/WRN <sup>2</sup>	ON	test port PCSSpp l r 2
1281		Conference Test (#7)	MIN/WRN <sup>2</sup>	ON	test port PCSSpp l r 2
1537		NPE Crosstalk Test (#6)	MIN/WRN <sup>2</sup>	ON	test port PCSSpp l r 2

1. Run the Short Test Sequence first. If all tests pass, run the Long Test Sequence. Refer to the appropriate test description and follow the recommended procedures.
2. Minor alarms on this MO may be downgraded to Warning alarms based on the values used in the **set options** command.

### Notes:

- a. This is an in-line error and can only be resolved over time. This indicates that no terminal equipment was present when ringing was attempted. Execute the short **test port PCSSpp** command, and follow the procedure for the results of Test #48.
  - 40960 — indicates that too many simultaneous incoming ringing attempts were made on this board. Only four ports on a board may be ringing simultaneously. A fifth incoming call will cause an inline error from the board.

**5 Maintenance Objects for DEFINITY ONE**  
*ANL-16-L (16-Port Neon Analog Line)*

5-28

- 40977 — indicates that no terminal equipment was connected when ringing was attempted. Run the short Test via the **test port PCSSpp** command, and follow the procedure for the results of Test #48.
- b. This is a software audit error that does not indicate any hardware malfunction. Run Short Test Sequence and investigate associated errors (if any).
- c. This error type indicates that the circuit pack has been removed or has been insane for more than 11 minutes. To clear the error, reinsert or replace the circuit pack.
- d. This is an in-line error and can only be resolved over time. This error indicates that ringing voltage is absent. If only one Analog circuit pack in the system has this problem, then replace the circuit pack. If only Analog circuit packs on a particular carrier have this error, then the ringing generator may not be connected to this carrier. If Analog circuit packs on many carriers have this error, then it is probably a problem with the ringing generator.
- e. Test #48 may cause some terminal equipment to ring briefly during daily maintenance. If this ringing is disturbing the customer or the terminal equipment, it should be disabled using the **change station <extension>** command. However, on some releases of the software, this action disables Tests #6, #7, #161, and #35 as well as Test #48.

---

**System Technician-Demanded Tests: Descriptions and Error Codes**

---

Always investigate tests in the order presented in the following table when inspecting errors in the system. By clearing error codes associated with the *Battery Feed Test*, for example, you may also clear errors generated from other tests in the testing sequence.

Order of investigation	Short test sequence	Long test sequence	D/ND <sup>1</sup>
Battery Feed Test (#35)	X	X	ND
Station Present Test (#48)	X	X	ND
Loop Around Test (#161)		X	ND
Conference Test (#7)		X	ND
NPE Crosstalk Test (#6)		X	ND
Station Status and Translation Audits and Updates Test (#36)	X	X	ND

---

1. D = Destructive; ND = Nondestructive

## NPE Crosstalk Test (#6)

---

One or more Network Processing Elements (NPEs) reside on each circuit pack with a TDM Bus interface. The NPE controls port connectivity and gain, and provides conferencing functions on a per-port basis. The NPE Crosstalk Test verifies that this port's NPE channel talks on the selected time slot and never crosses over to time slots reserved for other connections. If the NPE is not working correctly, one-way and noisy connections may be observed. This test is usually only part of a port's Long Test Sequence and takes about 20 to 30 seconds to complete.

Table 5-11. TEST #6 NPE Crosstalk Test

Error Code	Test Result	Description/ Recommendation
	ABORT	Could not allocate the necessary system resources to run this test. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
1000	ABORT	System resources required to run this test are not available. The port may be busy with a valid call. Use the <b>display port PCSSpp</b> command to determine the station extension. Use the <b>status station</b> command to determine the service state of the port. If the service state indicates that the port is in use, the port is unavailable for certain tests. (Refer to " <a href="#">status station</a> " on page 4-213 for a description of all possible states.) You must wait until the port is idle before retesting. <ol style="list-style-type: none"><li>1. If the port status is idle, retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
1001	ABORT	System resources required to run this test are not available. This could be due to a failure to seize the port. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
1002	ABORT	The system could not allocate time slots for the test. The system may be under heavy traffic conditions or it may have time slots out-of-service due to TDM-BUS errors. Refer to " <a href="#">TDM-BUS (TDM Bus)</a> " on page 5-1116 to diagnose any active TDM-BUS errors. <ol style="list-style-type: none"><li>1. If system has no TDM-BUS errors and is not handling heavy traffic, repeat test at 1-minute intervals a maximum of 5 times.</li></ol>

*Continued on next page*

Table 5-11. TEST #6 NPE Crosstalk Test — *Continued*

Error Code	Test Result	Description/ Recommendation
1003	ABORT	<p>The system could not allocate a tone receiver for the test. The system may be oversized for the number of Tone Detectors present or some Tone Detectors may be out-of-service.</p> <ol style="list-style-type: none"> <li>1. Look for TTR-LEV errors in the Error Log. If present, refer to "<a href="#">TTR-LEV (TTR Level)</a>" on page 5-1223.</li> <li>2. Look for TONE-PT errors in the Error Log. If present, refer to "<a href="#">TTR-LEV (TTR Level)</a>" on page 5-1223.</li> <li>3. If neither condition exists, retry the test at 1-minute intervals a maximum of 5 times.</li> </ol>
1004	ABORT	<p>The port was seized by a valid call during the test. The test has been aborted. Use the <b>display port PCSSpp</b> command to determine the station extension. Use the <b>status station</b> command to determine the service state of the port. If the service state indicates that the port is in use, the port is unavailable for certain tests. You must wait until the port is idle before retesting.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> <li>2. If the test continues to abort and the port is not in use, escalate the problem.</li> </ol>
1005	ABORT	<p>The test was aborted due to a configuration problem. This test may not be applicable, or it may be disruptive to terminal equipment other than a voice terminal (for example, the modem pool member or music on hold).</p>
1018	ABORT	<p>The test has been disabled via administration. The default for the 'Test' field on the 'Station' form is 'y'; thus, you may want to determine why this field has been set to 'n' on this station (this may be due to the ringing application test 48, which can be customer or terminal disturbing).</p> <ol style="list-style-type: none"> <li>1. To enable the test for a particular station being tested, enter <b>change station extension</b> and set the 'Test?' field on the station from 'n' to 'y.'</li> </ol>
2000	ABORT	<p>Response to the test request was not received within the allowable time period.</p>
2100	ABORT	<p>System resources required to run this test are not available. This could be due to a failure to seize the port.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>

*Continued on next page*

Table 5-11. TEST #6 NPE Crosstalk Test — *Continued*

Error Code	Test Result	Description/ Recommendation
Any	FAIL	<p>This test can fail due to on-board or off-board problems. Off-board problems of concern include EXP-INTF faults, TDM-BUS faults, and faults associated with the tone detectors/tone generators. Clear all off-board problems before replacing the board. Keep in mind that a TDM-BUS problem is usually the result of a faulty board connected to the backplane or bent pins on the backplane.</p> <ol style="list-style-type: none"><li>1. Look for EXP-INTF errors in the error log. If present, refer to the EXP-INTF Maintenance documentation.</li><li>2. Look for TDM-BUS errors in the error log. If present, refer to <a href="#">“TDM-BUS (TDM Bus)” on page 5-1116</a>.</li><li>3. Look for TONE-BD and/or TONE-PT errors in the error log. If present, refer to the TONE-BD Maintenance documentation and the <a href="#">“TONE-PT (Tone Generator)” on page 5-1204</a>.</li><li>4. Test the board when the faults from steps 1, 2, and 3 are cleared. Replace the board only if the test fails.</li></ol>
	PASS	<p>The port is correctly using its allocated time slots. User-reported troubles on this port should be investigated by using other port tests, by examining station wiring, or by examining the station.</p>
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board). This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"><li>1. Check to ensure that the board translations are correct. Use the <b>list config</b> command, and resolve any problems that are found.</li><li>2. If the board was found to be correctly inserted in step 1, issue the <b>busyout board</b> command.</li><li>3. Issue the <b>reset board</b> command.</li><li>4. Issue the <b>release busy board</b> command.</li><li>5. Issue the <b>test board long</b> command. This should re-establish the linkage between the internal ID and the port. If this is not the case, dispatch to check to ensure that there is a valid board inserted.</li></ol>

## Conference Circuit Test (#7)

One or more NPEs reside on each circuit pack with a TDM Bus interface. The NPE controls port connectivity and gain, and provides conferencing functions on a per-port basis. The Conference Circuit Test verifies that the NPE channel for the port being tested can correctly perform the conferencing function. The NPE is instructed to listen to several different tones and conference the tones together. The resulting signal is then measured by a Tone Detector port. If the level of the tone is within a certain range, the test passes.

Table 5-12. TEST #7 Conference Circuit Test

Error Code	Test Result	Description/ Recommendation
	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals a maximum of 5 times.
1000	ABORT	System resources required to run this test are not available. The port may be busy with a valid call. Use the <b>display port PCSSpp</b> command to determine the station extension. Use the <b>status station</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. You must wait until the port is idle before retesting. 1. If the port status is idle, then retry the command at 1-minute intervals a maximum of 5 times.
1004	ABORT	The port was seized by a valid call during the test. The test has been aborted. Use the <b>display port PCSSpp</b> command to determine the station extension. Use the <b>status station</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. You must wait until the port is idle before retesting. 1. Retry the command at 1-minute intervals a maximum of 5 times. 2. If the test continues to abort and the port is not in use, escalate the problem.
1005	ABORT	The test was aborted due to a configuration problem. This test may not be applicable, or it may be disruptive to terminal equipment other than a voice terminal (for example, the modem pool member or music on hold).
1018	ABORT	The test has been disabled via administration. The default for the 'Test' field on the 'Station' form is 'y'; thus, you may want to determine why this field has been set to 'n' on this station (this may be due to the ringing application test 48, which can be customer or terminal disturbing). 1. To enable the test for the particular analog station being tested, enter <b>change station extension</b> and set the 'Test?' field on the station from 'n' to 'y.'

Continued on next page

Table 5-12. TEST #7 Conference Circuit Test — *Continued*

Error Code	Test Result	Description/ Recommendation
2000	ABORT	Response to the test request was not received within the allowable time period.
2100	ABORT	<p>System resources required to run this test are not available.</p> <ol style="list-style-type: none"> <li>1. Look for TONE-PT errors in the error log. If present, refer to <a href="#">“TONE-PT (Tone Generator)” on page 5-1204.</a></li> <li>2. If there are no TONE-PT errors in the error log, retry the test at 1-minute intervals for a maximum of 5 times.</li> </ol>
Any	FAIL	<p>The NPE of the tested port did not conference the tones correctly. This will cause noisy and unreliable connections.</p> <ol style="list-style-type: none"> <li>1. Issue the <b>display port</b> and the <b>status station</b> commands to determine if the station is idle. If the station is found to be idle, issue the <b>test port</b> command for this port.</li> <li>2. If the test continues to fail, issue the <b>busyout port</b> and the <b>release port</b> commands, and then retest the port.</li> <li>3. If the test still fails, replace the board.</li> </ol>
	PASS	The port can correctly conference multiple connections. User-reported troubles on this port should be investigated by using other port tests and by examining station, trunk, or external wiring.
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board). This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"> <li>1. Check to ensure that the board translations are correct. Use the <b>list config</b> command, and resolve any problems that are found.</li> <li>2. If the board was found to be correctly inserted in step 1, issue the <b>busyout board</b> command.</li> <li>3. Issue the <b>reset board</b> command.</li> <li>4. Issue the <b>release busy board</b> command.</li> <li>5. Issue the <b>test board long</b> command. This should re-establish the linkage between the internal ID and the port. If this is not the case, dispatch to check to ensure that there is a valid board inserted.</li> </ol>

## Battery Feed Test (also called Port Diagnostic Test) (#35)

---

The battery feed chip provides power to the telephone equipment, signaling, rotary dial pulsing, transmission, and balance. This test checks the signaling and switchhook capabilities of the battery feed chip by terminating the port, applying battery, and by trying to detect a current.

**NOTE:**

For the TN746B 16-Port Neon Analog Line circuit pack, Test #35 always "passes." No actual testing is performed on the TN746B while the test is running. Test #35 operates in the normal manner for TN746.

Table 5-13. TEST #35 Battery Feed Test

---

Error Code	Test Result	Description/ Recommendation
	ABORT	Could not allocate the necessary system resources to run this test. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
1000	ABORT	System resources required to run this test are not available. The port may be busy with a valid call. Use the <b>display port PCSSpp</b> command to determine the station extension. Use the <b>status station</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. You must wait until the port is idle before retesting. <ol style="list-style-type: none"><li>1. If the port status is idle, then retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
1004	ABORT	The port was seized by a valid call during the test. The test has been aborted. Use the <b>display port PCSSpp</b> command to determine the station extension. Use the <b>status station</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. You must wait until the port is idle before retesting. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li><li>2. If the test continues to abort and the port is not in use, escalate the problem.</li></ol>
1005	ABORT	The test was aborted due to a configuration problem. This test may not be applicable, or it may be disruptive to terminal equipment other than a voice terminal (for example, the modem pool member or music on hold).

---

*Continued on next page*

Table 5-13. TEST #35 Battery Feed Test — *Continued*

Error Code	Test Result	Description/ Recommendation
1018	ABORT	<p>The test has been disabled via administration. The default for the 'Test' field on the 'Station' form is 'y'; thus, you may want to determine why this field has been set to 'n' on this station (this may be due to the ringing application test 48, which can be customer or terminal disturbing).</p> <ol style="list-style-type: none"> <li>To enable the test for the particular analog station being tested, enter <b>change station extension</b> and set the 'Test?' field on the station from 'n' to 'y.'</li> </ol>
2000	ABORT	Response to the test request was not received within the allowable time period.
2100	ABORT	<p>Could not allocate the necessary system resources to run this test.</p> <ol style="list-style-type: none"> <li>Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
	FAIL	<p>The port's battery feed chip is unable to supply sufficient power to the terminal equipment. This could be a marginal test, and the terminal equipment may be operating satisfactorily.</p> <ol style="list-style-type: none"> <li>Retry the test at 1-minute intervals for a maximum of 5 times.</li> <li>If the test continues to fail, determine whether the customer is experiencing problems on this line. Replace the circuit pack only if the customer is experiencing problems.</li> </ol>
	PASS	<p>The port's battery feed chip is able to provide power to the station equipment to detect on-/off-hook, but may not be able to supply power for touch-tones. If touch-tones are inoperative on this station, then replace the circuit pack because this port is inoperative. User-reported troubles on this port should be investigated by using other port tests, by examining station wiring, or by examining the station.</p>
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board). This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"> <li>Check to ensure that the board translations are correct. Use the <b>list config</b> command, and resolve any problems that are found.</li> <li>If the board was found to be correctly inserted in step 1, issue the <b>busyout board</b> command.</li> <li>Issue the <b>reset board</b> command.</li> <li>Issue the <b>release busy board</b> command.</li> <li>Issue the <b>test board long</b> command. This should re-establish the linkage between the internal ID and the port. If this is not the case, dispatch to check to ensure that there is a valid board inserted.</li> </ol>

## Station Status and Translation Audits and Updates Test (#36)

This test updates the Analog port's message lamp state (if it has one) and translations (such as station type, dial type, network connection) with information kept in the software. The software is updated with the switchhook state reported by the port processor. When the ringer is in the off state, this test also turns off the station's ringer to prevent constant ringing caused by defective hardware.

Table 5-14. TEST #36 Station Status and Translation Audits and Updates Test

Error Code	Test Result	Description/ Recommendation
	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals a maximum of 5 times.
1004	ABORT	The port was seized by a valid call during the test. The test has been aborted. Use the <b>display port PCSSpp</b> command to determine the station extension. Use the <b>status station</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. You must wait until the port is idle before retesting. 1. Retry the command at 1-minute intervals a maximum of 5 times. 2. If the test continues to abort and the port is not in use, escalate the problem.
1005	ABORT	The test was aborted due to a configuration problem. This test may not be applicable, or it may be disruptive to terminal equipment other than a voice terminal (for example, the modem pool member or music on hold).
1006	ABORT	This port has been busied out by command, or taken out-of-service by the failure of the NPE Crosstalk Test. 1. Look in the error log for error type 18 (port busied out) for this port. If this error is present, release the port with the <b>release station extension</b> command, and run the test again. 2. Look in the error log for error type 1025 (NPE crosstalk test failed) for this port. If this error is present, investigate the errors associated with the NPE Crosstalk Test 6. 3. Make sure that the terminal is connected and in service, and then retest.
2000	ABORT	Response to the test request was not received within the allowable time period.
2100	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals a maximum of 5 times.

*Continued on next page*

Table 5-14. TEST #36 Station Status and Translation Audits and Updates Test — *Continued*

Error Code	Test Result	Description/ Recommendation
1	FAIL	<p>This does not indicate a hardware problem. The switchhook audit failed. The other updates were not performed because of this failure. This may occur when the audit is performed at the same time that the terminal equipment goes off-hook. Use the <b>status station</b> command to determine when the port is available for testing.</p> <ol style="list-style-type: none"> <li>1. When the port becomes available for testing, retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
5	FAIL	<p>This does not indicate a hardware problem. However, there may be an internal software error. The message waiting lamp update failed. The translation and ringer updates were not performed because of this failure.</p>
7	FAIL	<p>The translation update failed. This does not indicate a hardware problem. However, there may be an internal software error. The ringer update was not performed because of this failure.</p>
8	FAIL	<p>This does not indicate a hardware problem. However, there may be an internal software error. The ringer update failed.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
	PASS	<p>The software and the port processor have the same status. User-reported troubles on this port should be investigated by using other port tests, by examining station wiring, or by examining the station.</p>
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board). This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"> <li>1. Check to ensure that the board translations are correct. Use the <b>list config</b> command, and resolve any problems that are found.</li> <li>2. If the board was found to be correctly inserted in step 1, issue the <b>busyout board</b> command.</li> <li>3. Issue the <b>reset board</b> command.</li> <li>4. Issue the <b>release busy board</b> command.</li> <li>5. Issue the <b>test board long</b> command. This should re-establish the linkage between the internal ID and the port. If this is not the case, dispatch to check to ensure that there is a valid board inserted.</li> </ol>

## Station Present Test (also called Ringing Application Test) (#48)

---

This test provides a burst of ringing current to the terminal equipment and detects that current flows. This test ascertains whether terminal equipment is connected to the port.

This test may cause some terminal equipment to ring briefly during daily maintenance. If this ringing is disturbing the customer or the terminal equipment, it should be disabled using the Tests field of the station administration screen form. However, on some releases of the software, this action disables Tests #6, #7, #161, and #35 as well as Test #48.

Table 5-15. TEST #48 Station Present Test

Error Code	Test Result	Description/ Recommendation
	ABORT	Could not allocate the necessary system resources to run this test. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
1000	ABORT	System resources required to run this test are not available. The port may be busy with a valid call. Use the <b>display port PCSSpp</b> command to determine the station extension. Use the <b>status station</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. You must wait until the port is idle before retesting. <ol style="list-style-type: none"><li>1. If the port status is idle, then retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
1004	ABORT	The port was seized by a valid call during the test. The test has been aborted. Use the <b>display port PCSSpp</b> command to determine the station extension. Use the <b>status station</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. You must wait until the port is idle before retesting. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li><li>2. If the test continues to abort and the port is not in use, escalate the problem.</li></ol>
1005	ABORT	The test was aborted due to a configuration problem. This test may not be applicable, or it may be disruptive to terminal equipment other than a voice terminal (for example, the modem pool member or music on hold).

*Continued on next page*

Table 5-15. TEST #48 Station Present Test — Continued

Error Code	Test Result	Description/ Recommendation
1008	ABORT	<p>Could not allocate a ringing circuit. Either all the ringing circuits are in use or the ringing generator is defective or it is not wired correctly.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> <li>2. If the test continues to abort, look for RING-GEN errors in the Error Log. If an ABORT 1008 occurs for this test on other circuit packs as well, then the ringing generator may be defective or is not wired correctly (see errors for RING-GEN). If it doesn't occur on other ports, then all four ring phases are in use.</li> </ol>
1018	ABORT	<p>The test has been disabled via administration. The default for the 'Test' field on the 'Station' form is 'y'; thus, you may want to determine why this field has been set to 'n' on this station (this may be due to the brief ringing disturbance that this test may cause).</p> <ol style="list-style-type: none"> <li>1. To enable the test for the particular analog station being tested, enter <b>change station extension</b> and set the 'Test?' field on the station from 'n' to 'y.'</li> </ol>
2000	ABORT	Response to the test request was not received within the allowable time period.
2100	ABORT	<p>Could not allocate necessary system resources to run this test.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
	FAIL	<p>The terminal equipment is not connected to the circuit pack. Some terminal equipment such as modems may fail even when connected properly.</p> <ol style="list-style-type: none"> <li>1. Remotely test the equipment.</li> <li>2. If the test fails again, look for RING-GEN errors in the error log. If present, refer to <a href="#">"RING-GEN (Analog Ring Generator)" on page 5-1036</a>.</li> <li>3. Check all of the wiring between the station equipment and the switch. Then, run the test again.</li> <li>4. If the test still fails, the set may be defective. Check the set, and replace it, if necessary.</li> <li>5. Some terminal equipment could fail even when it is connected properly. If this is the case, disable the test using the <b>change station extension</b> command (enter 'n' into the Test field). Note that this action also disables tests 6, 7, 161, and 35 on this port.</li> </ol>
	PASS	<p>The station is connected properly to the switch. This test may also pass if no terminal equipment is connected and the terminal is located very far from the switch. User-reported troubles on this port should be investigated by using other port tests, by examining station wiring, or by examining the station.</p>

Continued on next page

Table 5-15. TEST #48 Station Present Test — *Continued*


Error Code	Test Result	Description/ Recommendation
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board). This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"><li>1. Check to ensure that the board translations are correct. Use the <b>list config</b> command, and resolve any problems that are found.</li><li>2. If the board was found to be correctly inserted in step 1, issue the <b>busyout board</b> command.</li><li>3. Issue the <b>reset board</b> command.</li><li>4. Issue the <b>release busy board</b> command.</li><li>5. Issue the <b>test board long</b> command. This should re-establish the linkage between the internal ID and the port. If this is not the case, dispatch to check to ensure that there is a valid board inserted.</li></ol>

### Loop Around Test (#161)

Each Analog port consists of:

- An NPE for port connectivity and gain, and conferencing functionality
- A code that converts the digital signals of the TDM Bus to analog signals
- A battery feed chip that provides power to the telephone set for signaling, dial pulsing, transmission, and balance

This test is designed to check the on-board transmission capabilities of the NPE, the codec, and the battery feed chip of the analog port. A Tone Detector and a Tone Generator talk and listen on the same pair of time slots as the Analog Port. The Analog Port is then instructed to go into loop around mode (see the following below). The test passes if the signal measured by the Tone Detector is within acceptable limits.



\* BFC - BATTERY FEED CHIP  
NPE - NETWORK PROCESSING ELEMENT

Figure 5-2. Analog Loop Around Test

Table 5-16. TEST #161 Loop Around Test

Error Code	Test Result	Description/ Recommendation
	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals a maximum of 5 times.
1000	ABORT	System resources required to run this test are not available. The port may be busy with a valid call. Use the <b>display port PCSSpp</b> command to determine the station extension. Use the <b>status station</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. You must wait until the port is idle before retesting. 1. If the port status is idle, then retry the command at 1-minute intervals a maximum of 5 times.

Continued on next page

5 Maintenance Objects for DEFINITY ONE  
ANL-16-L (16-Port Neon Analog Line)

5-42

Table 5-16. TEST #161 Loop Around Test — *Continued*

Error Code	Test Result	Description/ Recommendation
1002	ABORT	<p>The system could not allocate time slots for the test. The system may be under heavy traffic conditions or it may have time slots out-of-service due to TDM-BUS errors. Refer to <a href="#">“TDM-BUS (TDM Bus)” on page 5-1116</a> to diagnose any active TDM-BUS errors.</p> <ol style="list-style-type: none"> <li>1. If system has no TDM-BUS errors and is not handling heavy traffic, repeat test at 1-minute intervals a maximum of 5 times.</li> </ol>
1003	ABORT	<p>The system could not allocate a tone receiver for the test. The system may be oversized for the number of Tone Detectors present or some Tone Detectors may be out-of-service.</p> <ol style="list-style-type: none"> <li>1. Look for TTR-LEV errors in the Error Log. If present, refer to <a href="#">“TTR-LEV (TTR Level)” on page 5-1223</a>.</li> <li>2. Look for TONE-PT errors in the Error Log. If present, refer to <a href="#">“TONE-PT (Tone Generator)” on page 5-1204</a>.</li> <li>3. If neither condition exists, retry the test at 1-minute intervals a maximum of 5 times.</li> </ol>
1004	ABORT	<p>The port was seized by a valid call during the test. The test has been aborted. Use the <b>display port PCSSpp</b> command to determine the station extension. Use the <b>status station</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. You must wait until the port is idle before retesting.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> <li>2. If the test continues to abort and the port is not in use, escalate the problem.</li> </ol>
1005	ABORT	<p>The test is not run because the port is administered as either an External Alert or Announcement port.</p>
1018	ABORT	<p>The test has been disabled via administration. The default for the 'Test' field on the 'Station' form is 'y'; thus, you may want to determine why this field has been set to 'n' on this station (this may be due to the ringing application test 48, which can be customer or terminal disturbing).</p> <ol style="list-style-type: none"> <li>1. To enable the test for the particular analog station being tested, enter <b>change station extension</b> and set the 'Test?' field on the station from 'n' to 'y.'</li> </ol>
2000	ABORT	<p>Response to the test request was not received within the allowable time period.</p>
2100	ABORT	<p>Could not allocate the necessary system resources to run this test. This could be due to a failure to seize the port.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>

*Continued on next page*

Table 5-16. TEST #161 Loop Around Test — *Continued*

Error Code	Test Result	Description/ Recommendation
	FAIL	<p>The reflective loop around test failed. This could cause noisy or unreliable connections, or users calling this port may hear an echo. The problem can also be off-board, as described below.</p> <ol style="list-style-type: none"><li>1. Since the test may be affected by a line seizure, repeat the test at 1-minute intervals for a maximum of 5 times.</li><li>2. Run circuit pack tests to check the tone generator circuit pack and the tone detector circuit pack by using the <b>test board PCSS short</b> command.</li><li>3. Resolve any problems that are detected on the tone generator circuit pack or the tone detector circuit pack.</li><li>4. If the tone generator and tone detector circuit packs are functioning properly and the test still fails and a voice terminal is connected and wired properly, replace the analog line circuit pack.</li></ol>
	PASS	<p>The port is able to provide an analog transmission path to the station equipment. User-reported troubles on this port should be investigated by using other port tests, by examining station wiring, or by examining the station.</p>
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board). This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"><li>1. Check to ensure that the board translations are correct. Use the <b>list config</b> command, and resolve any problems that are found.</li><li>2. If the board was found to be correctly inserted in step 1, issue the <b>busyout board</b> command.</li><li>3. Issue the <b>reset board</b> command.</li><li>4. Issue the <b>release busy board</b> command.</li><li>5. Issue the <b>test board long</b> command. This should re-establish the linkage between the internal ID and the port. If this is not the case, dispatch to check to ensure that there is a valid board inserted.</li></ol>

## ANL-24-L (24-Port Analog Line)

---

MO name (in alarm log)	Alarm level	Initial command to run <sup>1</sup>	Full name of MO
ANL-24-L	MIN	test port PCSSpp l	24-Port Analog Line
ANL-24-L	WRN	test port PCSSpp sh	24-Port Analog Line

- 
1. Where P is the port network number (1 for PPN); C is the carrier designation (for example, A, B, or C); SS is the address of the slot in the carrier where the circuit pack is located (for example, 01, 02, ..., etc.); and pp is the 2-digit port number (for example, 01).
- 

The 24-Port Analog Line circuit pack (TN793) provides 24 ports for voice terminals and supports both on-premises and off-premises analog voice terminals.

No maintenance of the terminal connected to the 24-Port Neon Analog Line circuit pack is performed, except to determine whether or not the terminal is connected. Failures of the neon message waiting lamp power and the common ringing application circuitry are reported as part of common port circuit pack errors. See errors 1281 and 1793 in [“XXX-BD \(Common Port Circuit Pack\)” on page 5-1343](#).

### NOTE:

This analog line circuit pack supports analog data modules. When assigned, analog data modules provide access to the Net Pkt (TN794) data ports. To activate an analog data module you must assign the port location on the data form and connect a modem to the port. (The analog data module may be used for connection to a CDR output or other adjuncts as needed.) These ports are tested the same as all other analog ports on the circuit pack.

## Ringling caused by maintenance testing

---

Test #48 may cause some terminal equipment to ring briefly during daily maintenance. If this ringing is disturbing the customer or the terminal equipment, it should be disabled in the `Tests` field of the **change station** extension form. Be aware that this action also disables Tests #6, 7, 161, and 35.

**Error log entries and test to clear values**

Table 5-17. 24-Port analog line error log entries

Error type	Aux data	Associated test	Alarm level	On/Off board	Test to clear value
0 <sup>1</sup>	0	Any	Any	Any	test port PCSSpp sh r 1
1(a)	40960 40975 40977	none			
15(a)	Any	Audits and Updates Test (#36)			
15(b)	Any	Audits and Updates Test (#36)			
18	0	busy-out station <i>extension</i>	WRN	OFF	release station < <i>extension</i> >
18	0	busy-out station <i>extension</i>	WRN	ON	release station < <i>extension</i> >
130(b)	0		WRN	ON	test port
130(c)		None	WRN	ON	test port PCSSpp sh
257(d)	40973	none			
513(e)		Station Present Test (#48)	WRN	OFF	test port PCSSpp sh r 2
769		Battery Feed Test (#35)	MIN/ WRN <sup>2</sup>	ON	test port PCSSpp sh r 2
1025		Looparound Test (#161)	MIN/ WRN <sup>2</sup>	ON	test port PCSSpp l r 2
1281		Conference Test (#7)	MIN/ WRN <sup>2</sup>	ON	test port PCSSpp l r 2
1537		NPE Crosstalk Test (#6)	MIN/ WRN <sup>2</sup>	ON	test port PCSSpp l r 2

1. Run the Short Test Sequence first. If all tests pass, run the Long Test Sequence. Refer to the appropriate test description and follow the recommended procedures.
2. Minor alarms on this MO may be downgraded to Warning alarms based on the values used in the set options command.

**Notes:**

- a. This is a software ausid error that does not indicate any hardware malfunction. Run Short Test Sequence and investigate errors.
- b. Indicates that the circuit pack has been removed or has been insane more than 11 minutes. To clear the error replace the circuit pack.

- c. These are in-line errors and can only be resolved over time.
    - 40960 indicates that too many simultaneous incoming ringing attempts were made on this board. Only 4 ports on a board may ring simultaneously. A 5th incoming call will cause an inline error from the board.
    - 40975 indicates that the terminal equipment was on-hook when ring-tip was detected during ringing. This usually indicates a failure in the terminal equipment or the type of terminal has a low ringer impedance. Call the terminal equipment and verify that the terminal rings. If the terminal does not ring, then replace it. Otherwise, issue the **test port PCSSpp** command, and follow the procedure for Test #48.
    - 40977 indicates that no terminal equipment was connected when ringing was attempted. Run the short test via the **test port PCSSpp** command, and follow the procedure for the results of Test #48.
  - d. This is an in-line error and can only be resolved over time. This error indicates that ringing voltage is absent. If only 1 analog circuit pack in the system has this problem, then replace the circuit pack. If only analog circuit packs on a particular carrier have this error, then the ringing generator may not be connected to this carrier. If analog circuit packs on many carriers have this error, then it is probably a problem with the ringing generator.
  - e. Test #48 may cause some terminal equipment to ring briefly during daily maintenance. If this disturbs the customer or the terminal equipment, disable it by setting the `Tests` field on the **change station** extension form to `n`. On some software releases, this will also disable Tests #6, 7, 161, and 35.
-

## System technician-demanded tests: descriptions and error codes

---

Always investigate tests in the order presented in the table below when inspecting errors in the system. By clearing error codes associated with the *Battery Feed Test*, for example, you may also clear errors generated from other tests in the testing sequence.

Order of investigation	Short test sequence	Long test sequence	D/ND <sup>1</sup>
Battery Feed Test (#35)	X	X	ND
Station Present Test (#48)	X	X	ND
Looparound Test (#161)	X	X	ND
Conference Test (#7)	X	X	ND
NPE Crosstalk Test (#6)	X	X	ND
Station Status and Translation Audits and Updates Test (#36)	X	X	ND

---

1. D = Destructive; ND = Nondestructive

---

### NPE crosstalk test (#6)

This test verifies that this port's NPE channel talks on the selected time slot and never crosses over to time slots reserved for other connections. If the NPE is not working correctly, one-way and noisy connections may be observed. This test is usually part of the long test sequence and takes about 20 to 30 seconds to complete.

Table 5-18. TEST #6 NPE crosstalk test

Error code	Test result	Description/Recommendation
	ABORT	Could not allocate the necessary system resources to run this test. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
1000	ABORT	System resources required to run test are not available. The port may be busy with a valid call. This result is also reported for the system's Music-On-Hold port when it is off-hook, which it usually is. <ol style="list-style-type: none"><li>1. Enter <b>display port PCSSpp</b> to determine the station's extension.</li><li>2. Enter <b>status station</b> extension to determine the service state of the port. (Refer to <a href="#">"status station" on page 4-213</a> for a description of all possible states.)</li><li>3. If the port is in use, wait until the port is idle. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
1001	ABORT	System resources required to run test are not available. This could be due to a failure to seize the port. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
1002	ABORT	The system could not allocate time slots for the test. The system may be under heavy traffic conditions or have time slots out-of-service due to TDM-BUS errors. Refer to <a href="#">"TDM-BUS (TDM Bus)" on page 5-1116</a> to diagnose any active TDM-BUS errors. <ol style="list-style-type: none"><li>1. If system has no TDM-BUS errors and is not handling heavy traffic, retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
1003	ABORT	The system could not allocate a tone receiver for the test. The system may be oversized for the number of tone detectors present or some tone detectors may be out-of-service. <ol style="list-style-type: none"><li>1. Look for TTR-LEV errors in the Error Log. If present, refer to <a href="#">"TTR-LEV (TTR Level)" on page 5-1223</a>.</li><li>2. Look for TONE-PT errors in the Error Log. If present, refer to <a href="#">"TONE-PT (Tone Generator)" on page 5-1204</a>.</li><li>3. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>

*Continued on next page*

Table 5-18. TEST #6 NPE crosstalk test — *Continued*

Error code	Test result	Description/Recommendation
1004	ABORT	<p>The port was seized by a valid call during the test. The test has been aborted. Use the <b>display port PCSSpp</b> command to determine the station extension. Use the <b>status station</b> command to determine the service state of the port. If the port is in use, wait until the port is idle before testing.</p> <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
1005	ABORT	<p>The test was aborted due to a configuration problem. This test may not be applicable, or it may be disruptive to terminal equipment other than a voice terminal (for example, the modem pool member or Music On Hold).</p>
1018	ABORT	<p>The test has been disabled by administration. The default for the <code>Test</code> field on the station form is <b>y</b>. Determine why this field has been set to <b>n</b> on this station (this may be due to the ringing application test 48, that can be customer or terminal disturbing).</p> <ol style="list-style-type: none"><li>1. To enable the test for a particular station being tested, enter <b>change station extension</b> and set the <code>Test?</code> field on the station from <b>n</b> to <b>y</b>.</li></ol>
2000	ABORT	<p>Response to the test request was not received within the allowable time period.</p>
2100	ABORT	<p>System resources required to run test are not available. This could be due to a failure to seize the port.</p> <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>

*Continued on next page*

Table 5-18. TEST #6 NPE crosstalk test — *Continued*

Error code	Test result	Description/Recommendation
Any	FAIL	<p>This test can fail due to on-board or off-board problems. Off-board problems include EXP-PN and EXP-INTF faults, TDM-BUS faults, and faults associated with the tone detectors/tone generators. Clear all off-board problems before replacing the board. A TDM-BUS problem is usually the result of a faulty board connected to the backplane, or bent pins on the backplane.</p> <ol style="list-style-type: none"><li>1. Look for EXP-PN and/or EXP-INTF errors in the error log. If present, refer to “EXP-PN” and “EXP-INTF”.</li><li>2. Look for TDM-BUS errors in the error log. If present, refer to <a href="#">“TDM-BUS (TDM Bus)” on page 5-1116</a>.</li><li>3. Look for TONE-BD and/or TONE-PT errors in the error log. If present, refer to “TONE-BD” and <a href="#">“TONE-PT (Tone Generator)” on page 5-1204</a>.</li><li>4. Test the board when the faults from Steps 1, 2, and 3 are cleared. Replace the board only if the test fails.</li></ol>
	PASS	<p>The port is correctly using its allocated time slots. User-reported troubles on this port should be investigated by using other port tests, by examining station wiring, or by examining the station.</p>
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board). This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"><li>1. Check to ensure that the board translations are correct. Use the <b>list config</b> command, and resolve any problems.</li><li>2. If the board was found to be correctly inserted in step 1, issue the <b>busyout board</b> command.</li><li>3. Issue the <b>reset board</b> command.</li><li>4. Issue the <b>release busy board</b> command.</li><li>5. Issue the <b>test board long</b> command. This should re-establish the linkage between the internal ID and the port. If this is not the case, check to ensure that there is a valid board inserted.</li></ol>

**Conference circuit test (#7)**

This test verifies that the NPE channel for the port being tested can correctly perform the conferencing function.

**Table 5-19. TEST #7 conference circuit test**

<b>Error code</b>	<b>Test result</b>	<b>Description/Recommendation</b>
	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals a maximum of 5 times.
1000	ABORT	System resources required to run this test are not available. The port may be busy with a valid call. This result is also reported for the system's Music-On-Hold port when it is off-hook, which it usually is. 1. Enter <b>display port PCSSpp</b> to determine the station's extension. 2. Enter <b>status station</b> extension to determine the service state of the port. 3. If the port is in use, wait until the port is idle and retry the command at 1-minute intervals a maximum of 5 times.
1004	ABORT	The port was seized by a valid call during the test. The test has been aborted. 1. Use the <b>display port PCSSpp</b> command to determine the station extension. 2. Use the <b>status station</b> command to determine the service state of the port. 3. If the port is in use, wait until the port is idle and retry the command at 1-minute intervals a maximum of 5 times.
1005	ABORT	The test was aborted due to a configuration problem. This test may not be applicable, or it may be disruptive to terminal equipment other than a voice terminal (for example, the modem pool member or Music On Hold).
1018	ABORT	The test has been disabled via administration. The default for the <code>Test</code> field on the station form is <b>y</b> . Determine why this field has been set to <b>n</b> on this station (this may be due to the ringing application test 48, that can be customer or terminal disturbing). 1. To enable the test for a particular station being tested, enter <b>change station extension</b> and set the <code>Test?</code> field on the station from <b>n</b> to <b>y</b> .
2000	ABORT	Response to the test request was not received within the allowable time period.

*Continued on next page*

Table 5-19. TEST #7 conference circuit test — *Continued*

Error code	Test result	Description/Recommendation
2100	ABORT	<p>System resources required to run this test are not available.</p> <ol style="list-style-type: none"><li>1. Look for TONE-PT errors in the error log. If present, refer to <a href="#">“TONE-PT (Tone Generator)” on page 5-1204</a>.</li><li>2. If there are no TONE-PT errors in the error log, retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
Any	FAIL	<p>The NPE of the tested port did not conference the tones correctly. This will cause noisy and unreliable connections.</p> <ol style="list-style-type: none"><li>1. Issue the <b>display port</b> and the <b>status station</b> commands to determine if the station is idle. If the station is idle, issue the <b>test port</b> command for this port.</li><li>2. If the test continues to fail, issue the <b>busyout port</b> and the <b>release port</b> commands, and then retest.</li><li>3. If the test still fails, replace the board.</li></ol>
	PASS	<p>The port can correctly conference multiple connections. User-reported troubles on this port should be investigated by using other port tests and by examining station, trunk, or external wiring.</p>
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board). This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"><li>1. Check to ensure that the board translations are correct. Use the <b>list config</b> command, and resolve any problems.</li><li>2. If the board was found to be correctly inserted in step 1, issue the <b>busyout board</b> command.</li><li>3. Issue the <b>reset board</b> command.</li><li>4. Issue the <b>release busy board</b> command.</li><li>5. Issue the <b>test board long</b> command. This should re-establish the linkage between the internal ID and the port. If this is not the case, check to ensure that there is a valid board inserted.</li></ol>

### Battery feed test (also called port diagnostic test) (#35)

The battery feed chip provides power to the telephone equipment, signaling, rotary dial pulsing, transmission, and balance. This test checks the signaling and switchhook capabilities of the battery feed chip by terminating the port, applying battery and detecting the resulting current.

For the TN746B, Test #35 does not actually run and instead always returns PASS. Test #35 operates in the normal manner for TN746.

Table 5-20. TEST #35 battery feed test

Error code	Test result	Description/Recommendation
	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals a maximum of 5 times.
1000	ABORT	System resources required to run this test are not available. The port may be busy with a valid call. This result is also reported for the system's Music-On-Hold port when it is off-hook, which it usually is.
1004	ABORT	The port was seized by a valid call during the test. The test has been aborted. 1. Use the <b>display port PCSSpp</b> command to determine the station extension. 2. Use the <b>status station</b> command to determine the service state of the port. 3. If the port is in use, wait until the port is idle and retry the command at 1-minute intervals a maximum of 5 times.
1005	ABORT	The test was aborted due to a configuration problem. This test may not be applicable, or it may be disruptive to terminal equipment other than a voice terminal (for example, the modem pool member or Music On Hold).
1018	ABORT	The test has been disabled via administration. The default for the <code>Test</code> field on the station form is <b>y</b> . Determine why this field has been set to <b>n</b> on this station (this may be due to the ringing application test 48, that can be customer or terminal disturbing). 1. To enable the test for a particular station being tested, enter <b>change station extension</b> and set the <code>Test?</code> field on the station from <b>n</b> to <b>y</b> .

*Continued on next page*

Table 5-20. TEST #35 battery feed test — *Continued*

Error code	Test result	Description/Recommendation
1392	ABORT	This port is currently a TTI port and the test will not execute on it. <ol style="list-style-type: none"><li>1. Verify that the port is a TTI port using either the <b>display port</b> command (the display shows that the port is a TTI port) or the <b>list config</b> command (the display shows a <math>\tau</math> for the port).</li><li>2. If the port is <i>not</i> a TTI port, escalate the problem. If both commands indicate that the port is a TTI port, the abort is correct for the test, and no action is necessary.</li></ol>
2000	ABORT	Response to the test request was not received within the allowable time period.
2100	ABORT	Could not allocate the necessary system resources to run this test. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
	FAIL	The port's battery feed chip is unable to supply sufficient power to the terminal equipment. This could be a marginal test, and the terminal equipment may be operating satisfactorily. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li><li>2. If the test continues to fail, determine whether the customer is experiencing problems on this line. If so, replace the circuit pack.</li></ol>

---

*Continued on next page*

Table 5-20. TEST #35 battery feed test — *Continued*

Error code	Test result	Description/Recommendation
	PASS	The port's battery feed chip is able to provide power to the station equipment to detect on-/off-hook, but may not be able to supply power for touch-tones. If touch-tones are inoperative on this station, then replace the circuit pack because this port is inoperative. User-reported troubles on this port should be investigated by using other port tests, by examining station wiring, or by examining the station.
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board). This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"><li>1. Check to ensure that the board translations are correct. Use the <b>list config</b> command, and resolve any problems.</li><li>2. If the board was found to be correctly inserted in step 1, issue the <b>busyout board</b> command.</li><li>3. Issue the <b>reset board</b> command.</li><li>4. Issue the <b>release busy board</b> command.</li><li>5. Issue the <b>test board long</b> command. This should re-establish the linkage between the internal ID and the port. If this is not the case, check to ensure that there is a valid board inserted.</li></ol>

**Station status and translation audits and updates  
test (#36)**

This test updates the analog port's message lamp state (if it has one) and translations with information in the software.

**Table 5-21. Test #36 station status and translation audits and updates**

<b>Error code</b>	<b>Test result</b>	<b>Description/ Recommendation</b>
	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals a maximum of 5 times.
1004	ABORT	The port was seized by a valid call during the test. The test has been aborted. 1. Use the <b>display port PCSSpp</b> command to determine the station extension. 2. Use the <b>status station</b> command to determine the service state of the port. 3. If the port is in use, wait until port is idle and retry the command at 1-minute intervals a maximum of 5 times.
1005	ABORT	The test was aborted due to a configuration problem. This test may not be applicable, or it may be disruptive to terminal equipment other than a voice terminal (for example, the modem pool member or Music On Hold).
1006	ABORT	This port has been busied out by command, or taken out-of-service by the failure of the NPE Crosstalk Test. 1. Look in the Error Log for error type 18 (port busied out) for this port. If this error is present, release the port with the <b>release station extension</b> command, and run the test again. 2. Check the Error Log for error type 1025 (NPE crosstalk test failed) for this port. If this error is present, investigate the errors associated with the NPE Crosstalk Test #6. 3. Make sure that the terminal is connected and in service, and then retest.
2000	ABORT	Response to the test request was not received within the allowable time period.
2100	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals a maximum of 5 times.

*Continued on next page*

Table 5-21. Test #36 station status and translation audits and updates — *Continued*

Error code	Test result	Description/ Recommendation
1	FAIL	<p>This does not indicate a hardware problem. The switchhook audit failed. The other updates were not performed because of this failure. This may occur when the audit is performed at the same time the terminal equipment goes off-hook.</p> <ol style="list-style-type: none"><li>1. Use the <b>status station</b> command to determine when the port is available and retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
5	FAIL	<p>This may be an internal software error. The message waiting lamp update failed. The translation and ringer updates were not performed because of this failure.</p>
7	FAIL	<p>The translation update failed. There may be an internal software error. The ringer update was not performed because of this failure.</p>
8	FAIL	<p>This does not indicate a hardware problem. There may be an internal software error. The ringer update failed.</p> <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
	PASS	<p>The software and the port processor have the same status. User-reported troubles on this port should be investigated by using other port tests, by examining station wiring, or by examining the station.</p>
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board). This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"><li>1. Check to ensure the board translations are correct. Use the <b>list config</b> command and resolve problems.</li><li>2. If the board was found to be correctly inserted in step 1, issue the <b>busyout board</b> command.</li><li>3. Issue the <b>reset board</b> command.</li><li>4. Issue the <b>release busy board</b> command.</li><li>5. Issue the <b>test board long</b> command. This should re-establish the linkage between the internal ID and the port. If this is not the case, check to ensure that there is a valid board inserted.</li></ol>

**Station present test (also called ringing application test) (#48)**

This test applies momentary ringing voltage to the terminal equipment and monitors resulting current flow to determine whether terminal equipment is connected to the port. This test may cause some terminal equipment to ring briefly during daily maintenance. If this ringing disturbs the customer or the terminal equipment, you can disable it via the Tests field on the **change station** form. However, on some software releases, Tests #6, 7, 161, and 35 are disabled.

**Table 5-22. TEST #48 station present test**

Error code	Test result	Description/Recommendation
	ABORT	Could not allocate the necessary system resources to run this test. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
1000	ABORT	System resources required to run this test are not available. The port may be busy with a valid call.
1004	ABORT	The port was seized by a valid call during the test. The test has been aborted. <ol style="list-style-type: none"><li>1. Use the <b>display port PCSSpp</b> command to determine the station extension.</li><li>2. Use the <b>status station</b> command to determine the service state of the port.</li><li>3. If the port is in use, wait until the port is idle and retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
1005	ABORT	The test was aborted due to a configuration problem. This test may not be applicable or it may be disruptive to terminal equipment other than a voice terminal (for example, the modem pool member or Music On Hold).
1008	ABORT	Could not allocate a ringing circuit. Either all the ringing circuits are in use or the ringing generator is defective or it is not wired correctly. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li><li>2. If the test continues to abort, look for RING-GEN errors in the Error Log. If an ABORT 1008 occurs for this test on other circuit packs as well, then the ringing generator may be defective or is not wired correctly (see errors for RING-GEN). If it does not occur on other ports, then all four ring phases are in use.</li></ol>

*Continued on next page*

Table 5-22. TEST #48 station present test — *Continued*

Error code	Test result	Description/Recommendation
1018	ABORT	<p>The test has been disabled by administration. The default for the <code>Test</code> field on the station form is <b>y</b>. Determine why this field has been set to <b>n</b> on this station (this may be due to the brief ringing disturbance that this test may cause).</p> <ol style="list-style-type: none"><li>To enable the test for a particular station being tested, enter <b>change station extension</b> and set the <code>Test?</code> field on the station from <b>n</b> to <b>y</b>.</li></ol>
2000	ABORT	<p>Response to the test request was not received within the allowable time period.</p>
2100	ABORT	<p>Could not allocate necessary system resources to run this test.</p> <ol style="list-style-type: none"><li>Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
	FAIL	<p>The terminal equipment is not connected to the circuit pack. Some terminal equipment, such as modems, may fail even when connected properly.</p> <ol style="list-style-type: none"><li>Remotely test the equipment.</li><li>If the test fails again, look for RING-GEN errors in the error log. If present, refer to <a href="#">“RING-GEN (Analog Ring Generator)” on page 5-1036</a>.</li><li>Check all of the wiring between the station equipment and the switch. Then, run the test again.</li><li>If the test still fails, the set may be defective. Check the set, and replace it, if necessary.</li><li>Some terminal equipment could fail even when it is connected properly. If this is the case, disable the test using the <b>change station extension</b> command (enter <b>n</b> into the <code>Test</code> field). Note that this action also disables tests 6, 7, 161, and 35 on this port.</li></ol>

*Continued on next page*

Table 5-22. TEST #48 station present test — *Continued*

Error code	Test result	Description/Recommendation
	PASS	The station is connected properly to the switch. This test may also pass if no terminal equipment is connected and the terminal is located very far from the switch. User-reported troubles on this port should be investigated by using other port tests, by examining station wiring, or by examining the station.
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board). This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"><li>1. Check to ensure that the board translations are correct. Use the <b>list config</b> command, and resolve any problems.</li><li>2. If the board was found to be correctly inserted in step 1, issue the <b>busyout board</b> command.</li><li>3. Issue the <b>reset board</b> command.</li><li>4. Issue the <b>release busy board</b> command.</li><li>5. Issue the <b>test board long</b> command. This should re-establish the linkage between the internal ID and the port. If this is not the case, check to ensure that there is a valid board inserted.</li></ol>

### Looparound test (#161)

This test checks the on-board transmission capabilities of the NPE, the codec, and the battery feed chip of the analog port. The test passes if the signal measured by the tone detector is within acceptable limits.

Table 5-23. TEST #161 looparound test

Error code	Test result	Description/Recommendation
	ABORT	Could not allocate the necessary system resources to run this test. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
1000	ABORT	System resources required to run this test are not available. The port may be busy with a valid call. <ol style="list-style-type: none"><li>1. Use the <b>display port PCSSpp</b> command to determine the station extension.</li><li>2. Use the <b>status station</b> command to determine the service state of the port.</li><li>3. If the port is in use, wait until the port is idle and retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
1002	ABORT	The system could not allocate time slots for the test. The system may be under heavy traffic conditions or it may have time slots out-of-service due to TDM-BUS errors. Refer to <a href="#">“TDM-BUS (TDM Bus)” on page 5-1116</a> to diagnose TDM-BUS errors. <ol style="list-style-type: none"><li>1. If system has no TDM-BUS errors and is not handling heavy traffic, retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
1003	ABORT	The system could not allocate a tone receiver for the test. The system may be oversized for the number of tone detectors present or some tone detectors may be out-of-service. <ol style="list-style-type: none"><li>1. Look for TTR-LEV errors in the Error Log. If present, refer to <a href="#">“TTR-LEV (TTR Level)” on page 5-1223</a>.</li><li>2. Look for TONE-PT errors in the Error Log. If present, refer to <a href="#">“TONE-PT (Tone Generator)” on page 5-1204</a>.</li><li>3. If neither condition exists, retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
1004	ABORT	The port was seized by a valid call during the test. The test has been aborted. <ol style="list-style-type: none"><li>1. Use the <b>display port PCSSpp</b> command to determine the station extension.</li><li>2. Use the <b>status station</b> command to determine the service state of the port.</li><li>3. If the port is in use, wait until the port is idle and retry the command at 1-minute intervals a maximum of 5 times.</li></ol>

*Continued on next page*

Table 5-23. TEST #161 looparound test — *Continued*

Error code	Test result	Description/Recommendation
1005	ABORT	This test is not run on ports administered as External Alert, Announcement or combined modem pool ports. This error can be ignored.
1018	ABORT	The test has been disabled by administration. The default for the <code>Test</code> field on the station form is <b>y</b> . Determine why this field has been set to <b>n</b> on this station (this may be due to the ringing application test 48, that can be customer or terminal disturbing).  1. To enable the test for a particular station being tested, enter <b>change station extension</b> and set the <code>Test?</code> field on the station from <b>n</b> to <b>y</b> .
2000	ABORT	Response to the test request was not received within the allowable time period.
2100	ABORT	Could not allocate the necessary system resources to run this test. This could be due to a failure to seize the port.  1. Retry the command at 1-minute intervals a maximum of 5 times.

*Continued on next page*

Table 5-23. TEST #161 looparound test — *Continued*

Error code	Test result	Description/Recommendation
	FAIL	<p>The reflective loop around test failed. This could cause noisy or unreliable connections, or users calling this port may hear an echo. The problem can also be off-board.</p> <ol style="list-style-type: none"><li>1. Since the test may be affected by a line seizure, repeat the test at 1-minute intervals for a maximum of 5 times.</li><li>2. Run circuit pack tests to check the tone generator circuit pack and the tone detector circuit pack by using the <b>test board PCSS short</b> command.</li><li>3. Resolve any problems on the tone generator circuit pack or the tone detector circuit pack.</li><li>4. If the tone generator and tone detector circuit packs are functioning properly, a voice terminal is connected and wired properly and the test still fails, replace the analog line circuit pack.</li></ol>
	PASS	<p>The port is able to provide an analog transmission path to the station equipment. User-reported troubles on this port should be investigated by using other port tests, by examining station wiring, or by examining the station.</p>
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board). This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"><li>1. Check to ensure that the board translations are correct. Use the <b>list config</b> command and resolve any problems.</li><li>2. If the board was found to be correctly inserted in step 1, issue the <b>busyout board</b> command.</li><li>3. Issue the <b>reset board</b> command.</li><li>4. Issue the <b>release busy board</b> command.</li><li>5. Issue the <b>test board long</b> command. This should re-establish the linkage between the internal ID and the port. If this is not the case, check to ensure that there is a valid board inserted.</li></ol>

## ANL-BD (analog line circuit pack)

---

MO name (in alarm log)	Alarm level	Initial command to run <sup>1</sup>	Full name of MO
ANL-BD	MIN	test board PCSS sh	8-Port Analog Line Circuit Pack
ANL-BD	WRN	test board PCSS sh	8-Port Analog Line Circuit Pack
ANL-BD	MIN	test board PCSS sh	8-Port Neon Analog Line Circuit Pack
ANL-BD	WRN	test board PCSS sh	8-Port Neon Analog Line Circuit Pack
ANL-BD	MIN	test board PCSS sh	16-Port Neon Analog Line Circuit Pack
ANL-BD	WRN	test board PCSS sh	16-Port Neon Analog Line Circuit Pack

- 
1. Where P is the port network number (1 for PPN); C is the carrier designation (for example, A, B, or C); and SS is the address of the slot in the carrier where the circuit pack is located (for example, 01, 02, ..., etc.).
- 

Refer to [“XXX-BD \(Common Port Circuit Pack\)” on page 5-1343](#) for circuit pack level errors. See also [“ANL-LINE \(8-port analog line\), ANL-NE-L \(8-port neon analog line\)” on page 5-65](#), and [“ANL-16-L \(16-Port Neon Analog Line\)” on page 5-26](#) for related line information.

## 5 Maintenance Objects for DEFINITY ONE

ANL-LINE (8-port analog line), ANL-NE-L (8-port neon analog line)

5-65

## ANL-LINE (8-port analog line), ANL-NE-L (8-port neon analog line)

MO name (in alarm log)	Alarm level	Initial command to run <sup>1</sup>	Full name of MO
ANL-LINE	MIN	test port PCSSpp l	8-Port Analog Line
ANL-LINE	WRN	test port PCSSpp sh	8-Port Analog Line
ANL-NE-L	MIN	test port PCSSpp l	8-Port Neon Analog Line
ANL-NE-L	WRN	test port PCSSpp sh	8-Port Neon Analog Line

- 
1. Where P is the port network number (1 for PPN); C is the carrier designation (for example, A, B, or C); SS is the address of the slot in the carrier where the circuit pack is located (for example, 01, 02,..., etc.); and pp is the 2-digit port number (for example, 01).
- 

The 8-Port Analog Line circuit packs are:

- TN742
- TN769
- TN467

These circuit packs provide 8 ports for single line on-premises or off-premises analog endpoints such as analog voice terminals, queue warning level lamp, recorded announcements, dictation machines, PagePac paging equipment, external alerting devices, modems, facsimile machines, and AUDIX voice ports. The TN769 supports a neon message waiting lamp. The other 8-port analog lines do not support the lamp.

Test #48 may cause some terminal equipment to ring briefly during daily maintenance. If this ringing is disturbing the customer or the terminal equipment, it should be disabled using the Tests field of the station administration screen. However, on some releases of the software, this action disables Tests #6, #47, and #35 as well as Test #48. Test #47 may cause a false alarm when the port is connected to off-premises equipment, some non-voice terminal equipment, and some loop equipment. If this is the case, then the test should be disabled using the Tests field of the **change station <extension>** command.

No maintenance of the terminal connected to the 8-Port Analog Line circuit pack or 8-Port Neon Analog Line circuit pack is performed, except to determine whether or not the terminal is connected. Failures of the neon message waiting lamp power (for ANL-NE-L only) and the common ringing application circuitry are reported as part of the Common Port Circuit Pack errors (see errors 1281 and 1793 in [“XXX-BD \(Common Port Circuit Pack\)” on page 5-1343](#)).

5 Maintenance Objects for DEFINITY ONE

ANL-LINE (8-port analog line), ANL-NE-L (8-port neon analog line)

5-66

**Hardware error log entries and test to clear values**

Table 5-24. 8-port analog line error log entries

Error type	Aux data	Associated test	Alarm level	On/Off board	Test to clear value
0 <sup>1</sup>	0	Any	Any	Any	test port PCSSpp sh r 1
1 (a)	40960 40975 40977	None			
15 (b)	Any	Audits and Updates Test (#36)			
18	0	busyout station <extension>	WRN	OFF	release station <extension>
130 (c)		None	WRN	ON	test port PCSSpp sh
257 (d)		Station Present Test (#48)	WRN	OFF	test port PCSSpp sh r 3
513		Battery Feed Test (#35)	MIN/ WRN <sup>2</sup>	ON	test port PCSSpp sh r 2
769 (e)		Loop Around and Conference Test(#47)			test port PCSSpp l r 3
1025		NPE Crosstalk Test (#6)	MIN/ WRN <sup>2</sup>	ON	test port PCSSpp l r 3
1281 (f)					
1793 (f)					

1. Run the Short Test Sequence first. If all tests pass, run the Long Test Sequence. Refer to the appropriate test description and follow the recommended procedures.
2. Major or Minor alarms on this MO may be downgraded to Warning alarms based on the values used in the **set options** command.

Notes:

- a. These are in-line errors and can only be resolved over time.
  - 40960 — indicates that too many simultaneous incoming ringing attempts were made on this board. Only four ports on a board may be ringing simultaneously. A fifth incoming call will cause an inline error from the board.

5 Maintenance Objects for DEFINITY ONE

ANL-LINE (8-port analog line), ANL-NE-L (8-port neon analog line)

5-67

- 40975 — indicates that the terminal equipment was on-hook when ring-tip was detected during ringing. This usually indicates a failure in the terminal equipment or the type of terminal has a low ringer impedance. Call the terminal equipment and verify that the terminal rings. If the terminal doesn't ring, then replace it. Otherwise, issue the **test port PCSSpp** command, and follow the procedure for Test #48.
  - 40977 — indicates that no terminal equipment was connected when ringing was attempted. Run the Short Test via the **test port PCSSpp** command, and follow the procedure for the results of Test #48.
- b. This is a software audit error that does not indicate any hardware malfunction. Run Short Test Sequence and investigate errors (if any).
  - c. This error type indicates that the circuit pack has been removed or has been insane for more than 11 minutes. To clear the error, reinsert or replace the circuit pack.
  - d. Test #48 may cause some terminal equipment to ring briefly during daily maintenance. If this ringing is disturbing the customer or the terminal equipment, it should be disabled via the **change station <extension>** command. However, on some releases of the software, this disables Tests #6, #47, and #35 as well as Test #48.
  - e. Test #47 may cause a false alarm when the port is connected to off-premises equipment, some non-voice terminal equipment, and some loop equipment. If this causes a false alarm, then disable the test by changing the Tests field of the **change station** command to "no."
  - f. Refer to ["XXX-BD \(Common Port Circuit Pack\)" on page 5-1343](#).
-

**5 Maintenance Objects for DEFINITY ONE**

ANL-LINE (8-port analog line), ANL-NE-L (8-port neon analog line)

5-68

**System technician-demanded tests: descriptions  
and error codes**

---

Always investigate tests in the order presented in the table below when inspecting errors in the system. By clearing error codes associated with the *Battery Feed Test*, for example, you may also clear errors generated from other tests in the testing sequence.

**Table 5-25. System technician-demanded tests: ANL-LINE**

---

<b>Order of investigation</b>	<b>Short test sequence</b>	<b>Long Test sequence</b>	<b>D/ND<sup>1</sup></b>
Battery Feed Test (#35)	X	X	ND
Station Present Test (#48)	X	X	ND
NPE Crosstalk Test (#6)		X	ND
Loop Around and Conference Test (#47)		X	ND
Station Status and Translation Audits and Updates Test (#36)	X	X	ND

---

---

1. D = Destructive, ND = Non-destructive

---

**NPE crosstalk test (#6)**

One or more NPEs reside on each circuit pack with a TDM Bus interface. The NPE controls port connectivity and gain, and provides conferencing functions on a per-port basis. The NPE Crosstalk Test verifies that this port's NPE channel talks on the selected time slot and never crosses over to time slots reserved for other connections. If the NPE is not working correctly, one-way and noisy connections may be observed. This test is usually only part of a port's Long Test Sequence and takes about 20 to 30 seconds to complete.

## 5 Maintenance Objects for DEFINITY ONE

ANL-LINE (8-port analog line), ANL-NE-L (8-port neon analog line)

5-69

Table 5-26. TEST #6 NPE crosstalk test

Error code	Test result	Description/ Recommendation
1000	ABORT	<p>System resources required to run this test are not available. The port may be busy with a valid call. Use the <b>display port PCSSpp</b> command to determine the station extension. Use the <b>status station</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. (Refer to <a href="#">“status station” on page 4-213</a> for a full description of all possible states.) You must wait until the port is idle before retesting.</p> <ol style="list-style-type: none"><li>1. If the port status is idle, then retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
1001	ABORT	<p>Could not allocate the necessary system resources to run this test.</p> <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
1002	ABORT	<p>The system could not allocate time slots for the test. The system may be under heavy traffic conditions or it may have time slots out-of-service due to TDM-BUS errors. Refer to <a href="#">“TDM-BUS (TDM Bus)” on page 5-1116</a> to diagnose any active TDM-BUS errors.</p> <ol style="list-style-type: none"><li>1. If system has no TDM-BUS errors and is not handling heavy traffic, repeat test at 1-minute intervals a maximum of 5 times.</li></ol>
1003	ABORT	<p>The system could not allocate a tone receiver for the test. The system may be oversized for the number of Tone Detectors present or some Tone Detectors may be out-of-service.</p> <ol style="list-style-type: none"><li>1. Look for TTR-LEV errors in the Error Log. If present, refer to <a href="#">“TTR-LEV (TTR Level)” on page 5-1223</a>.</li><li>2. Look for TONE-PT errors in the Error Log. If present, refer to <a href="#">“TONE-PT (Tone Generator)” on page 5-1204</a>.</li><li>3. If neither condition exists, retry the test at 1-minute intervals a maximum of 5 times.</li></ol>

*Continued on next page*

## 5 Maintenance Objects for DEFINITY ONE

ANL-LINE (8-port analog line), ANL-NE-L (8-port neon analog line)

5-70

Table 5-26. TEST #6 NPE crosstalk test — *Continued*

Error code	Test result	Description/ Recommendation
1004	ABORT	<p>System resources required to run this test are not available. The port may be busy with a valid call. Use the <b>display port PCSSpp</b> command to determine the station extension. Use the <b>status station</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. (Refer to <a href="#">“status station” on page 4-213</a> for a full description of all possible states.) You must wait until the port is idle before retesting.</p> <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
1005	ABORT	<p>The test was aborted due to a configuration problem. This code will result under either of the following conditions:</p> <ol style="list-style-type: none"><li>1. This test may not be applicable, or it may be disruptive to terminal equipment other than a voice terminal (for example, the modem pool member or music on hold).</li><li>2. The circuit pack is one of the following:<ul style="list-style-type: none"><li>— TN742 vintages 13, 14 and 15</li><li>— TN769 vintages 3, 4 and 5</li></ul></li></ol>
1018	ABORT	<p>Test disabled via administration. The default for the 'Test' field on the 'Station' form is 'y'; thus, you may want to determine why this field has been set to 'n' on this station (this may be due to the ringing application test 48, which can be customer or terminal disturbing).</p> <ol style="list-style-type: none"><li>1. To enable the test for a particular station, enter <b>change station extension</b> and set the 'Test?' field on the 'Station Form' to 'y.'</li></ol>
1020	ABORT	<p>The test did not run due to a previously existing error on the specific port or a more general circuit pack error.</p> <ol style="list-style-type: none"><li>1. Examine Error Log for existing errors against this port or the circuit pack and attempt to diagnose the previously existing error.</li></ol>

*Continued on next page*

5 Maintenance Objects for DEFINITY ONE

ANL-LINE (8-port analog line), ANL-NE-L (8-port neon analog line)

5-71

Table 5-26. TEST #6 NPE crosstalk test — *Continued*

Error code	Test result	Description/ Recommendation
2000	ABORT	Response to the test request was not received within the allowable time period.
2100	ABORT	<p>System resources required to run this test are not available. Either a system allocation to get information about the port or to put the port into a service state failed or the attempt to put the port in connection with a tone source failed (this could be a tone-clock problem). The tone-clock and tone detectors could be having a communication problem, for example, the companding modes could be out of synchronization.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
Any	FAIL	<p>This test can fail due to on-board or off-board problems. Off-board problems of concern include EXP-INTF faults, TDM-BUS faults, and faults associated with the tone detectors/tone generators. Clear all off-board problems before replacing the board. Keep in mind that a TDM-BUS problem is usually the result of a faulty board connected to the backplane or bent pins on the backplane.</p> <ol style="list-style-type: none"> <li>1. Look for EXP-INTF errors in the error log. If present, refer to the EXP-INTF Maintenance documentation.</li> <li>2. Look for TDM-BUS errors in the error log. If present, refer to the <a href="#">“TDM-BUS (TDM Bus)” on page 5-1116</a>.</li> <li>3. Look for TONE-BD and/or TONE-PT errors in the error log. If present, refer to the TONE-BD Maintenance documentation and the <a href="#">“TONE-PT (Tone Generator)” on page 5-1204</a>.</li> <li>4. Test the board when the faults from steps 1, 2, and 3 are cleared. Replace the board only if the test fails.</li> </ol>
	PASS	<p>The port is correctly using its allocated time slots. User-reported troubles on this port should be investigated by using other port tests, by examining station wiring, by examining the station, and by ensuring that the terminal is correctly translated as off-premises or on-premises.</p> <p> <b>NOTE:</b> This test always passes for Analog circuit packs TN742 prior to Vintage 4.</p>

*Continued on next page*

## 5 Maintenance Objects for DEFINITY ONE

ANL-LINE (8-port analog line), ANL-NE-L (8-port neon analog line)

5-72

Table 5-26. TEST #6 NPE crosstalk test — *Continued*

Error code	Test result	Description/ Recommendation
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board). This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"><li>1. Check to ensure that the board translations are correct. Use the <b>list config</b> command and resolve any problems.</li><li>2. If the board was found to be correctly inserted in step 1, issue the <b>busyout board</b> command.</li><li>3. Issue the <b>reset board</b> command.</li><li>4. Issue the <b>release busy board</b> command.</li><li>5. Issue the <b>test board long</b> command. This should re-establish the linkage between the internal ID and the port. If this is not the case, dispatch to check to ensure that there is a valid board inserted.</li></ol>

**Battery feed test (also called port diagnostic test)****(#35)**

The battery feed chip provides power to the telephone equipment, signaling, rotary dial pulsing, transmission, and balance. This test checks the signaling and switchhook capabilities of the battery feed chip by terminating the port, applying battery, and trying to detect a current.

## 5 Maintenance Objects for DEFINITY ONE

ANL-LINE (8-port analog line), ANL-NE-L (8-port neon analog line)

5-73

Table 5-27. TEST #35 battery feed test

Error code	Test result	Description/ Recommendation
	ABORT	Could not allocate the necessary system resources to run this test. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
1000	ABORT	System resources required to run this test are not available. The port may be busy with a valid call. Use the <b>display port PCSSpp</b> command to determine the station extension. Use the <b>status station</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. (Refer to the "Status Commands" section in Chapter 8, "Maintenance Commands and Trouble-Clearing Aids", for a full description of all possible states.) You must wait until the port is idle before retesting. <ol style="list-style-type: none"><li>1. If the port status is idle, then retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
1004	ABORT	System resources required to run this test are not available. The port may be busy with a valid call. Use the <b>display port PCSSpp</b> command to determine the station extension. Use the <b>status station</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. (Refer to the "Status Commands" section in Chapter 8, "Maintenance Commands and Trouble-Clearing Aids", for a full description of all possible states.) You must wait until the port is idle before retesting. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
1005	ABORT	The test was aborted due to a configuration problem. This code will result under either of the following conditions: <ol style="list-style-type: none"><li>1. This test may not be applicable, or it may be disruptive to terminal equipment other than a voice terminal (for example, the modem pool member or music on hold).</li><li>2. The circuit pack is one of the following:<ul style="list-style-type: none"><li>— TN742 vintages 13, 14 and 15</li><li>— TN769 vintages 3, 4 and 5</li></ul></li></ol>

*Continued on next page*

5 Maintenance Objects for DEFINITY ONE

ANL-LINE (8-port analog line), ANL-NE-L (8-port neon analog line)

5-74

Table 5-27. TEST #35 battery feed test — *Continued*

Error code	Test result	Description/ Recommendation
1018	ABORT	<p>Test disabled via administration. The default for the 'Test' field on the 'Station' form is 'y'; thus, you may want to determine why this field has been set to 'n' on this station (this may be due to the ringing application test 48, which can be customer or terminal disturbing).</p> <ol style="list-style-type: none"> <li>To enable the test for a particular station, enter <b>change station extension</b> and set the 'Test?' field on the 'Station Form' to 'y.'</li> </ol>
2000	ABORT	<p>Response to the test request was not received within the allowable time period.</p>
2100	ABORT	<p>System resources required to run this test are not available. Either a system allocation to get information about the port or to put the port into a service state failed or the attempt to put the port in connection with a tone source failed (this could be a tone-clock problem). The tone-clock and tone detectors could be having a communication problem, for example, the companding modes could be out of synchronization.</p> <ol style="list-style-type: none"> <li>Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
	FAIL	<p>The port's battery feed chip is unable to supply sufficient power to the terminal equipment. This may occur when the test is performed at the same time that the terminal equipment goes off-hook.</p> <ol style="list-style-type: none"> <li>Use <b>status station</b> to determine when the port is available for testing. When the port becomes available for testing, retry the command at 1-minute intervals a minimum of 5 times.</li> <li>If the test continues to fail, determine whether the customer is experiencing problems on this line. Replace the circuit pack only if the customer is experiencing problems.</li> </ol>

*Continued on next page*

## 5 Maintenance Objects for DEFINITY ONE

ANL-LINE (8-port analog line), ANL-NE-L (8-port neon analog line)

5-75

Table 5-27. TEST #35 battery feed test — *Continued*

Error code	Test result	Description/ Recommendation
	PASS	<p>The port's battery feed chip is able to provide power to the station equipment to detect on-/off-hook. However, the battery feed chip may still be unable to provide power for touch-tones. If tones are heard when buttons are pressed, then the battery feed chip is functioning correctly; otherwise, replace the circuit pack because this port is defective. User-reported troubles on this port should be investigated by using other port tests, by examining station wiring, by examining the station, and by ensuring that the terminal is correctly translated as off-premises or on-premises.</p> <p> <b>NOTE:</b> This test always passes for TN742 Analog circuit packs prior to Vintage 6.</p>
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board). This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"> <li>1. Check to ensure that the board translations are correct. Use the <b>list config</b> command, and resolve any problems that are found.</li> <li>2. If the board was found to be correctly inserted in step 1, issue the <b>busyout board</b> command.</li> <li>3. Issue the <b>reset board</b> command.</li> <li>4. Issue the <b>release busy board</b> command.</li> <li>5. Issue the <b>test board long</b> command. This should re-establish the linkage between the internal ID and the port. If this is not the case, dispatch to check to ensure that there is a valid board inserted.</li> </ol>

### Station status and translation audits and updates test (#36)

This test updates the analog port's message lamp state (if it has one) and translations (such as station type, dial type, network connection) with information kept in the software. The software is updated with the switchhook state reported by the port processor. When the ringer is in the off state, this test also turns off the station's ringer to prevent constant ringing caused by defective hardware.

5 Maintenance Objects for DEFINITY ONE

ANL-LINE (8-port analog line), ANL-NE-L (8-port neon analog line)

5-76

Table 5-28. TEST #36 station status and translation audits and updates test

Error code	Test result	Description/ Recommendation
1004	ABORT	Could not allocate the necessary system resources to run this test.
	ABORT	System resources required to run this test are not available. The port may be busy with a valid call. Use the <b>display port PCSSpp</b> command to determine the station extension. Use the <b>status station</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. (Refer to the "Status Commands" section in Chapter 8, "Maintenance Commands and Trouble-Clearing Aids", for a full description of all possible states.) You must wait until the port is idle before retesting. <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
1005	ABORT	The test was aborted due to a configuration problem. This code will result under either of the following conditions: <ol style="list-style-type: none"> <li>1. This test may not be applicable, or it may be disruptive to terminal equipment other than a voice terminal (for example, the modem pool member or music on hold).</li> <li>2. The circuit pack is one of the following:                             <ul style="list-style-type: none"> <li>— TN742 vintages 13, 14 and 15</li> <li>— TN769 vintages 3, 4 and 5</li> </ul> </li> </ol>
1006	ABORT	This port has been busied out by command or taken out-of-service by the failure of the NPE Crosstalk Test. <ol style="list-style-type: none"> <li>1. Look in the Error Log for Error Type 18 (port busied out) for this port. If this error is present, then release the port with the <b>release station extension</b> command and run the test again.</li> <li>2. Look in the Error Log for Error Type 1025 (NPE Crosstalk Test failed) for this port. If this error is present, then investigate the errors associated with the NPE Crosstalk Test (#6) first.</li> <li>3. Make sure that the terminal is connected and in service, and then retest.</li> </ol>
2000	ABORT	Could not allocate the necessary system resources to run this test.
	ABORT	Response to the test request was not received within the allowable time period.
2100	ABORT	Could not allocate the necessary system resources to run this test. <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>

Continued on next page

## 5 Maintenance Objects for DEFINITY ONE

ANL-LINE (8-port analog line), ANL-NE-L (8-port neon analog line)

5-77

Table 5-28. TEST #36 station status and translation audits and updates test — *Continued*

Error code	Test result	Description/ Recommendation
1	FAIL	<p>This does not indicate a hardware problem. The switchhook audit failed, and the other updates were not performed because of this failure. This condition may occur when the audit is performed at the same time that the terminal equipment goes off-hook. Use the <b>status station</b> command to determine when the port is available for testing.</p> <ol style="list-style-type: none"><li>1. When the port becomes available for testing, retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
5	FAIL	<p>This does not indicate a hardware problem but may indicate an internal software error. The message waiting lamp update failed. The translation and ringer updates were not performed because of this failure.</p>
7	FAIL	<p>The translation update failed. The ringer update was not performed because of this failure. This does not indicate a hardware problem but may be an internal software error.</p>
8	FAIL	<p>This does not indicate a hardware problem but may be an internal software error. The ringer update failed.</p> <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>

*Continued on next page*

## 5 Maintenance Objects for DEFINITY ONE

ANL-LINE (8-port analog line), ANL-NE-L (8-port neon analog line)

5-78

Table 5-28. TEST #36 station status and translation audits and updates test — *Continued*

Error code	Test result	Description/ Recommendation
	PASS	<p>The software and the port processor have the same status. User-reported troubles on this port should be investigated by using other port tests, by examining station wiring, by examining the station, and by ensuring that the terminal is correctly translated as off-premises or on-premises.</p> <p> <b>NOTE:</b> This test always passes for TN742 Analog circuit packs prior to Vintage 6.</p>
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board). This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"> <li>1. Check to ensure that the board translations are correct. Use the <b>list config</b> command, and resolve any problems that are found.</li> <li>2. If the board was found to be correctly inserted in step 1, issue the <b>busyout board</b> command.</li> <li>3. Issue the <b>reset board</b> command.</li> <li>4. Issue the <b>release busy board</b> command.</li> <li>5. Issue the <b>test board long</b> command. This should re-establish the linkage between the internal ID and the port. If this is not the case, dispatch to check to ensure that there is a valid board inserted.</li> </ol>

**Loop around and conference test (#47)**

Each Analog Port consists of:

- An NPE for port connectivity and gain, and conferencing functionality
- A code that converts the digital signals of the TDM Bus to analog signals
- A battery feed chip that provides power to the telephone set for signaling, dial pulsing, transmission, and balance

This test is designed to check the on-board transmission capabilities of the NPE, the code, and the battery feed chip of the Analog Port. A Tone Detector and a Tone Generator talk and listen on the same pair of time slots as the Analog Port. The Analog Port is then instructed to go into loop around mode (see [Figure 5-3](#)).

## 5 Maintenance Objects for DEFINITY ONE

ANL-LINE (8-port analog line), ANL-NE-L (8-port neon analog line)

5-79

The test passes if the signal measured by the Tone Detector is within acceptable limits.

The Conference Circuit Test verifies that the NPE channel for the port being tested can correctly perform the conferencing function. As part of Test #47, the operation of the port conference circuits in the NPE for three and four parties is also tested. In addition, a test is run to measure noise. The NPE is instructed to listen to several different tones and conference the tones together. The resulting signal is then measured by a Tone Detector port. If the level of the tone is within a certain range, the test passes.

The noise test is performed by filtering out the tone and then measuring inherent port noise.

**⇒ NOTE:**

This Loop Around Test is sensitive to the length of the loop, the equipment in the loop, or the equipment terminating the loop, such as off-premises stations. If this test is causing a false alarm, then disable the test by changing the Tests field to "no" using the **change station** command for this station.




Figure 5-3. Analog Loop Around and Conference Test

## 5 Maintenance Objects for DEFINITY ONE

ANL-LINE (8-port analog line), ANL-NE-L (8-port neon analog line)

5-80

Table 5-29. TEST #47 loop around and conference test

Error code	Test result	Description/ Recommendation
	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals a maximum of 5 times.
7	ABORT	The port was seized by a user for a valid call. 1. Enter <b>display port PCSSpp</b> to determine the station's extension. Enter <b>status station extension</b> to determine the service state of the port. If the port is in use, it will be unavailable for certain tests. Wait until the port is idle before retesting. 2. If the port is idle, retry the command at 1-minute intervals up to 5 times.
1000	ABORT	System resources required to run this test were not available. The port may be busy with a valid call. (This could be a Music-on-Hold port.) 1. Enter <b>display port PCSSpp</b> to determine the station's extension. Enter <b>status station extension</b> to determine the service state of the port. If the port is in use, it will be unavailable for certain tests. Wait until the port is idle before retesting. 2. If the port is idle, retry the command at 1-minute intervals up to 5 times.
1002	ABORT	The system could not allocate time slots for the test. The system may be under heavy traffic conditions or it may have time slots out-of-service due to TDM-BUS errors. Refer to <a href="#">"TDM-BUS (TDM Bus)" on page 5-1116</a> to diagnose any active TDM-BUS errors. 1. If system has no TDM-BUS errors and is not handling heavy traffic, repeat test at 1-minute intervals a maximum of 5 times.
1003	ABORT	The system could not allocate a tone receiver for the test. The system may be oversized for the number of Tone Detectors present or some Tone Detectors may be out-of-service. 1. Look for TTR-LEV errors in the Error Log. If present, refer to <a href="#">"TTR-LEV (TTR Level)" on page 5-1223</a> . 2. Look for TONE-PT errors in the Error Log. If present, refer to <a href="#">"TONE-PT (Tone Generator)" on page 5-1204</a> . 3. If neither condition exists, retry the test at 1-minute intervals a maximum of 5 times.

Continued on next page

## 5 Maintenance Objects for DEFINITY ONE

ANL-LINE (8-port analog line), ANL-NE-L (8-port neon analog line)

5-81

Table 5-29. TEST #47 loop around and conference test — *Continued*

Error code	Test result	Description/ Recommendation
1004	ABORT	<p>The port has been seized for a valid call during the conference or noise test. Use the <b>status station</b> command to determine when the port is available for testing.</p> <ol style="list-style-type: none"><li>1. If the circuit pack is a TN742 with vintage 10 or less, this test is not valid. Otherwise, proceed with #2.</li><li>2. When the port is available for testing, retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
1005	ABORT	<p>The test was aborted due to a configuration problem. This code will result under either of the following conditions:</p> <ol style="list-style-type: none"><li>1. This test may not be applicable, or it may be disruptive to terminal equipment other than a voice terminal (for example, the modem pool member or music on hold).</li><li>2. The circuit pack is one of the following:<ul style="list-style-type: none"><li>— TN742 vintages 13, 14 and 15</li><li>— TN769 vintages 3, 4 and 5</li></ul></li></ol>
1018	ABORT	<p>Test disabled via administration. The default for the 'Test' field on the 'Station' form is 'y'; thus, you may want to determine why this field has been set to 'n' on this station (this may be due to the ringing application test 48, which can be customer or terminal disturbing).</p> <ol style="list-style-type: none"><li>1. To enable the test for a particular station, enter <b>change station</b> extension and set the 'Test?' field on the 'Station Form' to 'y.'</li></ol>
2000	ABORT	<p>Response to the test request was not received within the allowable time period.</p>
2100	ABORT	<p>System resources required to run this test are not available. Either a system allocation to get information about the port or to put the port into a service state failed or the attempt to put the port in connection with a tone source failed (this could be a tone-clock problem). The tone-clock and tone detectors could be having a communication problem, for example, the companding modes could be out of synchronization.</p> <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>

*Continued on next page*

5 Maintenance Objects for DEFINITY ONE

ANL-LINE (8-port analog line), ANL-NE-L (8-port neon analog line)

5-82

Table 5-29. TEST #47 loop around and conference test — *Continued*

Error code	Test result	Description/ Recommendation
7  13  14  15	FAIL	<p>The conference test or the noise test failed. This could cause noisy or unreliable connections, or users calling this port may hear an echo. The problem can also be off-board, as described below.</p> <p>The reflective loop around with gain set to low and the 600-ohm balance failed. This will cause noisy or unreliable connections.</p> <p>The reflective loop around test (with the gain set to high, using RC balance) failed. This could cause noisy or unreliable connections. The problem can also be off-board, as described below.</p> <p>The nonreflective loop around test failed. This could cause noisy or unreliable connections, or users calling this port may hear an echo. The problem can also be off-board, as described below.</p> <p><i>More information follows.</i></p>
7 13 14 15  (cont'd.)	FAIL  (cont'd.)	<ol style="list-style-type: none"> <li>1. Disconnect the terminal equipment from the circuit pack at the cross-connect and run the test again.</li> <li>2. If the test fails again, replace the circuit pack and reconnect the terminal equipment. If the test passes the second time, then the test results were affected by the terminal equipment connected to the port; in this case, ignore the results of this test if all other tests pass or abort and the station is operating properly. Failure of test 47 does not cause an alarm. If there are failures of other tests, then investigate those errors. User reported troubles with this port should be investigated by using other port tests, by examining station wiring, and by examining the station to ensure that it is correctly translated as off-premises or on-premises.</li> </ol> <p><b>⇒ NOTE:</b> If the loop around and conference circuit test fails for all ports on a circuit pack, a -5 volt power problem is indicated.</p>
	PASS	<p>The port is able to provide an analog transmission path to the station equipment. User-reported troubles on this port should be investigated by using other port tests, by examining station wiring, by examining the station, and by ensuring that the terminal is correctly translated as off-premises or on-premises.</p> <p><b>⇒ NOTE:</b> This test always passes for TN742 Analog circuit packs prior to Vintage 6.</p>

*Continued on next page*

## 5 Maintenance Objects for DEFINITY ONE

ANL-LINE (8-port analog line), ANL-NE-L (8-port neon analog line)

5-83

Table 5-29. TEST #47 loop around and conference test — *Continued*

Error code	Test result	Description/ Recommendation
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board). This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"><li>1. Check to ensure that the board translations are correct. Use the <b>list config</b> command, and resolve any problems that are found.</li><li>2. If the board was found to be correctly inserted in step 1, issue the <b>busyout board</b> command.</li><li>3. Issue the <b>reset board</b> command.</li><li>4. Issue the <b>release busy board</b> command.</li><li>5. Issue the <b>test board long</b> command. This should re-establish the linkage between the internal ID and the port. If this is not the case, dispatch to check to ensure that there is a valid board inserted.</li></ol>

**Station present test (also called ringing application test) (#48)**

This test provides a burst of ringing current to the terminal equipment and detects that current flows. This test is to ascertain whether or not terminal equipment is connected to the port.

This test may cause some terminal equipment to ring briefly during daily maintenance. If this ringing is disturbing the customer or the terminal equipment, it should be disabled using the Tests field of the station administration screen. However, on some releases of the software, this action disables Tests #6, #47, and #35 as well as Test #48.

5 Maintenance Objects for DEFINITY ONE

ANL-LINE (8-port analog line), ANL-NE-L (8-port neon analog line)

5-84

Table 5-30. TEST #48 station present test

Error code	Test result	Description/ Recommendation
	ABORT	<p>Could not allocate the necessary system resources to run this test.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
1000	ABORT	<p>System resources required to run this test were not available. The port may be busy with a valid call.</p> <p>Use the <b>display port PCSSpp</b> to determine the station's extension. Enter <b>status station</b> extension to determine the service state of the port. If the port is in use, it will be unavailable for certain tests. Wait until the port is idle before retesting.</p> <ol style="list-style-type: none"> <li>1. If the port is idle, retry the command at 1-minute intervals up to 5 times.</li> <li>2. Check for phone left off-hook or for wiring problems.</li> </ol>
1004	ABORT	<p>System resources required to run this test are not available. The port may be busy with a valid call. Use the <b>display port PCSSpp</b> command to determine the station extension. Use the <b>status station</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. (Refer to the "Status Commands" section in Chapter 8, "Maintenance Commands and Trouble-Clearing Aids", for a full description of all possible states.) You must wait until the port is idle before retesting.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
1005	ABORT	<p>The test was aborted due to a configuration problem. This code will result under either of the following conditions:</p> <ol style="list-style-type: none"> <li>1. This test may not be applicable, or it may be disruptive to terminal equipment other than a voice terminal (for example, the modem pool member or music on hold).</li> <li>2. The circuit pack is one of the following: <ul style="list-style-type: none"> <li>— TN742 vintages 13, 14 and 15</li> <li>— TN769 vintages 3, 4 and 5</li> </ul> </li> </ol>

*Continued on next page*

5 Maintenance Objects for DEFINITY ONE

ANL-LINE (8-port analog line), ANL-NE-L (8-port neon analog line)

5-85

Table 5-30. TEST #48 station present test — *Continued*

Error code	Test result	Description/ Recommendation
1008	ABORT	<p>Could not allocate a ringing circuit for one of the following reasons:</p> <ul style="list-style-type: none"> <li>■ All the ringing circuits are in use, or</li> <li>■ The ringing generator is defective, or</li> <li>■ It is not wired correctly.</li> </ul> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> <li>2. If the test continues to abort, look for RING-GEN errors in the Error Log. If an ABORT 1008 occurs for Test #48 on other circuit packs as well, then the ring generator may be defective. If it does not occur on other ports, then that circuit pack is currently using all 4 ringing phases.</li> </ol>
1018	ABORT	<p>The test was disabled via administration. The default for the 'Test' field on the 'Station' form is 'y'; thus, you may want to determine why this field has been set to 'n' on this station (this may be due to the ringing application test 48, which can be customer or terminal disturbing).</p> <ol style="list-style-type: none"> <li>1. To enable the test for a particular station, enter <b>change station &lt;extension&gt;</b> and set the Test? field on the station form to <b>y</b>.</li> </ol>
2000	ABORT	<p>Response to the test request was not received within the allowable time period.</p>
2100	ABORT	<p>System resources required to run this test are not available. Either a system allocation to get information about the port or to put the port into a service state failed or the attempt to put the port in connection with a tone source failed (this could be a tone-clock problem). The tone-clock and tone detectors could be having a communication problem, for example, the companding modes could be out of synchronization.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>

*Continued on next page*

## 5 Maintenance Objects for DEFINITY ONE

ANL-LINE (8-port analog line), ANL-NE-L (8-port neon analog line)

5-86

Table 5-30. TEST #48 station present test — *Continued*

Error code	Test result	Description/ Recommendation
	FAIL	<p>The terminal equipment is not connected to the circuit pack or the ringing generator may have failed.</p> <ol style="list-style-type: none"><li>1. Remotely test the equipment.</li><li>2. If the test fails again, look for RING-GEN errors in the error log. If present, refer to the <a href="#">“RING-GEN (Analog Ring Generator)” on page 5-1036</a>.</li><li>3. Check all of the wiring between the station equipment and the switch. Then, run the test again.</li><li>4. If the test still fails, the set may be defective. Check the set, and replace it, if necessary.</li><li>5. Some terminal equipment (such as a modem) could fail even when it is connected properly. If this is the case, disable the test using the <b>change station extension</b> command (enter 'n' into the 'Test' field). Note that this action also disables tests 6, 7, 161, and 35 on this port.</li></ol>
	PASS	<p>The station is connected properly to the switch. This test may also pass if no terminal equipment is connected and the terminal is located far from the switch (that is, it is off-premises). User-reported troubles on this port should be investigated by using other port tests, by examining station wiring, by examining the station, and by ensuring that the terminal is correctly translated as off-premises or on-premises.</p> <p> <b>NOTE:</b> This test always passes for TN742 Analog circuit packs prior to Vintage 6.</p>

*Continued on next page*

## 5 Maintenance Objects for DEFINITY ONE

ANL-LINE (8-port analog line), ANL-NE-L (8-port neon analog line)

5-87

Table 5-30. TEST #48 station present test — *Continued*

Error code	Test result	Description/ Recommendation
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board). This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"><li>1. Check to ensure that the board translations are correct. Use the <b>list config</b> command, and resolve any problems that are found.</li><li>2. If the board was found to be correctly inserted in step 1, issue the <b>busyout board</b> command.</li><li>3. Issue the <b>reset board</b> command.</li><li>4. Issue the <b>release busy board</b> command.</li><li>5. Issue the <b>test board long</b> command. This should re-establish the linkage between the internal ID and the port. If this is not the case, dispatch to check to ensure that there is a valid board inserted.</li></ol>

## AN-LN-PT (Analog Line Port)

---

MO name (in alarm log)	Alarm level	Initial command to run <sup>1</sup>	Full name of MO
AN-LN-PT	MIN	test port UUCSSpp l	Analog Line Port
AN-LN-PT	WRN	test port UUCSSpp sh	Analog Line Port

- 
1. UU is the universal cabinet number (1 for PPN, 2 -44 for EPNs). C is the carrier designation (A, B, C, D, or E). SS is the number of the slot in which the circuit pack resides (01 to 21). pp is the two digit port number (01, 02, ...).
- 

The TN793B/TN2793B Analog Line circuit pack (w/ Caller ID), and the TN797 Analog Trunk and Line circuit pack both support this Maintenance Object.

The TN793B/TN2793B Analog Line circuit pack (w/ Caller ID) provides 24 ports for voice terminals and supports both on-premises and off-premises analog voice terminals.

The TN797 Analog Trunk and Line circuit pack provides 8 ports, each of which may be administered in any of several ways, as described in maintenance object TR-LN-BD.

### NOTE:

The TN793B/TN2793B analog line circuit pack supports analog data modules. When assigned, analog data modules provide access to the NetPkt (TN794 circuit pack) data ports. To activate an analog data module you must assign the port location on the data form and connect a modem to the port. The analog data module can be used for connection to a CDR output, or other adjuncts as needed. These ports are tested the same as all other analog ports on the circuit pack.

## Ringling caused by maintenance testing

---

Test #48 may cause some terminal equipment to ring briefly during daily maintenance. If this ringing disturbs the customer or the terminal equipment, disable it in the `Tests` field of the **change station extension** form. Be aware that this action also disables Tests #6, 7, 161, and 35 on some software releases.

5 Maintenance Objects for DEFINITY ONE  
AN-LN-PT (Analog Line Port)

5-89

Error log entries and test to clear values

Error type	Aux data	Associated test	Alarm level	On/Off board	Test to clear value
0 <sup>1</sup>	0	Any	Any	Any	test port UUCSSpp sh r 1
1(a)	40960 40975 40977	none			
15(b)	Any	Audits and Updates Test (#36)			
18	0	busy station extension	WRN	ON	release station <i>extension</i>
130(c)		None	WRN	ON	test port UUCSSpp sh
257(d)	40973	none			
513(e)		Station Present Test (#48)	WRN	OFF	test port UUCSSpp sh r 2
769		Battery Feed Test (#35)	MIN/ WRN <sup>2</sup>	ON	test port UUCSSpp sh r 2
1025		Looparound Test (#161)	MIN/ WRN <sup>2</sup>	ON	test port UUCSSpp l r 2
1281		Conference Test (#7)	MIN/ WRN <sup>2</sup>	ON	test port UUCSSpp l r 2
1537		NPE Crosstalk Test (#6)	MIN/ WRN <sup>2</sup>	ON	test port UUCSSpp l r 2

1. Run the Short Test Sequence first. If all tests pass, run the Long Test Sequence. Refer to the appropriate test description and follow the recommended procedures.
2. Minor alarms on this MO may be downgraded to Warning alarms based on the values used in the **set options** command.

## Notes:

- a. **Error Type 1:** these are in-line errors and can only be resolved over time.
  - Aux Data 40960 indicates that too many simultaneous incoming ringing attempts were made on this board. Only 4 ports on a board may ring simultaneously. A 5th incoming call will cause an inline error from the board.

5 Maintenance Objects for DEFINITY ONE  
AN-LN-PT (Analog Line Port)

5-90

- Aux Data 40975 indicates that the terminal equipment was on-hook when ring-tip was detected during ringing. This usually indicates a failure in the terminal equipment or the type of terminal has a low ringer impedance.
    1. Call the terminal equipment and verify that the terminal rings.
    2. If the terminal does not ring, then replace it.
    3. Otherwise, issue the **test port UUCSSpp** command, and follow the procedure for Test #48.
  - 40977 indicates that no terminal equipment was connected when ringing was attempted.
    1. Run the short test via the **test port UUCSSpp** command, and follow the procedure for the results of Test #48.
  - b. **Error Type 15:** this is a software audit error that does not indicate any hardware malfunction.
    1. Run the Short Test Sequence and investigate any associated errors.
  - c. **Error Type 130:** this error type indicates that the circuit pack has been removed or has been insane for more than 11 minutes.
    1. To clear the error, reseal or replace the circuit pack.
  - d. **Error Type 257:** this is an in-line error and can only be resolved over time. This error indicates that ringing voltage is absent.
    1. If only 1 analog circuit pack in the system has this problem, replace the circuit pack.
    2. If only analog circuit packs on a particular carrier have this error, the ringing generator may not be connected to this carrier.
    3. If analog circuit packs on many carriers have this error, it is probably a problem with the ringing generator.
  - e. **Error Type 513:** Test #48 can cause some terminal equipment to ring briefly during daily maintenance.
    1. If this disturbs the customer or the terminal equipment, disable it by setting the `Tests` field on the **change station extension** form to **n**. On some software releases, this also disables Tests #6, 7, 161, and 35.
-

## System technician-demanded tests: descriptions and error codes

---

Always investigate tests in the order presented in the table below when inspecting errors in the system. By clearing error codes associated with the *Battery Feed Test*, for example, you may also clear errors generated from other tests in the testing sequence.

Order of investigation	Short test sequence	Long test sequence	D/ND <sup>1</sup>
Battery Feed Test (#35)	X	X	ND
Station Present Test (#48)	X	X	ND
Looparound Test (#161)		X	ND
Conference Test (#7)		X	ND
NPE Crosstalk Test (#6)		X	ND
Station Status and Translation Audits and Updates Test (#36)	X	X	ND

---

1. D = Destructive; ND = Nondestructive

---

**NPE Crosstalk Test (#6)**

This test verifies that the port's NPE channel talks on the selected time slot and never crosses over to time slots reserved for other connections. If the NPE is not working correctly, one-way and noisy connections may be observed. This test is usually part of the long test sequence and takes about 20 to 30 seconds to complete.

**Table 5-31. TEST #6 NPE Crosstalk Test**

<b>Error Code</b>	<b>Test Result</b>	<b>Description/Recommendation</b>
	ABORT	Necessary system resources could not be allocated to run this test. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals no more than 5 times.</li><li>2. If the test continues to abort, escalate the problem.</li></ol>
1000	ABORT	System resources are unavailable. The port may be busy with a valid call. This result is also reported for the system's Music-On-Hold port when it is off-hook, which it usually is. <ol style="list-style-type: none"><li>1. Enter <b>display port UUCSSpp</b> to determine the station's extension.</li><li>2. Enter <b>status station extension</b> to determine the service state of the port. (Refer to <a href="#">"status station" on page 4-213</a> for a description of all possible states.)</li><li>3. If the port is in use, wait until the port is idle. Retry the command at 1-minute intervals no more than 5 times.</li><li>4. If the test continues to abort, escalate the problem.</li></ol>
1001	ABORT	System resources required to run test are not available. This could be due to a failure to seize the port. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals no more than 5 times.</li><li>2. If the test continues to abort, escalate the problem.</li></ol>

*Continued on next page*

Table 5-31. TEST #6 NPE Crosstalk Test — *Continued*

Error Code	Test Result	Description/Recommendation
1002	ABORT	<p>The system could not allocate time slots for the test. The system may be under heavy traffic conditions or have time slots out-of-service due to TDM-BUS errors.</p> <ol style="list-style-type: none"><li>1. Refer to <a href="#">“TDM-BUS (TDM Bus)” on page 5-1116</a> to diagnose any active TDM-BUS errors.</li><li>2. If the system has no TDM-BUS errors and is not handling heavy traffic, retry the command at 1-minute intervals no more than 5 times.</li><li>3. If the test continues to abort, escalate the problem.</li></ol>
1003	ABORT	<p>The system could not allocate a tone receiver for the test. The system may be oversized for the number of tone detectors present or some tone detectors may be out-of-service.</p> <ol style="list-style-type: none"><li>1. Resolve any TTR-LEV errors in the Error Log.</li><li>2. Resolve any TONE-PT errors in the Error Log.</li><li>3. If neither condition exists, retry the command at 1-minute intervals no more than 5 times.</li><li>4. If the test continues to abort, escalate the problem.</li></ol>
1004	ABORT	<p>A valid call seized the port during the test and aborted the test.</p> <ol style="list-style-type: none"><li>1. Use the <b>display port UUCSSpp</b> command to determine the station extension.</li><li>2. Use the <b>status station extension</b> command to determine the service state of the port.</li><li>3. If the port is in use, wait until the port is idle before testing. Retry the command at 1-minute intervals no more than 5 times.</li><li>4. If the test continues to abort, escalate the problem.</li></ol>
1005	ABORT	<p>This test was aborted due to a configuration problem. The test is not applicable for this type of analog port. This error can be ignored.</p>

*Continued on next page*

Table 5-31. TEST #6 NPE Crosstalk Test — *Continued*

Error Code	Test Result	Description/Recommendation
1018	ABORT	Administration has disabled the test. The default for the <code>Test?</code> field on the station form is <b>y</b> . Determine why this field has been set to <b>n</b> on this station (this may be due to the ringing application Test #48, which can be disturbing to customer or terminal equipment). <ol style="list-style-type: none"><li>To enable the test for a particular station being tested, enter <b>change station extension</b>.</li><li>Change the <code>Test?</code> field on the station form to <b>y</b>.</li></ol>
2000	ABORT	Response to the test request was not received within the allowable time period.
2100	ABORT	System resources required to run test are not available. This could be due to a failure to seize the port. <ol style="list-style-type: none"><li>Retry the command at 1-minute intervals no more than 5 times.</li><li>If the test continues to abort, escalate the problem.</li></ol>

*Continued on next page*

Table 5-31. TEST #6 NPE Crosstalk Test — Continued

Error Code	Test Result	Description/Recommendation
Any	FAIL	<p>This test can fail due to on-board or off-board problems. Off-board problems include TDM-BUS faults, EXP-PN and EXP-INTF faults, and faults associated with the tone detectors/tone generators. Clear all off-board problems before replacing the board.</p> <ol style="list-style-type: none"><li>1. A TDM-BUS problem is usually the result of a faulty board connection to the backplane, or bent pins on the backplane. Resolve any TDM-BUS errors in the error log.</li><li>2. Resolve any EXP-PN and/or EXP-INTF errors in the error log.</li><li>3. Resolve any TONE-BD and/or TONE-PT errors in the error log.</li><li>4. Test the board when the faults from Steps 1, 2, and 3 are cleared. Replace the board only if the test fails.</li></ol>
	PASS	<p>The port is correctly using its allocated time slots. Investigate user-reported troubles on this port by running other port tests, by examining station wiring, or by inspecting the station.</p>
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board). This result could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"><li>1. Check to make sure that the board translations are correct. Use the <b>list configuration</b> command, and resolve any problems.</li><li>2. If the board is correctly inserted, issue the <b>busy board UUCSS</b> command.</li><li>3. Issue the <b>reset board UUCSS</b> command.</li><li>4. Issue the <b>release board UUCSS</b> command.</li><li>5. Issue the <b>test board UUCSS long</b> command. This re-establishes the link between the internal ID and the port.</li><li>6. If this is not the case, check to make sure that a valid board is inserted.</li></ol>

### Conference Circuit Test (#7)

This test verifies that the NPE channel for the port being tested correctly performs the conferencing function.

Table 5-32. TEST #7 Conference Circuit Test

Error Code	Test Result	Description/Recommendation
	ABORT	Necessary system resources could not be allocated to run this test. <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals no more than 5 times.</li> <li>2. If the test continues to abort, escalate the problem.</li> </ol>
1000	ABORT	System resources are unavailable. The port may be busy with a valid call. This result is also reported for the system's Music-On-Hold port when it is off-hook, which it usually is. <ol style="list-style-type: none"> <li>1. Enter <b>display port UUCSSpp</b> to determine the station's extension.</li> <li>2. Enter <b>status station extension</b> to determine the service state of the port.</li> <li>3. If the port is in use, wait until the port is idle. Retry the command at 1-minute intervals no more than 5 times.</li> <li>4. If the test continues to abort, escalate the problem.</li> </ol>
1004	ABORT	A valid call seized the port during the test and aborted the test. <ol style="list-style-type: none"> <li>1. Use the <b>display port UUCSSpp</b> command to determine the station extension.</li> <li>2. Use the <b>status station extension</b> command to determine the service state of the port.</li> <li>3. If the port is in use, wait until the port is idle before testing. Retry the command at 1-minute intervals no more than 5 times.</li> <li>4. If the test continues to abort, escalate the problem.</li> </ol>
1005	ABORT	This test was aborted due to a configuration problem. The test is not applicable for this type of analog port. This error can be ignored.

*Continued on next page*

Table 5-32. TEST #7 Conference Circuit Test — *Continued*

Error Code	Test Result	Description/Recommendation
1018	ABORT	Administration has disabled the test. The default for the Test? field on the station form is <b>y</b> . Determine why this field has been set to <b>n</b> on this station (this may be due to the ringing application Test #48, which can be disturbing to customer or terminal equipment). <ol style="list-style-type: none"><li>To enable the test for a particular station being tested, enter <b>change station extension</b>.</li><li>Change the Test? field on the station form to <b>y</b>.</li></ol>
2000	ABORT	Response to the test request was not received within the allowable time period.
2100	ABORT	System resources required to run this test are not available. <ol style="list-style-type: none"><li>Resolve any TONE-PT errors in the error log.</li><li>If there are no TONE-PT errors, retry the command at 1-minute intervals no more than 5 times.</li><li>If the test continues to abort, escalate the problem.</li></ol>

*Continued on next page*

Table 5-32. TEST #7 Conference Circuit Test — *Continued*

Error Code	Test Result	Description/Recommendation
Any	FAIL	<p>The NPE of the tested port did not conference the tones correctly. This causes noisy and unreliable connections.</p> <ol style="list-style-type: none"><li>1. Issue the <b>display port UUCSSpp</b> and the <b>status station extension</b> commands to determine if the station is idle.</li><li>2. If the station is idle, issue the <b>test port UUCSSpp</b> command for this port.</li><li>3. If the test continues to fail, issue the <b>busy port UUCSSpp</b> and the <b>release port UUCSSpp</b> commands, and then retest.</li><li>4. If the test still fails, replace the board.</li></ol>
	PASS	<p>The port can correctly conference multiple connections. Investigate user-reported troubles on this port by running other port tests; by examining station, trunk, or external wiring; or by inspecting the station.</p>
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board). This result could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"><li>1. Check to make sure that the board translations are correct. Use the <b>list configuration</b> command, and resolve any problems.</li><li>2. If the board is correctly inserted, issue the <b>busy board UUCSS</b> command.</li><li>3. Issue the <b>reset board UUCSS</b> command.</li><li>4. Issue the <b>release board UUCSS</b> command.</li><li>5. Issue the <b>test board UUCSS long</b> command. This re-establishes the link between the internal ID and the port.</li><li>6. If this is not the case, check to make sure that a valid board is inserted.</li></ol>

**Battery Feed Test (also called Port Diagnostic Test) (#35)**

The battery feed chip provides power to the telephone equipment, signaling, rotary dial pulsing, transmission, and balance. This test checks the signaling and switchhook capabilities of the battery feed chip by terminating the port, applying battery power, and detecting the resulting current.

**Table 5-33. TEST #35 Battery Feed Test**

<b>Error Code</b>	<b>Test Result</b>	<b>Description/Recommendation</b>
	ABORT	Necessary system resources could not be allocated to run this test. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals no more than 5 times.</li><li>2. If the test continues to abort, escalate the problem.</li></ol>
1000	ABORT	System resources are unavailable. The port may be busy with a valid call. This result is also reported for the system's Music-On-Hold port when it is off-hook, which it usually is. <ol style="list-style-type: none"><li>1. Enter <b>display port UUCSSpp</b> to determine the station's extension.</li><li>2. Enter <b>status station extension</b> to determine the service state of the port.</li><li>3. If the port is in use, wait until the port is idle. Retry the command at 1-minute intervals no more than 5 times.</li><li>4. If the test continues to abort, escalate the problem.</li></ol>
1004	ABORT	A valid call seized the port during the test and aborted the test. <ol style="list-style-type: none"><li>1. Use the <b>display port UUCSSpp</b> command to determine the station extension.</li><li>2. Use the <b>status station extension</b> command to determine the service state of the port.</li><li>3. If the port is in use, wait until the port is idle before testing. Retry the command at 1-minute intervals no more than 5 times.</li><li>4. If the test continues to abort, escalate the problem.</li></ol>
1005	ABORT	This test was aborted due to a configuration problem. The test is not applicable for this type of analog port. This error can be ignored.

*Continued on next page*

Table 5-33. TEST #35 Battery Feed Test — *Continued*

Error Code	Test Result	Description/Recommendation
1018	ABORT	Administration has disabled the test. The default for the <code>Test?</code> field on the station form is <b>y</b> . Determine why this field has been set to <b>n</b> on this station (this may be due to the ringing application Test #48, which can be disturbing to customer or terminal equipment). <ol style="list-style-type: none"><li>To enable the test for a particular station being tested, enter <b>change station extension</b>.</li><li>Change the <code>Test?</code> field on the station form to <b>y</b>.</li></ol>
1392	ABORT	This port is currently a TTI port and the test does not execute on it. <ol style="list-style-type: none"><li>Verify that the port is a TTI port:<ul style="list-style-type: none"><li>Enter the <b>display port UUCSSpp</b> command (the display shows that the port is a TTI port).</li><li>Enter the <b>list configuration</b> command (the display shows a <b>t</b> for the port).</li></ul></li><li>If both commands indicate that the port is a TTI port, the abort is correct for the test, and no action is necessary.</li><li>If either command indicates that the port is <i>not</i> a TTI port, escalate the problem.</li></ol>
2000	ABORT	Response to the test request was not received within the allowable time period.
2100	ABORT	System resources required to run this test are not available. <ol style="list-style-type: none"><li>Retry the command at 1-minute intervals no more than 5 times.</li><li>If the test continues to abort, escalate the problem.</li></ol>

*Continued on next page*

Table 5-33. TEST #35 Battery Feed Test — *Continued*

Error Code	Test Result	Description/Recommendation
	FAIL	<p>The port's battery feed chip is unable to supply sufficient power to the terminal equipment. This test result might be marginal, and the terminal equipment may be operating satisfactorily.</p> <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals no more than 5 times.</li><li>2. If the test continues to fail, determine whether the customer is experiencing problems on this line. Replace the circuit pack only if the customer is experiencing problems.</li></ol>
	PASS	<p>The port's battery feed chip is able to provide sufficient power to the station equipment to detect on-/off-hook, but may not be able to supply power for touch-tones.</p> <ol style="list-style-type: none"><li>1. If touch-tones are inoperative on this station, replace the circuit pack because this port is inoperative.</li><li>2. Investigate user-reported troubles on this port by running other port tests, by examining station wiring, or by inspecting the station.</li></ol>
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board). This result could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"><li>1. Check to make sure that the board translations are correct. Use the <b>list configuration</b> command, and resolve any problems.</li><li>2. If the board is correctly inserted, issue the <b>busy board UUCSS</b> command.</li><li>3. Issue the <b>reset board UUCSS</b> command.</li><li>4. Issue the <b>release board UUCSS</b> command.</li><li>5. Issue the <b>test board UUCSS long</b> command. This re-establishes the link between the internal ID and the port.</li><li>6. If this is not the case, check to make sure that a valid board is inserted.</li></ol>

---

*Continued on next page*

## Station Status and Translation Audits and Updates Test (#36)

This test updates the analog port's message lamp state (if it has one) and translations with information in the software.

Table 5-34. Test #36 Station Status and Translation Audits and Updates

Error Code	Test Result	Description/ Recommendation
	ABORT	Necessary system resources could not be allocated to run this test. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals no more than 5 times.</li><li>2. If the test continues to abort, escalate the problem.</li></ol>
1004	ABORT	A valid call seized the port during the test and aborted the test. <ol style="list-style-type: none"><li>1. Use the <b>display port UUCSSpp</b> command to determine the station extension.</li><li>2. Use the <b>status station extension</b> command to determine the service state of the port.</li><li>3. If the port is in use, wait until the port is idle before testing. Retry the command at 1-minute intervals no more than 5 times.</li><li>4. If the test continues to abort, escalate the problem.</li></ol>
1005	ABORT	This test was aborted due to a configuration problem. The test is not applicable for this type of analog port. This error can be ignored.
1006	ABORT	The port is out-of-service. The <b>busy station extension</b> command has been given to this port, or it has been taken out-of-service by the failure of the NPE Crosstalk Test. <ol style="list-style-type: none"><li>1. Look for error type 18 (port busied out) for this port. If this error is present, release the port (<b>release station extension</b>), and run the test again.</li><li>2. Check for error type 1537 (NPE Crosstalk Test failed) for this port. If this error is present, investigate the errors associated with the NPE Crosstalk Test (#6).</li><li>3. Make sure that the terminal is connected and in service, and then retest.</li></ol>
2000	ABORT	Response to the test request was not received within the allowable time period.

*Continued on next page*

Table 5-34. Test #36 Station Status and Translation Audits and Updates — *Continued*

Error Code	Test Result	Description/ Recommendation
2100	ABORT	System resources required to run this test are not available. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals no more than 5 times.</li><li>2. If the test continues to abort, escalate the problem.</li></ol>
1	FAIL	The switchhook audit failed. This result does not indicate a hardware problem. The other updates were not performed because of this failure. This may occur if the audit is performed at the same time the terminal equipment goes off-hook. <ol style="list-style-type: none"><li>1. Use the <b>status station extension</b> command to determine when the port is available.</li><li>2. Retry the command at 1-minute intervals no more than 5 times.</li><li>3. If the test continues to fail, escalate the problem.</li></ol>
5	FAIL	The message waiting lamp update failed. This may be an internal software error. The translation and ringer updates were not performed because of this failure.
7	FAIL	The translation update failed. There may be an internal software error. The ringer update was not performed because of this failure.

*Continued on next page*

Table 5-34. Test #36 Station Status and Translation Audits and Updates — *Continued*

Error Code	Test Result	Description/ Recommendation
8	FAIL	<p>The ringer update failed. There may be an internal software error.</p> <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals no more than 5 times.</li><li>2. If the test continues to fail, escalate the problem.</li></ol>
	PASS	<p>The software and the port processor have the same status. Investigate user-reported troubles on this port by running other port tests, by examining station wiring, or by inspecting the station.</p>
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board). This result could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"><li>1. Check to make sure that the board translations are correct. Use the <b>list configuration</b> command, and resolve any problems.</li><li>2. If the board is correctly inserted, issue the <b>busy board UUCSS</b> command.</li><li>3. Issue the <b>reset board UUCSS</b> command.</li><li>4. Issue the <b>release board UUCSS</b> command.</li><li>5. Issue the <b>test board UUCSS long</b> command. This re-establishes the link between the internal ID and the port.</li><li>6. If this is not the case, check to make sure that a valid board is inserted.</li></ol>

## Station Present Test (also called Ringing Application Test) (#48)

This test applies momentary ringing voltage to the terminal equipment and monitors resulting current flow to determine whether terminal equipment is connected to the port. This test may cause some terminal equipment to ring briefly during daily maintenance. If this ringing disturbs the customer or the terminal equipment, you can disable it via the **TESTS** field on the **change station extension** form. However, on some software releases, Tests #6, 7, 161, and 35 also are disabled.

Table 5-35. TEST #48 Station Present Test

Error Code	Test Result	Description/Recommendation
	ABORT	Necessary system resources could not be allocated to run this test. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals no more than 5 times.</li><li>2. If the test continues to abort, escalate the problem.</li></ol>
1000	ABORT	System resources are unavailable. The port may be busy with a valid call. This result is also reported for the system's Music-On-Hold port when it is off-hook, which it usually is. <ol style="list-style-type: none"><li>1. Enter <b>display port UUCSSpp</b> to determine the station's extension.</li><li>2. Enter <b>status station extension</b> to determine the service state of the port.</li><li>3. If the port is in use, wait until the port is idle. Retry the command at 1-minute intervals no more than 5 times.</li><li>4. If the test continues to abort, escalate the problem.</li></ol>
1004	ABORT	A valid call seized the port during the test and aborted the test. <ol style="list-style-type: none"><li>1. Use the <b>display port UUCSSpp</b> command to determine the station extension.</li><li>2. Use the <b>status station extension</b> command to determine the service state of the port.</li><li>3. If the port is in use, wait until the port is idle before testing. Retry the command at 1-minute intervals no more than 5 times.</li><li>4. If the test continues to abort, escalate the problem.</li></ol>

*Continued on next page*

Table 5-35. TEST #48 Station Present Test — Continued

Error Code	Test Result	Description/Recommendation
1005	ABORT	This test was aborted due to a configuration problem. The test is not applicable for this type of analog port. This error can be ignored.
1008	ABORT	<p>A ringing circuit could not be allocated. Either all of the ringing circuits are in use, the ringing generator is defective, or it is not wired correctly.</p> <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals no more than 5 times.</li><li>2. If the test continues to abort, look for RING-GEN errors in the Error Log.</li><li>3. If ABORT 1008 occurs for this test on other circuit packs as well, the ringing generator may be defective or is not wired correctly (see RING-GEN).</li><li>4. If an ABORT 1008 does not occur on other ports, then all four ring phases are in use.</li></ol>
1018	ABORT	<p>Administration has disabled the test. The default for the Test? field on the station form is <b>y</b>. Determine why this field has been set to <b>n</b> on this station (this may be due to the ringing application Test 48, which can be disturbing to customer or terminal equipment).</p> <ol style="list-style-type: none"><li>1. To enable the test for a particular station being tested, enter <b>change station extension</b>.</li><li>2. Change the Test? field on the station form to <b>y</b>.</li></ol>
2000	ABORT	Response to the test request was not received within the allowable time period.
2100	ABORT	<p>System resources required to run this test are not available.</p> <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals no more than 5 times.</li><li>2. If the test continues to abort, escalate the problem.</li></ol>

*Continued on next page*

Table 5-35. TEST #48 Station Present Test — *Continued*

Error Code	Test Result	Description/Recommendation
	FAIL	<p>The terminal equipment is not connected to the circuit pack. Some terminal equipment, such as modems, may fail even when connected properly.</p> <ol style="list-style-type: none"><li>1. Remotely test the terminal equipment.</li><li>2. If the test fails again, resolve any RING-GEN errors in the error log, if present.</li><li>3. Check all of the wiring between the station equipment and the switch. Then, run the test again.</li><li>4. If the test still fails, the terminal equipment may be defective. Check and replace it, if necessary.</li><li>5. Some terminal equipment might fail even when it is connected properly. If this is the case, disable the test using the <b>change station extension</b> command (enter <b>n</b> into the <code>Test</code> field). Note that this action also disables Tests 6, 7, 35, and 161 on this port.</li></ol>
	PASS	<p>The station is connected properly to the switch. Investigate user-reported troubles on this port by running other port tests, by examining station wiring, or by inspecting the station.</p> <p> <b>NOTE:</b> This test may also pass if no terminal equipment is connected and the terminal is located very far from the switch.</p>

*Continued on next page*

Table 5-35. TEST #48 Station Present Test — *Continued*

---

Error Code	Test Result	Description/Recommendation
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board). This result could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"><li>1. Check to make sure that the board translations are correct. Use the <b>list configuration</b> command, and resolve any problems.</li><li>2. If the board is correctly inserted, issue the <b>busy board UUCSS</b> command.</li><li>3. Issue the <b>reset board UUCSS</b> command.</li><li>4. Issue the <b>release board UUCSS</b> command.</li><li>5. Issue the <b>test board UUCSS long</b> command. This re-establishes the link between the internal ID and the port.</li><li>6. If this is not the case, check to make sure that a valid board is inserted.</li></ol>

---

**Looparound Test (#161)**

This test checks the on-board transmission capabilities of the NPE, the codec, and the battery feed chip of the analog port. The test passes if the signal measured by the tone detector is within acceptable limits.

**Table 5-36. TEST #161 Looparound Test**

<b>Error Code</b>	<b>Test Result</b>	<b>Description/Recommendation</b>
	ABORT	<p>Necessary system resources could not be allocated to run this test.</p> <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals no more than 5 times.</li><li>2. If the test continues to abort, escalate the problem.</li></ol>
1000	ABORT	<p>System resources are unavailable. The port may be busy with a valid call. This result is also reported for the system's Music-On-Hold port when it is off-hook, which it usually is.</p> <ol style="list-style-type: none"><li>1. Enter <b>display port UUCSSpp</b> to determine the station's extension.</li><li>2. Enter <b>status station extension</b> to determine the service state of the port.</li><li>3. If the port is in use, wait until the port is idle. Retry the command at 1-minute intervals no more than 5 times.</li><li>4. If the test continues to abort, escalate the problem.</li></ol>
1002	ABORT	<p>The system could not allocate time slots for the test. The system may be under heavy traffic conditions or have time slots out-of-service due to TDM-BUS errors.</p> <ol style="list-style-type: none"><li>1. Refer to <a href="#">“TDM-BUS (TDM Bus)” on page 5-1116</a> to diagnose any active TDM-BUS errors.</li><li>2. If the system has no TDM-BUS errors and is not handling heavy traffic, retry the command at 1-minute intervals no more than 5 times.</li><li>3. If the test continues to abort, escalate the problem.</li></ol>

*Continued on next page*

Table 5-36. TEST #161 Looparound Test — *Continued*

Error Code	Test Result	Description/Recommendation
1003	ABORT	<p>The system could not allocate a tone receiver for the test. The system may be oversized for the number of tone detectors present or some tone detectors may be out-of-service.</p> <ol style="list-style-type: none"> <li>1. Resolve any TTR-LEV errors in the Error Log.</li> <li>2. Resolve any TONE-PT errors in the Error Log.</li> <li>3. If neither condition exists, retry the command at 1-minute intervals no more than 5 times.</li> <li>4. If the test continues to abort, escalate the problem.</li> </ol>
1004	ABORT	<p>A valid call seized the port during the test and aborted the test.</p> <ol style="list-style-type: none"> <li>1. Use the <b>display port UUCSSpp</b> command to determine the station extension.</li> <li>2. Use the <b>status station extension</b> command to determine the service state of the port.</li> <li>3. If the port is in use, wait until the port is idle before testing. Retry the command at 1-minute intervals no more than 5 times.</li> <li>4. If the test continues to abort, escalate the problem.</li> </ol>
1005	ABORT	<p>This test was aborted due to a configuration problem. The test is not applicable for this type of analog port. This error can be ignored.</p>
1018	ABORT	<p>Administration has disabled the test. The default for the <code>Test?</code> field on the station form is <b>y</b>. Determine why this field has been set to <b>n</b> on this station (this may be due to the ringing application Test 48, which can be disturbing to customer or terminal equipment).</p> <ol style="list-style-type: none"> <li>1. To enable the test for a particular station being tested, enter <b>change station extension</b>.</li> <li>2. Change the <code>Test?</code> field on the station form to <b>y</b>.</li> </ol>
2000	ABORT	<p>Response to the test request was not received within the allowable time period.</p>
2100	ABORT	<p>System resources required to run this test are not available.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals no more than 5 times.</li> <li>2. If the test continues to abort, escalate the problem.</li> </ol>

*Continued on next page*

Table 5-36. TEST #161 Looparound Test — Continued

Error Code	Test Result	Description/Recommendation
	FAIL	<p>The reflective Looparound Test failed. This could cause noisy or unreliable connections, or users calling this port may hear an echo. The problem can also be off-board.</p> <ol style="list-style-type: none"><li>1. Since a line seizure may affect the test, repeat the test at 1-minute intervals for no more than 5 times.</li><li>2. Using the <b>test board UUCSS short</b> command, run circuit pack tests to check the tone generator and the tone detector circuit packs.</li><li>3. Resolve any problems on the tone generator or the tone detector circuit packs.</li><li>4. If the tone generator and tone detector circuit packs are functioning properly, determine if a voice terminal is connected and wired properly. Resolve any problems found.</li><li>5. If the test still fails, replace the analog line circuit pack.</li></ol>
	PASS	<p>The port provides an analog transmission path to the station equipment. Investigate user-reported troubles on this port by running other port tests, by examining station wiring, or by inspecting the station.</p>
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board). This result could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"><li>1. Check to make sure that the board translations are correct. Use the <b>list configuration</b> command, and resolve any problems.</li><li>2. If the board is correctly inserted, issue the <b>busy board UUCSS</b> command.</li><li>3. Issue the <b>reset board UUCSS</b> command.</li><li>4. Issue the <b>release board UUCSS</b> command.</li><li>5. Issue the <b>test board UUCSS long</b> command. This re-establishes the link between the internal ID and the port.</li><li>6. If this is not the case, check to make sure that a valid board is inserted.</li></ol>

## ANN-BD (announcement circuit pack)

MO name (in alarm log)	Alarm level	Initial command to run <sup>1</sup>	Full name of MO
ANN-BD	MINOR	test board PCSS I	Announcement Circuit Pack
ANN-BD	WRN	test board PCSS I	Announcement Circuit Pack

1. Where P is the port network number (1 for PPN); C is the carrier designation (for example, A, B, or C); and SS is the address of the slot in the carrier where the circuit pack is located (for example, 01, 02, ..., etc.).

The TN750 Announcement circuit pack is a service circuit which provides an integrated means for recording announcements that can be played back on demand by call processing as part of a calling feature (for example, announcements on hunt group calls). There are 16 Announcement Ports on the Announcement circuit pack. Each port can play any integrated announcement, independently of the other ports. In addition to the 16 Announcement Ports, the Announcement circuit pack also has one Data Line Circuit Port (port 17). The Data Line Circuit Port is used for uploading/downloading the announcement memory to/from the memory card. If there are any errors associated with port 17, refer to [“DAT-LINE \(Data Line\)” on page 5-466](#). If there are any errors associated with any other port, refer to [“ANN-PT \(announcement port\)” on page 5-133](#).

### NOTE:

TN750C is required if your system has multiple announcement boards (up to ten are allowed). Only one TN750A/B may be present in the system when a TN750C is used. The announcements from a TN750A/B can be saved and restored to a TN750C — but once the announcements are recorded onto a TN750C, they are not backward compatible with the TN750A/B.

The Announcement circuit pack has two processors on it. The first processor, or Angel, controls the circuit pack and communicates with the switch via the control channel on the TDM Bus. The second processor, or Speech Processor (SP), controls the speech memory and announcements. Digital speech is converted from its TDM Bus form to an internal storage form (for recording) and vice versa (for playbacks) by the 140AY device on the circuit pack, which has 16 channels (one for each Announcement Port).

## General notes

---

Here are a few **very important** general notes that apply to any problem on the Announcement circuit pack. The user should read this before attempting to work on the TN750 Announcement circuit pack or Announcement Ports, **especially if the circuit pack needs to be replaced.**

1. The TN750 Announcement circuit pack retains all integrated announcements *as long as the circuit pack has power*. For this reason, whenever there is a problem with either the Announcement circuit pack or an Announcement Port that may require the circuit pack to be reset, it is always best to try to reset the circuit pack via the **reset board PCSS** command first. If that does not work, replace the circuit pack.  
**Announcements are preserved through a software reset, but they are lost when the circuit pack is resealed.**
2. **If a customer has announcements on the Announcement circuit pack, then announcements must be saved on the memory card to ensure that they are not lost.** This should be done as soon as the announcements are recorded on the circuit pack (or whenever they are changed), assuming that the circuit pack is in proper working order (see Note).

### NOTE:

Unlike translations, announcements are NEVER automatically saved to the memory card.

3. The **save announcements** command replaces the announcement file on the memory card. Care must be taken not to mistakenly enter this command and, as a result, destroy a valid file on the memory card.
4. The **restore announcements** command replaces the Announcement circuit pack speech memory with the announcement file on the memory card. Care must be taken not to mistakenly enter this command, destroying valid speech memory, especially if the memory card does not have a valid announcement file on it.
5. Whenever the Announcement circuit pack is replaced, announcements must always be rerecorded or downloaded to the new circuit pack. Otherwise, call processing is not able to use the pack.
6. If announcement speech memory is corrupted, announcements should not be saved [that is, if the Announcement Checksum Test (#209) fails, or if the speech sounds corrupted on playback]. This can ruin a good announcement file on the memory card and potentially cause errors/alarms on any circuit pack to which the new file is downloaded. However, if the customer does not have a valid announcement file on the memory card, announcements can be saved in an effort to try to retain some of them (all of the announcements recorded may not be corrupted).

7. Due to a hardware fault in the TN750 announcement board, the following sequence of events may cause the announcement file to become corrupted and unusable:
  - Fill the board with recorded announcements.
  - Delete the last few announcements recorded.
  - Re-record the announcements deleted.

If the announcement file becomes corrupted, the only solution is to re-record all announcements. To do this, follow these steps:

- a. Remove the announcement board.
- b. Remove the tape cartridge from the tape drive. Do this so that announcements are not automatically restored from tape.
- c. Re-insert the announcement board.
- d. Re-record all announcements.
- e. Insert the tape cartridge in the tape drive.
- f. Issue the save announcements command to save all the announcements on the tape.

This hardware fault is fixed in the TN750B announcement board. However, the TN750B board will not automatically correct an announcement file which has previously been corrupted by a TN750 board. The only way to correct an announcement file corrupted by the TN750 board is to follow the steps above.

## Announcement administration

A brief description of the integrated announcement administration is given here to aid in troubleshooting the Announcement circuit pack and its ports. In many cases, it is necessary to record, play back, and/or delete announcements to resolve an alarm. It may also be necessary to save and restore announcements as part of the maintenance procedures. For a complete description of integrated announcement administration, please refer to *DEFINITY Enterprise Communications Server Release 8 Administration and Feature Description*.

## Announcement session

Announcements can be recorded, played back, and deleted from an announcement session. A station's COS needs to include console permissions in order for that station to be able to enter an announcement session. To enter an announcement session, go off-hook on a station that has console permissions and enter the appropriate Feature Access Code (FAC), administered as Announcement access code on the FACs form. Dial tone should be returned at this point. Enter the extension of the announcement that needs to be recorded, deleted, or played back. Again, dial tone should be heard. To record an announcement, press station keypad digit 1, record after the tone, and hang up when done. To play back an announcement, press 2. To delete an announcement, press 3 (confirmation tone is given if the delete worked). Announcements can also be played back by simply calling the announcement extension associated with them.

## Uploading/Downloading announcements

Integrated announcements on the TN750 Announcement circuit pack can be uploaded to the memory card with the administration terminal **save announcements** command. Likewise, integrated announcements can be downloaded to the Announcement circuit pack with the **restore announcements** command. Both of these commands require a free data module of NETCON type to be administered, a data module of announcement type (on the Announcement circuit pack) to be administered, and a memory card. These commands are useful in maintaining the customer's recorded announcements. Depending on system traffic, announcement uploads and/or downloads take between 30 and 45 minutes.

The system **automatically** tries to download the Announcement circuit pack five minutes after it is inserted. This automatic download procedure is aborted if:

1. An announcement is recorded within 10 minutes of circuit pack insertion.
2. An announcement download is invoked sooner with the administration terminal **restore announcements** command.
3. No announcement and/or NETCON data module is administered.
4. Either the announcement data module is busy or all the administered NETCON data modules are busy.
5. No memory card is in the system.
6. The memory card in the system does not have a valid announcement file saved on it.

**Hardware error log entries and test to clear values**

Table 5-37. Announcement circuit pack error log entries

Error type	Aux data	Associated test	Alarm level (See WARNING message below)	On/Off board	Test to clear value
0 <sup>1</sup>	0	Any	Any	Any	test board PCSS sh r 1
1 (a)	0	Circuit pack removed or SAKI Test (#53)	MINOR	ON	
2 (p)		None			
14 (b)	1 to 64	Announcement Checksum Test (#209)			
18	0	busyout board PCSS	WARNING	OFF	release board PCSS
23 (c)	0	None	WARNING	OFF	
125 (d)		None	MINOR	ON	
170 (e)	0	None	MINOR	ON	
217 (f)	0	None	WARNING	OFF	
257	65535	Control Channel Test (#52)	MINOR	ON	test board PCSS I r 20
257 (g)	Any	None			
267 (f)	0	None	WARNING	OFF	
513 (h)	Any	None			
1025 (i)	4363	NPE Audit Test (#50)			test board PCSS I
1281 (j)	17699	None			
1538 (k)	Any	None	MINOR	ON	
1793		Angel-SP Handshake Test (#208)	MINOR	ON	test board PCSS I r 3
	17680	In-line Error			

Continued on next page

5 Maintenance Objects for DEFINITY ONE  
ANN-BD (announcement circuit pack)

5-117

Table 5-37. Announcement circuit pack error log entries — *Continued*

Error type	Aux data	Associated test	Alarm level (See WARNING message below)	On/Off board	Test to clear value
2049 (l) (m)		Clock Match Inquiry Test (#212)	MINOR	ON	test board PCSS sh r 3
	17674	In-line Error			
2305		140AY Loop Around Test (#210)	MINOR	ON	test board PCSS sh r 3
2561		Super Frame Match Inquiry Test (#211)	MINOR	ON	test board PCSS sh r 3
	17676	In-line Error			
2817 (l)		Announcement Checksum Test (#209)	MINOR	ON	test board PCSS sh r 3
	17682	In-line Error			
	17699 (m)	In-line Error			
3840 (n)	Any	None			
3999 (o)	Any	None			

1. Run the Short Test Sequence first. If all tests pass, run the Long Test Sequence. Refer to the appropriate test description and follow the recommended procedures.

**WARNING:**

All alarms are upgraded to MAJOR when the BASE Tone Generator is set to 12 (France).

## Notes:

- a. Error Type 1— This error indicates the circuit pack totally stopped functioning or it was physically removed from the system.

 **NOTE:**

The alarm is logged about 11 minutes after the circuit pack has been removed and/or SAKI Test (#53) fails.

If the circuit pack is not in the system, insert a circuit pack (in the same slot as the error indicates) to resolve this error. Or, if the circuit pack is in the system and the red LED is on, follow the instructions for "Red (alarm)" in the "Control and Port Circuit Pack Status LEDs" section in Chapter 7, "LED Interpretation".

 **NOTE:**

The alarm is logged about 11 minutes after the circuit pack has been removed and/or SAKI Test (#53) fails.

 **WARNING:**

*Reseating and/or replacing the circuit pack results in loss of integrated announcements (TN750/B only). See "[General notes](#)" near the beginning of this Maintenance procedure.*

- b. Error Type 14— Whenever the Announcement Checksum Test (#209) fails, this error is logged. The Aux Data indicates the number of the first defective announcement found. This number corresponds to the announcement numbers on the announcement form. The extension relating to the announcement can be determined by the **display announcement** command. This error only appears in the Error Log in conjunction with Error Type 2817. Follow the procedures for Error Type 2817 to troubleshoot Error Type 14.
- c. Error Type 23—The circuit pack has been logically administered but not physically installed. The alarm is cleared when the circuit pack is installed.
- d. Error Type 125—A wrong circuit pack is inserted in the slot where this circuit pack is logically administered. To resolve this problem, either remove the wrong circuit pack and insert the logically administered circuit pack OR use the **change circuit-pack** command to readminister this slot to match the circuit pack inserted.
- e. Error Type 217 and 267— Indicate that there is more than one TN750 Announcement circuit pack inserted in the system. Remove the alarmed circuit pack.
- f. Error Type 257—This error indicates transient communication problems with this circuit pack. This error is not service-affecting and no action is required.

- g. Error Type 513—This error, when reported with Aux Data in the range of 4352 to 4358, indicates the circuit pack has reported a hardware failure on the circuit pack. The circuit pack should be replaced.

**WARNING:**

*Replacing the circuit pack results in loss of integrated announcements (TN750/B only). See [“General notes”](#) near the beginning of this Maintenance procedure.*

- h. Error Type 1025—This error is not service-affecting and no action is required.
- i. Error Type 1281—The SP found a fault in the speech main memory (SMM) (that is, it found one or more faulty memory locations). Whenever this error is logged, error 2817 is also logged [see Note (j)], which causes the maintenance system to run the Announcement Checksum Test (#209) to determine if the bad memory location was being used by an announcement.
- j. Error Type 1538—The hyperactive circuit pack is out-of-service and may exhibit one or more of the following symptoms:
1. The tests run on the ports of this circuit pack are returning with a NO-BOARD.
  2. A busyout/release of the circuit pack has no effect on test results.
  3. A **list configuration** command shows that the circuit pack and ports are properly installed.

The system tries to restore the circuit pack within 15 minutes. If the error recurs after 15 minutes, replace the circuit pack. (Refer to [Chapter 2, “Maintenance Procedures for DEFINITY ONE Compact Modular Cabinets”](#).)

- k. Error Type 2049 and 2817—These errors are logged in conjunction with Error Type 1281, Aux Data 17699. Since that error [see Note (i)] means that a defective speech memory location was found, the announcement checksum error is also logged. This causes the Announcement Checksum Test (#209) to run, which determines if the defective memory location has corrupted any recorded announcements. If the Checksum Test passes, the faulty memory location is currently not being used, and the SP marks the location as faulty to ensure that future announcements do not attempt to use it.

**NOTE:**

As memory locations are marked faulty, the amount of available memory decreases, which decreases the total amount of announcement time available on the circuit pack.

5 Maintenance Objects for DEFINITY ONE  
ANN-BD (announcement circuit pack)

5-120

- l. Error Type 2049—A transient error that does not cause an alarm can occasionally occur during a SPE, TDM BUS, or Tone Clock interchange. It is possible for a marginal Tone-Clock circuit pack to cause this error against the ANN-BD without alarming the TONE-BD. If this error occurs again, replacing the Tone-Clock circuit pack may clear up this error. See the FAIL case in the Clock Match Inquiry Test (#212).
- m. Error Type 3840— This error is not service-affecting and no action is required.
- n. Error type 3999— Indicates that the circuit pack sent a large number of control channel messages to the switch within a short period of time. If error type 1538 is also present, then the circuit pack was taken out-of-service due to hyperactivity. If error type 1538 is not present, then the circuit pack has not been taken out-of-service, but it has generated 50% of the messages necessary to be considered hyperactive. This may be completely normal during heavy traffic periods. However, if this error type is logged when the circuit pack is being lightly used, it may indicate a problem with the circuit pack or the equipment attached to it.
- o. Error Type 2—Check the Class of Restriction (COR) administered for the Data Line extension assigned to the TN750 for uploading and downloading announcements. The extension can be found by using **list data-module**.

### System technician-demanded tests: descriptions and error codes

Always investigate tests in the order presented in [Table 5-38](#) when inspecting errors in the system. By clearing error codes associated with the *Control Channel Loop Around Test*, for example, you may also clear errors generated from other tests in the testing sequence.

Table 5-38. System Technician-demanded tests: ANN-BD

Order of investigation	Short test sequence	Long test sequence	Reset board sequence	D/ND <sup>1</sup>
Control Channel Loop Around Test (#52) (a)		X		ND
Angel-Speech Processor (SP) Handshake Test (#208)		X		ND
Clock Match Inquiry (#212)	X	X		ND
Super Frame Match Inquiry (#211)	X	X		ND

Continued on next page

**5** Maintenance Objects for DEFINITY ONE  
ANN-BD (announcement circuit pack)

5-121

**Table 5-38. System Technician-demanded tests: ANN-BD — Continued**

Order of investigation	Short test sequence	Long test sequence	Reset board sequence	D/ND <sup>1</sup>
140AY Loop Around Test (#210)	X	X		ND
Announcement Checksum Test (#209)	X	X		ND
Network Processor Element (NPE) Audit Test (#50) (a)		X		ND
SAKI Test (#53) (a)			X	D

1. D = Destructive, ND = Non-destructive

**Note:**

- a. For a complete description of these tests, refer to the [“XXX-BD \(Common Port Circuit Pack\)” on page 5-1343](#).

**Angel-speech processor (sp) handshake test (#208)**

This test checks the integrity of the communication link between the two processors on the Announcement circuit pack.

** WARNING:**

*Failure of this test indicates that the Speech Processor is insane and results in the loss of all integrated announcements on the circuit pack.*

Table 5-39. TEST #208 angel-speech processor (SP) handshake test

Error code	Test result	Description/ Recommendation
2000	ABORT	Response to the test request was not received within the allowable time period. If Error Type 1538 is present in the Error Log, follow the maintenance strategy recommended for this Error Type.
2100	ABORT ABORT	Could not allocate the necessary system resources to run this test. Internal system error.  1. Retry the command at 1-minute intervals a maximum of 5 times.
	FAIL	Test failed. Circuit pack cannot be used. <b>Announcement speech memory is cleared when this test fails. Therefore, when the problem has been resolved, announcements must be rerecorded or downloaded to the circuit pack.</b>  1. Reset the circuit pack via the <b>reset board PCSS</b> command and then run this test again. If the test continues to fail, replace the circuit pack and then run this test again.  2. If there are recurring alarms on this circuit pack caused by this test failing, replace the circuit pack <b>even if Step 1 works.</b>  <b>⚠ WARNING:</b> <i>Replacing the circuit pack results in loss of integrated announcements. See <a href="#">"General notes"</a> near the beginning of this Maintenance documentation.</i>
	PASS	The communications link between the two processors on the Announcement circuit pack is functioning properly. User-reported troubles on this circuit pack should be investigated using other circuit pack and port tests. Refer to <a href="#">"ANN-PT (announcement port)" on page 5-133</a> for a description of the port tests.

### Announcement checksum test (#209)

Associated with every recorded announcement is a checksum. In this test, the SP checks a stored global checksum covering all recorded announcements against a calculated one and returns the results to the maintenance system. If the global checksum failed, maintenance requests the SP to check each individual announcement's checksum.

5 Maintenance Objects for DEFINITY ONE  
ANN-BD (announcement circuit pack)

5-123

If the test fails, then it returns the total number of defective announcements found. In addition, associated with each failure is an error in the Error Log (Error Type 14). The Aux Data indicates the number of the first defective announcement found. This number corresponds to the announcement numbers on the announcement form. The extension relating to the announcement can be determined by the **display announcement** command.

Table 5-40. TEST #209 announcement checksum test

Error code	Test result	Description/ Recommendation
0	ABORT	An error code of 0 indicates that the announcement file has been corrupted due to a hardware fault in the TN750 board. Follow step #7 under " <a href="#">General notes</a> " at the beginning of this section.
1023	ABORT	There are no announcements currently recorded on the circuit pack.
1024	ABORT	<p>This abort code is given for the following reasons:</p> <ol style="list-style-type: none"> <li>1. An announcement upload or download is in progress.</li> <li>2. An announcement upload or download is requested when this test is running.</li> <li>3. A record is in progress.</li> <li>4. A record request comes in when this test is running.</li> </ol> <p>If an announcement upload or download is in progress, a <b>status data-module &lt;announcement data extension&gt;</b> command should show that the announcement data port is connected to a NETCON data channel, and the "card-in-use" LED for the memory card is on (to determine the extension of the announcement data module, use the <b>list data-module</b> command).</p> <p>See Note (a) at end of table for more information.</p> <ol style="list-style-type: none"> <li>1. Wait until the blocking event is finished, and then run this test again. An upload or download could take up to 45 minutes to complete, and a recording session is finished as soon as the station that was making the recording is placed on-hook.</li> <li>2. If the test continues to abort, and a record or upload/download is not in progress, escalate the problem.</li> </ol>
2000	ABORT	Response to the test request was not received within the allowable time period. If Error Type 1538 is present in the Error Log, follow the maintenance strategy recommended for this Error Type.
2100	ABORT	Could not allocate the necessary system resources to run this test.

*Continued on next page*

Table 5-40. TEST #209 announcement checksum test — *Continued*

Error code	Test result	Description/ Recommendation
	ABORT	<p>Internal system error.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
0-256	FAIL	<p>Test failed. The error code indicates the total number of defective announcements that were found.</p> <p>When TEST #209 fails with error code 0, the Global Checksum failed on the board, but no individual Checksum failed.</p> <p> <b>NOTE:</b></p> <p>Since the announcements are recorded digitally, it is possible for the Announcement Checksum Test to <i>fail</i> but still have all the announcements sound uncorrupted. When an individual announcement fails the Checksum Test, always listen to the announcement first before taking any action (an announcement can be played back by dialing the announcement extension associated with the announcement number). If the announcement sounds corrupted, then rerecord it or delete it.</p> <ol style="list-style-type: none"> <li>1. Look in the Error Log to determine the number of the first defective announcement. Play back the announcement. If the announcement sounds defective, rerecord it or delete it. If the error code was greater than one (indicating that there is more than one defective announcement), run this test again and repeat this step.</li> <li>2. If after deleting and rerecording all defective announcements, the checksum test still fails, reset the circuit pack using the <b>reset board PCSS</b> command and run this test again.</li> <li>3. If the test still continues to fail, reseal the circuit pack and restore all announcements with an appropriate time estimate (for example, 40 minutes.) Then rerecord the lost announcements (that is, those recorded since the last save operation) and run this test again.</li> <li>4. If the test still continues to fail, replace the circuit pack, and run this test again.</li> </ol> <p> <b>WARNING:</b></p> <p><i>Replacing the circuit pack results in loss of integrated announcements. See <a href="#">“General notes”</a> near the beginning of this Maintenance procedure.</i></p>
	PASS	<p>All recorded announcements checksum correctly, indicating that the speech main memory is functioning properly. User-reported troubles on this circuit pack should be investigated using other circuit pack and port tests. Refer to <a href="#">“ANN-PT (announcement port)” on page 5-133</a> Maintenance documentation for a description of the port tests.</p>

## Notes:

- a. The Announcement circuit pack can exhibit a condition that does not allow recording.

If the circuit pack gets locked into this state (this is an extremely rare condition), two of the Announcement Ports on the circuit pack will be unusable by software, one of which is the record port. Also, **save/restore announcements** will not work, since the record port looks busy to the circuit pack. Note that software does not have any way of knowing this, and attempts to use the ports.

If the circuit pack is locked into this state, the following symptoms are observed:

1. When attempting to record an announcement, users hear the proper record tone, but the announcement do not record (they do not know it until the announcement is played back).
2. Performing a **test board long** when the circuit pack is in this state yield the following abort codes:
  - Ports 1 AND 9 abort Test #206 with code 1024
  - Ports 1 AND 9 abort Test #205 with code 2000
  - Board level Tests #209 and #210 abort with code 1024
3. The **save/restore announcements** command times out with:

`Error encountered, can't complete request`

The Announcement circuit pack lock-up can be cleared remotely by performing a soft reset to the circuit pack:

- **busyout board PCSS** (this command drops all calls in progress on the Announcement circuit pack)
- Reset circuit pack using the **reset board PCSS** command
- Release circuit pack using the **release board PCSS** command

---

### 140AY loop around test (#210)

This test checks the integrity of the record channel on the Announcement circuit pack (Announcement Port 1). The main function of the 140AY device is to accept Pulse Code Modulation (PCM)/Adaptive Differential Pulse Code Modulation (ADPCM) samples and compress/expand the samples using ADPCM. This test connects a Tone Generator to one port (Announcement Port 1, the recording port), and a Tone Detector to another port (Announcement Port 9). A tone is generated by the Tone Generator on the first port and looped through the 140AY device to the second port. The Tone Detector then responds with a tone present/absent message. The 140AY Loop Around Test is repeated at three different speech compression rates.

5 Maintenance Objects for DEFINITY ONE  
ANN-BD (announcement circuit pack)

5-126

Since this test involves sending a tone through two different ports, the Playback Speech Memory Array (PSMA) Test (#206) is run on the two ports first to make sure that they are working properly. See [“ANN-PT \(announcement port\)”](#) for a description of this test.

Table 5-41. TEST #210 140AY loop around test

Error code	Test result	Description/ Recommendation
1-3	ABORT	Response to the test request was not received within the allowable time period. The error code indicates at which speech compression rate the test aborted (one being the first rate tested, three being the last). <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
10	ABORT	The PSMA Test (#206) failed on Announcement Port 1.
90	ABORT	The PSMA Test (#206) failed on Announcement Port 9. <ol style="list-style-type: none"><li>1. Refer to <a href="#">“ANN-PT (announcement port)” on page 5-133</a> Maintenance documentation, Test #206.</li></ol>
1000	ABORT	System resources required to run this test are not available. This test needs Announcement Ports 1 and 9 to run. One of the ports may be in use on a valid call. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li><li>2. If the test continues to abort and Ports 1 and 9 are not in use, escalate the problem.</li></ol>
1002	ABORT	The system could not allocate time slots for the test. The system may be under heavy traffic conditions or it may have time slots out-of-service due to TDM-BUS errors. Refer to <a href="#">“TDM-BUS (TDM Bus)” on page 5-1116</a> Maintenance documentation to diagnose any active TDM-BUS errors. <ol style="list-style-type: none"><li>1. If system has no TDM-BUS errors and is not handling heavy traffic, repeat test at 1-minute intervals a maximum of 5 times.</li></ol>

*Continued on next page*

Table 5-41. TEST #210 140AY loop around test — *Continued*

Error code	Test result	Description/ Recommendation
1003	ABORT	<p>The system could not allocate a tone receiver for the test. The system may be oversized for the number of Tone Detectors present or some Tone Detectors may be out-of-service.</p> <ol style="list-style-type: none"> <li>1. Look for TTR-LEV errors in the Error Log. If present, refer to the <a href="#">“TTR-LEV (TTR Level)” on page 5-1223</a>.</li> <li>2. Look for TONE-PT errors in the Error Log. If present, refer to the <a href="#">“TONE-PT (Tone Generator)” on page 5-1204</a>.</li> <li>3. If neither condition exists, retry the test at 1-minute intervals a maximum of 5 times.</li> </ol>
1007	ABORT	<p>The Announcement circuit pack thinks that Port 1 or Port 9 is busy.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> <li>2. If the test continues to abort, follow the Announcement Port maintenance procedures for Ports 1 and 9.</li> </ol>
1024	ABORT	<p>Announcement circuit pack blocked the test because an announcement download is in progress. If an announcement download is in progress, a <b>status data-module &lt;announcement data extension&gt;</b> command should show that the announcement data port is connected to a NETCON data channel, and the "card-in-use" LED for the memory card should be on (to determine the extension of the announcement data module, use the <b>list data-module</b> command). See Note (a) at end of table for more information.</p> <ol style="list-style-type: none"> <li>1. Wait until download is finished (can take up to 45 minutes), and then run the test again.</li> <li>2. If the test continues to abort and there is no download in progress, escalate the problem.</li> </ol>
2000	ABORT	<p>Response to the test request was not received within the allowable time period. If Error Type 1538 is present in the Error Log, follow the maintenance strategy recommended for this error type.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
2007	ABORT	<p>The Announcement circuit pack thinks that Port 1 or Port 9 is busy.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> <li>2. If the test continues to abort, follow the Announcement Port maintenance procedures for Ports 1 and 9.</li> </ol>

*Continued on next page*

Table 5-41. TEST #210 140AY loop around test — *Continued*

Error code	Test result	Description/ Recommendation
2100	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals a maximum of 5 times.
	ABORT	Internal system error. 1. Retry the command at 1-minute intervals a maximum of 5 times.
1-3	FAIL	Test failed. The error code indicates at which speech compression rate the test actually failed (one being the first rate tested, three being the last).  1. Reset the circuit pack via the <b>reset board PCSS</b> command and then run this test again. If the test still fails, replace the circuit pack (see Warning) and run this test again.  2. If there are recurring alarms on this circuit pack caused by this test failing, replace the circuit pack even if Step 1 works (see Warning).   <b>WARNING:</b> <i>Replacing the circuit pack results in loss of integrated announcements. See <a href="#">“General notes” on page 5-113</a>.</i>
	PASS	The record channel on the Announcement circuit pack is functioning properly. User-reported troubles on this circuit pack should be investigated using other circuit pack and port tests. Refer to <a href="#">“ANN-PT (announcement port)” on page 5-133</a> for a description of the port tests.

## Notes:

- a. The Announcement circuit pack can exhibit a condition that does not allow recording.

If the circuit pack gets locked into this state (this is an extremely rare condition), two of the Announcement Ports on the circuit pack will be unusable by software, one of which is the record port. Also, **save/restore announcements** will not work since the record port looks busy to the circuit pack. Note that software does not have any way of knowing this, and attempts to use the ports.

If the circuit pack is locked into this state, the following symptoms are observed:

1. When attempting to record an announcement, users hear the proper record tone, but the announcement does not record (they do not know it until the announcement is played back).
2. Performing a **test board long** when the circuit pack is in this state yields the following abort codes:
  - Ports 1 AND 9 abort Test #206 with code 1024
  - Ports 1 AND 9 abort Test #205 with code 2000
  - Board level Tests #209 and #210 abort with code 1024
3. The **save/restore announcements** command times out with:

Error encountered, can't complete request

The Announcement circuit pack lock-up can be cleared remotely by performing a soft reset to the circuit pack:

- **busyout board PCSS** (this command drops all calls in progress on the Announcement circuit pack)
  - Reset circuit pack using the **reset board PCSS** command
  - Release circuit pack using the **release board PCSS** command
-

**Super frame match inquiry test (#211)**

The super frame is a means by which the SP synchronizes with the 140AY device on the Announcement circuit pack. If the super frame is not synchronized, the SP is not able to properly process record/playback requests. Both the SP and the hardware generate a super frame pulse. When these two pulses are out of synch, the SP sets a flag to indicate the mismatch. When this test is run, the state of this flag is returned.

Table 5-42. TEST #211 super frame match inquiry

Error code	Test result	Description/ Recommendation
2000	ABORT	Response to the test request was not received within the allowable time period. If Error Type 1538 is present in the Error Log, follow the maintenance strategy recommended for this Error Type.
2100	ABORT ABORT	Could not allocate the necessary system resources to run this test. Internal system error.  1. Retry the command at 1-minute intervals a maximum of 5 times.
	FAIL	Test failed. Announcement playbacks should sound corrupted.  1. Reset the circuit pack via the <b>reset board PCSS</b> command and then run this test again. If the test continues to fail, replace the circuit pack (see Warning).  2. If there are recurring alarms on this circuit pack caused by this test failing, replace the circuit pack even if Step 1 works (see Warning).  <b>⚠ WARNING:</b> <i>Replacing the circuit pack results in loss of integrated announcements. See <a href="#">"General notes"</a> near the beginning of this Maintenance procedure.</i>
	PASS	The SP can properly process record/playback requests. User-reported troubles on this circuit pack should be investigated using other circuit pack and port tests. Refer to <a href="#">"ANN-PT (announcement port)" on page 5-133</a> for a description of the port tests.

## Clock match inquiry test (#212)

This test is supported to determine the state of the clock generation circuitry on the Announcement circuit pack. This circuitry is used for controlling various pieces of the hardware, like the 140AY device. It is also used to synchronize the Announcement circuit pack with the clock that is on the backplane.

Table 5-43. TEST #212 clock match inquiry test

Error code	Test result	Description/ Recommendation
2000	ABORT	Response to the test request was not received within the allowable time period. If Error Type 1538 is present in the Error Log, follow the maintenance strategy recommended for this Error Type.
2100	ABORT ABORT	Could not allocate the necessary system resources to run this test. Internal system error.  1. Retry the command at 1-minute intervals a maximum of 5 times.
	FAIL	Test failed. Announcements recorded or played back while the clock circuitry is not functioning properly sound distorted. The ANN-BD may be defective or the Active Tone-Clock circuit pack (TONE-BD) may be marginal and is causing this test to fail.  1. Reset the circuit pack via the <b>reset board PCSS</b> command and then run this test again. If the test continues to fail, proceed to Step 2 or 3 as applicable.   <b>WARNING:</b> <i>Replacing the circuit pack results in loss of integrated announcements. See "<a href="#">General notes</a>" near the beginning of this Maintenance procedure.</i>

*Continued on next page*

Table 5-43. TEST #212 clock match inquiry test — *Continued*

Error code	Test result	Description/ Recommendation
	FAIL ( <i>cont'd.</i> )	<p>2. Replace the ANN-BD. Rerun the test. If the test continues to fail, replace the Tone-Clock circuit pack.</p> <p><b>⚠ WARNING:</b> <i>Replacing the TONE-BD causes a COLD 2 reset. See the “How to Replace a Tone-Clock Circuit Pack” section in the “TONE-BD (Tone-Clock Circuit Pack)” Maintenance documentation. Replacing the ANN-BD results in loss of integrated announcements. See <a href="#">“General notes”</a> near the beginning of this Maintenance procedure.</i></p> <p>3. If there are recurring alarms on this circuit pack caused by this test failing, replace the ANN-BD even if the previous steps were successful.</p>
	PASS	<p>Announcement record/playbacks should have clear sound quality. User-reported troubles on this circuit pack should be investigated using other circuit packs and port tests. Refer to <a href="#">“ANN-PT (announcement port)” on page 5-133</a> for a description of the port tests.</p>

## ANN-PT (announcement port)

---

MO name (in alarm log)	Alarm level	Initial command to run <sup>1</sup>	Full name of MO
ANN-PT	MINOR	test port PCSSpp I	Announcement Port
ANN-PT	WRN	test port PCSSpp I	Announcement Port

- 
1. Where P is the port network number (1 for PPN); C is the carrier designation (for example, A, B, or C); and SS is the address of the slot in the carrier where the circuit pack is located (for example, 01, 02, ..., etc.).
- 

The TN750 Announcement circuit pack is a service circuit pack that provides an integrated means for recording announcements that can be played back on demand by call processing as part of a calling feature (that is, announcements on hunt group calls). There are 16 Announcement Ports on the Announcement circuit pack. Each port can play any integrated announcement, independently of the other ports. If there are any errors associated with the circuit pack, refer to [“ANN-BD \(announcement circuit pack\)” on page 5-112](#).

The Announcement circuit pack has two processors on it. The first processor, or Angel, controls the circuit pack, and communicates with the switch via the control channel on the TDM Bus. The second processor, or SP, controls the speech memory and announcements. Digital speech is converted from its TDM Bus form to an internal storage form (for recording) and vice versa (for playbacks) by the 140AY device on the circuit pack, which has 16 channels (one for each Announcement Port).

### General notes

---

Here are a few **very important** general notes that apply to any problem on the Announcement circuit pack. The user should read this before attempting to work on the TN750 Announcement circuit pack or Announcement Ports, **especially if the circuit pack needs to be replaced**.

1. The TN750/B Announcement circuit pack retains all integrated announcements *as long as the circuit pack has power*. For this reason, whenever there is a problem with either the Announcement circuit pack or an Announcement Port that may require the circuit pack to be reset, it is always better to try to reset the circuit pack via the **reset board PCSS** command first and, if that does not work, then try to reseat it. **Announcements are preserved through a software reset, but they are lost when the circuit pack is reseeded.**

2. **If a customer has announcements on the Announcement circuit pack, then announcements must be saved on the system tape to ensure that they are not lost.** This should be done as soon as the announcements are recorded on the circuit pack (or whenever they are changed), assuming that the pack is in proper working order (see Note).

**⇒ NOTE:**

Unlike translations, announcements are NEVER automatically saved to the memory card.

3. The **save announcements** command replaces the announcement file on the card with the Announcement circuit pack speech memory. Care must be taken not to mistakenly enter this command, thereby destroying a valid file on tape.
4. The **restore announcements** command replaces the Announcement circuit pack speech memory with the announcement file on the card. Care must be taken not to mistakenly enter this command, thereby destroying valid speech memory (especially if the card does not have a valid announcement file on it).
5. Whenever the Announcement circuit pack is replaced, announcements must always be re-recorded or downloaded to the new circuit pack. Otherwise, call processing is not able to use the circuit pack.
6. If announcement speech memory is corrupted, **announcements should not be saved**, that is, if the Announcement Checksum Test (#209) fails or if the speech sounds corrupted on playback. This can ruin a good announcement file and potentially cause errors/alarms on any circuit pack to which the new file is downloaded. However, if the customer does not have a valid announcement file, then announcements can be saved in an effort to try to retain some of them (all of the announcements recorded may not be corrupted).
7. Although Announcement Port 5 and Data Line Circuit Port 17 on the Announcement circuit pack are logically two separate ports, they are physically the same port. Therefore, if one of the ports is in use, the other one will be busy. Also, if Announcement Port 5 is out-of-service, the Data Line Circuit Port is taken out-of-service. However, if the Data Line Circuit Port is out-of-service, the Announcement Port remains in-service.

## Announcement administration

A brief description of the integrated announcement administration is given here to aid in the troubleshooting of the Announcement circuit pack and its ports. In many cases, it is necessary to record, play back, and/or delete announcements to resolve an alarm. It may also be necessary to save and restore announcements as part of the maintenance procedures. For a complete description of integrated announcement administration, please refer to *DEFINITY Enterprise Communications Server Release 8 Administration and Feature Description*, (555-230-522).

## Announcement session

Announcements can be recorded, played back, and deleted from an announcement session. A station's COS needs to include console permissions in order for that station to be able to enter an announcement session. To enter an announcement session, go off-hook on a station that has console permissions and enter the appropriate FAC (administered as Announcement access code on the FACs form). Dial tone should be returned at this point. Enter the extension of the announcement that needs to be recorded, deleted or played back. Again, dial tone should be heard. To record an announcement, press station keypad digit 1, record after the tone, and hang up when done. To play back an announcement, press station keypad digit 2. To delete an announcement, press station keypad digit 3 (confirmation tone is given if the delete worked). Announcements can also be played back by simply calling the announcement extension associated with them.

## Uploading/Downloading announcements

Integrated announcements on the TN750 Announcement circuit pack can be uploaded to the memory card with the **save announcements** command. Similarly, integrated announcements can be downloaded to the Announcement circuit pack with the **restore announcements** command. Both of these commands require a free data module of NETCON type to be administered, a data module of announcement type (on the Announcement circuit pack) to be administered, and a memory card. These commands are useful in maintaining the customer's recorded announcements. Depending on system traffic, announcement uploads/downloads take between 30 and 45 minutes.

The system **automatically** tries to download the Announcement circuit pack five minutes after it is inserted. This automatic download procedure is aborted if:

1. An announcement is recorded within 10 minutes of circuit pack insertion.
2. An announcement download is invoked sooner with the administration terminal **restore announcements** command.
3. There is no announcement and/or NETCON data module administered.
4. Either the announcement data module is busy or all the administered NETCON data modules are busy.
5. There is no memory card in the system.
6. The memory card in the system does not have a valid announcement file saved on it.

### NOTE:

Unlike translations, there is no provision in the system for automatically saving announcements to the memory card.

## Hardware error log entries and test to clear values

Table 5-44. Announcement port error log entries

Error type	Aux data	Associated test	Alarm level	On/Off board	Test to clear value
0 <sup>1</sup>	0	Any	Any	Any	test port PCSSpp sh r 1
1		Playback Speech Memory Array (PSMA) Test (#206)	MINOR	ON	test port PCSSpp sh r 3
18	0	The port was busied out	WARNING	OFF	release port PCSSpp
130 (a)		None	WARNING	ON	test port PCSSpp sh
257		Channel Administration Memory Array (CAMA) Test (#205)	MINOR	ON	test port PCSSpp l r 3
	17667	In-line error			
513		140AY Channel Sanity Inquiry Test (#222)	MINOR	ON	test port PCSSpp sh r 3
	17684	In-line error			
769 (b)		None			

1. Run the Short Test Sequence first. If all tests pass, run the Long Test Sequence. Refer to the appropriate test description and follow the recommended procedures.

Notes:

- a. This error type indicates that the circuit pack has been removed or has been insane for more than 11 minutes. To clear the error, reinsert or replace the circuit pack.
- b. This error is logged and the port is alarmed when an alarm is raised on the Announcement circuit pack because of a faulty condition with a common circuit pack resource. Any one of the following alarmed errors on the Announcement circuit pack causes this error to be logged against the Announcement Port: 1793, 2049, 2305, 2561. Follow the ANN-BD (Announcement Circuit Pack) Maintenance documentation to resolve these alarms. When the corresponding circuit pack alarm is cleared, this alarm clears.

## System technician-demanded tests: descriptions and error codes

Always investigate tests in the order presented in the table below when inspecting errors in the system. By clearing error codes associated with the *Channel Administration Memory Array (CAMA) Test*, for example, you may also clear errors generated from other tests in the testing sequence.

Order of investigation	Short test sequence	Long test sequence	D/ND <sup>1</sup>
Channel Administration Memory Array (CAMA) Test (#205)		X	ND
Playback Speech Memory Array (PSMA) Test (#206)	X	X	ND
140AY Channel Sanity Inquiry Test (#222)	X	X	ND

1. D = Destructive; ND = Nondestructive

### Channel administration memory array (cama) test (#205)

This test is a memory device that stores information used to control the 140AY device. The Angel asynchronously feeds the CAMA with the control information. During the CAMA test, the Angel writes patterns into the CAMA, reads them back, and verifies that they match. If the patterns do not match, the test fails. This test is run periodically by the switch maintenance and by the Announcement circuit pack in the background.

Table 5-45. TEST #205 channel administration memory array (CAMA) test

Error code	Test result	Description/ Recommendation
1000	ABORT	System resources required to run this test are not available. The port may be in use on a valid call. 1. Retry the command at 1-minute intervals a maximum of 5 times.
2000	ABORT	Response to the test request was not received within the allowable time period. See Note (a) at end of table for more information.
2100	ABORT	Could not allocate the necessary system resources to run this test.

*Continued on next page*

Table 5-45. TEST #205 channel administration memory array (CAMA) test — *Continued*

Error code	Test result	Description/ Recommendation
	ABORT	Internal system error.  1. Retry the command at 1-minute intervals a maximum of 5 times.
	FAIL	Test failed. Announcements played back on this port may sound corrupted.  1. Reset the circuit pack via the <b>reset board PCSS</b> command and then run this test again. If the test continues to fail, replace the circuit pack (see Warning).  2. If there are recurring alarms on this port caused by this test failing, replace the circuit pack even if Step 1 works (see Warning).   <b>WARNING:</b> <i>Replacing the circuit pack results in loss of integrated announcements. Refer to <a href="#">“General notes” on page 5-133</a>.</i>
	PASS	This test verifies that the Angel processor can properly set up this port for playbacks. User-reported troubles on this circuit pack should be investigated using other port and circuit pack tests. (Refer to <a href="#">“ANN-BD (announcement circuit pack)” on page 5-112</a> for a description of the circuit pack tests.)

## Notes:

- a. The Announcement circuit pack can exhibit a condition that does not allow recording.

If the circuit pack gets locked into this state (this is an extremely rare condition), two of the Announcement Ports on the circuit pack (one of which is the record port) will be unusable by software. Also, **save/restore announcements** will not work since the record port looks busy to the circuit pack. Note that software does not have any way of knowing this and attempts to use the ports.

If the circuit pack is locked into this state, the following symptoms are observed:

1. When attempting to record an announcement, users hear the proper record tone, but the announcement does not record (they do not know it until the announcement is played back).

2. Performing a **test board long** when the circuit pack is in this state yields the following abort codes:
  - Ports 1 AND 9 abort Test #206 with code 1024
  - Ports 1 AND 9 abort Test #205 with code 2000
  - Board level Tests #209 and #210 abort with code 1024

3. The **save/restore announcements** command times out with:

**Error encountered, can't complete request**

The Announcement circuit pack lock-up can be cleared remotely by performing a soft reset to the circuit pack:

- **busyout board PCSS** (this command drops all calls in progress on the Announcement circuit pack)
- Reset circuit pack using the **reset board PCSS** command
- Release circuit pack using the **release board PCSS** command

---

### Playback speech memory array (PSMA) test (#206)

The PSMA test checks the integrity of a playback channel's interface to the speech memory and the TDM Bus. The SP has an internal buffer that contains a specific 256-byte sequence. During this test, the byte sequence is "played" through the 140AY device onto the TDM Bus. A General Purpose Tone Detector is used to confirm that the proper sequence was played. **This test is very important.** It is the only test that actually checks an Announcement Port's ability to play back an announcement on the TDM Bus. If the test fails, the Tone Detector returns the number of bytes that did not match the expected sequence. The larger the number, the more severe the problem with that port. If this test fails, announcements played over this port should sound corrupted.

It is the only test that actually checks an Announcement Port's ability to play back an announcement on the TDM Bus. If the test fails, the Tone Detector returns the number of bytes that did not match the expected sequence. The larger the number, the more severe the problem with that port. If this test fails, announcements played over this port should sound corrupted.

Table 5-46. TEST #206 playback speech memory array (PSMA) test

Error code	Test result	Description/ Recommendation
1000	ABORT	<p>System resources required to run this test are not available. The port may be in use on a valid call.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
1002	ABORT	<p>The system could not allocate time slots for the test. The system may be under heavy traffic conditions or it may have time slots out-of-service due to TDM-BUS errors. Refer to <a href="#">“TDM-BUS (TDM Bus)” on page 5-1116</a> to diagnose any active TDM-BUS errors.</p> <ol style="list-style-type: none"> <li>1. If system has no TDM-BUS errors and is not handling heavy traffic, repeat the test at 1-minute intervals a maximum of 5 times.</li> </ol>
1003	ABORT	<p>The system could not allocate a tone receiver for the test. The system may be oversized for the number of Tone Detectors present or some Tone Detectors may be out-of-service.</p> <ol style="list-style-type: none"> <li>1. Look for TTR-LEV errors in the Error Log. If present, refer to <a href="#">“TTR-LEV (TTR Level)” on page 5-1223</a>.</li> <li>2. Look for TONE-PT errors in the Error Log. If present, refer to <a href="#">“TONE-PT (Tone Generator)” on page 5-1204</a>.</li> <li>3. If neither condition exists, retry the test at 1-minute intervals a maximum of 5 times.</li> </ol>
1024	ABORT	<p>Announcement circuit pack blocked the test because an announcement download is in progress. If an announcement download is in progress, a <b>status data-module &lt;announcement data extension&gt;</b> command should show that the announcement data port is connected to a NETCON data channel, and the memory card should be active. (To determine the extension of the announcement data module, use the <b>list data-module</b> command.)</p> <p>See Note (a) at end of table for more information.</p> <ol style="list-style-type: none"> <li>1. Wait until download is finished (could take a maximum of 45 minutes), and then run the test again.</li> <li>2. If the test continues to abort and there is no download in progress, escalate the problem.</li> </ol>

*Continued on next page*

Table 5-46. TEST #206 playback speech memory array (PSMA) test — *Continued*

Error code	Test result	Description/ Recommendation
2000	ABORT	Response to the test request was not received within the allowable time period.
2100	ABORT ABORT	<p>Could not allocate the necessary system resources to run this test.</p> <p>Internal system error.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
1 to 254	FAIL	<p>Test failed. The error code indicates the number of byte count errors found by the Tone Detector.</p> <ol style="list-style-type: none"> <li>1. Reset the circuit pack via the <b>reset board PCSS</b> command and then run this test again. If the test continues to fail, replace the circuit pack (see Warning).</li> <li>2. If there are recurring alarms on this port caused by this test failing, replace the circuit pack even if Step 1 works (see Warning).</li> </ol> <p><b>⚠ WARNING:</b> <i>Replacing the circuit pack results in loss of integrated announcements. Refer to <a href="#">“General notes” on page 5-133.</a></i></p>
255	FAIL	<p>Test failed. The Announcement Port and the Tone Detector never synchronized. Check for active GPTD-PT errors, and refer to <a href="#">“GPTD-PT [General Purpose Tone Detector Port (CPTR)]” on page 5-667</a> to diagnose them first.</p> <ol style="list-style-type: none"> <li>1. If there are no active GPTD-PT errors, reset the circuit pack via the <b>reset board PCSS</b> command and then run this test again. If the test continues to fail, replace the circuit pack (see Warning).</li> <li>2. If there are recurring alarms on this port caused by this test failing, replace the circuit pack even if Step 1 works (see Warning).</li> </ol> <p><b>⚠ WARNING:</b> <i>Replacing the circuit pack results in loss of integrated announcements. Refer to <a href="#">“General notes” on page 5-133.</a></i></p>
	PASS	<p>This port can cleanly play announcements. User-reported troubles on this pack should be investigated using other port and circuit pack tests. Refer to <a href="#">“ANN-BD (announcement circuit pack)” on page 5-112</a> for a description of the circuit pack tests.</p>

Notes:

- a. The Announcement circuit pack can exhibit a condition that does not allow recording.

If the circuit pack gets locked into this state (this is an extremely rare condition), two of the Announcement Ports on the circuit pack (one of which is the record port) will be unusable by software. Also, **save/restore announcements** will not work, since the record port looks busy to the circuit pack. Note that software does not have any way of knowing this and attempts to use the ports.

If the circuit pack is locked into this state, the following symptoms are observed:

1. When attempting to record an announcement, users hear the proper record tone, but the announcement does not record (they do not know it until the announcement is played back).
2. Performing a **test board long** when the circuit pack is in this state yields the following abort codes:
  - Ports 1 and 9 abort Test #206 with code 1024
  - Ports 1 and 9 abort Test #205 with code 2000
  - Board level Tests #209 and #210 abort with code 1024
3. The **save/restore announcements** command times out with:

**Error encountered, can't complete request**

The Announcement circuit pack lock-up can be cleared remotely by performing a soft reset to the circuit pack:

- **busyout board PCSS** (this command drops all calls in progress on the Announcement circuit pack)
  - Reset circuit pack using the **reset board PCSS** command
  - Release circuit pack using the **release board PCSS** command
-

**140AY channel sanity inquiry test (#222)**

The Angel keeps a sanity status bit for each of the 16 channels on the 140AY device. This test queries the Angel to determine the status for a particular channel. If a channel is insane, that implies that announcements cannot be played back on that channel.

**Table 5-47. TEST #222 140AY channel sanity inquiry test**

Error code	Test result	Description/ Recommendation
2000	ABORT	Response to the test request was not received within the allowable time period.
2100	ABORT ABORT	<p>Could not allocate the necessary system resources to run this test.</p> <p>Internal system error.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
	FAIL	<p>Test failed. Announcements cannot be played back over this port.</p> <ol style="list-style-type: none"> <li>1. Reset the circuit pack via the <b>reset board PCSS</b> command and then run this test again. If the test continues to fail, replace the circuit pack (see Warning).</li> <li>2. If there are recurring alarms on this port caused by this test failing, replace the circuit pack even if Step 1 works (see Warning).</li> </ol> <p> <b>WARNING:</b> <i>Replacing the circuit pack results in loss of integrated announcements. Refer to <a href="#">“General notes” on page 5-133.</a></i></p>
	PASS	<p>Announcements can be played back over this port. User-reported troubles on this pack should be investigated using other port and circuit pack tests. Refer to the <a href="#">“ANN-BD (announcement circuit pack)” on page 5-112</a> for a description of the circuit pack tests.</p>


## ANNOUNCE (announce)

MO name (in alarm log)	Alarm level	Initial command to run	Full name of MO
ANNOUNCE	none	none	ANNOUNCEMENT

The ANNOUNCE MO logs an error in the hardware error log if at least one of the following is true:

- System fails to restore announcements from the memory card at boot time.

[Figure 5-4](#) shows the connection of the Announcement Circuit Pack to the system. To save or restore announcements, an ANNOUNCEMENT Data Extension must be administered, and at least one DATA-CHL (Network Control Data Channel) must be in the in-service/idle state.



cydmacps RPY 062397

Figure 5-4. Connection of announcement circuit pack to the system

## Hardware error log entries

---

Table 5-48. ANNOUNCE error log entries

Error type	Aux data	Associated test	Alarm level	On/Off board	Test to clear value
1(a)(d)	any	None			
257(d)	any	None			
513(b)(d)	0	None			
769(d)	0	None			
1025(d)	any	None			

### Notes:

- a. Error occurred while saving announcements. (See [Table 5-49](#) in the next section for an explanation of Aux Data and for recommended repair actions.)
  - b. User pressed cancel while announcements were being saved.
  - c. Error occurred while restoring announcements. (See [Table 5-49](#) in the next section for an explanation of Aux Data and for recommended repair actions.)
  - d. The port field for this error contained the active PE complex when the error occurred.
-

## Aux data error codes and recommended repair procedures

Table 5-49. Aux data error codes and recommended repair procedures

Aux data	Description/ Recommendation
9000 through 9031	CARD-MEM errors Check and resolve CARD-MEM errors and alarms.
32001	Internal system error.  1. Check other ANNOUNCE errors and take corrective action. If there are no other ANNOUNCE errors, do the following:  2. Retry the command at 2-minute intervals a maximum of 3 times.  3. If the <b>save/restore announcements</b> command fails, escalate the problem.
32002	Announcement circuit pack is in use.  1. Retry the command at 2-minute intervals a maximum of three times.  2. If the <b>save/restore announcements</b> command fails, escalate the problem.
32003	Announcement port is in use.  1. Wait for all Announcement ports to become available.  2. Enter the <b>save/restore announcements</b> command.
32004	There are no announcements recorded on the Announcement Circuit Pack. The <b>save announcements</b> command is not allowed to prevent the destroying of the announcement file on tape [286 systems] or on the memory card [386 systems].
32005	Integrated announcement circuit pack is not present. The Announcement Circuit Pack is not inserted, or it is defective.  1. Enter the <b>list config</b> command to check for the presence of the circuit pack in the system.  2. If the Announcement Circuit Pack is present, use the <b>test board PCSS</b> command to check the status of the Announcement Circuit Pack.
32006	Announcement Data Module not available.  1. Use the <b>status</b> command to check the status of the Announcement Data Module.

*Continued on next page*

Table 5-49. Aux data error codes and recommended repair procedures — *Continued*

Aux data	Description/ Recommendation
32007	Announcement Data Module out of service. <ol style="list-style-type: none"><li>1. Use the <b>status</b> command to check the status of the Announcement Data Module.</li></ol>
32008	Announcement data is being saved or loaded. <ol style="list-style-type: none"><li>1. Retry the command at 2-minute intervals a maximum of three times.</li><li>2. If the <b>save/restore announcements</b> command fails, escalate the problem.</li></ol>
32009	Required DATA-CHL is not administered or out of service. (A DATA-CHL is required to save or restore announcements.) <ol style="list-style-type: none"><li>1. Add a DATA-CHL if none is administered.</li><li>2. If a DATA-CHL is administered, use the <b>status</b> command to check the status of all DATA-CHLs. At least one DATA-CHL should be in the in-service/idle state.</li></ol>
32010 32013	DATA-CHL is not administered, or it is unavailable. (A DATA-CHL is required to save or restore announcements.) <ol style="list-style-type: none"><li>1. Add a DATA-CHL if none is administered.</li><li>2. If a DATA-CHL is administered, use the <b>status</b> command to check the status of all DATA-CHLs. At least one DATA-CHL should be in the in-service/idle state.</li></ol>
32012	Required Announcement Data Module is not administered. <ol style="list-style-type: none"><li>1. Add an Announcement Data Module and repeat the command.</li></ol>
32015	Time of day not set. <ol style="list-style-type: none"><li>1. Set the time of day, and reenter the <b>save/restore announcements</b> command.</li></ol>
32016	Internal system errors. Check for any other ANNOUNCE errors and take corrective action. If there are no other announcements errors, do the following: <ol style="list-style-type: none"><li>1. Retry the command at 2-minute intervals a maximum of three times.</li><li>2. If the <b>save/restore announcements</b> command fails, escalate the problem.</li></ol>

## ASAI-BD (Multi-Application Platform Board)

---

MO name (in alarm log)	Alarm level	Initial command to run <sup>1</sup>	Full name of MO
ASAI-BD	MIN	test board PCSS sh	ASAI-BD
ASAI-BD	WRN	test board PCSS sh	ASAI-BD

1. Where P is the port network number (1 for PPN and 2 or 3 for EPN); C is the carrier designation (for example, A, B, C, or D); and SS is the address of the slot in the carrier where the circuit pack is located (for example, 01, 02, ..., and so forth).

Maintenance testing of the common circuit pack is handled by on-board firmware and SPE-controlled tests. Maintenance software queries the firmware for error and alarm information, status, and test results. Firmware automatically reports error conditions that result in SPE-controlled testing.

For MAPD board insertion, the switch makes an additional board query if any of the following circuit packs are inserted:

Circuit Pack	Vintage
TN754	49
TN556	49, 80 or greater
TN800	any

For any of the above initial board uplinks, the switch queries the board for administration data, as well as reporting the switch software release and the system type.

For the native mode, the response to the board query downlink messages consists of several CCMS uplink messages that identify the true board code, vintage, suffix, emulation type, and number of reserved slots needed.

**⇒ NOTE:**

Refer to LAN-BD Maintenance documentation for circuit pack level errors. See also [“ASAI-PT” on page 5-158](#) /ASAI-EPT (BRI Line) maintenance documentation for related line information. See the following exceptions listed below:

- **Hyperactivity:** currently, the common circuit pack is considered “hyperactive” if the Service Dispatcher receives 200 uplink messages from the circuit pack in a 10-second period. Since MAPD has 32 ports, the hyperactivity limit increases to 500 uplink messages per 10 seconds. The switch issues an alarm when the limit reaches 400; when it reaches 500 up-link messages in 10 seconds, the board is taken out of service.
- **LED use:** the LED Control Message 038x requests the Angel to drive the red, yellow, and green LEDs on the face plate of a typical port board on or off. On the MAPD, only the red LED is controlled by this message. Yellow and green change requests received from the switch by the MAPD drive LCD behavior rather than LED behavior. The DEFINITY switch continues to send the same LED control messages to the MAPD that the DEFINITY switch currently sends to all other port boards. The MAPD handles proper interpretation of these messages. You should note that the PC on the MAPD and the switch itself control the LEDs and the LCD on the MAPD.
- **Port Administration:** in Administration Without Hardware (AWOH), the switch allows administration of up to 8 ports in any of the first 12 ports. If the port type later reported by the board does not match the existing type, the switch assumes it to be a MAPD board with a different configuration and rejects the board.

**⇒ NOTE:**

Refer to the LAN-BD documentation for circuit pack level errors. For related information, see [“ASAI-PT” on page 5-158](#) and ASAI-EPT maintenance documentation.

## ASAI-EPT

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run	Full Name of MO
ASAI-EPT	MAJOR <sup>1</sup>	test station extension	ASAI-Adjunct

- The alarm level for ASAI adjuncts is administered using the [set options](#) command. The alarm level can be set independently for off-board and on-board alarms to WARNING, MINOR, or MAJOR for all ASAI adjuncts in the system.

The maintenance strategy for this endpoint MO is built on maintenance facilities offered in the Lucent ISDN-BRI protocol and in the ASAI adjuncts. Currently there are no facilities in the protocol that provide for maintenance of set data features.

The TN800 is a PC-based platform that allows interaction of multiple applications with DEFINITY at any time. DEFINITY Release 5 software (Native mode) supports emulation of three types of port MOs on this board. The type of ports to be emulated is defined by the applications running on the TN800.

### ⇒ NOTE:

If the TN800 is emulating BRI, the software/firmware supports a maximum of 12 ports, but only 8 of the 12 ports can be administered at any one time.

## Error Log Entries and Test to Clear Values

Table 5-50. ASAI-EPT Error Log Entries

Error Type	Aux Data	Associated Test	Alarm Level ASAI-EPT	On/ Off Board	Test to Clear Value
0 <sup>1</sup>	0	Any	Any	Any	test ASAI-ADJ
2 (a)	2-102	None			
257 (b)	Any	BRI Layer 3 Query	MAJ/WNG <sup>2</sup>	OFF	test station ext r 2 test data-module ext r 2
351 (c)	0	none	WARNING	OFF	busyout and release station
513 (d)	0	None			
769 (e)	0	None	MAJOR	OFF	
2561 (f)	0	None			
2562-2566 (g)	0	None			

Continued on next page

Table 5-50. ASAI-EPT Error Log Entries — *Continued*

Error Type	Aux Data	Associated Test	Alarm Level ASAI-EPT	On/ Off Board	Test to Clear Value
2567 (h)	0	None			
2568 (i)	0	None			
3329 (j)	Any	Signaling Link Status (626)	MAJ/WNG <sup>†</sup>	OFF	
3584-3839 (k)	0, 1	None			
3841 (l) 4095	0	None			

1. Run the Short Test Sequence first. If all tests pass, run the Long Test Sequence. Refer to the appropriate test description and follow the recommended procedures.
2. Major alarms on this MO may be downgraded to Warning alarms based on the value used in the **set options** command.

## Notes:

- a. Errors of this type indicate violations of the ISDN-BRI signaling protocol. Timers associated with certain Layer 3 messages have expired before a required response was received. In the following table, the aux data column indicates which timer has just expired. For more information, refer to the Lucent ISDN-BRI Specification.

Aux Data	Timer Type
2	First T303 (SETUP timer)
3	Second T303 (SETUP timer)
4	T305 (DISConnect timer)
5	First T308 (RELease timer)
6	Second T308 (RELease timer)
10	T316 (REStart timer)
12	T309 (Layer 2 Failure timer)
16	TM100 (Management Information Message timer 1)
17	TM200 (Management Information Message timer 2)
102	TASAI (ASAI Routing Timer)

The switch sent a message to an endpoint that did not respond in the allotted time. This may be due to failure of the point-to-point signaling link or because of a problem in the ASAI adjunct. To repair:

- Execute the **test station extension** command and perform the associated repair procedures for those tests.
- b. An endpoint is not responding to the service state query message sent to the adjunct or to the endpoint. This error causes an alarm to be raised. The alarm is retired when the switch receives a response to the service state query to the endpoint or to the adjunct.

When this error occurs for an ASAI adjunct, the Aux Data field indicates the state of the ASAI link and whether an invalid response or no response was received to the query from the switch, as shown in the following table:

Aux Data	ASAI Link State	Error
102	13-restarting	No response to RESTART message
104	13-restarting	Invalid response to RESTART message
152	13-restarted	No response to Layer 3 query
154	13-restarted	Invalid response to Layer 3 query
202	13-established	No response to Layer 3 query
204	13-established	Invalid response to Layer 3 query

See [“status bri-port” on page 4-151](#) for an explanation of the ASAI link states.

For ASAI or Lucent adjuncts, the switch queries the adjunct every two minutes. The Layer 3 Query Test is not executed for ASAI or Lucent adjuncts through a command issued from the management terminal. While alarmed for this error, the switch takes the associated port out-of-service for five seconds every 15 minutes. This action attempts to stimulate recovery actions to be taken by the adjunct.

When this error occurs for an ASAI or Lucent adjunct, the service technician should:

1. Execute the **test station extension** command and perform the associated repair procedures for those tests.
  2. Check the health of the adjunct by following the recommended repair procedures of the manufacturer of the adjunct if the preceding step does not resolve the problem.
- c. This error and associated warning alarm are logged against an ASAI endpoint when the adjunct has asked the switch to suspend maintenance on the ASAI endpoint. Busying out and releasing the ASAI station clears this alarm.
- d. This error occurs when the endpoint sends more messages than the switch can handle. The switch suspends the reception of messages from the endpoint for a short period of time. There is no repair procedure for this error. If the condition persists, replace the endpoint.

- e. This error occurs when the signaling link associated with the ASAI endpoint has too much link-establishment related traffic. This occurs if the signaling link is alternating between assigned and established states. If this problem persists, replace the endpoint.
- f. This error occurs when the ASAI-EPT message is not transmitted because the PKT-CTRL (packet control circuit pack) transmit buffers are exhausted. Frequent or persistent occurrence of these events may indicate a hardware problem or traffic overload on the PKT-CTRL, the signaling link, or the ASAI adjunct. Resolve the problem by following the repair procedures for the PKT-CTRL. If these attempts fail, re-engineering the traffic on the PKT-CTRL, signaling link, or adjunct may be necessary.
- g. The ASAI message is not transmitted because the transmit buffer for the ASAI link is full, causing the link to be flow-controlled. Frequent or persistent occurrence of these events may indicate a hardware problem or traffic overload on the PKT-CTRL, the signaling link, or the ASAI adjunct. Resolve the problem by following the repair procedures issued by the manufacturer of the adjunct. If these attempts fail, re-engineering of the traffic on the PKT-CTRL, signaling link, or adjunct may be necessary.
- h. This version of ASAI is not supported. Check the software version that is running on the ASAI adjunct.
- i. The adjunct identification is invalid. Check the vendor ID or software running on the ASAI adjunct.
- j. This occurs when the point-to-point signaling link to the endpoint goes down, except when the link goes down because either a system technician has busied out the PKT-CTRL or the PKT-BUS, or they have failed. This error raises an alarm against the endpoint or adjunct. Execute the **test station extension short** command and note the results of the Signaling Link Status Test (#626). If this test fails, follow the repair procedure for Test #626. The alarm is retired when the signaling link is re-established to the endpoint or adjunct.
- k. The switch software logs certain ASAI cause values. The cause value is determined from the following formulas:
  - If the error type is greater than 3712, then the ASAI cause value is equal to the error type minus 3712. The switch sent this value to the adjunct.
  - If the error type is less than 3712, then the ASAI cause value is equal to the error type minus 3584. The switch sent this value to the adjunct.

[Table 5-51 on page 5-154](#) contains a description of the various ASAI cause values and recommended system technician actions associated with the cause value. The ISDN-BRI Specification (801-802-100) contains further information. In addition, the Aux Data field of the Error Log entry contains additional diagnostic information.

- I. The switch software logs certain ASAI cause values. The cause value is determined from the following formula:
- If the error type is greater than 3968, then the ASAI cause value is equal to the error type minus 3968. The switch sent this value to the endpoint.
  - If the error type is less than 3968, then the ASAI cause code is equal to the error type minus 3840. The switch sent this value to the endpoint.

Table 5-51. ASAI Cause Values

Code	Explanation	Recommendation
0	Unrecognized ASAI Protocol Operation.	Requested ASAI protocol is not implemented by switch or adjunct. Aux data field of error log entry contains protocol identifier for unrecognized operation. <ol style="list-style-type: none"><li>1. Consult switch and adjunct documentation to determine which set of operations is supported by switch and the adjunct. Adjunct administration turning off operations not implemented by the switch may resolve the problem.</li></ol>
34	No circuit or channel available	A resource on the switch is unavailable for a call. For BRI endpoints, this cause value is not logged. For ASAI, this condition means that there are no available trunks for an outgoing call request. <ol style="list-style-type: none"><li>1. Verify that the adjunct is administered to support the trunk capabilities of the switch.</li><li>2. Investigate trunk group status by issuing the <a href="#">status trunk</a> command from the SAT or by requesting trunk group queries) from the adjunct.</li><li>3. Perform trunk diagnostic procedures outlined in this manual.</li></ol>
40	Resources not available.	No available internal resources to service switch or adjunct request. Exceeds system transaction capacity for adjunct or switch. <ol style="list-style-type: none"><li>1. May require re-engineering of adjunct services.</li></ol>

*Continued on next page*

Table 5-51. ASAI Cause Values — *Continued*

Code	Explanation	Recommendation
50	Requested facility not subscribed	<p>Requested facility is implemented, but not administered. Potential administration problem with endpoint or adjunct.</p> <p>For BRI endpoints:</p> <ol style="list-style-type: none"> <li>1. Verify the switch administration of endpoint using either the <b>display station</b> or <b>display data-module</b> commands.</li> <li>2. If Step 1 does not resolve the problem, refer to the endpoint's service manual and verify administration on the endpoint.</li> </ol> <p>For ASAI adjuncts:</p> <ol style="list-style-type: none"> <li>1. Display the Customer Optional Features Form (administration screen) on the switch to determine which ASAI capabilities are turned on in the switch.</li> <li>2. Verify that the adjunct is administered to support the identical capabilities as the switch. If there is a mismatch in the administered capabilities, then readminister the switch and/or the adjunct to establish a consistent set of desired capabilities on both the switch and the adjunct.</li> </ol>
58	Bearer capability not presently available	Requested bearer capability is implemented, but not administered. No B-channel administered. See code 50 above.
63	Service or option not available	<p>Requested ASAI capability or resource is not available on the switch or adjunct. More than one adjunct may be contending for the same switch resource. Potential administration mismatch between the resource domains administered on the switch and those administered on the adjunct.</p> <ol style="list-style-type: none"> <li>1. Verify that no overlapping administration of switch resources (for example, requesting notifications on a single domain by multiple adjuncts attempting to control a single call) exists across all adjuncts connected to the switch. If overlaps exist, then re-administer the adjuncts to ensure that each adjunct is associated with a unique set of switch resources.</li> </ol>
65	Bearer service not implemented	Requested service not implemented in switch or endpoint.
69	Requested facility not implemented	<p>Requested service not supported in switch or endpoint.</p> <ol style="list-style-type: none"> <li>1. Consult switch and endpoint documentation to determine service support.</li> </ol>

*Continued on next page*

Table 5-51. ASAI Cause Values — *Continued*

Code	Explanation	Recommendation
79	Service or option not implemented	Requested service or option (or combination of selected options) is not supported (implemented) in switch or the adjunct.  1. Consult switch and adjunct documentation to determine ASAI service and options supported by both switch and adjunct. Re-administration of the switch-administered capabilities (see Customer Optional Feature Form) or those of the adjunct may be necessary to correct the problem.
81	Invalid CRV	An invalid CRV was sent by the adjunct.  1. This may indicate a CRV inconsistency between the switch and the adjunct. See the CallVisor protocol reference manual.
87	Internal switch audit	There is an inconsistency in switch data records.  1. There is no action needed, since the switch has corrected the data inconsistency.

### System Technician-Demanded Tests: Descriptions and Error Codes

When inspecting errors in the system, always investigate errors associated with the circuit pack and port first. Clearing these error codes first may also clear errors generated against the endpoint. When all circuit pack and port errors have been cleared, but errors still exist against the endpoint, investigate errors in the table below. By clearing error codes associated with the Signaling Link Status Test, for example, you may also clear errors generated from other tests in the testing sequence.

Order of Investigation	Short Test Sequence	Long Test Sequence	D/ND <sup>1</sup>
Signaling Link Status Test (#626)	X	X	ND

1. D = Destructive; ND = Nondestructive

### BRI Layer 3 Query Test (#629)

This test is not used by the ASAI-ADJ maintenance object. For information about this test, see [“BRI-SET, ASAI-ADJ, BRI-DAT” on page 5-334](#).

**Signaling Link Status Test (#626)**

This test determines the current status of the signaling link. This test passes if the link is "bound" to an endpoint and fails if the link is "not bound."

The definition of the term "bound" for a link depends upon the type of endpoint and may depend on the successful completion of procedures at both Layers 2 and 3 of the protocol. The definition of "bound" for ASAI type of endpoint is:

- ASAI adjuncts and BRI endpoints not administered for MIM initialization (point-to-point):

For endpoints of this type, the signaling link is "bound" when the link is connected at Layer 2 (L2 established).

**Table 5-52. TEST #626 Signaling Link Status Test**

Error Code	Test Result	Description/ Recommendation
1139	ABORT	The Packet Bus in the port network is out-of-service. <ol style="list-style-type: none"> <li>1. Follow the repair procedures for the Packet Bus.</li> <li>2. After completing Step 1, execute the <b>test port long PCSSpp</b> command and review the results of the BRI Port Local LAN Looparound Test to verify the repair.</li> </ol>
1141	ABORT	The PKT-CTRL is out-of-service. <ol style="list-style-type: none"> <li>1. Refer to PKT-CTRL maintenance documentation.</li> </ol>
1144	ABORT	The PPN Packet Bus is out-of-service. <ol style="list-style-type: none"> <li>1. Follow the repair procedures for the Packet Bus in the PPN.</li> <li>2. Execute the <b>test port long PCSSpp</b> command and review the results of the BRI Port Local LAN Looparound Test to verify the repair.</li> </ol>
2012	ABORT	Internal system error
2100	ABORT	Could not allocate the necessary system resources to run this test. <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
1113	FAIL	The signaling link is not "bound" to the adjunct. For ASAI adjuncts this error indicates that the link is disconnected at Layer 2. Since the signaling link associated with the endpoint has been identified by administration, the link is only "unbound" from the endpoint when it is disconnected. <ol style="list-style-type: none"> <li>1. Execute the <b>status bri-port PCSSpp</b> command and refer to the associated procedures for this command contained in "<a href="#">BRI-PORT (ISDN-BRI Port)</a>, <a href="#">ABRI-PORT (ASAI ISDN-BRI Port)</a>" on page 5-312.</li> </ol>
	PASS	The signaling link is connected at Layer 2 and "bound" to the ASAI adjunct.

## ASAI-PT

---

MO name (in alarm log)	Alarm level	Initial command to run <sup>1</sup>	Full name of MO
ASAI-PT	MAJOR <sup>2,3</sup>	test port PCSSpp I	ASAI ISDN BRI Port
ASAI-PT	WARNING	test port PCSSpp I	ASAI ISDN BRI Port

1. Where P is the port network number (1 for PPN and 2 or 3 for EPN); C is the carrier designation (for example, A, B, C, or D); and SS is the address of the slot in the carrier where the circuit pack is located (for example, 01, 02, ..., and so forth).
2. The alarm level for ASAI adjunct ports may be administered using the **set options** command. The alarm level can be set independently for off-board and on-board alarms to WARNING, MINOR, or MAJOR for all ASAI adjunct ports in the system.
3. All alarming for an ASAI adjunct and off-board alarming for an ASAI port is disabled if the ASAI adjunct asks the switch to suspend maintenance. When this occurs, an error and a WARNING alarm is logged against the ASAI adjunct. Check the Hardware Error and Alarm Logs to see if the adjunct has disabled alarming.

Unless otherwise stated, all maintenance actions contained in this section apply to ASAI-PT and ISDN-BRI ports connected to ASAI adjuncts. This port type is administered as an ASAI-BD on the TN800 circuit pack.

The TN800 circuit pack is a PC-based platform that allows interaction of multiple applications with DEFINITY at any time. DEFINITY software (Native mode) will support emulation of three types of port MOs on this board. The type of ports to be emulated are defined by the applications running on the TN800. The TN800 can support a maximum of 32 ports (time slots) at a time.

The TN800 connects to the switch through a single slot in the backplane, however its width is not limited to one slot. The number of slots occupied by the TN800 is supplied by the board during its insertion. The TN800 is 3 slots wide. The blank (reserve) slots are to the left of the functional slot.

In non-native mode the TN800 is recognized as TN556, TN2181, TN754, or TN746 based on the switch software and the application running on the TN800. In non-native mode only one type of port MOs will run at any time, and the port type depends on the application running on the TN800. If the TN800 fails diagnostics in non-native mode, the system's alarm and error logs would show a failure for the board type the TN800 is emulating.

**Error log entries and test to clear values****Table 5-53. ASAI-PT Port Error Log Entries**

Error type	Aux Data	Associated Test	Alarm level ASAI-PORT	On/Off Board	Test to Clear Value
0 <sup>1</sup>	0	Any	Any	Any	test port PCSSpp sh r 1
1 (a)	(a)	Level 1 Status Inquiry (#621)	MAJ <sup>2</sup>	OFF	test port PCSSpp sh r 2
513 (b)	0	none	(b)	ON	
1537 (c)	46210	CRC Error Counter (#623)	MAJ <sup>2</sup>	OFF	
3841 (d)	46208	None			
3844 (e)	46223	None			
3845 (f)		None			
3846 (g)	TEI	None			

1. Run the Short Test Sequence first. If all tests pass, run the Long Test Sequence. Refer to the appropriate test description and follow the recommended procedures.
2. Major and Minor alarms may be downgraded to warning alarms based on the value used in the **set options** command.

**Notes:**

- a. This error occurs when the Level 1 Status Inquiry fails or when the BRI circuit pack detects that Level 1 has been deactivated on the port. The aux data field contains one of the following values:

Blank This indicates that the Level 1 Status Inquiry failed.

32773 This is a message from the ASAI-Line circuit pack indicating Level 1 has been deactivated.

Refer to the repair procedures for Test #621 on page [5-164](#).

- b. The circuit pack is having problems transmitting data to the Packet Bus, thus affecting the conveyance of signalling information over D-channel. This error occurs when the Packet Bus transmit FIFO buffer overflows. This condition probably indicates a hardware problem as well. The ASAI-PORT alarm level is MAJOR with aux data 0. Use troubleshooting procedures for both on-board hardware problems and potential off-board Packet Bus problems.

- c. The port received an invalid frame over the D-channel. When the Cyclical Redundancy Check (CRC) errors exceed 5 within 15 minutes, the port is taken out of service for 5 seconds. If 5 more CRC errors are received within 15 minutes of the first set of 5 errors, the port is taken out of service for one minute. If 5 more CRC errors are received within 15 minutes of the last 5, the port is taken out of service for 15 minutes.

This error is most likely due to a problem with the wiring to the set or adjunct, interference on the wiring due to a noise source, or no termination (an open circuit). It usually does not indicate a problem with the circuit pack.

- Check the wiring to the endpoints or the adjunct.
  - If the problem persists, replace the endpoints or adjuncts.
- d. This error occurs when a Layer 1 Transmission error is detected for the port. Run the Long Test Sequence and note the results of the Layer 1 Transmission Error Counter Test (#624).
- e. This error occurs when the circuit pack detects an overflow of its receive buffers. Run the Long Test Sequence and note the results of the Receive FIFO Overflow Counter Test (#625).
- f. This error occurs when the BRI Port Local LAN Looparound Test (#618) fails. Run the Long Test Sequence and note the results of Test (#618).
- g. The Terminal Endpoint Identifier (TEI) administered for the ASAI endpoint most likely does not match the TEI administered in the ASAI adjunct. Check the switch administration of the TEI against that of the adjunct, and make sure that both are using the same TEI.

## System Technician-Demanded Tests: Descriptions and Error Codes

Always investigate tests in the order presented in the following tables when inspecting errors in the system. For example, by clearing error codes associated with the NPE Crosstalk Test, you may also clear errors generated from other tests in the testing sequence.

Order of investigation	Short test sequence	Long test sequence	D/ND <sup>1</sup>
ASAI Port Local LAN Looparound Test (#618)		X	D
Level 1 Status Inquiry Test (#621)	X	X	ND
CRC Error Counter Test (#623)		X	ND
Layer 1 Transmission Error Counter Test (#624)		X	ND
Receive FIFO Overflow Error Counter Test (#625)		X	ND
Clear Error Counters (#270)	X	X	ND


1. D = Destructive; ND = Nondestructive

## BRI Port Local LAN Looparound Test (#618)

**This test is destructive.**

This test verifies the connectivity of a BRI port across the LAN Bus and executes only if the port is out-of-service. The test aborts if calls associated with the port are in-progress. Failures of this test indicate either on-board faults associated with the ASAI-PT hardware on the circuit pack or problems with the LAN Bus, which is used to form connectivity between the switch and the ASAI-PT.

The dotted lines in Figure 10-5 show how a Looparound Test is performed across the Packet Bus for the D-channel.




---

Figure 5-5. BRI Port Local LAN Looparound Path

Table 5-54. TEST #618 BRI Port Local LAN Looparound

Error Code	Test Result	Description/Recommendation
1015	ABORT	<p>The port is not in the out-of-service state.</p> <ol style="list-style-type: none"> <li>1. Display the Port Status form using the <b>status bri-port PCSSpp</b> command to determine which stations or adjuncts are on this port.</li> <li>2. Use the extension shown on this form in the <b>status station</b> command to determine if the station or adjunct is in use.</li> <li>3. If the port is in use, wait until it is idle, and use the <b>busyout port PCSSpp</b> command to place it in the out-of-service state and repeat this test.</li> </ol> <p> <b>WARNING:</b></p> <p><i>Since the "busyout" command is destructive, using this command prior to the port being idle causes all transactions associated with the ASAI on the port to be torn down. Note that third party calls established by an ASAI adjunct remain connected even though the port is taken out-of-service.</i></p>
1139	ABORT	<p>The Packet Bus in the port network is out-of-service.</p> <ol style="list-style-type: none"> <li>1. Follow the repair procedures for the Packet Bus.</li> <li>2. After completing Step 1, execute the <b>test port long PCSSpp</b> command and review the results of the BRI Port Local LAN Looparound Test to verify the repair.</li> </ol>
1141	ABORT	<p>The PKT-CTRL is out-of-service.</p> <ol style="list-style-type: none"> <li>1. Follow the repair procedures for the PKT-CTRL.</li> <li>2. Issue the <b>test port long PCSSpp</b> command and review the results of the BRI Port Local LAN Looparound Test to verify the repair.</li> </ol>
1144	ABORT	<p>The PPN Packet Bus is out-of-service.</p> <ol style="list-style-type: none"> <li>1. Follow the repair procedures for the Packet Bus.</li> <li>2. Issue the <b>test port long PCSSpp</b> command and review the results of the BRI Port Local LAN Looparound Test to verify the repair.</li> </ol>
2012	ABORT	Internal system error
2100	ABORT	<p>Could not allocate the necessary system resources to run this test.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>

Continued on next page

Table 5-54. TEST #618 BRI Port Local LAN Looparound — *Continued*

Error Code	Test Result	Description/Recommendation
	FAIL	<p>The Looparound test has failed.</p> <ol style="list-style-type: none"><li>1. If the test fails repeatedly, attempt to reset the circuit pack if the other ports on the board are not in use. Reset the circuit pack by issuing the <b>busyout board PCSS</b> and the <b>reset board PCSS</b> commands.</li><li>2. If the test fails again, execute <b>test pkt P</b> on the management terminal. If this fails, follow the failure procedures the in <a href="#">“PKT-BUS (Packet Bus)”</a> section.</li><li>3. If the tests executed in Step 2 pass, the problem is local to the BRI board. Replace the circuit pack.</li></ol>
	PASS	The BRI Port Local LAN Looparound test has passed.

### Level 1 Status Inquiry Test (#621)

This test determines the state of the transmission facility of a BRI port at the Level 1 (L1) or physical layer. L1 can be in one of two possible states: Activated or Deactivated.

The Activated state is the correct state for an ISDN-BRI port. In this state the Level 1 interface can communicate with the BRI endpoint or ASAI adjunct administered on this port. This test passes if the state of L1 is activated. This test also passes if software has taken this port out of service.

The Deactivated state indicates a problem with the ASAI circuit pack. When in this state, the Level 1 interface is idle and is not trying to communicate with the BRI endpoints or adjunct. When an ASAI port is placed in the out-of-service state, Level 1 is also put into the deactivated state. This could be due either to the system detecting a fault with the port or in response to a **busyout port PCSSpp** request.

Table 5-55. TEST #621 Level 1 Status Inquiry

Error Code	Test Result	Description/Recommendation
1187	ABORT	<p>The board, port, or station may have been busied-out by a technician.</p> <ol style="list-style-type: none"> <li>1. Look in the Error Log for Error Type 18 (port busied out) for this port and ASAI-BD (board busied out). If this error type is present for ASAI-PT only, then release the port using the <b>release port pp</b> command and run the test again. If the error is present for both ASAI-BD and ASAI-PT, then release the board with the <b>release port PCSS</b> command and run the test again.</li> </ol> <p> <b>NOTE:</b> When you release a port, you release all ports associated with it. If certain ports still need to be busied out, use the <b>release port PCSSpp</b> command to busy them out.</p> <ol style="list-style-type: none"> <li>2. Make sure the terminal is connected.</li> <li>3. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
2000	ABORT	<p>Response was not received from the circuit pack within the allowable time period.</p> <ol style="list-style-type: none"> <li>1. If the test aborts repeatedly a maximum of 5 times, reset the circuit pack using the <b>busyout board PCSS</b> and <b>reset board PCSS</b> commands.</li> <li>2. If the test aborts again, replace the circuit pack.</li> </ol>
2012	ABORT	Internal system error
2100	ABORT	<p>Could not allocate the necessary system resources to run this test.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
3	FAIL	<p>Received a status of Level 1 Deactivated; the port is out-of-service.</p> <ol style="list-style-type: none"> <li>1. Issue the <b>status bri-port PCSSpp</b> command to verify that the service state of the port is out-of-service. If the port is not out-of-service, proceed to Step 2.</li> <li>2. If the port has been placed out-of-service using the <b>busyout port PCSSpp</b> command, try releasing the port by executing the <b>release port PCSSpp</b> command. Then issue the <b>test port long PCSSpp</b> command, and review the results of Level 1 Status Inquiry test. If this test is still failing, proceed to Step 3.</li> <li>3. After executing the <b>test port long PCSSpp</b> command, review the results of all the tests. Follow the repair procedures for any tests that fail. Verify repair of the problem by executing the <b>test port PCSSpp</b> command and by determining that the Level 1 Status test passes.</li> </ol>
	PASS	<p>This test indicates that Level 1 is activated, or that software has taken the port out of service.</p>

## Layer 1 Transmission Error Counter Test (#624)

This test reads and clears the BRI port's Layer 1 Transmission error counter maintained on the ASAI circuit pack. This counter is incremented by the circuit pack when it detects a Layer 1 transmission problem. The test passes if the value of the counter is 0 (that is, the error is cleared). If the counter is not zero, the test fails, and the value of the counter is displayed in the Error Code field.

This error is most likely due to a problem with the wiring or adjunct (verify that the wiring meets the configuration rules defined in *DEFINITY Communications System Generic 1 and Generic 3i Wiring*, 555-204-111). It does not indicate a problem with the TN800 circuit pack. This test is useful for verifying the repair of the problem

Table 5-56. TEST #624 Layer 1 Transmission Error Counter Test

Error Code	Test Result	Description/Recommendation
2000	ABORT	Response was not received from the circuit pack within the allowable time period. <ol style="list-style-type: none"><li>1. If the test aborts repeatedly a maximum of 5 times, reset the circuit pack using the <b>busyout board PCSS</b> and <b>reset board PCSS</b> commands.</li><li>2. If the test aborts again, replace the circuit pack.</li></ol>
2012	ABORT	Internal system error
2100	ABORT	Could not allocate necessary system resources to run test. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
Any	FAIL	The TN800 circuit pack is still detecting errors of this type. The Error Code field contains the value of this counter. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li><li>2. If the test continues to fail, review the results of other tests in the Long Test Sequence. Note the results of the Level 1 Status Inquiry test. Follow the repair procedures for any of the executed tests if they fail. Otherwise, go to the next step.</li><li>3. Replace the circuit pack.</li></ol>
	PASS	The Layer 1 Transmission error counter was read correctly and has a value of 0.

**Receive FIFO Error Counter Test (#625)**

This test reads and clears the BRI port's Receive FIFO error counter maintained on the TN800 circuit pack. This counter is incremented by the circuit pack when it detects an overflow of its receive buffers. The test passes if the value of the counter is 0 (that is, the error is cleared). If the counter is not zero, the test fails, and the value of the counter is displayed in the Error Code field.

This error can occur if signaling frames are being received from a Packet Bus at a rate sufficient to overflow the receive buffers on the circuit pack for a port or if hardware fault is causing the receive buffers not to be emptied properly. This test is useful for verifying the repair of the problem.

**Table 5-57. TEST #625 Receive FIFO Error Counter Test**

Error Code	Test Result	Description/Recommendation
2000	ABORT	Response was not received from the circuit pack within the allowable time period. <ol style="list-style-type: none"> <li>1. If the test aborts repeatedly a maximum of 5 times, reset the circuit pack via the <b>busyout board PCSS</b> and <b>reset board PCSS</b> commands.</li> <li>2. If the test aborts again, replace the circuit pack.</li> </ol>
2012	ABORT	Internal system error
2100	ABORT	Could not allocate necessary system resources to run test. <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
Any	FAIL	The TN800 circuit pack is still detecting errors of this type. The Error Code field contains the value of this counter. <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> <li>2. If the test continues to fail, review the results of other tests in the Long Test Sequence. Note the results of the Level 1 Status Inquiry test. Follow repair procedures for any of the tests that fail. Otherwise, go to the next step.</li> <li>3. If the tests for the endpoints or adjunct pass and the Layer 1 Transmission Error Counter Test continues to fail, check the wiring to the endpoints or adjunct.</li> </ol>
	PASS	The Layer 1 Transmission error counter was read correctly and has a value of 0.

**Clear Error Counters Test (#270)**

There are various error counters associated with each ASAI-PT. This test clears those counters and triggers the auditing of Layer 3 reinitialization. This test is used only to send messages to the ASAI-PT and, therefore, should neither abort nor fail. ASAI uses a fixed TEI value of 1.

**Table 5-58. TEST #270 Clear Error Counters**

<b>Error Code</b>	<b>Test Result</b>	<b>Description/Recommendation</b>
Any	ABORT	This test should never abort.
Any	FAIL	This test should never fail.  1. Retry the command at 1-minute intervals a maximum of 5 times.
	PASS	The message to clear the error counters of the ASAI-PT has been sent.

## ASAI-RES/E-DIG-RES (TN800 reserve slot)

---

MO name (in alarm log)	Alarm level	Initial command to run	Full name of MO
ASAI-RES	NONE	NONE	TN800 ASAI reserve slot
E-DIG-RES	NONE	NONE	TN800 DIG reserve slot

There are no tests associated with these MOs. Both the **test board** and **busy out board** commands abort when either is attempted on a reserved slot. An error message indicates the slot is associated with the circuit pack that the TN800 is emulating, but the requested operation is not valid.

The TN800 MAPD (Multi-Application Platform for DEFINITY) circuit pack connects to the switch through a single slot in the backplane. The number of slots occupied by the MAPD pack is supplied by the board when inserted. The TN800 in R5EM is 3 slots wide. The TN800 requires 2 reserve slots to its left. The reserve (blank) slots are to left of the functional slot and are place holders on the switch, and do not have any interaction with the switch.

Each instance of these MOs represents a reserve slot associated with respective circuit pack mode in which the MAPD is working.

## ATM-BCH (ATM B-channel trunk)

MO name (in alarm log)	Alarm level	Initial command to run <sup>1</sup>	Full name of MO
ATM-BCH <sup>2</sup>	MAJOR <sup>3</sup>	test port UUCSSppp l	ATM B-Channel Trunk
ATM-BCH	MINOR	test port UUCSSppp l	ATM B-Channel Trunk
ATM-BCH	WARNING	test port UUCSSppp sh	ATM B-Channel Trunk

1. UU is the universal cabinet number (1 for PPN, 2-44 for EPNs). C is the carrier designation (A, B, C, D, or E). SS is the number of the slot where the circuit pack resides (01-21). ppp is the 3-digit port number (9-256).
2. For additional repair information, see also [“ATM-DCH \(ATM D-channel port\)”](#), [“ATM-SGRP \(ATM signaling group\)”](#) and [“PKT-BUS \(Packet Bus\)”](#).
3. A MAJOR alarm on a trunk means that alarms on these trunks are not downgraded by the **set options** command, and at least 75% of the trunks in this trunk group are alarmed.

This maintenance object explains how you test and repair TN230x ATM Interface circuit packs (TN2305 and TN2306) that have been administered as ATM B-channel trunks for ATM Circuit Emulation Service (CES).

For maintenance instructions for TN230x circuit packs that are administered as Expansion Interfaces for ATM network connectivity, see the [“ATM-EI \(Expansion Interface Circuit Pack\)”](#) maintenance object.

### ATM circuit emulation service

Under ATM Circuit Emulation Service, you simulate ISDN-PRI circuits by assigning ATM ports to *signaling groups*. Each signaling group represents a PRI circuit, and the ports in the group represent the D-channel and B-channels of that circuit. TN230x circuit packs support up to 248 ports per circuit pack.

### Signaling group components

Bearer (B) channels (ATM-BCH) transmit digitized voice or data, while a separate D-channel (ATM-DCH) handles call-control signaling. One D-channel handles signaling for a group of B-channels that combine to form a signaling group (ATM-SGRP).

### B-channel service states

The ISDN specification defines 2 service state categories for B-channels as listed in [Table 5-59](#).

Table 5-59. ATM ISDN service states

Category	Description		
<b>Service states</b>			
In-Service (INS)	B-channel is in normal operating state	Active	A call is connected over the B-channel.
		Idle	There is no call on the B-channel.
Out-of-Service/Far-end (OOS/FE)	<p>The switch has not successfully negotiated B-channel connection as of yet. Calls cannot be placed or received.</p> <p>When you first administer a B-channel, the switch initializes the B-channel to this state while it tries to negotiate a connection to the far end. If the request times out with no response from the far end, the switch leaves the B-channel in the OOS/FE state.</p>		
Out-of-Service/Near-End (OOS/NE)	The NPE Crosstalk Test has failed or the trunk is busied out. Calls cannot be placed or received.		
Maintenance/Far-End (MTC/FE)	A request has timed out with no response from the far end after signaling is in place and B-channels are in service. Calls can be received but not placed, and stable calls are unaffected.		
Maintenance/Near-End (MTC/NE)	The signaling channel (ISDN-LNK) has been busied out, possibly after a <b>test trunk grp#/mbr# long</b> command. Calls cannot be placed or received, but stable calls are unaffected.		
<b>Pending states<sup>1</sup></b>			
Pending-in-Service	The near-end is waiting for a response to a transition-to-service request.		
Pending-Maintenance	The near-end is waiting for a transition-to-maintenance-service request (US and other country-protocol-1 systems).		

---

1. The switch is waiting for a reply from the far-end. Pending service states remain in effect until the near end receives a response or times out.

---

## B-channel alarms

The Maintenance/Far-End and Out-Of-Service/Far-End states generate warning alarms displayed with **status trunk grp#/mbr#**.

Table 5-60. ATM-BCH alarms by service state

Service state	Alarm <sup>1</sup>	Possible cause	Possible solution
Out-of-Service/NE	Warning	Trunk busied out	Release the port ( <b>release trunk grp#/mbr#</b> ).
	Minor	NPE Crosstalk Test (#6) failed	Replace ATM circuit pack.
	None	ATM circuit pack lost signal or there is a circuit pack problem.	Install circuit pack or cable. Check circuit pack using procedures in ATM-BCH. Check far-end switch status.
Out-of-Service/FE	Warning	Unadministered far-end	Administer the corresponding trunk on the far-end switch.
	Warning	Far-end busied out	Check the status of the far-end switch.
Pending/In-Service Pending/Maint	None	Maintenance message timed out waiting for reply	Wait 2 minutes after the pending state clears, and check the service state.
Maint/NE	None	ISDN test call in progress ( <b>test trunk long</b> )	Wait for the test to finish and recheck.
	None	System link busied out	Check link status. Run <b>release link link#</b> .
Maint/FE	Warning	Signaling channel down for over 90 sec.	See <a href="#">“ATM-SGRP (ATM signaling group)”</a> or <a href="#">“ATM-DCH (ATM D-channel port)”</a> .
	Warning	Repeated lack of response to messages sent to the far end	Wait. Maintenance software resends messages periodically. Or run <b>test trunk grp#/mb#</b> or <b>test signaling-grp grp#</b> .
	Warning	The far-end trunk is being tested.	Check status of the far-end switch. Wait for testing to finish.
In-Service	None	Normal operating state	

1. ATM-BCH alarms; alarms against other maintenance objects may also be present.

**Error log entries and test to clear values**

Table 5-61. ATM-BCH error log entries

Error type	Aux data	Associated test	Alarm level	On/Off board	Test to clear value
0 <sup>1</sup>	0	Any	Any	Any	test port UUCSSppp
1(a)	Any	None			test port UUCSSppp
18	0	busyout trunk <i>grp/mbr</i>			release trunk grp/mbr
129 (b)		None	WNG	OFF	test port UUCSSppp
130 (c)					test port UUCSSppp
257(d)	Any	Service State Audit (Test #256)			test port UUCSSppp
513(e)	Any	None	WNG	OFF	test port UUCSSppp
769(f)	Any	Service State Audit (Test #256)			test port UUCSSppp
1793(g)	Any	None			test port UUCSSppp
3073(h)	Any	Service State Audit (#256)			test port UUCSSppp
3585(i)	Any	None			none
3841(j)	Any	None	WNG	OFF	none

1. Run the Short Test Sequence first. If all tests pass, run the Long Test Sequence. Refer to the appropriate test description and follow the recommended procedures.

**Notes:**

- a. Error Type 1: the two ends of the ATM trunk do not agree on the ISDN call state. Possible causes:
  - Received a DISConnect or RELease COMplete message with cause value 52 (outgoing calls barred)

5 Maintenance Objects for DEFINITY ONE  
ATM-BCH (ATM B-channel trunk)

5-173

- Received a DISConnect or RELease COMplete message with cause value 54 (incoming calls barred)
- Outgoing call renegotiated by the far end to another B-channel in the absence of SETUP message glare
- Near end attempted a call on a B-channel that the far end has marked OOS

When running the Short Test Sequence, pay close attention to the results of the Call State Audit Test (#257).

- b. Error Type 129: the far-end switch changed its ISDN service state to either out-of-service or maintenance. This may be a temporary condition because the far-end is testing that trunk or a hardware problem with the trunk. Outgoing calls may not be allowed over that trunk.
  1. Investigate the trunk status (**status trunk grp#/mbr#**).
- c. Error Type 130: the circuit pack has been removed or has been insane for more than 11 minutes.
  1. Reinsert or replace the circuit pack to clear the error.
- d. Error Type 257: SETUP received for a B-channel that is in an invalid service state. Service states may be incompatible at the two ends of the trunk. A normal call was received while the B-channel was MTC/FE, MTC/NE, OOS/FE, or OOS/NE or a test call was received while the B-channel was OOS/FE or OOS/NE.
- e. Error Type 513: RELease COMplete message received with cause value 82 (nonexistent channel). The B-channel may not be administered at the far end. The trunk has been placed in the OOS/FE state.
- f. Error Type 769: inconsistent SERvice or SERvice ACKnowledge message. Possible causes:
  - SERvice or SERvice ACKnowledge message received containing a change status that is more available than the previously-transmitted SERvice message.
  - Unsolicited SERvice ACKnowledge message received containing a change status that does not match the current B-channel state.

ISDN-PRI service-state negotiation rules have been violated and may indicate that a pending service-state audit is failing. The system

- Cancels the maintenance timer
- Increments the Service State Audit counter
- Attempts a Service State Audit

When running the Short Test Sequence, pay close attention to the results of the Service State Audit Test (#256).

- g. Error Type 1793: TN230x circuit pack has failed. The maintenance system
  - Places the trunk in the OOS/NE state
  - Sends a SERvice message to the far-end (if possible) containing a change status of OOS for the B-channel
  - Returns the trunk to service when the ATM trunk circuit pack reports the failure cleared
- h. Error Type 3073: Service State Audit attempt failed (see Test #256). Calls can be received but not placed until the test passes and the trunk state returns to In-Service.
  1. Check the trunk status (**status trunk grp#/mbr#**).
- i. Error Type 3585: ISDN RESTART message received. Active calls have been dropped.

The following Aux Data values (Error Type 3585 only) below represent the trunk's ISDN call state at the time Error 3585 occurred. This information can be useful if users report dropped calls on the ISDN-PRI trunks.

Aux data	Description
0	An idle trunk received a restart.
10	An ISDN RESTART from the far-end has unexpectedly cleared a call in the ACTIVE state (call stable, parties talking).
4 7 8 260 263	An ISDN RESTART from the far-end has unexpectedly cleared a RINGING call.
1 3 6 9 265	An ISDN RESTART from the far-end has unexpectedly cleared a call before the call entered the RINGING state.
11 12 19 531 267 268	An ISDN RESTART from the far-end has unexpectedly cleared a call that was already in the process of clearing.  If this condition occurs frequently, the far-end may be trying to clear trunks that appear to be in the "hung" state.

- j. Error Type 3841: the far-end rejected an ATM CES trunk selected by the near-end 10 times. The ATM CES trunk may not be administered on the far-end.
1. Get the physical name of the ATM trunk by noting the decimal number in the `Aux Data` field.
  2. Check administration for the named trunk on the far-end.
  3. If problems persist, then busyout the ATM trunk to take it out of the hunt group.

The WARNING alarm retires automatically whenever a called endpoint answers an outgoing or incoming call that uses the alarmed trunk.

---

### System technician-demanded tests: descriptions and error codes

---

Always investigate problems in the order presented in the table below. When you clear one of the error codes associated with a given test, you clear errors generated by other tests in the testing sequence. If you clear errors out of order, you can lose important information.

Table 5-62. System technician-demanded tests: ATM-BCH

Order of investigation	Short test sequence	Long test sequence	Destructive or non-destructive
Signaling Link State Check Test (#255)	X	X	ND
Service State Audit Test (#256)	X	X	ND
Call State Audit Test (#257)	X	X	ND
ISDN Test Call Test (#258)		X	ND

---

## Signaling link state audit test (#255)

This non-destructive test checks the status of the TN230x ATM-CES Interface circuit pack and the ATM D-channel (ATM-DCH) trunk, which are both important elements to the health of the ATM-BCH trunk.

Table 5-63. TEST #255 signaling link state audit test

Error code	Test result	Description/ Recommendation
None	ABORT	Internal system error
0	ABORT	
1114	ABORT	Signaling link in transitional state 1. Retry the command up to 5 times at 1-minute intervals.
1018	ABORT	Maintenance disabled 1. Enable maintenance. Enter <b>y</b> in the <code>Maintenance Tests?</code> field on page 2 of the <b>change trunk-group</b> form.
4	FAIL	Signaling channel problem 1. Look for errors or alarms against the <a href="#">“ATM-SGRP (ATM signaling group)”</a> and <a href="#">“ATM-DCH (ATM D-channel port)”</a> maintenance objects.
8	FAIL	TN230x circuit pack failed 1. See the <a href="#">“ATM-INTF (TN2305/6)”</a> maintenance object.
	PASS	Signaling link OK.

## Service state audit (#256)

This test checks the service state of the trunk.

**Country protocol 1.** If the interface uses country protocol 1 (includes USA), the service-state audit executes in all trunk service states. It queries the service state on the far end and waits 2 minutes for a reply. If the first request times out, the service-state audit asks again. If the request times out again, it logs error 3073 and resends the request every 15 minutes. It places in-service trunks in the MAINTENANCE/FAR-END state (outgoing calls blocked, incoming calls accepted). Incoming calls trigger an immediate service-state audit without waiting for the end of a 15-minute cycle.

**Any other country protocol.** If the interface uses some other country protocol, the service-state audit executes only on trunks that are in the OUT-OF-SERVICE/FAR-END state. It asks the far-end switch to bring the trunk back into the IN-SERVICE state and waits 2 minutes for a reply. If the first request times out, the service-state audit asks again. If the request times out again, it leaves the trunk in the OUT-OF-SERVICE/FAR-END state and tries again in 1 hour.

**NOTE:**

PASS for this test only means that a message to the far-end was successfully sent.

To check the service state of the ATM-BCH trunk, run **status trunk grp#mbr#**.

Table 5-64. TEST #256 service state audit test

Error code	Test result	Description/ Recommendation
1000	ABORT	Needed resources not available, port on a call or initializing <ol style="list-style-type: none"> <li>1. Run <b>status trunk grp#mbr#</b>.</li> <li>2. Check the results of Test #255.</li> </ol>
1018	ABORT	Maintenance disabled <ol style="list-style-type: none"> <li>1. Enable maintenance by entering <b>y</b> in the Maintenance Tests? field on page 2 of the <b>change trunk-group</b> form.</li> </ol>
1113	ABORT	Signaling link failed <ol style="list-style-type: none"> <li>1. Run <b>status trunk grp#mbr#</b>.</li> <li>2. Check the results of Test #255.</li> <li>3. See the "<a href="#">ATM-SGRP (ATM signaling group)</a>" maintenance object.</li> </ol>
1114	ABORT	Signaling link in transitional state <ol style="list-style-type: none"> <li>1. Retry the command up to 5 times at 1-minute intervals.</li> </ol>
1116	ABORT	Trunk not in Out-of-Service/Far-end state and country protocol other than 1
1117	ABORT	Service-state audit message outstanding <ol style="list-style-type: none"> <li>1. Wait 2 minutes, then try again.</li> </ol>
2100	ABORT	Could not allocate needed resources <ol style="list-style-type: none"> <li>1. Retry the command up to 5 times at 1-minute intervals.</li> </ol>

*Continued on next page*

Table 5-64. TEST #256 service state audit test — *Continued*

Error code	Test result	Description/ Recommendation
1113	FAIL	Signaling link failed <ol style="list-style-type: none"><li>1. See the <a href="#">“ATM-SGRP (ATM signaling group)”</a> and ISDN-LNK (ISDN Signaling Link Port) maintenance objects.</li></ol>
	FAIL	Internal system error <ol style="list-style-type: none"><li>1. Retry the command up to 5 times at 1-minute intervals.</li></ol>
	PASS	<ol style="list-style-type: none"><li>1. Wait 4 minutes, then check the Error Log for any new Error Type 3073.<ul style="list-style-type: none"><li>■ If there are none, both sides of the ISDN connection agree on the service state. The negotiation succeeded.</li><li>■ If there is a new 3073 error, then the negotiation failed (the request timed out).</li></ul></li></ol>

### Call state audit test (#257)

This test audits the internal call state by asking the far-end switch for the ISDN call state. The test is particularly useful when you are trying to clear a hung call. If the internal call state on the near-end differs from that on the far-end, the call is torn down.

The ISDN specification allows up to 2 minutes for a reply. If a reply is not received within the 2 minute window, the test logs a protocol time-out violation against the associated signaling channel (ATM-DCH, Error Type 1).

**NOTE:**

PASS simply means that an appropriate message was composed and sent to the far-end switch.

Table 5-65. TEST #257 call state audit test

Error code	Test result	Description/ Recommendation
1018	ABORT	Maintenance disabled 1. Enable maintenance by entering <b>y</b> in the <code>Maintenance Tests?</code> field on page 2 of the <b>change trunk-group</b> form.
1019	ABORT	Audit already in progress 1. Wait 2 minutes, and try again.
1113	ABORT	Signaling link failed 1. Check the results of Test #255 (Signaling Link State Check).
1114	ABORT	Signaling link in transitional state 1. Retry the command up to 5 times at 1-minute intervals.
1116	ABORT	Trunk out-of-service 1. Check the trunk service state ( <b>status trunk grp#mbr#</b> ).
2100	ABORT	Could not allocate needed resources 1. Retry the command up to 5 times at 1-minute intervals.
	FAIL	Internal system error 1. Retry the command up to 5 times at 1-minute intervals.
	PASS	1. Wait 4 minutes, then check the Error Log for call-state mismatches. If a call state mismatch is found, the call is torn down.

### ISDN test call test (#258)

This non-destructive test performs a far-end looparound test over an ATM-BCH trunk if:

- The trunk is IN-SERVICE, MAINTENANCE/NEAR-END, or OUT-OF-SERVICE/NEAR-END
- No calls are active on the trunk
- The system uses country protocol 1 (including US) or the far-end has looparound capability

The test sets up a call to a far-end switch over the ATM-BCH trunk. Then the digital port on a TN711D Maintenance/Test circuit pack sends a bit pattern to the far-end and back. If the received pattern matches that sent, the test passes. If there are differences, it fails.

### Synchronous test calls

You can initiate a synchronous outgoing test call (including a test call for ISDN-PRI trunks) with these commands:

- **test trunk *grp#/mbr# long [repeat #]***
- **test board *UUCSS long [repeat #]***
- **test port *UUCSSpp long [repeat #]***

Table 5-66. TEST #258 ISDN test call

Error code	Test result	Description/ Recommendation
4	ABORT	Signaling channel problem 1. Look for errors or alarms against the <a href="#">“ATM-SGRP (ATM signaling group)”</a> and <a href="#">“ATM-DCH (ATM D-channel port)”</a> maintenance objects.
8	ABORT	TN230x circuit-pack problem 1. See the <a href="#">“ATM-INTF (TN2305/6)”</a> maintenance object.
1004	ABORT	B-channel in use. 1. See if a call is active. Run <b>status trunk <i>grp#/mbr#</i></b> command. 2. If the service state is In-Service/Idle, retry the test.
1005	ABORT	Bad configuration (for example, no Maintenance/Test circuit pack) 1. Make sure that the Maintenance/Test Circuit Pack is inserted. 2. Repeat the test.
1018	ABORT	Test call disabled 1. Enable Maintenance on the Trunk Group form.
1020	ABORT	TN230x circuit-pack problem 1. See the <a href="#">“ATM-INTF (TN2305/6)”</a> maintenance object.

*Continued on next page*

Table 5-66. TEST #258 ISDN test call — *Continued*

Error code	Test result	Description/ Recommendation
1024	ABORT	Maintenance/Test Digital Port in use  1. Wait until yellow and green LEDs on the Maintenance/Test circuit pack are OFF. 2. Rerun the test. 3. If the problem persists, see the M/T-DIG (Maintenance/Test Digital Port) maintenance object.
1113	ABORT	Signaling link failed  1. Check the results of Test #255 (Signaling Link State Check Test).
1116	ABORT	Switch could not change the service state  1. See if calls are active. Run <b>status trunk grp#/mbr#</b> . 2. If a call is active. proceed as for Error Code 1119. 3. If not, check the Error and Alarm Logs and refer to <a href="#">“ATM-TRK (circuit emulation service circuit pack)” on page 5-264</a> .
1117	ABORT	ISDN service message outstanding  1. Wait 2 minutes. Then try again.
1118	ABORT	Far-end not administered  1. Check the administration of the far-end of the ATM trunk. Run <b>status trunk grp#/mbr#</b> . 2. Try the test again.
1119	ABORT	Test call aborted, normal call attempted  1. Wait for the call to terminate normally or drop it by running <b>busyout trunk grp#/mbr#</b> . 2. When the trunk is idle, retry the test.
1120	ABORT	Trunk OUT-OF-SERVICE/FAR-END  1. Try to change the service state via Test #256 (Service State Audit Test). 2. Try the test again.
1122	ABORT	No test-line number for the far-end switch  1. Check the Trunk Group Administration form.

*Continued on next page*

Table 5-66. TEST #258 ISDN test call — *Continued*

Error code	Test result	Description/ Recommendation
1123	ABORT	No Feature Access Code administration for this Facility Test 1. Check the Dial Plan and Feature Administration forms.
2000 2012 None	ABORT	Internal system error 1. Retry the command up to 5 times at 1-minute intervals.
2035	ABORT	Call timed out 1. Wait 1 minute, and try again.
2036- 2037	ABORT	Internal system error 1. Retry the command up to 5 times at 1-minute intervals.
2038- 2039	ABORT	Problem reading test data 1. Wait 1 minute, and then try again. 2. If the test aborts again, there is a serious internal problem.
2040	ABORT	Internal system error 1. Retry the command up to 5 times at 1-minute intervals.
2041	ABORT	Call timed out 1. Wait 1 minute, and try again.
2066	ABORT	Could not establish test call 1. Retry the command up to 5 times at 1-minute intervals.
2067	ABORT	Call timed out 1. Wait 1 minute, and try again.
2074	ABORT	Bit and Block Error query failed 1. Retry the command up to 5 times at 1-minute intervals. 2. If the test continues to abort, there may be a serious internal problem in the Maintenance/Test Digital Port. See the M/T-DIG (Maintenance/Test Digital Port) maintenance object.
2075	ABORT	Internal system error 1. Retry the command up to 5 times at 1-minute intervals.
2100	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals a maximum of 5 times.

*Continued on next page*

Table 5-66. TEST #258 ISDN test call — *Continued*

Error code	Test result	Description/ Recommendation
2201-2205	ABORT	Internal system error 1. Retry the command up to 5 times at 1-minute intervals.
2206	ABORT	Could not allocate needed resources 1. Retry the command at 1-minute intervals a maximum of 5 times.
2208	ABORT	Internal system error 1. Retry the command at 1-minute intervals a maximum of 5 times.
2209-2210	ABORT	Could not allocate needed resources 1. Follow recommendations for ABORT code 2100.
2211	ABORT	Internal system error. 1. Retry the command at 1-minute intervals a maximum of 5 times.
2212	ABORT	Call terminated by unexpected disconnect 1. Wait 1 minute and then try again.
2213	ABORT	Call timed out 1. Wait 1 minute, and try again.
2214	ABORT	Call terminated by unexpected disconnect 1. Wait 1 minute and then try again.
2215-2219	ABORT	Internal system error 1. Retry the command at 1-minute intervals a maximum of 5 times.
2220	ABORT	Call terminated prematurely 1. Wait 1 minute, and try again.
2221-2226	ABORT	Internal system error 1. Retry the command at 1-minute intervals a maximum of 5 times.
2227	ABORT	Could not allocate needed resources 1. Retry the command at 1-minute intervals a maximum of 5 times.
2042	FAIL	Test data corrupt
	PASS	Test pattern intact. If the synchronous test call was performed (long test sequence), the communications path is operating properly.

## ATM-DCH (ATM D-channel port)

MO name (in alarm log)	Alarm level	Initial system technician command to run <sup>1</sup>	Full name of MO
ATM-DCH <sup>2</sup>	MINOR	test port <i>UUCSSpp l</i>	ATM D-Channel
ATM-DCH	WARNING	test port <i>UUCSSpp sh</i>	ATM D-Channel

1. pp is administered as a port in the range of 9 through 32.
2. For additional related information, see [“ATM-TRK \(circuit emulation service circuit pack\)”](#).

**NOTE:**

TN230x circuit packs are not interchangeable. Always replace an ATM circuit pack with the same type.

This MO (ATM-DCH) utilizes the existing ISDN-PLK or D-channel maintenance strategy with modifications. The ATM circuit pack can be administered for up to 8 Circuit Emulation Service (CES) or signaling groups, each with its own D-channel, as opposed to one D-channel for an entire DS1 circuit pack.

**NOTE:**

Due to the dual personalities and the number of D channels the ATM board can possess, the in-line errors and signaling port LAN loopback test have been moved to the maintenance object ATM-TRK. When an in-line error is sent due to PACKET BUS errors, the ATM circuit pack maintenance object receives the error, not ATM-DCH.

The D-channel ISDN-PRI interface, which is emulated for ATM-CES, uses out-of-band signaling to transmit control messages between two endpoints. User information or bearer channels (B-channels) carry digitized voice and digital data and are assigned to DS1 ISDN trunks or PRI endpoints. Call control signaling for the B-channels is combined and carried over the separate ISDN-PRI Signaling Link Port D-channel.

Problems with ATM-DCH affects all of the associated B-channels, since call control signaling cannot reach the far-end switch or terminal adapter. Stable calls may remain operational, but no new calls can be made. ATM-DCH in turn depends on the TN230X ATM Trunk circuit pack it resides on and the packet bus which provides the link to the processor.

When working ATM-DCH alarms or errors, also investigate

- [“ATM-TRK \(circuit emulation service circuit pack\)”](#)
- [“PKT-BUS \(Packet Bus\)”](#)

## Hardware error log entries and test to clear values

Table 5-67. ATM D-channel error log entries

Error type	Aux data	Associated test	Alarm level	On/Off board	Test to clear value
0 <sup>1</sup>	0	Any	Any	Any	test port UUCSSpp <sup>2</sup>
18 (a)	0	busyout port <i>UUCSSpp</i>	WARNING	OFF	release port UUCSSpp
130 (b)		None	WARNING	ON	test port UUCSSpp
1793 (c)		Signaling Link Board Check (#643)			test board UUCSS I

1. Run the Short Test Sequence first. If all tests pass, run the Long Test Sequence. Refer to the appropriate test description and follow the recommended procedures.
2. pp is for ports 9-32.

### Notes:

- a. Error Type 18: D-channel busied out; no calls possible over this D-channel.
- b. Error Type 130: circuit pack removed or has been insane for more than 11 minutes. To clear the error, reinsert or replace the circuit pack.
- c. Error Type 1793: ATM Trunk circuit pack failed the Signaling Link Board Check (#643). Resolve any ATM-TRK errors in the Error Log.

## System technician-demanded tests: descriptions and error codes

---

The command to test the ATM-DCH maintenance object is **test port UUCSSpp**, where pp is for ports 9-32.

Table 5-68. System technician-demanded tests: ATM-DCHL

Order of investigation	Short test sequence	Long test sequence	D/ND <sup>1</sup>
Signaling Link Board Check (#643)	X	X	ND

---

1. D = Destructive, ND = Non-destructive

---

### Signaling link board check (#643)

This nondestructive test checks the health of the ATM TN230X Trunk circuit pack hardware. The test runs on a periodic or scheduled basis, during initialization testing, and upon demand.

**NOTE:**

The board-level maintenance is handled independently of the ATM-CES signaling link maintenance, raising the possibility of inconsistent states.

Table 5-69. TEST #643 signaling link board check

Error code	Test result	Description/ Recommendation
	ABORT	Internal System Error 1. Retry the command at 1-minute intervals for a maximum of 5 times.
8	FAIL	The TN230X circuit pack is not in-service. 1. Check the Error Log for ATM-TRK errors and resolve any using <a href="#">"ATM-TRK (circuit emulation service circuit pack)"</a> .
	PASS	The ATM TN230X circuit pack is in-service.

## ATM-EI (Expansion Interface Circuit Pack)

MO name (in alarm log)	Alarm level	Initial command to run <sup>1</sup>	Full name of MO
ATM-EI	MAJOR	test board UUCSS	ATM Expansion Interface Circuit Pack
ATM-EI	MINOR	test board UUCSS	ATM Expansion Interface Circuit Pack
ATM-EI	WARNI NG	test board UUCSS	ATM Expansion Interface Circuit Pack

1. UU is the universal cabinet number (1 for PPN, 2 - 44 for EPNs). C is the carrier designation (A, B, C, D, or E). SS is the number of the slot in which the circuit pack resides (01 to 21).

This maintenance object covers the ATM circuit pack administered as an ATM-Port Network Connectivity (PNC) Expansion Interface (ATM-EI). The ATM-EI provides PNC between a DEFINITY PPN and all the EPNs through the ATM switch.

The circuit packs listed in [Table 5-70](#) are ATM-EI boards *if they are administered to serve the ATM Port Network Connectivity (ATM-PNC) for DEFINITY.*

**Table 5-70. ATM-EI circuit packs for R8**

Circuit pack	Fiber	Echo cancellation
TN2305	Multi mode	Y
TN2306	Single mode	Y

**⇒ NOTE:**  
TN230x circuit packs are not interchangeable. Always replace an ATM circuit pack with the same type.

**⇒ NOTE:**  
ATM switch maintenance is not covered in this section. When DEFINITY ECS maintenance software suspects the ATM switch connections, it raises appropriate DEFINITY alarms.  
To clear any ATM switch faults, refer to the particular ATM switch's documentation.

## LEDs

---

The ATM Interface circuit pack has three LEDs:

- red indicates some alarm condition
- green indicates maintenance testing in progress
- yellow provides useful visual information regarding the operating mode of the ATM-EI and possible error conditions.

The possible LED states are in [Table 5-71](#).

**Table 5-71. ATM Interface LED codes**

LED	LED status	Condition
Red	Steady on	Board is not healthy
	Never on	Normal conditions
Red and Green	Red LED solid on Green LED 200 ms on; 200 ms off	Board is in the processes of booting
Green	Steady on <sup>1</sup>	Maintenance is running tests on the board
	100 ms on - 100 ms off	No links to the board
Yellow	100 ms on -100 ms off	Fiber Loss of Signal (LOS), LOF, MS_RDI, MS_AIS, LCD, HP_RDI, HP_AIS, LOP, PSC (See <a href="#">Table 5-75</a> )
Yellow	500 ms on; 500 ms off	Signal to the ATM switch is down
Yellow	2 s on; 0.2 s off	ATM-EI is Expansion Archangel (EAA)
Yellow	Steady on	ATM-EI active (PPN)
Yellow	Never on	ATM-EI standby

---

---

1. The green LED flashes between tests.

---

## ATM-EI-related commands

---

The following commands may be helpful in resolving ATM-EI problems:

add atm pnc	list measurements atm
busyout/release atm pnc	remove atm pnc
busyout/release board	reset board
change system-parameters customer-options (atm pnc)	status atm-pnc
change atm pnc (pnc duplication)	status cabinet
display atm pnc	status port-network
list atm oam-statistics	test board
list atm pnc	

## Replacing an ATM-EI circuit pack

---

### Standard Reliability

1. Enter **busyout atm-pnc #** (this will affect service) at the DEFINITY SAT.
2. Replace the ATM-PNC circuit pack and re-connect the fiber.
3. Enter **release atm-pnc**.
4. Wait 2.5 minutes for board insertion.
5. Enter **list sys-link** to verify that the links are up.
6. Enter **test board UUCSS** and verify that all tests pass.

### High Reliability

There are 2 ATM-EI circuit packs in the PPN, 1 in the EPN.

1. Enter **busyout atm pnc #** at the DEFINITY SAT.



#### NOTE:

If the ATM-EI is in an EPN, this will affect service.

2. Replace the circuit pack.
3. Enter **release atm pnc**.
4. Wait 2.5 minutes for board insertion.
5. Enter **list sys-link** to verify that the links are up.
6. Enter **test board UUCSS** and verify that all tests pass.

## Critical Reliability

There are 2 ATM-EI circuit packs in the PPN, 2 in the EPN.

1. Enter **status pnc** at the DEFINITY SAT. If the board is on the active side, enter **reset pnc interchange** to switch the active ATM-EI board to the standby side.
2. Enter **busyout pnc-standby**.
3. Enter **busyout atm-pnc # a-pnc** or **b-pnc**.
4. Replace the circuit pack.
5. Enter **release atm pnc #**.
6. Enter **release pnc-standby**.
7. Wait 2.5 minutes for board insertion.
8. Enter **test board UUCSS** and verify that all tests pass.

## Basic ATM PNC administration

---



### NOTE:

This section contains basic administration information only. Refer to *DEFINITY ECS Installation, Upgrade, and Administration for ATM* for more detailed information.

ATM PNC connections involve administering

- 1 ATM-EI board in each Port Network (Standard Reliability)
- 2 ATM-EI boards in the PPN; 1 in each EPN (High Reliability)
- 2 ATM-EI boards in every Port Network (Critical Reliability)

## Adding ATM PNC connections

### Standard Reliability

1. If the ATM-EI circuit pack is not present or if the circuit pack is present but is in an EPN, use the **change circuit-pack** command to add circuit pack translation.
2. Enter **add atm pnc n** (connection number), and administer the circuit pack location and ATM address.

### Critical Reliability

1. Enter **change system-parameters duplication** and change the Enable Operation of PNC Duplication field to **n**.
2. If the ATM-EI circuit pack is not present or is present but it is in an EPN that does not yet have PNC connectivity to it, use the **change circuit-pack** command to add circuit pack translation for the missing circuit pack.

3. Enter **add atm pnc n** (connection number), and administer the circuit pack location and ATM address.
4. Enter **change system-parameters duplication** and change the Enable Operation of PNC Duplication field to **y**.

## Removing ATM PNC connections

### Standard Reliability



#### NOTE:

Standard Reliability systems are *not* equipped with PNC duplication.

1. Enter **busyout atm-pnc n** (connection number)
2. Enter **remove atm-pnc n** (connection number)

### Critical Reliability

1. Enter **status pnc** and ensure that the A-PNC is active. If it is not active, request a PNC interchange using the **reset pnc interchange** command.
2. Enter **busyout pnc-standby**.
3. Enter **change system-parameters duplication** and change the Enable Operation of PNC Duplication field to **n**.
4. Enter **busyout atm-pnc n** (port network number).
5. Enter **remove atm pnc n** (port network number) to remove both ATM-EI boards, or enter **change atm pnc** to remove the B-side ATM-EI board.
6. Enter **change system-parameters duplication** and change the Enable Operation of PNC Duplication field to **y**.

## Changing circuit pack location or ATM address

### Standard Reliability



#### NOTE:

Standard Reliability systems are *not* equipped with PNC duplication.

1. Remove the ATM PNC connection (see [“Removing ATM PNC connections”](#) above).
2. Add an ATM PNC connection (see [“Adding ATM PNC connections”](#) above).

### A-side ATM-EI — Critical Reliability

1. Remove the ATM PNC connection (see [“Removing ATM PNC connections”](#) above).
2. Add an ATM PNC connection (see [“Adding ATM PNC connections”](#) above).

### B-side ATM-EI — Critical Reliability

1. Enter **status pnc** and ensure that the A-PNC is active.  
If it is not active, request a pnc interchange using the **reset pnc interchange** command.
2. Enter **busyout pnc-standby**.
3. Enter **list config car** and verify that an ATM circuit pack is administered for the new location. If it is not, add the ATM circuit pack translations.
4. Enter **busyout atm pnc n** (connection number) **b-pnc**.
5. Enter **change atm pnc n** (connection number) and change circuit pack location for the B side.
6. Enter **release pnc-standby**.

### Changing ATM address of a Standby ATM-PNC EI — Critical Reliability

1. Enter **busy pnc-standby**.
2. Enter **change atm pnc n** (connection number) and change the ATM address for the standby side.
3. Enter **release pnc-standby**.

**Error log entries and test to clear values**

**Table 5-72. ATM-EI Error Log Entries**

Error type	Aux Data	Associated Test	Alarm level	On/Off Board	Test to Clear Value
0 <sup>1</sup>	0	Any	Any	Any	test board UUCSS
2 (a)		None	MIN	ON	
18 (b)	0	busy out board UUCSS	WAR	OFF	release board UUCSS
23 (c)	0	None	WAR	OFF	
125 (d)		None	MIN	ON	
131 (e)		None	MIN	ON	
257-9 (f)	Any	Expansion Interface Control Channel Test (#316)	MAJ	ON	test board UUCSS r 2
513 (g)	Any	ATM Crosstalk Test (#1298)	MIN	ON	test board long UUCSS
769 (h)	34, 35	ATM Board Error Query Test (#1259)	WRN	OFF	test board UUCSS
770 (h)	31	ATM Board Error Query Test (#1259)	WRN	OFF	test board UUCSS
771 (h)	26	ATM Board Error Query Test (#1259)	WRN	OFF	test board UUCSS
1024 - 1151 (i)	Any	None	WRN/ MIN	ON	test board UUCSS
1153 (j)		None	WRN	ON	test board UUCSS
1281 (k)		ATM Board Error Query Test (#1259)	MAJ	OFF	test board UUCSS r 1
1537 (l)	12	None	MIN	ON	
1538 (m)	0	None	MIN	ON	
1793 (n)	13	None	MIN	ON	
2049 (o)	15	None	MIN	OFF	test board UUCSS r 4
2050 (o)		Expansion Interface Lock Query test (#304)	MIN	OFF	test board UUCSS r 4
2305 (p)		None	MIN	ON	

*Continued on next page*

Table 5-72. ATM-EI Error Log Entries — Continued

Error type	Aux Data	Associated Test	Alarm level	On/Off Board	Test to Clear Value
2309 (p)		Packet interface test (#598)	MIN	ON	test board UUCSS r 2
2561 (q)		Expansion Interface 2-way Transmission test (#241)	MAJ	OFF	test board UUCSS r 3
2817 (r)	Any	ATM Board DSP test (#1293)	MIN	ON	test board UUCSS
2818 (r)	Any	None	MIN	ON	test board UUCSS
3329 (s)	3	LANHO critical error	MAJ	OFF	
3585 (t)		ATM Framer Looparound Test (#1260)	MAJ	ON	test board UUCSS I
3586 (t)		ATM Framer Looparound Test (#1260)	MAJ	ON	test board UUCSS I
3841 (u)					
3842 (v)					
3999 (w)	Any	None			
Any	32767 2	None			

1. Run the Short Test Sequence first. If all tests pass, run the Long Test Sequence. Refer to the appropriate test description and follow the recommended procedures.
2. Aux Data 32767 for any error log entry indicates that an alarmed ATM-EI was busied out and then released. When this occurs, existing service-affecting alarms must be preserved. Typically, all alarms are resolved when the ATM-EI is released. Therefore, the Alarm and Error Logs must be repopulated with the alarms present at time of busyout. This Aux Data indicates that existing Error Type and Error Log time stamps are no longer valid because they were lost when the circuit pack was released.

## Notes:

- a. Error Type 2: on-board DUART chip failed. This results in communication failure between the port network's maintenance board and the ATM-EI board. The Maintenance circuit pack should have a red LED lit, because the link to the ATM-EI is down in this EPN.
  1. Reset the board with the **reset board UUCSS** command.
  2. If the board does not recover, replace the board.

- b. Error Type 18: the ATM-EI circuit pack has been busied out.
  - 1. Release the circuit pack (**release board UUCSS**).
- c. Error Type 23: an ATM-EI circuit pack has been administered with the **add atm-pnc n** command, but the circuit pack has not been inserted into the system.
  - 1. Insert an ATM-EI circuit pack at this location.
- d. Error Type 125: a wrong circuit pack is located in the slot where the ATM-EI circuit pack is logically administered.
  - 1. Either remove the wrong circuit pack and insert the ATM-EI circuit pack or remove the ATM-EI administration (see [“Basic ATM PNC administration”](#)).
  - 2. Remove the ATM-INTF administration and re-administer the slot (**change circuit-pack**) to match the circuit-pack that is physically present in this slot.
- e. Error Type 131: an ATM-EI circuit pack has been removed from the slot for 5 minutes.
  - 1. Insert the ATM-EI circuit pack into its administered slot.
  - 2. Another way to resolve or prevent this alarm is to remove the ATM-EI administration (see [“Basic ATM PNC administration”](#)), then remove the ATM-INTF administration (**change circuit-pack**).

It is possible that the ATM-EI could be held in reset by the EPN Maintenance board and is not inserted in the system.

- 1. Try issuing the **test maint P long** command on the maintenance board in the same port network.
- f. Error Type 257: Expansion Interface Control Channel Test #316 failed (board cannot communicate on the TDM bus control channel). Follow the suggested test procedures.

Error Type 258: The archangel is out of sequence (Aux Data indicates angel number).

Error type 259: the expansion archangel link (EAL) to the active ATM-EI board is down. See SYS-LINK.

- g. Error Type 513: ATM Crosstalk test failed. The board is either writing to or reading from a TDM time slot that is not allocated to the board.
  - 1. Test the board (**test board UUCSS**) and follow the test procedures suggested for this test. In random tests of a single DSP during low or high traffic, the same DSP may be tested more than once.

- h. Error Type 769 and 770 (Error Type 771 below): board-degraded alarm errors that result when the ATM switch is sending corrupted cells or excessive AAL/LAPD retransmissions (off-board ATM cell corruption errors). These errors indicate the detection of a problem in handling ATM cells that are received from the fiber interface.

Aux Data:

Error type	Aux Data	Description
769	34	AAL5 Excessive: retransmission requests
769	35	LAPD Excessive: retransmission requests
770	25	ATM Uncorrectable cell headers - threshold
771	26	VPI,VCI pair unknown

The problem is most likely *not* on the ATM-EI circuit pack reporting the errors, but it could be due to one or more of the following reasons:

- The fiber is not snugly connected to either the board or the ATM switch.
- The PN packet bus is corrupting the cells. See Packet maintenance objects (Aux Data 35 only).
- The fiber between the ATM switch and the ATM-EI is too long (greater than 2km for multimode fiber). Use loopback to see if the fiber is corrupting the cells.
- Some other ATM-EI board is not receiving the cells properly.
- The intervening ATM switch is dropping the ATM cells due to a shortage of bandwidth, or the DEFINITY is using more than the subscribed bandwidth.

Error Type 771: the ATM switch is sending cells with unknown VPI and VCI address (wrong connection).

1. Ensure that the ATM-EI board address on the ATM switch matches the ATM-EI (ATM) address on the DEFINITY side.
- i. Error Type 1024-1151: These errors represent problems detected by the ATM-EI board in response to SETUP and ADDPARTY requests from software.
- The Error Types and descriptions are in [Table 5-73](#):
  - Aux Data values represent port network and angel numbers and are in [Table 5-74](#).

Table 5-73. ATM Error types 1024 - 1151

Error Type	Description	General problem
1024	Next node unreachable	ATM protocol stack on ATM-EI circuit pack
1056	DTL Transit not my node ID	
1088 or 1104	ATM-EI circuit pack received a request with an invalid connection identifier.	Firmware-detected problems on the ATM-EI circuit pack. Note: Error Types 1088-1103 are reported by the board that is originating the connection. Error Types 1104-1119 are reported by the board that is terminating the connection. In most cases, when the terminating board reports one of these errors, the originating board will also report an ATM-NTWK error for the same event (usually with Error Type 21).
1089 or 1105	ATM-EI circuit pack received a request with a reference to an unknown VC token.	
1090 or 1106	ATM-EI circuit pack did not have enough resources (memory) for the requested operation.	
1091 or 1107	Internal failure in the local protocol stack. This can occur when the connection to the ATM switch failed, perhaps because the: <ul style="list-style-type: none"> <li>■ ATM switch rebooted</li> <li>■ fiber between the ATM switch and the ATM-EI circuit pack disconnected</li> </ul>	
1092 or 1108	ATM-EI circuit pack received a request for which the referenced VC was in the wrong call state.	
1093 or 1109	ATM-EI circuit pack received a request for which the VPI/VCI pair was invalid or out of range.	
1094 or 1110	ATM-EI circuit pack received a request to add a party to an existing VC. The add party request failed, and a retry was not possible.	
1095 or 1111	ATM-EI circuit pack in link recovery after the lower ATM layer (Q.SAAL portion of the protocol stack) failed. This can occur when the connection to the ATM switch failed, perhaps because the: <ul style="list-style-type: none"> <li>■ ATM switch rebooted</li> <li>■ fiber between the ATM switch and the ATM-EI circuit pack disconnected</li> </ul>	
1096 or 1112	ATM-EI circuit pack received an error from the local protocol stack for which no more detailed cause was specified.	
1102	ATM-EI circuit pack asked to create more connections that it was capable of creating.	
1103	ATM-EI circuit pack detected an illegal message from software. <ol style="list-style-type: none"> <li>1. Check the Error Log for CONN-M proc errors for more information.</li> </ol>	
1113		Problems detected by the board terminating the connection

1. Test the ATM-EI circuit pack (**test board UUCSS**) and investigate further based on each test's results. If all tests pass, the error was a transient problem.

Aux Data values: For each connection request failure type, the port network and the angel number of the destination ATM-EI circuit pack are logged Aux Data values in the form XXYYY, where

- port network number = XX
- angel number = YYY

Since you need to know the slot number also, [Table 5-74](#) converts the Aux Data to slot numbers.

Table 5-74. Error type 1024-1151 Aux Data values (XXYYY) converted to slot number

Slot	Carrier									
	A		B		C		D		E	
	Failure type									
Setup	Add Party									
1	28	528	66	566	98	598	34	534	02	502
2	29	529	67	567	99	599	35	535	03	503
3	30	530	68	568	100	600	36	536	04	504
4	31	531	69	569	101	601	37	537	05	505
5	56	556	70	570	102	602	38	538	06	506
6	57	557	71	571	103	603	39	539	07	507
7	58	558	72	572	104	604	40	540	08	508
8	59	559	73	573	105	605	41	541	09	509
9	60	560	74	574	106	606	42	542	10	510
10	61	561	75	575	107	607	43	543	11	511
11	62	562	76	576	108	608	44	544	12	512
12	63	563	77	577	109	609	45	545	13	513
13	88	588	78	578	110	610	46	546	14	514
14	89	589	79	579	111	611	47	547	15	515
15	90	590	80	580	112	612	48	548	16	516
16	91	591	81	581	113	613	49	549	17	517
17	92	592	82	582	114	614	50	550	18	518

Table 5-74. Error type 1024-1151 Aux Data values (XXYYY) converted to slot number — *Continued*

Slot	Carrier									
	A		B		C		D		E	
	Failure type									
Setup	Add Party									
18	93	593	83	583	115	615	51	551	19	519
19	94	594	84	584	116	616	52	552	20	520
20	95	595	85	585	117	617	53	553	21	521
21	NA	NA	86	586	118	618	54	554	22	522
22	NA	NA	87	587	119	619	55	555	23	523

- j. Error type 1153: the ATM connection audit found some discrepancy in the firmware's VC token numbers and live VCs. The problem is rectified in firmware and no action is needed.
- k. Error Type 1281: loss of high-level signal indicating operational problems of equipment located outside of the circuit pack and the fiber connected to the board. Aux Data values are listed in [Table 5-75](#).

Table 5-75. Error type 1281 Aux Data and repair procedures

Aux Data	Alarm Description	Repair procedure
15	SYSCLOCK failed	<p>The board is not locked to the TDM backplane clock signal. This is probably due to a Tone Clock problem.</p> <ol style="list-style-type: none"><li>1. Check for TDM-BUS or TONE-BD errors in the Error Log.</li><li>2. If no other problems are present, reset the circuit pack (<b>reset board UUCSS</b>)</li></ol>
16	Loss of Signal: LOS	<p>The fiber is not connected properly to the ATM-TRK board or ATM switch (or to the multiplexer section [MUX] if present).It is possible that the board transceivers are not functioning properly.</p> <ol style="list-style-type: none"><li>1. Run <b>test board UUCSS</b> command.</li><li>2. If Test #1259 fails, connect a fiber back-to-back in a looped mode (one strand of fiber connecting the transmit transceiver to the receive transceiver of the board) and see if the yellow LED flash goes away. If it does the problem is off-board.</li><li>3. If the yellow LED continues to flash, replace the circuit pack.</li></ol>
17	Loss of Frame: LOF	<p>The fiber signal cannot obtain or maintain STM-1/OC-3 framing.</p> <ol style="list-style-type: none"><li>1. Try to move the fiber on the ATM switch side to a different port. This may require administration on the ATM switch.</li><li>2. If the problem persists, reset the circuit pack (<b>reset board UUCSS</b>).</li></ol>

*Continued on next page*

Table 5-75. Error type 1281 Aux Data and repair procedures — *Continued*

Aux Data	Alarm Description	Repair procedure
18	Multiplexer Section Alarm Indication Signal: MS_AIS	<p>There is a major problem on the far end (between multiplexer section [MUX] and the switch) that prohibits the circuit pack from sending a valid signal.</p> <ol style="list-style-type: none"><li>1. See if the ports at the MUX and/or the ATM switch are connected snugly.</li><li>2. Run <b>test board UUCSS</b> command</li><li>3. If Test #1259 fails with Error Code 18, connect a fiber back-to-back in a looped mode (one strand of fiber connecting the transmit transceiver to the receive transceiver of the board) and see if the yellow LED flash goes away.</li><li>4. If it does the problem is off-board.</li><li>5. If the yellow LED continues to flash, replace the circuit pack; if the error persists, escalate the problem.</li></ol>
19	Multiplexer Section Remote Defect Indicator: MS_RDI	<p>The far-end is detecting a major problem with the signal that this board is transmitting.</p> <ol style="list-style-type: none"><li>1. Make sure the ATM switch port (or a MUX port, if present between ATM switch and the ATM-TRK board) is the same as the ATM-TRK circuit pack's cable interface</li><li>2. Run <b>test board UUCSS</b> command.</li><li>3. If Test #1259 fails with Error Code 19, connect a fiber back-to-back in a looped mode (one strand of fiber connecting the transmit transceiver to the receive transceiver of the board) and see if the yellow LED flash goes away.</li><li>4. If it does the problem is off-board.</li><li>5. If the yellow LED continues to flash, replace the circuit pack; if the error persists, escalate the problem.</li></ol>
20	Loss of pointer: LOP	<p>ATM framer chip is unable to access the payload part of the signal.</p> <ol style="list-style-type: none"><li>1. Reset the board (<b>reset board UUCSS</b>).</li><li>2. If the error persists replace the board.</li></ol>

*Continued on next page*

Table 5-75. Error type 1281 Aux Data and repair procedures — *Continued*

Aux Data	Alarm Description	Repair procedure
21	Path Signal Error (PSL) (STM1/SONET)	<p>The incoming signal payload is not set up for transmission of ATM data.</p> <ol style="list-style-type: none"><li>1. Make sure the ATM switch port (or a MUX port, if present between ATM switch and the ATM-TRK board) is the same as the ATM-TRK circuit pack's cable interface.</li></ol>
22	High-level Path Alarm Indication Signal: HP_AIS	<p>The payload is invalid.</p> <ol style="list-style-type: none"><li>1. Make sure the ATM switch port (or a MUX port, if present between ATM switch and the ATM-TRK board) is the same as the ATM-TRK circuit pack's cable interface.</li><li>2. Run <b>test board UUCSS</b>.</li><li>3. If Test #1259 fails with Error Code 22, connect a fiber back-to-back in a looped mode (one strand of fiber connecting the transmit transceiver to the receive transceiver of the board) and see if the yellow LED flash goes away.</li><li>4. If it does the problem is off-board.</li><li>5. If the yellow LED continues to flash, replace the circuit pack.</li></ol>
23	High-level path Remote defect Indicator: HP_RDI	<p>The far-end is detecting a major problem with the signal that this board is transmitting. The transmitted payload is invalid.</p> <ol style="list-style-type: none"><li>1. Make sure the ATM switch port (or a MUX port, if present between ATM switch and the ATM-TRK board) is the same as the ATM-TRK circuit pack's cable interface.</li><li>2. Run <b>test board UUCSS</b> command; if the Test #1259 fails with Error Code 23, connect a fiber back-to-back in a looped mode (one strand of fiber connecting the transmit transceiver to the receive transceiver of the board) and see if the yellow LED flash goes away.</li><li>3. If it does the problem is off-board.</li><li>4. If the yellow LED continues to flash, replace the circuit pack.</li></ol>

*Continued on next page*

Table 5-75. Error type 1281 Aux Data and repair procedures — *Continued*

Aux Data	Alarm Description	Repair procedure
24	Loss of cell delineation (LCD)	<p>On board ATM framer chip is not able to frame cells based on the cell header.</p> <ol style="list-style-type: none"> <li>1. Reset the board (<b>reset board UUCSS</b>).</li> <li>2. If the error persists, replace the board.</li> </ol>
27	SIGCON_DOWN ATM switch high level signal.	<p>The board cannot communicate with the ATM switch.</p> <ol style="list-style-type: none"> <li>1. Busyout the board (busyout board UUCSS).</li> <li>2. Test the board (<b>test board long UUCSS</b>).</li> <li>3. If Test #1260 fails, replace the board.</li> <li>4. If Test #1260 passes, make sure the ATM address on both the DEFINITY and the ATM switch sides are the same for this board.</li> <li>5. If the address is the same, change the port on the ATM switch side. This may require administration on the ATM switch.</li> <li>6. If the error is resolved, the problem is on the ATM switch port.</li> </ol>

- l. Error Type 1537: LAN bus time out. The circuit pack is transmitting a packet larger than 1,024 bytes. Replace the circuit pack.
- m. Error Type 1538: A hyperactive ATM-EI circuit pack is generating an abnormal amount of control messages to the processor. When this error is generated, the system automatically resets the ATM-EI.

Duplicated PNC?	Then:
Y	service to the EPN is disrupted
N	the system switches to the standby PNC

1. Enter the **reset board UUCSS** command for this ATM-EI circuit pack.
2. If the same error persists, replace the ATM-EI circuit pack.

- n. Error Type 1793: LANHO transmit FIFO overflow error (the transmit FIFO RAM buffers on the circuit pack overflowed). This most likely indicates a hardware problem on the circuit pack, because the speed of the LAN/Packet Bus is much higher than the speed of the link connected to the port.
  - 1. Test this ATM-EI circuit pack (**test board UUCSS**).
  - 2. If Test #598 fails again, replace the ATM-EI circuit pack.
- o. Error Type 2049, 2050: the ATM-EI is out of lock with the backplane system clock.
  - 1. Test this ATM-EI circuit pack (**test board UUCSS**).
  - 2. If Test #304 fails, follow the repair procedures suggested for this test.
- p. Error Type 2305: too many parity errors on data received from the LAN/Packet Bus (could be due to packet bus problems).
  - 1. Test the ATM-EI circuit pack (**test board UUCSS**).
  - 2. If Test #598 fails, follow the repair procedures suggested for this test.
  - 3. If the test passes, look for and resolve any [“PKT-BUS \(Packet Bus\)”](#) alarms/errors.
  - 4. If there are no [“PKT-BUS \(Packet Bus\)”](#) errors and the problem persists, escalate the problem.

Error Type 2309: packet interface chip (LANHO) malfunctioning.

- 1. Test the ATM-EI circuit pack (**test board UUCSS**).
  - 2. If Test #598 fails, follow the repair procedures suggested for this test.
- q. Error Type 2561: ATM-EI 2-way Transmission Failure (circuit pack is having problems creating connections to other port networks in the system).
    - 1. Test the ATM-EI circuit pack (**test board UUCSS**).
    - 2. Follow the repair procedures suggested for Test #241.

- r. Error Type 2817, 2818: DSP test failure detected along the circuit path of the ATM-EI circuit pack.

Error type	Description	Aux Data indicates
2817	DSP test failure	The Aux Data field contains the following information about the failed DSPs: <ul style="list-style-type: none"> <li>■ X is the number of talker DSPs</li> <li>■ Y is the number of listener DSPs</li> <li>■ Z is the number of echo-cancelling DSPs</li> </ul>
2818	One or more DSPs failed	DSP number that has failed

1. Test the ATM-EI circuit pack (**test board UUCSS**).
  2. Follow the repair procedures suggested for Test #1258.
- s. Error Type 3329: on-board LANHO chip is insane, possibly due to a problem in Packet Bus arbitration, the transmission line frame, or the circuit pack itself. The circuit pack cannot talk to the packet bus.

If the packet bus is alarmed:

1. Resolve "[PKT-BUS \(Packet Bus\)](#)" errors, if any. The probability of this error being related to Packet bus problem increases with the number of other circuit packs using the Packet bus that are also displaying this error.

If the Packet Bus is *not* alarmed:

1. Reset the circuit pack (**reset board UUCSS**).
2. If the problem persists, replace the ATM-EI circuit pack.

If the system has a duplicated PNC, and the in-line error received is from an active ATM-EI, the system switches to the standby PNC.



**CAUTION:**

*If the system does not have duplicated PNC, services to the EPN could be disrupted.*

- t. Error Type 3585, 3586 (Major board alarm): failure of critical components involved in the operation of the circuit pack, and the switch may no longer recognize the circuit pack. If the system has a duplicated PNC and the in-line error received is from an active ATM-EI, the system switches to standby PNC.

**CAUTION:**

*If the system does not have duplicated PNC, services to the EPN could be disrupted.*

Error Type 3585:

Aux Data (Error Type 3585 only):

Aux Data	Description
1	ATM framer failure
2	NCE failed (only from ATM-EIs in EPN)
4	TDM_PLD_FAILED
5	DSP_ALL FAILED
6	Receive Network Processor (RNP) failure
7	Transmit Network Processor (TNP) failure
8	MEMORY read/write failure

1. If the board is in a PPN, or if the system has duplicated PNC:
  - a. Test the ATM-EI (**test board UUCSS I**).
  - b. If Error 3585 is detected again, or if the board is not recognized anymore, replace the ATM-EI circuit pack.
2. If the system does *not* have duplicated PNC, and the circuit pack is in an EPN:
  - a. Replace the ATM-EI circuit pack.

Error Type 3586: Framer Looparound Test #1260 failed.

Aux Data (Error Code 3586 only):

Aux Data	Description
2	Packet path failed
3	Circuit path failed
4	TDM loop cannot be created
5	Packet loop cannot be created

1. If Error Type 3586 is detected again, replace the circuit pack.
- u. Error Type 3841: the board received a message from the switch that it does not recognize, and the board responded with an inconsistent down link error message. This error does not affect service, and no action is required.
  - v. Error type 3842: the circuit pack received data from the Packet Bus faster than it could distribute the data to its endpoint. This circuit pack should be able to recover by itself, and no action is necessary.
  - w. Error Type 3999: circuit pack sent a large number of control channel messages to the switch within a short period of time.

If	Then
Error Type 1538 is also present	Circuit pack is taken out of service
If Error Type 1538 is not present	<p>Circuit pack is <i>not</i> taken out of service, but has generated 50% of the messages necessary to be considered hyperactive.</p> <ul style="list-style-type: none"> <li>■ This may be normal during heavy traffic.</li> <li>■ If the error is logged during light traffic, it may indicate a problem with the circuit pack or the equipment attached to it.</li> </ul>

## System Technician-Demanded Tests: Descriptions and Error Codes

Always investigate tests in the order presented in [Table 5-76](#) when inspecting the errors in the system. By clearing error codes associated with the Expansion Interface Test, for example, you may also clear errors generated from other tests in the testing sequence.

**Table 5-76. System Technician-Demanded Tests: ATM-EI**

Order of investigation	Short Test Sequence	Long Test Sequence	Reset Board Sequence	D/ND <sup>1</sup>
Expansion Interface 2way-Transmission Test (#241)	X	X		ND
ATM Board Frammer Looparound Test (#1260)		X		D
Expansion Interface Lock Query Test (#304)	X	X		ND
ATM Board Error Query Test (#1259)	X	X		ND
ATM Expansion Interface Reset (#1256)			X	D
ATM board DSP test(#1293) for TN2305 and TN2306 circuit packs.	X	X		ND
ATM Cross Talk test(#1298) for TN2305 and TN2306 circuit packs		X		ND

1. D = Destructive, ND = Non-destructive

**NOTE:**


To get a better indication of a problem's location, test both ATM-EI circuit packs on the associated fiber link, whether the circuit packs are both ATM-EI circuit packs or not.

## Expansion Interface 2-way Transmission Test (#241)

This test is non-destructive and applies to all ATM-EIs, both active and standby. It is run as part of craft short and long testing, periodic, scheduled, initialization, and error analysis testing. The test sets up a connection between a Tone/Clock in one cabinet and a Tone Detector in a separate cabinet and transmits a digital test count between the port networks. The ATM-EIs used to set up this connection are chosen by maintenance, not call processing. After the connection is checked for dial-tone, the connection is torn down and re-established in the opposite direction.

In this test the second ATM-EI may be in any port network outside the port network of the ATM-EI under test. Therefore if the test should fail in any direction, the test is repeated with a different port network, if available, which aids the fault isolation procedure.

The test results indicate if the test failed in one or both directions. The test aborts if the ATM-EIs do not exist on both ends (for example, the EIs are not administered correctly). If the test passes, the TDM and ATM framer interfaces of both ATM-EIs are functioning properly. If the test fails, a series of tests are run on the board. [Figure 5-6](#) shows a schematic of this test.



---

**Figure 5-6. Expansion Interface 2-Way Transmit Test #241**  
PN X and PN Y represent any of 43 possible port networks.

Table 5-77. Expansion Interface 2-way Transmission Test (#241)

Error Code	Test Result	Description/ Recommendation
	ABORT	<p>Could not allocate the necessary system resources to run this test.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals for a maximum of 5 times.</li> </ol>
1002	ABORT	<p>The system could not allocate time slots for the test. The system may be under heavy traffic conditions or it may have time slots out of service due to TDM-BUS errors.</p> <ol style="list-style-type: none"> <li>1. If system has no TDM-BUS errors and is not handling heavy traffic, retry the command at 1-minute intervals a maximum of 3 times.</li> </ol>
1003	ABORT	<p>The system could not allocate a tone receiver for the test. The system may be oversized for the number of tone detectors present, or some tone detectors may be out of service.</p> <ol style="list-style-type: none"> <li>1. Resolve any TTR-LEV errors. Even if there are not TTR-LEV errors, there may not be a tone detector available on the network that contains the circuit pack being tested. Verify that there is at least one tone detector on this network. If not, this test always aborts for this ATM-EI circuit pack, but does not harm the system.</li> </ol> <p> <b>NOTE:</b> DEFINITY Systems require that Tone Clock circuit packs (TN2182) must be of vintage "B" or newer. If older Tone Detector circuit packs are installed in the system, this test always aborts with this abort code.</p> <ol style="list-style-type: none"> <li>2. Resolve any TONE-PT errors.</li> <li>3. If neither condition exists, retry the command at 1-minute intervals a maximum of 3 times.</li> </ol>

*Continued on next page*

Table 5-77. Expansion Interface 2-way Transmission Test (#241) — *Continued*

Error Code	Test Result	Description/ Recommendation
1033	ABORT	<p>The test cannot run because either the ATM-EI board is not administered, or there were no other PNs administered that had its ATM-EI board in-service.</p> <ol style="list-style-type: none"> <li>1. Ensure that the board is administered as ATM PNC Expansion Interface circuit pack.  If the board is administered as ATM-EI circuit pack, then there has been some change in the ability of the ATM-EI circuit pack in the other PNs to communicate with the ATM-EI on the other end of its connection.</li> <li>2. Using <b>status port x</b> (the port-network number in which the board is administered), see if both ACL and EAL are up to this board. If they are not, see the service procedure for SYS-LINK.</li> <li>3. Check the Error Log for Error Type 1281 with Aux Data 27 (board cannot talk to the ATM switch). See <a href="#">Table 5-75</a> for repair procedures.  If present, check both the ATM switch and the DEFINITY administrations for consistent ATM addresses. Reset the board and see if the problem resolves.</li> <li>4. Repeat Test #241. If it continues to abort with this abort code, replace the board.</li> </ol>
1394	ABORT	<ol style="list-style-type: none"> <li>1. See <a href="#">Table 5-75</a> (Error Type 1281) with Aux Data 27 (board cannot talk to the ATM switch), and if present, check both the ATM switch and the DEFINITY administrations for consistent ATM addresses.</li> <li>2. Reset the board and see if the problem resolves.</li> <li>3. Repeat the test.</li> </ol>
1395	ABORT	<p>This test cannot run on an ATM-EI circuit pack if it is part of the B-side PNC and Duplicated PNC is not enabled.</p> <ol style="list-style-type: none"> <li>1. If this test needs to run on this ATM-EI circuit pack, enable PNC with the <b>change system-parameters duplication</b> command.</li> <li>2. Prevent the system from doing a PNC interchange by executing the <b>set PNC lock</b> command.</li> <li>3. Repeat this test.</li> </ol>

*Continued on next page*

Table 5-77. Expansion Interface 2-way Transmission Test (#241) — *Continued*

Error Code	Test Result	Description/ Recommendation
1413	ABORT	<p>This test requires the use of a Tone/Clock circuit pack in each of the port networks (PN) used in this test. This abort code indicates that a Tone/Clock circuit pack is not present in one of the PNs.</p> <ol style="list-style-type: none"><li>1. Make sure that there is a Tone/Clock circuit pack located in the PN in which the ATM PNC Expansion Interface circuit pack under test is located.</li><li>2. In ATM PNC configurations, make sure that there is at least one other PN besides the PN where the ATM-EI circuit pack under test resides that contains a Tone/Clock circuit pack.</li></ol>
1414	ABORT	<p>The active Tone/Clock circuit pack in one of the port networks being used for the test has a MAJOR or MINOR alarm logged against it.</p> <ol style="list-style-type: none"><li>1. Enter <b>display alarms</b> and resolve any TONE-BD and TONE-PT alarms.</li></ol>
1956	ABORT	<p>ACL to the board is not up. See ACL status with the <b>list sys-link</b> command and follow the repair procedures for SYS-LINK.</p>
2000	ABORT	<p>Response to the test request was not received within the allowable time period.</p>
2100	ABORT	<p>System resources required to run this test are not available.</p>
2500	ABORT	<p>Internal system error</p> <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 3 times.</li></ol>
	FAIL	<p>The test tone was not detected correctly in either direction.</p> <ol style="list-style-type: none"><li>1. Test the active Tone/Clocks on the Port Networks for which the ATM-EI circuit pack under test provides a link. This determines if the dial tone is supplied.</li></ol>

*Continued on next page*

Table 5-77. Expansion Interface 2-way Transmission Test (#241) — *Continued*

Error Code	Test Result	Description/ Recommendation
10MM	FAIL	<p>The failure codes only apply to a system equipped with an ATM Switch. The letters “MM” refer to the distant or far-end port network (PN), and “NN” to the near-end ATM-EI under test.</p> <p>The test tone was detected correctly in forward direction (data sent from the PN in which the circuit pack under test resides and detected correctly in port network MM), but not the opposite direction.</p> <ol style="list-style-type: none"><li>1. Test the active Tone/Clocks on the “MM” PN and the PN in which the ATM-EI under test resides (<b>test tone-clock UUCSS</b>). This determines if a dial tone is supplied.</li><li>2. Ensure that the ATM address of the ATM-EI circuit pack under test matches the ATM address on the ATM switch for the port to which this circuit pack is connected. Refer to the “ATM Tips” section in Chapter 1 of <i>DEFINITY Enterprise Communications System R 8.2 Maintenance (555-233-119)</i> for the procedure to check the ATM port address on the ATM switch.</li><li>3. Run this Test #241 on the active ATM-EI in port network MM. If this test fails with Error Code 10NN or 30NN, go back to Step 2.</li></ol> <p>If the address was the same, replace the active ATM-EI circuit pack on port network MM.</p> <p>If this test fails with Error Code 20NN or 40NN, replace ATM-EI circuit pack that had the initial problem.</p>

---

*Continued on next page*

Table 5-77. Expansion Interface 2-way Transmission Test (#241) — *Continued*

Error Code	Test Result	Description/ Recommendation
20MM	FAIL	<p>The failure codes only apply to a system equipped with an ATM Switch. The letters “MM” refer to the distant or far-end port network (PN), and “NN” to the near-end ATM-EI under test.</p> <p>The test tone was detected correctly in reverse direction (data sent from the MM port network was detected correctly in the port network in which the circuit pack under test resides, but not the opposite direction).</p> <ol style="list-style-type: none"><li>1. Test the active Tone/Clock on the “MM” PN and the PN in which the ATM-EI under test resides (<b>test tone-clock UUCSS</b>). This determines if dial tone is supplied.</li><li>2. Ensure that the ATM address of the active ATM-EI circuit pack under test matches the ATM address on the ATM switch for the port to which this circuit pack is connected. Refer to the “ATM Tips” section in Chapter 1 for the procedure to check the ATM port address on the ATM switch.</li><li>3. Run this Test #241 on the active ATM-EI in port network MM. If this test fails with Error Code 20NN or 40NN, go back to Step 2.</li></ol> <p>If the address was the same, replace the active ATM-EI circuit pack on port network MM.</p> <p>If this test fails with Error Code 10NN or 30NN, replace ATM-EI circuit pack with the initial problem.</p>

---

*Continued on next page*

Table 5-77. Expansion Interface 2-way Transmission Test (#241) — *Continued*

Error Code	Test Result	Description/ Recommendation
30MM	FAIL	<p>The failure codes only apply to a system equipped with an ATM Switch. The letters “MM” refer to the distant or far-end port network (PN), and “NN” to the near-end ATM-EI under test.</p> <p>The test failed for the first connection from the ATM-EI board under test to another EPN, and the test tone was detected correctly in the forward direction (data sent from the port network in which the circuit pack under test resides was detected correctly in port network MM, but not the opposite direction).</p> <ol style="list-style-type: none"><li>1. Test the active Tone/Clock on the “MM” PN and the PN in which the ATM-EI under test resides (<b>test tone-clock UUCSS</b>). This determines if dial tone is supplied.</li><li>2. Ensure that the ATM address of the ATM-EI circuit pack under test matches the ATM address on the ATM switch for the port to which this circuit pack is connected. Refer to the “ATM Tips” section in Chapter 1 of <i>DEFINITY Enterprise Communications System R 8.2 Maintenance</i> (555-233-119) for the procedure to check the ATM port address on the ATM switch.</li><li>3. Run this Test #241 on the active ATM-EI in port network MM. If this test fails with Error Code 10NN or 30NN, go back to Step 2.</li></ol> <p>If the address was the same, replace the active ATM-EI circuit pack on port network MM.</p> <p>If this test fails with Error Code 20NN or 40NN, replace ATM-EI circuit pack with the initial problem.</p>

---

*Continued on next page*

Table 5-77. Expansion Interface 2-way Transmission Test (#241) — *Continued*

Error Code	Test Result	Description/ Recommendation
40MM	FAIL	<p>Failure code only applies to a system equipped with an ATM Switch. The letters “MM” refer to the distant or far-end port network (PN), and “NN” to the near-end ATM-EI under test.</p> <p>The test failed for the first connection from the ATM-EI board under test to another EPN, and the test tone was detected correctly in the reverse direction (data sent from the MM port network was detected correctly in the port network in which the circuit pack under test resides), but not the opposite direction.</p> <ol style="list-style-type: none"> <li>1. Test for the Active Tone-Clocks on the MM PN and the PN in which the ATM-EI under test resides. This determines if dial tone is supplied.</li> <li>2. Ensure that the ATM address of the active ATM-EI circuit pack in port network MM matches the ATM address on the ATM switch for the port to which this circuit pack is connected. Refer to the “ATM Tips” section in Chapter 1 of <i>DEFINITY Enterprise Communications System R 8.2 Maintenance (555-233-119)</i> for the procedure to check the ATM port address on the ATM switch.</li> <li>3. Run this Test #241 on the active ATM-EI in port network MM. If this test fails with Error Code 20NN or 40NN, go back to Step 2.</li> </ol> <p>If the address was the same, replace the active ATM-EI circuit pack on port network MM.</p> <p>If this test fails with Error Code 10NN or 30NN, replace ATM-EI circuit pack with the initial problem.</p>
	PASS	Tone successfully transmitted in both directions. Both ATM-EI boards and their lightwave transceivers are functioning properly.
0	NO BOARD	<p>No board was detected by the test.</p> <ol style="list-style-type: none"> <li>1. Resolve either wrong board (Error 125) or no board (Error 131) issues.</li> <li>2. Check that the board is properly translated and inserted. If so, check for hyperactivity (Error 1538). If hyperactive, use the <b>reset board UUCSS</b> command.</li> <li>3. Run the test again. If it fails, the ID chip on board may be bad. Replace the board and retest.</li> </ol>

**Expansion Interface Lock Query Test (#304)**

This test is non-destructive and is used to query the ATM and EI circuit packs (both active and standby) for its status concerning lock to the backplane system clock. It is run as part of periodic, scheduled, initialization, and error analysis testing. When an in-line, "out-of-lock" report comes in, this test is run to check the circuit pack's status. The ATM-EI responds with "in lock" or "out of lock." If the response is "in lock," the test passes; if the response is "out of lock," the test fails.

**Table 5-78. TEST #304 Expansion Interface Lock Query Test (#304)**

<b>Error Code</b>	<b>Test Result</b>	<b>Description/ Recommendation</b>
2000	ABORT	Response to the test request was not received within the allowable time period.
2100	ABORT	Could not allocate the necessary system resources to run this test.
2500	ABORT	Internal system error 1. Retry the command at 1-minute intervals a maximum of 3 times.
	FAIL	The ATM-EI circuit pack responded incorrectly or if it is the EPN active ATM-EI circuit pack, it could not talk to EPN circuit packs. 1. If the active ATM-EI circuit pack in the EPN is failing and duplicated PNC is enabled, attempt to switch to the standby PNC using the <b>reset PNC interchange</b> command. 2. Repeat the short test sequence. 3. If test continues to fail, reset the ATM-EI circuit pack with the <b>reset board UUCSS</b> command. 4. If the ATM-EI circuit pack in the EPN is failing, enter <b>display errors</b> and <b>display alarms</b> and follow the associated repair procedures for TDM-CLK, TONE-BD, or SYNC alarms/errors and repeat the Short Test Sequence. 5. If test continues to fail, replace the circuit pack or transceiver.
	PASS	Communication from software to the ATM-EI circuit pack is functioning correctly.

*Continued on next page*

Table 5-78. TEST #304 Expansion Interface Lock Query Test (#304) — *Continued*

Error Code	Test Result	Description/ Recommendation
0	NO BOARD	<p>No board was detected by the test.</p> <ol style="list-style-type: none"> <li>1. Check the error log for wrong board (error 125) or no board (error 131). Resolve either of these issues.</li> <li>2. Check that the board is properly translated and inserted. If so, check for hyperactivity (error 1538). If hyperactive, use the <b>reset board UUCSS</b> command.</li> <li>3. Run the test again. If it fails, the NCE chip on board may be bad. Replace the board and retest.</li> </ol>

### Expansion Interface Control Channel Test (#316)

This test is non-destructive. If an ATM-EI circuit pack is an *active* ATM-EI in the EPN (yellow LED on long/off short), the Expansion Interface Control Channel test checks to see if the ATM-EI circuit pack can communicate with other circuit packs in the EPN using the EPN TDM bus.

If the circuit pack is a *standby* ATM-EI (yellow LED off) or if the ATM PNC Expansion Interface is in the PPN (yellow LED on), this test queries the ATM PNC Expansion Interface circuit pack for its circuit pack type and vintage information.

Table 5-79. Expansion Interface Control Channel Test #316

Error Code	Test Result	Description/ Recommendation
2000	ABORT	Response to the test request was not received within the allowable time period.
2100	ABORT	Could not allocate the necessary system resources to run this test.
2500	ABORT	<p>Internal system error</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 3 times.</li> </ol>

*Continued on next page*


Table 5-79. Expansion Interface Control Channel Test #316 — *Continued*

Error Code	Test Result	Description/ Recommendation
	FAIL	<p>The ATM-EI circuit pack responded incorrectly or if it is the EPN active ATM-EI circuit pack, it could not talk to EPN circuit packs.</p> <ol style="list-style-type: none"><li>1. If the active ATM-EI circuit pack in the EPN is failing and duplicated PNC is enabled, attempt to switch to the standby PNC using the <b>reset PNC interchange</b> command.</li><li>2. Repeat the short test sequence.</li><li>3. If test continues to fail, reset the ATM-EI circuit pack with the <b>reset board UUCSS</b> command.</li><li>4. If the ATM-EI circuit pack in the EPN is failing, enter <b>display errors</b> and <b>display alarms</b> and resolve any TDM-CLK, TONE-BD, or SYNC alarms/errors and repeat the Short Test Sequence.</li><li>5. If test continues to fail, replace the circuit pack or transceiver.</li></ol>
	PASS	<p>The ATM-EI circuit pack did respond correctly to test. Communication from software to the ATM-EI circuit pack is functioning.</p> <ol style="list-style-type: none"><li>1. Refer to other ATM-EI circuit pack tests if the link is not functioning correctly.</li></ol>
0	NO BOARD	<p>No board was detected by the test.</p> <ol style="list-style-type: none"><li>1. Resolve any wrong board (Error 125) or no board (Error 131) issues.</li><li>2. Check that the board is properly translated and inserted. If so, check for hyperactivity (Error 1538). If hyperactive, use the <b>reset board UUCSS</b> command.</li><li>3. Run the test again. If it fails, the NCE chip on board may be bad. Replace the board and retest.</li></ol>

## Packet Interface Test (#598)

This test is non-destructive and attempts to send a data packet from the TN1655 Packet Interface circuit pack through any ATM PNC Expansion Interface circuit packs. The path the data packet takes depends on the location of the ATM-PNC Expansion Interface circuit pack being tested and whether the system has duplicate Port Network Connectivity.

The Packet Interface Looparound test checks the Packet Bus interface circuitry on this board. The on-board LANHO chip sends a data stream to the bus, retrieves it back, and checks for its consistency. If the data is consistent, the test passes; otherwise, it fails. The test aborts if the Packet Bus in the specified port network has a minor alarm active, is out of service, or if the Packet Bus in the PPN is out of service. This test runs as a part of initialization, periodic, scheduled, error analysis, and demand test sequences. [Figure 5-7](#) shows a schematic of the test.



**Figure 5-7. Packet Interface Test (#598)**

Table 5-80. Packet Interface Test (#598)

Error Code	Test Result	Description/ Recommendation
2000	ABORT	Response to the test request was not received within the allowable time period. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals for a maximum of 3 retries.</li><li>2. If the test fails repeatedly, attempt to reset the circuit pack.</li><li>3. If the test continues to fail, replace the circuit pack.</li></ol>
2012	ABORT	Internal system error
2100	ABORT	Could not allocate the necessary system resources to run this test. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
ANY	FAIL	The transmitted data packet was not received correctly by the Packet Interface circuit pack. The failure may be in the ATM-EI under test, the DS1 CONV circuit packs, or the intervening Center Stage components. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of five times</li><li>2. If the test continues to fail, replace the circuit pack.</li></ol>
	PASS	The Packet Interface Test passed.

### ATM Board Error Query Test (#1259)

This test is non-destructive. The ATM circuit pack firmware maintains counters for some of the on-board and off-board errors. The maintenance software queries the board for its health information to do error analysis. These alarms have assigned priority: if a higher priority alarm occurs, the remaining alarms are not reported to the software (through the inline errors), avoiding unnecessary up-link, in-line error message traffic. This is run as a part of a craft demand test sequence periodic testing, initialization, and error analysis.

Table 5-81. ATM Board Error Query Test (#1259)

Error Code	Test Result	Description/ Recommendation
2000	ABORT	Response to the test was not received within the allowable time period.
2100	ABORT	System resources required to run this test are not available.
2500	ABORT	Internal system error 1. Retry the command at 1-minute intervals a maximum of 3 times.
XXYY	FAIL	On-board hardware or off-board signalling errors on the board. XX indicates the on-board hardware error, and YY indicates the off-board errors on the as shown in <a href="#">Table 5-82</a> . 1. Resolve any errors in error logs.
	PASS	No service effecting errors or alarms were detected on the circuit pack.
0	NO BOARD	No board was detected by the test. 1. Check the Error Log for wrong board (Error Type 125) or no board (Error Type 131). Resolve either of these issues, if applicable. 2. Check that the board is properly translated and inserted. If so, check for hyperactivity (Error Type 1538). If hyperactive, use the <b>reset board UUCSS</b> command. 3. Run the test again. If it fails, the NCE chip on board may be bad. Replace the board and retest.

Table 5-82. XXYY Error Codes for Test #1259  
(ATM Board Error Query Test)

XX Aux Data	Description
1	ATM framer chip failed
2	NCE chip failed
3	LANHO critical error
4	TDM Prog. logic device failed

Continued on next page

**Table 5-82. XYYY Error Codes for Test #1259**  
(ATM Board Error Query Test) — *Continued*

<b>XX Aux Data</b>	<b>Description</b>
5	All on-board DSPs failed
6	Receive network processor failed
7	Transmit network processor failed
8	Memory read failed
9	Dual UART chip failed
10	LANHO receive parity error
11	LANHO FIFO overflow error
12	LAN Bus timeout
13	LANHO Xmit FIFO overflow
14	One or more on-board DSPs failed
<b>YY Aux Data</b>	<b>Description</b>
15	Backplane clock failed
16	Loss of signal
17	Loss of frame
18	Multiplexer Section Alarm indication signal error
19	Multiplexer Section remote defect indicator error
20	Loss of pointer
21	Path signal level mismatch
22	High level path alarm indication signal
23	High level path remote defect indicator
24	Loss of cell delineation
25	Uncorrectable headers sent by the ATM switch
26	Too many cells with invalid Virtual Path Indicator (VPI)/Virtual Circuit Indicator (VCI) combination
27	The signalling link between the board and the ATM switch is down.

*Continued on next page*

**Table 5-82. XYYY Error Codes for Test #1259**  
(ATM Board Error Query Test) — *Continued*

XX Aux Data	Description
28	Board to the ATM switch connection is down
34	AAL5 (ATM signalling protocol) excessive retransmission requests
35	LAPD excessive retransmission requests

## ATM Board Framer Looparound Test (#1260)


**This test is destructive.**

### ⇒ NOTE:

This test can be run on the standby PNC only if the board is busied out.

This test places the ATM circuit pack in ATM framer looparound mode. Once the board receives this message, it creates a dummy virtual circuit that originates and ends on the same board, without leaving the board. This test verifies both the TDM path and the Packet Path. If the TDM test path passes, then the packet path is tested. Definitions of each test path are:

- **The circuit (TDM) path:** one of the tone generators sends a bit pattern through a TDM bus time slot to the ATM framer. The pattern is converted into ATM cells and looped back to the ATM-EI board, which converts the cell back into the bit pattern and puts it on a pre-determined time slot. A tone detector tests for the bit pattern and reports the test result. This test verifies that a large portion of the ATM-EIs circuit paths are functioning correctly. [Figure 5-8](#) shows a diagram of the test.




**Figure 5-8. ATM Board Framer Looparound Test (#1260)**

- **Packet path:** the Packet Interface circuit pack sends packet data to the ATM framer interface, where it is mapped into ATM cells and then looped around internally. The cells are converted back to packet data after it has been looped. This portion of the test verifies correct operation of the ATM-EI's Packet bus interface and a large portion of the ATM-EI's packet paths. [Figure 5-9](#) shows the packet switched signal path for the ATM circuit pack.

This test verifies the operation of a large portion of the ATM-EI circuit and packet paths, but does not verify the optical portion of the lightwave transceiver. If this test passes, the ATM-EI circuit pack is functioning correctly, but faults may exist in the lightwave transceiver. If the test fails, the fault may lie on the board. After the test results are reported, the ATM framer is taken out of loopback.

**⇒ NOTE:**

This test may be run on active or standby ATM-EIs, but it is *not* allowed if an ATM-EI is the Expansion Archangel.



**Figure 5-9. ATM Board Framer Looparound Test (#1260)  
(non-EAA, Packet Path)**

Table 5-83. ATM Board Framer Looparound Test (#1260)

Error Code	Test Result	Description/ Recommendation
1002	ABORT	<p>The system could not allocate timeslots for the test. The system may be under heavy traffic conditions or it may have timeslots out of service due to TDM-BUS errors.</p> <ol style="list-style-type: none"> <li>1. If system has no TDM-BUS errors and is not handling heavy traffic, retry the command at 1-minute intervals a maximum of 3 times.</li> </ol>
1003	ABORT	<p>The system could not allocate a tone receiver for the test. The system may be oversized for the number of Tone Detectors present or some Tone Detectors may be out of service.</p> <ol style="list-style-type: none"> <li>1. Resolve any TTR-LEV errors. Even if there are no TTR-LEV errors, there may not be a Tone Detector available on the network that contains the circuit pack being tested. Verify that there is at least one Tone Detector on this network. If there is not at least one Tone Detector, this test always aborts for this ATM-EI board. This will not harm the system.</li> </ol> <p> <b>NOTE:</b> DEFINITY Systems require that Tone Clock circuit packs (TN2182) must be of vintage "B" or newer. If older Tone Detector circuit packs are installed in the system, this test always aborts with this abort code.</p> <ol style="list-style-type: none"> <li>2. Resolve any TONE-PT errors.</li> <li>3. If neither condition exists, retry the command at 1-minute intervals a maximum of 3 times.</li> </ol>
1015	ABORT	<p>The ATM-EI circuit pack has not been busied out.</p> <ol style="list-style-type: none"> <li>1. Busyout the ATM-Expansion Interface circuit pack, then repeat the <b>test board UUCSS long</b> command.</li> </ol>
1031	ABORT	<p>If the ATM Expansion Interface circuit pack is in an EPN and is on the active PNC, this test cannot be executed.</p> <ol style="list-style-type: none"> <li>1. If PNC Duplication is enabled, attempt to make the standby PNC active with the <b>reset pnc interchange</b> command.</li> <li>2. If the PNC Interchange is successful, rerun the test.</li> </ol>

*Continued on next page*

Table 5-83. ATM Board Framer Looparound Test (#1260) — *Continued*

Error Code	Test Result	Description/ Recommendation
1033	ABORT	The ATM-EI circuit pack is not present.  1. Issue the <b>list atm-pnc</b> command to verify that switch recognizes the circuit pack.  2. Retry the command.
1139	ABORT	The packet bus in the EPN where this ATM-EI board is located has a major alarm against it. This test needs to use the alarmed port network's Packet Bus.  1. Resolve any " <a href="#">PKT-BUS (Packet Bus)</a> " problems.  2. Retry the command.
1141	ABORT	The Packet Interface circuit pack is out of service.  1. Resolve any PKT-INTF problems.
1144	ABORT	The Packet Bus in the PPN has a major alarm against it. This test needs to use the alarmed PPN packet bus.  1. Resolve any " <a href="#">PKT-BUS (Packet Bus)</a> " problems.  2. Retry the command.
1394	ABORT	The ATM-EI board is out of service and the test cannot be run. This condition is due to a change in the ATM-EI board's ability to communicate with the ATM switch.  1. Run Test #241. If it does not pass, refer to repair procedures for " <a href="#">Expansion Interface 2-way Transmission Test (#241)</a> " on page <a href="#">5-209</a> .
1395	ABORT	This test cannot be run on an ATM-EI circuit pack if it is part of the B-side PNC and duplicated PNC is not enabled.  1. If this test needs to run on this ATM-EI circuit pack, enable PNC duplication with the <b>change system-parameters duplication</b> command.  2. Prevent the system from doing a PNC interchange by executing the <b>set PNC lock</b> command.  3. Repeat this test.

*Continued on next page*

Table 5-83. ATM Board Framer Looparound Test (#1260) — *Continued*

Error Code	Test Result	Description/ Recommendation
1407	ABORT	<p>This test cannot be run on an ATM-EI board that is on the active PNC because it cannot be busied out. This error code indicates that PNC duplication is enabled.</p> <ol style="list-style-type: none"> <li>1. Attempt to perform a PNC interchange with the <b>reset pnc interchange</b> command.</li> <li>2. If the PNC interchange is successful, busy out the original ATM-Expansion Interface circuit pack with the <b>busyout board UUCSS</b> (address of the original ATM-EI board) command.</li> <li>3. Retry the command.</li> </ol>
2000	ABORT	<p>Response to the test was not received in the allowable time period.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 3 times.</li> </ol>
2060	ABORT	<p>The link on the packet bus being used to perform the test has failed.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 3 times.</li> <li>2. If the test continues to abort, resolve any PKT-INTF errors.</li> </ol>
2100	ABORT	<p>Could not allocate the necessary system resources to run this test.</p>
2500	ABORT	<p>Internal system error.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 3 times.</li> </ol>
1	FAIL	<p>The test did not detect the test tone through the looparound connection.</p> <p><b>⇒ NOTE:</b> The packet portion of this test was not run since the circuit portion failed.</p> <ol style="list-style-type: none"> <li>1. Test the active Tone/Clock (<b>test tone-clock UUCSS</b>) on the PN that contains the defective ATM-EI circuit pack to verify that dial tone is being supplied.</li> <li>2. If the Tone/Clock is healthy, test the ATM-EI circuit pack (<b>test board UUCSS long</b>).</li> <li>3. If this test continues to fail, replace the ATM-EI circuit pack or transceiver.</li> <li>4. Test the new ATM-EI circuit pack (<b>test board UUCSS long</b>).</li> </ol>

*Continued on next page*

Table 5-83. ATM Board Framer Looparound Test (#1260) — *Continued*

Error Code	Test Result	Description/ Recommendation
2	FAIL	<p>The test tone was transmitted and detected correctly, but the correct data packet was not detected by the Packet Interface circuit pack.</p> <ol style="list-style-type: none"><li>1. Test the Packet Interface circuit pack to verify that it is functioning properly. If any tests fail, investigate those tests and repair the Packet Interface circuit pack.</li><li>2. If the Packet Interface circuit pack is OK, resolve any DS1 CONV-BD alarms or errors (if so equipped).</li><li>3. Test the ATM-EI circuit pack (<b>test board UUCSS long</b>).</li><li>4. If this test continues to fail, replace the ATM-EI board.</li><li>5. Test the new ATM-EI circuit pack (<b>test board UUCSS long</b>).</li></ol>
3	FAIL	<p>The test tone was transmitted correctly, but the returned tone was distorted.</p> <ol style="list-style-type: none"><li>1. If the Tone/Clock is healthy, test the ATM-EI circuit pack (<b>test board UUCSS long</b>).</li><li>2. If this test continues to fail, replace the ATM-EI circuit pack.</li><li>3. Test the new ATM-EI circuit pack (<b>test board UUCSS long</b>).</li></ol>
4	FAIL	<p>Unable to create loop for TDM path for this test.</p> <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 3 times.</li><li>2. If this test continues to fail, replace the ATM-EI circuit pack.</li><li>3. Test the new ATM-EI circuit pack (<b>test board UUCSS long</b>).</li></ol>
5	FAIL	<p>Unable to create loop for packet path for this test.</p> <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 3 times.</li><li>2. If this test continues to fail, replace the ATM-EI circuit pack.</li><li>3. Test the new ATM-EI circuit pack (<b>test board UUCSS long</b>).</li></ol>

---

*Continued on next page*

Table 5-83. ATM Board Framer Looparound Test (#1260) — *Continued*

Error Code	Test Result	Description/ Recommendation
6	FAIL	<p>A previously-established looparound was not released.</p> <ol style="list-style-type: none"><li>1. Issue the <b>reset board UUCSS</b> command.</li><li>2. Retry the command at 1-minute intervals a maximum of 3 times.</li><li>3. If this test continues to fail, replace the ATM-EI circuit pack.</li><li>4. Test the new ATM-EI circuit pack (<b>test board UUCSS long</b>).</li></ol>
	PASS	<p>The ATM-EI board is functioning properly, however this test does not verify that the optical portion of the lightwave transceiver is functioning.</p>
0	NO BOARD	<p>No board was detected by the test.</p> <ol style="list-style-type: none"><li>1. Resolve either wrong board (Error 125) or no board (Error 131) issues, if applicable.</li><li>2. Check that the board is properly translated and inserted. If so, check for hyperactivity (Error 1538). If hyperactive, use the <b>reset board UUCSS</b> command.</li><li>3. Run the test again. If it fails, the NCE chip on board may be bad. Replace the board and retest.</li></ol>

**ATM Board Time Of Day Update (#1261)**

This test is non-destructive. The ATM circuit pack requires a reference time to do SDH/SONET performance monitoring. This test updates the system time to the board and synchronizes the board with the DEFINITY system clock during initialization, scheduled maintenance, and craft long test.

**Table 5-84. ATM Board Time Of Day Update (#1261)**

<b>Error Code</b>	<b>Test Result</b>	<b>Description/ Recommendation</b>
2031	FAIL	The attempt to send the message to the ATM-EI circuit pack was not successful.
2500	FAIL	Did not send the time of day information to the board. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 3 times.</li></ol>
	PASS	The ATM-EI circuit pack is successfully updated with system time. <ol style="list-style-type: none"><li>1. If the <b>status port-network</b> command still indicates that this link is down, it is possible that one or both of the ATM-EI circuit packs have been busied out.</li><li>2. If the link still does not come up, reset one or both ATM-EI circuit packs on the link.</li></ol>
0	NO BOARD	No board detected. <ol style="list-style-type: none"><li>1. Resolve either wrong board (Error 125) or no board (Error 131) issues, if applicable.</li><li>2. Check that the board is properly translated and inserted. If so, check for hyperactivity (Error 1538). If hyperactive, use the <b>reset board UUCSS</b> command.</li><li>3. Run the test again. If it fails, the NCE chip on the circuit pack may be bad. Replace the pack and retest.</li></ol>

**ATM Board Reset (#1256)**

This test is destructive. If the ATM-EI board is in the PPN or is a standby in the EPN, the reset is done through the SAKI reset interface. If the ATM-EI is an Expansion Arch Angel (active ATM-EI board in the EPN) a special message is sent to the board over the EAL if the EAL is present.

Table 5-85. ATM Board Reset (#1256)

Error Code	Test Result	Description/ Recommendation
1386	ABORT	No Active EAL to the board. This error applies only if the board under test is in EPN. Check the error logs for SYS-LINK errors against the port network in which the ATM-EI is residing and take appropriate diagnostic action for the SYS-LINK.
1015	ABORT	This test cannot be run because the ATM-TRK circuit pack has not been busied out.  1. Busyout the ATM circuit pack, then repeat the <b>test board UUCSS long</b> command.
1407	ABORT	1. Perform a PNC Interchange 2. Try to reset the board again.
None	ABORT	Could not allocate the necessary system resources to run this test.  1. Retry the command at 1-minute intervals a maximum of 5 times. 2. If the test continues to abort escalate the problem.
2000	ABORT	Did not receive the SANITY response in the given time.  1. Wait for 5 minutes and see if board is visible to the system by using list config all command. 2. If the board is visible, run the test again. If same abort code results, escalate the problem. 3. If the board is not visible to the system via list config all command, re-seat the board. 4. If the board is still not recognized by the system, replace the board.
2100	ABORT	Could not allocate the necessary system resources to run this test.  1. Retry the command at 1-minute intervals a maximum of 5 times.

*Continued on next page*

Table 5-85. ATM Board Reset (#1256) — *Continued*

Error Code	Test Result	Description/ Recommendation
2500	ABORT	Internal system error  1. Try to reset the board again.
1	FAIL	The circuit pack failed to reset
2	FAIL	The circuit pack failed to restart.  1. Execute command again.  2. If the problem persists, replace the circuit pack.
	PASS	The ATM-EI circuit pack is successfully reset.  1. If the <b>status port-network</b> command still indicates that this link is down, it is possible that one or both of the ATM-EI circuit packs are busied out.  2. If the links do not come up after reset, review the error logs and take appropriate diagnostic action.

### ATM Cross Talk Test (#1298)

This test is non-destructive. The ATM board Cross Talk test verifies that the selected TDM bus time slot never crosses over to time slots reserved for other connections. The test also checks for cross connections, where the board talks to time slots other than those specified. Since this test uses many system resources (TDM time slots, tone generator, tone detector, and others), it runs as a part of demand test only.

This test fails if either the TDM programmable logic and/or the interface to the DSP is not operating properly. Failure of these components may result in one-way or noisy connections. Refer to [Figure 5-10 on page 5-234](#) for a schematic of this test.

#### NOTE:

Note: This test takes approximately 12 minutes and applies only to TN2305 and TN2306 circuit packs.




Figure 5-10. ATM Cross Talk Test #1298 schematic

Table 5-86. ATM Crosstalk Test (#1298)

Error Code	Test Result	Description/ Recommendation
	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals for a maximum of 5 times.
1002	ABORT	The system could not allocate time slots for the test. The system may be under heavy traffic conditions or it may have time slots out-of-service due to TDM-Bus errors. Refer to <a href="#">“TDM-BUS (TDM Bus)” on page 5-1116</a> to diagnose these errors. 1. If system has no TDM-Bus errors and is not handling heavy traffic, repeat test at 1-minute intervals for a maximum of 5 times.
1003	ABORT	The system could not allocate a tone receiver for the test. The system may be oversized for the number of tone detectors present or some tone detectors may be out-of-service. 1. Resolve any TTR-LEV errors in the Error Log. 2. Resolve any TONE-PT errors in the Error Log. 3. If neither condition exists, retry the test at 1-minute intervals for a maximum of 5 times.
2000	ABORT	Response to the test was not received within the allowable time period.
2100	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals for a maximum of 5 times.

Continued on next page

Table 5-86. ATM Crosstalk Test (#1298) — *Continued*

Error Code	Test Result	Description/ Recommendation
1962	ABORT	All the TALKER DSPs are busy (an unlikely event). <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 3 times.</li></ol>
2302	ABORT	Inconsistent uplink message from the ATM-EI board. This is a very unlikely event. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 3 times.</li></ol>
2752	ABORT	The circuit pack in this location is not a TN230X.
1-8, None	FAIL	The board is writing to unauthorized TDM time slots. The error code indicates the number of faulted TALKER DSPs. <ol style="list-style-type: none"><li>1. Retry the command a maximum of 3 times.</li><li>2. If the failure persists, replace the circuit pack.</li></ol>
1-8	PASS	The board is not talking to unauthorized time slots on the TDM Bus. The error code indicates the number of TALKER DSPs that were tested.

## ATM Board DSP Test (#1293)


This test is non-destructive and is designed to test the board's interface to the TDM bus and the functions of all 24 on-board DSPs (Digital Signal Processors). There are three functional types of DSPs:

- talkers - put data on the TDM bus
- listeners - take data off the TDM bus
- echo cancelers - as implied

Listener and echo cancelers are tightly coupled because firmware allocates *sets* of DSPs. Since there are a total of 24 DSPs on the board, there may be up to 8 triplets allocated.

If the test fails for all DSPs, a MAJOR alarm is raised against the board. If the test fails for one or more DSPs, a MINOR alarm is raised. If a DSP is "busy," the test for that particular DSP is considered passed. The test aborts if the system resources (for example, the TDM time slots, tone generator, and others) are not available.

This test applies to TN2305 and TN2306 ATM-EIs, both active and standby, and is run as part of craft short and long testing, periodic, scheduled, initialization, and error analysis testing. Refer to [Figure 5-11 on page 5-236](#) for a diagram of this looparound test.



---

**Figure 5-11. ATM Board DSP Test (#1293)**

Table 5-87. ATM Board DSP Test (#1293)

Error Code	Test Result	Description/ Recommendation
1002	ABORT	<p>The system could not allocate time slots for the test. The system may be under heavy traffic conditions or it may have time slots out of service due to TDM-BUS errors.</p> <ol style="list-style-type: none"> <li>1. If system has no TDM-BUS errors and is not handling heavy traffic, retry the command at 1-minute intervals a maximum of 3 times.</li> </ol>
1003	ABORT	<p>The system could not allocate a tone receiver for the test. The system may be oversized for the number of tone detectors present, or some tone detectors may be out of service.</p> <ol style="list-style-type: none"> <li>1. Resolve any TTR-LEV errors.</li> </ol> <p>Even if there are no TTR-LEV errors, there may not be a tone detector available on the network that contains the circuit pack being tested. Verify that there is at least one tone detector on the network. If not, this test always aborts for this ATM-EI circuit pack and does not harm the system.</p> <ol style="list-style-type: none"> <li>2. Resolve any TONE-PT errors.</li> <li>3. If neither condition exists, retry the command at 1-minute intervals a maximum of 3 times.</li> </ol>
1962	ABORT	<p>All DSPs are busy (an unlikely event).</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 3 times.</li> </ol>
2000	ABORT	<p>Response to the test was not received within the allowable time period for some of the DSPs.</p> <ol style="list-style-type: none"> <li>1. If the board is in standby, reset the board and run the test again.</li> <li>2. Look into the Error Log for Error Type 1218 (bad DSP). If Error Type 1218 is not logged against this board, run the DSP test again and see if the error persists.</li> </ol>
2100	ABORT	<p>Could not allocate the necessary system resources to run this test.</p>
2302	ABORT	<p>Inconsistent uplink message from the ATM-EI board (an unlikely event).</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 3 times.</li> </ol>

Table 5-87. ATM Board DSP Test (#1293) — Continued

Error Code	Test Result	Description/ Recommendation
2500	ABORT	Internal system error
2752	ABORT	The circuit pack in this location is not a TN230X.
XYZ	FAIL	<p>A device on the circuit pack is failing. There is at least one bad DSP on the board. Values are as follows:</p> <ul style="list-style-type: none"><li>■ The X value indicates the number of talker DSPs</li><li>■ Y indicates the number of listener DSPs</li><li>■ Z indicates the number of Echo Canceler DSPs that have failed the test.</li></ul> <ol style="list-style-type: none"><li>1. Run the tests for the active Tone-Clock on the PN that contains the indicted ATM-EI circuit pack to verify that dial-tone is supplied.</li><li>2. If the tone-clock is healthy, repeat the short test on the ATM-EI board.</li><li>3. If this test continues to fail, replace the ATM-EI circuit pack.</li></ol>
XYZ	PASS	<p>The test passed for some or all DSPs depending on XYZ values. XYZ indicates the number of talker, listener and echo-canceler DSPs for which the test passed, respectively. In the DSPs that passed the test, the test tone was correctly detected by the DSP Listener and by tone-detector for the DSP Talkers on both busses, and the Echo Canceler DSPs are working properly.</p>
0	NO BOARD	<p>No board was detected by the test.</p> <ol style="list-style-type: none"><li>1. Check the Error Log for wrong board (Error Type 125) or no board (Error Type 131). Resolve either of these issues, if applicable.</li><li>2. Check that the board is properly translated and inserted. If so, check for hyperactivity (Error Type 1538). If hyperactive, use the <b>reset board UUCSS</b> command.</li><li>3. Run the test again. If it fails, the circuit pack may be bad. Replace the circuit pack and retest.</li></ol>

## ATM-INTF (TN2305/6)

---

MO name (in alarm log)	Alarm level	Initial command to run	Full name of MO
ATM-INTF	WARNING	test board UUCSSpp	ATM interface board

The TN2305/6 is recognized by the system as an ATM Interface board (ATM-INTF) if it has not been assigned a personality through the **add atm-pnc** command or **add atm trunk** command. ATM-INTF does not have a maintenance strategy associated with it, although the Control Channel test can be run on demand by using the **test board** command, and the board can be reset by using the **reset board** command. The board is visible through the **list config** and **change circuit-pack** commands.

The circuit packs listed in [Table 5-88](#) are ATM-EI boards if they are administered to serve the ATM Port Network Connectivity (ATM-PNC).

Table 5-88. ATM-EI circuit packs for ATM-PNC

---

Circuit pack	Fiber	Echo cancellation	Release
TN2305	Multi mode	Y	7.1
TN2306	Single mode	Y	7.1

---

**NOTE:**

Always replace an ATM-EI circuit pack with the same type.

## LED states

---

The ATM-INTF circuit pack has the standard red, green and yellow LEDs. The red and green LEDs have the traditional use: red indicates an alarm condition, green means maintenance testing in progress. The yellow LED is not used. The possible LED states are listed below:

LED	Condition	LED
Red	Board is not healthy	Solid on never off
Red Green	Board is in the processes of booting	Red: solid on Green: 200 ms on 200 ms off
Green	Maintenance is running tests on the board	Solid on (off when maintenance completed)
Yellow	Fiber LOS	100 ms on, 100ms off
Yellow	Signal to the ATM switch is down	500 ms on, 500 ms off

## Error log entries and test to clear values

---

Table 5-89. ATM-INTF error log entries

Error type	Aux data	Associated test	Alarm level	On/Off board	Test to clear value
23(a)	0	None	WAR	OFF	
125(b)		None	MIN	ON	
217(c)	0	None	WAR	OFF	

### Notes:

- Error Type 23: ATM Expansion Interface circuit pack is administered through a **change circuit-pack** command, but has not been inserted into the system. Insert the circuit pack.
  - Error Type 125: A wrong circuit pack is located in the slot where this circuit pack is logically administered. To resolve this problem, either remove the wrong circuit pack or insert the logically administered circuit pack.
  - Error Type 217: The ATM circuit pack is physically present but has not been given a personality. Remove the circuit pack or administer it using the **add atm pnc** command or **add atm trunk** command.
-

**System Technician-Demanded Tests: Descriptions  
and Error Codes**

Failure of this test is not logged in the Error Log.

Order of investigation	Short test sequence	Long test sequence	D/ND <sup>1</sup>
Control Channel Loop Around Test (#52)	X	X	N

1. D = Destructive, ND = Non-destructive

**Control channel loop-around test (#52)**

This test is non-destructive. This test queries the circuit pack for its circuit pack code and vintage and verifies its records.

Table 5-90. TEST #52 control channel loop-around test

Error code	Test result	Description/ Recommendation
2000	ABORT	Response to the test request was not received within the allowable time period.
2100	ABORT	System resources required to run this test are not available.
2500	ABORT	Internal system error 1. Retry the command at 1-minute intervals for a maximum of 5 times.

*Continued on next page*

Table 5-90. TEST #52 control channel loop-around test — *Continued*

Error code	Test result	Description/ Recommendation
	FAIL	The circuit pack failed to return the circuit pack code or vintage. <ol style="list-style-type: none"><li>1. Retry the command a few times for a maximum of 5 times.</li><li>2. If the problem continues to fail, reset the circuit pack.</li><li>3. Retry the command a few times for a maximum of 5 times.</li></ol>
	PASS	Communication with this circuit pack is successful.
Any	NO BOARD	This is normal if the test is being done when: <ul style="list-style-type: none"><li>■ The board is not physically in the system.</li><li>■ The system is booting up.</li></ul> Otherwise, there is some inconsistency in the data kept in the system. <ol style="list-style-type: none"><li>1. Verify that the board is physically in the system.</li><li>2. Verify that the system is not in the process of booting up.</li><li>3. Retry the command at 1-minute intervals for a maximum of 5 times.</li></ol>

## ATM-NTWK (ATM Network Error)

---

MO name (in alarm log)	Physical Name in Error Logs <sup>1</sup>	Alarm level	Full name of MO
ATM-NTWK	ATUUP	WARNING	ATM Network Error

- 
1. *AT* indicates it is an ATM switch related address, *UU* is the connection number. The connection number can be converted into a board location by the command **display atm pnc UU**, which shows the translations for the board that reported the ATM network error. *P* indicates if the ATM-EI board (reporting the ATM network error) is the A side or the B side of the PNC. If the system is simplex, only A is valid.
- 

In the ATM PNC configuration, the proprietary Center Stage Switch (CSS) is replaced by the ATM network. Since the CSS switch nodes are replaced by the ATM network in the ATM PNC configuration, the SNI boards are no longer needed. In place of SNI board, the ATM EI boards are connected to an ATM switch port over a fiber optic cable. The port on the ATM switch is under the control of ATM switch maintenance software. Refer to the "ATM Tips" section in Chapter 1 of DEFINITY ONE Communications System Release 2.0 (555-233-111) for a schematic of these connections.

An error against this MO indicates a problem in the ATM network (including the ATM switch) that is affecting the service quality. These error events are reported by the ATM network to the ATM EI board or are detected by the ATM EI board. Since these errors are *not* related to the ATM EI board, these errors are not reported against the ATM-EI Maintenance Object. However, some of these errors invoke alarms that require action by DEFINITY maintenance, while other log-only errors require no action.

### Error Codes and Aux Data values

---

The Cause Code/Error Type information is shown in the table below. These are the possible errors that can be logged against the ATM-NTWK MO.

If the ATM-NTWK Maintenance Object receives more than 6 errors, the most recent errors are discarded.

Cause Code/ Error type	Aux Data	Cause Codes Description
<b>NORMAL EVENTS</b>		
0	(a)	Network unreachable
1	(a)	Unallocated (unassigned) number. This cause indicates that the called party cannot be reached because, although the number is in a valid format, it is not currently assigned (allocated).
2	(a)	No route to specified transit network. This cause indicates that the equipment sending this cause has received a request to route the call through a particular network which it does not recognize, either because the transit network does not exist or because that particular transit network does not serve the equipment which is sending this cause. This cause is supported on a network-dependent basis.
3	(a)	No route to destination. This cause indicates that the called party cannot be reached because the network through which the call has been routed does not serve the destination desired. This cause is supported on a network-dependent basis.
10	(a)	VPCI/VCI unacceptable. This cause indicates that the virtual channel most recently identified is not acceptable to the sending entity for use in this call.
16	(a)	Normal call clearing. This cause indicates that the call is being cleared because one of the users involved in the call has requested that the call be cleared. Under normal situations, the source of this cause is not the network.
17	(a)	User busy. This cause indicates that the called party is unable to accept another call because the user busy condition has been encountered. This cause value may be generated by the called user or by the network.
18	(a)	No user responding. This cause is used when a called party does not respond to a call establishment message with a connect indication within the prescribed period of time allocated.

*Continued on next page*

5 Maintenance Objects for DEFINITY ONE  
ATM-NTWK (ATM Network Error)

5-245

Cause Code/ Error type	Aux Data	Cause Codes Description
21	(a)	<p>Call rejected. This cause indicates that the equipment sending this cause does not wish to accept this call, although it could have accepted the call because the equipment sending this cause is neither busy nor incompatible.</p> <p><b>⇒ NOTE:</b> If the call was rejected by the far-end ATM-EI board, there may also be additional information about this rejection in an ATM-EI error log entry. Look for an ATM-EI error with an Error Type between 1104 and 1119 inclusive, with approximately the same time stamp as this error.</p>
22	(a)	<p>Number changed. This cause is returned to a calling party when the called party number indicated by the calling user is no longer assigned. The new called party number may optionally be included in the diagnostic field. If a network does not support this capability, cause number 1 "<i>unassigned (unallocated) number</i>" is used.</p>
23	(a)	<p>User rejects all calls with calling line identification restriction (CLIR). This cause is returned by the called party when the call is offered without calling party number information and the called party requires this information.</p>
27	(a)	<p>Destination out of order. This cause indicates that the destination indicated by the user cannot be reached because the interface to the destination is not functioning correctly. The term "not functioning correctly" indicates that a signalling message was unable to be delivered to the remote user; for example, a physical layer or SAAL failure at the remote user or user equipment off-line.</p>
28	(a)	<p>Invalid number format (address incomplete). This cause indicates that the called user cannot be reached because the called party number is not in a valid format or is not complete.</p>
30	(a)	<p>Response to STATUS ENQUIRY. This cause is included in the STATUS message when the reason for generating the STATUS message was the prior receipt of a STATUS ENQUIRY message.</p>
31	(a)	<p>Normal, unspecified. This cause is used to report a normal event only when no other cause in the normal class applies.</p>
32	(a)	<p>DTL transit not-my-node ID</p>

Continued on next page

Cause Code/ Error type	Aux Data	Cause Codes Description
<b>RESOURCE UNAVAILABLE</b>		
35	(a)	Requested VPCI/VCI not available. This cause indicates that the requested VPCI/VCI is not available. This can be caused by mismatched VCI ranges on different ATM switches.
36	(a)	VPCI/VCI assignment failure
37	(a)	User Cell Rate not available
38	(a)	Network out of order. This cause indicates that the network is not functioning correctly and that the condition is likely to last a relatively long period of time; for example, immediately re-attempting the call is not likely to be successful.
41	(a)	Temporary failure. This cause indicates that the network is not functioning correctly and that the condition is not likely to last a long period of time; for example, the user may wish to try another call attempt immediately.
43	(a)	Access information discarded. This cause indicates that the network could not deliver access information to the remote user as requested; that is, ATM adaptation layer parameters, Broadband low layer information, Broadband high layer information, or sub-address as indicated in the diagnostic.
45	(a)	No VPCI/VCI available. This cause indicates that there is no appropriate VPCI/VCI presently available to handle the call.
47	(a)	Resource unavailable, unspecified. This cause is used to report a resource unavailable event only when no other cause in the resource unavailable class applies.

*Continued on next page*

Cause Code/ Error type	Aux Data	Cause Codes Description
<b>SERVICE OR OPTION UNAVAILABLE</b>		
49	(a)	Quality of Service unavailable. This cause is used to report that the requested Quality of Service cannot be provided.
51	(a)	User cell rate not available. This cause is used to report that the requested ATM Traffic Descriptor is unobtainable.
57	(a)	Bearer capability not authorized. This cause indicates that the user has requested a bearer capability which is implemented by the equipment which generated this cause but the user is not authorized to use.
58	(a)	Bearer capability not presently available. This cause indicates that the user requested a bearer capability implemented by the equipment that generated the cause but is not available at this time.
63	(a)	Service or option not available, unspecified. This cause is used to report a service or option not available event only when no other cause in the service or option not available class applies.
65	(a)	Bearer capability not implemented. This cause indicates that the equipment sending this cause does not support the bearer capability requested.
73	(a)	Unsupported combination of traffic parameters. This cause indicates that the combination of traffic parameters contained in the ATM traffic descriptor information element is not supported.
78	(a)	AAL parameters cannot be supported.
<b>INVALID MESSAGES</b>		
81	(a)	Invalid call reference value. This cause indicates that the equipment sending this cause has received a message with a call reference which is not currently in use on the user-network interface.
82	(a)	Identified channel does not exist. This cause indicates that the equipment sending this cause has received a request to use a channel not activated on the interface for a call.
88	(a)	Incompatible destination. This cause indicates that the equipment sending this cause has received a request to establish a call which has Broadband low layer information, Broadband high layer information, or other compatibility attributes which cannot be accommodated.

---

*Continued on next page*

Cause Code/ Error type	Aux Data	Cause Codes Description
89	(a)	Invalid endpoint reference value. This cause indicates that the equipment sending this cause has received a message with an endpoint reference that is currently not in use on the user-network interface.
91	(a)	Invalid transit network selection. This cause indicates that a transit network identification was received in an incorrect format as defined in Annex D.
92	(a)	Too many pending add party requests. This cause indicates a temporary condition when the calling party sends an add party message, but the network is unable to accept another add party message because its queues are full.
93	(a)	AAL parameters cannot be supported. This cause indicates that the equipment sending this cause has received a request to establish a call with ATM adaptation layer parameters that cannot be accommodated.
<b>PROTOCOL ERROR</b>		
96	(a)	Mandatory information element is missing. This cause indicates that the equipment sending this cause has received a message that is missing an information element.
97	(a)	Message type non-existent or not implemented. This cause indicates that the equipment sending this cause has received a message with a message type it does not recognize either because this is a message not defined or defined but not implemented by the equipment sending this cause.
99	(a)	Information element non-existent or not implemented. This cause indicates that the equipment sending this cause has received a message that includes information element(s) not recognized because the information element identifier(s) are not defined or are defined but not implemented by the equipment sending the cause. This cause indicates that the information element was discarded. However, the information element is not required to be present in the message in order for the equipment sending this cause to process the message.
100	(a)	Invalid information element contents. This cause indicates that the equipment sending this cause has received and implemented an information element. However, one or more of the fields in the information element are coded in such a way that has not been implemented by the equipment sending this cause.

*Continued on next page*

Cause Code/ Error type	Aux Data	Cause Codes Description
101	(a)	Message not compatible with call state. This cause indicates receipt of a message that is incompatible with the call state.
102	(a)	Recovery on timer expiration. This cause indicates that a procedure has been initiated by the expiration of a timer in association with error handling procedures.
104	(a)	Incorrect message length
111	(a)	Protocol error, unspecified. This cause is used to report a protocol error event only when no other cause in the protocol error class applies.
257 to 300 (b)	(b)	<p>ATM Impaired Paths</p> <p>Examine the error log ('display errors'), atm setup-events log ('list measurements atm svc-setup'), and atm pnc-latency ('list measurements atm latency') screens to help diagnose the problem -- it is possible the switch is operating normally. In this case, you should consider raising the Activation threshold and/or increasing the Timeout value on the ATM-RELEASED System Parameters form. ('change system atm').</p> <p>You can use the list measurements atm svc-setup command to provide information about errors associated with connection numbers.</p> <p>After entering the above command, make note of the time stamps displayed in the list measurements atm setup-events screen. Execute the above command periodically and note the time stamps. If the time stamps have changed for a particular 'From Conn' 'To Conn' pair, this indicates there are still setup failures/delays for that connection.</p> <p>After verifying that all associated ATM end-points are operating correctly, and if errors are still occurring, contact your local service provider.</p>
301 (c)	ANY	<p>System wide ATM Impaired Paths.</p> <p>See the suggestions listed above to trouble shoot these errors.</p>

## Note:

- a. Aux Data values (XX = Port Network, YYY = location code).

[Table 5-91](#) is a list of UNI 3.1 location codes:

Table 5-91. Location codes from Aux Data values

Setup (Location Code)	Add Party (Location Code)	Location Code Meaning
0	500	User
1	501	Private network serving the local user
2	502	Public network serving the local user
3	503	Transit network
4	504	Public network serving the remote user
5	505	Private network serving the remote user
7	507	International network
10	510	Network beyond interworking point

- b. Error Type 257 to 300: These error type numbers are used to determine the destination PNC connection number of an ATM Network connection that is experiencing an impaired path. The connection number is obtained by subtracting 256 from number that is displayed in the Error Type field. See the following example:

ERROR TYPE field= 263

Subtract                -256

PNC destination connection # =     7

The AUX DATA field contains the originating and destination PN number (XXYY). Where XX = the originating PN #, and YY = the destination PN # for example:

1. Example AUX DATA = 302

3 = orig

2 = dest

2. Example AUX DATA = 1510

15 = orig

10 = dest

- c. Error Type 301: This error indicates that there is a system wide impaired path network problem.

**NOTE:**

Under certain circumstances network errors can be against the ATM EI board.

## ATM-SGRP (ATM signaling group)

MO name (in alarm log)	Alarm level	Initial command to run <sup>1</sup>	Full name of MO
ATM-SGRP	MINOR	test sig-group <i>grp#</i>	ATM-CES Signaling Group
ATM-SGRP	WARNING	test sig-group <i>grp#</i>	ATM-CES Signaling Group

1. *grp#* is the signaling group number (1-166); the test sequence can be either short or long.

This Maintenance Object (ATM-SGRP) applies when there are administered ATM signaling groups on the ATM circuit pack.

[Table 5-92](#) outlines the differences between ATM interface circuit packs:

**Table 5-92. R7 ATM-SGR circuit packs**

Circuit pack	Channel types	Interface	Fiber	Echo cancellation
TN2305	B and D channels	24 or 32 channel	Multimode	Y
TN2306	B and D channels	24 or 32 channel	Single mode	Y

The TN2305 and TN2306 ATM Interface circuit boards are referred to as TN230X for the remainder of this MO.

An ATM Signaling Group is a collection of B-channels for which a given ISDN-PRI Signaling Channel Port (ATM D-channel) carries signaling information. ATM B-channels (ATM-BCH) carry voice or data and are assigned to ISDN trunks. For more information see [“ATM-TRK \(circuit emulation service circuit pack\)”](#).

The operation of the entire ATM signaling group depends on several other entities:

- The ATM-DCH signaling channel port
- The TN230X Interface circuit pack on which the D-channels reside
- The system link that is carried over the packet bus to the processor

When there are problems with ATM-SGRP (ATM signaling group), also investigate:

- [“ATM-DCH \(ATM D-channel port\)”](#)
- [“ATM-DCH \(ATM D-channel port\)”](#)
- [“SYS-LINK \(System Links\)”](#)
- [“PKT-BUS \(Packet Bus\)”](#)

### Error log entries and test to clear values

Table 5-93. ATM-SGRP signaling group error log entries

Error type	Aux data	Associated test	Alarm level	On/Off board	Test to clear value
0	0	Any	Any		test sig-group <i>grp#</i>
1 (a)	Any	None			
18 (b)		MO busied out			
257 (c)	Any	None			test sig-group <i>grp#</i>
769 (d)	Any	Primary Signaling Link Hardware Check (#636)			test sig-group <i>grp#</i>
1281 (e)	Any	Secondary Signaling Link Hardware Check (#639)			test sig-group <i>grp#</i>
1793 (f)	Any	Layer 2 Status (Test #647)	WNG	OFF	test sig-group <i>grp#</i>
2305 (g)	Any	Remote Layer 3 Query (Test #637)	MINOR	OFF	test sig-group <i>grp#</i>
3585 (h)	Port number	None			
3840 - 3928 (i)	Port number	None			

## Notes:

- a. Error Type 1: switch sent a message to the far-end switch or terminal adapter, and the far-end did not respond in the allotted time. Possible causes include link failure and congestion or outage at the far-end. The Aux Data field contains Layer 3 protocol information used by internal counters.

If no other symptoms are present, no action is required. If Layer 3 communication is down:

- a. Check for alarms and errors against link components
- b. Check out other errors against ATM-SGRP, ATM-TRK, and other hardware components on the link.

There is no test to clear these errors. The error counter is decremented by 1 every 15 minutes.

- b. Error Type 18: the ATM circuit pack has been busied out (either **busyout atm sig-grp** or **busyout board UUCSS**).
  1. Release the ATM signaling group (**release atm sig-grp**) or the circuit pack (**release board UUCSS**).
- c. Error Type 257: the primary signaling channel connection has been lost for more than 90 seconds.
  - The associated B-channels are placed in the ISDN Maintenance/Far-End state.
  - The B-channels are not usable for outgoing calls, although incoming calls can be accepted.
  - The switch automatically attempts to recover the signaling link.
  1. Pay particular attention to the results of Test #636 (Primary Signaling Link Hardware Check) in the test sequence.
    - When the link does recover, the B-channels are negotiated back to the In-Service state and their alarms are retired.
  2. When this error occurs, the state of the Signaling Group is changed to out-of-service (verify using the **status sig-group** command).
- d. Error Type 769: signaling link hardware error.

Service-affecting failures of the hardware used to transport the D-Channel are reported to the ATM CES Signaling Group MO. Maintenance logs this error, places the D-Channel into the OOS state, and raises a board-level alarm. The D-Channel is returned to service and the alarm is retired once the hardware failure condition clears.

- e. Error Type 1281: Degraded PVC Alarms indicate that a particular Permanent Virtual Circuit, or signaling group, has encountered sufficient errors to exceed firmware thresholds. Operations can continue but at a lower level of reliability or performance. Firmware filters these alarms so that only one is reported active at a given time. The following in-line error is considered a Degraded PVC Alarm:
- Excessive AAL - The AAL layer is experiencing an excessive number of errors in trying to reconstruct Service Data Unit (SDUs). Possible causes:
    - Something may be wrong with the ATM switch.
    - The communication paths on the other side of the ATM switch may be noisy.
    - The sending node might not be healthy.
    - Could be a problem with congestion on the ATM switch.
- f. Error Type 1793: failure of the Layer 2 Query Test for the primary signaling channel.
- Excessive AAL - The AAL layer is experiencing an excessive number of errors in trying to reconstruct Service Data Unit (SDUs). Possible causes:
    - Something may be wrong with the ATM switch.
    - The communication paths on the other side of the ATM switch may be noisy.
    - The sending node might not be healthy. It could also be a problem with congestion on the ATM switch.
- g. Error Type 2305: the Remote Layer 3 Query Test (#637) failed. A specific message was sent to the far-end switch, and it did not respond within the allotted time.
1. Investigate elements of the ATM D-channel(s) (ATM-DCH) for both this switch and the Far-end switch.
- If Test #637 fails twice in a row, the B-channels are alarmed and made unavailable for outgoing calls (although incoming calls are still accepted). When Test #637 succeeds and the Far-end switch starts responding properly, the ATM Trunk (B-channels) are placed back into normal operation and their alarms retired.
- h. Error Type 3585: A SERV or SERV ACK ISDN D-channel message has been received by a non-US-type interface (country option other than 1 on the DS1 administration form). However, these messages are used only for duplex NFAS signaling, which is supported by country protocol 1.
- Thus, there may be a mismatch in administration between the local and far-end switches.
1. Consult with the customer's network provider to determine whether the D-channel is set up correctly on the far-end switch.

- i. Error Type 3840-3928: These error types are used to report certain error messages received by the ATM-SGRP Signaling Group for one of its associated B-channels. The Aux Data field is the port number of the B-channel from which the message was received.

The error code generated equals 3840+ x, where x is a Cause Value defined by the ISDN PRI Specification. Note that there is no Test to Clear Value for these error types; selected ISDN cause values are placed in the log when they are received, but no direct action or alarming is performed solely in response to receiving them. They provide added data that may prove useful when tracking down obscure networking and routing problems. [Table 5-94](#) provides more information about this range of Error Codes:

Table 5-94. Descriptions and repair recommendations (error types 3840-3928)

Error code	Description	Recommendation
3842	A request has been made to use a transit network or common carrier that cannot be accessed.	<p>From the circuit pack and port number (in the Aux Data field), determine the trunk group against which the error was reported.</p> <ol style="list-style-type: none"> <li>1. Check all routing patterns containing this trunk group for validity of interexchange carriers requested (IXC field).</li> </ol>
3846	The far-end switch has indicated that the B-channel (trunk) is not acceptable for use in the call for which it was requested.	<p>This could indicate:</p> <ul style="list-style-type: none"> <li>■ An administration problem (for example, the local switch and the far-end switch have different B-channels administered)</li> <li>■ A normal race condition (for example, the local switch has requested use of a B-channel which the far-end switch had just reserved for use on another call).</li> </ul> <ol style="list-style-type: none"> <li>1. From the circuit pack and port number (in the Aux Data field), determine the trunk group against which the error was reported.</li> <li>2. Issue the <b>status trunk</b> command for the indicated trunk.</li> <li>3. Refer to <a href="#">Table 5-59 on page 5-170</a> in "<a href="#">ATM-BCH (ATM B-channel trunk)</a>" for recovery suggestions.</li> </ol>

Continued on next page

Table 5-94. Descriptions and repair recommendations (error types 3840-3928) — *Continued*

Error code	Description	Recommendation
3858	Similar to Error Type 1. The switch sent an ISDN message to the far-end switch or terminal adapter which did not respond in the allotted time.	<ol style="list-style-type: none"> <li>1. Check for alarms and errors against link components</li> <li>2. Check out other errors against <a href="#">“ATM-SGRP (ATM signaling group)”</a>, <a href="#">“ATM-TRK (circuit emulation service circuit pack)”</a>, and other hardware components on the link.</li> </ol>
3878	The far-end switch has indicated that the network is not functioning correctly and that the condition may last a relatively long period of time (for example, immediately re-attempting the call may not be successful).	<ol style="list-style-type: none"> <li>1. From the circuit pack and port number (in the Aux Data field, determine the trunk group against which the error was reported.</li> <li>2. Consult with the network provider to determine the nature and expected duration of the out of service condition.</li> <li>3. Consider modifying all routing patterns containing this trunk group, to route calls around the network which is out of service.</li> </ol>
3890	A request to use a network service (for example, SDN) has been denied. Administration somewhere on the network has indicated that the requested service has not been subscribed to or purchased for this trunk.	<p>This could indicate:</p> <ul style="list-style-type: none"> <li>■ A local administration problem</li> <li>■ A mismatch between the local administration and that of the network provider</li> </ul> <ol style="list-style-type: none"> <li>1. From the circuit pack and port number (in the Aux Data field), determine the trunk group against which the error was reported.</li> <li>2. Display the trunk group form.                     <p>If the trunk group is Call-by-Call (the <i>Service Type</i> field is <i>cbc</i>), check all routing pattern forms containing this trunk group to see if the <i>Service/Feature</i> fields contain the correct network services purchased for this trunk.</p> <p>If the trunk group is not Call-by-Call, check that the <i>Service Type</i> field contains the single network service purchased for this trunk.</p> </li> <li>3. If local administration appears correct, consult with the customer and/or the network provider to determine the services that the customer has subscribed to for this trunk group.</li> </ol>

Table 5-94. Descriptions and repair recommendations (error types 3840-3928) — *Continued*

Error code	Description	Recommendation
3892	Protocol detail; may offer a clue if customer is having ISDN calls denied with an unexpected intercept tone.	1. If customer is complaining of unexpected intercept tones when accessing ISDN trunks or PRI endpoints and no other cause can be found, escalate the problem and provide the next tier with this Error Log information.
3894	Protocol detail; may offer a clue if customer is having ISDN calls denied with an unexpected intercept tone.	1. Eliminate any transitory state mismatch problems ( <b>test port UUCSSpp</b> for the trunk port shown in the Aux Data field). Test #256 (Service State Audit) is the important test in the sequence. 2. If Test #256 passes yet the customer continues to complain of unexpected intercept tones when accessing ISDN trunks or PRI endpoints and no other cause can be found, escalate the problem and provide the next tier with this Error Log information.
3905	Protocol detail; may offer a clue if customer is having ISDN calls denied with an unexpected intercept tone.	1. If customer is complaining of unexpected intercept tones when accessing ISDN trunks or PRI endpoints and no other cause can be found, escalate the problem and provide the next tier with this Error Log information.
3906	Protocol detail; may offer a clue if customer is having ISDN calls denied with an unexpected intercept tone.	1. If customer is complaining of unexpected intercept tones when accessing ISDN trunks or PRI endpoints and no other cause can be found, escalate to the problem and provide the next tier with this Error Log information.
3909	A request to use a network service has been made, but the network has rejected the request because the requested service is not implemented.	1. Follow the recommendations listed above for Error Type 3890.

*Continued on next page*

Table 5-94. Descriptions and repair recommendations (error types 3840-3928) — *Continued*

Error code	Description	Recommendation
3928	A call was denied because of a basic incompatibility between the type of call and either the facilities selected by the routing pattern or the called user itself.	<p>This error might be helpful as a clue if the customer complains of receiving unexpected intercept tone after accessing ISDN trunks or PRI endpoints.</p> <ol style="list-style-type: none"> <li>1. Determine the trunk group from the circuit pack and port number (in the aux data field)</li> <li>2. check the BCC fields of the pertinent routing patterns.</li> <li>3. Also, investigate whether or not the calling and called endpoints are compatible (for example, some ISDN switches may not allow a voice station to call a data extension).</li> </ol>

### System technician-demanded tests: descriptions and error codes

Always investigate tests in the order presented in the table below when inspecting errors in the system. By clearing error codes associated with the Primary Signaling Link Hardware Check, for example, you may also clear errors generated from other tests in the testing sequence.

Table 5-95. System technician-demanded tests: ATM-SGRP

Order of investigation	Short test sequence	Long test sequence	D/ND <sup>1</sup>
Primary Signaling Link Hardware Check (#636)	X	X	ND
Layer 2 Status Test (#647)	X	X	ND
Remote Layer 3 Query Test (#1291)	X	X	ND

1. D = Destructive, ND = Non-destructive

**Primary signaling link hardware check (#636)**

The ATM-SGRP Signaling Group D-Channel port depends on the health of the TN230X interface circuit pack on which it resides. This test fails if there are problems with either the ATM-DCH (D-channel port) maintenance object or the TN230X circuit pack. Investigate the ATM TN230X circuit pack (ATM-TRK) anytime there are problems with the ATM D-channel port (ATM-DCH).

**Table 5-96. Primary signaling link hardware check (#636)**

Error code	Test result	Description/ Recommendation
	ABORT	Internal system error  Retry the command at 1-minute intervals a maximum of 5 times.
8	FAIL	There is a problem with the ATM TN230X Circuit Pack or the ATM Signaling Channel (D-Channel), preventing any ISDN trunk calls until the problem is resolved.  1. Consult the procedures for the TN230X Circuit Pack (ATM-TRK) and the ATM D-channel (ATM-DCH).
	PASS	The basic physical connectivity of the D-channel is intact and functional.  1. Try this test repeatedly to ensure the link is up and to uncover any transitory problems.

**Layer 2 status test (#647)**

The Layer 2 Status Test checks the layer 2 status of the ATM-SRG Signaling Channel (D-channel). This test fails when:

- There is a hardware failure.
- There is a facility problem.
- The D-channels are not administered correctly.

The Signaling Link Hardware Check (Test #637) and the Remote Layer 3 Query Test (#1291) detects most problems caused by hardware failures or incorrect administration.

**Table 5-97. TEST #647 layer 2 status query test**

Error code	Test result	Description/ Recommendation
1132	ABORT	Internal system error. The port location for the D-channel is not known. This condition should not be possible since an administered ATM circuit pack must be specified when a Signaling Group is administered:  1. Retry the command at one minute intervals a maximum of five times.
1134	ABORT	Internal system error. The associated ATM circuit pack is not administered. This condition should not be possible, since an administered ATM circuit pack must be specified when administering a Signaling Group.  1. Retry the command at one minute intervals a maximum of three times.
2500	ABORT	Internal system error  1. Retry the command at one minute intervals a maximum of five times.

*Continued on next page*

Table 5-97. TEST #647 layer 2 status query test — *Continued*

Error code	Test result	Description/ Recommendation
1	FAIL	<p>Layer 2 of the signaling channel is down</p> <ol style="list-style-type: none"><li>1. Examine the results of the Signaling Test (#636) and follow recommendations provided there.</li><li>2. If Test #636 (Primary Signaling Link Hardware Check) passes, the Layer 2 Query test may still fail if the Signaling Channel at the far end has not been administered correctly or if the Signaling Channel has been busied out.</li><li>3. Verify that the Signaling Channel (D-channel) at the far end has been administered correctly.</li><li>4. Verify that the ATM-DCH port used for the D-channel has not been busied out at the far end.</li></ol>
3	FAIL	<p>The D-Channel is down.</p> <ol style="list-style-type: none"><li>1. Examine the results of the Primary Signaling Link Hardware Check (#636) and follow recommendations provided there.</li><li>2. If Test #636 (Primary Signaling Link Hardware Check) passes, the Layer 2 Query test may still fail if the Signaling Channel at the far end has not been administered correctly or if the Signaling Channel has been busied out.</li><li>3. Verify that the Signaling Channel (D-channel) at the far end has been administered correctly.</li><li>4. Verify that the ATM-DCH port used for the Primary and Secondary D-channels has not been busied out at the far end.</li></ol>
	PASS	<p>The Primary Signaling Channel is up.</p>

## Remote layer 3 query (#1291)

This test queries the far-end switch or terminal adapter to determine if the signaling connection is functioning properly at Layer 3. It selects a B-channel in the in-service or maintenance service state and sends an ISDN Layer 3 SERVICE message, which requires a response from the far end (similar to performing Test #256 on an ISDN trunk). The test is not performed if there are no B-channels in an appropriate ISDN service state (for example, when none are administered or they are all out of service).

### NOTE:

The service state can be displayed by using the **status trunk <trunk group/trunk member>** or **status pri-endpoint** command.

As is the case with Test #256 for an ISDN trunk, a PASS only indicates that a message was composed and sent to the far-end switch or terminal adapter. The ISDN PRI Specification allows up to 2 minutes for a response. Check the Error Log for ATM-SGRP errors of type 2305 for evidence of a Remote Layer 3 Query failure.

Test #636 checks the health of the D-channels and ATM Interface Circuit Packs. This test goes one step further by checking the communication path from the processor, through the TDM/Packet Bus and ATM Interface circuit pack, and on to the far-end switch or terminal adapter. A special ISDN message is sent to the far-end switch or terminal adapter, which must respond within a specified amount of time. This test is designed to ensure that the communication path between the switch and the far-end is up and operational, and that the two endpoints can properly exchange ISDN control messages.

Table 5-98. TEST #1291 remote layer 3 query

Error code	Test result	Description/ Recommendation
1006	ABORT	<p>There are no associated B-channels in an ISDN "in-service" or "maintenance" service state. This is a NORMAL ABORT.</p> <ol style="list-style-type: none"> <li>1. Administer or release an ISDN trunk or PRI endpoint before retrying the test. For an ATM trunk, use the <b>status trunk grp#/mbr#</b> command to verify the ISDN trunk state.</li> <li>2. Retry this test when at least one B-channel is in the "in-service" or "maintenance" states.</li> </ol>
1113	ABORT	<p>The signaling channel is down. Therefore, no messages can be sent to the far-end switch or terminal adapter.</p> <ol style="list-style-type: none"> <li>1. Examine the results of Tests #636 and follow recommendations provided there.</li> </ol>
2100	ABORT	<p>Could not allocate the necessary system resources to run this test.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
2500 or none	ABORT	<p>Internal system error or administration problem</p> <ol style="list-style-type: none"> <li>1. Determine if any B-channels are administered.</li> <li>2. If there are none, then this is a normal ABORT, since this test cannot run unless at least one B-channel is administered.</li> <li>3. If at least one B-channels is administered, there is an internal system error. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
	FAIL	<p>Internal system error</p> <ol style="list-style-type: none"> <li>1. See description of ABORT with Error Code 2500.</li> </ol>
	PASS	<p>A message was sent to the far-end switch or terminal adapter. The ISDN PRI specification allows up to 2 minutes for a reply.</p> <ol style="list-style-type: none"> <li>1. Check the Error Log for ATM-SGRP errors of type 2305 for evidence of a Remote Layer 3 Query failure.</li> <li>2. If no new errors were logged since this test was run, then this switch and the far-end switch can exchange call control messages.</li> <li>3. If there is still a problem with a particular ATM trunk, busyout the trunk and run the long test sequence, paying particular attention to the results of Test #258 (ISDN Test Call).</li> </ol>

## ATM-TRK (circuit emulation service circuit pack)

---

MO name (in alarm log)	Alarm level	Initial command to run <sup>1</sup>	Full name of MO
ATM-TRK	MAJOR	test board UUCSS	ATM TRUNK (ATM Circuit Emulation Service)
ATM-TRK	MINOR	test board UUCSS	ATM TRUNK (ATM Circuit Emulation Service)
ATM-TRK	WARNING	test board UUCSS	ATM TRUNK (ATM Circuit Emulation Service)

1. UU is the universal cabinet number (1 for PPN, 2 - 44 for EPNs). C is the carrier designation (A, B, C, D, or E). SS is the number of the slot in which the circuit pack resides (01 to 21).

This maintenance object explains how you test and repair TN230x ATM Interface circuit packs (TN2305 and TN2306) that have been administered as virtual ISDN-PRI trunks for ATM Circuit Emulation Service (CES). The maintenance instructions for TN230x circuit packs that have been administered as Expansion Interfaces for WAN connectivity are in the [“ATM-EI \(Expansion Interface Circuit Pack\)”](#) maintenance object.

### Description

---

The TN2305 and TN2306 ([Table 5-99](#)) are dual-purpose ATM circuit packs that can be administered as either personality:

- [“ATM circuit emulation service”](#) or virtual ISDN-PRI signaling trunks.
- Expansion Interfaces (ATM-EI) for Port Network Connectivity (ATM-PNC) between the PPN and the EPNs.

Either circuit pack “personality” requires SONET OC-3 or SDH STM-1 fiber cable connections between the circuit pack and the ATM switch. As a trunk board, it supports direct connection between ATM CES circuit packs without an intervening ATM switch.

Table 5-99. R7 ATM-TRK circuit packs

Circuit pack	Channel types	Interface	Fiber	Echo cancellation
TN2305	B and D channels	24 or 32 channel	Multi mode	Y
TN2306	B and D channels	24 or 32 channel	Single mode	Y

**NOTE:**

TN230x circuit packs are not interchangeable.

**ATM circuit emulation service**

Under ATM Circuit Emulation Service (CES), you simulate ISDN-PRI circuits by assigning ports to *signaling groups*. Each signaling group represents a PRI circuit, and the ports in the group represent the D-channel and B-channels of that circuit. TN230x circuit packs support up to 248 ports per circuit pack.

**Virtual D-channels.** Non-facility associated signaling is not supported under ATM-CES, so you must reserve one port in each signaling group for use as a D-channel (channel 24 when emulating a T-1 ISDN facility, channel 16 when emulating an E-1 facility). The D-channel can be any physical port from 9 to 32.

**Virtual circuits.** The TN230x can support a varied number of virtual circuits, depending on the switch and the administration of the circuit pack. [Table 5-100](#) lists the possibilities for various G3V4 models.

Table 5-100. Circuit and channel capacities, for each DEFINITY model

Model	Ports	Emulated circuits (signaling groups)	Channels/circuit	Virtual D-channels	Virtual B-channels
R6csi	248	1 to 8	24 (T1), 31 (E1)	1-8	6-240
R6si	248	1 to 8	24 (T1), 31 (E1)	1-8	6-240
R6r	248	1 to 8	24 (T1), 31 (E1)	1-8	6-240

**5 Maintenance Objects for DEFINITY ONE**  
*ATM-TRK (circuit emulation service circuit pack)*

5-266

**Virtual trunk groups.** You cannot bundle physical DS1 ISDN-PRI circuits and virtual ATM-CES circuits into the same trunk groups. Virtual circuits can only be assigned to all-virtual, all-ATM trunk groups. [Table 5-101](#) lists the possible trunk-group capacities for various G3V4 models.

**Table 5-101. ATM CES capacities by DEFINITY model**

Mode l	Ports per trunk group (max)	Trunk groups per switch (max)	Trunks per switch (max)
R6csi	99	99	400
R6si	99	99	400
R6r	255	666	400

[Table 5-102](#) shows the ATM CES capacities for both T1 and E1 circuits.

**Table 5-102. Ports available for trunking, for each ISDN facility type**

Type	Channels per signaling group (trunk)	Max. signaling groups (trunks) per circuit pack	Max. available ports	Reserved ports	Total ports
T1:	24	8	192	ports 1-8	256
E1:	31	8	248	ports 1-8	256

**LEDs**

The ATM circuit pack LEDs give you a visual indication of the condition of the TN230x circuit pack ([Table 5-103](#)).

5 Maintenance Objects for DEFINITY ONE  
ATM-TRK (circuit emulation service circuit pack)

5-267

Table 5-103. ATM-TRK LED interpretation

LEDs	Condition	LED status
Red	Error (alarm logged)	On
Red and Green	Booting (LEDs being tested)	Blinking (on 200 ms, off 200 ms)
Green	Test/maintenance in progress	On
Yellow	Fiber Loss of Signal (LOS), LOF, MS_RDI, MS_AIS, LCD, HP_RDI, HP_AIS, LOP, PSC	Blinking fast (100 ms on, 100 ms off)
Yellow	Signal to ATM switch down	Blinking slowly (500 ms on, 500 ms off)
Yellow	One or more CES signaling groups administered	On
Yellow	CES signaling group not administered or not reporting to firmware	Off

**ATM-TRK-related commands**

[Table 5-104](#) lists some commands that can be useful in troubleshooting ATM errors and alarms.

Table 5-104. ATM CES troubleshooting commands

Command	Description
<b>display circuit-packs cabinet</b>	Displays the circuit packs in the cabinet, identifying ATM Trunk as well as ATM-EI boards. "ATM Interface" boards have not been administered as CES or PNC.
<b>display atm ports UUCSSppp</b>	Displays the 256 ports on the ATM board with the corresponding signaling and trunk group.
<b>list configuration atm</b>	Lists the ATM boards, identifying equipment location, board code, type, and vintage.
<b>list configuration trunks</b>	Lists boards identifying assigned ports. While the ATM board is listed, the 256 ports are not.

Continued on next page

Table 5-104. ATM CES troubleshooting commands — *Continued*

Command	Description
busyout/release atm signaling-group	Busyout or release of an ATM signaling group within a trunk group.
status atm signaling-group	Show current status of an ATM signaling group.
status trunk-group	Shows status of the trunk group (ATM signaling groups are part of trunk groups).

### Error log entries and test to clear values

Table 5-105. ATM-TRK error log entries

Error type	Aux Data	Associated Test	Alarm level	On/Off Board	Test to Clear Value
0	0	Any	Any		test board UUCSS
1(a)		None	MIN	ON	
18(b)	0	busy out board UUCSS	MIN	ON	release board UUCSS
23(c)	0	None	MIN	ON	
125(d)		None	MIN	ON	
257(e)	Any	Control Channel Loop Test (#52)	MIN	ON	test board UUCSS r 2
513(f)	Any	ATM Cross talk Test (#1298)	MIN	ON	test board UUCSS l r 1
769(g)	35	ATM Error Query Test #1259	WRN	OFF	test board UUCSS
770(g)	25	ATM Error Query Test #1259	WRN	OFF	test board UUCSS
771(h)	26	ATM Error Query Test #1259	WRN	OFF	test board UUCSS

*Continued on next page*

5 Maintenance Objects for DEFINITY ONE  
ATM-TRK (circuit emulation service circuit pack)

5-269

Table 5-105. ATM-TRK error log entries — Continued

Error type	Aux Data	Associated Test	Alarm level	On/Off Board	Test to Clear Value
1281(i)		ATM Board Error Query Test (#1259)	WRN/ MIN	OFF	test board UUCSS r 1
1537(j)	12	None	WRN/ MIN	ON	
1538(k)	0	None	WRN/ MIN	ON	reset board UUCSS
1794(l)	13	None	MIN	ON	
2049(m) )	15	None	WRN	OFF	test board UUCSS
2306(n)		None			
2561(o)		Packet interface test (#598)	MIN	ON	test board UUCSS r 2
2817(p)	1-24	ATM Board DSP test (#1293)	WRN/ MIN	ON	test board UUCSS
2818(p)	1-24		WRN/ MIN	ON	test board UUCSS
3330(q)	3		MIN	OFF	
3585(r)		ATM Board Error Query test (#1259)	WRN/ MIN	ON	test board UUCSS I
3841(s)	Any	None			
3842(t)	11	None			
3999(u)	Any	None			

## Notes:

- a. Error Type 1: the ATM-TRK circuit pack does not appear to be in its assigned slot.
  1. Make sure that the ATM-TRK circuit pack is installed correctly seated in the slot administered for the ATM trunk.
- b. Error Type 18: the ATM circuit pack is busied out.
  1. Run **release board UUCSS**.
- c. Error Type 23: an ATM trunk is administered, but the corresponding ATM-TRK circuit pack does not appear to be physically installed.

5 Maintenance Objects for DEFINITY ONE  
ATM-TRK (circuit emulation service circuit pack)

5-270

1. Make sure the ATM-TRK circuit pack is installed and correctly seated in the slot.
- d. Error Type 125: an ATM trunk is administered but a non-ATM-TRK circuit pack is installed in the corresponding slot. You have two options:
  - Replace the incorrect circuit pack with an ATM-TRK circuit pack.
  - Or re-administer the slot for the circuit pack that is physically present, locate the slot where the ATM-TRK circuit pack is actually installed, and re-administer the ATM trunk.
- e. Error Type 257: Control Channel Loop Test #52 failed. The circuit pack is not properly connected with the control channel on the TDM bus.
  1. Take the corrective action specified by Test #52?.
- f. Error Type 513: ATM Crosstalk Test (#1298) failed. The board is writing to or reading from a TDM time slot that is not allocated to the board, or the Digital Signal Processor (DSP) selected for this test has malfunctioned.
  1. Run **test board UUCSS**.
  2. Take the corrective action specified for Test #1298.
- g. Error Type 769, 770: the ATM switch is requesting too many LAPD retransmissions (off-board ATM cell corruption errors).

Error type	Aux data	Description
769	35	LAPD excessive retransmission requests
770	25	ATM uncorrectable cell headers - threshold

1. Check the connections between the fiber cable, the ATM-TRK circuit pack, and the ATM switch.
2. See the "[PKT-BUS \(Packet Bus\)](#)" for test and corrective procedures (Aux Data 35 only).
3. Determine what type of fiber is installed between the ATM-TRK circuit pack and the ATM switch.

If	Then
There is multimode fiber	Check the length of the fiber. If the cable is longer than 2 km, it is probably causing the errors.
There is single-mode fiber or the length of the multimode fiber is less than 2 km	The source of the errors may lie in the ATM facility, the ATM-TRK circuit pack, or the far-end circuit pack.

5 Maintenance Objects for DEFINITY ONE  
ATM-TRK (circuit emulation service circuit pack)

5-271

4. Perform ATM loopback tests on the near-end ATM-TRK circuit pack and on the far-end circuit pack or ATM switch.

If	Then
The ATM-TRK circuit pack fails the loopback test.	The problem is in the ATM-TRK circuit pack. Replace the circuit pack.
The far-end circuit pack or ATM switch fails the loopback test.	The problem is in the far-end circuit pack or ATM switch. Consult the circuit-pack or ATM switch documentation for advice.
The equipment at each end of the ATM span passes the loopback test	The problem is somewhere in the ATM span. Lack of bandwidth may be forcing an intermediate ATM switch to drop cells.

5. Check capacity and peak bandwidth consumption for the ATM span.

If	Then
The capacity of the span is inadequate or bandwidth consumption is too high.	Reduce traffic on the G3V4 switch to ensure that it is using no more than its subscribed bandwidth.

- h. Error Type 771: the ATM switch is sending cells with unknown Virtual Path-Identifier (VPI) and Virtual Channel-Identifier (VCI) addresses.
    1. Make sure that the ATM-TRK circuit-pack address is administered identically on the ATM switch and the DEFINITY ECS.
  - i. Error Type 1281: Board major signals error (loss of high-level signal). The far-end has detected a major problem in transmissions originating from the ATM-TRK circuit pack. The possible Aux Data values for this software counter are listed in [Table 5-106](#).
-

Table 5-106. Error type 1281 Aux data and repair procedures

Aux data	Alarm description	Repair procedure
15	SYSCLOCK failed	<p>The board is not locked to the TDM backplane clock signal. This is probably due to a Tone Clock problem.</p> <ol style="list-style-type: none"><li>1. Check for TDM-BUS or TONE-BD errors in the Error Log.</li><li>2. If no other problems are present, reset the circuit pack (<b>reset board UUCSS</b>)</li></ol>
16	Loss of Signal: LOS	<p>The fiber is not connected properly to the ATM-TRK board or ATM switch (or to the multiplexer section [MUX] if present). It is possible that the board transceivers are not functioning properly.</p> <ol style="list-style-type: none"><li>1. Run <b>test board UUCSS</b> command.</li><li>2. If Test #1259 fails with Error Code 16, connect a fiber back-to-back in a looped mode (one strand of fiber connecting the transmit transceiver to the receive transceiver of the board) and see if the yellow LED flash goes away. If it does the problem is off-board.</li><li>3. If the yellow LED continues to flash, replace the circuit pack.</li></ol>
17	Loss of Frame: LOF	<p>The fiber signal cannot obtain or maintain STM-1/OC-3 framing.</p> <ol style="list-style-type: none"><li>1. Try to move the fiber on the ATM switch side to a different port.</li><li>2. If the problem persists, reset the circuit pack (<b>reset board UUCSS</b>).</li></ol>

*Continued on next page*

Table 5-106. Error type 1281 Aux data and repair procedures — *Continued*

Aux data	Alarm description	Repair procedure
18	Multiplexer Section Alarm Indication Signal: MS_AIS	<p>There is a major problem on the far end (between multiplexer section [MUX] and the switch) that prohibits the circuit pack from sending a valid signal.</p> <ol style="list-style-type: none"><li>1. See if the ports at the MUX and/or the ATM switch are connected snugly.</li><li>2. Run <b>test board UUCSS</b> command</li><li>3. If Test #1259 fails with Error Code 18, connect a fiber back-to-back in a looped mode (one strand of fiber connecting the transmit transceiver to the receive transceiver of the board) and see if the yellow LED flash goes away.</li><li>4. If it does the problem is off-board.</li><li>5. If the yellow LED continues to flash, replace the circuit pack; if the error persists, escalate the problem.</li></ol>
19	Multiplexer Section Remote Defect Indicator: MS_RDI	<p>The far-end is detecting a major problem with the signal that this board is transmitting.</p> <ol style="list-style-type: none"><li>1. Make sure the ATM switch port (or a MUX port, if present between ATM switch and the ATM-TRK board) is the same as the ATM-TRK circuit pack's cable interface</li><li>2. Run <b>test board UUCSS</b> command.</li><li>3. If Test #1259 fails with Error Code 19, connect a fiber back-to-back in a looped mode (one strand of fiber connecting the transmit transceiver to the receive transceiver of the board) and see if the yellow LED flash goes away.</li><li>4. If it does the problem is off-board.</li><li>5. If the yellow LED continues to flash, replace the circuit pack; if the error persists, escalate the problem.</li></ol>
20	Loss of pointer: LOP	<p>ATM framer chip is unable to access the payload part of the signal.</p> <ol style="list-style-type: none"><li>1. Reset the board (<b>reset board UUCSS</b>).</li><li>2. If the error persists replace the board.</li></ol>

*Continued on next page*

Table 5-106. Error type 1281 Aux data and repair procedures — *Continued*

Aux data	Alarm description	Repair procedure
21	Path Signal Error (PSL) (STM1/SONET)	<p>The incoming signal payload is not set up for transmission of ATM data.</p> <ol style="list-style-type: none"><li>1. Make sure the ATM switch port (or a MUX port, if present between ATM switch and the ATM-TRK board) is the same as the ATM-TRK circuit pack's cable interface.</li></ol>
22	High-level Path Alarm Indication Signal: HP_AIS	<p>The payload is invalid.</p> <ol style="list-style-type: none"><li>1. Make sure the ATM switch port (or a MUX port, if present between ATM switch and the ATM-TRK board) is the same as the ATM-TRK circuit pack's cable interface.</li><li>2. Run <b>test board UUCSS</b>.</li><li>3. If Test #1259 fails with Error Code 22, connect a fiber back-to-back in a looped mode (one strand of fiber connecting the transmit transceiver to the receive transceiver of the board) and see if the yellow LED flash goes away.</li><li>4. If it does the problem is off-board.</li><li>5. If the yellow LED continues to flash, replace the circuit pack.</li></ol>
23	High-level path Remote defect Indicator: HP_RDI	<p>The far-end is detecting a major problem with the signal that this board is transmitting. The transmitted payload is invalid.</p> <ol style="list-style-type: none"><li>1. Make sure the ATM switch port (or a MUX port, if present between ATM switch and the ATM-TRK board) is the same as the ATM-TRK circuit pack's cable interface.</li><li>2. Run <b>test board UUCSS</b> command; if the Test #1259 fails with Error Code 23, connect a fiber back-to-back in a looped mode (one strand of fiber connecting the transmit transceiver to the receive transceiver of the board) and see if the yellow LED flash goes away.</li><li>3. If it does the problem is off-board.</li><li>4. If the yellow LED continues to flash, replace the circuit pack.</li></ol>

*Continued on next page*

Table 5-106. Error type 1281 Aux data and repair procedures — *Continued*

Aux data	Alarm description	Repair procedure
24	Loss of cell delineation (LCD)	On board ATM framer chip is not able to frame cells based on the cell header. <ol style="list-style-type: none"><li>1. Reset the board (<b>reset board UUCSS</b>).</li><li>2. If the error persists, replace the board.</li></ol>
27	SIGCON_DOWN ATM switch high level signal.	The board cannot communicate with the ATM switch. <ol style="list-style-type: none"><li>1. Busyout the board (busyout board UUCSS).</li><li>2. Test the board (<b>test board long UUCSS</b>).</li><li>3. If Test #1260 fails, replace the board.</li><li>4. If Test #1260 passes, make sure the ATM address on both the DEFINITY and the ATM switch sides are the same for this board.</li><li>5. If the address is the same, change the port on the ATM switch side.</li><li>6. If the error is resolved, the problem is on the ATM switch port.</li></ol>

- a. Error Type 1537: LANHO bus timeout. The circuit pack is transmitting too many bytes on the LAN bus for a single frame. This may be due to:

- On-board fault
- Faulty data received on one of the circuit pack's external ports

If the error occurs 3 times in 10 minutes, the board is isolated from the Packet Bus and the board is alarmed. To clear the alarm:

1. Restore this circuit pack to the Packet Bus with this command sequence:
  - a. **busyout board UUCSS**
  - b. **reset board UUCSS**
  - c. **test board UUCSS long**
  - d. **release board UUCSS**
2. If the problem persists and there are no ["PKT-BUS \(Packet Bus\)"](#) or port alarms, replace the circuit pack.

- b. Error Type 1538: The ATM-TRK circuit pack is hyperactive (sending an abnormal number of control messages to the processor). Use the following command sequence for this ATM-TRK circuit pack:
  1. **busyout board UUCSS**
  2. **reset board UUCSS**
  3. **test board UUCSS long**
  4. **release board UUCSS**
  5. If this error persists, replace the circuit pack.
- c. Error Type 1794: LANHO transmit FIFO overflow. The circuit pack's transmit buffers have overflowed.
  1. Run **test board UUCSS r 5**.

If	Then
Test #598 fails	Replace the circuit pack.

- d. Error Type 2049: ACL Link Failure (link is down). The ATM Control Link (ACL) has failed, communication has been interrupted between the SPE and the ATM-TRK circuit packs on the system, and signaling-group parameters are not communicated across the packet bus.
  1. Check the [“PKT-BUS \(Packet Bus\)”](#) and [“SYS-LINK \(System Links\)”](#) maintenance objects, and follow the repair procedures indicated.
  2. Run **test board UUCSS** against the ATM-TRK circuit pack.

If	Then
Test 598 fails.	Follow the repair procedures suggested for that test.

- e. Error Type 2306: too many parity errors in data received from the LAN/packet bus.
  1. Run **test board UUCSS**.

If	Then
Test 598 fails.	Follow the repair procedures suggested for that test
Test 598 passes.	See the <a href="#">“PKT-BUS (Packet Bus)”</a> maintenance object, and perform the specified repair.
There are no errors against the packet bus maintenance object.	This may be a transient condition. Do nothing now, but escalate if the error occurs repeatedly.

5 Maintenance Objects for DEFINITY ONE  
ATM-TRK (circuit emulation service circuit pack)

5-277

- f. Error Type 2561: Packet Interface Loop Around Test (598) Failure. The ATM-TRK circuit pack has failed, the packet bus has a minor alarm active, or the packet bus is out of service.

1. Run **test board UUCSS**.

If	Then
Test 598 fails.	Follow the repair procedures suggested for that test
Test 598 passes.	See the " <a href="#">PKT-BUS (Packet Bus)</a> " maintenance object, and perform the specified repair.
There are no errors against the packet bus maintenance object.	This may be a transient condition. Do nothing now, but escalate if the error occurs repeatedly.

- g. Error Type 2817, 2818: DSP failure detected along the circuit path.

1. Run **test board UUCSS**.
2. Follow the repair procedures suggested for Test #1293.

Error type	Description
2818	One or more DSPs failed. The <code>Aux Data</code> field contains the ID number of DSP that failed
2817	DSP test failure. The <code>Aux Data</code> field contains the following information about the failed DSPs: <ul style="list-style-type: none"> <li>■ X is the number of talker DSPs</li> <li>■ Y is the number of listener DSPs</li> <li>■ Z is the number of echo-cancelling DSPs</li> </ul>

- h. Error Type 3330: LANHO critical error. The circuit pack reports that the on-board LANHO chip is insane (possibly due to a problem in Packet Bus arbitration, in the transmission line frame, or in the circuit pack itself). The circuit pack cannot talk to the Packet Bus.

1. Check for "[PKT-BUS \(Packet Bus\)](#)" alarms.

If	Then
There is a packet-bus alarm.	There is probably a packet-bus problem, particularly if other circuit packs on the packet bus report the same error. See the " <a href="#">PKT-BUS (Packet Bus)</a> " maintenance object and the packet-bus fault-isolation and recovery sections of the maintenance manual for repair procedures.
There are no packet-bus alarms.	Run the following command sequence: <b>busyout board UUCSS</b> <b>reset board UUCSS.</b> <b>test board UUCSS long</b> release board UUCSS
The problem persists.	Replace the ATM-TRK circuit pack.

- i. Error Type 3585: Major board alarm; failure of critical components involved in the operation of the circuit pack. The circuit pack has failed, and the switch may no longer recognize it.

Aux Data	Description
1	ATM framer chip failure
2	NCE failed
4	TDM PLD failed
5	All DSPs on the circuit pack have failed
6	Receive Network Processor (RNP) failed
7	Transmit Network Processor (TNP) failed
8	MEMORY read/write failure
9	DUART failure

1. Run **test board UUCSS long**.

If	Then
Test #1259 fails with Error Code XXYY and XX is an AUX value in the preceding table	Replace the ATM-TRK circuit pack.
The system does not recognize the circuit pack	Replace the ATM-TRK circuit pack.

5 Maintenance Objects for DEFINITY ONE

ATM-TRK (circuit emulation service circuit pack)

5-279

- j. Error Type 3841: the ATM-TRK circuit pack received an unrecognized message from the switch and responded with an inconsistent down-link error message.
  - 1. Do nothing. This error does not affect service.
- k. Error Type 3842: LANHO Receive FIFO Overflow error; the packet bus is delivering data to the ATM-TRK circuit pack faster than the circuit pack can distribute it to the endpoint.
  - 1. Do nothing. The circuit pack can recover by itself.
- l. Error Type 3999: circuit pack sent a large number of control channel messages to the switch within a short period of time.

If	Then
Error Type 1538 is also present	Circuit pack is taken out of service
If Error Type 1538 is not present	<p>Circuit pack is <i>not</i> taken out of service, but has generated 50% of the messages necessary to be considered hyperactive.</p> <ul style="list-style-type: none"> <li>■ This may be normal during heavy traffic.</li> <li>■ If the error is logged during light traffic, it may indicate a problem with the circuit pack or the equipment attached to it.</li> </ul>

**System technician-demanded tests: descriptions  
and error codes**

Always investigate problems in the order presented. When you clear one of the error codes associated with a given test, you clear errors generated by other tests in the testing sequence. If you clear errors out of order, you can lose important information.

**Table 5-107. System technician-demanded tests: ATM-TRK**

Order of investigation	Short test sequence	Long test sequence	Reset board sequence	D/ND <sup>1</sup>
ATM Board Time Of Day Update (#1261)		X		ND
Connection Audit Test (#50)		X		ND
Control Channel Loop Test (#52)		X		ND
Packet Interface Loop Around Test (#598)	X	X		ND
ATM DSP Test (#1293)	X	X		ND
ATM Board Framer Looparound Test (#1260)		X		D
ATM Board Error Query Test (#1259)	X	X		ND
ATM Cross Talk Test (#1298)		X		ND
ATM Board Reset (#1256)			X	D

---

1. D = Destructive, ND = Non-destructive

---

**Connection audit test (#50)**

Non-destructive (in a sane switch environment).

The Connection Audit test updates TDM time slots. It sends network-update Control Channel Message Set (CCMS) messages that tell the ATM-TRK circuit pack to listen to, talk to, or disconnect particular time slots.

The test passes if software successfully sends the downlink network-update messages. It aborts otherwise.

**CAUTION:**

*Though normally non-destructive, this test might unintentionally tear down an active call if the connection-manager software's tables are corrupt.*

**Table 5-108. TEST #50 connection audit test**

Error code	Test result	Description/ Recommendation
None 2100	ABORT	System resources required for this test are not available. 1. Retry the command up to 5 times at 1-minute intervals.
1019	ABORT	The test aborted because a test was already running on the port. 1. Retry the command up to 5 times at 1-minute intervals.
	FAIL	Internal system error 1. Retry the command up to 5 times at 1-minute intervals.

*Continued on next page*

Table 5-108. TEST #50 connection audit test — *Continued*

Error code	Test result	Description/ Recommendation
	PASS	The circuit pack has been updated with its translation.
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board). This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"><li>1. Check the board translations.</li><li>2. If the ATM-TRK circuit pack is not administered, run <b>add atm trunk UUCSS</b>.</li><li>3. If the ATM-TRK circuit pack is administered correctly, check the error log.</li><li>4. If ATM-TRK circuit pack is hyperactive, shut down, and reseal the circuit pack to force re-initialization.</li><li>5. If the ATM-TRK circuit pack is correctly inserted, run <b>busyout board</b>.</li><li>6. Run <b>reset board</b>.</li><li>7. Run <b>release busy board</b>.</li><li>8. Run <b>test board long</b> to re-establish the linkage between the internal ID and the port.</li></ol>

**Control channel loop test (#52)**

The non-destructive Control Channel Loop Test is part of the maintenance subsystem's "[XXX-BD \(Common Port Circuit Pack\)](#)" feature. The Common Port Board test sends board vintage queries to a port circuit pack and checks the responses. CCMS downlink notifications tell the circuit pack which TDM Bus (A or B) carries the control channel and which carries the touch tones.

The test passes if the port circuit pack responds. The test aborts if the circuit pack does not respond. The test fails otherwise.

Table 5-109. Control channel test #52

Error code	Test result	Description/ Recommendation
2000	ABORT	Test request timed out.
2100	ABORT	Could not allocate needed system resources.
2500	ABORT	Internal system error 1. Retry the command up to 3 times at 1-minute intervals.
	FAIL	The ATM circuit pack responded incorrectly. 1. Retry the command up to 3 times at 1-minute intervals. 2. If the test continues to fail, reset the ATM-TRK circuit pack ( <b>reset board UUCSS</b> ). 3. If test continues to fail, replace the circuit pack or transceiver.
	PASS	The ATM-TRK circuit pack is communicating correctly with the software.
0	NO BOARD	Circuit pack not detected. 1. Check the error log for Error 125 (wrong board) or Error 131 (no board), and correct any errors found. 2. Make sure that the ATM-TRK circuit pack is properly translated and inserted. 3. Check for Error 1538 (hyperactivity). If hyperactive, run <b>reset board UUCSS</b> . 4. Run the test again. If it fails, replace the ATM-TRK circuit pack, and retest.

**Packet interface loop around test (#598)**

This nondestructive test checks the ATM-TRK circuit pack's packet-bus interface. The LANHO chip sends data through the bus and back to itself. [Table 5-40](#) describes this test, substituting "CES mode" for "PNC mode."

If the data received is consistent with the data sent, the test passes; otherwise it fails. The test does not run if the packet bus in the specified port network has a minor alarm, or is out of service, or if the packet but in the PPN is out of service.

**Table 5-110. Packet interface loop around test (#598)**

Error code	Test result	Description/ Recommendation
1144	ABORT	The packet bus in the PPN has a major alarm against it. <ol style="list-style-type: none"> <li>1. Run <b>display alarms</b> and <b>display errors</b>.</li> <li>2. Perform the "<a href="#">PKT-BUS (Packet Bus)</a>" repair procedures associated with the alarms.</li> <li>3. Retry the command.</li> </ol>
2000	ABORT	Test request timed out. <ol style="list-style-type: none"> <li>1. Retry the command up to 3 times at 1-minute intervals.</li> <li>2. If the test fails repeatedly, run <b>reset board UUCSS</b>.</li> <li>3. If the test continues to fail, replace the ATM-TRK circuit pack.</li> </ol>
2012	ABORT	Internal system error.
2100	ABORT	Could not allocate needed system resources. <ol style="list-style-type: none"> <li>1. Retry the command up to 5 times at 1-minute intervals.</li> </ol>
ANY	FAIL	Data packet not received correctly by the ATM Interface circuit pack. <ol style="list-style-type: none"> <li>1. Retry the command up to 5 times at 1-minute intervals.</li> <li>2. If the test continues to fail, replace the ATM-TRK circuit pack.</li> </ol>
	PASS	The Packet Interface Test passed.

**ATM board reset (#1256)****This test is destructive.**

This test checks the sanity of the angel processor using the Sanity and Control Interface (SAKI) test (Common Port Board test #53). It resets the circuit pack if the SAKI test fails and runs the test again. The ATM Board Reset test passes if SAKI can successfully reset and retest the board.

Before running the SAKI test, you must:

- Move synchronization off the ATM-TRK circuit pack
- Busyout the ATM-TRK circuit pack

The test aborts if the ATM-TRK circuit pack is supplying synchronization.

Table 5-111. ATM board reset (#1256)

Error code	Test result	Description/ Recommendation
1005	ABORT	Wrong circuit pack configuration to run this test. The ATM CES Trunk Interface circuit pack provides timing for the system and cannot be reset without major system disruptions. <ol style="list-style-type: none"> <li>1. Set synchronization to another ATM CES trunk circuit pack or to the Tone-Clock circuit pack and test again.</li> </ol>
1015	ABORT	Test cannot be run because the ATM-TRK circuit pack has not been busied out. <ol style="list-style-type: none"> <li>1. Busyout out the circuit pack (<b>busyout board UUCSS</b>).</li> <li>2. Repeat the test (<b>test board UUCSS long</b>).</li> </ol>
None	ABORT	Could not allocate the required system resources <ol style="list-style-type: none"> <li>1. Retry the command up to 5 times at 1-minute intervals.</li> <li>2. If the test continues to abort escalate the problem.</li> </ol>
2000	ABORT	Sanity test timed out. <ol style="list-style-type: none"> <li>1. Wait 5 minutes. Then see if ATM-TRK circuit pack is visible to the system by running <b>list config all</b>.</li> <li>2. If the ATM-TRK circuit pack is visible (<b>list configuration all</b>), run the test again, and escalate if the problem recurs.</li> <li>3. If the ATM-TRK circuit pack is not visible to the system (<b>list configuration all</b>), re-seat the ATM-TRK circuit pack, and retest.</li> <li>4. If the ATM-TRK circuit pack is still not recognized by the system, replace the board.</li> </ol>

*Continued on next page*

5 Maintenance Objects for DEFINITY ONE  
ATM-TRK (circuit emulation service circuit pack)

5-286

Table 5-111. ATM board reset (#1256) — *Continued*

Error code	Test result	Description/ Recommendation
2100	ABORT	Could not allocate required system resources 1. Retry the command up to 5 times at 1-minute intervals.
2500	ABORT	Internal system error. 1. Try to reset the circuit pack ( <b>reset board UUCSS</b> ).
1	FAIL	The circuit pack failed to reset
2	FAIL	The circuit pack failed to restart. 1. Retry command. 2. If the problem persists, replace the ATM-TRK circuit pack.
	PASS	The ATM-TRK circuit pack is successfully reset.
0	NO BOARD	No board detected. 1. Check the error log for Error 125 (wrong board) or Error 131 (no board), and perform the appropriate repair, if needed. 2. Ensure that the board is properly translated and inserted. 3. Check for Error 1538 (hyperactivity). If hyperactive, run <b>reset board UUCSS</b> . 4. Run the test again. If it fails, replace the ATM-TRK circuit pack, and retest.

**ATM board error query test (#1259)**

This non-destructive ATM Error Query Test retrieves the most severe, active, on- and off-board problem from the ATM-TRK circuit pack's firmware and increments error counts in the Error Log.

The test passes if there are no errors and fails otherwise. A passing test clears the software counters; a failure increments the counter associated with the problem that caused the failure and clears the others.

**Table 5-112. ATM board error query test (#1259)**

Error code	Test result	Description/ Recommendation
2000	ABORT	Test request timed out.
2031	ABORT	SCD failure. Unable to sent down-link message.
2100	ABORT	Could not allocate needed system resources.
2500	ABORT	Internal system error <ol style="list-style-type: none"><li>1. Retry the command up to 3 times at 1-minute intervals.</li></ol>
XXYY	FAIL	On-board error XX ( <a href="#">Table 5-113</a> ) and/or off-board error YY ( <a href="#">Table 5-114</a> ). <ol style="list-style-type: none"><li>1. Examine the error logs and repair any errors found.</li></ol>
	PASS	The ATM circuit pack has passed this test. No service effecting errors/alarms have been detected on board.
0	NO BOARD	ATM-TRK circuit pack not found <ol style="list-style-type: none"><li>1. Check the error log, and correct Error 125 (wrong board) or Error 131 (no board), if found.</li><li>2. Make sure that the board is properly translated and inserted.</li><li>3. Check for hyperactivity (Error 1538). Run <b>reset board UUCSS</b> if hyperactive.</li><li>4. Run the test again. If it fails, replace the board, and retest.</li></ol>

## Aux data XX

Table 5-113. Aux data XX for ATM board error query test (#1259)

If XX=	Then
1	ATM framer chip failed
2	NCE chip failed
3	LANHO critical error
4	TDM Programmable Logic Device Failed
5	All on-board DSPs failed
6	Receive Network Processor failed
7	Transmit Network Processor failed
8	Memory read failed
9	Dual UART chip failed
10	LANHO receive parity error
11	LANHO FIFO over flow error
12	LAN bus time out.
13	LANHO Xmit FIFO overflow error
14	One or more on-board DSPs failed

## Aux data YY

Table 5-114. Aux data YY for ATM board error query test (#1259)

If YY=	Then
15	Back plane clock failed
16	Loss of signal
17	Loss of frame
18	MS alarm indication signal error
19	MS remote defect indicator error

*Continued on next page*

Table 5-114. Aux data YY for ATM board error query test (#1259) — *Continued*

If YY=	Then
20	Loss of Pointer
21	Path Signal Level mismatch
22	High-level Path alarm indication signal
23	High-level Path remote defect indicator
24	Loss of Cell Delineation
25	Uncorrectable headers sent by the ATM switch.
26	Too may cells with invalid VPI/VCI combination.
27	The signalling link between the board and the ATM switch is down.
28	Board to ATM switch connection is down
34	AAL5 Excessive retransmission requests -per VC
35	LAPD Excessive retransmission requests - per VC

## ATM board framer looparound test (#1260)

### Destructive

This test verifies the board's circuit (Time Division Multiplexing) and packet paths using an on-board, dummy virtual circuit. Before running the test, you must

- Busyout the ATM-TRK circuit pack (**busyout board UUCSS**) and
- Switch synchronization (**change synchronization**) from the ATM-TRK circuit pack

If the ATM-TRK circuit pack is supplying synchronization, the test aborts.

The test sends a digital counter from one of the tone generators via one of the TDM bus time slots. The ATM framer interface converts this digital counter to ATM cells and loops them back internally. The ATM-TRK circuit pack converts the cells back to a digital counter and sends it to the tone receiver for verification. If the circuit pack passes the circuit check, the software checks the packet path by sending a packet from the packet-interface circuit pack to the ATM-TRK circuit pack via the ATM protocol stack.

Table 5-115. ATM board framer looparound test (#1260)

Error code	Test result	Description/ Recommendation
1002	ABORT	<p>Time slots could not be allocated. Traffic may be heavy or time slots may be out-of-service.</p> <ol style="list-style-type: none"><li>1. Run <b>display errors</b>, and perform repairs associated with TDM-BUS errors.</li><li>2. Retry the command up to 3 times at 1-minute intervals.</li></ol>
1003	ABORT	<p>Tone receiver could not be allocated.</p> <ol style="list-style-type: none"><li>1. Run <b>display errors</b>, and perform the repairs associated with TTR-LEV and TONE-PT errors.</li></ol> <p>The test cannot run unless there is at least one Tone Detector available on the network that holds the ATM-TRK circuit pack.</p> <ol style="list-style-type: none"><li>2. Retry the command up to 3 times at 1-minute intervals.</li></ol>
1015	ABORT	<p>ATM-TRK circuit pack not busied out</p> <ol style="list-style-type: none"><li>1. Busyout the ATM circuit pack.</li><li>2. Rerun the command.</li></ol>
1033	ABORT	<p>ATM-TRK circuit pack not found</p> <ol style="list-style-type: none"><li>1. See if the switch can see the circuit pack. Run status Trunk Group.</li><li>2. Retry the command.</li></ol>
1139	ABORT	<p>Major alarm on the EPN packet bus</p> <ol style="list-style-type: none"><li>1. Run <b>display alarms</b>, and perform the repairs associated with <a href="#">“PKT-BUS (Packet Bus)”</a> errors.</li><li>2. Run <b>display errors</b>, and perform the repairs associated with <a href="#">“PKT-BUS (Packet Bus)”</a> errors.</li><li>3. Retry the command.</li></ol>
1141	ABORT	<p>Packet-interface circuit pack out of service</p> <ol style="list-style-type: none"><li>1. See <a href="#">“PKT-INT (Packet Interface)”</a>.</li></ol>

*Continued on next page*

Table 5-115. ATM board framer looparound test (#1260) — *Continued*

Error code	Test result	Description/ Recommendation
1144	ABORT	Major alarm on the PPN packet bus <ol style="list-style-type: none"><li>1. Run <b>display alarms</b>, and perform the repairs associated with <a href="#">“PKT-BUS (Packet Bus)”</a>.</li><li>2. Run <b>display errors</b>, and perform the repairs associated with <a href="#">“PKT-BUS (Packet Bus)”</a>.</li><li>3. Retry the command.</li></ol>
1394	ABORT	ATM-TRK circuit pack out of service <ol style="list-style-type: none"><li>1. Run ATM Board Reset Test #1256.</li></ol>
2000	ABORT	Request timed out. <ol style="list-style-type: none"><li>1. Retry the command up to 3 times at 1-minute intervals.</li></ol>
2060	ABORT	Packet-bus link has failed. <ol style="list-style-type: none"><li>1. Retry the command up to 3 times at 1-minute intervals.</li><li>2. If the test continues to abort, run <b>display errors</b>, and perform the repairs associated with PKT-INT errors.</li></ol>
2100	ABORT	Could not allocate the necessary system resources to run this test.
2500	ABORT	Internal system error <ol style="list-style-type: none"><li>1. Retry the command up to 3 times at 1-minute intervals.</li></ol>
1	FAIL	Test tone not detected over the looparound; packet-path test aborted. <ol style="list-style-type: none"><li>1. Test the active tone clock on the port network, and verify that a tone is reaching the ATM-TRK circuit pack. If not, correct the condition.</li><li>2. Run <b>test board UUCSS long</b>.</li><li>3. If the test continues to fail, replace the ATM-TRK circuit pack or transceiver.</li><li>4. Rerun <b>test board UUCSS long</b>.</li></ol>

*Continued on next page*

Table 5-115. ATM board framer looparound test (#1260) — *Continued*

Error code	Test result	Description/ Recommendation
2	FAIL	<p>TN1655 Packet Interface circuit pack could not detect the correct data packet.</p> <ol style="list-style-type: none"><li>1. Test the TN1655 Packet Interface circuit pack to verify that it is functioning properly. If not, correct the condition.</li><li>2. Run <b>display errors</b>, and perform the repairs associated with DS1 CONV-BD errors, if applicable.</li><li>3. Run <b>display alarms</b>, and perform the repairs associated with DS1 CONV-BD alarms, if applicable.</li><li>4. Run <b>test board UUCSS long</b>.</li><li>5. If this test continues to fail, replace the ATM-TRK circuit pack.</li><li>6. Run <b>test board UUCSS long</b>.</li></ol>
3	FAIL	<p>Distorted tone returned</p> <ol style="list-style-type: none"><li>1. Test the active tone clock on the port network, and verify that a tone is reaching the ATM-TRK circuit pack. If not, correct the condition.</li><li>2. Run <b>test board UUCSS long</b>.</li><li>3. If the test continues to fail, replace the ATM-TRK circuit pack.</li><li>4. Run <b>test board UUCSS long</b>.</li></ol>
4	FAIL	<p>Unable to create TDM-path loop.</p> <ol style="list-style-type: none"><li>1. Retry the command up to 3 times at 1-minute intervals.</li><li>2. If this test continues to fail, replace the ATM-TRK circuit pack.</li><li>3. Run <b>test board UUCSS long</b>.</li></ol>
5	FAIL	<p>Unable to create packet-path loop.</p> <ol style="list-style-type: none"><li>1. Retry the command up to 3 times at 1-minute intervals.</li><li>2. If this test continues to fail, replace the ATM-TRK circuit pack.</li><li>3. Rerun <b>test board UUCSS long</b>.</li></ol>

---

*Continued on next page*

Table 5-115. ATM board framer looparound test (#1260) — *Continued*

Error code	Test result	Description/ Recommendation
6	FAIL	A previously established looparound was not released. <ol style="list-style-type: none"><li>1. Run <b>reset board UUCSS</b>.</li><li>2. Retry the command up to 3 times at 1-minute intervals.</li><li>3. If this test continues to fail, replace the ATM-TRK circuit pack.</li><li>4. Rerun <b>test board UUCSS long</b>.</li></ol>
	PASS	The non-optical parts of the ATM-TRK circuit pack are functioning properly.
0	NO BOARD	ATM-TRK circuit pack not found <ol style="list-style-type: none"><li>1. Check the error log for Error 125 (wrong board) or Error 131 (no board), and correct as necessary.</li><li>2. Check that the board is properly translated and inserted.</li><li>3. Check for Error 1538 (hyperactivity), and run <b>reset board UUCSS</b> if necessary.</li><li>4. Rerun <b>test board UUCSS long</b>.</li><li>5. If the test fails, replace the board, and rerun <b>test board UUCSS long</b>.</li></ol>

## ATM board time of day update (#1261)

This non-destructive test updates the system time that the ATM-TRK circuit pack uses for SDH/SONET performance monitoring and synchronizes the ATM-TRK circuit pack with the DEFINITY system clock. The test is run during initialization, scheduled maintenance, and craft long tests.

Table 5-116. ATM board time of day update (#1261)

Error code	Test result	Description/ Recommendation
2031	FAIL	The attempt to send the message to the ATM-TRK circuit pack was not successful.
2500	FAIL	Internal system error. Did not send the time of day information to the board. <ol style="list-style-type: none"> <li>1. Retry the command up to 3 times at 1-minute intervals.</li> <li>2. If the test aborts with the same error code, escalate the problem.</li> </ol>
	PASS	The ATM-TRK circuit pack is successfully updated with system time. <ol style="list-style-type: none"> <li>1. If the <b>status port-network</b> command still indicates that this link is down, it is possible that one or both of the ATM-TRK circuit packs have been busied out.</li> <li>2. If the link still does not come up, reset one or both ATM-TRK circuit packs on the link.</li> </ol>
0	NO BOARD	No board detected. <ol style="list-style-type: none"> <li>1. Check the error log for wrong board (Error 125) or no board (Error 131). Resolve either of these issues, if applicable.</li> <li>2. Check that the board is properly translated and inserted. If so, check for hyperactivity (Error 1538). If hyperactive, use the <b>reset board UUCSS</b> command.</li> <li>3. Run the test again. If it fails, the board may be bad. Replace the board and retest.</li> </ol>

**ATM board DSP test (#1293)**

Non-destructive

There are three kinds of digital signal processors (DSPs): talkers, listeners, and echo cancelers. Talkers put data on the TDM bus, listeners take data off the TDM bus, and echo cancelers filter out echoes of the main transmission. Firmware allocates DSPs in sets of three (one of each type), up to a maximum of 8 sets. This has three parts, one for each type of DSP. If the test fails for all DSPs, a MAJOR alarm is raised. If the test fails for one or more DSPs, a MINOR alarm is raised. If a DSP is busy, the test passes for that DSP. The test aborts if system resources are not available. Each part of the test returns the number of DSPs that passed or failed. The test is run during initialization, error analysis testing, periodic, scheduled, and craft short and long testing.

Table 5-117. ATM board DSP test (#1293)

Error code	Test result	Description/ Recommendation
1002	ABORT	<p>Could not allocate time slots. Traffic may be heavy or time slots may be out-of-service</p> <ol style="list-style-type: none"> <li>1. Run <b>display errors</b>, and follow associated repair procedures for TDM-BUS.</li> <li>2. Retry the command up to 3 times at 1-minute intervals.</li> </ol>
1003	ABORT	<p>Could not allocate a tone detector. Too few tone detectors present or tone detectors out-of-service.</p> <ol style="list-style-type: none"> <li>1. Run <b>display errors</b>, and follow the repair procedures associated with any "<a href="#">TTR-LEV (TTR Level)</a>" errors that appear.</li> <li>2. Make sure that there is at least one tone detector on the network that holds the ATM-TRK circuit pack.</li> <li>3. Resolve any "<a href="#">TONE-PT (Tone Generator)</a>" errors listed in the Error Log.</li> <li>4. Retry the command up to 3 times at 1-minute intervals.</li> </ol>
1962	ABORT	<p>All DSPs are busy. This is a very unlikely event.</p> <ol style="list-style-type: none"> <li>1. Retry the command up to 3 times at 1-minute intervals.</li> </ol>
2000	ABORT	<p>Test timed out.</p> <ol style="list-style-type: none"> <li>1. If the ATM-TRK circuit pack is in standby, reset the board and run the test again after the ATM-TRK circuit pack is inserted.</li> <li>2. Examine the Error Log for Error 1218 (bad DSP).</li> <li>3. Run the test again.</li> </ol>

*Continued on next page*

Table 5-117. ATM board DSP test (#1293) — *Continued*

Error code	Test result	Description/ Recommendation
2100	ABORT	Could not allocate required system resources.
2302	ABORT	Inconsistent uplink message from the ATM-TRK circuit pack.
2500	ABORT	Internal system error 1. Retry the command up to 5 times at 1-minute intervals.
2752	ABORT	Circuit pack not a TN2305A/2306A.
XYZ	FAIL	There is at least one bad DSP on the board. The <b>X</b> value indicates the number of bad talker DSPs, <b>Y</b> indicates the number of bad listener DSPs and <b>Z</b> indicates the number of bad echo canceler DSPs.  1. Test the Active Tone-Clock on the port network that contains the ATM-TRK circuit pack for dial-tone. Repair as needed.  2. Repeat the short test on the ATM-TRK circuit pack.  3. If the test continues to fail, check for service-affecting MINOR alarms. If a MINOR alarm is raised for Error Type 2817 or 1818, replace the circuit pack.  4. If a WARNING alarm is raised, this is a non-service-affecting error, and the circuit pack can still process calls.
XY8	PASS	The test passed for some or all DSPs. XY8 indicates the number of talker, listener, and echo-canceler DSPs for which the test passed (the rest of the DSPs were skipped). The <b>X</b> value indicates the number of good talker DSPs, <b>Y</b> indicates the number of good listener DSPs and <b>Z</b> indicates the number of good echo canceler DSPs.
0	NO BOARD	No board detected.  1. Check the Error Log for wrong board Error 125 (wrong board) or Error 131 (no board). Replace or insert the circuit pack if necessary.  2. Check that the board is properly translated and inserted.  3. If Error 1538 (hyperactivity) is listed in the Error Log, and run <b>reset board UUCSS</b> .  4. Run the test again, and, if it fails, replace the ATM-TRK circuit pack.  5. Retest.

### ATM cross talk test (#1298)

This nondestructive ATM Cross Talk test makes sure that TDM time slots are correctly allocated to connections. It is useful for diagnosing one-way or noisy connections. The test fails if the TDM programmable logic and/or the interface to the DSP is not operating properly. The test can take more than 10 minutes.

Table 5-118. ATM crosstalk test (#1298)

Error code	Test result	Description/ Recommendation
	ABORT	Could not allocate required system resources. 1. Retry the command up to 5 times at 1-minute intervals.
1002	ABORT	Could not allocate time slots. Traffic may be heavy or time slots may be out-of-service. 1. Identify and correct TDM-bus errors (if any) using the procedures in the <a href="#">"TDM-BUS (TDM Bus)"</a> maintenance object. 2. Repeat the test up to 5 times at 1-minute intervals.
1003	ABORT	Could not allocate a tone receiver. Too few tone detectors installed or tone detectors out-of-service. 1. Identify and correct any <a href="#">"TTR-LEV (TTR Level)"</a> errors listed in the Error Log. 2. Resolve any <a href="#">"TONE-PT (Tone Generator)"</a> errors listed in the Error Log. 3. Retry the test up to 5 times at 1-minute intervals a maximum.
2000	ABORT	Test timed out.
2100	ABORT	Could not allocate required system resources 1. Retry the command 5 times at 1-minute intervals.
1962	ABORT	All TALKER DSPs are busy.
2302	ABORT	Inconsistent uplink message from the ATM-TRK circuit pack. 1. Retry the command up to 3 times at 1-minute intervals.

*Continued on next page*

5 Maintenance Objects for DEFINITY ONE  
ATM-TRK (circuit emulation service circuit pack)

5-298

Table 5-118. ATM crosstalk test (#1298) — *Continued*

Error code	Test result	Description/ Recommendation
2752	ABORT	The circuit pack in this location is not a TN2305A/2306A.
1-8, None	FAIL	ATM-TRK circuit pack writing on unauthorized TDM time slots. The error code indicates the number of TALKER DSPs that are at fault. These DSPs cannot be used again until this test of the ATM DSP Test (#1293) tells the circuit pack to use them again.  1. Retry the command up to 3 times at 1-minute intervals.  2. If the failure persists, replace the circuit pack.
1-8	PASS	ATM-TRK circuit pack not talking to un-authorized time slots on the TDM bus. The error code indicates the number of TALKER DSPs tested.

**Line Circuit Pack**

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run <sup>1</sup>	Full Name of MO
BRI-BD	MAJOR	test board PCSS I	ISDN-BRI Line Circuit Pack
BRI-BD	MINOR	test board PCSS I	ISDN-BRI Line Circuit Pack
BRI-BD	WARNING	test board PCSS sh	ISDN-BRI Line Circuit Pack
LGATE-BD	MAJOR	test board PCSS I	DEFINITY LAN Gateway
LGATE-BD	MINOR	test board PCSS I	DEFINITY LAN Gateway
LGATE-BD	WARNING	test board PCSS sh	DEFINITY LAN Gateway

1. Where P is the port network number (1 for PPN); C is the carrier designation (A, B, or C); and SS is the address of the slot in the carrier where the circuit pack is located (01, 02, ..., etc.).

**NOTE:**

Some of the information in this section is reserved for future use.

ISDN-BRI Line is a packet port circuit pack that provides access to ISDN-BRI endpoints. The ISDN-BRI Line circuit pack supports 12 ports, each of which provides access to ISDN stations. Voice and circuit-switched data from the ISDN stations are carried on the Time Division Multiplex (TDM) Bus.

## LEDS

The ISDN-BRI Line circuit pack performs extensive initialization tests and lights both the red and green LEDS during the initialization testing. See [“LED interpretation”](#) in [Chapter 1, “Maintenance Concepts for DEFINITY ONE”](#), for more details on circuit pack status LEDS.

## Hardware Error Log Entries and Test to Clear Values

Table 5-119. BRI-BD Error Log Entries

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
0 <sup>1</sup>	0	Any	Any	Any	test board PCSS sh r 1
1(a)	Any	None	MINOR	ON	
18(b)	0	busyout board PCSS	WARNING	OFF	release board PCSS
23(c)	0	None	WARNING	OFF	
257(d)	65535	Control Channel Loop Test (#52)	MINOR	ON	test board PCSS r 20
513(e)	4352 to 4357				
769(f)	4358				
1025(g)	4363	NPE Audit Test (#50)			
1293 to 1294 (h)	46088 to 46096	SAKI Sanity Test (#534)	MINOR	ON	See footnote (h)
1537 to 1538 (i)	46082		MINOR	ON	
1793 (j)	46080		MINOR	ON	
1794 (j)	46094		MINOR	ON	
1795 (j)	46085		MINOR	ON	
2306 (j)		LANBIC Receive Parity Error Counter Test (#595)			
3330 (k)	46083		MINOR	OFF	
3840 (l)	4096 to 4101				
3843 (m)	46097				
3999 (n)	Any	None			

1. Run the Short Test Sequence first. If all tests pass, run the Long Test Sequence. Refer to the appropriate test description and follow the recommended procedures.

## Notes:

- a. This error indicates the circuit pack totally stopped functioning or it was physically removed from the system.

**NOTE:**

The alarm is logged approximately 11 minutes after the circuit pack has been removed and/or SAKI Sanity Test (#53) fails.

If the circuit pack is not in the system, insert a circuit pack (in the same slot as the error indicates) to resolve this error. Or, if the circuit pack is in the system and the red LED is on, then follow the instructions for a Red alarm in the [“Circuit pack status LEDs”](#) section in [Chapter 1, “Maintenance Concepts for DEFINITY ONE”](#).

- b. This circuit pack has been busied out via the **busyout board PCSS** command.
- c. Port(s) has (have) been administered on this circuit pack but the circuit pack is not physically present.
- d. This error indicates transient communication problems between the switch and this circuit pack. Execute the **test board PCSS** command and refer to the repair procedures for the [“Control Channel Loop Around Test \(#52\)”](#) on [page 5-1244](#).
- e. An on-board hardware failure has been detected by the circuit pack.

The reported aux data values correspond to the following detected errors:

4352	External RAM error
4353	Internal RAM error
4355	ROM Checksum error
4357	Instruction set error

Reset the circuit pack by executing the **busyout board PCSS** and **reset board PCSS** commands. When it is reset, the circuit pack executes a set of tests to detect the presence of any of the above faults. The detection of one of these errors during initialization causes the circuit pack to lock-up and appear insane to the system. See the repair procedure in footnote (a) for error type 1.

- f. This error is reported by the circuit pack when it detects a program logic error. While no action is required, this error may lead to errors of other types being reported against this circuit pack.
- g. This error is reported by the circuit pack when it cannot update NPE memory and read it back. This error type can be ignored, but may lead to errors of other types being reported against this circuit pack.

5 Maintenance Objects for DEFINITY ONE  
ATM-TRK (circuit emulation service circuit pack)

5-301

- h. A critical hardware failure has been detected on the circuit pack. Reset the circuit pack via the **busyout board PCSS** and **reset board PCSS** commands. If the Circuit Pack Restart Test (#594) passes, then the on-board circuitry is healthy. Retire the alarm via the **test board PCSS long clear** command. If the Circuit Pack Restart Test (#594) fails, replace the circuit pack.

The reported error types correspond to the following detected errors:

- |      |                                     |
|------|-------------------------------------|
| 1293 | On-board auxiliary processor insane |
| 1294 | Internal memory access error        |

- i. These error types are reported when the following errors are detected:

- |      |  |
|------|--|
| 1537 | Frame overrun at Packet Bus interface. This condition may be caused by an on-board fault or by faulty data received on one of the circuit pack's external ports. If any of the ports on this circuit pack are alarmed, refer to the repair procedures for those maintenance objects.   |
| 1538 | Circuit packet is hyperactive; that is, it is flooding the switch with messages sent over the control channel. The circuit pack is taken out-of-service when a threshold number of these errors is reported to the switch. Clear the alarm via the following commands: <b>busyout board PCSS</b> , <b>reset board PCSS</b> , <b>test board PCSS long clear</b> , <b>release board PCSS</b> . If the error recurs within 10 minutes, then replace the circuit pack. |

- j. These errors indicate that the circuit pack is having problems transmitting data to the Packet Bus.

- |      |   |
|------|---|
| 1793 | Parity errors are detected when transmitting data to the Packet Bus.  |
| 1794 | Overflow of Packet Bus transmit buffers has occurred.   |
| 1795 | Circuit pack cannot find end of frame when transmitting to Packet Bus. Clear the alarm via the following commands: <b>busyout board PCSS</b> , <b>reset board PCSS</b> , <b>test board PCSS long clear</b> , <b>release board PCSS</b> . If the error recurs within 10 minutes, then replace the circuit pack.  |
| 2306 | This error occurs when the circuit pack detects an error in a received frame from the packet bus. These errors are most likely caused by a packet bus problem, but may be due to a circuit pack fault. An invalid Link Access Procedure Data (LAPD) frame error occurs if the frame contains a bad Cyclical Redundancy Checking (CRC), is greater than the maximum length, or violates the link level protocol. When bus parity errors are reported, the LANBIC Receive Parity Error Counter Test (#595) should be performed to determine if the condition had cleared. |

5 Maintenance Objects for DEFINITY ONE  
ATM-TRK (circuit emulation service circuit pack)

5-302

- k. A critical failure has been detected in the Packet Bus interface of the circuit pack. This failure may be due to either a Packet Bus fault or an on-board fault. The probability of this error being related to Packet bus problems increases with the number of ISDN-BRI circuit packs displaying this error.

If the Packet Bus is not alarmed, reset the circuit pack via the **busyout board PCSS** and **reset board PCSS** commands. If the Circuit Pack Restart Test (#594) passes, then the on-board circuitry is healthy. Retire the alarm via the **test board PCSS long clear** command. If the Circuit Pack Restart Test (#594) fails, replace the circuit pack. If the problem persists after complying with the above instructions, then follow normal escalation procedures.

- l. These errors are not service-affecting. No action is required. These errors are reported by the circuit pack when it receives a bad control channel message from the switch. The auxiliary data identifies the following error events:

4096	Bad major heading
4097	Bad port number
4098	Bad data
4099	Bad sub-qualifier
4100	State inconsistency
4101	Inconsistent downlink message

- m. This error is not service-affecting. No action is required.

3843	Bad translation RAM detected, but call continues by using another translation location.
------	---

- n. Error type 3999— Indicates that the circuit pack sent a large number of control channel messages to the switch within a short period of time. If error type 1538 is also present, then the circuit pack was taken out-of-service due to hyperactivity. If error type 1538 is not present, then the circuit pack has not been taken out-of-service, but it has generated 50% of the messages necessary to be considered hyperactive. This may be completely normal during heavy traffic periods. However, if this error type is logged when the circuit pack is being lightly used, it may indicate a problem with the circuit pack or the equipment attached to it.
-

## System Technician-Demanded Tests: Descriptions and Error Codes

---

Always investigate tests in the order presented in the following tables when inspecting errors in the system. By clearing error codes associated with the *Control Channel Loop Around Test*, for example, you may also clear errors generated from other tests in the testing sequence.

Order of Investigation	Short Test Sequence	Long Test Sequence	D/ND <sup>1</sup>
Control Channel Loop-Around Test (#52)	X	X	ND
NPE Audit Test (#50)		X	ND
LANBIC Receive Parity Error Counter Test (#595)		X	ND

- 
1. D = Destructive; ND = Nondestructive

### NPE Audit Test (#50)

Refer to the repair procedure described in [“NPE Connection Audit Test \(#50\)” on page 5-1243](#).

### Control Channel Loop Around Test (#52)

Refer to the repair procedure described in [“Control Channel Loop Around Test \(#52\)” on page 5-1244](#).

### SAKI Sanity Test (#53)

Refer to the repair procedure described in [“SAKI Sanity Test \(#53\)” on page 5-1245](#).

### LANBIC Receive Parity Error Counter Test (#595)

**This test is destructive.**

The test reads and clears the LANBIC Receive Parity Error Counter on the circuit pack. This counter is incremented by the circuit pack when it detects a parity error in data received from the Packet Bus.

These errors may be indicative of a circuit pack problem, Packet Bus problem, or a problem with another circuit pack on the bus. This test is useful for verifying the repair of the problem.

5 Maintenance Objects for DEFINITY ONE  
ATM-TRK (circuit emulation service circuit pack)

5-304

Table 5-120. TEST #595 LANBIC Receive Parity Error Counter Test

Error Code	Test Result	Description/ Recommendation
2000	ABORT	Response to the test was not received from the circuit pack within the allowable time period. <ol style="list-style-type: none"><li>1. If the test aborts repeatedly a maximum of 5 times, reset the circuit pack via the <b>busyout board PCSS</b> and <b>reset board PCSS</b> commands.</li><li>2. If the test aborts again, replace the circuit pack.</li></ol>
2100	ABORT	Could not allocate the necessary system resources to run this test.
2012	ABORT	Internal system error <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
1-10	FAIL	The circuit pack is still detecting errors of this type. The error code indicates the value of the on-board error counter. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li><li>2. If the test continues to fail, verify the validity of the Packet Bus. Run the Packet Bus maintenance test with the <b>test pkt P long</b> command.</li><li>3. If the Packet Bus test passes, check the validity of the circuit pack. Execute a test that involves data transmission onto the Packet Bus. For example, the BRI may use the connectivity tests of the port-level maintenance object (BRI-PORT) by executing the <b>test port PCSSpp</b> command. Refer to the repair procedures for the executed test if it fails. Otherwise, proceed to the next step.</li><li>4. Other circuit packs on the Packet Bus may be the cause of the parity error. Use the <b>display errors</b> command to check the Error Log for other circuit packs that are alarmed. If any alarms are present for the other circuit packs, retire those alarms also. Then, rerun the LANBIC Receive Parity Error Counter Test (#595) on this circuit pack.</li></ol>
	PASS	No errors detected by circuit pack.

## BRI-BD/LGATE-BD (ISDN-BRI Line Circuit Pack)

---

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run <sup>1</sup>	Full Name of MO
BRI-BD	MAJOR	test board PCSS I	ISDN-BRI Line Circuit Pack
BRI-BD	MINOR	test board PCSS I	ISDN-BRI Line Circuit Pack
BRI-BD	WARNING	test board PCSS sh	ISDN-BRI Line Circuit Pack
LGATE-BD	MAJOR	test board PCSS I	DEFINITY LAN Gateway
LGATE-BD	MINOR	test board PCSS I	DEFINITY LAN Gateway
LGATE-BD	WARNING	test board PCSS sh	DEFINITY LAN Gateway

- Where P is the port network number (1 for PPN and 2 or 3 for EPN); C is the carrier designation (A, B, C, D, or E); and SS is the address of the slot in the carrier where the circuit pack is located (01, 02, ..., etc.).

**NOTE:**

Some of the information in this section is reserved for future use.

**CAUTION:**

*A detailed flowchart for isolating and resolving Packet Bus faults is included in Chapter 9, "Packet Bus Fault Isolation and Correction". This flowchart, along with the other information presented in the chapter, can help in resolving problems that involve more than a single station or circuit pack. Whenever the repair procedures for this Maintenance Object refer to Packet Bus and/or Packet Control maintenance, be sure to reference Chapter 9, "Packet Bus Fault Isolation and Correction", in addition to the relevant MO documentation.*

ISDN-BRI Line is a packet port circuit pack that provides access to ISDN-BRI endpoints. The ISDN-BRI Line circuit pack supports 12 ports, each of which provides access to ISDN stations. Voice and circuit-switched data from the ISDN stations are carried on the Time Division Multiplex (TDM) Bus. Signaling is carried over the Packet Bus.

## LEDS

---

The ISDN-BRI Line circuit pack performs extensive initialization tests and lights both the red and green LEDS during the initialization testing. See Chapter 7, "LED Interpretation", for more details on circuit pack status LEDS.

## Hardware Error Log Entries and Test to Clear Values

Table 5-121. BRI-BD Error Log Entries

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
0 <sup>1</sup>	0	Any	Any	Any	test board PCSS sh r 1
1(a)	Any	None	MINOR	ON	
18(b)	0	busyout board PCSS	WARNING	OFF	release board PCSS
23(c)	0	None	WARNING	OFF	
257(d)	65535	Control Channel Loop Test (#52)	MINOR	ON	test board PCSS r 20
513(e)	4352 to 4357				
769(f)	4358				
1025(g)	4363	NPE Audit Test (#50)			
1293 to 1294 (h)	46088 to 46096	SAKI Sanity Test (#534)	MINOR	ON	See footnote (h)
1537 to 1538 (i)	46082		MINOR	ON	
1793 (j)	46080		MINOR	ON	
1794 (j)	46094		MINOR	ON	
1795 (j)	46085		MINOR	ON	
2306 (j)		LANBIC Receive Parity Error Counter Test (#595)			
3330 (k)	46083		MINOR	OFF	
3840 (l)	4096 to 4101				
3843 (m)	46097				
3999 (n)	Any	None			

1. Run the Short Test Sequence first. If all tests pass, run the Long Test Sequence. Refer to the appropriate test description and follow the recommended procedures.

## Notes:

- a. This error indicates the circuit pack totally stopped functioning or it was physically removed from the system.

 **NOTE:**

The alarm is logged approximately 11 minutes after the circuit pack has been removed and/or SAKI Sanity Test (#53) fails.

If the circuit pack is not in the system, insert a circuit pack (in the same slot as the error indicates) to resolve this error. Or, if the circuit pack is in the system and the red LED is on, then follow the instructions for “Red (alarm)” in the “Control and Port Circuit Pack Status LEDs” section in Chapter 7, “LED Interpretation”. (Also, refer to the “Handling Control Circuit Packs” section in Chapter 5, “Routine Maintenance Procedures”.

- b. This circuit pack has been busied out via the **busyout board PCSS** command.
- c. Port(s) has (have) been administered on this circuit pack but the circuit pack is not physically present.
- d. This error indicates transient communication problems between the switch and this circuit pack. Execute the **test board PCSS** command and refer to the repair procedures for the [“Control Channel Loop Around Test \(#52\)” on page 5-1244](#).
- e. An on-board hardware failure has been detected by the circuit pack.

The reported aux data values correspond to the following detected errors:

4352	External RAM error
4353	Internal RAM error
4355	ROM Checksum error
4357	Instruction set error

Reset the circuit pack by executing the **busyout board PCSS** and **reset board PCSS** commands. When it is reset, the circuit pack executes a set of tests to detect the presence of any of the above faults. The detection of one of these errors during initialization causes the circuit pack to lock-up and appear insane to the system. See the repair procedure in footnote (a) for error type 1.

- f. This error is reported by the circuit pack when it detects a program logic error. While no action is required, this error may lead to errors of other types being reported against this circuit pack.
- g. This error is reported by the circuit pack when it cannot update NPE memory and read it back. This error type can be ignored, but may lead to errors of other types being reported against this circuit pack.

5 Maintenance Objects for DEFINITY ONE  
BRI-BD/LGATE-BD (ISDN-BRI Line Circuit Pack)

5-308

- h. A critical hardware failure has been detected on the circuit pack. Reset the circuit pack via the **busyout board PCSS** and **reset board PCSS** commands. If the Circuit Pack Restart Test (#594) passes, then the on-board circuitry is healthy. Retire the alarm via the **test board PCSS long clear** command. If the Circuit Pack Restart Test (#594) fails, replace the circuit pack.

The reported error types correspond to the following detected errors:

1293	On-board auxiliary processor insane
1294	Internal memory access error

- i. These error types are reported when the following errors are detected:

1537 Frame overrun at Packet Bus interface. This condition may be caused by an on-board fault or by faulty data received on one of the circuit pack's external ports. If any of the ports on this circuit pack are alarmed, refer to the repair procedures for those maintenance objects.

1538 Circuit packet is hyperactive; that is, it is flooding the switch with messages sent over the control channel. The circuit pack is taken out-of-service when a threshold number of these errors is reported to the switch. Clear the alarm via the following commands: **busyout board PCSS**, **reset board PCSS**, **test board PCSS long clear**, **release board PCSS**. If the error recurs within 10 minutes, then replace the circuit pack.

- j. These errors indicate that the circuit pack is having problems transmitting data to the Packet Bus.

1793 Parity errors are detected when transmitting data to the Packet Bus.

1794 Overflow of Packet Bus transmit buffers has occurred.

1795 Circuit pack cannot find end of frame when transmitting to Packet Bus. Clear the alarm via the following commands: **busyout board PCSS**, **reset board PCSS**, **test board PCSS long clear**, **release board PCSS**. If the error recurs within 10 minutes, then replace the circuit pack.

2306 This error occurs when the circuit pack detects an error in a received frame from the packet bus. These errors are most likely caused by a packet bus problem, but may be due to a circuit pack fault. An invalid Link Access Procedure Data (LAPD) frame error occurs if the frame contains a bad Cyclical Redundancy Checking (CRC), is greater than the maximum length, or violates the link level protocol. When bus parity errors are reported, the LANBIC Receive Parity Error Counter Test (#595) should be performed to determine if the condition had cleared. Refer to the "[PKT-BUS \(Packet Bus\)](#)" Maintenance documentation to determine if the problem is isolated to this circuit pack or if the problem is caused by Packet Bus faults.

- k. A critical failure has been detected in the Packet Bus interface of the circuit pack. This failure may be due to either a Packet Bus fault or an on-board fault. If the Packet Bus is alarmed, refer to the "[PKT-BUS \(Packet Bus\)](#)" section and Chapter 9, "Packet Bus Fault Isolation and Correction" for recommended repair procedures. The probability of this error being related to Packet bus problems increases with the number of ISDN-BRI circuit packs displaying this error.

If the Packet Bus is not alarmed, reset the circuit pack via the **busyout board PCSS** and **reset board PCSS** commands. If the Circuit Pack Restart Test (#594) passes, then the on-board circuitry is healthy. Retire the alarm via the **test board PCSS long clear** command. If the Circuit Pack Restart Test (#594) fails, replace the circuit pack. If the problem persists after complying with the above instructions, then follow normal escalation procedures.

- l. These errors are not service-affecting. No action is required. These errors are reported by the circuit pack when it receives a bad control channel message from the switch. The auxiliary data identifies the following error events:

4096	Bad major heading
4097	Bad port number
4098	Bad data
4099	Bad sub-qualifier
4100	State inconsistency
4101	Inconsistent downlink message

- m. This error is not service-affecting. No action is required.

3843 Bad translation RAM detected, but call continues by using another translation location.

**5 Maintenance Objects for DEFINITY ONE**  
*BRI-BD/LGATE-BD (ISDN-BRI Line Circuit Pack)*

5-310

- n. Error type 3999 — Indicates that the circuit pack sent a large number of control channel messages to the switch within a short period of time. If error type 1538 is also present, then the circuit pack was taken out-of-service due to hyperactivity. If error type 1538 is not present, then the circuit pack has not been taken out-of-service, but it has generated 50% of the messages necessary to be considered hyperactive. This may be completely normal during heavy traffic periods. However, if this error type is logged when the circuit pack is being lightly used, it may indicate a problem with the circuit pack or the equipment attached to it.

**System Technician-Demanded Tests: Descriptions  
and Error Codes**

Always investigate tests in the order presented in the following tables when inspecting errors in the system. By clearing error codes associated with the *Control Channel Loop Around Test*, for example, you may also clear errors generated from other tests in the testing sequence.

Order of Investigation	Short Test Sequence	Long Test Sequence	D/ND <sup>1</sup>
Control Channel Loop-Around Test (#52)	X	X	ND
NPE Audit Test (#50)		X	ND
LANBIC Receive Parity Error Counter Test (#595)		X	ND

1. D = Destructive; ND = Nondestructive

**NPE Audit Test (#50)**

Refer to the repair procedure described in the [“NPE Audit Test \(#50\)” on page 5-310](#).

**Control Channel Loop Around Test (#52)**

Refer to the repair procedure described in the [“Control Channel Loop Around Test \(#52\)” on page 5-310](#).

**SAKI Sanity Test (#53)**

Refer to the repair procedure described in the [“SAKI Sanity Test \(#53\)” on page 5-310](#).

**LANBIC Receive Parity Error Counter Test (#595)****This test is destructive.**

The test reads and clears the LANBIC Receive Parity Error Counter on the circuit pack. This counter is incremented by the circuit pack when it detects a parity error in data received from the Packet Bus.

These errors may be indicative of a circuit pack problem, Packet Bus problem, or a problem with another circuit pack on the bus. This test is useful for verifying the repair of the problem.

**Table 5-122. TEST #595 LANBIC Receive Parity Error Counter Test**

Error Code	Test Result	Description/ Recommendation
2000	ABORT	Response to the test was not received from the circuit pack within the allowable time period. <ol style="list-style-type: none"> <li>1. If the test aborts repeatedly a maximum of five times, reset the circuit pack via the <b>busyout board PCSS</b> and <b>reset board PCSS</b> commands.</li> <li>2. If the test aborts again, replace the circuit pack.</li> </ol>
2100	ABORT	Could not allocate the necessary system resources to run this test.
2012	ABORT	Internal System Error <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
1-10	FAIL	The circuit pack is still detecting errors of this type. The error code indicates the value of the on-board error counter. <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> <li>2. If the test continues to fail, verify the validity of the Packet Bus. Run the Packet Bus maintenance test with the <b>test pkt P long</b> command. If any Packet Bus tests fail, refer to the <a href="#">“PKT-BUS (Packet Bus)”</a> Maintenance documentation for recommended repair procedures.</li> <li>3. If the Packet Bus test passes, check the validity of the circuit pack. Execute a test that involves data transmission onto the Packet Bus. For example, the BRI may use the connectivity tests of the port-level maintenance object (BRI-PORT) by executing the <b>test port PCSSpp</b> command. Refer to the repair procedures for the executed test if it fails. Otherwise, proceed to the next step.</li> <li>4. Other circuit packs on the Packet Bus may be the cause of the parity error. Use the <b>display errors</b> command to check the Error Log for other circuit packs that are alarmed. If any alarms are present for the other circuit packs, retire those alarms also. Then, rerun the LANBIC Receive Parity Error Counter Test (#595) on this circuit pack.</li> </ol>
	PASS	No errors detected by circuit pack.

5 Maintenance Objects for DEFINITY ONE  
BRI-DAT (ISDN-BRI)

5-312

**BRI-DAT (ISDN-BRI)**

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run	Full Name of MO
BRI-DAT	WARNING <sup>1</sup>	test data-module	ISDN-BRI Standalone Data Module

1. The alarm level for ASAI adjuncts may be administered using the **set options** command. The alarm level can be set independently for Off-Board and On-Board alarms to WARNING, MINOR, or MAJOR for all ASAI adjuncts in the system.

Refer to [“BRI-SET, ASAI-ADJ, BRI-DAT” on page 5-334.](#)

**BRI-PORT (ISDN-BRI Port),  
ABRI-PORT (ASAI ISDN-BRI Port)**

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run <sup>1</sup>	Full Name of MO
BRI-PORT	MINOR	test port PCSSpp l	ISDN-BRI Port
BRI-PORT	WARNING	test port PCSSpp sh	ISDN-BRI Port
ABRI-PORT	MAJOR <sup>2,3</sup>	test port PCSSpp l	ASAI ISDN-BRI Port
ABRI-PORT	WARNING <sup>2,3</sup>	test port PCSSpp l	ASAI ISDN-BRI Port
ATT-PORT	MAJOR <sup>2,3</sup>	test port PCSSpp l	Lucent Adjunct ISDN-BRI Port
ATT-PORT	WARNING <sup>2,3</sup>	test port PCSSpp l	Lucent Adjunct ISDN-BRI Port
LGATE-PORT	MAJOR <sup>2,3</sup>	test port PCSSpp l	Ethernet ASAI Port
LGATE-PORT	WARNING <sup>2,3</sup>	test port PCSSpp l	Ethernet ASAI Port
ATTE-PT	MAJOR <sup>2,3</sup>	test port PCSSpp l	Ethernet Lucent Adjunct Port
ATTE-PT	WARNING <sup>2,3</sup>	test port PCSSpp l	Ethernet Lucent Adjunct Port

1. Where P is the port network number (1 for PPN); C is the carrier designation; and SS is the address of the slot in the carrier where the circuit pack is located (01, 02, ..., etc.); and pp is the 2-digit port number (for example, 01).
2. The alarm level for ASAI and Lucent adjunct ports may be administered using the **set options** command. The alarm level can be set independently for Off-Board and On-Board alarms to WARNING, MINOR, or MAJOR for all ASAI and Lucent adjunct ports in the system.
3. All alarming for an ASAI and Lucent adjunct and OFF-BOARD alarming for an ASAI or Lucent port is disabled if the ASAI or Lucent adjunct asks the switch to suspend maintenance. When this occurs, an error and a WARNING alarm is logged against the ASAI or Lucent adjunct. The Hardware Error and Alarm Logs should be checked to see if the adjunct has disabled alarming.

**NOTE:**

Some of the information in this section is reserved for future use.

**WARNING:**

*If a significant Packet Bus failure occurs, errors and alarms may not be logged as expected for  
BRI-PORT/ABRI-PORT/ATT-PORT/LGATE-PT/ATTE-PT.*

The TN2208 LGATE MFB provides DEFINITY with the interface to Adjunct-Switch Application Interface (ASAI) and Lucent adjuncts (for example, CONVERSANT. Voice System). The circuit pack contains 12 ports of line circuit interface (although only 8 are usable by the switch), each of which operates with two B-channels (referred to as B1 and B2 throughout this section) and one D-channel as specified in the Lucent ISDN-BRI Specification. In this context, the term "ISDN-BRI port" is used to refer collectively to ports on the TN2208 circuit pack which are connected to ASAI or Lucent adjuncts.

The TN556C and TN2198 ISDN-BRI Line circuit packs provide DEFINITY with the interface to ISDN-BRI end points, Adjunct-Switch Application Interface (ASAI) and Lucent adjuncts (for example, CONVERSANT. Voice System). The circuit packs contain 12 ports of line circuit interface, each of which operates with two B-channels (referred to as B1 and B2 throughout this section) and one D-channel as specified in the Lucent ISDN-BRI Specification. In this context, the term "ISDN-BRI port" is used to refer collectively to ports on the TN556C and TN2198 circuit packs which are connected to either BRI endpoints or ASAI or Lucent adjuncts.

For BRI endpoints, each B-channel may support voice or circuit-switched data and may be circuit-switched simultaneously. The B-channels are not used on ports connected to ASAI or Lucent adjuncts. The D-channel is used for conveying signaling between the switch and a BRI endpoint(s) or ASAI or Lucent adjunct.

ISDN-BRI endpoints are available in various configurations. All endpoints require the D-channel to convey signaling information to the switch. Only one B-channel is required for a voice-only set or a stand-alone data module (BRI-DAT). A voice and data-capable set requires both B-channels (one for voice and one for data). Therefore, each TN556 or TN2198 port can support either two voice-only sets, two stand-alone data modules (BRI-DAT), or one voice and data-capable set. Only a single ASAI or Lucent adjunct may be connected to an ISDN-BRI port. Multiple adjuncts per line are not supported.

[Figure 5-12](#) illustrates the physical connection (solid line) between an ISDN-BRI Port and its associated ISDN-BRI set(s). Each physical connection allows for two B-channels and one D-channel. Each ISDN-BRI circuit pack can support up to 12 of these *physical* connections to different voice and voice/data sets or ASAI or Lucent adjuncts. On a TN2198 each ISDN-BRI circuit pack can support up to 12 *physical* connections to a NT1, which, in turn, connects to 2 terminals.

This section covers the maintenance documentation for ISDN-BRI ports. Some of the results of maintenance testing of ISDN-BRI ports may be affected by the health of the ISDN-BRI Line circuit pack (BRI-BD), BRI endpoint (BRI-SET), or ASAI adjunct (ASAI-AJ/LGATE-AJ) or Lucent adjunct (ATT\_AJ/ATTE-AJ). These interactions should be kept in mind when investigating the cause of ISDN-BRI port problems. For more information on the circuit pack and endpoints, refer to [“BRI-BD/LGATE-BD \(ISDN-BRI Line Circuit Pack\)” on page 5-305](#), BRI-SET (ISDN-BRI Endpoint) Maintenance documentation, and ASAI-AJ (Adjunct-Switch Application Interface) Maintenance documentation, ATT-AJ (Lucent Adjunct) Maintenance documentation, LGATE-AJ (Ethernet Adjunct-Switch Application Interface) Maintenance documentation, and ATTE-AJ (Ethernet Lucent Adjunct) Maintenance documentation.




Figure 5-12. ISDN-BRI Port Interactions

## Hardware Error Log Entries and Test to Clear Values

Table 5-123. ISDN-BRI Port Error Log Entries

Error Type	Aux Data	Associated Test	Alarm Level BRI-PORT	Alarm Level ABRI-PORT ATT-PORT LGATE-PORT ATTE-PT	On/ Off Board	Test to Clear Value
0 <sup>1</sup>	0	Any	Any	Any	Any	test port PCSSpp sh r 1
1 (a)	(a)	Level 1 Status Inquiry (#621)	WRN	MAJ/MIN/ WRN <sup>2</sup>	OFF	test port PCSSpp sh r 2
18		busyout port PCSSpp	WRN		OFF	release port PCSSpp
130 (b)			WRN		ON	test port PCSS sh
257 (c)	(c)	EPF Inquiry (#622)	WRN	MAJ/MIN/ WRN <sup>2</sup>	OFF	test port PCSSpp sh r 1
513 (d)	(d)	none	(d)	(d)	ON	
769 (e)	0	none	WRN	MAJ	OFF	
1281 (f)		NPE Crosstalk (#617)	MIN/ WRN <sup>2</sup>		ON	test port PCSSpp l r 2
1537 (g)	46210	CRC Error Counter (#623)	WRN	MAJ/MIN/ WRN <sup>2</sup>	OFF	
1793 (h)		BRI Port Local TDM	MIN/ WRN <sup>2</sup>		ON	test port PCSSpp l r 2
		Loop Around (#619)				
3841 (i)	46208	None				
3842 (j)	0	None				
3843 (k)	0	None				
3844 (l)	46223	None				
3845 (m)		None				
3846 (n)	TEI	None				
3847 (o)	0	None				

1. Run the Short Test Sequence first. If all tests pass, run the Long Test Sequence. Refer to the appropriate test description, and follow the recommended procedures.
2. Major and Minor alarms on this MO may be downgraded to Warning alarms based on the value used in the **set options** command.

## Notes:

- a. This error occurs when the Level 1 Status Inquiry fails or when the BRI circuit pack detects that Level 1 has been deactivated on the port. The aux data field contains one of the following values:
  - blank - this indicates that the Level 1 Status Inquiry failed.
  - 32773 - this is a message from the BRI-LINE circuit pack indicating Level 1 has been deactivated.

Refer to the repair procedures in [“Level 1 Status Inquiry Test \(#621\)” on page 5-326.](#)

- b. This error type indicates that the circuit pack has been removed or has been insane for more than 11 minutes. To clear the error, replace or reinsert the circuit pack.
- c. This error occurs when the EPF Status Inquiry fails due to an overcurrent condition or when the BRI-LINE circuit pack detects that the EPF is in an overcurrent condition. The aux data field contains one of the following values:
  - blank - this indicates that the EPF Status Inquiry failed due to an overcurrent condition.
  - 40988 - this indicates that the BRI-LINE circuit pack has detected an overcurrent condition and has turned the EPF off.

Execute the Short Test Sequence and see the repair procedures for Test #622.

- d. This error indicates that the circuit pack is having problems transmitting data to the Packet Bus, thus affecting the conveyance of signaling information over the D-channel. With Aux Data 46222, this error occurs when the Packet Bus transmit buffers overflow. This condition probably indicates a hardware problem. The BRI-PORT Alarm Level for the error with Aux Data 46222 is “MIN/WRN,” and the ABRI-PORT/ATT-PORT/LGATE-PT/ATTE-PT Alarm Level is “MAJ/MIN/WNR.” With Aux Data 0, this error occurs whenever the Packet Bus transmit FIFO buffers overflow. This condition can be caused by an on-board hardware problem as well as by problems on the Packet Bus that disrupt the BRI circuit pack’s ability to transmit data onto the Packet Bus. Use troubleshooting procedures for both on-board hardware problems and potential off-board Packet Bus problems. See the [“PKT-BUS \(Packet Bus\)”](#) Maintenance section in this chapter as well as Chapter 9, “Packet Bus Fault Isolation and Correction” for more details on Packet Bus troubleshooting procedures. The BRI-PORT Alarm Level for the error with Aux Data 0 is “MINOR,” and the ABRI-PORT/ATT-PORT/LGATE-PT/ATTE-PT Alarm Level is “MAJOR.”
- e. This error occurs when the NPE Crosstalk Test (#617) fails. Run the Long Test Sequence, and pay particular attention to the results of Test #617.

## 5 Maintenance Objects for DEFINITY ONE

*BRI-PORT (ISDN-BRI Port), ABRI-PORT (ASAI ISDN-BRI Port)*

5-317

- f. This error occurs when broadcast signaling links associated with this port have too much link establishment related traffic. This could occur if an endpoint on this port is sending link establishment traffic on a port level broadcast link, or if there are Level 1 problems on the port. Check the error logs for Level 1 errors. If Level 1 problems exist, follow the repair procedures listed in [“Level 1 Status Inquiry Test \(#621\)” on page 5-326](#). Software will suspend activity to this port for 75 minutes when the port is alarmed due to this error (note that service suspension does not occur if the port is an ABRI-PORT/LGATE-PT/ATTE-PT/ATT-PORT). If this problem persists, replace the endpoint or endpoints associated with this port. If replacing the endpoints does not fix the problem, follow normal escalation procedures.
- g. This error occurs when the port receives an invalid frame over the D-channel. When CRC errors exceed five within 15 minutes, the port is taken out of service for five seconds. If five more CRC errors are received within 15 minutes of the first set of five errors, the port is taken out of service for one minute. If five more CRC errors are received within 15 minutes of the last five, the port is taken out of service for 15 minutes.

This error is most likely due to a problem with the wiring to the set or adjunct, interference on the wiring due to a noise source or no termination (an open circuit). It usually does not indicate a problem with the circuit pack.

- Check the wiring to the endpoints or the adjunct.
  - If the problem persists, replace the endpoints or adjuncts.
- h. This error occurs when the BRI Port Local TDM Loop Around Test (#619) fails. Run the Long Test Sequence, and pay particular attention to the results of Test #619.

There are no Test to Clear Values for the following error types. The error types are simply provided as additional data that may prove useful while troubleshooting.

- i. This error occurs when a Layer 1 Transmission error is detected for the port. Run the Long Test Sequence, and pay particular attention to the results of the Layer 1 Transmission Error Counter Test (#624).
- j. A BRI port supports up to three Terminal Endpoint Identifiers (TEIs). This error occurs when the switch receives a request for a fourth TEI on a port. Check the number of endpoints administered for this port.
- k. This error occurs when an SPID initialization request is made from an endpoint and the switch determines that the SPID value is invalid or is a duplicate of another SPID that is already initialized at Layer 3 on the port. Check the administration of the endpoints.
- l. This error occurs when the circuit pack detects an overflow of its receive buffers. Run the Long Test Sequence, and pay particular attention to the results of the Receive First In First Out (FIFO) Overflow Error Counter Test (#625).

## 5 Maintenance Objects for DEFINITY ONE

*BRI-PORT (ISDN-BRI Port), ABRI-PORT (ASAI ISDN-BRI Port)*

5-318

- m. This error occurs when the BRI Port Local LAN Loop Around Test (#618) fails. Run the Long Test Sequence, and pay particular attention to the results of Test #618.
- n. This error most likely occurs when the Terminal Endpoint Identifier (TEI) administered for the ASAI or Lucent endpoint does not match the TEI administered in the ASAI or Lucent adjunct. Check the switch administration of the TEI against that of the adjunct, and make sure that both are using the same TEI.
- o. Indicates that sets on the port do not support Layer 3 initialization. Consult the Service Set documentation.

## System Technician-Demanded Tests: Descriptions and Error Codes

Always investigate tests in the order presented in the following tables when inspecting errors in the system. By clearing error codes associated with the *NPE Crosstalk Test*, for example, you may also clear errors generated from other tests in the testing sequence.

Order of Investigation	Short Test Sequence	Long Test Sequence	D/ND <sup>1</sup>
NPE Crosstalk Test (#617)		X	D
BRI Port Local LAN Loop Around Test (#618)		X	D
BRI Port Local TDM Loop Around Test (#619)		X	D
Electronic Power Feed Restoral Test (#620)	X	X	ND
Level 1 Status Inquiry Test (#621)	X	X	ND
Electronic Power Feed Inquiry Test (#622)	X	X	ND
CRC Error Counter Test (#623)		X	ND
Layer 1 Transmission Error Counter Test (#624)		X	ND
Receive FIFO Overflow Error Counter Test (#625)		X	ND
Clear Error Counters (#270)	X	X	ND

1. D = Destructive; ND = Nondestructive

**NOTE:**

The NPE Crosstalk Test and the BRI Port Local TDM Loop Around Test are not executed for ABRI-PORT/ATT-PORT/LGATE-PT/ATTE-PT.

**NPE Crosstalk Test (#617)****This test is destructive.**

One or more NPEs reside on each circuit pack with a TDM Bus interface. The NPE controls port connectivity and gain and provides conferencing functions on a per-port basis. The NPE Crosstalk Test verifies that this port's NPE channel talks on the selected time slot and never crosses over to time slots reserved for other connections. If the NPE is not working correctly, one-way and noisy connections may be observed. This test is part of a port's Long Test Sequence and takes approximately 20 to 30 seconds to complete. Crosstalk testing is performed on both B-channels (B1 and B2) associated with a BRI port. If this test fails on either channel, any endpoints connected to the port are taken out-of-service.

This test is not executed for ABRI-PORT/ATT-PORT/LGATE-PT/ATTE-PT because the B-channels associated with the port are not used by ASAI or Lucent adjuncts.

**Table 5-124. TEST #161 Loop Around Test**

Error Code	Test Result	Description/ Recommendation
1000	ABORT	System resources required to run this test are not available. The port may be busy with a valid call. Use the <b>display port PCSSpp</b> command to determine the station extension or trunk group/member number of the port. Use the <b>status bri-port PCSSpp</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. Wait until the port is idle before retesting. <ol style="list-style-type: none"> <li>1. If the port status is idle, then retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
1004	ABORT	The port has been seized by a user for a valid call. Use the <b>status station</b> command for the station associated with this port and determine when the port is available for testing. <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
1005	ABORT	This test is not valid for this type of translation. Ports administered as "ASAI" or "ADJK" can not run this test, because the B channels associated with the port are not used by ASAI or Lucent Adjunct Links. This is a normal condition.
2012	ABORT	Internal system error
2100	ABORT	Could not allocate the necessary resources to run this test. <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>

*Continued on next page*

Table 5-124. TEST #161 Loop Around Test — *Continued*

Error Code	Test Result	Description/ Recommendation
1, 2	FAIL	The NPE of the tested port was found to be transmitting in error. This causes noisy and unreliable connections. Error code 1 indicates that the NPE Crosstalk Test failed on Channel B1. Error code 2 indicates that the NPE Crosstalk Test failed on Channel B1. <ol style="list-style-type: none"><li>1. Replace circuit pack.</li></ol>
	PASS	The port is correctly using its allocated time slots. <ol style="list-style-type: none"><li>1. To be sure that this is not an intermittent problem, repeat this test a maximum of 10 times to make sure it continues to pass.</li><li>2. If complaints still exist, examine the station, connections, and wiring.</li></ol>

## BRI Port Local LAN Loop Around Test (#618)

### **This test is destructive.**

This test, which verifies the connectivity of a BRI port across the LAN Bus, executes only if the port is out-of-service. The test aborts if calls associated with the port are in-progress. Failures of this test indicate either on-board faults associated with the BRI-PORT hardware on the circuit pack or problems with the LAN Bus, which is used to form connectivity between the switch and the BRI-PORT.

The dotted lines in [Figure 5-13](#) show how a Loop Around Test is performed across the Packet Bus for the D-channel.




Figure 5-13. Path of the BRI Port Local LAN Loop Around

Table 5-125. TEST #618 BRI Port Local LAN Loop Around

Error Code	Test Result	Description/ Recommendation
1015	ABORT	<p>The port is not in the out-of-service state.</p> <ol style="list-style-type: none"> <li>1. Display the BRI Port Status form via the <b>status bri-port PCSSpp</b> command to determine which stations or adjuncts are on this port.</li> <li>2. Use the extension shown on this form in the <b>status station</b> command to determine if the station or adjunct is in use.</li> <li>3. If it is in use, wait until it is idle, and then busyout the port (using the <b>busyout port PCSSpp</b> command) to place it in the out-of-service state and repeat this test.</li> </ol> <p><b>⚠ WARNING:</b>  <i>Since the "busyout" command is destructive, execution of this command prior to the port being idle causes all calls associated with BRI endpoints and all transactions associated with ASAI or Lucent adjuncts on the port to be torn down. Note that third party calls established by an ASAI or Lucent adjunct remain connected even though the port is taken out-of-service.</i></p>

## 5 Maintenance Objects for DEFINITY ONE

BRI-PORT (ISDN-BRI Port), ABRI-PORT (ASAI ISDN-BRI Port)

5-322

Table 5-125. TEST #618 BRI Port Local LAN Loop Around — Continued

Error Code	Test Result	Description/ Recommendation
1139	ABORT	The Packet Bus in the port network is out-of-service. <ol style="list-style-type: none"> <li>1. Follow the repair procedures for the Packet Bus.</li> <li>2. After completing Step 1, execute the <b>test port long PCSSpp</b> command, and review the results of the BRI Port Local LAN Loop Around Test to verify the repair.</li> </ol>
1141	ABORT	The PKT-CTRL is out-of-service. <ol style="list-style-type: none"> <li>1. Follow the repair procedures for the PKT-CTRL.</li> <li>2. After completing Step 1, execute the <b>test port long PCSSpp</b> command, and review the results of the BRI Port Local LAN Loop Around Test to verify the repair.</li> </ol>
1144	ABORT	The PPN Packet Bus is out-of-service. <ol style="list-style-type: none"> <li>1. Follow the repair procedures for the Packet Bus.</li> <li>2. After completing Step 1, execute the <b>test port long PCSSpp</b> command, and review the results of the BRI Port Local LAN Loop Around Test to verify the repair.</li> </ol>
2012	ABORT	Internal system error
2100	ABORT	Could not allocate the necessary system resources to run this test. <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
	FAIL	The Loop Around Test has failed. <ol style="list-style-type: none"> <li>1. If the test fails repeatedly, attempt to reset the circuit pack if the other ports on the board are not in use. Reset the circuit pack by issuing the <b>busyout board PCSS</b> and the <b>reset board PCSS</b> commands.</li> <li>2. If the test fails again, execute <b>test pkt P</b> on the G3MT terminal. If this fails, follow failure procedures in "<a href="#">PKT-BUS (Packet Bus)</a>" section.</li> <li>3. If tests executed in Step 2 pass, the problem is local to the BRI board. Replace the circuit pack.</li> </ol>
	PASS	The BRI Port Local LAN Loop Around Test has passed.

## BRI Port Local TDM Loop Around Test (#619)

**This test is destructive.**

This test verifies the connectivity of a BRI port across the TDM Bus. It aborts if calls associated with the port are in progress. Failure of this test indicates an on-board fault associated with the port hardware on the circuit pack.


This Loop Around Test runs a series of individual tests on the two B-channels (B1 and B2) associated with the port. It is a collection of the following:

- A Loop Around Test across the TDM Bus for B1.
- A Conference Circuit Test for B1.
- A Loop Around Test across the TDM Bus for B2.
- A Conference Circuit Test for B2.

The tests are run in the above order. If one fails, the remaining tests in the sequence are not executed. An error code is returned at that point.

This test is not executed for ABRI-PORT/ATT-PORT/LGATE-PT/ATTE-PT because the B-channels associated with the port are not used by ASAI or Lucent adjuncts.

The dotted lines in [Figure 5-14](#) show how a Loop Around Test is performed for the B-channels. The figure shows a terminal connected to a BRI line board using a TN556. If a TN2198 is used, the terminal would be connected to a NT1, and the NT1 to the BRI board.



---

Figure 5-14. Path of the BRI Port Local TDM Loop Around

5 Maintenance Objects for DEFINITY ONE  
BRI-PORT (ISDN-BRI Port), ABRI-PORT (ASAI ISDN-BRI Port)

5-324

Table 5-126. TEST #619 BRI Port Local TDM Loop Around

Error Code	Test Result	Description/ Recommendation
1000	ABORT	<p>The system resources required to run this test are not available. The port may be busy with a valid call. Use the <b>display port PCSSpp</b> command to determine the station extension or trunk group/member number of the port. Use the <b>status bri-port PCSSpp</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. Wait until the port is idle before retesting.</p> <ol style="list-style-type: none"> <li>1. If the port is idle, then retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
1002	ABORT	<p>The system could not allocate time slots for the test. The system may be under heavy traffic conditions or it may have time slots out-of-service due to TDM-BUS errors. Refer to <a href="#">"TDM-BUS (TDM Bus)" on page 5-1116</a> to diagnose any active TDM Bus errors.</p> <ol style="list-style-type: none"> <li>1. If the system has no TDM-BUS errors and is not handling heavy traffic, repeat test at 1-minute intervals a maximum of 5 times.</li> </ol>
1003	ABORT	<p>The system could not allocate a tone receiver for the test. The system may be oversized for the number of Tone Detectors present or some Tone Detectors may be out-of-service.</p> <ol style="list-style-type: none"> <li>1. Look for TTR-LEV errors in the Error Log. If present, refer to <a href="#">"TTR-LEV (TTR Level)" on page 5-1223</a>.</li> <li>2. Look for TONE-PT errors in the Error Log. If present, refer to <a href="#">"TONE-PT (Tone Generator)" on page 5-1204</a>.</li> <li>3. If neither condition exists, retry the test at 1-minute intervals a maximum of 5 times.</li> </ol>
1004	ABORT	<p>The port has been seized by a user for a valid call. Use the <b>status station</b> command for the station associated with this port and determine when the port is available for testing.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
1005	ABORT	<p>This test is not valid for this type of translation. Ports administered as "ASAI" or "ADJK" can not run this test, because the B channels associated with the port are not used by ASAI or Lucent Adjunct Links. This is a normal condition.</p>
2000	ABORT	<p>Response to the test was not received from the BRI-LINE circuit pack within the allowable time period.</p> <ol style="list-style-type: none"> <li>1. If this result occurs repeatedly, attempt to reset the circuit pack if the other ports are not in use. Reset the circuit pack by issuing the <b>busyout board PCSS</b> and the <b>reset board PCSS</b> commands.</li> <li>2. If this result occurs again, replace the circuit pack.</li> </ol>

*Continued on next page*

## 5 Maintenance Objects for DEFINITY ONE

BRI-PORT (ISDN-BRI Port), ABRI-PORT (ASAI ISDN-BRI Port)

5-325

Table 5-126. TEST #619 BRI Port Local TDM Loop Around — *Continued*

Error Code	Test Result	Description/ Recommendation
2012	ABORT	Internal system error.
2100	ABORT	Could not allocate the necessary resources to run this test. 1. Retry the command at 1-minute intervals a maximum of 5 times.
2103	ABORT	The system could not make the conference connection for the test. 1. Retry the command at 1-minute intervals a maximum of 5 times.
1, 2	FAIL	As stated previously, this test runs a TDM Loop Around Test on each B-channel. This indicates that the loop around failed on one of the channels. Error Code 1 indicates that the TDM Loop Around Test failed on B1. Error Code 2 indicates that the TDM Loop Around Test failed on B2.
7, 8	FAIL	As stated previously, this test runs a Conference Circuit Test on each B-channel. A failure here indicates that one of these conference tests failed; Error Code 7 means that the test failed on B1; Error Code 8 means that the test failed on B2.  1. If the test fails repeatedly, attempt to reset the circuit pack if the other ports on the circuit pack are not in use. Reset the circuit pack by issuing the <b>busyout board PCSS</b> and the <b>reset board PCSS</b> commands.  2. If the test fails again, replace the circuit pack.
	PASS	The BRI Port Local TDM Loop Around Test has passed.

**Electronic Power Feed Restoral Test (#620)**

This test attempts to restore the Electronic Power Feed (EPF) on an ISDN-BRI port twice. In this test, the processor requests that the EPF be turned on for a given port. An attempt is made to turn on the power unit to the station or adjunct. If no current is being drawn by a station, this probably indicates that the station is not connected. No current being drawn by an adjunct is the normal condition. If an overcurrent condition is sensed (that is, too much current is being drawn), this condition may indicate a short in the wiring to the endpoint or adjunct. Depending on what condition is sensed, a message is returned stating that either the EPF was turned on successfully with no problems or that an overcurrent condition is sensed. This response is reported by the Electronic Power Feed Inquiry (#622), which follows in the testing sequence. EPF Restoral is attempted again by this test five seconds later. This test always passes for the TN2198 because it has no EPF. This test will always abort when run on the TN2208.

Table 5-127. TEST #620 Electronic Power Feed Restoral

Error Code	Test Result	Description / Recommendation
1005	ABORT	This test is not valid for this port type. The TN2208 does not have an electronic power feed, and the test will abort.
2012	ABORT	Internal system error. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
	PASS	The EPF Test passed. The message to turn on the power feed to the station or the adjunct was successfully sent to the port. <ol style="list-style-type: none"><li>1. Although this test should not return a fail result, after running this test, the Error Log should be checked for any entries with error type 257 to examine the real results of this test.</li><li>2. An error type of 257 in the Error Log indicates some problem with the power to the station or the adjunct. Check for a short in the wiring, a damaged jack, a defective voice terminal or adjunct, or an incorrect type of terminal.</li></ol>

### Level 1 Status Inquiry Test (#621)

This test determines the state of the transmission facility of a BRI port at the physical layer (that is, Level 1). Level 1 can be in one of three possible states: Activated, Pending Activation, or Deactivated.

The Activated state is the correct state for an ISDN-BRI port. In this state the Level 1 interface can communicate with the BRI endpoint or ASAI or Lucent adjunct administered on this port. This test passes if the state of Level 1 (L1) is Activated. This test also passes if software has taken this port out of service. See the description of the Level 1 "Deactivated State" below for more details.

The Pending Activation state indicates a problem with the endpoints or adjunct, the wiring to the sets or adjunct, or the BRI-LINE circuit pack. When in this state, the Level 1 interface is either not receiving any L1 framing from the endpoint or adjunct (Endpoint Idle), or it is communicating with the endpoint or adjunct but cannot transition to the Activated state (Endpoint Active).

## 5 Maintenance Objects for DEFINITY ONE

BRI-PORT (ISDN-BRI Port), ABRI-PORT (ASAI ISDN-BRI Port)

5-327

The Deactivated state indicates a problem with the BRI-LINE circuit pack. When in this state, the Level 1 interface is idle and is not trying to communicate with the BRI endpoints or adjunct. When an ISDN-BRI port is placed in the out-of-service state, Level 1 is also put into the Deactivated state. This could be due either to the system detecting a fault with the port or to a **busyout port PCSSpp** request.

Table 5-128. TEST #621 Level 1 Status Inquiry

Error Code	Test Result	Description/ Recommendation
1187	ABORT	<p>The board, port or station may have been busied out by a technician.</p> <ol style="list-style-type: none"> <li>1. Look in the Error Log for Error Type 18 (port busied out) for this port and BRI-BD (board busied out). If this error type is present for BRI-PORT only, then release the port via the <b>release port pp</b> command and run the test again. If the error is present for both BRI-BD and BRI-PORT, then release the board via the <b>release port PCSS</b> command and run the test again.</li> </ol> <p> <b>NOTE:</b> When you release a port, you release all ports associated with it. If certain ports still need to be busied out, use the <b>release port PCSSpp</b> command to busy them out.</p> <ol style="list-style-type: none"> <li>2. Make sure the terminal is connected.</li> <li>3. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
2000	ABORT	<p>Response to the test was not received from the circuit pack within the allowable time period.</p> <ol style="list-style-type: none"> <li>1. If the test aborts repeatedly a maximum of 5 times, reset the circuit pack via the <b>busyout board PCSS</b> and <b>reset board PCSS</b> commands.</li> <li>2. If the test aborts again, replace the circuit pack.</li> </ol>
2012	ABORT	Internal system error.
2100	ABORT	<p>Could not allocate the necessary system resources to run this test.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>

*Continued on next page*

5 Maintenance Objects for DEFINITY ONE  
BRI-PORT (ISDN-BRI Port), ABRI-PORT (ASAI ISDN-BRI Port)

5-328

Table 5-128. TEST #621 Level 1 Status Inquiry — Continued

Error Code	Test Result	Description/ Recommendation
1	FAIL	<p>Received a status of Level 1 Pending Activation-Endpoint Idle which indicates a problem with the BRI endpoint or ASAI or Lucent adjunct, the wiring to the endpoint or adjunct, or the ISDN-BRI port.</p> <p>For the TN2198, received a status of Level 1 Pending Activation. U interface down, which indicates a problem with a connection between the switch and the NT1.</p> <ol style="list-style-type: none"> <li>For the TN556 or TN2208, verify that an endpoint is connected to the port. If an endpoint is connected to the port, then proceed to step 2. For the TN2198 verify that the connections are good between the switch and the NT1. Verify that the NT1 has power.</li> <li>As necessary, check and repair the wiring between the circuit pack and the endpoint or adjunct. If a TN2198 is used, the set must have been plugged in for at least 15 seconds before it will stabilize. Execute the <b>test port PCSSpp</b> command, and review the results of the Level 1 Status Inquiry Test to verify the repair. If this test is still failing, proceed to Step 3.</li> <li>For BRI endpoints, replace the BRI endpoint(s) connected to the port or the NT1 if a TN2198 is used. For ASAI or Lucent adjuncts, follow the recommended repair procedures of the manufacturer for link communication problems. For the NT1, follow the manufacturers repair procedures. Then execute the <b>test port PCSSpp</b> command and review the results of the Level 1 Status Inquiry Test to verify repair. If this test is still failing, proceed to Step 4.</li> </ol>
2	FAIL	<p>For the TN556 or TN2208, received a status of Level 1 Pending Activation-Endpoint Active which indicates a problem with the BRI endpoint or ASAI or Lucent adjunct, the wiring to the endpoint or adjunct, or the ISDN-BRI port.</p> <p>For the TN2198, received a status of Level 1 Pending Activation. U interface up S/T interface down, which indicates a problem with the NT1 or the wiring between the NT1 and the BRI endpoint (S/T interface).</p> <ol style="list-style-type: none"> <li>As necessary, check and repair the wiring between the circuit pack and the endpoint or adjunct. Execute the <b>test port PCSSpp</b> command, and review the results of the Level 1 Status Inquiry test to verify the repair. If this test is still failing, proceed to Step 2.</li> <li>For BRI endpoints, try replacing the BRI endpoint(s) connected to the port. For ASAI or Lucent adjuncts, follow the recommended repair procedures of the manufacturer for link communication problems. For the NT1, follow the recommended repair procedures of the manufacturer. Then execute the <b>test port PCSSpp</b> command, and review the results of the Level 1 Status Inquiry test to verify repair.</li> </ol>

*Continued on next page*

5 Maintenance Objects for DEFINITY ONE  
BRI-PORT (ISDN-BRI Port), ABRI-PORT (ASAI ISDN-BRI Port)

5-329

Table 5-128. TEST #621 Level 1 Status Inquiry — Continued

Error Code	Test Result	Description/ Recommendation
3	FAIL	<p>Received a status of Level 1 Deactivated; the port is out-of-service.</p> <ol style="list-style-type: none"><li>1. Issue the <b>status bri-port PCSSpp</b> command to verify that the service state of the port is out-of-service. If the service state of the port is not out-of-service, proceed to Step 2.</li><li>2. If the port has been placed out-of-service via the <b>busyout port PCSSpp</b> command, try releasing the port by executing the <b>release port PCSSpp</b> command. Then issue the <b>test port long PCSSpp</b> command, and review the results of Level 1 Status Inquiry test. If this test is still failing, proceed to Step 3.</li><li>3. After executing the <b>test port long PCSSpp</b> command, review the results of all the tests. Follow the repair procedures for any tests that fail. Verify repair of the problem by executing the <b>test port PCSSpp</b> command and by determining that the Level 1 Status test passes.</li></ol>
4	FAIL	<p>For the TN2198 only:</p> <p>Received a status of Level 1 Pending Activation, the NT1 has a loss of power indicating a problem with the NT1.</p> <ol style="list-style-type: none"><li>1. For the NT1 follow the manufacturers recommended repair procedures.</li><li>2. Execute the <b>test port PCSSpp</b> command, and review the results of the Level 1 Status Inquiry test to verify the repair.</li></ol>
	PASS	<p>This test indicates that Level 1 is activated, or that software has taken the port out of service.</p>

## Electronic Power Feed Inquiry (#622)

This test queries the BRI-LINE circuit pack for the status of the Electronic Power Feed (EPF) supplied to a BRI endpoint or an ASAI or Lucent adjunct. If the EPF is on and no overcurrent condition exists, this test passes. All other states are not normal and indicate a problem with the endpoint or adjunct, the wiring to the endpoint or adjunct, or the BRI-LINE circuit pack. This test is not run on the TN2208 circuit pack or the TN2198 and will always return a pass for a TN2198. The TN2208 has no power feeds.

Table 5-129. TEST #622 Electronic Power Feed Inquiry

Error Code	Test Result	Description/ Recommendation
1005	ABORT	This test is not valid for this port type. Ports on the TN2208 cannot run this test because this board does not have an electronic power feed.
2000	ABORT	Response to the test was not received from the circuit pack within the allowable time period. <ol style="list-style-type: none"> <li>1. If the test aborts repeatedly a maximum of 5 times, reset the circuit pack via the <b>busyout board PCSS</b> and <b>reset board PCSS</b> commands.</li> <li>2. If the test aborts again, replace the circuit pack.</li> </ol>
2012	ABORT	Internal system error.
2100	ABORT	Could not allocate the necessary system resources to run this test. <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
1	FAIL	The BRI-LINE circuit pack reports that it has detected an overcurrent condition and has turned off the EPF. <ol style="list-style-type: none"> <li>1. As necessary, check and repair the wiring between the circuit pack and the endpoint or adjunct. Check the endpoints and replace one or both sets if the sets are drawing too much current. Execute the <b>test port PCSSpp</b> command and review the results of the EPF Inquiry Test to verify the repair. If this test is still failing, proceed to Step 2.</li> <li>2. Execute the <b>test port PCSSpp</b> command, and review the results of the Level 1 Status Inquiry Test. If this test is also failing, then follow the repair procedure for the Level 1 Status Inquiry Test.</li> </ol>
2000	ABORT	Response to the test was not received from the circuit pack within the allowable time period. <ol style="list-style-type: none"> <li>1. If the test aborts repeatedly a maximum of 5 times, reset the circuit pack via the <b>busyout board PCSS</b> and <b>reset board PCSS</b> commands.</li> <li>2. If the test aborts again, replace the circuit pack.</li> </ol>
	PASS	The Electronic Power Feed Inquiry Test reports that the EPF is on.

**Layer 1 Transmission Error Counter Test (#624)**

This test reads and clears the BRI port's Layer 1 Transmission error counter maintained on the BRI-LINE circuit pack. This counter is incremented by the circuit pack when it detects a Layer 1 transmission problem. The test passes if the value of the counter is 0 (that is, the error is cleared). If the counter is not zero, the test fails, and the value of the counter is displayed in the Error Code field.

This error is most likely due to a problem with the wiring or the endpoint or adjunct (verify that the wiring meets the configuration rules defined in *DEFINITY Communications System Generic 1 and Generic 3i Wiring*, 555-204-111). It does not indicate a problem with the ISDN-BRI circuit pack. This test is useful for verifying the repair of the problem.

**Table 5-130. TEST #624 Layer 1 Transmission Error Counter Test**

Error Code	Test Result	Description/ Recommendation
2000	ABORT	Response to the test was not received from the circuit pack within the allowable time period. <ol style="list-style-type: none"> <li>1. If the test aborts repeatedly a maximum of 5 times, reset the circuit pack via the <b>busyout board PCSS</b> and <b>reset board PCSS</b> commands.</li> <li>2. If the test aborts again, replace the circuit pack.</li> </ol>
2012	ABORT	Internal system error
2100	ABORT	Could not allocate necessary system resources to run test. <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
value	FAIL	The BRI-LINE circuit pack is still detecting errors of this type. The Error Code field contains the value of this counter. <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> <li>2. If the test continues to fail, review the results of other tests in the Long Test Sequence. Pay particular attention to the results of the Level 1 Status Inquiry test. Follow repair procedures for any of the executed tests if they fail. Otherwise, go to the next step.</li> <li>3. If the tests for the endpoints or adjunct pass and the Layer 1 Transmission Error Counter Test continues to fail, check the wiring to the endpoints or adjunct.</li> </ol>
	PASS	The Layer 1 Transmission error counter was read correctly and has a value of 0.

**Receive FIFO Overflow Error Counter Test (#625)**

This test reads and clears the BRI port's Receive FIFO Overflow error counter maintained on the BRI-LINE circuit pack. This counter is incremented by the circuit pack when it detects an overflow of its receive buffers. The test passes if the value of the counter is 0 (that is, the error is cleared). If the counter is non-zero, the test fails, and the value of the counter is displayed in the Error Code field.

This error can occur if signaling frames are being received from the Packet Bus at a rate sufficient to overflow the receive buffers on the circuit pack for a port OR if a hardware fault is causing the receive buffers not to be emptied properly by the circuit pack. This test is useful for verifying the repair of the problem.

**Table 5-131. TEST #625 Receive FIFO Overflow Error Counter Test**

Error Code	Test Result	Description/ Recommendation
2000	ABORT	Response to the test was not received from the circuit pack within the allowable time period. <ol style="list-style-type: none"> <li>1. If the test aborts repeatedly a maximum of 5 times, reset the circuit pack via the <b>busyout board PCSS</b> and <b>reset board PCSS</b> commands.</li> <li>2. If the test aborts again, replace the circuit pack.</li> </ol>
2012 2100	ABORT ABORT	Internal system error Could not allocate the necessary system resources to run this test. <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
value	FAIL	The BRI-LINE circuit pack is still detecting errors of this type. The Error Code field contains the value of this counter. <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> <li>2. If the test continues to fail, run the Long Test Sequence and pay particular attention to the Loop Around Tests (#618 and #619). See the repair procedures for the executed test if it fails. Otherwise, go to the next step.</li> <li>3. Replace the circuit pack.</li> </ol>
	PASS	The Receive FIFO Overflow error counter was read correctly and has a value of 0.

**Clear Error Counters Test (#270)**

This test is not an actual test in the strict sense of the word. There are various error counters associated with each BRI-PORT/ABRI-PORT/ATT-PORT/LGATE-PT/ATTE-PT. This test clears those counters and triggers the auditing of Terminal Endpoint Identifier (TEI) values and layer 3 reinitialization. This test is used only to send messages to the BRI-PORT/ABRI-PORT/ATT-PORT/LGATE-PT/ATTE-PT and, therefore, should neither abort nor fail.

**Table 5-132. TEST #270 Clear Error Counters**

Error Code	Test Result	Description/ Recommendation
Any	ABORT	This test should never abort.
Any	FAIL	This test should never fail. 1. Retry the command at 1-minute intervals a maximum of 5 times.
	PASS	The message to clear the error counters of the BRI-Port/ABRI-Port/ATT-PORT/LGATE-PT/ATTE-PT has been sent.

## BRI-SET, ASAI-ADJ, BRI-DAT

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run <sup>1</sup>	Full Name of MO
BRI-SET	WARNING <sup>2</sup>	test station extension l, test data-module extension	ISDN-BRI Set
ASAI-ADJ	MAJOR <sup>2</sup>	test station extension	ASAI-Adjunct
ASAI-ADJ	MAJOR <sup>2</sup>	test data-module extension	ASAI-Adjunct
ASAI-ADJ	WARNING <sup>3</sup>	test data-module extension	ASAI-Adjunct
ATT-ADJ	MAJOR <sup>2</sup>	test station extension	Lucent-Adjunct
ATT-ADJ	MAJOR <sup>2</sup>	test station extension	Lucent-Adjunct
ATT-ADJ	WARNING <sup>3</sup>	test station extension	Lucent-Adjunct
LGATE-AJ	MAJOR <sup>2</sup>	test station extension	Ethernet ASAI-Adjunct
LGATE-AJ	MAJOR <sup>2</sup>	test station extension	Ethernet ASAI-Adjunct
LGATE-AJ	WARNING <sup>3</sup>	test station extension	Ethernet ASAI-Adjunct
ATTE-AJ	MAJOR <sup>2</sup>	test station extension	Ethernet Lucent-Adjunct
ATTE-AJ	MAJOR <sup>2</sup>	test station extension	Ethernet Lucent-Adjunct
ATTE-AJ	WARNING <sup>3</sup>	test station extension	Ethernet Lucent-Adjunct
BRI-DAT		test data-module	

1. Where P is the port network number (1 for PPN); C is the carrier designation (A, B, or C); SS is the address of the slot in the carrier where the circuit pack is located (01, 02, ..., etc.); and pp is the 2-digit port number (for example, 01). The alternate name field contains the extension of the endpoint. This field is used to distinguish between endpoints on the same port.
2. The alarm level for ASAI and Lucent adjuncts may be administered using the **set options** command. The alarm level can be set independently for Off-Board and On-Board alarms to WARNING, MINOR, or MAJOR for all ASAI and Lucent adjuncts in the system.
3. Alarming for an ASAI and Lucent adjuncts is disabled if the adjunct asks the switch to suspend maintenance. When this occurs, an error and a WARNING alarm are logged against the endpoint. Busing out and releasing the ASAI station or ADJLK station will clear the alarm.

The TN2208 ESAI MFB provides DEFINITY with an Ethernet interface to Adjunct-Switch Application Interface (ASAI) and Lucent adjuncts (for example, CONVERSANT Voice System). This circuit pack contains 8 ports of line circuit interface, each of which operates with two B-channels (referred to as B1 and B2 throughout this section) and one D-channel as specified in the Lucent ISDN-BRI Specification. In this context, the term “ISDN-BRI port” is used to refer collectively to ports on the TN2208 MFB circuit pack which is connected to ASAI or Lucent adjuncts. The TN2208 ESAI MFB is handled by switch software as it is an ISDN BRI compatible board and all maintenance actions referring to ASAI and Lucent Adjunct Links in this section apply.

ISDN-BRI endpoints come in a number of configurations. All endpoints require the D-channel to convey signaling information to the switch. A voice-only set requires only one B-channel. A voice and data-capable set requires both B-channels (one for voice and one for data). Therefore, each TN556 port can support either two voice-only sets or one voice and data-capable set. Only a single ASAI or Lucent adjunct may be connected to an ISDN-BRI port. Multiple adjuncts per line are not supported.

[Figure 5-15](#) illustrates the physical connection (solid line) between an ISDN-BRI Circuit Pack and a voice or voice/data set. Each physical connection allows for two B-channels, as stated above, plus one D-channel. Each ISDN-BRI circuit pack can support up to 12 of these PHYSICAL connections to different voice and voice/data sets or ASAI and Lucent adjuncts.




Figure 5-15. ISDN-BRI Set Interactions

This section contains the ISDN-BRI Set, ASAI Adjunct, and Lucent Adjunct Maintenance documentation. Some of the results of maintenance testing of the ISDN-BRI Set or the ASAI and Lucent Adjunct may be affected by the health of the ISDN-BRI circuit pack and Port. These interactions should be kept in mind when investigating the cause of ISDN-BRI Set problems.

## Hardware Error Log Entries and Test to Clear Values

Table 5-133. BRI-SET/ASAI-ADJ Error Log Entries

Error Type	Aux Data	Associated Test	Alarm Level BRI-PORT	Alarm Level ABRI-PORT ATT-PORT LGATE-PORT ATTE-PT	On/ Off Board	Test to Clear Value
0 <sup>1</sup>	0	Any	Any	Any	Any	test BRI-SET or ASAI-ADJ ATT-ADJ LGATE-AJ ATTE-AJ
2(a)	2-102	None				
18	0	busyout station ext	WARNING	MAJOR/ WARNING <sup>2</sup>	OFF	release station <ext>
130(b)			WARNING		ON	test port PCSS sh
257(c)	Any	BRI Layer 3 Query (#629)	WARNING	MAJOR/ WARNING <sup>2</sup>	OFF	test station ext r 2 test data-module ext r 2
351(d)	0	None		WARNING	OFF	busyout and release station
513(e)	0	None				
769(f)	0	None	WARNING	MAJOR	OFF	
2561(g)	0	None				
2562- 2566(h)	0	None				
2567(o)	0	None				
2568(p)	0	None				
2817(i)	0	XID Test (#628)	WARNING	MAJOR/ WARNING <sup>2</sup>	OFF	test station ext r 2 test data-module ext r 2
3073(j)	0	BRI Remote Loop Back (#627)	WARNING		OFF	test station ext l r 2 test data-module ext l r 2

Continued on next page

Table 5-133. BRI-SET/ASAI-ADJ Error Log Entries — *Continued*

Error Type	Aux Data	Associated Test	Alarm Level BRI-PORT	Alarm Level ABRI-PORT ATT-PORT LGATE-PORT ATTE-PT	On/ Off Board	Test to Clear Value
3329(k)	Any	Signaling Link Status (626)	WARNING	MAJOR/ WARNING <sup>2</sup>	OFF	†
3584	0, 1	None				
3585- 3839(i)	0	None				
3840- 4095(m) (n)	0	None				

- Run the Short Test Sequence first. If all tests pass, run the Long Test Sequence. Refer to the appropriate test description and follow the recommended procedures.
- Major alarms on this MO may be downgraded to Warning alarms based on the value used in the **set options** command.

## Notes:

- Errors of this type indicate violations of the ISDN-BRI signaling protocol; timers associated with certain Layer 3 messages have expired before a required response was received. In [Table 5-134](#), the Aux Data field indicates which timer has just expired. (For more information, refer to the Lucent ISDN-BRI Specification.)

Table 5-134. Error Type 2 Cause Values

Aux Data	Timer Type
2	First T303 (SETUP timer)
3	Second T303 (SETUP timer)
4	T305 (DISConnect timer)
5	First T308 (RELease timer)
6	Second T308 (RELease timer)
10	T316 (REStart timer)
12	T309 (Layer 2 Failure timer)

*Continued on next page*

Table 5-134. Error Type 2 Cause Values — *Continued*

Aux Data	Timer Type
16	TM100 (Management Information Message timer 1)
17	TM200 (Management Information Message timer 2)
102	TASAI (ASAI Routing Timer)

The switch sent a message to the endpoint which did not respond in the allotted time. This can happen occasionally due to failure of the point-to-point signaling link or because of a problem in the BRI endpoint or ASAI adjunct or Lucent adjunct. Execute the **test station extension sh** command and pay particular attention to the results of the BRI Layer 3 Query Test (#629). If this test fails, follow the repair procedure for Test #629.

- b. This error type indicates that the circuit pack has been removed or has been insane for more than 11 minutes. To clear the error, replace or reinsert the circuit pack.
- c. This error occurs when the endpoint does not respond to the service state query message sent to the adjunct or the endpoint. This error causes an alarm to be raised. The alarm is retired when the switch receives a response to the service state query to the endpoint or the adjunct.

For BRI endpoints, the Aux Data field for this error contains "0." When it occurs, execute the **test station <extension> sh** command and pay particular attention to the results of the BRI Layer 3 Query Test (#629). If this test fails, follow the repair procedure for Test #629.

When this error occurs for an ASAI or Lucent adjunct, the Aux Data field indicates the state of the ASAI link or Lucent link and whether an invalid response or no response was received to the query from the switch, as shown in [Table 5-135](#):

Table 5-135. ASAI Link State

Aux Data	ASAI Link State	Error
102	13-restarting	No response to RESTART message
104	13-restarting	Invalid response to RESTART message
152	13-restarted	No response to Layer 3 query
154	13-restarted	Invalid response to Layer 3 query
202	13-established	No response to Layer 3 query
204	13-established	Invalid response to Layer 3 query

(See [“status bri-port”](#) in [Chapter 4, “Maintenance Commands for DEFINITY ONE”](#) for an explanation of the ASAI link states.)

For ASAI or Lucent adjuncts, the switch automatically queries the adjunct every two minutes (and therefore the Layer 3 Query Test is not executed for ASAI or Lucent adjuncts via a command issued from the G3MT terminal). While alarmed for this error, the switch momentarily (for five seconds) takes the associated port out-of-service every 15 minutes. This action is taken in an attempt to stimulate recovery actions to be taken by the adjunct.

When this error occurs for an ASAI or Lucent adjunct, the service technician should:

1. Execute the **test station extension** command, paying particular attention to any tests which fail, and perform the associated repair procedures for those tests.
  2. Check the health of the adjunct by following the recommended repair procedures of the manufacturer of the adjunct if the preceding step does not resolve the problem.
  3. The alarm condition persists and, if the above steps do not resolve the problem, follow normal escalation procedures.
- d. This error and associated WARNING alarm are logged against an ASAI or Lucent endpoint when the adjunct has asked the switch to suspend Maintenance on the ASAI or Lucent endpoint. Busying out and releasing the ASAI station or ADJLK station will clear this alarm.
- e. This error occurs when the endpoint sends more messages than the switch can handle. The switch suspends the reception of messages from the endpoint for a short period of time. There is no repair procedure for this error. If the condition persists, replace the endpoint.

- f. This error occurs when the signaling link associated with a BRI endpoint has too much link establishment related traffic. This could occur if the signaling link is bouncing between assigned and established states. Software will suspend activity to this endpoint for 75 minutes when the endpoint is alarmed due to this problem (note that service suspension does not occur if the endpoint is an ASAI or Lucent adjunct). If this problem persists, replace the endpoint. If replacing the endpoint does not fix the problem, follow normal escalation procedures.
- g. This error occurs when the ASAI-ADJ or ATT-ADJ or LGATE-AJ or ATTE-AJ message is not transmitted because the PKT-CTRL (Packet Control Circuit Pack) transmit buffers are exhausted. Frequent or persistent occurrence of these events may indicate a hardware problem or traffic overload on the PKT-CTRL, the signaling link, or the ASAI or Lucent adjunct. Attempt to resolve the problem by following the repair procedures for the PKT-CTRL. If these attempts fail, the problem should be escalated because re-engineering of the traffic on the PKT-CTRL, signaling link, or adjunct may be necessary.
- h. This error occurs when the ASAI message is not transmitted because the transmit buffer for the ASAI link is full, causing the link to be flow controlled. Frequent or persistent occurrence of these events may indicate a hardware problem or traffic overload on the PKT-CTRL, the signaling link, or the ASAI or Lucent adjunct. Attempt to resolve the problem by following the repair procedures issued by the manufacturer of the adjunct. If these attempts fail, the problem should be escalated because re-engineering of the traffic on the PKT-CTRL, signaling link, or adjunct may be necessary.
- i. This error indicates a problem with Layer 2 over the D-channel between the switch and the endpoint. When this error occurs, an alarm is raised against the station or adjunct. Execute the **test station extension short** command and pay particular attention to the results of the BRI XID Test (#628). If this test fails, follow the repair procedure for Test #628.
- j. This error indicates a problem with the B-channel connection between the switch and the endpoint. When this error occurs, a warning alarm is raised against the endpoint. Execute the **test station <extension> long** command, and pay particular attention to the results of the BRI Remote Loop Back Test (#627). If this test fails, follow the repair procedure for Test #627.
- k. This error occurs whenever the point-to-point signaling link to the endpoint goes down (except when it goes down because either the PKT-CTRL or the PKT-BUS has failed or has been busied out by system technician). When this error occurs, an alarm is raised against the endpoint or adjunct. Execute the **test station <extension> short** command and pay particular attention to the results of the Signaling Link Status Test (#626). If this test fails, follow the repair procedure for Test #626. The alarm is retired when the signaling link is reestablished to the endpoint or adjunct.

- I. Certain ASAI protocol-specific cause codes are logged by switch software. The cause code can be determined from the following formula:

If the error type is greater than 3712, then the ASAI cause code is equal to the error type minus 3712. This code was sent to the adjunct by the switch.

If the error type is less than 3712, then the ASAI cause code is equal to the error type minus 3584. This code was sent to the switch by the adjunct.

A description of the various ASAI cause values is contained in the Table 10-64. This table also contains recommended system technician actions associated with the cause value. Further information can also be found in the Lucent ASAI Specification (288-500-03). In addition, the Aux Data field of the Error Log entry contains additional diagnostic information.

Table 5-136. ASAI Cause Values

Code	Explanation	Recommendation
	Service or Option Not Available	
0	Unrecognized ASAI Protocol Operation	Requested ASAI protocol operation is not implemented by the switch or adjunct. Aux Data field of Error Log entry contains protocol identifier for unrecognized operation.  1. Consult switch and adjunct documentation to determine which set of operations is supported by the switch and the adjunct. Adjunct administration turning off operations not implemented by the switch may resolve the problem.
40	Resources not available	No available internal resources to service switch or adjunct request. System transaction capacity for adjunct or switch is exceeded.  1. Re-engineering of adjunct services may be required.

*Continued on next page*



5 Maintenance Objects for DEFINITY ONE  
BRI-SET, ASAI-ADJ, BRI-DAT

5-343

- m. Certain ISDN-BRI cause codes are logged by switch software. The cause code can be determined from the following formula:

If the error type is greater than 3968, then the ISDN-BRI cause code is equal to the error type minus 3968. This code was sent to the endpoint by the switch.

If the error type is less than 3968, then the ISDN-BRI cause code is equal to the error type minus 3840. This code was sent to the switch by the endpoint.

A description of the various ISDN-BRI cause values is contained in Table 10-65. This table also contains recommended system technician actions associated with the cause value. Further information can also be found in the Lucent ISDN-BRI Specification (801-802-100). In addition, the Aux Data field of the Error Log entry contains additional diagnostic information.

- n. Error 3847 indicates that sets on the port do not support level 3 initialization. Consult the Set Service documentation
  - o. For the Error 2567 indicates that the version of ASAI is not supported, check version of the software running on the ASAI or Lucent adjunct.
  - p. For Error 2568 indicates that the adjunct id is invalid, check the vender id or software running on the Lucent adjunct.
-

Table 5-137. ISDN-BRI Cause Values

Code	Explanation	Recommendation
1	Channel in use	Requested channel is in use by another station on the BRI-PORT. (Not applicable for ASAI or Lucent adjuncts.) For BRI endpoints: <ol style="list-style-type: none"><li>1. Try to originate a call to or from this port.</li><li>2. If the error persists, busy out and release the port.</li><li>3. If the problem still persists, replace stations on the port.</li></ol>
34	Switch resources not available	A resource on the switch is unavailable for a call. For BRI endpoints: This cause value is not logged. For ASAI or Lucent Adjuncts: This condition means that there are no available trunks for an outgoing call request. <ol style="list-style-type: none"><li>1. Verify that the adjunct is administered to support the trunk capabilities of the switch.</li><li>2. Investigate trunk group status by issuing <b>status trunk</b> commands from the SAT or by requesting a trunk group query or queries from the adjunct.</li><li>3. Perform trunk diagnostic procedures outlined in this manual.</li></ol>
42	Switch Equipment Congestion	Switch takes control to limit received traffic. For BRI endpoints: This cause value is not logged. For ASAI or Lucent Adjuncts: <ol style="list-style-type: none"><li>1. See CallVisor protocol reference manual.</li></ol>

*Continued on next page*

Table 5-137. ISDN-BRI Cause Values — *Continued*

Code	Explanation	Recommendation
50	Service or Option Not Available  Requested Facility Not Subscribed	<p>Requested facility is implemented, but not administered. Potential administration problem with endpoint or adjunct. For BRI endpoints:</p> <ol style="list-style-type: none"><li>1. Verify the switch administration of endpoint using either the <b>display station</b> or <b>display data-module</b> commands.</li><li>2. If Step 1 does not resolve the problem, refer to the endpoint's service manual and verify administration on the endpoint.</li></ol> <p>For ASAI adjuncts:</p> <ol style="list-style-type: none"><li>1. Display the Customer Optional Features Form (administration screen) on the switch to determine which ASAI capabilities are turned on in the switch.</li><li>2. Verify that the adjunct is administered to support the identical capabilities as the switch. If there is a mismatch in the administered capabilities, then readminister the switch and/or the adjunct to establish a consistent set of desired capabilities on both the switch and the adjunct.</li></ol> <p>For Lucent adjuncts:</p> <ol style="list-style-type: none"><li>1. Display the Customer Optional Features Form (administration screen) on the switch to determine if the adjunct is set enabled on in the switch.</li><li>2. If error type 2567 or 2568, verify the adjunct version, and readminister if needed.</li></ol>
58	Bearer Capability Not Presently Available	Requested bearer capability is implemented, but not administered. No B-channel administered. See recommendation 50 above.
65	Service or Option Not Implemented  Bearer Service Not Implemented	Requested service not implemented in switch or endpoint.

*Continued on next page*

Table 5-137. ISDN-BRI Cause Values — *Continued*

Code	Explanation	Recommendation
69	Requested Facility Not Implemented	Requested service not supported in switch or endpoint. 1. Consult switch and endpoint documentation to determine service support.
	Adjunct switch error conditions	
81	Invalid CRV	An invalid CRV was sent by the adjunct.  This may indicate a CRV inconsistency between the switch and the adjunct. See the CallVisor protocol reference manual.

## System Technician-Demanded Tests: Descriptions and Error Codes

When inspecting errors in the system and deciding which ones to address, always investigate errors associated with the circuit pack and port first. Clearing these error codes first may also clear errors generated against the endpoint. When all circuit pack and port errors have been cleared, and errors still exist against the endpoint, always investigate errors in the order they are presented in the table below. By clearing error codes associated with the *Signaling Link Status Test*, for example, you may also clear errors generated from other tests in the testing sequence.

Table 5-138. System Technician-Demanded Tests: BRI-SET

Order of Investigation	Short Test Sequence	Long Test Sequence	D/ND <sup>1</sup>
Signaling Link Status Test (#626)	X	X	ND
BRI XID Test (#628)	X	X	ND
BRI Layer 3 Query (#629)	X (a)	X (a)	ND
BRI Remote Loop Back (#627)		X (a)	ND
BRI Set Audits (#630)	X (a)	X (a)	ND

*Continued on next page*

Table 5-138. System Technician-Demanded Tests: BRI-SET — *Continued*

Order of Investigation	Short Test Sequence	Long Test Sequence	D/ND <sup>1</sup>
BRI Vendor ID Test (#631)		X (a)	ND
BRI Model/Vintage ID Test (#632)		X (a)	ND

1. D = Destructive, ND = Non-destructive

Note:

- a. Execute the **test port long PCSSpp** command and review the results of the BRI Port Local LAN Loop Around Test to verify the repair.

## Signaling Link Status Test (#626)

This test determines the current status of the signaling link. This test passes if the link is “bound” to an endpoint and fails if the link is “not bound.”

The definition of the term “bound” for a link depends upon the type of endpoint and may depend on the successful completion of procedures at both Layers 2 and 3 of the protocol. The definition of “bound” for each type of endpoint is as follows:

- **BRI endpoints administered for MIM (management information messages) initialization (multipoint):**

 **NOTE:**

An MIM is a level 3 message that conveys management and maintenance information between a communications system and a BRI terminal.

For endpoints of this type, the signaling link is “bound” when the link is connected at Layer 2 and the link has been associated with an endpoint, [that is, the endpoint has completed SPID initialization (L3 established)].

- **ASAI adjuncts and BRI endpoints not administered for MIM initialization (point-to-point):**

For endpoints of this type, the signaling link is “bound” when the link is connected at Layer 2 (L2 established).

For all endpoint types, a signaling link becomes “unbound” when it is disconnected at Layer 2. For BRI endpoints supporting MIM initialization, a signaling link may also become “unbound” if a subsequent attempt to perform SPID initialization on a “bound” link fails, (that is, wrong SPID is entered into the endpoint by the user).

Table 5-139. TEST #626 Signaling Link Status Test

Error Code	Test Result	Description/ Recommendation
1139	ABORT	The Packet Bus in the port network is out-of-service. <ol style="list-style-type: none"><li>1. Follow the repair procedures for the Packet Bus.</li><li>2. After completing Step 1, execute the <b>test port long PCSSpp</b> command, and review the results of the BRI Port Local LAN Loop Around Test to verify the repair.</li></ol>
1141	ABORT	The PKT-CTRL is out-of-service. <ol style="list-style-type: none"><li>1. Refer to PKT-CTRL (Packet Control Circuit Pack) Maintenance documentation.</li></ol>
1144	ABORT	The PPN Packet Bus is out-of-service. <ol style="list-style-type: none"><li>1. Follow the repair procedures for the Packet Bus in the PPN.</li><li>2. After completing Step 1, execute the <b>test port long PCSSpp</b> command, and review the results of the BRI Port Local LAN Loop Around Test to verify the repair.</li></ol>

*Continued on next page*

Table 5-139. TEST #626 Signaling Link Status Test — *Continued*

Error Code	Test Result	Description/ Recommendation
1187	ABORT	<p>The circuit pack, port or station may have been busied out by a technician.</p> <ol style="list-style-type: none"> <li>1. Look in the Error Log for Error Type 18 (busied out ) for BRI-BD, BRI-PORT, or BRI-SET.</li> <li>2. If this error type is present for BRI-SET only, then release the station via the <b>release station</b> command.                             <ol style="list-style-type: none"> <li>a. If this error type is present for BRI-PORT and BRI-SET, then release the port via the <b>release port PCSSpp</b> command and run the test again.</li> <li>b. If the error is present for BRI-BD, BRI-PORT, and BRI-SET, then release the circuit pack via the <b>release port PCSSpp</b> command and run the test again. If the error is present for BRI-SET only, then release the circuit pack via the <b>release port PPCSS</b> command and run the test again. If the error is present for both BRI-BD and BRI-PORT, then release the circuit pack via the <b>release board PPCSS</b> command and run the test again.</li> </ol> </li> </ol> <p style="text-align: center;"><b>⇒ NOTE:</b> When you release the circuit pack, you release all ports associated with it. If certain ports still need to be busied out, use the <b>release port PCSSpp</b> command to busy them out.</p> <ol style="list-style-type: none"> <li>3. Make sure the terminal is connected.</li> <li>4. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
2012	ABORT	Internal system error
2100	ABORT	<p>Could not allocate the necessary system resources to run this test.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>

*Continued on next page*

Table 5-139. TEST #626 Signaling Link Status Test — *Continued*

Error Code	Test Result	Description/ Recommendation
1113	FAIL	<p>The signaling link is not "bound" to the adjunct or endpoint. For BRI endpoints supporting MIM initialization, this error indicates that the endpoint has not been bound to a signaling link (that is, SPID initialization has not been completed). Since the signaling link associated with the endpoint is not identified until SPID initialization completes, this error does not imply that the signaling link is connected or disconnected at Layer 2 nor does it provide the status of TEI assignment for the endpoint. For ASAI adjuncts and BRI endpoints not supporting MIM initialization, this error indicates that the link is disconnected at Layer 2. Since the signaling link associated with the endpoint has been identified via administration, the link is only "unbound" from the endpoint when it is disconnected.</p> <ol style="list-style-type: none"><li>1. Execute the <b>status bri-port PCSSpp</b> command and refer to the associated procedures for this command contained in the <a href="#">"BRI-PORT (ISDN-BRI Port), ABRI-PORT (ASAI ISDN-BRI Port)"</a> on page 5-312.</li></ol>
	PASS	<p>The signaling link is connected at Layer 2 and "bound" to the BRI endpoint or ASAI adjunct.</p>

### BRI Remote Loop Back Test (#627)

This test checks the integrity of a circuit switched B-channel connection between the switch and the endpoint.

In this test, the endpoint is put in the "maintenance busy" state to prevent the switch from issuing calls to the endpoint during the test. An application message containing a loop back activate request for the appropriate B-channel is sent to the endpoint. The endpoint responds with a loop back activated response. Maintenance then sends data to the endpoint over the B-channel under test. Since the B-channel is looped back at the endpoint, maintenance should receive the data that it sent. If no data is detected, the test fails. An application message containing a loop back deactivate request is then sent to the endpoint to terminate the remote loop back test. The endpoint responds with an MIM message containing a loop back deactivate response. Maintenance then releases the endpoint so that it is available to terminate calls.

This test is not executed for ASAI adjuncts because adjuncts do not support MIMs upon which this test is based.

Table 5-140. TEST #627 BRI Remote Loop Back

Error Code	Test Result	Description/ Recommendation
1000	ABORT	Could not seize the endpoint or B-channels for test. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
1005	ABORT	The endpoint's MIMs Supported field is administered to "no." <ol style="list-style-type: none"><li>1. Use the <b>change station extension</b> command to change parameter only if the endpoint documentation reflects support for ISDN-BRI Management and Maintenance Procedures.</li></ol>
1113	ABORT	The signaling link between the switch and the endpoint is down. <ol style="list-style-type: none"><li>1. Use the <b>test port PCSSpp long</b> command to clear any errors which prevent establishment of the signaling link.</li><li>2. Examine the results of the Signaling Link Status Test (#626) which is run as part of this command. If this test aborts or fails, follow the repair procedure for Test #626.</li><li>3. If the XID Test continues to abort, escalate the problem.</li></ol>
1139	ABORT	The Packet Bus in the port network is out-of-service. <ol style="list-style-type: none"><li>1. Follow the repair procedures for the Packet Bus.</li><li>2. After completing Step 1, execute the <b>test port long PCSSpp</b> command, and review the results of the BRI Port Local LAN Loop Around Test to verify the repair.</li></ol>
1141	ABORT	The PKT-CTRL is out-of-service. <ol style="list-style-type: none"><li>1. Refer to PKT-CTRL (Packet Control Circuit Pack) Maintenance documentation.</li></ol>
1144	ABORT	The PPN Packet Bus is out-of-service. <ol style="list-style-type: none"><li>1. Follow the repair procedures for the Packet Bus in the PPN.</li><li>2. After completing Step 1, execute the <b>test port long PCSSpp</b> command, and review the results of the BRI Port Local LAN Loop Around Test to verify the repair.</li></ol>

*Continued on next page*

Table 5-140. TEST #627 BRI Remote Loop Back — *Continued*

Error Code	Test Result	Description/ Recommendation
1187	ABORT	<p>The circuit pack, port or station may have been busied out by a technician.</p> <ol style="list-style-type: none"> <li>1. Look in the Error Log for Error Type 18 (busied out ) for BRI-BD, BRI-PORT, or BRI-SET.</li> <li>2. If this error type is present for BRI-SET only, then release the station via the <b>release station</b> command. <ol style="list-style-type: none"> <li>a. If this error type is present for BRI-PORT and BRI-SET, then release the port via <b>release port PCSSpp</b> command and run the test again.</li> <li>b. If the error is present for BRI-BD, BRI-PORT, and BRI-SET, then release the circuit pack via the <b>release port PCSSpp</b> command and run the test again. If the error is present for both BRI-BD and BRI-PORT, then release the circuit pack via the <b>release board PPCSS</b> command and run the test again. If the error is present for BRI-SET only, then release the circuit pack via the <b>release port PPCSS</b> command and run the test again.</li> </ol> </li> </ol> <p style="text-align: center;"> <b>NOTE:</b> When you release the circuit pack, you release all ports associated with it. If certain ports still need to be busied out, use the <b>release port PCSSpp</b> command to busy them out.</p> <ol style="list-style-type: none"> <li>3. Make sure the terminal is connected.</li> <li>4. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
2012	ABORT	<p>Internal system error</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
2068	ABORT	<p>The endpoint has rejected the switch sent application message. This indicates that the endpoint does not support the ISDN-BRI Management and Maintenance Procedure for Loop Back Testing.</p> <ol style="list-style-type: none"> <li>1. Use the <b>change station extension</b> command and change the MIMs Supported field to <b>n</b>.</li> </ol>
2069	ABORT	<p>The endpoint has returned an error response to the application message sent by the switch.</p>
2100	ABORT	<p>Could not allocate the necessary system resources to run this test.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>

*Continued on next page*

Table 5-140. TEST #627 BRI Remote Loop Back — *Continued*

Error Code	Test Result	Description/ Recommendation
2000	FAIL	No loop back activation or deactivation response is received from the endpoint. <ol style="list-style-type: none"><li>1. Consult the endpoint documentation to determine if ISDN-BRI Management and Maintenance Procedures are supported. If not supported, use <b>change station extension</b> command to change the MIMs Supported? field to <b>n</b>. Use the <b>busyout station extension</b> and <b>release station extension</b> commands to busyout and release the endpoint to resolve any endpoint alarms resulting from failure of this test.</li><li>2. If the endpoint supports these procedures and the test continues to fail, assume the endpoint is defective and replace it.</li></ol>
2071	FAIL	No data is detected on Channel B1 during loop back.
2072	FAIL	No data is detected on Channel B2 during loop back. <ol style="list-style-type: none"><li>1. Replace the endpoint and repeat test.</li><li>2. If test continues to fail, check the wiring between the endpoint and the switch and repeat the test.</li></ol>
	PASS	The endpoint has responded to the switch activate and deactivate loop back application messages. Data has been detected on the looped back channels.
1000	ABORT	Could not seize the endpoint or B-channels for test. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>

### BRI XID Test (#628)

This test checks the D-channel connection between the SPE and the endpoint or adjunct.

In this test, a D-channel XID frame is sent to the endpoint or adjunct over the point-to-point signaling link. The test passes if the endpoint or adjunct responds with a Layer 2 XID-RESPONSE frame.

This test must be administered to not run in the station administration form for ports on a TN2208.

Table 5-141. TEST #628 BRI XID

Error Code	Test Result	Description/ Recommendation
1000	ABORT	<p>The BRI-SET, ASAI-ADJ, ATT-ADJ, LGATE-AJ, ATTE-AJ is busy. The test cannot be executed at this time:</p> <ol style="list-style-type: none"> <li>1. Pause momentarily (30 seconds) and re-execute at this time.</li> </ol> <p> <b>NOTE:</b> A BRI-PORT can also be busy. When using this for BRI-PORT/ABRI-PORT tests, the words "BRI-SET, ASAI-ADJ, ATT-ADJ, " can be changed to "BRI-PORT, ABRI-PORT, ATT-ADJ."</p>
1005	ABORT	<p>The endpoint is not administered to support XID Testing.</p> <ol style="list-style-type: none"> <li>1. If the endpoint documentation reflects support XID testing, use the <b>change station extension</b> command to change the XID Testing? field on the form to <b>y</b>.</li> </ol>
1113	ABORT	<p>The signaling link between the switch and the endpoint is down.</p> <ol style="list-style-type: none"> <li>1. Use the <b>test port PCSSpp l</b> command to clear any errors which prevent establishment of the signaling link.</li> <li>2. Examine the results of the Signaling Link Status Test (#626) which is run as part of this command. If this test aborts or fails, follow the repair procedure for Test #626.</li> <li>3. If the XID test continues to abort, escalate the problem.</li> </ol>
1139	ABORT	<p>The Packet Bus in the port network is out-of-service.</p> <ol style="list-style-type: none"> <li>1. Follow the repair procedures for the Packet Bus.</li> <li>2. After completing Step 1, execute the <b>test port long PCSSpp</b> command, and review the results of the BRI Port Local LAN Loop Around Test to verify the repair.</li> </ol>
1141	ABORT	<p>The PKT-CTRL is out-of-service.</p> <ol style="list-style-type: none"> <li>1. Refer to PKT-CTRL (Packet Control Circuit Pack) Maintenance documentation.</li> </ol>
1144	ABORT	<p>The PPN Packet Bus is out-of-service.</p> <ol style="list-style-type: none"> <li>1. Follow the repair procedures for the Packet Bus in the PPN.</li> <li>2. After completing Step 1, execute the <b>test port long PCSSpp</b> command, and review the results of the BRI Port Local LAN Loop Around Test to verify the repair.</li> </ol>

Continued on next page

Table 5-141. TEST #628 BRI XID — *Continued*

Error Code	Test Result	Description/ Recommendation
1187	ABORT	<p>The circuit pack, port or station may have been busied out by a technician.</p> <ol style="list-style-type: none"> <li>1. Look in the Error Log for Error Type 18 (busied out ) for BRI-BD, BRI-PORT, or BRI-SET.</li> <li>2. If this error type is present for BRI-SET only, then release the station via the <b>release station</b> command.                             <ol style="list-style-type: none"> <li>a. If this error type is present for BRI-PORT and BRI-SET, then release the port via <b>release port PCSSpp</b> command and run the test again.</li> <li>b. If the error is present for BRI-BD, BRI-PORT, and BRI-SET, then release the circuit pack via the <b>release port PCSSpp</b> command and run the test again. If the error is present for BRI-SET only, then release the circuit pack via the <b>release port PCSSpp</b> command and run the test again. If the error is present for both BRI-BD and BRI-PORT, then release the circuit pack via the <b>release board PPCSS</b> command and run the test again.</li> </ol> </li> </ol> <p> <b>NOTE:</b> When you release the circuit pack, you release all ports associated with it. If certain ports still need to be busied out, use the <b>release port PCSSpp</b> command to busy them out.</p> <ol style="list-style-type: none"> <li>3. Make sure the terminal is connected.</li> <li>4. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
2012	ABORT	Internal system error
2100	ABORT	<p>Could not allocate the necessary system resources to run this test.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
2000	FAIL	<p>The XID-RESPONSE message was not received from the endpoint.</p> <ol style="list-style-type: none"> <li>1. Consult the endpoint documentation to determine if the Layer 2 XID and XID-RESPONSE messages are supported. If the documentation reflects no support for these messages, change XID Testing? field to <b>n</b> using the <b>change station extension</b> command.</li> <li>2. If the endpoint supports these Layer 2 messages and the test continues to fail, assume the endpoint is defective and replace it.</li> </ol>
	PASS	The switch can successfully pass messages over the D-channel to the BRI endpoint.

**BRI Layer 3 Query Test (#629)**

This test is used to check the application layer communications between the switch and the endpoint or adjunct.

For BRI endpoints, an application message containing the appropriate endpoint service state is sent by the switch to the endpoint. The endpoint responds with an acknowledgment to the application message.

For ASAI and Lucent adjuncts, this test is not executed from the administration terminal. Rather, a query message is automatically sent by the switch every two minutes. Failure of the switch to receive a response to a query from the adjunct is logged in the Hardware Error Log.

Table 5-142. TEST #629 BRI Layer 3 Query

Error Code	Test Result	Description/ Recommendation
1005	ABORT	The endpoint's MIMs Supported? field is administered to "no." <ol style="list-style-type: none"> <li>1. Use the <b>change station extension</b> command to change the parameter only if the endpoint documentation reflects support for ISDN-BRI Management and Maintenance Procedures.</li> </ol>
1113	ABORT	The signaling link between the switch and the endpoint or adjunct is down. <ol style="list-style-type: none"> <li>1. Use the <b>test port PCSSpp long</b> command to clear any errors which prevent establishment of the signaling link.</li> <li>2. Examine the results of Test #626, which is executed with the command. If this test aborts or fails, follow the repair procedure for the Signaling Link Status Test.</li> </ol>
1139	ABORT	The Packet Bus in the port network is out-of-service. <ol style="list-style-type: none"> <li>1. Follow the repair procedures for the Packet Bus.</li> <li>2. After completing Step 1, execute the <b>test port long PCSSpp</b> command, and review the results of the BRI Port Local LAN Loop Around Test to verify the repair.</li> </ol>
1141	ABORT	The PKT-CTRL is out-of-service. <ol style="list-style-type: none"> <li>1. Consult the repair procedure for PKT-CTRL (Packet Control Circuit Pack) Maintenance documentation.</li> </ol>
1144	ABORT	The PPN Packet Bus is out-of-service. <ol style="list-style-type: none"> <li>1. Follow the repair procedures for the Packet Bus in the PPN.</li> <li>2. After completing Step 1, execute the <b>test port long PCSSpp</b> command, and review the results of the BRI Port Local LAN Loop Around Test to verify the repair.</li> </ol>

*Continued on next page*

Table 5-142. TEST #629 BRI Layer 3 Query — *Continued*

Error Code	Test Result	Description/ Recommendation
1187	ABORT	<p>The circuit pack, port or station may have been busied out by a technician.</p> <ol style="list-style-type: none"> <li>1. Look in the Error Log for Error Type 18 (busied out ) for BRI-BD, BRI-PORT, or BRI-SET.</li> <li>2. If this error type is present for BRI-SET only, then release the station via the <b>release station</b> command.               <ol style="list-style-type: none"> <li>a. If this error type is present for BRI-PORT and BRI-SET, then release the port via the <b>release port PCSSpp</b> command and run the test again.</li> <li>b. If the error is present for BRI-BD, BRI-PORT, and BRI-SET, then release the circuit pack via the <b>release port PCSSpp</b> command and run the test again. If the error is present for BRI-SET only, then release the circuit pack via the <b>release port PPCSS</b> command and run the test again. If the error is present for both BRI-BD and BRI-PORT, then release the circuit pack via the <b>release board PPCSS</b> command and run the test again.</li> </ol> </li> </ol> <p style="text-align: center;"> <b>NOTE:</b> When you release the circuit pack, you release all ports associated with it. If certain ports still need to be busied out, use the <b>release port PCSSpp</b> command to busy them out.</p> <ol style="list-style-type: none"> <li>3. Make sure the terminal is connected.</li> <li>4. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
2012	ABORT	Internal system error
2100	ABORT	<p>Could not allocate the necessary system resources to run this test.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
2068	ABORT	<p>The endpoint has rejected the switch sent application message. This indicates that the endpoint does not support the ISDN-BRI Management and Maintenance Procedure for Endpoint Service Messages.</p> <ol style="list-style-type: none"> <li>1. Use the <b>change station extension</b> command and change the MIMs Supported? field to <b>n</b>.</li> </ol>

*Continued on next page*

Table 5-142. TEST #629 BRI Layer 3 Query — *Continued*

Error Code	Test Result	Description/ Recommendation
2069	ABORT	The endpoint has returned an error response to the switch sent application message. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
2000	FAIL	No response is received from the endpoint or the adjunct. For BRI endpoints: <ol style="list-style-type: none"><li>1. Consult the endpoint documentation to determine if ISDN-BRI Management and Maintenance Procedures are supported. If not supported, use the <b>change station extension</b> command to change the MIMs Supported? field to <b>n</b>. Use the <b>busyout station extension</b> and <b>release station extension</b> commands to busyout and release the endpoint to resolve any endpoint alarms resulting from failure of this test.</li><li>2. If the endpoint supports these procedures and the test continues to fail, assume the endpoint is defective and replace it.</li></ol>
	PASS	The endpoint has successfully responded to the switch's application message.

**BRI Set Audits Test (#630)**

This is a series of two tests which are classified as audits. The switch sends messages to the BRI endpoint to perform the following tests:

- Ringer Audit - This audit ensures that both the switch and the endpoint agree as to the current state of the endpoint's ringer.
- Lamps Audit - This audit ensures that both the switch and the endpoint agree as to the current state of the endpoint's lamps.
- Call Activity Audit - This audit ensures that the state of calls is consistent between the switch and the endpoint.

This test is not executed for ASAI or Lucent adjunct because adjuncts do not employ ringers or lamps, or establish calls on the B-channels associated with the BRI interface.

Table 5-143. TEST #630 BRI Set Audits

Error Code	Test Result	Description/ Recommendation
1113	ABORT	The signaling link between the switch and the endpoint is down. <ol style="list-style-type: none"> <li>1. Use the <b>test port PCSSpp long</b> command to clear any errors which prevent establishment of the signaling link.</li> <li>2. Examine the results of the Signaling Link Status Test (#626) which is run as part of this command. If this test aborts or fails, follow the repair procedure for Test #626.</li> </ol>
1139	ABORT	The Packet Bus in the port network is out-of-service. <ol style="list-style-type: none"> <li>1. Follow the repair procedures for the Packet Bus.</li> <li>2. After completing Step 1, execute the <b>test port long PCSSpp</b> command, and review the results of the BRI Port Local LAN Loop Around Test to verify the repair.</li> </ol>
1141	ABORT	The PKT-CTRL is out-of-service. <ol style="list-style-type: none"> <li>1. Refer to PKT-CTRL (Packet Control Circuit Pack) Maintenance documentation.</li> </ol>
1144	ABORT	The PPN Packet Bus is out-of-service. <ol style="list-style-type: none"> <li>1. Follow the repair procedures for the Packet Bus in the PPN.</li> <li>2. After completing Step 1, execute the <b>test port long PCSSpp</b> command, and review the results of the BRI Port Local LAN Loop Around Test to verify the repair.</li> </ol>

*Continued on next page*

Table 5-143. TEST #630 BRI Set Audits — *Continued*

Error Code	Test Result	Description/ Recommendation
1187	ABORT	<p>The circuit pack, port or station may have been busied out by a technician.</p> <ol style="list-style-type: none"> <li>1. Look in the Error Log for Error Type 18 (busied out ) for BRI-BD, BRI-PORT, or BRI-SET.</li> <li>2. If this error type is present for BRI-SET only, then release the station via the <b>release station</b> command.               <ol style="list-style-type: none"> <li>a. If this error type is present for BRI-PORT and BRI-SET, then release the port via the <b>release port PCSSpp</b> command and run the test again.</li> <li>b. If the error is present for BRI-BD, BRI-PORT, and BRI-SET, then release the circuit pack via the <b>release port PCSSpp</b> command and run the test again. If the error is present for both BRI-BD and BRI-PORT, then release the circuit pack via the <b>release board PPCSS</b> command and run the test again.</li> </ol> </li> </ol> <p><b>⇒ NOTE:</b> When you release the circuit pack, you release all ports associated with it. If certain ports still need to be busied out, use the <b>release port PCSSpp</b> command to busy them out.</p> <ol style="list-style-type: none"> <li>3. Make sure the terminal is connected.</li> <li>4. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
2012	ABORT	Internal system error
2100	ABORT	<p>Could not allocate the necessary system resources to run this test.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>

## SPID Facility Test

This test is used to verify the wiring and operation of the signaling link between the switch and a endpoint or adjunct on a BRI interface. **This test is not executed from the administration terminal, but rather is executed by using a BRI test set equipped with a display.** The test set may replace the BRI set, ASAI or Lucent adjunct under test by plugging it into the same jack or by bridging it onto the wiring at some point between the switch and the endpoint (or adjunct), thereby creating a pseudo-BRI multipoint configuration.

When plugged into the port in this manner, the test set establishes a signaling link connection with the switch and attempts to complete SPID initialization by using the Service SPID administered for the system (see the System Maintenance Administration Form). If the test set displays the correct administered port address for the endpoint or adjunct under test, the test passes (see Service SPID Display which follows). If after one minute nothing is displayed on the test set, the test fails.

Table 5-144. SPID Facility Test

Test Result	Description/ Recommendation
FAIL	No response is received from the endpoint. <ol style="list-style-type: none"><li>1. Check the physical wiring between the switch and the endpoint or adjunct.</li></ol>
FAIL	Display does not match administered port address for the endpoint or adjunct. <ol style="list-style-type: none"><li>1. Change station administration for endpoint or adjunct to match displayed port address.</li></ol>
PASS	Display matches administered port address for the endpoint or adjunct. For BRI endpoints: <ol style="list-style-type: none"><li>1. Verify that the SPID values administered in the switch and the endpoint are consistent.</li><li>2. If the SPID values are correct, replace the endpoint.</li></ol> For ASAI adjuncts: <ol style="list-style-type: none"><li>1. Verify that the TEI values administered in the switch and the adjunct are consistent.</li><li>2. If the TEI values are correct, consult the recommended repair procedures of the manufacturer for the adjunct.</li></ol>

The abbreviations used in (Service SPID Display) have the following meanings:

- P port network (1,2, ...)
- C Carrier (A,B,C, ...)
- SS Slot (01, 02, ...)
- pp port (01-12)
- ext extension one and two (one through 99999)
- SPID service order profile identifier

**Restricted Service  
Starting Display Column**

1		8		14		25		31
PCSSpp	-	ext1	-	SPID111111	-	ext2	-	SPID222222

**Bound to First Endpoint Translation  
Starting Display Column**

1		8		14		25		31
PCSSpp	*	ext1	*	SPID111111	-	ext2	-	SPID222222

**Bound to Second Endpoint Translation  
Starting Display Column**

1		8		14		25		31
PCSSpp	-	ext1	-	SPID111111	*	ext2	*	SPID222222

## CABINET (Cabinet Sensors)

---

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run	Full Name of MO
CABINET	MAJOR	test environment	Cabinet Sensors

The Compact Modular Cabinet (CMC) AC Power Supply (650A) supports one alarm lead that indicates the state of both the power and fan. The CMC uses variable speed fans to reduce noise. The CMC power unit contains Thermal Speed Control. A variable speed fan has a 3-pin connector for the variable input power for speed control and its alarm circuitry.

[Table 5-145](#) shows the LED and alarm conditions.

**Table 5-145. LED and Alarm Conditions**


Condition	LED Status	Alarm State	Fan/Power Alarm
Normal	Red off; Yellow on	Open	Normal
No input power	Red off; Yellow off	Closed	No input power
DC output not present (except Neon)	Red on; Yellow off	Closed	DC output not present (except Neon)
Fan alarm	Red on; Yellow on	Closed	Fan/Power alarm

---

## Fan and Filter Removal/Replacement

---

1. Remove the left door.
2. Remove the fan/filter access panel. See [Figure 5-16](#).



---

Figure 5-16. Fan/Filter Removal

## Fan Assembly Removal/Replacement

1. Pull (unplug) the fan assembly from the chassis using the thumb/finger notch provided. The power for the fan automatically disconnects when the assembly is unplugged.
2. Plug in the new fan assembly. The power for the fan automatically connects when the fan assembly is plugged in.
3. Replace the fan/filter access panel and the left door.

## Fan Filter Removal/Replacement

1. Remove the fan access panel from the left side of the cabinet.
2. Pull the fan filter from the chassis.
3. Clean (vacuum or wash with water) or replace the filter as needed and slide the filter back into the chassis.
4. Replace the fan access panel.

**Hardware Error Log Entries and Test to Clear Values**

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
0 <sup>1</sup>	0	Any	Any	Any	test environment
1(a) 257 (b) 513 (c) 769 (d) 1025 (e) 1281 (f) 1537 (g) 1793 (h)	Any	Cabinet Temperature or Voltage Query Test (#122)	MAJOR	ON	test environment

1. Run the Short Test Sequence first. If all tests pass, run the Long Test Sequence. Refer to the appropriate test description and follow the recommended procedures.

**Notes:**

- a. Error Type: 1 - The Power/Fan Status lead indicates that the power supply of one or more CMC cabinets has detected an alarm condition. The condition can be caused by the failure of any fan or the failure of any power supply output. If more than one CMC cabinet exists, all of the Power/Fan Status leads are tied together (the fan and power lead is an O-ring of all cabinets' status leads). Since an error condition on a fan or power supply output could be the result of a temporary overload (e.g. during board insertion) or caused by the location of the equipment (e.g. fan blockage), a single event may be an anomaly that eventually clears. However, a repeating condition will cause a major alarm.
- b. Error Type: 257 - Temperature Sensor 1: Monitors the temperature near the Pentium processor (SPE). Since temperature alarms can be transient, a single event may be an anomaly that eventually clears. However, a repeating condition will cause a major alarm and may indicate a need to replace one or more components (e.g. a Cabinet Fan may be bad, or check to see if the equipment room air conditioning supply/unit is functional).

- c. Error Type: 513 - Temperature Sensor 2: The temperature sensors are mounted on the TN795 and monitor the temperature near the disk drive (NT C: drive). Since temperature alarms can be transient a single event may be an anomaly that eventually clears. However, a repeating condition will cause a major alarm and may indicate a need to replace one or more components (e.g. a Cabinet Fan may be bad, or check to see if the equipment room air conditioning supply/unit is functional).

 **NOTE:**

An out-of-tolerance voltage condition may be caused by transient conditions (e.g. board insertion or electrical noise). Voltage problems can cause serious damage to the TN795 or highly unpredictable failure modes. Therefore, a repeating condition will cause a major alarm. The following Error Types 769 through 1793 represents the various system voltages and are listed below:

- d. Error Type: 769 - Out-Of-Tolerance voltage condition for -48 VDC.  
 e. Error Type: 1025 - Out-Of-Tolerance voltage condition for -5 VDC.  
 f. Error Type: 1281 - Out-Of-Tolerance voltage condition for +5 VDC.  
 g. Error Type: 1537 - Out-Of-Tolerance voltage condition for +12 VDC.  
 h. Error Type: 1793 - Out-Of-Tolerance voltage condition for +3.3 VDC.

## System Technician-Demanded Tests: Descriptions and Error Codes

Always investigate tests in the order presented in the following table. By clearing error codes associated with the *Cabinet Temperature Query Test*, for example, you may also clear errors generated from other tests in the testing sequence. Test descriptions and recommended maintenance procedures follow for all errors that can occur during system technician-demanded testing.

Order of Investigation	Short Test Sequence	Long Test Sequence	D/ND <sup>1</sup>
Cabinet Test (#122)	X	X	ND
Emergency Transfer Query Test (#124) (a)	X	X	ND
External Alarm Lead Query Test (#120) (b)	X	X	ND
Analog Ring Generator Initialization Test (#117)(c)	X	X	ND
Analog Ring Generator Query Test (#118)(d)	X	X	ND

1. D = Destructive; ND = Nondestructive

## Notes:

- a. Refer to [“EMG-XFER” on page 5-641](#) for a description of this test.
- b. Refer to [“EXT-DEV ADMIN? N \(External Device Alarm\)” on page 5-660](#) for a description of this test.
- c. Refer to [“RING-GEN \(Analog Ring Generator\)” on page 5-1036](#) for a description of this test.
- d. Refer to [“RING-GEN \(Analog Ring Generator\)” on page 5-1036](#) for a description of this test.

---

**Cabinet Test (#122)**

This test queries the Processor circuit pack for the status of the cabinet sensors in the Compact Modular Cabinet. Only one alarm lead is supported by this cabinet type to indicate a power, temperature, or a fan problem. This means that a failure of this test can also mean a power problem, not necessarily just a temperature/fan problem.

**Table 5-146. TEST #122 Cabinet Temperature Query Test**

Error Code	Test Result	Description/ Recommendation
1000	ABORT	System resources required to run this test are not available. 1. Retry the command at 1-minute intervals a maximum of 5 times.
2000	ABORT	Response to the test request was not received within the allowable time period.
2029	ABORT	Internal System Error. 1. Retry the command at 1-minute intervals a maximum of 5 times.

---

*Continued on next page*

Table 5-146. TEST #122 Cabinet Temperature Query Test

Error Code	Test Result	Description/ Recommendation
1	FAIL	<p>There is a fan, temperature, power or voltage problem in one or more of the cabinets. The LEDs on the power supply may indicate the problem source. Otherwise follow the procedures below for each cabinet: From a LAC bash, type "environment". Note voltage ranges and temperature of cabinet.</p> <ol style="list-style-type: none"><li>1. If none of the fans are running, then:<ol style="list-style-type: none"><li>a. Verify 8-14 volt DC power is available to the fan units by checking the wiring connector.<ul style="list-style-type: none"><li>— If there is 8-14 volt DC power at the connector, there should be power to the fans. If the fans still do not run, replace the fan assembly.</li><li>— If there is no 8-14 volt DC power at the connector, then the power unit fan output is defective or thermally shut down. Let the power unit cool and recycle AC input power. If no fan output, replace the power unit. If the fans still do not run, escalate the problem.</li></ul></li></ol></li><li>2. If only 1 of the fans is not running, replace the fan.</li><li>3. If all the fans can be started, wait five minutes and rerun the test. If the test fails again, proceed to Step 4 or 5 as applicable.</li></ol>

*Continued on next page*

Table 5-146. TEST #122 Cabinet Temperature Query Test

Error Code	Test Result	Description/ Recommendation
1	FAIL (cont'd.)	<p>4. If the fans are not at high speed, measure the cabinet temperature at the air intake and the air exhaust at the top of the cabinet.</p> <p>a. If the 5 - 60<sup>0</sup> C criteria is met, there is a problem with the fans that is preventing the fans from operating at high speed. Replace the fans. If the fans run at high speed, wait 5 minutes to give the cabinet time to cool down and, rerun the test. If the problem persists, go to step 5.</p> <p>b. If the 5 - 60<sup>0</sup> C criteria is not met, the Processor circuit pack is incorrectly reporting this condition. Look for and resolve all errors on these maintenance objects first, then rerun the test.</p> <p>5. If the fans are running at the high speed, check the items on list that follows. Any one of the items could be restricting or redirecting the flow of air within the cabinet.</p> <p>a. Check filter. If the filter is dirty or clogged it should be cleaned or replaced. The filter can either be washed with soap and water or vacuumed.</p> <p>b. Make sure there is nothing other than circuit packs in the carrier slots that could be restricting the air flow.</p> <p>c. Make sure there are no missing (blank) circuit pack or carrier faceplates. Install and/or replace them as necessary.</p> <p>d. Make sure the cabinet doors are properly closed. The doors must be closed for the fans to be able to properly cool the cabinet. Wait five minutes to give the fans a chance to cool the cabinet. Rerun the test. If the tests still fails, proceed to Step 6.</p>
1	FAIL	<p>6. At this point, there should be nothing impeding the air flow, and the fans should be running at high speed. Check the temperatures for the 5 - 60<sup>0</sup> C criteria.</p> <p>a. If the 5 - 60<sup>0</sup> C criteria exists, a temperature problem exists, and the fans (at high speed) should cool down the switch. Wait five minutes and rerun the test. If the test still fails, the ambient room temperature is probably too high, and the room should be cooled.</p> <p>b. If the 5 - 60<sup>0</sup> C criteria does not exist, the fans are defective. Replace the fan assembly and rerun the test. Failures can occur on the Processor circuit pack that <b>is not</b> detected by the respective maintenance object, but that cause many, if not all, environment tests to fail. If many environment tests are failing, the suspect circuit pack (depending on the system configuration) should be replaced and the test rerun.</p>

Continued on next page

Table 5-146. TEST #122 Cabinet Temperature Query Test

Error Code	Test Result	Description/ Recommendation
1	FAIL ( <i>cont'd.</i> )	There is a problem with the environment of the power system: 7. The power unit for the cabinet may be defective. a. Verify and, if necessary, replace the power unit b. Rerun the test. If the test still fails, proceed to Step 8.
	PASS	There is neither a power nor a fan problem in the cabinet. If a problem is reported, troubleshoot by using the procedures for the FAIL cases described previously.

## CDR-LNK (CDR Link)

---

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run	Full Name of MO
CDR-LINK	MINOR	test cdr-link	CDR Link
CDR-LINK	WARNING	test cdr-link	CDR Link

The CDR feature records detailed call information on incoming and outgoing calls on specified trunk groups and on calls set up between local stations based on the options specified using the change system-parameters `cdr` command. The CDR feature stores this call duration information in a CDR output file on DEFINITY ONE. This information is read by a Call Accounting Software (CAS) application software package running on a user-provided PC.

CDR Link Maintenance provides a strategy for verifying that the CDR files generated by DEFINITY ONE are being retrieved by the CAS application software running on the customer's PC. This strategy includes a set of tests for periodic diagnosis, detection of errors during normal operation, actions for troubleshooting, and raising alarms for serious problems.

DEFINITY ONE and the customer's PC are connected to a LAN which allows the CDR directory on DEFINITY ONE to be mapped to a directory on the PC. The CDR software on DEFINITY ONE writes CDR records to a `cdr.out` file on its hard drive. Every 10 minutes DEFINITY ONE renames the file as `cas.in` if the `cas.in` file does not exist and opens a new `cdr.out` file. Within a few minutes after the `cas.in` file is created, the CAS software on the PC should read and delete the `cas.in` file to allow the DEFINITY ONE to move a new `cdr.out` file to `cas.in` at the next 10 minute trigger.

The CAS software running on the customer's PC should retrieve the data from the `cas.in` file and delete the file at least every 10 minutes to allow DEFINITY ONE to move the `cdr.out` file to the `cas.in` file. The size of the `cdr.out` file has been engineered to not fill up as long as the transfer takes place within 10 minutes. If the `cas.in` file is not removed by CAS by the time DEFINITY ONE needs to rename `cdr.out` to `cas.in`, DEFINITY ONE sets the state of the CDR link to "down" and keeps writing to the `cdr.out` file until the `cdr.out` file reaches a maximum size, at which time a CDR-LINK alarm is generated. New CDR data will continue to be written to an internal buffer on DEFINITY ONE but eventually that buffer will be filled up and CDR data will be lost. To clear the problem, the `cas.in` file must be deleted by the CAS system. The CDR link will then be put in the "up" state, the `cdr.out` file will be renamed to `cas.in`, and the buffered CDR data along with new CDR data will be written to the `cdr.out` file.

The ability for DEFINITY ONE to move the cdr.out file to the cas.in file is monitored by the CDR-LINK Maintenance Object. From a user's viewpoint the CDR-LINK MO is similar to the PRI-CDR link MO used by DEFINITY to provide maintenance of the physical link between DEFINITY and an external CDR device. The DEFINITY ONE CDR-LINK MO can be tested using the test CDR-LINK command, it can be busied out and released with the busyout CDR-LINK and release CDR-LINK commands, and it has an "up" and "down" state as displayed by the status CDR-LINK command.

## Procedures for Restoring the CDR Link

1. Get the status of CDR links.  
Enter **status cdr-link** command and make sure that the CDR links are not busied out for maintenance. If the link is down, then continue to the next step.
2. Verify that the PC running the CAS application software is in service and that the CAS application software is running.
3. Verify that the Cdr directory on DEFINITY ONE is shared. For more information about the Cdr directory, see "Set up Call Accounting" in Chapter 3 of *DEFINITY ONE Communications System Release 2.0 Installation and Upgrades (555-233-109)*.
4. Verify that the customer's PC has a drive mapped to the shared directory on DEFINITY ONE (see Possible Problem Areas below).
5. Log on to DEFINITY ONE and select the "bash" application. From the bash session, change the current directory to `d:/LucentData/Cdr` (`cd d:/LucentData/Cdr`). Verify that the cas.in file is being read and deleted by CAS every few minutes by checking that a new cas.in file is created every 10 minutes (`ls -l cas.in`) and that it is removed within a few minutes after it is created.

NOTE: To prevent generating false alarms when CDR is administered on DEFINITY ONE but the CAS software on the PC is not operational, the CDR link can be busied out using the *busyout CDR-LINK* command.

## Possible Problem Areas

1. The CDR directory (`d:/LucentData/Cdr`) on DEFINITY ONE has to be shared with full control permissions from DEFINITY ONE. For more information about the Cdr directory, see "Set up Call Accounting" in Chapter 3 of *DEFINITY ONE Communications System Release 2.0 Installation and Upgrades (555-233-109)*.
2. A login has to be created on DEFINITY ONE that matches the login of the person logging into the WINDOWS 95 PC running the CAS application.
3. The login used for CAS on DEFINITY ONE has to have administration rights.

4. On the WINDOWS 95 PC, the network drive used by CAS has to be mapped to the CDR directory on DEFINITY ONE.
5. CAS on the WINDOWS 95 PC has to be configured to read the mapped drive.




Figure 5-17. CDR Configuration

## Error Log Entries and Test to Clear Values

---

Table 5-147. CDR Link Maintenance Error Log Entries

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
0 <sup>1</sup>	0	Any	Any	Any	test cdr-link sh
18 (a)	0	busyout cdr-link	WARNING	OFF	release cdr-link
257 (b)	Any	Link Retry Test (#215)	MINOR/ WARNING <sup>2</sup>	OFF	test cdr-link
513 (c)	Any				test cdr-link

---

1. Run the Short Test Sequence first. If all tests pass, run the Long Test Sequence. Refer to the appropriate test description and follow the recommended procedures.
2. Minor alarms on this MO may be downgraded to Warning alarms based on the value used in the **set options** command.

### Notes:

- a. System Technician has busied out the CDR link to the out-of-service state. No CDR records will be written to the cdr.out file on DEFINITY ONE.
  - b. Link Retry Test (#215) fails. Refer to [“Procedures for Restoring the CDR Link” on page 5-372](#) for resolution.
  - c. The CDR link is down since the CAS system has not deleted the cas.in file in time for DEFINITY ONE to move the cdr.out file to the cas.in file. Use the status CDR-LINK command to verify that the link is down and refer to [“Procedures for Restoring the CDR Link” on page 5-372](#) for resolution. This error indicates that the CAS system is in an off-line state. Enter **test cdr-link** command to verify that the CDR link is back in the UP state.
-

## System Technician-Demanded Tests: Descriptions and Error Codes

Always investigate tests in the order presented in the table below when inspecting errors in the system. By clearing error codes associated with the *Link Retry Test*, for example, you may also clear errors generated from other tests in the testing sequence.

Order of Investigation	Short Test Sequence	Long Test Sequence	D/ND <sup>1</sup>
Link Tear Down Test (#213)		X	D
Link Retry Test (#215)	X	X	ND

1. D = Destructive; ND = Nondestructive

### Link Tear Down Test (#213)

This test puts the CDR logical link in a DOWN state for DEFINITY ONE. The link will be restored to the UP state automatically by the Link Retry test (#215). The Link Tear Down test is used to help verify that the Link Retry test (#215) will return the state of the link to UP if the cdr.out file is not full. On DEFINITY this test is used to actually take down the physical link to a CDR output device but on DEFINITY ONE there is no hardware link to control.

CDR records will continue to be written to an internal buffer when the link is down so this is may not be a destructive test as long as the link is restored by the Link Retry test which is executed as part of the sequence of tests run for the test cdr-link long command.

Table 5-148. TEST #213 Link Tear Down Test

Error Code	Test Result	Description/ Recommendation
40	ABORT	Internal system error
50	ABORT	Internal system error 1. Retry the command at 1-minute intervals a maximum of 5 times.
1010	ABORT	The CDR link has been busied out to out-of-service. 1. Enter the <b>release cdr-link</b> command to release the CDR link from busyout state. 2. Retry the <b>test cdr-link long</b> command to execute the test.

Continued on next page

Table 5-148. TEST #213 Link Tear Down Test — *Continued*

Error Code	Test Result	Description/ Recommendation
	FAIL	Internal system error  1. Retry the command at 1-minute intervals a maximum of 5 times.
	PASS	The CDR link has been put in a DOWN state.  CDR records are still recorded in an internal buffer but DEFINITY ONE will not write to the cdr.out file. Test 215 is used to put the logical link into an UP state.

**Link Retry Test (#215)**

This test sets the state of the CDR link to UP if the cdr.out file is not full and to DOWN if the cdr.out file is full. The cdr.out file is used to record CDR records on DEFINITY ONE. The file will not get full if CAS system is periodically retrieving and deleting the cas.in file so that DEFINITY ONE can rename the cdr.out file to cas.in.

Table 5-149. TEST #215 Link Retry Test

Error Code	Test Result	Description/ Recommendation
10	ABORT	Internal system error
20	ABORT	Internal system error. Internal error in Maintenance Action Process (MAP). MAP returns an error back to maintenance script (HMM). Timer expires while waiting for the reply from MAP.  1. Retry the command at 1-minute intervals a maximum of 5 times.
30	ABORT	Internal system error  1. Refer to <a href="#">“Procedures for Restoring the CDR Link”</a> on page 5-372.
1010	ABORT	The CDR link has been busied out to out-of-service.  1. Enter <b>release cdr</b> command to release the CDR link from busyout state.  2. Retry <b>test cdr-link</b> command to execute the test.

*Continued on next page*

Table 5-149. TEST #215 Link Retry Test — *Continued*

Error Code	Test Result	Description/ Recommendation
	FAIL	<p>The cdr.out file on DEFINITY ONE is full since CAS is not retrieving call records from DEFINITY ONE. DEFINITY ONE may still be storing CDR records in an internal buffer but it has stopped writing data to the cdr.out file.</p> <p>The cdr.out file on DEFINITY ONE is periodically renamed as the cas.in file on DEFINITY ONE to allow CAS software to retrieve the CDR records. The CAS software runs on a separate PC which maps the directory containing the cas.in file on DEFINITY ONE to a drive letter on the PC. If CAS does not read and delete the cas.in file every few minutes, the cdr.out file may reach its maximum size which causes an alarm to be generated. The Link Retry test will fail when the cdr.out file is full.</p> <ol style="list-style-type: none"><li>1. Refer to the <a href="#">“Procedures for Restoring the CDR Link” on page 5-372</a> for instructions.</li></ol>
	PASS	<p>The CDR link is up.</p> <p>CAS is reading and deleting the cas.in file on DEFINITY ONE on a periodic basis so DEFINITY ONE is able to move the cdr.out file to the cas.in file and continue writing new CDR records to the cdr.out file.</p>

## CLAN-BD (Control LAN Circuit Pack)

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run <sup>1</sup>	Full Name of MO
CLAN-BD	MINOR	<b>test board UUCSS long</b>	Control LAN Circuit Pack
CLAN-BD	WARNING	<b>test board UUCSS short</b>	Control LAN Circuit Pack

1. UU is the universal cabinet number (1 for PPN, 2 - 44 for EPNs). C is the carrier designation (A, B, C, D, or E). SS is the number of the slot in which the circuit pack resides (01 to 21).

### Control LAN Circuit Pack

The TN799 Control LAN (C-LAN) packet port circuit pack provides TCP/IP connection to adjuncts applications such as CMS, INTUITY, and DCS Networking. The C-LAN circuit pack has 1 10baseT Ethernet connection and up to 16 DS0 physical interfaces for PPP connections. In addition to the TCP/IP functionality, C-LAN extends the ISDN capabilities for csi models by providing Packet bus access.

A remote socket control link (RSCL) links the C-LAN and the SPE to pass call control and other management information. Since one link serves all the ports on the circuit pack, maintenance of the RSCL is part of the C-LAN circuit pack maintenance.

The C-LAN TN799 circuit pack combines the functions of the PGATE and PI circuit packs into one circuit pack. The PGATE or PI can be used with the C-LAN to create an X.25-to-TCP/IP bridge for adjunct and DCS connectivity.

### Control LAN Congestion Controls

The switch activates congestion controls on C-LAN when it detects buffers exceeding the threshold. The switch releases the congestion controls when the C-LAN reports that its buffer level has returned to normal levels.

<u>If congestion:</u>	<u>Then the switch:</u>
Persists for a 14-minute interval,	Raises MINOR alarm.
Exhausts buffers,	Raises MINOR alarm.
Ceases for 12 minutes,	Retires MINOR alarm.

## Error Log Entries and Test to Clear Values

Table 5-150. CLAN-BD Error Log Entries

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
1(a)	0		MINOR	ON	
18 (b)	0		WARNING	OFF	release board UUCSS
217 (c)	0	None	WARNING	ON	
257	65535	Control Channel Loop Test (#52)	MINOR	ON	test board UUCSS l r 20
257 (d)					
513 (e)	4352-4357		MINOR	ON	
769 (f)	4358				
1293 to 1295 (g)	Any		MINOR	ON	reset board UUCSS
1537(h)	Any		MINOR	ON	
1794 (i)			MINOR	ON	
1798 (j)					
2049 (k)		Packet Interface Test (#598)	MINOR	ON	test board UUCSS l r 3
2305 2306 (l)					
2561 to 2668 (m)	Any				
2817 2819 (n)		Congestion Query Test (#600)	MINOR	ON	test board UUCSS s r 3
3073 (o)		Link Status Test (#601)	MINOR	ON	test board UUCSS s
3330 (p)			MINOR	ON	reset board UUCSS
3586 (q)					
3999 (q)	Any	None			
3840 (r)	4096-4102				
3841 3843 (s)					

*Continued on next page*

Table 5-150. CLAN-BD Error Log Entries

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
3842 (t)					
3844 (u)	Any				
3845 (v)	Any				
3846 (w)	Any				
3848 (x)	Any				
3849 (y)	Any				
3850-3861 (z)	Any				
3862 (aa)	Any				

## Notes:

- a. **Error Type 1:** Circuit pack stopped functioning or is not physically present.
  1. Verify that the circuit pack is present.
  2. If circuit pack is present, reset the circuit pack (**reset board UUCSS**).
  3. If the error persists, replace the circuit pack.
- b. **Error Type 18:** The C-LAN circuit pack busied out.
- c. **Error Type 217:** applies to 10 circuit packs:
  1. Remove the circuit pack(s) against which the error is logged.
- d. **Error Type 257:** Transient communication problem between switch and circuit pack; does not affect service and can be ignored.
  1. Ignore this error, unless the Control Channel Loop Test (#52) fails.
  2. If Test #52 fails, replace the circuit pack.

Repetitive failures of the Control Channel Loop Test indicate circuit pack hardware failure.

- e. **Error Type 513:** Circuit pack detected and reported hardware failure.

1. Reset the circuit pack (**reset board UUCSS**).

Aux Data:

4352	External RAM error
4353	Internal RAM error
4355	ROM Checksum error
4356	Angel Message Corruption error
4357	Instruction set error

- f. **Error Type 769:** Logic error. By itself this error may be ignored, but it may result in other error types being reported.

- g. **Error Type 1293-1295:** Critical hardware or firmware error.

If the switch detects:	Then the switch:
1 error,	Resets circuit pack.
3 errors in 15 minutes,	Raises MINOR alarm.

Error Type descriptions are as follows:

1293	Insane onboard processor
1294	Onboard translation RAM error
1295	(Aux 3) RSCL link down (Aux 0) RSCL keep alive failure

1. Attempt to clear the alarm (**reset board UUCSS**).
2. If alarm persists, replace circuit pack.

- h. **Error Type 1537:** Switch removed hyperactive circuit pack that reported threshold number of errors.

1. Attempt to clear the alarm (**reset board UUCSS**).
2. If the error recurs within 15 minutes, replace the circuit pack.

- i. **Error Type 1794:** Packet bus transmit buffers has overflowed.

1. Attempt to clear the alarm (**reset board UUCSS**).
2. If the error recurs within 15 minutes, replace the circuit pack.

- j. **Error Type 1798:** Unable to write translation RAM.

1. Attempt to clear alarm (**reset board UUCSS**).
2. If alarm recurs within 15 minutes, replace the circuit pack.

- k. **Error Type 2049:** Packet Interface Test (#598) failed.
1. Attempt to clear the alarm (**test board UUCSS I r 3**).
  2. If alarm does not clear, reset the circuit pack (**reset board UUCSS**).
  3. If circuit pack resets, execute Packet Interface Test (#598) several times.
  4. If Packet Interface Test (#598) continues to fail, replace the circuit pack.
- l. **Error Type 2305-2306:** Error in received frame from packet bus.

Error Type:	Description
2305	Received invalid LAPD frame.
2306	Detected parity error on received frame.

Most likely cause—packet bus problem.

Other cause—circuit pack fault.

Invalid LAPD frame errors occur when the frame

- Contains a bad Cyclic Redundancy Check (CRC)
  - Is greater than the maximum length
  - Violates the link level protocol
1. Retry the command (**test board UUCSS**) and see if the condition clears.
  2. If condition persists, execute PPE/LANBIC Receive Parity Error Counter Test (# 597) and determine if the condition clears.
  3. If condition persists, execute Packet Interface Test (# 598) to verify circuit pack integrity.
  4. If Packet Interface Test (# 598) fails, consult repair procedure for the packet bus.
- m. **Error Type 2561-2668:** System software received an indication that the socket was closed due to an error. Errors are reported as log only. Errors logged here are for the sockets that had *no* processor channels associated with them, for example, sockets to read SNMP data. The counter base is offset by the application type of the application associated with this socket that is down. The Aux Data field of the log entry contains this application's number, for example, a SNMP application would have its application number in the Aux Data field.

**⇒ NOTE:**

2561 - 2668 is a range of reserved numbers for future applications.  
2570 currently represents an SNMP socket failure.

- n. **Error Type 2817-2819:** Congestion Query Test (#600) failed.

The Error Types correspond to the descriptions:

- 2817 All buffers exhausted.
- 2819 Utilized buffers exceed threshold.

If:	Then:
Active buffers exceed threshold,	C-LAN enters congested state.

1. Refer to [“Congestion Query Test \(#600\)” on page 5-391](#) for Abort and Fail Error Codes.
- o. **Error Type 3073:** Remote Socket Control Link (RSCL) or Link Status Test (#601) failed. This failure may be due to:
- This circuit pack
  - The packet bus
  - The packet interface circuit pack

If:	Then:
RSCL disconnects at link level	Link fails
Link cannot be reconnected quickly	Switch raises MINOR alarm

- p. **Error Type 3330:** Critical failure in Packet Bus interface.

Below, Error Types correspond to descriptions.

If the switch detects:	Then it:
1 error,	Resets circuit pack.
2 errors in 15 minutes,	Raises MINOR alarm.

1. Attempt to clear the alarm (**reset board UUCSS**).
2. If alarm persists, replace circuit pack.

- q. **Error Type 3586 and 3999:** Switch removed hyperactive circuit pack that reported threshold number of errors. One or more of the following symptoms may be present:
- Circuit pack port tests return NO BOARD.
  - List configuration command shows circuit pack and ports are installed properly.

If Error Type 3999:	And traffic volume is:	Then:
Does not accompany Error Type 3586,	Heavy	Circuit pack is in service, but sent at least half hyperactive threshold. With heavy traffic, this is normal.
Does not accompany Error Type 3586,	Light	Circuit pack is in service, but sent at least half hyperactive threshold. With light traffic, this error indicates a problem with the circuit pack, its links, or the equipment attached to the links.
Accompanies Error Type 3586,	Either Light or Heavy	Switch removed hyperactive circuit pack.

1. Busyout (**busyout board UUCSS**) and release (**release board UUCSS**) circuit pack
  2. Allow 30 minutes for condition to clear itself.
  3. To re-establish circuit pack into service manually, busyout (**busyout board UUCSS**), reset (**reset board UUCSS**), and release (**release board UUCSS**) the circuit pack.
  4. If error recurs within 15 minutes, replace the circuit pack.
  5. If the same error occurs on a different circuit pack, follow normal escalation procedures.
- r. **Error Type 3840:** Circuit pack received bad control channel message from switch.

Aux Data:

4096	Bad major heading
4097	Bad port number
4098	Bad data
4099	Bad sub-qualifier
4100	State inconsistency
4101	Bad logical link
4102	Bad application identifier

- s. **Error Type 3841-3843:** errors do not affect service.

Below, Error Types correspond to descriptions.

3841	Internal firmware error.
3843	Bad translation RAM. Call uses another translation location.

These errors do not affect service, however, they may cause reports of other errors that do affect service.

If Error Type 3843 begins to affect service, it escalates to Error Type 1294.

- t. **Error Type 3842:** Packet interface receive buffers overflowed.

If this error occurs frequently, the overflow may be congesting the circuit pack.

1. Refer to "[Receive FIFO Overflow Error Counter Test \(#596\)](#)" on [page 5-389](#).

- u. **Error Type 3844:** LAPD frame contains LAPD Protocol Error.

By themselves, these errors do not affect service.

- v. **Error Type 3845:** Angel inter processor error.

By themselves, these errors do not affect service.

- w. **Error Type 3846:** High CPU occupancy.

By themselves, these errors do not affect service.

- x. **Error Type 3848:** Interprocessor LAPD protocol error.

By themselves, these errors do not affect service.

- y. **Error Type 3849:** Interprocessor LAPD frame error.

By themselves, these errors do not affect service.

- z. **Error Type 3850 - 3861:** IBL error.

By themselves, these errors do not affect service. These errors can occur only on a G3csi machine that has an Interboard Link (IBL).

- aa. **Error Type 3862:** Memory allocation failure.

By themselves, these errors do not affect service.

---

## System Technician-Demanded Tests: Descriptions and Error Codes

Investigate errors in the order they appear in the table below.

Order of Investigation	Short Test Sequence	Long Test Sequence	D/ND <sup>1</sup>
Control Channel Loop-Around Test #52	X	X	ND
Circuit Pack Restart Test #252			D
Invalid LAPD Frame Error Counter Test #597		X	ND
PPE/LANBIC Receive Parity Error Counter Test #595		X	ND
Receive FIFO Overflow Error Counter Test #596		X	ND
Packet Interface Test #598	X	X	ND
Congestion Query Test #600	X	X	ND
Link Status Test #601	X	X	ND

1. D = Destructive; ND = Nondestructive

### Control Channel Loop-Around Test (#52)

This non-destructive test fails if the circuit pack does not return to a sane state after being reset. This test queries the circuit pack for its code and vintage, and verifies its records.

Table 5-151. TEST #52 Control Channel Loop-Around Test

Error Code	Test Result	Description/ Recommendation
None 2100	ABORT	Could not allocate the necessary system resources to run test. <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals, up to 5 times.</li> <li>2. If the problem persists, escalate the problem.</li> </ol>
	FAIL	The circuit pack failed to return the code or vintage. <ol style="list-style-type: none"> <li>1. Retry command at 1-minute intervals, up to 5 times.</li> <li>2. Reset the board (<b>reset board UUCSS</b>).</li> <li>3. If reset aborts with error code 1115, busyout (<b>busyout board UUCSS</b>), reset (<b>reset board UUCSS</b>), and release board (<b>release board UUCSS</b>).</li> <li>4. If test continues to fail, replace the circuit pack.</li> <li>5. Escalate the problem if failures continue.</li> </ol>
	PASS	Test successful.

## Circuit Pack Restart Test (#252)

**NOTE:****This test is destructive.**

Execute this test (not part of either short or long demand test sequence) to reset the circuit pack only if there are PPCPU errors. This test fails if the circuit pack does not return to a sane state after being reset. The circuit pack resets through the SAKI Sanity Test (#53).

**Table 5-152. Test #252 Circuit Pack Restart Test**

Error Code	Test Result	Description/ Recommendation
None	ABORT	Could not allocate the necessary system resources to run test. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals, up to 5 times.</li><li>2. If the problem persists, escalate the problem.</li></ol>
1015	ABORT	Port is not out-of-service. <ol style="list-style-type: none"><li>1. Busyout the circuit pack (<b>busyout board UUCSS</b>).</li><li>2. Retry the command at 1-minute intervals, up to 5 times.</li><li>3. If the problem persists, escalate the problem.</li></ol>
2100	ABORT	Could not allocate the necessary system resources to run test. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals, up to 5 times.</li><li>2. If the problem persists, escalate the problem.</li></ol>
1, 2	FAIL	The circuit pack failed to reset. <ol style="list-style-type: none"><li>1. Retry command at 1-minute intervals, up to 5 times.</li><li>2. If the problem persists, pull out and reseal the circuit pack.</li><li>3. If the problem persists, replace the circuit pack.</li></ol>
	PASS	The circuit pack initialized correctly.

**PPE/LANBIC Receive Parity Error Counter Test  
(#595)**

This test is non-destructive. When the C-LAN circuit pack detects a parity error with a received frame, it increments the PPE/LANBIC Receive Parity error counter. This test reads and clears the counter, and may verify repair of problem.

Errors may indicate a problem with:

- This circuit pack
- A packet bus
- Another circuit pack on the bus

**Table 5-153. TEST #595 PPE/LANBIC Receive Parity Error Counter Test**

Error Code	Test Result	Description/ Recommendation
2000	ABORT	Did not receive circuit pack test response within the allowable time period. <ol style="list-style-type: none"> <li>1. Retry command at 1-minute intervals, up to 5 times.</li> <li>2. If the problem persists, reset the circuit pack (<b>reset board UUCSS</b>).</li> <li>3. If the problem persists, replace the circuit pack.</li> </ol>
2100 2500	ABORT ABORT	Could not allocate the necessary system resources to run test. Internal system error. <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals, up to 5 times.</li> <li>2. If the problem persists, escalate the problem.</li> </ol>
1-10	FAIL	Circuit pack detects parity errors. The Error Code indicates the value of the on-board error counter. <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals, up to 5 times.</li> <li>2. If the test continues to fail, execute the Packet Interface Test (#598) (<b>test board UUCSS</b>).</li> <li>3. If Packet Interface Test (#598) fails, see Packet Bus repair procedures.</li> </ol>
	PASS	Circuit pack detects no errors.

**Receive FIFO Overflow Error Counter Test (#596)**

This test is non-destructive. When the C-LAN circuit pack detects packet bus buffer overflow, it increments the error on the FIFO Overflow error counter. This test reads and clears the counter.

If errors are:	Then they may be due to:
Occasional	Statistical buffer sizing
Persistent	Circuit pack congestion that requires redistribution of traffic load

**Table 5-154. TEST #596 Receive FIFO Overflow Error Counter Test**

Error Code	Test Result	Description/ Recommendation
2000	ABORT	Did not receive circuit pack test response within the allowable time period. <ol style="list-style-type: none"> <li>1. Retry command at 1-minute intervals, up to 5 times.</li> <li>2. If the problem persists, reset the circuit pack (<b>reset board UUCSS</b>).</li> <li>3. If the problem persists, replace the circuit pack.</li> </ol>
2100	ABORT	Could not allocate the necessary system resources to run test.
2500	ABORT	Internal system error. <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals, up to 5 times.</li> <li>2. If the problem persists, escalate the problem.</li> </ol>
1-10	FAIL	Circuit pack detects overflow errors. The error code indicates the value of the on-board error counter. <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals, up to 5 times.</li> <li>2. If the test continues to fail, execute the Packet Interface Test (#598) (<b>test board UUCSS</b>).</li> <li>3. If Packet Interface Test (#598) fails, refer to Packet Bus repair procedures.</li> </ol>
	PASS	Circuit pack detects no errors.

**Invalid LAPD Frame Error Counter Test (#597)**

This test is non-destructive.

C-LAN detects invalid frames when it receives

- A frame with a CRC error
- An unrecognizable frame
- A recognizable frame in an unexpected state

When the C-LAN circuit pack detects an invalid LAPD frame, it increments the Invalid LAPD Frame error counter. This test reads and clears the counter, and verifies the repair of the problem.

Errors may indicate a:

- Circuit pack problem
- Packet bus problem
- Problem with another circuit pack on the bus

**Table 5-155. TEST #597 Invalid LAPD Frame Error Counter Test**

Error Code	Test Result	Description/ Recommendation
2000	ABORT	Did not receive circuit pack test response within the allowable time period. <ol style="list-style-type: none"> <li>1. Retry command at 1-minute intervals, up to 5 times.</li> <li>2. If the problem persists, reset the circuit pack (<b>reset board UUCSS</b>).</li> <li>3. If the problem persists, replace the circuit pack.</li> </ol>
2100	ABORT	Could not allocate the necessary system resources to run this test.
2500	ABORT	Internal system error. <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals, up to 5 times.</li> <li>2. If the problem persists, escalate the problem.</li> </ol>
1-10	FAIL	The circuit pack detects LAPD frame errors. The error code indicates the value of the on-board error counter. <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals, up to 5 times.</li> <li>2. If the test continues to fail, execute the Packet Interface Test (#598) (<b>test board UUCSS long</b>).</li> <li>3. If Packet Interface Test (#598) fails, refer to Packet Bus repair procedures.</li> </ol>
	PASS	Circuit pack detects no errors.

## Packet Interface Test (#598)

This non-destructive test checks the packet bus interface circuitry on the C-LAN circuit pack. Test failure indicates faulty circuit pack.

Table 5-156. TEST #598 Packet Interface Test

Error Code	Test Result	Description/ Recommendation
2000	ABORT	Did not receive circuit pack test response within the allowable time period. 1. Retry command at 1-minute intervals, up to 5 times. 2. If the problem persists, reset the circuit pack ( <b>reset board UUCSS</b> ). 3. If the problem persists, replace the circuit pack.
2012	ABORT	Could not allocate the necessary system resources to run test.
2100	ABORT	Internal system error. 1. Retry the command at 1-minute intervals, up to 5 times. 2. If the problem persists, escalate the problem.
	FAIL	Circuit pack has detected a failure of the Packet Interface Test (#598). 1. Retry command at 1-minute intervals, up to 5 times. 2. If the problem persists, reset the circuit pack ( <b>reset board UUCSS</b> ). 3. If the test continues to fail, replace the circuit pack.
	PASS	The Packet Interface Test (#598) passed.

## Congestion Query Test (#600)

This non-destructive test queries the number of used buffers to determine if the C-LAN circuit pack is congested.

If:	Then:
Used buffers are, or are nearly, exhausted,	The test fails
The test fails,	The switch redirects outgoing calls to another available C-LAN, and denies new incoming calls

Normal call handling resumes when the C-LAN circuit pack has recovered from congestion.

Table 5-157. TEST #600 Congestion Query Test

Error Code	Test Result	Description/ Recommendation
2000	ABORT	<p>Did not receive circuit pack test response within the allowable time period.</p> <ol style="list-style-type: none"> <li>1. Retry command at 1-minute intervals, up to 5 times.</li> <li>2. If the problem persists, reset the circuit pack (<b>reset board UUCSS</b>).</li> <li>3. If the problem persists, replace the circuit pack.</li> </ol>
2012	ABORT	<p>Could not allocate the necessary system resources to run test.</p>
2100	ABORT	<p>Internal system error.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals, up to 5 times.</li> <li>2. If the problem persists, escalate the problem.</li> </ol>
1	FAIL	<p>The buffer level is nearly exhausted.</p>
2	FAIL	<p>The C-LAN is congested, and no buffers are available.</p> <ol style="list-style-type: none"> <li>1. Retry command at 1-minute intervals, up to 5 times.</li> <li>2. If command continues to fail, examine the C-LAN port measurements to determine which ports are heavily utilized and the processor occupancy of the circuit pack.</li> </ol> <p><i>Low processor occupancy</i> when C-LAN congested indicates circuit pack failure.</p> <ol style="list-style-type: none"> <li>1. If the problem persists, reset the circuit pack (<b>reset board UUCSS</b>).</li> <li>2. If congestion recurs, replace the circuit pack.</li> </ol> <p><i>High processor occupancy</i> indicates the C-LAN is congested due to traffic load.</p> <ol style="list-style-type: none"> <li>1. To relieve congestion in the short term, selectively busyout ports (<b>busyout port UUCSSpp</b>) on the Control LAN circuit pack.</li> <li>2. To achieve a more permanent resolution, it may be necessary to move ports on this circuit pack to other Control LAN circuit packs.</li> <li>3. Consider replacing affected C-LAN ports with new ports.</li> </ol>
3	FAIL	<p>The C-LAN circuit pack is not operating normally and is congested.</p>
	PASS	<p>Hardware setting and attached cable type match C-LAN circuit pack administration. The circuit pack detects no errors.</p>

**Link Status Test (#601)**

This non-destructive test determines the state of the call control signaling link for Control LANs. If the signaling link is physically connected, the test sends a test frame over the link and checks for a response. The test passes only if both the signaling link is connected and the test frame is successfully transmitted.

A failure may indicate a problem with:

- This circuit pack
- The packet bus
- The packet interface circuit pack

**Table 5-158. TEST #601 Link Status Test**

Error Code	Test Result	Description/ Recommendation
2012	ABORT	Could not allocate the necessary system resources to run this test.
2100	ABORT	Internal system error. <ol style="list-style-type: none"> <li>1. Retry command at 1-minute intervals, up to 5 times.</li> <li>2. If the problem persists, escalate the problem.</li> </ol>
2	FAIL	The RSCL control link disconnected. <ol style="list-style-type: none"> <li>1. Retry command at 1-minute intervals, up to 5 times.</li> <li>2. If the test continues to fail, execute the Packet Interface Test (#598) (<b>test board UUCSS</b>) to determine if the problem is due to the circuit pack.</li> <li>3. If the Packet Interface Test (#598) fails, refer to Packet Interface Test repair procedures.</li> <li>4. If the Packet Interface Test (#598) passes, refer to Packet Control Circuit Pack and Packet Bus repair procedures.</li> </ol>
3	FAIL	Received no response to RSCL control link test frame. <ol style="list-style-type: none"> <li>1. Retry command at 1-minute intervals, up to 5 times.</li> <li>2. If the problem persists, reset the circuit pack (<b>reset board UUCSS</b>).</li> <li>3. If test continues to fail, replace the circuit pack.</li> </ol>
	PASS	RSCL control link connected.

## CLSFY-BD (Call Classifier Circuit Pack)

---

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run <sup>1</sup>	Full Name of MO
CLSFY-BD	MIN	test board PCSS sh	Call Classifier Circuit Pack
CLSFY-BD	WRN	test board PCSS sh	Call Classifier Circuit Pack

- 
1. Where P is the port network number (1 for PPN); C is the carrier designation (for example, A, B, or C); and SS is the address of the slot in the carrier where the circuit pack is located (for example, 01, 02, ..., etc.).
- 

Refer to [“XXX-BD \(Common Port Circuit Pack\)” on page 5-1343](#) for circuit pack level errors. See also Call Classifier Port (CLSFY-PT) Maintenance documentation for related port information.

## CLSFY-PT (Call Classifier Port)

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run <sup>1</sup>	Full Name of MO
CLSFY-PT(a)	MAJOR	test port PCSSpp sh	Call Classifier Port Maintenance
CLSFY-PT	MINOR	test port PCSSpp sh	Call Classifier Port Maintenance
CLSFY-PT	WARNING	release port PCSSpp	Call Classifier Port Maintenance

1. Where P is the port network number (1 for PPN); C is the carrier designation; SS is the address of the slot in the carrier where the circuit pack is located (01, 02, ..., and so forth); and pp is the 2-digit port number (01, 02, ..., and so forth).

The TN744D Call Classifier (CLSFY-BD) circuit pack is a service circuit pack that enables usage of the Outbound Call Management (OCM) and the Inbound Call Management (ICM) features. The TN744D also enables usage of R2-MFC signaling for incoming and outgoing feature operation. There are eight ports (CLSFY-PTs) on the Call Classifier circuit pack. Each port can handle call classification, touch-tone reception, or MFC tone generation and detection or touch-tone reception.

The CLSFY-PT maintenance feature defines a set of tests to ensure that the Call Classifier circuit pack ports are capable of detecting tones for call classification and detecting and generating necessary tones for correct MFC feature operation.

### NOTE:

A TN744D Call Classifier/Tone Detector circuit pack may be required in systems with heavy traffic. This circuit pack can be installed into any slot, although slot 3 of Cabinet A is preferred.

## Hardware Error Log Entries and Test to Clear Values

---

Table 5-159. Call Classifier Port (CLSFY-PT) Error Log Entries

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
1	any	Tone Detector Audit/Update Test (#43)	MAJOR/ MINOR (a)	ON	test port PCSSpp r 2
18		Port has been busied out by system technician	WARNING	OFF	release port PCSSpp
257 (b)	17666	Test (#43)	MAJOR/ MINOR (a)	ON	test port PCSSpp r 3
513 (c)	any	Tone Detection Verification Test (#42)	MAJOR/ MINOR (a)	ON	test port PCSSpp r 3

---

### Notes:

- a. There are two possible alarm levels for this error type: major alarm and minor alarm. A major alarm is raised if the total number of call classifier ports currently in-service is less than or equal to 1/2 of the administered threshold number. Otherwise, a minor alarm is raised. In either case, run the short test sequence against the port and follow the error code procedures for the individual tests.

The threshold number of call classifier ports for service is administered using the **change system-parameters maintenance** command.

- b. The call classifier port lost its translation. Testing the call classifier port is sufficient to reload its translation. If testing the call classifier port does not clear the error, then the call classifier circuit pack containing the defective call classifier port should be replaced.
  - c. This error indicates the call classifier port is having problems detecting system tones (DTMF, etc.) or detecting and generating necessary R2-MFC tones. This error should accompany some percentage of failed calls. If this error type is persistently logged, then the call classifier circuit pack containing the defective call classifier port should be replaced.
-

## System Technician-Demanded Tests: Descriptions and Error Codes

Always investigate tests in the order presented in the following tables when inspecting errors in the system. By clearing error codes associated with the *Tone Detection Verification Test*, for example, you may also clear errors generated from other tests in the testing sequence.

Table 5-160. System Technician-Demanded Tests: CLSFY-PT

Order of Investigation	Short Test Sequence	Long Test Sequence	D/ND <sup>1</sup>
Tone Detection Verification Test (#42)	X	X	ND
Tone Detection Audit/Update Test (#43)	X	X	ND

1. D = Destructive, ND = Non-destructive

### Tone Detection Verification Test (#42)

This test checks out each port in both the touch-tone receiver mode and in the R2-MFC tone detection/generation mode. During the first half of the test, the touch-tone receiver mode is tested. In the second half of the test, each port is put into the R2-MFC mode. During this portion of the test, each port's ability to accurately detect and generate all forward and backward MFC tones is verified.

Table 5-161. TEST #42 Tone Detection Verification Test

Error Code	Test Result	Description/ Recommendation
none	ABORT	The system was not able to allocate all the resources needed for this test OR there was an internal system error
1	ABORT	The system could not allocate all the resources needed to test the tones.
1001	ABORT	The system was unable to put the Call Classifier port in the appropriate mode to test it.

*Continued on next page*

Table 5-161. TEST #42 Tone Detection Verification Test — Continued

Error Code	Test Result	Description/ Recommendation
1002	ABORT	<p>The system could not allocate time slots for the test connection. This situation could occur when the system is heavily loaded. If the system is not heavily loaded, then test the TDM-BUS via the <b>test tdm [1 2]</b> command. Refer to the <a href="#">“TDM-BUS (TDM Bus)”</a> on page 5-1116 for details.</p> <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
1003	ABORT	<p>The system could not allocate a Tone-Clock circuit pack for the test connection. This situation could occur when the system is heavily loaded or if a Tone-Clock circuit pack is not present in the port network when this test is executed.</p> <ol style="list-style-type: none"><li>1. Verify the existence of a Tone-Clock circuit pack in the same port network.</li><li>2. If a Tone-Clock circuit pack is missing, install one in the same port network.</li><li>3. Allow approximately 1 minute for the Tone-Clock circuit pack maintenance to run on the newly inserted Tone-Clock circuit pack.</li><li>4. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
2006	ABORT	<p>This abort code indicates that the active Tone-Clock circuit pack might not be functioning properly. If there is more than one Tone Detector circuit pack in the system, then the problem can be either with the Tone-Clock circuit pack or the Tone Detector circuit pack. This could also be caused by the mode administered for the system not matching that of the Tone Detector circuit pack.</p> <ol style="list-style-type: none"><li>1. Make sure that the commanding mode of the system matches that of the Tone Detector (TN748 for mu-law systems and TN420 for A-law systems).</li><li>2. Test the active Tone-Clock circuit pack in the port network. This test is being executed via the <b>test tone-clock qualifier</b> system technician command. (“qualifier” is the carrier of the active Tone-Clock circuit pack to be tested. Valid qualifiers are: a, b, 1a, 1b, 2a, and 2b.) Refer to <a href="#">“TONE-PT (Tone Generator)”</a> on page 5-1204 for details.</li><li>3. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>

Continued on next page

Table 5-161. TEST #42 Tone Detection Verification Test — *Continued*

Error Code	Test Result	Description/ Recommendation
2000	ABORT	Response to the test request was not received within the allowable time period.
2100	ABORT	Could not allocate the necessary system resources to run this test. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
1-3	FAIL	DTMF digits were not detected correctly. This may or may not impact reception of R2-MFC calls. <ol style="list-style-type: none"><li>1. Run the short test sequence via the <b>test port PCSSpp sh r 1</b> command.</li><li>2. If the problem persists, the system is still operating properly but system capacity will be reduced. In order to restore system performance to normal, replace the Call Classifier circuit pack containing the defective CLSFY-PT (Call Classifier Port).</li></ol>
101-122	FAIL	Forward or Backward MFC signals were not correctly generated or detected. This impacts reception of incoming MFC calls. <ol style="list-style-type: none"><li>1. Run the short test sequence via the <b>test port PCSSpp sh r 1</b> command.</li><li>2. If the problem persists, the system is still operating properly but system capacity will be reduced. In order to restore system performance to normal, replace the Call Classifier circuit pack containing the defective CLSFY-PT (Call Classifier Port).</li></ol>
	PASS	Tone Detection Verification is successful. The Call Classifier Port (CLSFY-PT) is able to detect/generate all necessary tones.

## Tone Detector Audit/Update Test (#43)

A sanity audit is performed on the CLSFY-PT (Call Classifier Port).

Table 5-162. Tone Detector Audit/Update Test (#43)

Error Code	Test Result	Description/ Recommendation
none	ABORT	The system was not able to allocate all the resources needed for this test. <ol style="list-style-type: none"><li>1. Wait 1 minute, and repeat the command a maximum of 5 times.</li></ol>
2000	ABORT	Response to the test request was not received within the allowable time period.
2100	ABORT	Could not allocate the necessary system resources to run this test. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
	FAIL	Hardware audit failed. <ol style="list-style-type: none"><li>1. Run the short test sequence via the <b>test port PCSSpp sh r 1</b> command.</li><li>2. If the problem persists, the system is still operating properly but system capacity will be reduced. In order to restore system performance to normal, replace the CLSFY-BD (Call Classifier circuit pack) containing the defective CLSFY-PT (Call Classifier Port).</li></ol>
	PASS	The (CLSFY-PT) Call Classifier Port has passed the sanity inquiry.

**5** Maintenance Objects for DEFINITY ONE  
CO-BD (Central Office Trunk Circuit Pack)

5-401

**CO-BD (Central Office Trunk Circuit Pack)**

---

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run <sup>1</sup>	Full Name of MO
CO-BD	MIN	test board PCSS sh	Central Office Trunk Circuit Pack
CO-BD	WRN	test board PCSS sh	Central Office Trunk Circuit Pack

- 
1. Where P is the port network number (1 for PPN); C is the carrier designation (for example, A, B, C, D, or E); and SS is the address of the slot in the carrier where the circuit pack is located (for example, 01, 02, ..., etc.).
- 

Refer to [“XXX-BD \(Common Port Circuit Pack\)” on page 5-1343](#) for circuit pack level errors. See also CO-TRK (CO Trunk) Maintenance documentation for related trunk information.

## CO-DS1 (DS1 CO Trunk)

---

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run	Full Name of MO
CO-DS1	MAJOR <sup>1</sup>	test trunk <grp/mbr> l	DS1CO Trunk
CO-DS1	MINOR	test trunk <grp/mbr> l	DS1CO Trunk
CO-DS1	WARNING	test trunk <grp/mbr>	DS1CO Trunk

- 
1. A Major alarm on a trunk indicates that alarms on these trunks are not downgraded by the **set options** command and that at least 75 percent of the trunks in this trunk group are alarmed.
- 

A DS1CO (central office) trunk provides a communications channel between the system and a central office switch through either a 1.544 Mbps or a 2.048 Mbps [G3iV2-386] DS1 link. A 24 channel DS1 link consists of 24 digital DS1CO trunks. A 32 channel DS1 link [G3iV2-386] consists of 30 digital DS1CO trunks. A DS1CO trunk can be used for both voice and data communication.

The DS1CO Trunk Maintenance provides a strategy in the system to maintain a CO trunk via a port on the DS1 Interface circuit pack. The TN767B or later and TN464C or later DS1 Interface circuit packs support the low level CO trunk signaling interfaces, ground-start and loop-start. This strategy covers the in-line errors log, initialization tests, periodic tests, system technician-demanded tests, and alarm resolution and escalation.

Three trunk service states are specified in the DS1CO trunk maintenance:

1. *out-of-service*: The trunk is in a deactivated state and cannot be used for either incoming or outgoing calls.
2. *in-service*: The trunk is in an activated state and can be used for both incoming and outgoing calls.
3. *disconnect* (ready-for-service): The trunk is in an activated state but can only be used for an incoming call.

If the DS1 Interface circuit pack is out-of-service, then all trunks on the DS1 Interface circuit pack are also in the out-of-service state, and a Warning alarm is raised for each trunk.

## Hardware Error Log Entries and Test to Clear Values

Table 5-163. DS1 CO Trunk Error Log Entries

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
0 <sup>1</sup>	0	Any	Any	Any	test trunk <grp>/<mbr>
1 (a)	57408				
1 (a)	57487				
15 (b)	Any	Port Audit and Update Test (#36)			
18 (c)	0	busyout trunk <grp>/<mbr>	WARNING	OFF	release trunk <grp>/<mbr>
130 (d)		None	WARNING	ON	test trunk <grp>/<mbr>
257 (e)	57392	DS1 CO Dial Tone Seizure Test (#314)	MIN/MAJ <sup>2</sup>	OFF	
513 (f)	57393	DS1 CO Dial Tone Seizure Test (#314)	MIN/MAJ <sup>2</sup>	OFF	
769 (g)	57484				
1025		DS1CO Dial Tone Seizure Test (#314)	WARNING	OFF	test trunk <grp>/<mbr>
1281		Conference Circuit Test (#7)	MAJ/MIN/WRN <sup>3</sup>	ON	test trunk <grp>/<mbr> r 4
1537		NPE Crosstalk Test (#6)	MAJ/MIN/WRN <sup>3</sup>	ON	test trunk <grp>/<mbr> r 3
1793 (h)				ON	test board PCSS I
2562(i)	16665				
2817(j)	52992				
3840 (k)		Port Audit and Update Test (#36)			

1. Run the Short Test Sequence first. If all tests pass, run the Long Test Sequence. Refer to the appropriate test description and follow the recommended procedures.
2. This alarm will only be raised when the System-Parameter Country form has the Base Tone Generator field set to 4 (Italy). This alarm will be a MINOR alarm unless 75% or more trunks in this trunk group are out of service, then the alarm will be upgraded to a MAJOR alarm.
3. Minor alarms on this maintenance object (MO) may be downgraded to Warning alarms based on the values used in the **set options** command. If the Minor alarm is not downgraded by the **set options** values, the Minor alarm is upgraded to a Major alarm if 75 percent of the trunks in this group are alarmed.

## Notes:

- a. Error Type 1—Aux Data 57408—No tip ground is detected on an outgoing call.

Aux Data 57487—PBX could not get “loop close” signal (TN767).

The DS1 Interface circuit pack detected a hardware fault. These errors cause the Dial Tone Test (#314) to run and are only considered a problem if the Dial Tone Test fails (in which case Error Type 1025 also shows up). In this case, the trunk may be put in ready-for-service state (shown as “disconnected” by status command), which allows only incoming calls. Run the Dial Tone Test (#314) and follow its outlined procedures.

- b. Error Type 15—This is a software audit error that does not indicate any hardware malfunction. Run Short Test Sequence and investigate associated errors (if any).
- c. Error Type 18—System Technician has busied-out the trunk to the out-of-service state. No calls can be made on this trunk except the Facility Access Test Call.
- d. Error Type 130—This error type indicates that the circuit pack has been removed or has been insane for more than 11 minutes. To clear the error, reinsert or replace the circuit pack.
- e. Error Type 257—The DS1 Interface circuit pack detects a hardware fault. The Aux Data field contains the following error type: 57392—no external release on PBX disconnect [E030]. Escalate the problem.
- f. Error Type 513—The DS1 Interface circuit pack detects a hardware fault. The Aux Data field contains the following error type: 57393—belated external release on PBX disconnect [E031]. Escalate the problem.
- g. Error Type 769—The DS1 Interface circuit pack detects a hardware fault. The Aux Data field contains the following error type:—57484, fault is detected on tip/ring [E08C]. Escalate the error.
- h. Error Type 1793—DS1 Interface circuit pack is out-of-service. Look for DS1-BD errors in the Hardware Error Log. Refer to the [“DS1-BD \(DS1 Interface Circuit Pack\)” on page 5-548](#) for details.
- i. Error Type 2562—Retry Failure error. This error is logged only. It is not a hardware failure and hence does not start any testing or generate any alarms. This error comes from call processing and is generated when a second attempt (retry) to seize an outgoing trunk fails.
- j. Error Type 2817—Glare error. This error is logged only. It is not a hardware failure and hence does not start any testing or generate any alarms. This error is the result of a simultaneous seizure of a two-way trunk from both the near-end and the far-end. Attempt to place the call again. If the error persists, execute the Dial Tone Seizure Test (#314) and follow those procedures.

**5 Maintenance Objects for DEFINITY ONE**  
*CO-DS1 (DS1 CO Trunk)*

5-405

- k. Error Type 3840—Port Audit and Update Test (#36) failed due to an internal system error. Enter the **status trunk** command to verify the status of the trunk. If the trunk is out-of-service, then enter the **release trunk** command to put it back into in-service. Retry the test command. If the test continues to abort, then escalate the problem.

---

**System Technician-Demanded Tests: Descriptions and Error Codes**

---

Always investigate tests in the order they are presented in the table below when inspecting errors in the system. By clearing error codes associated with the *NPE Crosstalk Test*, for example, you may also clear errors generated from other tests in the testing sequence.

Order of Investigation	Short Test Sequence	Long Test Sequence	D/ND <sup>1</sup>
NPE Crosstalk Test (#6)		X	ND
Conference Circuit Test (#7)		X	ND
DS1CO Trunk Seizure Test (#314)	X	X	ND
Port Audit and Update Test (#36)	X	X	ND

---

1. D = Destructive; ND = Nondestructive

---

**NPE Crosstalk Test (#6)**

One or more Network Processing Elements (NPEs) resides on each circuit pack with a TDM Bus interface. The NPE controls port connectivity and gain, and provides conferencing functions on a per-port basis. The NPE Crosstalk Test verifies that this port's NPE channel talks on the selected time slot and never crosses over to time slots reserved for other connections. If the NPE is not working correctly, one-way and noisy connections may be observed. This test is usually only part of a port's Long Test Sequence and takes about 20 to 30 seconds to complete.

Table 5-164. TEST #6 NPE Crosstalk Test

Error Code	Test Result	Description/ Recommendation
	ABORT	System resources required for this test are not available. 1. Retry the command at one-minute intervals a maximum of five times.
1000	ABORT	System resources required to run this test were not available. The port may be busy with a valid call. Use the <b>display port PCSSpp</b> command to determine the trunk group/member number of the port. Use the <b>status trunk</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. (Refer to <a href="#">"status station" on page 4-213</a> for a description of all possible states.) You must wait until the port is idle before retesting. 1. If the port status is active but the port is not in use (no calls), check the error log for error type 1025 (see the error log table for a description of this error and required actions). The port may be locked up. 2. If the port status is idle, retry the command at 1-minute intervals for a maximum of 5 times.
1001	ABORT	System resources required for this test are not available. 1. Retry the command at one-minute intervals a maximum of 5 times.
1002	ABORT	The system could not allocate time slots for the test. The system may be under heavy traffic conditions or it may have time slots out-of-service due to TDM-BUS errors. Refer to the <a href="#">"TDM-BUS (TDM Bus)" on page 5-1116</a> to diagnose any active TDM-BUS errors. 1. If system has no TDM-BUS errors and is not handling heavy traffic, repeat test at one-minute intervals a maximum of 5 times.
1003	ABORT	The system could not allocate a tone receiver for the test. The system may be oversized for the number of Tone Detectors present or some tone detectors may be out-of-service. 1. Look for TTR-LEV errors in the Error Log. If present, refer to <a href="#">"TTR-LEV (TTR Level)" on page 5-1223</a> . 2. Look for TONE-PT errors in the Error Log. If present, refer to <a href="#">"TONE-PT (Tone Generator)" on page 5-1204</a> . 3. If neither condition exists, retry the test at 1-minute intervals a maximum of 5 times.
1004	ABORT	The port was seized by a user for a valid call. Use the <b>display port PCSSpp</b> command to determine the trunk group/member number of the port. Use the <b>status trunk</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. You must wait until the port is idle before retesting. 1. If the port status is idle, retry the command at 1-minute intervals for a maximum of 5 times.

Table 5-164. TEST #6 NPE Crosstalk Test — *Continued*

Error Code	Test Result	Description/ Recommendation
1020	ABORT	<p>The test did not run due to a previously existing error on the specific port or a more general circuit pack error.</p> <ol style="list-style-type: none"> <li data-bbox="303 390 1091 449">1. Examine Error Log for existing errors against this port or the circuit pack and attempt to diagnose the already existing error.</li> </ol>
2000	ABORT	<p>Response to the test request was not received within the allowable time period.</p>
2100	ABORT	<p>System resources required for this test are not available.</p> <ol style="list-style-type: none"> <li data-bbox="303 578 1091 618">1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
2053	ABORT	<p>At least one of the following errors was found on the DS1 circuit pack: loss of signal (1281), blue alarm (1793), red alarm (2049), yellow alarm (2305), or hyperactivity (1537).</p> <ol style="list-style-type: none"> <li data-bbox="303 727 1091 820">1. Look for the above error types in the Hardware Error Log and follow the procedures given in the appropriate DS1-BD or UDS1-BD maintenance documentation for the listed error types.</li> </ol>
	FAIL	<p>The NPE of the tested port was found to be transmitting in error. This causes noisy and unreliable connections.</p> <ol style="list-style-type: none"> <li data-bbox="303 903 1091 939">1. Replace the circuit pack.</li> </ol>
	PASS	<p>The port is correctly using its allocated time slots. User-reported troubles on this port should be investigated using other port tests and examining station, trunk, or external wiring.</p>

*Continued on next page*

Table 5-164. TEST #6 NPE Crosstalk Test — *Continued*

Error Code	Test Result	Description/ Recommendation
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board). This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, an insane board is inserted, or the board is hyperactive (see note below).</p> <ol style="list-style-type: none"><li>1. Check to ensure that the board translations are correct. Use the <b>list config</b> command, and resolve any problems that are found.</li><li>2. If the board was found to be correctly inserted in step 1, issue the <b>busyout board</b> command.</li><li>3. Issue the <b>reset board</b> command.</li><li>4. Issue the <b>release busy board</b> command.</li><li>5. Issue the <b>test board long</b> command. This should re-establish the linkage between the internal ID and the port. If this is not the case, dispatch to check to ensure that there is a valid board inserted.</li></ol> <p> <b>NOTE:</b></p> <p>Hyperactivity causes some special problems with the sequence suggested above. If the ports are translated after issuing the <b>list config</b> command but the <code>Vintage</code> field reports that there is no board (when there really is a board), then the <b>busyout board</b> and the <b>release busy board</b> commands will not work (even though the <b>reset board</b> command will work). The software puts the hyperactive board back in service after the hyperactivity clears.</p>

## Conference Circuit Test (#7)

One or more Network Processing Elements (NPEs) reside on each circuit pack with a TDM Bus interface. The NPE controls port connectivity and gain, and provides conferencing functions on a per-port basis. The Conference Circuit Test verifies that the NPE channel for the port being tested can correctly perform the conferencing function. The NPE is instructed to listen to several different tones and conference the tones together. The resulting signal is then measured by a tone detector port. If the level of the tone is within a certain range, the test passes.

Table 5-165. TEST #7 Conference Circuit Test

Error Code	Test Result	Description/ Recommendation
	ABORT	System resources required for this test are not available. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
1000	ABORT	The test was aborted. System resources required to run this test were not available. The port may be busy with a valid call. Use the <b>display port PCSSpp</b> command to determine the trunk group/member number of the port. Use the <b>status trunk</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. You must wait until the port is idle before retesting. <ol style="list-style-type: none"><li>1. If the port status is active but the port is not in use (no calls), check the error log for error type 1025 (see the error log table for a description of this error and required actions). The port may be locked up.</li><li>2. If the port status is idle, retry the command at 1-minute intervals for a maximum of 5 times.</li></ol>
1002	ABORT	The test was aborted. The system could not allocate time slots for the test. The system may be under heavy traffic conditions, or it may have time slots out of service due to TDM-BUS errors. Refer to the <a href="#">"TDM-BUS (TDM Bus)" on page 5-1116</a> to diagnose any active TDM-BUS errors. <ol style="list-style-type: none"><li>1. If the system has no TDM-BUS errors and is not handling heavy traffic and the port status is idle, retry the command at 1-minute intervals for a maximum of 5 times.</li></ol>

*Continued on next page*

Table 5-165. TEST #7 Conference Circuit Test — *Continued*

Error Code	Test Result	Description/ Recommendation
1003	ABORT	<p>The system could not allocate a tone receiver for the test. The system may be oversized for the number of tone detectors present or some of the tone detectors may be out of service. Issue the <b>list measurements tone-receiver</b> command to display basic information about the system's tone receivers.</p> <ol style="list-style-type: none"> <li>1. Look for TTR-LEV errors in the error log. If present, refer to <a href="#">"TTR-LEV (TTR Level)" on page 5-1223</a>.</li> <li>2. Look for TONE-PT errors in the error log. If present, refer to <a href="#">"TONE-PT (Tone Generator)" on page 5-1204</a>.</li> <li>3. If neither condition exists, retry the test at 1-minute intervals for a maximum of 5 times.</li> </ol>
1004	ABORT	<p>The port has been seized by a user for a valid call. Use the <b>status station</b> or <b>status trunk</b> command to determine when the port is available for testing.</p> <ol style="list-style-type: none"> <li>1. Retry the command at one-minute intervals a maximum of five times.</li> <li>2. If the test continues to abort, and the port is not in use, escalate the problem.</li> </ol>
1018	ABORT	<p>The test was disabled via translation. You may want to determine why the test has been disabled before you enable it.</p> <ol style="list-style-type: none"> <li>1. Verify that the <code>Maintenance Test</code> field on the Trunk Administration screen is set to <b>n</b>. To enable the test, change the trunk administration and enter <b>y</b> into the <code>Maintenance Test</code> field.</li> <li>2. Repeat the test.</li> </ol>
1020	ABORT	<p>The test did not run due to a previously existing error on the specific port or a more general circuit pack error.</p> <ol style="list-style-type: none"> <li>1. Examine Error Log for existing errors against this port or the circuit pack and attempt to diagnose the previously existing error.</li> </ol>
2000	ABORT	Response to the test request was not received within the allowable time period.
2100	ABORT	<p>System resources required for this test are not available.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
2053	ABORT	<p>At least one of the following errors was found on the DS1 circuit pack: loss of signal (1281), blue alarm (1793), red alarm (2049), yellow alarm (2305), or hyperactivity (1537).</p> <ol style="list-style-type: none"> <li>1. Look for the above error types in the Hardware Error Log and follow the procedures given in the appropriate DS1-BD or UDS1-BD maintenance documentation for the listed error types.</li> </ol>

*Continued on next page*

Table 5-165. TEST #7 Conference Circuit Test — *Continued*

Error Code	Test Result	Description/ Recommendation
	FAIL	<ol style="list-style-type: none"><li>1. Enter the <b>list configuration board PCSS</b> command. If the circuit pack is a TN767B vintage 8 or 9, replace the circuit pack with a TN767C V3 or later. The error log may have error type 1281 entries.</li><li>2. Test all administered trunks on the board. If one fails, this could be an off-board problem (such as an incoming seizure or an off-hook port seizure during the test). Retest the board.</li><li>3. If several ports fail, check the error log for TONE-BD or TONE-PT errors. If there are such errors, take the appropriate action. When the TONE errors have cleared, rerun the test.</li><li>4. If the retry passes and troubles have been reported, coordinate isolation with the CO. Make sure that the switch, the CO, and any NTCE equipment (the CSU's) have the correct administration.</li><li>5. Replace the circuit pack.</li></ol> <p><b>⇒ NOTE:</b> If the conference circuit test fails for all ports on a circuit pack, a -5 volt power problem is indicated.</p>
	PASS	The port can correctly conference multiple connections. User-reported troubles on this port should be investigated by using other port tests and by examining station, trunk, or external wiring.

*Continued on next page*

Table 5-165. TEST #7 Conference Circuit Test — *Continued*

Error Code	Test Result	Description/ Recommendation
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board).</p> <p>This result could be due to incorrect translations, no board is inserted, an incorrect board is inserted, an insane board is inserted, or the board is hyperactive (see note below).</p> <ol style="list-style-type: none"><li>1. Check to ensure that the board translations are correct. Use the <b>list config</b> command, and resolve any problems that are found.</li><li>2. If the board was found to be correctly inserted in step 1, issue the <b>busyout board</b> command.</li><li>3. Issue the <b>reset board</b> command.</li><li>4. Issue the <b>release busy board</b> command.</li><li>5. Issue the <b>test board long</b> command.</li></ol> <p>This should re-establish the linkage between the internal ID and the port. If this is not the case, dispatch to check to ensure that there is a valid board inserted.</p> <p> <b>NOTE:</b> Hyperactivity causes some special problems with the sequence suggested above. If the ports are translated after issuing the <b>list config</b> command but the <code>Vintage</code> field reports that there is no board (when there really is a board), then the <b>busyout board</b> and the <b>release busy board</b> commands will not work (even though the <b>reset board</b> command will work). The software puts the hyperactive board back in service after the hyperactivity clears.</p>

## Port Audit and Update Test (#36)

This test sends port level translation data from switch processor to the DS1 Interface circuit pack to assure that the trunk's translation is correct. Translation updates include the following data: trunk type (in/out), dial type, timing parameters, and signaling bits enabled. The port audit operation verifies the consistency of the current state of trunk kept in the DS1 Interface circuit pack and in the switch software.

Table 5-166. TEST 36 Port Audit and Update Test

Error Code	Test Result	Description/ Recommendation
1000	ABORT	Internal system error <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
	ABORT	The test was aborted because system resources required to run this test were not available. The port may be busy with a valid call. Issue the <b>display port PCSSpp</b> command to determine the trunk group/member number of the port. Use the <b>status trunk</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. You must wait until the port is idle before retesting. <ol style="list-style-type: none"><li>1. If the port status is active but the port is not in use (no calls), check the error log for error type 1025 (see the error log table for a description of this error and required actions). The port may be locked up.</li><li>2. If the port status is idle, retry the command at 1-minute intervals for a maximum of 5 times.</li></ol>
2000	ABORT	Response to the test request was not received within the allowable time period.
2100	ABORT	Could not allocate the necessary system resources to run this test.

*Continued on next page*

Table 5-166. TEST 36 Port Audit and Update Test — *Continued*

Error Code	Test Result	Description/ Recommendation
	FAIL	<p>Test failed due to internal system error.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
	PASS	<p>Trunk translation has been updated successfully. The current trunk states kept in the DS1 Interface circuit pack and switch software are consistent. If the trunk is busied out, the test does not run, but returns to PASS. To verify that the trunk is in-service:</p> <ol style="list-style-type: none"> <li>1. Enter <b>status trunk</b> command to verify that the trunk is in-service. If the trunk is in-service, no further action is necessary. If the trunk is out-of-service, continue to Step 2.</li> <li>2. Enter <b>release-trunk</b> command to put trunk back into in-service.</li> <li>3. Retry the test command.</li> </ol>
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board). This result could be due to incorrect translations, no board is inserted, an incorrect board is inserted, an insane board is inserted, or the board is hyperactive (see note below).</p> <ol style="list-style-type: none"> <li>1. Check to ensure that the board translations are correct. Use the <b>list config</b> command, and resolve any problems that are found.</li> <li>2. If the board was found to be correctly inserted in step 1, issue the <b>busyout board</b> command.</li> <li>3. Issue the <b>reset board</b> command.</li> <li>4. Issue the <b>release busy board</b> command.</li> <li>5. Issue the <b>test board long</b> command.</li> </ol> <p>This should re-establish the linkage between the internal ID and the port. If this is not the case, dispatch to check to ensure that there is a valid board inserted.</p> <p>Hyperactivity causes some special problems with the sequence suggested above. If the ports are translated after issuing the <b>list config</b> command but the <code>Vintage</code> field reports that there is no board (when there really is a board), then the <b>busyout board</b> and the <b>release busy board</b> commands will not work (even though the <b>reset board</b> command will work). The software puts the hyperactive board back in service after the hyperactivity clears.</p>

**DS1 CO Dial Tone Seizure Test (#314)**

DS1CO Dial Tone Seizure Test checks the trunk's signaling capability provided by the DS1 Interface circuit pack. The maintenance software initiates the test by sending a "seizure" message to the DS1 Interface circuit pack and expects an "active" reply from the DS1 interface circuit pack. If the "active" message is received, then the test passes. If no message is received and the timer expires, the test is aborted. If the DS1 Interface circuit pack sends a "reorder" message back to maintenance software, then the test fails.

The test **CANNOT** be run on a trunk if one of the following cases is true:

- a. The trunk direction is administered as an incoming only trunk.
- b. The trunk has been seized by a normal trunk call.
- c. The trunk is administered with maintenance test disabled.

**Table 5-167. TEST #314 DS1CO Dial Tone Seizure Test**

Error Code	Test Result	Description/ Recommendation
	ABORT	Internal system error <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
1000	ABORT	The test was aborted because system resources required to run this test were not available. The port may be busy with a valid call. Use the <b>display port PCSSpp</b> command to determine the trunk group/member number of the port. Use the <b>status trunk</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. You must wait until the port is idle before retesting. <ol style="list-style-type: none"><li>1. If the port status is active but the port is not in use (no calls), check the error log for error type 1025 (see the error log table for a description of this error and required actions). The port may be locked up.</li><li>2. If the port status is idle, retry the command at 1-minute intervals for a maximum of 5 times.</li></ol>
1004	ABORT	The test was aborted because the port was seized by a user for a valid call. Use the <b>display port PCSSpp</b> command to determine the trunk group/member number of the port. Use the <b>status trunk</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. You must wait until the port is idle before retesting. <ol style="list-style-type: none"><li>1. If the port status is idle, retry the command at 1-minute intervals for a maximum of 5 times.</li></ol>

*Continued on next page*

Table 5-167. TEST #314 DS1CO Dial Tone Seizure Test — *Continued*

Error Code	Test Result	Description/ Recommendation
1005	ABORT	<p>Test failed due to incompatible configuration administered in trunk group form.</p> <ol style="list-style-type: none"><li>1. Verify the following fields on the trunk group administration screen: Is trunk direction incoming only? Is trunk the port 24 of the DS1 Interface circuit pack while common control channel signaling is specified? Is trunk group type the automatic CO (for example, FX)?</li><li>2. If the trunk has been administered using the above information, then this test should abort.</li></ol>
1018	ABORT	<p>The test is disabled via translation. You may want to determine why the test has been disabled before you enable it.</p> <ol style="list-style-type: none"><li>1. Verify that the <code>Maintenance Test</code> field on the Trunk Group form is set to <b>n</b>. To enable the test, issue the <b>change trunk-group x</b> command (x equals the number of the trunk group to be tested). Then, change the entry in the <code>Maintenance Test</code> field on the form to <b>y</b>.</li><li>2. Repeat the test.</li></ol>
1020	ABORT	<p>The DS1 Interface circuit pack is out-of-service.</p> <ol style="list-style-type: none"><li>1. Look for DS1-BD errors in the Hardware Error Log. If present, refer to <a href="#">“DS1-BD (DS1 Interface Circuit Pack)” on page 5-548</a>.</li><li>2. Retry the command.</li></ol>
1040	ABORT	<p>The test was aborted because this port may be an access endpoint.</p> <ol style="list-style-type: none"><li>1. Verify that this port is an access endpoint by issuing the <b>display port</b> command.</li><li>2. If the port has been administered as an access endpoint, then this is a normal abort.</li></ol>
2000	ABORT	<p>Response to the test request was not received within the allowable time period.</p>
2012	ABORT	<p>The test was aborted due to an internal system error.</p> <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals for a maximum of 5 times.</li></ol>
2100	ABORT	<p>Could not allocate the necessary system resources to run this test.</p> <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals for a maximum of 5 times.</li></ol>

*Continued on next page*

Table 5-167. TEST #314 DS1CO Dial Tone Seizure Test — *Continued*

Error Code	Test Result	Description/ Recommendation
	FAIL	<p>The trunk cannot be seized for an outgoing call. This could cause in-line failures to be reported against the trunk (no answer would report error type 257 with auxiliary data 57487 in the error log).</p> <ol style="list-style-type: none"> <li>1. Verify that the Trunk Type field on the trunk administration screen form matches the trunk type administered on far end switch.</li> <li>2. Look for DS1-BD/UDS1-BD errors in Hardware Error Log. If present, refer to <a href="#">“DS1-BD (DS1 Interface Circuit Pack)” on page 5-548</a> or <a href="#">“UDS1-BD (UDS1 Interface Circuit Pack)” on page 5-1227</a>.</li> <li>3. Retry the test at 1-minute intervals for a maximum of 5 times.</li> </ol>
2000	FAIL	<p>Response to the seizure message was not received within the allowable time period.</p> <ol style="list-style-type: none"> <li>1. Enter the <b>list configuration board PCSS</b> command. If the circuit pack is a TN767B vintage 8 or 9, a failure of test 314 causes a subsequent failure of test 7 due to a firmware bug. Eventually, the board and all of its ports will be taken out of service and extraneous on-board alarms will be generated. Replace the circuit pack with a TN767C V3 or later.</li> <li>2. Verify that the 'Trunk Type' field on the 'Trunk Administration' screen matches the trunk type administered on far-end switch.</li> <li>3. Look for DS1-BD or UDS1-BD errors in the hardware error log. If present, refer to <a href="#">“DS1-BD (DS1 Interface Circuit Pack)” on page 5-548</a> or to <a href="#">“UDS1-BD (UDS1 Interface Circuit Pack)” on page 5-1227</a>.</li> <li>4. Retry the test at 1-minute intervals for a maximum of 5 times.</li> </ol>
2053	FAIL	<p>At least one of the following errors was found on the DS1 circuit pack: loss of signal (1281), blue alarm (1793), red alarm (2049), yellow alarm (2305), or hyperactivity (1537).</p> <ol style="list-style-type: none"> <li>1. Look for these error types in the Hardware Error Log and then follow the procedures given in the maintenance documentation that is appropriate for the error type that was found.</li> </ol>
	PASS	The trunk can be seized for an outgoing call.

*Continued on next page*

Table 5-167. TEST #314 DS1CO Dial Tone Seizure Test — *Continued*

Error Code	Test Result	Description/ Recommendation
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board). This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, an insane board is inserted, or the board is hyperactive (see Note below).</p> <ol style="list-style-type: none"><li>1. Check to ensure that the board translations are correct. Use the <b>list config</b> command, and resolve any problems that are found.</li><li>2. If the board was found to be correctly inserted in step 1, issue the <b>busyout board</b> command.</li><li>3. Issue the <b>reset board</b> command.</li><li>4. Issue the <b>release busy board</b> command.</li><li>5. Issue the <b>test board long</b> command. This should re-establish the linkage between the internal ID and the port. If this is not the case, dispatch to check to ensure that there is a valid board inserted.</li></ol> <p> <b>NOTE:</b></p> <p>Hyperactivity causes some special problems with the sequence suggested above. If the ports are translated after issuing the <b>list config</b> command but the 'Vintage' field reports that there is no board (when there really is a board), then the <b>busyout board</b> and the <b>release busy board</b> commands will not work (even though the <b>reset board</b> command will work). The software will put the hyperactive board back in service after the hyperactivity clears.</p>

## CO-TRK (CO Trunk)

---

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run <sup>1</sup>	Full Name of MO
CO-TRK	MAJOR <sup>2</sup>	test port PCSSpp l	CO Trunk
CO-TRK	MINOR	test port PCSSpp l	CO Trunk
CO-TRK	WARNING	test port PCSSpp l	CO Trunk

1. Where P is the port network number (1 for PPN); c is the carrier designation (for example, A, B, C, D, or E); and SS is the address of the slot in the carrier where the circuit pack is located (for example, 01, 02, ...etc.).
2. A MAJOR alarm on a trunk indicates that alarms on these trunks are not downgraded by the **set options** command and that at least 75 percent of the trunks in this trunk group are alarmed.

### ⇒ NOTE:

If ATMS testing is enabled, check the error log for ATMS Errors #3840 and #3841. If the error log indicates that measurements exceeded acceptable thresholds, and if no other trouble is found with the **test trunk** command, run the ATMS test call with the **test analog-testcall port UCCSSpp full** command.

Central Office (CO) trunks are 2-wire analog lines to the CO which support both incoming and outgoing calls. A CO trunk circuit pack provides an interface between the 2-wire analog line from the CO and the system's (4-wire) Time Division Multiplex (TDM) Bus. The CO Trunk circuit packs include:

- TN747B (United States), 8 port loop start or ground start CO, foreign exchange (FX), or Wide Area Telecommunications (WATS) trunks.
- TN438B (Australia), 8 port loop start.
- TN447 (United Kingdom), 8 port ground start.
- TN465B/C (multiple countries), 8 port loop start.
- TN2138 (Italy), 8 port loop start.
- TN2147C (multiple countries), 8 port loop start and United Kingdom Earth Calling or Loop Calling Guarded Clearing.

## Loop Start and UK Loop Calling Guarded Clearing Operation

Idle State - Tip \_ ground, Ring = CO Battery

- a. Outgoing Call
  1. PBX Off-Hook (Seize Message): Closes the Tip-Ring Loop
    - a. CO Response: DC loop current + Dial tone
  2. PBX On-Hook (Drop Message): Open Tip-Ring loop, no loop current
    - a. CO Response: CO goes to idle state (see Note)
- b. Incoming Call
  1. CO Applies Ringing Voltage
    - a. PBX Response: Detect ringing current
  2. PBX Off-Hook (Answer Message): Close loop
    - a. CO Response: Trip ringing, provide loop current
  3. PBX On-Hook (Drop Message): Open Tip-Ring loop, no loop current
    - a. CO Response: CO goes to idle state (see Note)



### NOTE:

Except for the Netherlands Loop Start and UK Loop Calling Guarded Clearing trunks, CO does not normally provide an On-Hook (Disconnect) signal.

## Ground Start and UK Earth Calling Operation

Idle state - Tip \_ open, Ring = CO Battery

- a. Outgoing Call
  1. PBX Off-Hook (Seize Message): Places ground on Ring
    - a. CO Response: Places ground on Tip
    - b. PBX Response: close the loop
    - c. CO Response: provide loop current
    - d. PBX response: dial out digits
  2. PBX On-Hook first (Drop Message): Open the Tip-Ring Loop, no loop current
    - a. CO Response: Open circuit on Tip

3. CO On-Hook first (Disconnect): Open circuit on Tip, no loop current.
  - a. PBX Response: Open Tip-Ring loop
- b. B. Incoming Call
  1. CO Off-Hook (Seizure): CO applies ground on Tip, CO applies ringing voltage
    - a. PBX Response: Detect ringing, ring destination
  2. PBX Off-Hook (Answer Message): Close loop
    - a. CO Response: Trip ringing, provide loop current
  3. PBX On-Hook first (Drop Message): Open the Tip-Ring Loop, no loop current
    - a. CO Response: Open circuit on Tip
  4. CO On-Hook first (Disconnect): Open circuit on Tip, no loop current

## Hardware Error Log Entries and Test to Clear Values

Table 5-168. CO Trunk Error Log Entries

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
0 <sup>1</sup>	0	Any	Any	Any	test port PCSSpp sh r 1
1 (a)	57347	None			
15 (b)	any	Port Audit Update Test (#36)			
18	0	busyout trunk <grp>/<mbr>	WARNING	OFF	release trunk <grp>/<mbr>
130(c)		None	WARNING	ON	test trunk <grp>/<mbr>
257 (a)	50176	None			
513 (a)	57364	None	MAJ/MIN/WRN <sup>2</sup>	ON	
769 (a)	57392	None	MAJ/MIN/WRN <sup>2</sup>	OFF	
1025 (e)	Any	Demand Diagnostic Test (#3)	MAJ/MIN/WRN <sup>2</sup>	OFF	test port PCSS sh r 2

Continued on next page

5 Maintenance Objects for DEFINITY ONE  
CO-TRK (CO Trunk)

5-422

Table 5-168. CO Trunk Error Log Entries — Continued

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
1281 (e)	Any	Demand Diagnostic Test (#3)	MAJ/MIN/WRN <sup>2</sup>	ON	test port PCSS sh r 3
1537		Dial Tone Test (#0)	MAJ/MIN/WRN <sup>2</sup>	OFF	test port PCSS l r 2
1793		Loop Around and Conference Test (#33)	MAJ/MIN/WRN <sup>2</sup>	ON	test port PCSS l r 3
2049		NPE Cross Talk Test (#6)	MAJ/MIN/WRN <sup>2</sup>	ON	test port PCSS l r 3
2561 (d)	57345	None			
2817 (a)	57360	None			
2817 (a)	57393	None			
2817 (d)	57484	Dial Tone Test (#0)	MAJ/MIN/WRN <sup>2</sup>	OFF	test port PCSS l r 1
3073 (d)	57376	None			
3329 (d)	57408	None			
3329 (d)	57484	Dial Tone Test (#0)	MAJ/MIN/WRN <sup>2</sup>	OFF	test port PCSS l r 1
3585 (d)	57424	None			
3840 (f)	8000	Analog Transmission (#844-848)		OFF	
3841 (f)		Analog Transmission (#844-848)	MINOR	OFF	test analog testcall PCSS pp r 2

1. Run the Short Test Sequence first. If all tests pass, run the Long Test Sequence. Refer to the appropriate test description and follow the recommended procedures.
2. Minor alarms on this MO may be downgraded to warning alarms based on the values used in the **set options** command. If the Minor alarm is not downgraded by the **set-options** values, the Minor alarm is upgraded to a Major alarm if 75 percent of the trunks in this trunk group are alarmed.

## Notes:

- a. These are in-line errors that have no specific test associated with them. Refer to Table 10-93 for an explanation and appropriate action.
- b. This is a software audit error that does not indicate any hardware malfunction. Run the Short Test Sequence and investigate associated errors (if any).
- c. This error type indicates that the circuit pack has been removed or has been insane for more than 11 minutes. To clear the error, reinsert or replace the circuit pack.
- d. Aux data 57345 -- Single polarity ringing current  
Aux data 57376 -- No loop current on incoming call  
Aux data 57408 -- No tip ground detected on outgoing call  
Aux data 57424 -- No loop current on outgoing call  
Aux data 57484 -- No dial tone on outgoing call

These errors cause the Dial Tone Test (#0) to run and are only considered a problem if the Dial Tone Test fails (in which case Error Type 1537 also shows up). In this case, the trunk may be put in "Ready-for-Service" state (shown as "disconnected" by status command), which allows only incoming calls. Run the Dial Tone Test (#0) and follow its outlined procedures.

If error count associated with this error type is very high (that is, 255) and if Alarm Status on the Hardware Error Report is "n" (not alarmed), then the existence of this error type indicates that, despite the fact that many in-line error messages have been received, all Call Seizure Tests have passed. Problems at the CO may cause this condition rather than problems with the PBX.

- e. These errors are logged for all versions of the CO-TRK/CO-BD. However, no MINOR alarms are generated for Central Office Trunks [TN747B] with vintages V8 or greater. Any failures received by this test are still logged as Error type 1025/1281 as additional information for the system technician person.

The system technician person should check for the use of MFT/Range extenders. If there are extenders present, and there are no other complaints or maintenance errors against this trunk, then there is a good chance that Test #3 failed due to excessive loop current and may be ignored.

- f. Test calls made by the Automatic Transmission Measurement System (ATMS) returned measurements that were outside the acceptable limits. Use the **list testcall detail** command to examine specific transmission parameters that are out of spec, and investigate the trunk for that kind of noise. If the noise is acceptable, the limits administered on the "change trunk" screen should be changed.
-

Table 5-169. CO Trunk Errors with NO Tests

Error Type	Aux Data	Description and System Action	System Technician Action
1	57347	Port error. Ringing without ground. This error is detected on an incoming call on a ground-start CO trunk. The CO trunk circuit pack has not detected a Tip ground before ringing current is detected. This may indicate that the ground detector is not working. However, the call is accepted.	See Note 1 at end of table.
257	50176	Battery reversal detected. This is usually caused by the CO (often seen with step-by-step and cross-bar offices in connection with outgoing calls). This is detected if the direction of the loop current changes from normal to reverse for at least 40 msec. Could occur if the trunk was just installed and for some reason the Tip and Ring wires were reversed at the PBX. If battery reversals occur during dialing, wrong numbers may result. The CO should be asked to remove the battery reversal option.	Refer problem to CO.
513	57364	Ground detector stuck active. After several occurrences, an on-board minor alarm is generated.	Run short test. If test aborts with Error Code 1000, disconnect Tip and Ring and repeat short test. If test still aborts, replace circuit pack. If test passes, refer problem to CO. If any other error code is received, pursue that problem.
769	57392	CO not releasing after call is dropped from PBX end (off-board alarm after several occurrences), or the loop is not open after a disconnect (on-board alarm after several occurrences).	For off-board alarm, refer problem to CO. For on-board alarm, the circuit pack has an on-board problem (for example, stuck relay) and should be replaced.

*Continued on next page*

Table 5-169. CO Trunk Errors with NO Tests — *Continued*

Error Type	Aux Data	Description and System Action	System Technician Action
2561	57345	Single polarity ringing current. This error results from abnormal ringing current, but does not prevent the incoming call from being accepted. One cause could be that the reverse current detector associated with the port is failing. (Will not be detected by any tests.) Another cause could be that normal current is not detected. In this case, neither incoming nor outgoing calls can be completed, and the dial tone test also fails. The last cause could be that certain types of noise are present on the CO line during the silent period of ringing.	Check for other errors first and then see Note 4 at end of table.
2817	57360	Ground but no ringing. This error occurs on an incoming call on a ground-start trunk. If ringing is not detected within 5 seconds of the Tip being grounded, the call is still accepted. If the CO is of the No. 5ESS switch type, ringing delays of more than 5 seconds during heavy traffic are fairly common.	Check for other errors.
2817	57393	On the TN465, the loop is opening too slowly after a disconnect. This error indicates an on-board problem, although the trunk may be functional. On the TN2138, CO released the trunk at least 4 minutes after the PBX dropped the call. This error code is log-only and causes no other testing to occur. No alarm is generated.	Check for other errors.
3073	57376	No loop current on incoming call. The incoming destination has already answered and no loop current has been detected. If this is a hard fault, the dial tone test and all outgoing calls should also fail.	Check for other errors.
3329	57408	Trunk error. No Tip ground detected on outgoing call. This error occurs when an attempt is made to seize a ground-start CO trunk for an outgoing call and Tip ground is not detected or the caller hangs up before Tip ground is detected.	See Notes 1 and 2 at end of table.

*Continued on next page*

Table 5-169. CO Trunk Errors with NO Tests — *Continued*

Error Type	Aux Data	Description and System Action	System Technician Action
3585	57424	No loop current on outgoing call. This error occurs on attempt to seize a loop or ground-start trunk for an outgoing call. An error occurs if loop current is not detected or the caller hangs up before it is detected.	See Note 3 at end of table.

Notes for [Table 5-169](#):

1. At the administration terminal, busyout the affected port, and run a Long Test Sequence. Observe the test results. If any tests fail, refer to the description of the tests and the associated error codes. Release the port. If users continue to report troubles, check for other errors and make test calls to determine whether the problem should be escalated or referred to the CO.
2. At the administration terminal, busyout the affected port, and run a Long Test Sequence. If Dial Tone Test #0 passes, ignore this error. Release the port.
3. At the administration terminal, busyout the affected port, and run a Long Test Sequence. If CO Demand Diagnostic Test #3 passes and this error keeps occurring, refer problems to CO. Release the port.
4. If the error count associated with this error type is very high (that is, 255) and all tests pass, then either the reverse current detector is defective or the CO line is noisy. If the CO line is suspected, Tip and Ring observations should be made. If the line is determined to be noisy, the problem should be referred to the CO. If the reverse current detector is defective, ignore this error.

## System Technician-Demanded Tests: Descriptions and Error Codes

---

Always investigate tests in the order they are presented in the table below when inspecting errors in the system. By clearing error codes associated with the *NPE Crosstalk Test*, for example, you may also clear errors generated from other tests in the testing sequence.

For example, you may also clear errors generated from other tests in the testing sequence.

Order of Investigation	Short Test Sequence	Long Test Sequence	D/ND <sup>1</sup>
NPE Crosstalk Test (#6)		X	ND
Dial Tone Test (#0)		X	ND
CO Demand Diagnostic Test (#3) (a)	X	X	ND
Loop Around and Conference Test (#33)		X	ND
Audit Update Test (#36) Analog Transmission Test (#844-848) (b)	X (c)	X (c)	ND

---

1. D = Destructive; ND = Nondestructive

### Notes:

- a. A demand test of Diagnostic Test (#3) always returns a PASS indication for CO-TRK/CO-BD [TN747B] version 8 or greater. However, any errors produced as a result of this test are logged and produce no alarms.

If errors logged by Test #3 are the only complaints against this trunk, then the system technician person should check if MFT/Range Extenders are being used. If extenders are present, then there is a good chance that there is excessive loop current, which causes Test #3 to log errors.

However, all else being normal, these errors should not affect the customer.

- b. Refer to ["TIE-TRK \(Tie Trunk\)" on page 5-1161](#) for a description of this test.
  - c. ATMS test are not part of either sequence. They are run either on demand with the **test analog-testcall** command or via the ATMS schedule.
-

## Dial Tone Test (#0)

This test attempts to seize a port and checks for the return of a dial tone.

Table 5-170. TEST #0 Dial Tone Test

Error Code	Test Result	Description/ Recommendation
	ABORT	Could not allocate system resources to run this test.  1. Retry the command at 1-minute intervals a maximum of 5 times.
1000	ABORT	System resources required to run this test are not available. The port may be busy with a valid call. Use the command <b>display port PCSSpp</b> to determine the trunk group/member number of the port. Use the <b>status trunk</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. (Refer to " <a href="#">status station</a> " on page 4-213 for a description of all possible states.) You must wait until the port is idle before retesting.  1. If the port status is idle, then retry the command at 1-minute intervals a maximum of 5 times.
1001	ABORT	System resources required to run this test were not available. This could be due to a failure to seize the port.  1. Retry the command at 1-minute intervals for a maximum of 5 times.
1002	ABORT	The system could not allocate time slots for the test. The system may be under heavy traffic conditions or it may have time slots out-of-service due to TDM-BUS errors. Refer to " <a href="#">TDM-BUS (TDM Bus)</a> " on page 5-1116 to diagnose any active TDM-BUS errors.  1. If the system has no TDM-BUS errors and is not handling heavy traffic, repeat test at 1-minute intervals a maximum of 5 times.
1004	ABORT	The port was seized by a user for a valid call. Use the <b>display port PCSSpp</b> command to determine the trunk group/member number of the port. Use the <b>status trunk</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. You must wait until the port is idle before retesting.  1. If the port status is idle, retry the command at 1-minute intervals for a maximum of 5 times.
1005	ABORT	Trunk has been administered as incoming-only; dial tone can only be obtained on outgoing trunks. This is a normal condition.
1018	ABORT	Test has been disabled via administration.  1. Verify that the <code>Maintenance Tests?</code> field on the Trunk Group Form is set to <b>n</b> . To enable the test, issue the <b>change trunk-group x</b> command where "x" equals the number of the trunk group to be tested. Then change the entry in the <code>Maintenance Tests?</code> field on the form to <b>y</b> .

Table 5-170. TEST #0 Dial Tone Test — *Continued*

Error Code	Test Result	Description/ Recommendation
2000	ABORT	<p>Response to the test was not received within the allowable time period.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
	FAIL	<p>Trunk was seized, but dial tone could not be detected.</p> <ol style="list-style-type: none"> <li>1. Test all administered outgoing ports on the board. Failure of 1 indicates a problem toward the CO.</li> <li>2. If all fail, see note below.</li> <li>3. Check for errors on the TONE-BD or TONE-PT. Clear any errors found, and repeat the test.</li> <li>4. If the error has still not cleared, refer the problem to the CO.</li> <li>5. If no service problems exist on the port, continue to use the port until the circuit pack can be replaced (as a last resort). Perform a trunk test call to see if the trunk is operable.</li> </ol> <p> <b>NOTE:</b> If the dial tone test fails for all ports on a circuit pack, a -5 volt power problem is indicated.</p>
2002	FAIL	<p>Seizure portion of test failed due to hardware problem. Fault is usually caused by a disconnected trunk.</p> <ol style="list-style-type: none"> <li>1. If the CO Demand Diagnostic Test (#3) also failed, display the Hardware Error Log. If the CO Demand Diagnostic Test failed because it could not detect ground (indicated by Error Type 1281 in the Hardware Error Log) AND Error Type 3329 or 3585 appears in the Hardware Error Log (with the same last occurred time as Error Type 1281 and 1537), replace the circuit pack.</li> <li>2. Check trunk wiring to ensure good connection; repeat test if wiring correction made.</li> <li>3. Locate another identical CO trunk and swap its wiring with one under test. Repeat test on both trunks and determine if problem follows trunk or remains at original port. If problem follows trunk, refer problem to CO. If problem remains at port, replace circuit pack and repeat test.</li> <li>4. If replacing circuit pack does not clear failure, escalate the problem.</li> </ol>
1009	PASS	<p>Detected tone was not pure dial tone. No action is required.</p>
	PASS	<p>Trunk was seized, and dial tone was detected. User-reported troubles on this port should be investigated by using other port tests and by examining trunk or external wiring.</p>

*Continued on next page*

Table 5-170. TEST #0 Dial Tone Test — *Continued*

Error Code	Test Result	Description/ Recommendation
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board).</p> <ol style="list-style-type: none"> <li>1. Check to ensure that the board translations are correct. Translate the board, if necessary.</li> <li>2. Issue the <b>busyout board</b> command.</li> <li>3. Issue the <b>reset board</b> command.</li> <li>4. Issue the <b>release busy board</b> command.</li> <li>5. Issue the <b>test board</b> command. This should re-establish the linkage between the internal ID and the port.</li> </ol>

### CO Demand Diagnostic Test (#3)

For ground start trunks only, port circuit pack relays are operated and checks are made to see if the port can detect and apply ground on the Tip lead. This test also verifies that there is no external ground on the Ring lead. In the absence of other failures, the circuit pack should be replaced only if this test fails with the CO line disconnected.

For the TN2147 World Class Central Office circuit pack, this test also checks the on-board programmable transmission circuitry that allows the circuit pack to support the transmission characteristics of several countries.

Table 5-171. TEST #3 CO Demand Diagnostic Test

Error Code	Test Result	Description/ Recommendation
	ABORT	<p>Could not allocate system resources to run this test.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
1000	ABORT	<p>System resources required to run this test are not available. The port may be busy with a valid call. Use the <b>display port PCSSpp</b> command to determine the trunk group/member number of the port. Use the <b>status trunk</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. You must wait until the port is idle before retesting.</p> <ol style="list-style-type: none"> <li>1. If the port status is idle, then retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>

*Continued on next page*

Table 5-171. TEST #3 CO Demand Diagnostic Test — *Continued*

Error Code	Test Result	Description/ Recommendation
1004	ABORT	<p>The port was seized by a user for a valid call. Use the <b>display port PCSSpp</b> command to determine the trunk group/member number of the port. Use the <b>status trunk</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. You must wait until the port is idle before retesting.</p> <ol style="list-style-type: none"><li>1. If the port status is idle, retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
1005	ABORT	Test inapplicable to present configuration. This is a normal condition.
1018	ABORT	<p>Test has been disabled via administration.</p> <ol style="list-style-type: none"><li>1. Verify that the <code>Maintenance Tests?</code> field on the Trunk Group Form is set to <b>n</b>. To enable the test, issue the <b>change trunk-group x</b> command where "x" equals the number of the trunk group to be tested. Then change the entry in the <code>Maintenance Tests?</code> field on the form to <b>y</b>.</li></ol>
2000	ABORT	<p>Response to the request was not received within the allowable time period.</p> <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>

*Continued on next page*

Table 5-171. TEST #3 CO Demand Diagnostic Test — *Continued*

Error Code	Test Result	Description/ Recommendation
	FAIL	<p>Failure to detect ground or faulty ground detected on Ring lead. Display the hardware errors for this trunk, to determine if the fault was on- or-off board. Look for Error Type 1025 or 1281 (if both appear in the Hardware Error Log, pick the most recent error). Error Type 1025 indicates a faulty ground detected on Ring lead (an off-board fault) and Error Type 1281 indicates failure to detect (internally generated) ground (an on-board fault). Faulty ground detected on Ring lead (Error Type 1025):</p> <p> <b>NOTE:</b> On TN747B vintage 8 and greater circuit packs, an incoming seizure during this test may cause it to fail with an off-board fault.</p> <ol style="list-style-type: none"> <li>1. Repeat test. If test passes, ignore the original failure. If test aborts, follow the recommended procedures.</li> <li>2. Repeat test with CO line removed.</li> <li>3. If test fails, replace the circuit pack.</li> <li>4. If test passes, refer problem to CO.</li> </ol> <p>Failure to detect ground (Error Type 1281):</p> <ol style="list-style-type: none"> <li>1. Run the long test sequence. If the CO Demand Diagnostic Test fails, the Dial Tone Test (#0) fails with Error Code 2002, AND Error Type 3329 or 3585 appears in the Hardware Error Log (with the same last occurred time as Error Type 1281 and 1537), replace the circuit pack.</li> <li>2. Repeat test with CO line removed.</li> <li>3. If test fails, replace the circuit pack.</li> <li>4. If test passes, the CO may be drawing too much current. Refer problem to CO.</li> </ol>
57481	FAIL	<p>On-board test of programmable transmission circuitry failed.</p> <ol style="list-style-type: none"> <li>1. Replace the circuit pack.</li> </ol>

*Continued on next page*

Table 5-171. TEST #3 CO Demand Diagnostic Test — *Continued*

Error Code	Test Result	Description/ Recommendation
	PASS	This test verifies that the port is able to apply ground for outgoing calls and detect ground for incoming calls; however, it does not provide information on whether a CO line is actually connected. User-reported troubles on this port should be investigated by using other port tests and by examining trunk or external wiring.
0	NO BOARD	The test could not relate the internal ID to the port (no board). <ol style="list-style-type: none"><li>1. Check to ensure that the board translations are correct. Translate the board, if necessary.</li><li>2. Issue the <b>busyout board</b> command.</li><li>3. Issue the <b>reset board</b> command.</li><li>4. Issue the <b>release busy board</b> command.</li><li>5. Issue the <b>test board</b> command. This should re-establish the linkage between the internal ID and the port.</li></ol>

**NPE Crosstalk Test (#6)**

One or more Network Processing Elements (NPEs) reside on each circuit pack with a TDM Bus interface. The NPE controls port connectivity and gain, and provides conferencing functions on a per port basis. The NPE Crosstalk Test verifies that this port's NPE channel talks on the selected time slot and never crosses over to time slots reserved for other connections. If the NPE is not working correctly, one way and noisy connections may be observed. This test is usually only part of a port's long test sequence and takes approximately 20 to 30 seconds to complete.

**Table 5-172. TEST #6 NPE Crosstalk Test**

Error Code	Test Result	Description/ Recommendation
	ABORT	<p>Could not allocate the necessary system resources to run this test.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
1000	ABORT	<p>The port was seized by a user for a valid call. Use the <b>display port PCSSpp</b> command to determine the trunk group/member number of the port. Use the <b>status trunk</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. (Refer to <a href="#">"status station" on page 4-213</a> for a description of all possible states.) You must wait until the port is idle before retesting.</p> <ol style="list-style-type: none"> <li>1. If the port status is active but the port is not in use (no calls), check the error log for error type 1025 (see the Error Log table for a description of this error and required actions). The port may be locked up. Check the CO wiring, check for excessive loop current, and check the trunk translations. (If the trunk is translated incorrectly, this test will abort.)</li> <li>2. If the port status is idle, busyout and release the trunk, and then retry the command at 1-minute intervals for a maximum of 5 times.</li> <li>3. If the test still aborts, replace the circuit pack.</li> </ol>
1001	ABORT	<p>Could not allocate the necessary system resources to run this test.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
1002	ABORT	<p>The system could not allocate time slots for the test. The system may be under heavy traffic conditions or it may have time slots out-of-service due to TDM-BUS errors. Refer to <a href="#">"TDM-BUS (TDM Bus)" on page 5-1116</a> to diagnose any active TDM-BUS errors.</p> <ol style="list-style-type: none"> <li>1. If system has no TDM-BUS errors and is not handling heavy traffic, repeat test at 1-minute intervals a maximum of 5 times.</li> </ol>

*Continued on next page*

Table 5-172. TEST #6 NPE Crosstalk Test — *Continued*

Error Code	Test Result	Description/ Recommendation
1003	ABORT	<p>The system could not allocate a tone receiver for the test. The system may be oversized for the number of tone detectors present or some tone detectors may be out-of-service.</p> <ol style="list-style-type: none"> <li>1. Look for TTR-LEV errors in the Error Log. If present, refer to <a href="#">“TTR-LEV (TTR Level)” on page 5-1223</a>.</li> <li>2. Look for TONE-PT errors in the Error Log. If present, refer to <a href="#">“TONE-PT (Tone Generator)” on page 5-1204</a>.</li> <li>3. If neither condition exists, retry the test at 1-minute intervals a maximum of 5 times.</li> </ol>
1004	ABORT	<p>The port was seized by a valid call during the test. The test has been aborted. Use the <b>display port PCSSpp</b> command to determine the trunk group/member number of the port. Use the <b>status trunk</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. You must wait until the port is idle before retesting.</p>
2000	ABORT	<p>Response to the test request was not received within the allowable time period.</p>
2100	ABORT	<p>Could not allocate the necessary system resources to run this test.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
Any	FAIL	<p>The NPE of the tested port was found to be transmitting in error. This causes noisy and unreliable connections.</p> <ol style="list-style-type: none"> <li>1. Replace the circuit pack.</li> </ol>
	PASS	<p>The port is correctly using its allocated time slots. User-reported troubles on this port should be investigated by using other port tests and by examining trunk or external wiring.</p>
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board).</p> <ol style="list-style-type: none"> <li>1. Check to ensure that the board translations are correct. Translate the board, if necessary.</li> <li>2. Issue the <b>busyout board</b> command.</li> <li>3. Issue the <b>reset board</b> command.</li> <li>4. Issue the <b>release busy board</b> command.</li> <li>5. Issue the <b>test board</b> command. This should re-establish the linkage between the internal ID and the port.</li> </ol>

**Loop Around and Conference Circuit Test (#33)**

This test checks the reflective loop around and conference capabilities of a CO port circuit. The test uses 404-Hz, 1004-Hz, and 2804-Hz tones. Each tone is transmitted separately through the loop and checked.

**Table 5-173. TEST #33 Loop Around and Conference Circuit Test**

Error Code	Test Result	Description/ Recommendation
7	ABORT	Could not allocate the necessary system resources to run this test.
129	ABORT	Conference Circuit Test aborted.
131	ABORT	The 404-Hz reflective loop around test aborted. Response to the test request was not received within the allowable time period.
133	ABORT	The 1004-Hz reflective loop around test aborted. Response to the test request was not received within the allowable time period.
		The 2804-Hz reflective loop around test aborted. Response to the test request was not received within the allowable time period.
		1. Retry the command at 1-minute intervals a maximum of 5 times.
1000	ABORT	System resources required to run this test are not available. The port may be busy with a valid call. Use the <b>display port PCSSpp</b> command to determine the trunk group/member number of the port. Use the <b>status trunk</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. You must wait until the port is idle before retesting.
		1. If the port status is active but the port is not in use (no calls), check the error log for error type 769 (see the Error Log table for a description of this error and required actions). The port may be locked up.
		2. If the port status is idle, retry the command at 1-minute intervals for a maximum of 5 times.
1002	ABORT	The system could not allocate time slots for the test. The system may be under heavy traffic conditions or it may have time slots out-of-service due to TDM-BUS errors. Refer to <a href="#">"TDM-BUS (TDM Bus)" on page 5-1116</a> to diagnose any active TDM-BUS errors.
		1. If system has no TDM-BUS errors and is not handling heavy traffic, repeat test at 1-minute intervals a maximum of 5 times.

*Continued on next page*

Table 5-173. TEST #33 Loop Around and Conference Circuit Test — *Continued*

Error Code	Test Result	Description/ Recommendation
1003	ABORT	<p>The system could not allocate a tone receiver for the test. The system may be oversized force.</p> <ol style="list-style-type: none"><li>1. Look for TTR-LEV errors in the Error Log. If present, refer to <a href="#">“TDM-BUS (TDM Bus)” on page 5-1116</a>.</li><li>2. Look for TONE-PT errors in the Error Log. If present, refer to <a href="#">“TONE-PT (Tone Generator)” on page 5-1204</a>.</li><li>3. If neither condition exists, retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
1004	ABORT	<p>System resources required to run this test are not available. The port may be busy with a valid call. Use the <b>display port PCSSpp</b> command to determine the trunk group/member number of the port. Use the <b>status trunk</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. You must wait until the port is idle before retesting.</p> <ol style="list-style-type: none"><li>1. If the port status is idle, retry the command at 1-minute intervals for a maximum of 5 times.</li></ol>
1018	ABORT	<p>The test was disabled via administration. Verify that the 'Maintenance Test' field on the 'Trunk Group' form is set to 'n'. To enable the test, issue the 'change trunk-group x' command (x equals the number of the trunk group to be tested). Then, change the entry in the 'Maintenance Test' field on the form to 'y'.</p> <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
2000	ABORT	<p>Response to the test was not received within the allowable time period.</p>
2100	ABORT	<p>Could not allocate the necessary system resources to run this test.</p> <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>

*Continued on next page*

Table 5-173. TEST #33 Loop Around and Conference Circuit Test — *Continued*

Error Code	Test Result	Description/ Recommendation
7, 129, 131, or 133	FAIL	<p>The conference capabilities of the port failed (Error Code 7).</p> <p>The reflective 404-Hz Tone Test failed. No transmission was detected to or from the port (Error Code 129).</p> <p>The reflective 1004-Hz Tone Test failed. No transmission was detected to or from the port (Error Code 131).</p> <p>The reflective 2804-Hz Tone Test failed. No transmission was detected to or from the port (Error Code 133).</p> <p>FAULT ISOLATION: Proceed as follows unless power or tone problems are suspected (see note below).</p> <ol style="list-style-type: none"> <li>1. To make sure the problem is on-board, disconnect the port from the CO and retry the test. Coordinate this with the CO, or do it after busy hours; otherwise, the CO may put the connection out of service.</li> <li>2. If the retry fails, replace the circuit pack.</li> <li>3. If the retry passes and no troubles have been reported, disable the test. If the retry passes and troubles have been reported, refer the problem to the CO.</li> </ol> <p> <b>NOTE:</b> If the looparound and conference circuit test fails for all ports on a circuit pack, a -5 volt power problem is indicated. When the tone errors are cleared, rerun the test. If the test fails again, see FAULT ISOLATION above.</p>
	PASS	CO Trunk Loop Around and Conference Test is successful. User-reported troubles on this port should be investigated by using other port tests and by examining trunk or external wiring.
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board).</p> <ol style="list-style-type: none"> <li>1. Check to ensure that the board translations are correct. Translate the board, if necessary.</li> <li>2. Issue the <b>busyout board</b> command.</li> <li>3. Issue the <b>reset board</b> command.</li> <li>4. Issue the <b>release busy board</b> command.</li> <li>5. Issue the <b>test board</b> command. This should re-establish the linkage between the internal ID and the port.</li> </ol>

## Port Audit Update Test (#36)

This test sends updates of the CO port translation for all ports on the circuit pack that have been translated. The update is non-disruptive and guards against possible corruption of translation data contained on the circuit pack. No response message is expected from the circuit pack once it receives translation updates. The port translation data includes: ground or loop start trunk, tone or rotary dialing trunk, rotary dialing inter-digit timing, network balance R/RC, and disconnect timing.

Table 5-174. TEST #36 Port Audit Update Test

Error Code	Test Result	Description/ Recommendation
	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals a maximum of 5 times.
1006	ABORT	The port has been placed out of service, perhaps by craft busyout. Use the <b>display port PCSSpp</b> command to determine the trunk group/member number of the port. Use the <b>status trunk</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. You must wait until the port is idle before retesting. 1. If the port status is idle, retry the command at 1-minute intervals a maximum of 5 times.
2100	ABORT	System resources required to run this test were not available. 1. If the port status is idle, retry the command at 1-minute intervals a maximum of 5 times.
	FAIL	Internal system error 1. Retry the command at 1-minute intervals a maximum of 5 times.

*Continued on next page*

Table 5-174. TEST #36 Port Audit Update Test — *Continued*

Error Code	Test Result	Description/ Recommendation
	PASS	<p>This test passed. Translation information was successfully updated on the circuit pack. User-reported troubles on this port should be investigated by using other port tests and by examining trunk or external wiring. If the trunk is busied out, the test does not run, but returns PASS. To verify that the trunk is in-service:</p> <ol style="list-style-type: none"> <li>1. Enter <b>status-command</b> to verify that the trunk is in-service. If the trunk is in-service, no further action is necessary. If the trunk is out-of-service, continue to Step 2.</li> <li>2. Enter <b>release-trunk</b> command to put the trunk back into in-service.</li> <li>3. Retry the test command.</li> </ol>
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board).</p> <ol style="list-style-type: none"> <li>1. Check to ensure that the board translations are correct. Translate the board, if necessary.</li> <li>2. Issue the <b>busyout board</b> command.</li> <li>3. Issue the <b>reset board</b> command.</li> <li>4. Issue the <b>release busy board</b> command.</li> <li>5. Issue the <b>test board</b> command. This should re-establish the linkage between the internal ID and the port.</li> </ol>

### Transmission Test (#844-848)

This test is non-destructive.



#### NOTE:

Tests #844-848 are not supported on non-US Systems.

These tests are run by the Automatic Transmission Measurement System (ATMS). They are not part of the long or short trunk test sequences. Instead, they are run on demand with the **test analog-testcall** command or as part of ATMS scheduled testing.

The test call attempts to seize a port and make a call to a terminating test line (TTL) on the trunk's far end. Transmission performance measurements are made and compared to administered thresholds. Errors are generated when results fall outside of "marginal" or "unacceptable" thresholds. Detail and summary measurement reports are obtainable via the **list testcalls** command.

Table 5-175. TEST #844-848 Transmission Test

Error Code	Test Result	Description/ Recommendation
1000	ABORT	System resources required to run this test are not available. The port may be busy with a valid call. Use <b>display port PCSSpp</b> to determine the trunk group/member number of the port. Use the <b>status trunk</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port unavailable for this test. You must wait until the port is idle before retesting.  1. If the port status is idle, then retry the command at 1-minute intervals a maximum of 5 times.
1001	ABORT	Could not allocate the necessary system resources to run this test.  1. Retry the command at 1-minute intervals a maximum of 5 times.
1002	ABORT	The system could not allocate time slots for the test. The system may be under heavy traffic conditions or it may have timeslots out of service due to TDM bus errors. Refer to <a href="#">"TDM-BUS (TDM Bus)" on page 5-1116</a> to diagnose any active TDM bus errors.  1. If system has no TDM bus errors and is not handling heavy traffic, repeat test at 1-minute intervals a maximum of 5 times.
1004	ABORT	The port has been seized by a user for a valid call. Use status trunk to determine when the port is available for testing.  1. Retry the command at 1-minute intervals a maximum of 5 times.  2. If the test continues to abort and the port is not in use, escalate the problem.
1005	ABORT	Trunk has been administered as incoming-only; transmission tests can only be run on outgoing trunks.
1115	ABORT	The near end test line could not be allocated.  1. Verify that the TN795 circuit pack's port 1 is administered and in service with the <b>status port</b> command.  2. Retry the command at 1-minute intervals a maximum of 5 times.
1900	ABORT	The test completion message was not received from the TN795 circuit pack.  1. Test the TN795 circuit pack.
1901	ABORT	This error occurs when the TN795 circuit pack uplinks a message that is not the proper response for this test. The anticipated uplink messages are seize, ring or answer.  1. Verify that the Trunk is administered properly.

*Continued on next page*

Table 5-175. TEST #844-848 Transmission Test — Continued

Error Code	Test Result	Description/ Recommendation
1905	ABORT	Intercept tone detected from far end. <ol style="list-style-type: none"><li>1. Get the test line data and verify it with the far end. Dial the test number manually to see if the TTL is reached. If it is not, then either the number is wrong, or the far end is administered incorrectly.</li></ol>
1906	ABORT	Reorder tone detected from far end. <ol style="list-style-type: none"><li>1. See actions for error code 1905.</li></ol>
1907	ABORT	Other unexpected tone detected from far end. <ol style="list-style-type: none"><li>1. See actions for error code 1905.</li></ol>
1913	ABORT	Audible Ring detected from far end. <ol style="list-style-type: none"><li>1. See actions for error code 1905.</li></ol>
1914	ABORT	Unidentified interrupted tone detected from far end. <ol style="list-style-type: none"><li>1. See actions for error code 1905</li></ol>
1915	ABORT	Busy tone detected from far end. <ol style="list-style-type: none"><li>1. Since the test line at the far end was busy. Try the test again.</li><li>2. If the test continues to abort, the problem is with the far end system.</li></ol>
1918	ABORT	Test progress tone not removed from far end (type 105 test line only). <ol style="list-style-type: none"><li>1. The problem is with the far end system; a technician at the far end should test the test line.</li></ol>
1919	ABORT	Unexpected far end release <ol style="list-style-type: none"><li>1. The problem is with the far end system; a technician at the far end should test the test line.</li></ol>
1920	ABORT	No response from far end. <ol style="list-style-type: none"><li>1. The problem is with the far end system; a technician at the far end should test the test line.</li></ol>
1921	ABORT	No data returned from far end. <ol style="list-style-type: none"><li>1. The problem is with the far end system; a technician at the far end should test the test line.</li></ol>
1922	ABORT	Steady, unidentifiable tone from far end <ol style="list-style-type: none"><li>1. See actions for error code 1905.</li></ol>
1923	ABORT	Broadband energy detected from far end (such as voice or announcement). <ol style="list-style-type: none"><li>1. See actions for error code 1905.</li></ol>

*Continued on next page*

Table 5-175. TEST #844-848 Transmission Test — *Continued*

Error Code	Test Result	Description/ Recommendation
1924	ABORT	No test tone from far end 1. See actions for error code 1905.
1938	ABORT	Near-end self test failed. 1. Test the TN795 circuit pack.
1939	ABORT	Loss self check at 0dBm at 1004 Hz failed. 1. Test the TN795 circuit packs. 2. If the test continues to abort escalate the problem.
1940	ABORT	Far end noise self check failed. 1. The problem is with the far end system; a technician at the far end should test the test line.
1941	ABORT	High frequency singing return loss self check failed. 1. Test the TN795 circuit packs.
1942	ABORT	Echo return loss self check failed. 1. Test the TN795 circuit packs.
1943	ABORT	Singing return loss self check failed. 1. Test the TN795 circuit packs.
1944	ABORT	Loss self check at -16 dBm at 1004 Hz failed. 1. Test the TN795 circuit packs
1945	ABORT	Loss self check at -16 dBm at 404 Hz failed. 1. Test the TN795 circuit packs.
1946	ABORT	Loss self check at -16 dBm at 2804 Hz failed. 1. Test the TN795 circuit packs.
1947	ABORT	Noise with tone self check failed. 1. Test the TN795 circuit packs.
2000	ABORT	The test timed out while waiting for a response from the TN795 circuit pack. 1. Retry the command at 1-minute intervals a maximum of 5 times.
2012	ABORT	An internal software error occurred. 1. Retry the command at 1-minute intervals a maximum of 5 times.
2053	ABORT	The test call could not be established, but no information on why is available. 1. Retry the command at 1-minute intervals a maximum of 5 times.

*Continued on next page*

Table 5-175. TEST #844-848 Transmission Test — *Continued*

Error Code	Test Result	Description/ Recommendation
2056	ABORT	An error occurred while trying to obtain results from the TN795 circuit pack.  1. Test the TN795 circuit pack.
	FAIL	Measured transmission performance was in the unacceptable range as administered on the trunk group form. Retrieve a measurement report via the <b>list testcalls</b> command. Make sure that ATMS thresholds are set properly on page 4 of the trunk group form. Besides the facility, test failures can be caused by faulty test lines or switch paths. If the measurements point to a facility problem, report the results to the trunk vendor.
8000	FAIL	Measured transmission performance was in the marginal range as administered on the trunk group form. This generally means that the trunk is usable but has an undesirable amount of noise or loss. If the user does not report unacceptable effects, it may not be necessary to take any action. Retrieve a measurement report via the <b>list testcalls</b> command. Make sure that ATMS thresholds are set properly on page 4 of the trunk group form.

## CONFIG (System Configuration)

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run	Full Name of MO
CONFIG	major	none	System Configuration

The System Configuration maintenance object (MO) oversees logical insertion and removal of circuit packs in the system. When Switch Control detects that a circuit pack is present in a port slot, it informs System Configuration and System Configuration queries the circuit pack to determine the type and vintage of the circuit pack. Similarly, when Switch Control detects that a circuit pack has been removed from a port slot, it informs System Configuration.

There are no major alarms or tests for System Configuration, but 4 types of errors are logged to the Hardware Error Log (see below).

### Hardware Error Log Entries and Test to Clear Values

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
0 <sup>1</sup>	0	Any	Any	Any	none
2-117(a)	0-2	none			
257(b)		none			
1002-1117(c)	0-2	none			

1. Run the Short Test Sequence first. If all tests pass, run the Long Test Sequence. Refer to the appropriate test description and follow the recommended procedures.

#### Notes:

- a. This error indicates that a Port circuit pack in the system did not respond to a circuit pack type inquiry. Follow the procedures outlined in (c) to determine if there is an error.
- b. This error indicates that less than 25% of Trunk Group is available.
- c. This error indicates that a Port circuit pack in the system did not respond to a vintage inquiry.

As a result of either of these errors, a Port circuit pack may be physically inserted in a Port slot, but the system may not recognize it.

## CUST-ALM (Customer-Provided Alarming Device)

---

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run <sup>1</sup>	Full Name of MO
CUST-ALM	none	test customer-alarm PC	Customer-Provided Alarming Device

- 
1. Where PC is an appropriate port network number and carrier.
- 

The system provides customers a way to connect their own alarm indication device to a switch. The CUST-ALM maintenance object represents this Customer-Provided Alarming Device (CPAD). When an alarm occurs at least to the level to which the CPAD is administered, the CPAD in the Processor Port Network (PPN) is activated. The CPAD is administered by the Maintenance-Related System-Parameters Form (CPE Alarm Activation Level field). The CPAD is connected to the Processor circuit pack. The valid levels to which to set the CPE Alarm Activation Level are: *none*, *warning*, *minor*, or *major*. The CPAD is also activated within a cabinet whenever Emergency Transfer is invoked within that cabinet. The CUST-ALM MO is not maintained by the system and does not generate any alarms. If a problem is suspected with the CPAD, it may be tested using the **test customer-alarm** command, which activates the device by closing the relay on the Processor circuit pack for 1 minute. The repeat parameter may be used to close the relay for a longer length of time (5 minutes is the suggested repeat value).

The CPAD is also activated within a cabinet whenever Emergency Transfer is invoked within that cabinet. The CUST-ALM MO is not maintained by the system, and does not generate any alarms. If a problem is suspected with the CPAD, it may be tested using the **test customer-alarm** command, which activates the device by closing the relay on either the Processor circuit pack for 1 minute. The repeat parameter may be used to close the relay for a longer length of time (5 minutes is the suggested repeat value).

5 Maintenance Objects for DEFINITY ONE  
CUST-ALM (Customer-Provided Alarming Device)

5-447

Error Log Entries and Test to Clear Values

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
none	none	none			

System Technician-Demanded Tests: Descriptions and Error Codes

There are no errors associated with the CPAD CUST-ALM MO. The **test customer-alarm PC** command is provided to allow a technician to check that the customer-provided alarming device is correctly installed and functional. It is recommended that this test be run at least once after both the switch and the customer alarm have been installed.

Always investigate tests in the order presented in the table below when inspecting errors in the system. By clearing error codes associated with the *Customer-Provided Alarming Device Test*, for example, you may also clear errors generated from other tests in the testing sequence.

Order of Investigation	Short Test Sequence	Long Test Sequence	D/ND <sup>1</sup>
Customer-Provided Alarming Device Test (#115)	X	X	ND

---

1. D = Destructive; ND = Nondestructive

---

## Customer-Provided Alarming Device Test (#115)

This test closes the relay that activates the CPAD for 1 minute only within the port network specified. If it takes longer than 1 minute to check that the CPAD has been activated, the Repeat field on the **test customer-alarm PC** command can be used to close the relay for up to 99 minutes. Note that when the repeat option is used, the results for Test #115 come back immediately and, for each test that passed, the CPAD is kept on for that many minutes. The CPAD does not go off after 1 minute and then come back on. Instead, the CPAD is kept on continuously for the entire time. If the CPAD is being activated and deactivated in a flickering fashion, there is a problem with either the CPAD or the Processor circuit pack.

Table 5-176. TEST #115 Customer-Provided Alarming Device Test

Error Code	Test Result	Description/Recommendation
(blank) 1000 2029	ABORT	Internal system error  1. Try the command at 1-minute intervals a maximum of 5 times.
	PASS	The switch software successfully sent the request to the Processor circuit pack to turn on the CPAD. The CPAD must be physically inspected to verify that it is working. If the CPAD is working and the customer has complained that the CPAD did not indicate a system alarm when it occurred, then check the administered levels for turning on the CPAD via the Display System-Parameter Maintenance screen form. Compare these levels with the customer's specifications. If Test #115 passes, and the CPAD is not being activated, check the connection of the CPAD to the Processor circuit pack. If the CPAD can be activated but cannot be deactivated, first check to make sure Emergency Transfer is not activated in the affected port network via the <b>status system</b> command. Emergency Transfer can be forced to manual OFF by the Emergency Transfer switch on the Processor circuit pack. If Emergency Transfer is OFF and the CPAD still cannot be deactivated, check the administered levels for the CPAD with the Display System-Parameter Maintenance screen form and compare against the alarm levels currently present in the system ( <b>display alarms</b> command).

## DATA-CHL (Data Channel)

---

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run	Full Name of MO
DATA-CHL <sup>1</sup>	MINOR	test data-module ext l	Data Channel
DATA-CHL <sup>2</sup>	WARNING	test data-module ext sh <sup>3</sup>	Data Channel

1. The **test data-module ext long** command drops all sessions on all of the Data Channels. Refer to Data Channel Reset Test (#107).
2. *ext* is the extension of the Data Channel to be tested. The extension can be determined by issuing the **list data-module** command from the administration terminal. The resulting form provides a mapping from the 1CXXpp designation of the Data Channel to its corresponding extension, where pp indicates which one of the four (TN777B Netcon) or eight (TN794 NetPkt) Data Channels is alarmed (01, 02, etc.) and C indicates the carrier on which the alarmed Data Channel resides.
3. The **test data-module ext long** command drops all sessions on all of the Data Channels. Refer to Data Channel Reset Test (#107).

The Data Channels (DATA-CHLs) provide a data communications interface that allows data terminal equipment connected to port circuit packs to communicate with software applications running on the system.

The TN777B Netcon circuit pack contains four (4) Data Channels and the TN794 NetPkt circuit pack contains eight (8) Data Channels.

Each DATA-CHL represents a dial-up/dial-out asynchronous communications port that interfaces to the TDM Bus. Data is transported between the terminal equipment and the software application over the DATA-CHL.

## Error Log Entries and Test to Clear Values

Table 5-177. Data Channel Error Log Entries

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
0 <sup>1</sup> (a)	0	Any	Any	Any	test data-module ext sh r 1
1	Any	Local Loop Back Test (#111)	MINOR	ON	test data-module ext sh r 3
18	0	busyout data-module ext	WARNING	OFF	release data-module ext
130		None	WARNING	ON	test data-module ext sh
257	Any	Remote Maintenance Looparound Test (#109)	MINOR	ON	test data-module ext sh r 5
513	Any	Crosstalk Test (#110)	MINOR	ON	test data-module ext sh r 3
769	Any	Dual Port RAM Test (#108)	MINOR	ON	test data-module ext l r 3

1. Run the Short Test Sequence first. If all tests pass, run the Long Test Sequence. Refer to the appropriate test description and follow the recommended procedures.

- a. **Error Type 0:** Switch has removed circuit pack has been removed or circuit pack has been insane for more than 11 minutes.
  1. Reinsert the circuit pack.
  2. Verify that the alarm clears.
  3. If problem persists, replace the circuit pack.

## System Technician-Demanded Tests: Descriptions and Error Codes

---

Two system technician test commands include the Data Channels (DATA-CHLs).

- The **test data-module ext [short | long]** command tests the single DATA-CHL, specified by *ext*.
- The **test network-control [short | long]** command tests each administered DATA-CHL that resides on the TN777B Netcon or TN794 NetPkt circuit pack in the specified carrier.

Investigate errors in the order they appear in the table below.

Order of Investigation	Short Test Sequence	Long Test Sequence	D/ND <sup>1</sup>
Data Channel Reset Test (#107) (a)		X	D
Data Channel Dual Port Ram Test (#108) (a)		X	D
Data Channel Remote Maintenance Loop Around Test (#109)	X	X	ND
Data Channel Local Loop Back Test (#111)	X	X	ND
Data Channel Crosstalk Test (#110)	X	X	ND

---

1. D = Destructive; ND = Nondestructive

a. These tests are destructive.

1. Determine if there are any active links:

- CDR (**status smdr-link**)
- System printer (**status sp-link**)
- Journal printer (**status journal-link wakeup-log** and **status journal-link pms-log**)
- PMS links (**status pms-link**).

2. Busyout links if necessary:

- CDR (**busyout smdr-link**)
- System printer (**busyout sp-link**)
- Journal printer (**busyout journal-link wakeup-log** and **busyout journal-link pms-log**)
- PMS links (**busyout pms-link**)

Table 5-178. System Technician-Demanded Tests: DATA-CHL

Order of Investigation	Short Test Sequence	Long Test Sequence	D/ND <sup>1</sup>
Control Channel Test (Common Port Circuit Pack) (#52) (a)		X	ND
NPE Audit Test (Common Port Circuit Pack) (#50) (a)	X	X	ND
Data Channel Reset Test (#107)		X	D
Data Channel DPR Test (#108)		X	D
Data Channel Maintenance Loop Around Test (#109)	X	X	ND
Data Channel Crosstalk Test (#110)	X	X	ND
Data Channel Local Loop Back Test (#111)	X	X	ND
Switch Control Reset Test (#93) (b) (d)			D
Time-of-Day Clock Test (#95) (b)	X	X	ND
Control Channel Interface Test (#92) (b)	X	X	ND
Control Channel Transmission Test (#94) (b)	X	X	ND
12-Volt Power Supply Test (#701) (c)	X	X	ND
Memory Card Insertion Test (#695) (c)	X	X	ND
Memory Card Format and Read Test (#696) (c)	X	X	ND
Memory Card Match Test (#697) (c)	X	X	ND
Memory Card Write-Protected Test (#698) (c)	X	X	ND
Memory Card Directory Recovery Test (#699) (c)	X	X	ND
Memory Card Translation Data Integrity Test (#694) (c)		X	ND
Memory Card Erase/Write/Read Test (#693) (c)	X		ND

1. D = Destructive, ND = Non-destructive

- a. Refer to DATA-BD (Netcon or NetPkt Circuit Pack) Maintenance documentation for a description of these tests.
- b. Refer to SW-CTL (Switch Control) Maintenance documentation for a description of these tests.
- c. Refer to CARD-MEM for information on this test.
- d. This test runs only as part of the [reset switch-control](#) command.

## Data Channel Reset Test (#107)

**This test is destructive.**

This test resets the data communications interface that DATA-CHLs provides and drops all existing connections.

Table 5-179. TEST #107 Data Channel Reset Test

Error Code	Test Result	Description/Recommendation
1000	ABORT	Could not allocate the necessary system resources to run this test. 1. Try the command at 1-minute intervals, up to 5 times.
2100	ABORT	Could not allocate the necessary system resources to run this test.
10704	ABORT	Internal system error 1. Try the command at 1-minute intervals, up to 5 times.
Any	FAIL	The circuit pack failed to reset. 1. Execute the command again. 2. If the problem persists, replace the Processor circuit pack. 3. Reset Time-of-Day clock ( <b>set time</b> ).
	PASS	The circuit pack initializes correctly.

## Data Channel Dual Port RAM Test (#108)

**This test is destructive.**

Hardware and software share the dual port RAM. This test requests each side to read and write the dual port RAM, first one at a time and then simultaneously in alternate locations.

This test prevents new connections from establishing over the DATA-CHLs, however, existing connections are not (and cannot) be dropped.

**Table 5-180. TEST #108 Data Channel Dual Port RAM Test**

Error Code	Test Result	Description/Recommendation
1000	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals, up to 5 times.
	FAIL	Dual port RAM not functioning correctly. 1. Execute the command again. 2. If the problem persists, replace the Netcon or NetPkt circuit pack. 3. If problem persists, reset Time-of-Day clock ( <b>set time</b> ).
	PASS	The dual port RAM is functioning.

## Data Channel Remote Maintenance Loop Around Test (#109)

This non-destructive test verifies the integrity of the entire DATA-CHL (that is, the software, dual port RAM, and hardware that comprise it). The test places a call from arbitrary DATA-CHL and into target DATA-CHL to loop over the connection in each direction, and it checks that the data received by one data channel is the same as the data that was sent by the other.

By establishing a connection between two data channels across the TDM Bus, this test also verifies the integrity of the TDM Bus and Tone-Clock circuit.

Tests #107, #108, #110, and #111 on the DATA-CHL maintenance object can help to determine which data channel is defective.



### NOTE:

If Error Code recommends busying out a CDR, System Printer, Journal Printer, or PMS Link, restore each busied-out link to service before concluding work on the problem.

Table 5-181. TEST #109 Data Channel Remote Maintenance Loop Around Test

Error Code	Test Result	Description/Recommendation
4	ABORT	<p>Error Code 4 can mean 1 of 2 problems:</p> <ol style="list-style-type: none"> <li>Target DATA-CHL is busy and, therefore, not available for use.</li> <li>Internal system error.</li> </ol> <p>If the results of Tests #110 and #111 are both PASS, then there is a high probability that the target DATA-CHL is not defective.</p> <p>Proceed with the remaining steps <b>only if it is necessary to completely test the target DATA-CHL:</b></p> <ol style="list-style-type: none"> <li>Determine if errors exist on links using target DATA-CHL (<a href="#">status link</a>).</li> <li>If there are no errors, busyout the links (<a href="#">busyout link</a>).</li> <li>Retry the command at 1-minute intervals, up to 5 times.</li> <li>Restore any busied out links.</li> </ol>
30 31 32 33 40 41 70 75	ABORT	<p>Internal system error</p> <ol style="list-style-type: none"> <li>Retry the command at 1-minute intervals, up to 5 times.</li> </ol>

Table 5-181. TEST #109 Data Channel Remote Maintenance Loop Around Test — *Continued*

Error Code	Test Result	Description/Recommendation
1000	ABORT	<p>Error Code of 1000 can mean one of several things:</p> <ol style="list-style-type: none"><li>Target DATA-CHL is busy and, therefore, not available for use.</li><li>No other DATA-CHLs are administered and, therefore, not available to place the call to the target DATA-CHL.</li><li>All other DATA-CHLs are busy and, therefore, not available to place the call to the target DATA-CHL.</li><li>Could not allocate the necessary system resources to run this test.</li><li>Internal system error.</li></ol> <p>If the results of Tests #110 and #111 are both PASS, then there is a high probability that the target DATA-CHL is not defective.</p> <p>Proceed with the remaining steps <b>only if it is necessary to completely test the target DATA-CHL:</b></p> <ol style="list-style-type: none"><li>Determine if errors exist on links using target DATA-CHL (<a href="#">status link</a>).</li><li>If there are no errors, busyout the links (<a href="#">busyout link</a>).</li><li>Determine if no other DATA-CHLs are administered (<a href="#">list data-module</a>).</li><li>If no other DATA-CHLs are administered, administer at least one.</li><li>Determine if links exist on all non-target DATA-CHLs (<a href="#">status link</a>).</li><li>If links exist on all DATA-CHLs, busyout the links (<a href="#">busyout link</a>).</li><li>Retry the command at 1-minute intervals, up to 5 times.</li><li>Restore any busied out links.</li></ol>

*Continued on next page*

Table 5-181. TEST #109 Data Channel Remote Maintenance Loop Around Test — *Continued*

Error Code	Test Result	Description/Recommendation
1006	ABORT	<p>For this test, an Error Code of 1006 can have one of several different meanings:</p> <ol style="list-style-type: none"> <li>No other DATA-CHLs are administered and, therefore, not available to place the call to the target DATA-CHL.</li> <li>All other DATA-CHLs are busy and, therefore, not available to place the call to the target DATA-CHL.</li> <li>Could not allocate the necessary system resources to run this test.</li> <li>Internal system error.</li> </ol> <p>If the results of Tests #110 and #111 are both PASS, then there is a high probability that the target DATA-CHL is not defective.</p> <p>Proceed with the remaining steps <b>only if it is necessary to completely test the target DATA-CHL:</b></p> <ol style="list-style-type: none"> <li>Determine if no other DATA-CHLs are administered (<b>list data-module</b>).</li> <li>If no other DATA-CHLs are administered, administer at least one.</li> <li>Determine if errors exist on links using target DATA-CHL (<a href="#">status link</a>).</li> <li>If there are no errors, busyout the links (<a href="#">busyout link</a>).</li> <li>Retry the command at 1-minute intervals, up to 5 times.</li> <li>Restore any busied out links.</li> </ol>
1016	ABORT	<p>Could not allocate the necessary system resources to run this test.</p> <ol style="list-style-type: none"> <li>Retry the command at 1-minute intervals, up to 5 times.</li> </ol>
1018	ABORT	<p>Test disabled through software patch.</p>
2003	ABORT	<p>Internal system error</p>
2004	ABORT	<p>Internal system error</p> <ol style="list-style-type: none"> <li>Check dial plan to ensure data channel extensions are set up as local extensions rather than remote or UDP extensions.</li> <li>Retry the command at 1-minute intervals, up to 5 times.</li> </ol>

*Continued on next page*

Table 5-181. TEST #109 Data Channel Remote Maintenance Loop Around Test — *Continued*

Error Code	Test Result	Description/Recommendation
40 41	FAIL	Error Codes 40 and 41: Remote Maintenance Looparound Test failed because data was corrupted.
2000 2003 2004		Error Codes 2000-2004: Remote Maintenance Looparound Test failed because data was lost.  Test cannot indicate which DATA-CHL is defective. <ol style="list-style-type: none"> <li>1. Check dial plan to ensure data channel extensions are set up as local extensions rather than remote or UDP extensions.</li> <li>2. Determine if links exist on DATA-CHLs (<a href="#">status link</a>).</li> <li>3. Execute tests #110 and #111 in the Short Test Sequence for the <i>target</i> DATA-CHL to determine which actions to take, based on the results below. <ol style="list-style-type: none"> <li>a. Both Test results are PASS: Arbitrarily chosen DATA-CHL is probably defective. <ol style="list-style-type: none"> <li>1. Run Short Test Sequence for <i>each</i> DATA-CHL not in use.</li> <li>2. Note the test results for Tests #110 and #111 for each DATA-CHL.</li> <li>3. Remove DATA-CHLs (<b>remove data-module ext</b>) for which the results of Tests #110 and #111 were both FAIL.</li> <li>4. Replace the Netcon or NetPkt circuit pack at earliest convenience.</li> </ol> </li> <li>b. Only one test result is FAIL for any other DATA-CHLs not in use: TDM Bus is probably defective.</li> <li>c. Test #110 result is FAIL and Test #111 result is PASS (for target DATA-CHL): Either the RDM Bus or Tone-Clock circuit pack is defective. <ol style="list-style-type: none"> <li>1. Check for TDM bus alarms or errors (TDM-BUS) and/or Tone-Clock circuit pack alarms or errors (TONE-BD, TONE-PT, and TDM-CLK).</li> <li>2. If there are no errors or alarms, the target DATA-CHL, or Netcon or NetPkt circuit pack are probably defective: refer to steps in 3a above.</li> <li>3. If there are errors or alarms, refer to Maintenance documentation to clear the alarms and errors.</li> <li>4. Repeat the test.</li> </ol> </li> </ol> </li> </ol>

*Continued on next page*

Table 5-181. TEST #109 Data Channel Remote Maintenance Loop Around Test — *Continued*

Error Code	Test Result	Description/Recommendation
40 41 2000 2003 2004	FAIL ( <i>cont'd.</i> )	<p>d. Test #110 result is either PASS or FAIL and Test #111 result is FAIL (for target DATA-CHL): the target DATA-CHL, or Netcon or NetPkt circuit pack are probably defective.</p> <ol style="list-style-type: none"> <li>1. Busyout the links to all DATA-CHLs (<b>busyout link</b>).</li> <li>2. Test the target DATA-CHL (<b>test data-module ext long</b>).</li> <li>3. If Test #107 result or Test #108 is FAIL, replace the Netcon or NetPkt circuit pack when convenient.</li> <li>4. Reset Time-of-Day clock on new circuit pack (<b>set time</b>).</li> <li>5. Repeat the test.</li> <li>6. If Test #107 result is PASS, and Test #108 result is FAIL,</li> <li>7. Replace the Netcon or NetPkt circuit pack when convenient.</li> <li>8. Repeat the test.</li> </ol> <p>If both Test #107 result and Test #108 results ARE PASS, the target DATA-CHL is defective.</p> <ol style="list-style-type: none"> <li>1. Remove target DATA-CHL from operation (<b>remove data-module ext</b>).</li> <li>2. Replace the Netcon or NetPkt circuit pack when convenient.</li> <li>3. Reset Time-of-Day clock on new circuit pack (<b>set time</b>)</li> <li>4. Restore any busied out links.</li> </ol>
	PASS	Connections can be established over the DATA-CHLs.

### Data Channel Crosstalk Test (#110)

This non-destructive test verifies the integrity of the entire DATA-CHL. Unlike the Remote Maintenance Looparound Test (#109), this test only involves the target DATA-CHL.

The test establishes a looparound connection over the DATA-CHL, to test the DATA-CHL as a sender receiver of data. The test checks that the data received by the DATA-CHL is the same as the data that was sent by the DATA-CHL. Because the looparound connection is across the TDM Bus, this test also verifies the integrity of the TDM Bus and Tone-Clock circuit pack.

Tests #107, #108, and #111 on the DATA-CHL can be helpful to determine which DATA-CHL is defective.



**NOTE:**

If Error Code recommend busying out a CDR, System Printer, Journal Printer, or PMS Link, restore each busied out link to service before concluding work on the problem.

Table 5-182. TEST #110 Data Channel Crosstalk Test

Error Code	Test Result	Description/Recommendation
4	ABORT	<p>Error Code 4 can mean 1 of 2 problems:</p> <ul style="list-style-type: none"> <li>a. Target DATA-CHL is busy and, therefore, not available for use.</li> <li>b. Internal system error.</li> </ul> <p>If the results of Tests #110 and #111 are both PASS, then there is a high probability that the target DATA-CHL is not defective.</p> <p>Proceed with the remaining steps <b>only if it is necessary to completely test the target DATA-CHL:</b></p> <ol style="list-style-type: none"> <li>1. Determine if errors exist on links using target DATA-CHL (<a href="#">status link</a>).</li> <li>2. If there are no errors, busyout the links (<a href="#">busyout link</a>).</li> <li>3. Retry the command at 1-minute intervals, up to 5 times.</li> <li>4. Restore any busied out links.</li> </ol>
40 70 75	ABORT	<p>Internal system error</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals, up to 5 times.</li> </ol>

*Continued on next page*

Table 5-182. TEST #110 Data Channel Crosstalk Test — *Continued*

Error Code	Test Result	Description/Recommendation
1000	ABORT	<p>Error Code of 1000 can mean one of several things:</p> <ol style="list-style-type: none"> <li>a. The target DATA-CHL is busy and, therefore, not available for use.</li> <li>b. Could not allocate the necessary system resources to run this test.</li> <li>c. Internal system error</li> </ol> <p>If the results of Tests #110 and #111 are both PASS, then there is a high probability that the target DATA-CHL is not defective.</p> <p>Proceed with the remaining steps <b>only if it is necessary to completely test the target DATA-CHL:</b></p> <ol style="list-style-type: none"> <li>1. Determine if errors exist on links using target DATA-CHL (<a href="#">status link</a>).</li> <li>2. If there are no errors, busyout the links (<b>busyout link</b>).</li> <li>3. Determine if no other DATA-CHLs are administered (<b>list data-module</b>).</li> <li>4. If no other DATA-CHLs are administered, administer at least one.</li> <li>5. Determine if links exist on all non-target DATA-CHLs (<a href="#">status link</a>).</li> <li>6. If links exist on all DATA-CHLs, busyout the links (<a href="#">busyout link</a>).</li> <li>7. Retry the command at 1-minute intervals, up to 5 times.</li> <li>8. Restore any busied out links.</li> </ol>
1002	ABORT	<p>Error Code 1002 can mean 1 of 2 problems:</p> <ol style="list-style-type: none"> <li>a. Could not allocate the necessary system resources to run this test.</li> <li>b. Internal system error.</li> </ol>
1006	ABORT	<p>Could not allocate the necessary system resources to run this test.</p>
1016	ABORT	<p>Resources for the test are not available.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals, up to 5 times.</li> </ol>
1018	ABORT	<p>Test disabled through software patch.</p>
2000	ABORT	<p>Could not allocate the necessary system resources to run this test.</p>
2003	ABORT	<p>Internal system error</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals, up to 5 times.</li> </ol>

*Continued on next page*

Table 5-182. TEST #110 Data Channel Crosstalk Test — *Continued*

Error Code	Test Result	Description/Recommendation
14 16 40 2000 2003 2004	FAIL	<p>Error Codes 40 and 41: Remote Maintenance Looparound Test failed because data was corrupted.</p> <p>Error Codes 2000, 2003, and 2004: Remote Maintenance Looparound Test failed because data was lost.</p> <p>Test cannot indicate which DATA-CHL is defective.</p> <ol style="list-style-type: none"> <li>1. Check dial plan to ensure data channel extensions are set up as local extensions rather than remote or UDP extensions.</li> <li>2. Determine if links exist on DATA-CHLs (<a href="#">status link</a>).</li> <li>3. Execute tests #110 and #111 in the Short Test Sequence for the <i>target</i> DATA-CHL to determine which actions to take, based on the results below. <ol style="list-style-type: none"> <li>a. Both Test results are PASS: Arbitrarily chosen DATA-CHL is probably defective. <ol style="list-style-type: none"> <li>1. Run Short Test Sequence for <i>each</i> DATA-CHL not in use.</li> <li>2. Note the test results for Tests #110 and #111 for each DATA-CHL.</li> <li>3. Remove DATA-CHLs (<b>remove data-module ext</b>) for which the results of Tests #110 and #111 were both FAIL.</li> <li>4. Replace the Netcon or NetPkt circuit pack at earliest convenience.</li> </ol> </li> <li>b. Only one test result is FAIL for any other DATA-CHLs not in use: TDM Bus is probably defective.</li> <li>c. Test #110 result is FAIL and Test #111 result is PASS (for target DATA-CHL): Either the RDM Bus or Tone-Clock circuit pack is defective. <ol style="list-style-type: none"> <li>1. Check for TDM bus alarms or errors (TDM-BUS) and/or Tone-Clock circuit pack alarms or errors (TONE-BD, TONE-PT, and TDM-CLK).</li> <li>2. If there are no errors or alarms, the target DATA-CHL, or Netcon or NetPkt circuit pack are probably defective: refer to steps in 3.a above.</li> <li>3. If there are errors or alarms, refer to Maintenance documentation to clear the alarms and errors.</li> <li>4. Repeat the test.</li> </ol> </li> </ol> </li> </ol>

*Continued on next page*

Table 5-182. TEST #110 Data Channel Crosstalk Test — *Continued*

Error Code	Test Result	Description/Recommendation
14 16 40 2000 2003 2004	FAIL ( <i>cont'd.</i> )	<p>d. Test #110 result is either PASS or FAIL and Test #111 result is FAIL (for target DATA-CHL): the target DATA-CHL, or Netcon or NetPkt circuit pack are probably defective.</p> <ol style="list-style-type: none"> <li>1. Busyout the links to all DATA-CHLs (<b>busyout link</b>).</li> <li>2. Test the target DATA-CHL (<b>test data-module ext long</b>).</li> <li>3. If Test #107 result or Test #108 is FAIL, replace the Netcon or NetPkt circuit pack when convenient.</li> <li>4. Reset Time-of-Day clock on new circuit pack (<b>set time</b>).</li> <li>5. Repeat the test.</li> <li>6. If Test #107 result is PASS, and Test #108 result is FAIL,</li> <li>7. Replace the Netcon or NetPkt circuit pack when convenient.</li> <li>8. Repeat the test.</li> </ol> <p>e. If both Test #107 result and Test #108 results ARE PASS, the target DATA-CHL is defective.</p> <ol style="list-style-type: none"> <li>1. Remove target DATA-CHL from operation (<b>remove data-module ext</b>).</li> <li>2. Replace the Netcon or NetPkt circuit pack when convenient.</li> <li>3. Reset Time-of-Day clock on new circuit pack (<b>set time</b>)</li> <li>4. Restore any busied-out links.</li> </ol>
	PASS	DATA-CHLs establish connections.

### Data Channel Local Loop Back Test (#111)

Hardware and software share the dual port RAM. This non-destructive test verifies the dual port RAM integrity. The test loops back data from the DATA-CHL to the DATA-CHL, within the dual port RAM, and checks that the DATA-CHL receives the data it sent.

 **NOTE:**

If Error Code recommend busying out a CDR, System Printer, Journal Printer, and/or PMS Link, restore each busied out link to service according to Maintenance documentation, before concluding work on the problem.

Table 5-183. TEST #111 Data Channel Local Loop Back Test

Error Code	Test Result	Description/Recommendation
4	ABORT	<p>Error Code 4 can mean 1 of 2 problems:</p> <ol style="list-style-type: none"> <li>1. Target DATA-CHL is busy and, therefore, not available for use.</li> <li>2. Internal system error.</li> </ol> <p>If the results of Tests #110 and #111 are both PASS, then there is a high probability that the target DATA-CHL is not defective.</p> <p>Proceed with the remaining steps <b>only if it is necessary to completely test the target DATA-CHL:</b></p> <ol style="list-style-type: none"> <li>1. Determine if errors exist on links using target DATA-CHL (<a href="#">status link</a>).</li> <li>2. If there are no errors, busyout the links (<a href="#">busyout link</a>).</li> <li>3. Retry the command at 1-minute intervals, up to 5 times.</li> <li>4. Restore any busied out links.</li> </ol>
40 70 75	ABORT	<p>Internal system error</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals, up to 5 times.</li> </ol>
1000	ABORT	<p>Error Code of 1000 can mean one of several things:</p> <ol style="list-style-type: none"> <li>a. The target DATA-CHL is busy and, therefore, not available for use.</li> <li>b. Could not allocate the necessary system resources to run this test.</li> <li>c. Internal system error</li> </ol> <p>If the results of Tests #110 and #111 are both PASS, then there is a high probability that the target DATA-CHL is not defective.</p> <p>Proceed with the remaining steps <b>only if it is necessary to completely test the target DATA-CHL:</b></p> <ol style="list-style-type: none"> <li>1. Determine if errors exist on links using target DATA-CHL (<a href="#">status link</a>).</li> <li>2. If there are no errors, busyout the links (<a href="#">busyout link</a>).</li> <li>3. Determine if no other DATA-CHLs are administered (<a href="#">list data-module</a>).</li> <li>4. If no other DATA-CHLs are administered, administer at least one.</li> <li>5. Determine if links exist on all non-target DATA-CHLs (<a href="#">status link</a>).</li> <li>6. If links exist on all DATA-CHLs, busyout the links (<a href="#">busyout link</a>).</li> <li>7. Retry the command at 1-minute intervals, up to 5 times.</li> <li>8. Restore any busied out links.</li> </ol>

*Continued on next page*

Table 5-183. TEST #111 Data Channel Local Loop Back Test — *Continued*

Error Code	Test Result	Description/Recommendation
1006	ABORT	<p>Error Code 1006 can mean 1 of 2 problems:</p> <ul style="list-style-type: none"> <li>a. Could not allocate the necessary system resources to run this test.</li> <li>b. Internal system error.</li> </ul> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals, up to 5 times.</li> </ol>
1016	ABORT	<ul style="list-style-type: none"> <li>a. Could not allocate the necessary system resources to run this test.</li> </ul> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals, up to 5 times.</li> </ol>
1018	ABORT	Test disabled through software patch.
2000	ABORT	Internal system error
2003	ABORT	<p>Internal system error</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals, up to 5 times.</li> </ol>
40 2000 2003 2004	FAIL	<p>Error Code 40: Local Loop Back Test failed—data corrupt.</p> <p>Error Code 2000-2004: Local Loop Back Test—data lost.</p> <ol style="list-style-type: none"> <li>1. Determine if links exist on DATA-CHLs (<a href="#">status link</a>).</li> <li>2. Busyout the links to all DATA-CHLs (<a href="#">busyout link</a>).</li> <li>3. Test the target DATA-CHL (<b>test data-module ext long</b>).</li> <li>4. If Test #107 result is FAIL, replace the Netcon or NetPkt circuit pack when convenient.</li> <li>5. Reset Time-of-Day clock on new circuit pack (<b>set time</b>).</li> <li>6. Repeat the test.</li> <li>7. If Test #107 result is PASS, and Test #108 result is FAIL, replace the Netcon or NetPkt circuit pack when convenient.</li> <li>8. Repeat the test.</li> <li>9. If both Test #107 result and Test #108 results ARE PASS, the target DATA-CHL is defective.</li> <li>10. Remove target DATA-CHL from operation (<b>remove data-module ext</b>).</li> <li>11. Replace the Netcon or NetPkt circuit pack when convenient.</li> <li>12. Reset Time-of-Day clock on new circuit pack (<b>set time</b>).</li> <li>13. Restore any busied out links.</li> </ol>
	PASS	DATA-CHLs establish connections.

## DAT-LINE (Data Line)

---

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run <sup>1</sup>	Full Name of MO
DAT-LINE	MINOR	test port PCSSpp l	Data Line
DAT-LINE	WARNING	test port PCSSpp sh	Data Line

- 
1. Where P is the port network number (1 for PPN); C is the carrier designation (for example, A, B, or C); and SS is the address of the slot in the carrier where the circuit pack is located (for example, 01, 02, ..., etc.).
- 

The TN726 Data Line circuit pack is a port circuit that provides connectivity from the system to asynchronous CPE having RS232-compatible serial interfaces. There are eight data lines (DAT-LINEs) on the Data Line circuit pack. If there are errors associated with the DT-LN-BD (Data Line Circuit Pack), refer to [“XXX-BD \(Common Port Circuit Pack\)” on page 5-1343](#).

Data Lines are administered via the administration terminal **add data-module** command. The data module type is *data-line*. The **list data-module** command lists all administered data modules in the system.

The TN750 Announcement circuit pack has one Data Line on it. The Data Line is used for saving and restoring announcements. For a description of this feature, refer to [“ANN-BD \(announcement circuit pack\)” on page 5-112](#). Also, if there are errors associated with the Announcement circuit pack, refer to [“ANN-BD \(announcement circuit pack\)”](#).

### NOTE:

If the tests for the Data Line in question pass and there are still user-reported problems, there is probably an external problem. Test the ADU, following the procedures outlined in *User Manual Z3A Asynchronous Data Unit*, 555-401-701. If the ADU appears to be working properly, check the external wiring and, finally, check the customer equipment.

## Error Log Entries and Test to Clear Value

Table 5-184. Data Line Error Log Entries

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
0 <sup>1</sup>	0	Any	Any	Any	test port PCSSpp sh r 1
1		Digital Loop Around Test (#171)	MINOR	ON	test port PCSSpp sh r 2
15(a)	Any	Audit Update Test (#36)			
18	0	busyout port PCSSpp	WARNING	OFF	release port PCSSpp
130 (b)		None	WARNING	ON	test port PCSSpp sh
257		Conference Circuit Test (#7)	MINOR	ON	test port PCSSpp l r 2
513		NPE Crosstalk Test (#6)	MINOR	ON	test port PCSSpp l r 2
769(a)	Any (c)	None			

1. Run the Short Test Sequence first. If all tests pass, run the Long Test Sequence. Refer to the appropriate test description and follow the recommended procedures.

### Notes:

- a. This is a software audit error that does not indicate any hardware malfunction. Run the Short Test Sequence and investigate errors (if any).
- b. This error type indicates that the circuit pack has been removed or has been insane for more than 11 minutes. To clear the error, reinsert or replace the circuit pack.
- c. This error is logged when the Data Line circuit pack finds an error with the transmit/receive circuitry of an administered Data Line on circuit pack insertion. Perform the following procedure:
  1. Issue the **busyout board PCSS** command to busyout the Data Line circuit pack on which this port resides.
  2. Issue the **reset board PCSS** command. Check the Hardware Error Log to determine if Error Type 769 is logged again for the DAT-LINE MO.



### NOTE:

When displaying errors, set the Active Alarms Only field to **n**.

If Error Type 769 reappears, replace the DAT-LINE circuit pack. If Error Type 769 does not reappear, proceed to Step 3.

3. Issue the **release board PCSS** command to release the Data Line circuit pack on which this port resides.

## System Technician-Demanded Tests: Descriptions and Error Codes

Always investigate tests in the order presented in the table below when inspecting errors in the system. By clearing error codes associated with the *Digital Loop Around Test*, for example, you may also clear errors generated from other tests in the testing sequence.

Order of Investigation	Short Test Sequence	Long Test Sequence	D/ND <sup>1</sup>
Digital Loop Around Test (#171)	X	X	ND
NPE Crosstalk Test (#6)		X	ND
Conference Circuit Test (#7)		X	ND
Audit Update Test (#36)	X	X	ND

1. D = Destructive; ND = Nondestructive

### NPE Crosstalk Test (#6)

The NPE Crosstalk Test verifies that this port's NPE channel talks on the selected time slot and never crosses over to time slots reserved for other connections. If the NPE is not working correctly, one-way and noisy connections may be observed. This test is usually part of a port's Long Test Sequence and takes about 20 to 30 seconds to complete.

Table 5-185. TEST #6 NPE Crosstalk Test

Error Code	Test Result	Description/Recommendation
	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals a maximum of 5 times.
1000	ABORT	System resources required to run this test are not available. The port may be in use on a valid call. Use <b>status data-module</b> to determine when the port is available for testing. (Refer to <a href="#">"status station" on page 4-213</a> for a description of all possible states.) 1. Retry the command at 1-minute intervals a maximum of 5 times.
1001	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals a maximum of 5 times.

*Continued on next page*

Table 5-185. TEST #6 NPE Crosstalk Test — *Continued*

Error Code	Test Result	Description/Recommendation
1002	ABORT	The system could not allocate time slots for the test. The system may be under heavy traffic conditions or it may have time slots out-of-service due to TDM-BUS errors. Refer to <a href="#">“TDM-BUS (TDM Bus)” on page 5-1116</a> to diagnose TDM-BUS errors.  1. If system has no TDM-BUS errors and is not handling heavy traffic, repeat test at 1-minute intervals a maximum of 5 times.
1003	ABORT	The system could not allocate a tone receiver for the test. The system may be oversized for the number of Tone Detectors present or some Tone Detectors may be out-of-service.  1. Resolve any TTR-LEV errors. 2. Resolve any TONE-PT errors. 3. If neither condition exists, retry the test at 1-minute intervals a maximum of 5 times.
1004	ABORT	The port has been seized by a user for a valid call. Use <b>status data-module</b> to determine when the port is available for testing.  1. Retry the command at 1-minute intervals a maximum of 5 times.
1020	ABORT	The test did not run due to an already existing error on this port (Error Type 769).  1. Refer to the procedure for Error Type 769. If Error Type 769 still occurs on this port, replace the circuit pack.
2000	ABORT	Response to the test request was not received within the allowable time period.
2100	ABORT	Could not allocate the necessary system resources to run this test.  1. Retry the command at 1-minute intervals a maximum of 5 times.
Any	FAIL	The NPE of the tested port was found to be transmitting in error. This causes noisy and unreliable connections.  1. Replace the circuit pack.
	PASS	The port is correctly using its allocated time slots. User-reported troubles on this port should be investigated using other port tests, examining the ADU, external wiring, and customer equipment.

**Conference Circuit Test (#7)**

The Conference Circuit Test verifies that the NPE channel for the port being tested can correctly perform the conferencing function. The NPE is instructed to listen to several different tones and conference the tones together. The resulting signal is then measured by a Tone Detector port. If the level of the tone is within a certain range, the test passes.

**Table 5-186. TEST #7 Conference Circuit Test**

Error Code	Test Result	Description/Recommendation
	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals a maximum of 5 times.
1000	ABORT	System resources required to run this test are not available. The port may be in use on a valid call. Use <b>status data-module</b> to determine when the port is available for testing.
1004	ABORT	The port has been seized by a user for a valid call. Use <b>status data-module</b> to determine when the port is available for testing. 1. Retry the command at 1-minute intervals a maximum of 5 times.
1020	ABORT	The test did not run due to an already existing error on this port (Error Type 769). 1. Refer to the procedure for Error Type 769. If Error Type 769 still occurs on this port, replace the circuit pack.
2000	ABORT	Response to the test request was not received within the allowable time period.
2100	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals a maximum of 5 times.
Any	FAIL	The conference circuit test failed (possible off-board problem). 1. Busyout and release the port (data line), and then retest. 2. Replace the circuit pack if the test continues to fail.
	PASS	The port can correctly conference multiple connections. User-reported troubles on this port should be investigated using other port tests, examining the ADU, external wiring, and customer equipment.

## Audit Update Test (#36)

This audit makes sure that the hardware state of the Data Line is consistent with the system translations. When this audit is run, the port is queried for the switchhook state, and the software state is updated according to the returned value. Also, the data line options are sent down to the port.

Table 5-187. TEST #36 Audit Update Test

Error Code	Test Result	Description/ Recommendation
1006	ABORT	The test did not run due to an already existing error on this port (Error Type 769). <ol style="list-style-type: none"><li>1. Refer to the procedure for Error Type 769. If Error Type 769 still occurs on this port, replace the circuit pack.</li></ol>
2000	ABORT	Response to the test request was not received within the allowable time period.
2100	ABORT	Could not allocate the necessary system resources to run this test. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
7	FAIL	Internal system error <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
	PASS	The hardware port state is consistent with the software state. User-reported troubles on this port should be investigated using other port tests, examining the ADU, external wiring, and customer equipment.

## Digital Loop Around Test (#171)

The Digital Loop Around Test checks the Data Line's ability to transmit and receive data on the TDM Bus. Data is sent through Data Channel 3 (data channel port 3) over the TDM Bus, internally looped through the Data Line back onto the TDM Bus, and received again by Data Channel 3.

If data channel 3 is in use or not administered, this test aborts. This test may fail if Network Control Data Channel 3 is not functioning properly. If there are any DATA-CHL errors in the Error Log, refer to the DATA-BD (Data Channel Processor circuit pack) Maintenance documentation to clear them up first. This test passes regardless of any customer equipment that may be connected to the port, as long as the port is not in use by the equipment.

Table 5-188. TEST #171 Digital Loop Around Test

Error Code	Test Result	Description/Recommendation
	ABORT	Internal system error 1. Retry the command at 1-minute intervals a maximum of 5 times.
1000	ABORT	System resources required to run this test are not available. The port may be in use on a valid call. Use <b>status data-module</b> to determine when the port is available for testing. 1. Retry the command at 1-minute intervals a maximum of 5 times.
1005 1007	ABORT	Data Channel 3 is not administered. This port is required to run this test. 1. Verify that data channel 3 is not administered with the <b>list data-module</b> command. Administer data channel 3 with the <b>add data-module</b> command, and run this test again.
1016	ABORT	Data Channel 3 is busy. The port may be in use on a valid call. Use <b>status data-module</b> to determine when the port is available for testing. 1. Retry the command at 1-minute intervals a maximum of 5 times.
1020	ABORT	The test did not run due to an already existing error on this port (Error Type 769). 1. Reseat the circuit pack and look in the Error Log. If Error Type 769 still occurs on this port, replace the circuit pack.
2003	ABORT	Failed to receive an off-hook from the Data Line. 1. Retry the command at 1-minute intervals a maximum of 5 times.

*Continued on next page*

Table 5-188. TEST #171 Digital Loop Around Test — *Continued*

Error Code	Test Result	Description/Recommendation
2004	ABORT	Failed to receive an off-hook from the Data Channel.
2005	ABORT	<p>The handshake between the data channel and the data line port failed.</p> <ol style="list-style-type: none"> <li>1. Look for DATA-CHL errors in the Error Log. If present, refer to DATA-BD (Data Channel Processor circuit pack) Maintenance documentation.</li> <li>2. Retry the command at 1-minute intervals a maximum of 5 times.</li> <li>3. If the test still aborts, replace the circuit pack.</li> </ol>
2100	ABORT	<p>Could not allocate the necessary system resources to run this test.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
	FAIL	<p>The test failed because the data received did not match the data sent. This would indicate that there is a fault somewhere in the transmit/receive path to the TDM Bus, which probably results in data corruption over this port. This test may fail if Data Channel 3 is not functioning properly.</p> <ol style="list-style-type: none"> <li>1. Look for DATA-CHL errors in the Error Log. If present, refer to DATA-BD (Data Channel Processor circuit pack) Maintenance documentation.</li> <li>2. Repeat this test.</li> <li>3. If the test fails again, replace the Data Line circuit pack.</li> </ol>
2000	FAIL	<p>The test failed waiting for the transmitted data to be looped back.</p> <ol style="list-style-type: none"> <li>1. Look for DATA-CHL errors in the Error Log. If present, refer to DATA-BD (Data Channel Processor circuit pack) Maintenance documentation.</li> <li>2. Repeat this test.</li> <li>3. If the test fails again, replace the Data Line circuit pack.</li> </ol>
	PASS	<p>The port can correctly transmit/receive data. User-reported troubles on this port should be investigated by examining the ADU, external wiring, and customer equipment.</p>

## DETR-BD (International Version)

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run <sup>1</sup>	Full Name of MO
DETR-BD	MINOR	test board PCSS	Tone Detector Circuit Pack
DETR-BD	WARNING	test board PCSS	Tone Detector Circuit Pack

1. Where P is the port network number (1 for PPN); C is the carrier number (for example, A, B, or C); SS is the address of the slot in the carrier where the circuit pack is located (for example, 01, 02, ..., etc.).

The companding mode of the DETR-BD circuit pack must match the administered mode for the system for proper tone detection. The companding mode is administered on the System-Parameters Country-Options form. Refer to *DEFINITY Enterprise Communications Server Release 8 Administration and Feature Description*, (555-230-522).

For all DETR-BD circuit pack level errors, refer to [“XXX-BD \(Common Port Circuit Pack\)” on page 5-1343](#).

## DID-BD (Direct Inward Dial Trunk Circuit Pack)

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run <sup>1</sup>	Full Name of MO
DID-BD	MIN	test board PCSS sh	Direct Inward Dial Trunk Circuit Pack
DID-BD	WRN	test board PCSS sh	Direct Inward Dial Trunk Circuit Pack

1. Where P is the port network number (1 for PPN); C is the carrier designation (for example, A, B, or C); and SS is the address of the slot in the carrier where the circuit pack is located (for example, 01, 02, ..., etc.).

Refer to [“XXX-BD \(Common Port Circuit Pack\)” on page 5-1343](#) for circuit pack level errors. See also [“DID-TRK \(DID Trunk\)” on page 5-486](#) for related trunk information.

## DID-DS1 (DS1 DID Trunk)

---

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run	Full Name of MO
DID-DS1	MAJOR <sup>1</sup>	test trunk <grp>/<mbr>	Direct Inward Dial Trunk
DID-DS1	MINOR	test trunk <grp>/<mbr>	Direct Inward Dial Trunk
DID-DS1	WARNING	test trunk <grp>/<mbr>	Direct Inward Dial Trunk

- 
1. A major alarm on a trunk indicates that alarms on these trunks are not downgraded by the **set options** command and that at least 75 percent of the trunks in this trunk group are alarmed.
- 

The DID-DS1 trunk provides a digital DID trunk from a CO switch into the system through a DS1 link. A 24 channel DS1 link can support up to 24 DID-DS1 trunk calls simultaneously. A 32 channel DS1 link can support up to 30 DID-DS1 trunk calls simultaneously. A DID-DS1 trunk can be used for both voice and data communications with appropriate DS1 signaling mode (for example, common channel signaling). Only the TN767 and TN464 DS1 Interface circuit packs support the DID-DS1 trunk call processing signalings, wink-start, and immediate-start.

DID-DS1 trunk maintenance provides a means to maintain a DID trunk on a port of DS1 Interface circuit pack. Information included covers the in-line errors log, initialization tests, periodic tests, system technician demand tests, and alarms escalation and elimination. Two trunk service states are specified in the DID-DS1 trunk maintenance. They are: *out-of-service*, the trunk is in a deactivated state and can't be used for incoming calls; *in-service*, the trunk is in an activated state and can be used for incoming calls. If the DS1 Interface circuit pack is out-of-service, then all trunks on the DS1 Interface circuit pack are put into out-of-service state and a Warning alarm is raised.

5 Maintenance Objects for DEFINITY ONE  
DID-DS1 (DS1 DID Trunk)

5-476

**Hardware Error Log Entries and Test to Clear Values**

Table 5-189. DID-DS1 Error Log Entries

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
0 <sup>1</sup>	0	Any	Any	Any	test trunk <grp>/<mbr> sh r 1
1 (a)	Any				
15 (b)	Any	Port Audit and Update Test (#36)			
18 (c)			WARNING	OFF	release trunk <grp>/<mbr>
130 (d)		None	WARNING	ON	test trunk <grp>/<mbr>
257 (e)	57474 57473				
513 (f)	57392	None	MIN/MAJ <sup>2</sup>	OFF	
769 (g)	57393	None	MIN/MAJ <sup>2</sup>	OFF	
1281		Conference Circuit Test (#7)	MAJ/MIN/ WRN <sup>3</sup>	ON	test trunk <grp>/<mbr> l
1537		NPE Crosstalk Test (#6)	MAJ/MIN/ WRN <sup>3</sup>	ON	test trunk <grp>/<mbr> l
1793 (h)				ON	test board PCSS l
2305(i)	50944	None	MIN/MAJ <sup>2</sup>	OFF	
3840 (j)		Port Audit and Update Test (#36)			

1. Run the Short Test Sequence first. If all tests pass, run the Long Test Sequence. Refer to the appropriate test description and follow the recommended procedures.
2. This alarm will only be raised when the System-Parameter Country form has the Base Tone Generator field set to 4 (Italy). This alarm will be a MINOR alarm unless 75% or more trunks in this trunk group are out of service, then the alarm will be upgraded to a MAJOR alarm.
3. Minor alarms on this MO may be downgraded to Warning alarms based on the values used in the **set options** command. If the Minor alarm is not downgraded by the **set options** values, the Minor alarm is upgraded to a Major alarm if 75 percent of the trunks in this trunk group are alarmed.

## Notes:

- a. DS1 Interface circuit pack detects a hardware error. The Aux Data field contains the Error Type: 57476, on-hook before wink; 57477, on-hook before ready to receive digits; 57485, wink too short for valid signal.
- b. This is a software audit error that does not indicate any hardware malfunction. Run the Short Test Sequence and investigate errors (if any).

- c. System Technician has busied out the trunk to out-of-service state. No calls can be made on this trunk.
- d. This error type indicates that the circuit pack has been removed or has been insane for more than 11 minutes. To clear the error, reinsert or replace the circuit pack.
- e. DS1 Interface circuit pack detects a hardware error. The Aux Data field contains the Error Type: 57474, rotary dial rate above 12 pulses per second; 57473, rotary dial rate below eight pulses per second.
- f. DS1 Interface circuit pack detects a hardware error. The Aux Data field contains the Error Type: 57392, no external release on PBX disconnect.
- g. DS1 Interface circuit pack detects a hardware error. The Aux Data field contains the Error Type: 57393, belated external release on PBX disconnect.
- h. DS1 Interface circuit pack is out-of-service. Look for DS1-BD errors in Hardware Error Log. Refer to [“DS1-BD \(DS1 Interface Circuit Pack\)” on page 5-548](#) for details.
- i. Error Type 2305—This error indicates that a signaling change was detected by the PBX trunk circuit pack which is inconsistent with the present state of the trunk.
- j. Port Audit and Update Test (#36) failed due to an internal system error. Enter **status trunk** command to verify the status of the trunk. If the trunk is out-of-service, then enter the **release trunk** command to put it back to in-service. Retry the test command.

---

## System Technician-Demanded Tests: Descriptions and Error Codes

---

Always investigate tests in the order they are presented in the table below when inspecting errors in the system. By clearing error codes associated with the *NPE Crosstalk Test*, for example, you may also clear errors generated from other tests in the testing sequence.

Order of Investigation	Short Test Sequence	Long Test Sequence	D/ND <sup>1</sup>
NPE Crosstalk Test (#6)		X	ND
Conference Circuit Test (#7)		X	ND
Port Audit and Update Test (#36)		X	ND

---

1. D = Destructive; ND = Nondestructive

**NPE Crosstalk Test (#6)**

One or more NPEs reside on each circuit pack with a TDM Bus interface. The NPE controls port connectivity and gain, and provides conferencing functions on a per-port basis. The NPE Crosstalk Test verifies that this port's NPE channel talks on the selected time slot and never crosses over to time slots reserved for other connections. If the NPE is not working correctly, one-way and noisy connections may be observed. This test is usually only part of a port's Long Test Sequence and takes about 20 to 30 seconds to complete.

**Table 5-190. TEST #6 NPE Crosstalk Test**

Error Code	Test Result	Description/ Recommendation
	ABORT	System resources required for this test are not available.  1. Retry the command at 1-minute intervals a maximum of 5 times.
1000	ABORT	System resources required to run this test were not available.  The port may be busy with a valid call. Use the <b>display port PCSSpp</b> command to determine the trunk group/member number of the port. Use the <b>status trunk</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. (Refer to " <a href="#">status station</a> " on page 4-213 for a description of all possible states.) You must wait until the port is idle before retesting.  1. If the port status is active but the port is not in use (no calls), check the error log for error type 1025 (see the Error Log table for a description of this error and required actions). The port may be locked up.  2. If the port status is idle, retry the command at 1 minute intervals for a maximum of 5 times.
1001	ABORT	System resources required for this test are not available.  1. Retry the command at 1-minute intervals a maximum of 5 times.
1002	ABORT	The system could not allocate time slots for the test. The system may be under heavy traffic conditions or it may have time slots out-of-service due to TDM BUS error. Refer to " <a href="#">TDM-BUS (TDM Bus)</a> " on page 5-1116 to diagnose any active TDM Bus errors.  1. If system has no TDM-BUS errors and is not handling heavy traffic, repeat test at 1-minute intervals a maximum of 5 times.

*Continued on next page*

Table 5-190. TEST #6 NPE Crosstalk Test — *Continued*

Error Code	Test Result	Description/ Recommendation
1003	ABORT	<p>The system could not allocate a tone receiver for the test. The system may be oversized for the number of Tone Detectors present or some Tone Detectors may be out-of-service.</p> <ol style="list-style-type: none"> <li>1. Look for TTR-LEV errors in the Error Log. If present, refer to <a href="#">“TTR-LEV (TTR Level)” on page 5-1223</a>.</li> <li>2. Look for TONE-PT errors in the Error Log. If present, refer to <a href="#">“TONE-PT (Tone Generator)” on page 5-1204</a>.</li> <li>3. If neither condition exists, retry the test at 1-minute intervals a maximum of 5 times.</li> </ol>
1004	ABORT	<p>The port was seized by a user for a valid call. Use the <b>display port PCSSpp</b> command to determine the trunk group/member number of the port. Use the <b>status trunk</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. You must wait until the port is idle before retesting.</p> <ol style="list-style-type: none"> <li>1. If the port status is idle, retry the command at 1 minute intervals for a maximum of 5 times.</li> </ol>
1020	ABORT	<p>The test did not run due to a previously existing error on the specific port or a more general circuit pack error.</p> <ol style="list-style-type: none"> <li>1. Examine Error Log for existing errors against this port or the circuit pack and attempt to diagnose the previously existing error.</li> </ol>
2000	ABORT	<p>Response to the test request was not received within the allowable time period.</p>
2100	ABORT	<p>System resources required for this test are not available.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
2053	ABORT	<p>At least one of the following errors is found on the DS1 circuit pack: 1281—Loss of signal, 1793—Blue Alarm, 2049—Red Alarm, 2305—Yellow Alarm, 1537—Hyperactivity.</p> <p>Look for the above error types in the Hardware Error Log and follow the procedures given in the appropriate DS1-BD or UDS1-BD maintenance documentation for the listed error types.</p>

*Continued on next page*

Table 5-190. TEST #6 NPE Crosstalk Test — *Continued*

Error Code	Test Result	Description/ Recommendation
ANY	FAIL	<p>The test failed. This can be due to on-board or off-board problems. Off-board problems of concern include EXP-PN and EXP-INTF faults, TDM-BUS faults, and faults associated with the tone detectors/tone generators. Clear all off-board problems before replacing the board. Keep in mind that a TDM-BUS problem is usually the result of a faulty board connected to the backplane or bent pins on the backplane.</p> <ol style="list-style-type: none"> <li>1. Look for EXP-PN and/or EXP-INTF errors in the error log. If present, refer to the EXP-PN and the EXP-INTF Maintenance documentation.</li> <li>2. Look for TDM-BUS errors in the error log. If present, refer to <a href="#">“TDM-BUS (TDM Bus)” on page 5-1116</a>.</li> <li>3. Look for TONE-BD and/or TONE-PT errors in the error log. If present, refer to the TONE-BD and <a href="#">“TONE-PT (Tone Generator)” on page 5-1204</a>.</li> <li>4. Retest when the faults from steps 1, 2, and 3 are cleared. Replace the board only if the test fails.</li> </ol>
	PASS	<p>The port is correctly using its allocated time slots. User-reported troubles on this port should be investigated using other port tests and by examining station, trunk, or external wiring.</p>
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board). This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"> <li>1. Check to ensure that the board translations are correct. Use the <b>llst config</b> command and resolve any problems that are found.</li> <li>2. If the board was found to be correctly inserted in step 1, issue the <b>busyout board</b> command.</li> <li>3. Issue the <b>reset board</b> command.</li> <li>4. Issue the <b>release busy board</b> command.</li> <li>5. Issue the <b>test board long</b> command. This should re-establish the linkage between the internal ID and the port. If this is not the case, check to see that there is a valid board inserted.</li> </ol>

**Conference Circuit Test (#7)**

One or more NPEs reside on each circuit pack with a TDM Bus interface. The NPE controls port connectivity and gain, and provides conferencing functions on a per-port basis. The Conference Circuit Test verifies that the NPE channel for the port being tested can correctly perform the conferencing function. The NPE is instructed to listen to several different tones and conference the tones together. The resulting signal is then measured by a Tone Detector port. If the level of the tone is within a certain range, the test passed.

**Table 5-191. TEST #7 Conference Circuit Test**

Error Code	Test Result	Description/Recommendation
	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals a maximum of 5 times.
1000	ABORT	System resources required to run this test were not available. The port may be busy with a valid call. Use the <b>display port PCSSpp</b> command to determine the trunk group/member number of the port. Use the <b>status trunk</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. You must wait until the port is idle before retesting.  1. If the port status is active but the port is not in use (no calls), check the error log for error type 1025 (see the Error Log table for a description of this error and required actions). The port may be locked up.  2. If the port status is idle, retry the command at 1-minute intervals for a maximum of 5 times.
1002	ABORT	The system could not allocate time slots for the test. The system may be under heavy traffic conditions, or it may have time slots out of service due to TDM-BUS errors. Refer to <a href="#">“TDM-BUS (TDM Bus)” on page 5-1116</a> to diagnose any active TDM-BUS errors.  1. If the system has no TDM-BUS errors and is not handling heavy traffic and the port status is idle, retry the command at 1-minute intervals for a maximum of 5 times.
1003	ABORT	The system could not allocate a tone receiver for the test. The system may be oversized for the number of tone detectors present or some of the tone detectors may be out of service. Issue the <b>list measurements tone-receiver</b> command to display basic information about the system's tone receivers.  1. Look for TTR-LEV errors in the error log. If present, refer to <a href="#">“TTR-LEV (TTR Level)” on page 5-1223</a> .  2. Look for TONE-PT errors in the error log. If present, refer to <a href="#">“TONE-PT (Tone Generator)” on page 5-1204</a> .  3. If neither condition exists, retry the test at 1-minute intervals for a maximum of 5 times.

*Continued on next page*

Table 5-191. TEST #7 Conference Circuit Test — *Continued*

Error Code	Test Result	Description/Recommendation
1004	ABORT	<p>The port was seized by a user for a valid call. Use the <b>display port PCSSpp</b> command to determine the trunk group/member number of the port. Issue the <b>status trunk</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. You must wait until the port is idle before retesting.</p> <ol style="list-style-type: none"><li>1. If the port status is idle, retry the command at 1-minute intervals for a maximum of 5 times.</li></ol>
1018	ABORT	<p>The test was disabled via translation. You may want to determine why the test has been disabled before you enable it.</p> <ol style="list-style-type: none"><li>1. Verify that the 'Maintenance Test' field on the 'Trunk Administration' screen is set to 'n'. To enable the test, change the trunk administration and enter 'y' into the 'Maintenance Test' field.</li><li>2. Repeat the test.</li></ol>
1020	ABORT	<p>The test did not run due to a previously existing error on the specific port or a more general circuit pack error.</p> <ol style="list-style-type: none"><li>1. Examine Error Log for existing errors against this port or the circuit pack and attempt to diagnose the previously existing error.</li></ol>
2000	ABORT	<p>Response to the test request was not received within the allowable time period.</p>
2100	ABORT	<p>Could not allocate the necessary system resources to run this test.</p> <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
2053	ABORT	<p>At least one of the following errors is found on the DS1 circuit pack: 1281—Loss of signal, 1793—Blue Alarm, 2049—Red Alarm, 2305—Yellow Alarm, 1537—Hyperactivity.</p> <p>Look for the above error types in the Hardware Error Log and follow the procedures given in the appropriate DS1-BD or UDS1-BD maintenance documentation for the listed error types.</p>

*Continued on next page*

Table 5-191. TEST #7 Conference Circuit Test — *Continued*

Error Code	Test Result	Description/Recommendation
	FAIL	<p>The NPE of the tested port did not conference the tones correctly. This can cause noisy and unreliable connections.</p> <ol style="list-style-type: none"> <li>1. Enter the <b>list configuration board PCSS</b> command. If the circuit pack is a TN767B vintage 8 or 9, replace the circuit pack with a TN767C V3 or later. The error log may have error type 1281.</li> <li>2. Test all administered trunks on the board. If one fails, this could be an off-board problem (such as an incoming seizure or an off-hook port seizure during the test). Retest the board.</li> <li>3. If all of the ports fail, check the CABINET (see note below).</li> <li>4. If several ports fail, check the error log for TONE-BD or TONE-PT errors. If there are such errors, take the appropriate action. When the TONE errors have cleared, rerun the test.</li> <li>5. If the retry passes and troubles have been reported, coordinate isolation with the CO. Make sure that the switch, the CO, and any NTCE equipment (the CSUs) have the correct administration.</li> <li>6. Replace the circuit pack.</li> </ol> <p><b>⇒ NOTE:</b> If the conference circuit test fails for all ports on a circuit pack, a -5 volt power problem is indicated.</p>
	PASS	<p>The port can correctly conference multiple connections. User-reported troubles on this port should be investigated using other port tests and by examining station, trunk, or external wiring.</p> <p><b>⇒ NOTE:</b> This test always passes for TN742 Analog circuit packs prior to Vintage 4.</p>
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board). This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"> <li>1. Check to ensure that the board translations are correct. Use the <b>llst config</b> command and resolve any problems that are found.</li> <li>2. If the board was found to be correctly inserted in step 1, issue the <b>busyout board</b> command.</li> <li>3. Issue the <b>reset board</b> command.</li> <li>4. Issue the <b>release busy board</b> command.</li> <li>5. Issue the <b>test board long</b> command. This should re-establish the linkage between the internal ID and the port. If this is not the case, check to see that there is a valid board inserted.</li> </ol>

**Port Audit and Update Test (#36)**

This test sends port level translation data from the switch processor to the DS1 Interface circuit pack to assure that the trunk's translation is correct. Translation updates include the following data: trunk type (in/out), dial type, timing parameters, and signaling bits enabled. The port audit operation verifies the consistency of the current state of the trunk as kept in the DS1 Interface circuit pack and in the switch software.

**Table 5-192. TEST #36 Port Audit and Update Test**

Error Code	Test Result	Description/ Recommendation
	ABORT	Internal system error 1. Retry the command at 1-minute intervals a maximum of 5 times.
1000	ABORT	The port may be busy with a valid call. Issue the <b>display port PCSSpp</b> command to determine the trunk group/member number of the port. Use the <b>status trunk</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. You must wait until the port is idle before retesting. 1. If the port status is active but the port is not in use (no calls), check the error log for error type 1025 (see the Error Log table for a description of this error and required actions). The port may be locked up. 2. If the port status is idle, retry the command at 1-minute intervals a maximum of 5 times.
1006	ABORT	The test was aborted because the trunk is out of service. 1. Use the <b>status trunk</b> command to verify that the trunk is out of service. 2. If the trunk is out of service, determine why. 3. If it is OK to put the trunk back in service, issue the <b>release trunk</b> command to put the trunk back in service, and then retry the test.
2000	ABORT	Response to the test was not received within the allowable time period.
2100	ABORT	Could not allocate resources to run this test. 1. Retry the command at 1-minute intervals for a maximum of 5 times.
	FAIL	Test failed due to Internal system error 1. Retry the command at 1-minute intervals a maximum of 5 times.

*Continued on next page*

Table 5-192. TEST #36 Port Audit and Update Test — *Continued*

Error Code	Test Result	Description/ Recommendation
	PASS	<p>Trunk translation has been updated successfully. The current trunk states kept in the DS1 Interface circuit pack and switch software are consistent. If the trunk is busied out, the test does not run, but returns PASS. To verify that the trunk is in-service:</p> <ol style="list-style-type: none"><li>1. Enter <b>status-command</b> to verify that the trunk is in-service. If the trunk is in-service, no further action is necessary. If the trunk is out-of-service, continue to Step 2.</li><li>2. Enter <b>release-trunk</b> command to put trunk back into in-service.</li><li>3. Retry the test command.</li></ol>
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board). This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"><li>1. Check to ensure that the board translations are correct. Use the <b>list config</b> command, and resolve any problems that are found.</li><li>2. If the board was found to be correctly inserted in step 1, issue the <b>busyout board</b> command.</li><li>3. Issue the <b>reset board</b> command.</li><li>4. Issue the <b>release busy board</b> command.</li><li>5. Issue the <b>test board long</b> command. This should re-establish the linkage between the internal ID and the port. If this is not the case, check to see that there is a valid board inserted.</li></ol>

## DID-TRK (DID Trunk)

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run <sup>1</sup>	Full Name of MO
DID-TRK	MAJOR <sup>2</sup>	test port PCSSpp l	DID Trunk
DID-TRK	MINOR	test port PCSSpp l	DID Trunk
DID-TRK	WARNING	test port PCSSpp l	DID Trunk

1. Where P is the port network number (1 for PPN); C is the carrier designation (for example, A, B, or C); and SS is the address of the slot in the carrier where the circuit pack is located (for example, 01, 02, ..., etc.).
2. A MAJOR alarm on a trunk indicates that alarms on these trunks are not downgraded by the **set options** command and that at least 75 percent of the trunks in this trunk group are alarmed.

Direct Inward Dial (DID) trunks coming from the Central Office (CO) allow outside parties to call directly to an extension in the system. DID Trunk circuit packs include:

TN753	United States
TN2146	Belgium and the Netherlands
TN2139	Italy
TN 436	Australia
TN459	United Kingdom

The DID Trunk circuit packs support eight, incoming-only, ports. Each port provides an interface between the 2-wire analog line from the CO and the DEFINITY system. The DID port receives 3 to 5 digits from the CO that is used to directly connect an outside caller to the called station without assistance from an attendant. See [Figure 5-18](#).




Figure 5-18. DID Trunk Interactions

For each call, the CO switch signals the system by opening and closing individual DID loops (one of the eight ports) and causing the starting or stopping of loop current.

A DID trunk operation involves three significant aspects:

1. **Transmission**—deals with the interface requirements regarding all AC signals. Transmission includes gain, analog to digital encoding, and digital to analog decoding.
2. **Signaling**—involves interpretation of DC signals appearing on Tip and Ring to and from the CO. These signals include off-hook, on-hook, and dial pulse detection.
3. **Switch Connection**—involves the connection between the trunk circuitry and the TDM Bus of the system. It operates the switchhook connection to the TDM Bus.

Four tests are implemented to diagnose the health of a DID trunk. All of them test on-board circuitry only. They are:

1. **Looparound and Conference Circuit Test**—verifies the transmission operation of the circuit pack (loop around within the port), and checks the conference capabilities of all ports.

This test may fail due to noise induced by adjacent electric power lines. Customers having this problem should resolve it with their local power company. To temporarily alleviate the alarm caused by the failure of this test, the test may be disabled from trunk administration Test field. (This also disables the port diagnostic test).

2. **NPE Crosstalk Test**—verifies the switch connection operation of the circuit pack. The test also verifies that the trunk circuitry only talks on the selected time slot on the TDM Bus and never crosses over to time slots reserved for other connections.
3. **Port Diagnostic Test**—the battery feed circuitry is tested for hook detection.
4. **Port Audit Update Test**—updates the DID translation information on individual ports of the DID trunk. The port translation data consists of signaling parameters whose values depend on the CO switch connected to the trunk. These parameters include:
  - Wink (signal indicating PBX is ready to receive digits) or immediate start
  - Dial tone or rotary dialing trunk
  - Rotary dialing inter-digit timing
  - Network balance R/RC
  - Disconnect timing

Additional in-line testing is performed while a call is in progress. Thus, in-line errors may occur during operation. See Error Log table for a description of these errors. These errors may be reproduced by using the trunk (that is, placing a call) and checking their occurrence in the Hardware Error Log.

Problems detected during signaling may be caused by faults off-board (in the CO switch or connections) for which a Warning alarm is raised.

Before a maintenance test can be run on a port, the port must be idle. If an incoming call seizes the port which is being tested by maintenance, the test is aborted, and the incoming call proceeds.

For transmission and signaling standard specification, refer to Digital PBX Standards document RS4648.

## Hardware Error Log Entries and Test to Clear Values

Table 5-193. DID Trunk Error Log Entries

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
0 <sup>1</sup>	0	Any	Any	Any	test port PCSSpp sh r 1
1 (a)	Any	None	WRN	OFF	
1 (b)	57476	None	WRN	OFF	
1 (c)	57477	None	WRN	OFF	
1 (d)	57483	None	WRN	OFF	
15 (e)	Any	Port Audit Update (#36)			
18	0	busyout trunk <grp/mbr>	WRN	OFF	release trunk <grp/mbr>
130 (f)		None	WRN	ON	test trunk <grp>/<mbr>
257 (g)	57472	None	WRN	OFF	
257 (h)	57473	None	WRN	OFF	
257 (i)	57474	None	WRN	OFF	
257 (j)	57475	None	WRN	OFF	
513 (k)	57392	None	MAJ/MIN/ WRN <sup>2</sup>	OFF	
510 (l)	57393	None			
769	Any	Port Diagnostic (#35)	MAJ/MIN/ WRN <sup>2</sup>	ON	test port PCSSpp r 3

Continued on next page

Table 5-193. DID Trunk Error Log Entries — *Continued*

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
1025		Loop Around and Conference (#33)	MAJ/MIN/ WRN <sup>2</sup>	ON	test port PCSSpp r 3
1281		NPE Crosstalk (#6)	MAJ/MIN/ WRN <sup>2</sup>	ON	test port PCSSpp r 3
1537	Any	Port Diagnostic (#35)	MAJ/MIN/ WRN <sup>2</sup>	OFF	test port PCSSpp r 3
1793 (m)	57489	None	None		

- Run the Short Test Sequence first. If all tests pass, run the Long Test Sequence. Refer to the appropriate test description and follow the recommended procedures.
- Minor alarms on this MO may be downgraded to Warning alarms based on the values used in the **set options** command. If the Minor alarm is not downgraded by the **set-options** values, the Minor alarm is upgraded to a Major alarm if 75 percent of the trunks in this trunk group are alarmed.

## Notes:

A common trouble on DID trunks, which reports no errors or alarms, occurs when the CO busies out the port (disconnects port). This situation occurs when the CO thinks there are problems with the DID port. In this case, no incoming calls are possible through this port. In addition to complaints received from outside callers trying unsuccessfully to call in, this problem can be diagnosed by listing measurements on lightly used trunks. If a particular port is detected as not in use, a call to the CO is necessary to get the connection back in service.

- This condition occurs when the tone detector times out waiting for digits.
  - Verify trunk administered wink/immediate-start parameter.
  - Verify the dial type.
  - Refer problem to the CO.
- Rotary dial before wink – This condition occurs when the CO starts dialing before the PBX sends wink on a wink-start trunk.
  - Verify trunk administered wink/immediate-start parameter.
  - Refer problem to CO.
- Rotary dial too early – This condition occurs when the CO starts dialing too soon after seizure on an immediate-start trunk.
  - Verify trunk administered wink/immediate-start parameter.
  - Refer problem to CO.

5 Maintenance Objects for DEFINITY ONE  
DID-TRK (DID Trunk)

5-490

- d. Rotary dial pulse during wink – This condition occurs when the CO sends rotary dial digits too soon after seizure on a wink-start trunk.
  - 1 – Verify trunk administered wink/immediate-start parameter.
  - 2 – Refer problem to CO.
- e. This is a software audit error that does not indicate any hardware malfunction. Run the Short Test Sequence and investigate associated errors (if any).
- f. This error type indicates that the circuit pack has been removed or has been insane for more than 11 minutes. To clear the error, reinsert or replace the circuit pack.
- g. Rotary dial pulse on-hook longer than 105 msec – Break between rotary pulses is too long.
  - 1 – Test trunk by performing an incoming test call.
  - 2 – Refer problem to CO.
- h. Rotary dial rate below eight pulses/sec – More than 135 msec between two successive breaks.
  - 1 – Verify trunk administered interdigit-timing parameters.
  - 2 – Refer problem to CO.
- i. Rotary dial rate above 12 pulses/sec – Less than 75 msec between two successive breaks.
  - 1 – Verify trunk administered interdigit-timing parameters.
  - 2 – Refer problem to CO.
- j. Digit detection – Co is starting new rotary dial digit within 150 msec of previous digit.
  - 1 – Verify trunk administered interdigit timing parameters.
  - 2 – Refer problem to CO.
- k. Loop current active – CO not releasing trunk after PBX disconnect. Occurs when the PBX end drops first and the CO does not release the trunk within four minutes.
  - 1 – Verify the interface to the network with a hand telephone set. If calls are placed correctly, then refer problem to the CO.
  - 2 – If unable to place calls or this equipment is not available, check the status on port using the **status trunk** command. If active but not connected, disconnect bridging clips at the network interface. Check status on the trunk. If trunk went idle, then replace clips. If trunk is still active but unable to place calls, refer problem to the CO.

**5 Maintenance Objects for DEFINITY ONE**  
*DID-TRK (DID Trunk)*

5-491

- l. Late CO trunk release – This event only happens after the occurrence of Error Type 513. The CO released the trunk four minutes after the PBX dropped the call. This event decrements the severity (error count) of Error Type 513, or may mean the problem related to Error Type 513 has been fixed.
- 1 – Verify that Error Type 513 does not occur again. Refer to Error 513.
- m. Incomplete Dial timer expired. This error applies only to the TN459. Problem with incoming dialing stream. Refer problem to the CO.
- 

**System Technician-Demanded Tests: Descriptions  
and Error Codes**

---

Always investigate tests in the order presented in the table below when inspecting errors in the system. By clearing error codes associated with the *DID-TRK Loop Around and Conference Circuit Test*, for example, you may also clear errors generated from subsequent tests in the testing sequence.

Order of Investigation	Short Test Sequence	Long Test Sequence	D/ND <sup>1</sup>
NPE Crosstalk Test (#6)		X	ND
Port Diagnostic Test (#35)	X	X	ND
Loop Around and Conference Circuit Test (#33)		X	ND
Port Audit Update Test (#36)	X	X	ND

---

1. D = Destructive; ND = Nondestructive

## NPE Crosstalk Test (#6)

One or more NPEs reside on each circuit pack with a TDM Bus interface. The NPE controls port connectivity and gain, and provides conferencing functions on a per-port basis. The NPE Crosstalk Test verifies that this port's NPE channel talks on the selected time slot and never crosses over to time slots reserved for other connections. If the NPE is not working correctly, one-way and noisy connections may be observed. This test is usually only part of a port's Long Test Sequence and takes about 20 to 30 seconds to complete.

Table 5-194. TEST #6 NPE Crosstalk Test

Error Code	Test Result	Description/ Recommendation
	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals a maximum of 5 times.
1000	ABORT	System resources required to run this test are not available. The port may be busy with a valid call. Use the <b>display port PCSSpp</b> command to determine the station extension, attendant number, or trunk group/member number of the port. Use the <b>status station</b> , <b>status attendant</b> , or <b>status trunk</b> command to determine the service state of the port. (Refer to " <a href="#">status station</a> " on page 4-213 for a description of all possible states.) If the service state indicates that the port is in use, then the port is unavailable for certain tests. You must wait until the port is idle before retesting. Attendants are always in use (off-hook) if the handset is plugged in and the port is not busied out.  1. If the port status is active but the port is not in use (no calls), then check the Error Log for Error Type 513 (see Error Log table for description of this error and required actions). The port may be locked up.  2. If the port status is idle, then retry the command at 1-minute intervals a maximum of 5 times.
1001	ABORT	Could not allocate the necessary system resources to run this test. This could be due to a failure to seize the port.  1. Retry the command at 1-minute intervals a maximum of 5 times.
1002	ABORT	The system could not allocate time slots for the test. The system may be under heavy traffic conditions or it may have time slots out-of-service due to TDM-BUS errors. Refer to " <a href="#">TDM-BUS (TDM Bus)</a> " on page 5-1116 to diagnose any active TDM-BUS errors.  1. If system has no TDM-BUS errors and is not handling heavy traffic, repeat test at 1-minute intervals a maximum of 5 times.

*Continued on next page*

Table 5-194. TEST #6 NPE Crosstalk Test — *Continued*

Error Code	Test Result	Description/ Recommendation
1003	ABORT	<p>The system could not allocate a tone receiver for the test. The system may be oversized for the number of Tone Detectors present or some Tone Detectors may be out-of-service.</p> <ol style="list-style-type: none"> <li>1. Look for TTR-LEV errors in the Error Log. If present, refer to <a href="#">“TTR-LEV (TTR Level)” on page 5-1223</a>.</li> <li>2. Look for TONE-PT errors in the Error Log. If present, refer to <a href="#">“TONE-PT (Tone Generator)” on page 5-1204</a>.</li> <li>3. If neither condition exists, retry the test at 1-minute intervals a maximum of 5 times.</li> </ol>
1004	ABORT	<p>The port was seized by a valid call during the test. The test has been aborted. Use the <b>display port PCSSpp</b> command to determine the station extension, attendant number, or trunk group/member number of the port. Use the <b>status station</b>, <b>status attendant</b>, or <b>status trunk</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. You must wait until the port is idle before retesting. Attendants are always in use (off-hook) if the handset is plugged in and the port is not busied out.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
2000	ABORT	<p>Response to the test request was not received within the allowable time period.</p>
2100	ABORT	<p>Could not allocate the necessary system resources to run this test. This could be due to a failure to seize the port.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
Any	FAIL	<p>This test can fail due to on-board or off-board problems. Off-board problems of concern include EXP-INTF faults, TDM-BUS faults, and faults associated with the tone detectors/tone generators. Clear all off-board problems before replacing the board. Keep in mind that a TDM-BUS problem is usually the result of a faulty board connected to the backplane or bent pins on the backplane.</p> <ol style="list-style-type: none"> <li>1. Look for EXP-INTF errors in the error log. If present, refer to the EXP-INTF Maintenance documentation.</li> <li>2. Look for TDM-BUS errors in the error log. If present, refer to <a href="#">“TDM-BUS (TDM Bus)” on page 5-1116</a>.</li> <li>3. Look for TONE-BD and/or TONE-PT errors in the error log. If present, refer to the TONE-BD Maintenance documentation and <a href="#">“TONE-PT (Tone Generator)” on page 5-1204</a>.</li> <li>4. Test the board when the faults from steps 1, 2, and 3 are cleared. Replace the board only if the test fails.</li> </ol>

*Continued on next page*

Table 5-194. TEST #6 NPE Crosstalk Test — *Continued*

Error Code	Test Result	Description/ Recommendation
	PASS	The port is correctly using its allocated time slots. User-reported troubles on this port should be investigated using other port tests and by examining station, trunk, or external wiring.
0	NO BOARD	The test could not relate the internal ID to the port (no board). <ol style="list-style-type: none"><li>1. Check to ensure that the board translations are correct. Translate the board, if necessary.</li><li>2. Issue the <b>busyout board</b> command.</li><li>3. Issue the <b>reset board</b> command.</li><li>4. Issue the <b>release busy board</b> command.</li><li>5. Issue the <b>test board</b> command. This should re-establish the linkage between the internal ID and the port.</li></ol>

### Looparound and Conference Circuit Test (#33)

This test checks the reflective and non-reflective loop around and conference capabilities of a DID port circuit. The test that uses 404-Hz, 1004-Hz, and 2804-Hz tones is an on-board test only. Each tone is separately transmitted to and from the port (loop around within the port) and verified.

This test may fail due to noise induced by adjacent electric power lines. Customers having this problem should resolve it with their local power company. To temporarily alleviate the alarm caused by the failure of this test, the test may be disabled from trunk administration Test field. (This also disables the port diagnostic test.

Table 5-195. TEST #33 Looparound and Conference Circuit Test

Error Code	Test Result	Description/Recommendation
	ABORT	<p>Could not allocate the necessary system resources to run this test. This could be due to a failure to seize the port.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
1000	ABORT	<p>System resources required to run this test are not available. The port may be busy with a valid call. Use the <b>display port PCSSpp</b> command to determine the station extension, attendant number, or trunk group/member number of the port. Use the <b>status station</b>, <b>status attendant</b>, or <b>status trunk</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. You must wait until the port is idle before retesting. Attendants are always in use (off-hook) if the handset is plugged in and the port is not busied out.</p> <ol style="list-style-type: none"> <li>1. If the port status is active but the port is not in use (no calls), check the Error Log for Error Type 513 (see Error Log table for description of this error and required actions). The port may be locked up.</li> <li>2. If the port status is idle, then retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
1004	ABORT	<p>The port was seized by a valid call during the test. The test has been aborted. Use the <b>display port PCSSpp</b> command to determine the station extension, attendant number, or trunk group/member number of the port. Use the <b>status station</b>, <b>status attendant</b>, or <b>status trunk</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. You must wait until the port is idle before retesting. Attendants are always in use (off-hook), if the handset is plugged in and the port is not busied out.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
1018	ABORT	<p>Test disabled via administration. Verify that the "Maintenance Tests?" field on the Trunk Group Form is set to "n." To enable the test, issue the <b>change trunk-group x</b> command where "x" equals the number of the trunk group to be tested. Then change the entry in the "Maintenance Tests?" field on the form to "y."</p>
2000	ABORT	<p>Response to the test was not received within the allowable time period.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals for a maximum of 5 times.</li> </ol>
2100	ABORT	<p>System resources required to run this test are not available. This may be due to the port being seized.</p> <ol style="list-style-type: none"> <li>1. This abort code is usually associated with tone-clock (TONE-BD, TONE-PT, and TDM-CLK) resources. First, clear any tone errors in the error log.</li> <li>2. Retry the command at 1-minute intervals for a maximum of 5 times.</li> </ol>

Continued on next page

Table 5-195. TEST #33 Looparound and Conference Circuit Test — Continued

Error Code	Test Result	Description/Recommendation
3	FAIL	The nonreflective 1004 Hz tone test of the port failed. An echo was detected from the port. Poor quality transmission was detected to or from the port. The problem may be off-board.
7		The conference capabilities of the port failed. Poor quality transmission was detected to or from the port. The problem may be off-board.
129		The reflective 404-Hz tone test failed. Poor quality transmission was detected to or from the port. The problem may be off-board.
131		The reflective 1004-Hz tone test failed. Poor quality transmission was detected to or from the port. The problem may be off-board.
133		The reflective 2804-Hz tone test failed. Poor quality transmission was detected to or from the port. The problem may be off-board.
		<p> <b>CAUTION:</b>  <i>The port may still be operational, or the fault may be off-board (connections or CO). Off-board problems also include incoming seizures or off-hook port seizures during the test and, perhaps somewhat unlikely, noise induced by adjacent electric power lines. Customers having this problem should resolve it with their local power company to temporarily alleviate the alarm caused by the failure of this test. The test may be disabled from trunk administration 'Test' field. This turns off all testing for that trunk group except for tests 6 and 36.</i></p> <p>Proceed as follows unless power or tone problems are suspected (see note below).</p> <ol style="list-style-type: none"> <li>1. To make sure the problem is on-board, disconnect the port from the far-end and retry the test. Coordinate this with the CO, or do it after busy hours.</li> <li>2. If the retry fails, replace the circuit pack.</li> <li>3. If the retry passes and no troubles have been reported, disable the test in the trunk group administration. If the retry passes and troubles have been reported, coordinate isolation with the CO.</li> </ol> <p>If the loop around and conference circuit test fails for all ports on a circuit pack, a -5 volt power problem is indicated.</p>

*Continued on next page*

Table 5-195. TEST #33 Looparound and Conference Circuit Test — *Continued*

Error Code	Test Result	Description/Recommendation
	PASS	DID Trunk Loop Around and Conference Test is successful. This port is functioning properly. <ol style="list-style-type: none"><li>1. If users are reporting troubles, examine loop connections to the port and refer problem to the CO.</li></ol>
0	NO BOARD	The test could not relate the internal ID to the port (no board). <ol style="list-style-type: none"><li>1. Check to ensure that the board translations are correct. Translate the board, if necessary.</li><li>2. Issue the <b>busyout board</b> command.</li><li>3. Issue the <b>reset board</b> command.</li><li>4. Issue the <b>release busy board</b> command.</li><li>5. Issue the <b>test board</b> command. This should re-establish the linkage between the internal ID and the port.</li></ol>

**Port Diagnostic Test (#35)**

This test checks a port's battery feed circuitry. The battery feed circuitry is tested for on-/off-hook detection, battery shutdown, and battery reversal (WINK) capabilities.

**Table 5-196. TEST #35 Port Diagnostic Test**

Error Code	Test Result	Description/ Recommendation
	ABORT	<p>System resources required to run this test were not available.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
1000	ABORT	<p>System resources required to run this test were not available. The port may be busy with a valid call. Use the <b>display port PCSSpp</b> command to determine the trunk group/member number of the port. Use the <b>status trunk</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. You must wait until the port is idle before retesting.</p> <ol style="list-style-type: none"> <li>1. If the port status is active but the port is not in use (no calls), then check the error log for error type 513 (refer to the Error Log table for a description of this error and required actions). The port may be locked up.</li> <li>2. If the port status is idle, busyout and release the trunk, and then retry the command at 1-minute intervals for a maximum of 5 times.</li> <li>3. If the test continues to abort, check for wiring errors toward the CO which may cause the trunk to lock up.</li> <li>4. If the wiring is OK and the test continues to abort, replace the TN753.</li> </ol>
1004	ABORT	<p>The port was seized by a valid call during the test. The test has been aborted. Use the <b>display port PCSSpp</b> command to determine the station extension, attendant number, or trunk group/member number of the port. Use the <b>status station</b>, <b>status attendant</b>, or <b>status trunk</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. You must wait until the port is idle before retesting. Attendants are always in use (off-hook) if the handset is plugged in and the port is not busy out.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
1018	ABORT	<p>Test has been disabled by trunk group administration. Verify that the <code>Maintenance Tests?</code> field on the Trunk Group Form is set to <b>n</b>. To enable the test, issue the <b>change trunk-group x</b> command where "x" equals the number of the trunk group to be tested. Then change the entry in the <code>Maintenance Tests?</code> field on the form to <b>y</b>.</p>

*Continued on next page*

Table 5-196. TEST #35 Port Diagnostic Test — Continued

Error Code	Test Result	Description/ Recommendation
2000	ABORT	Response to the test request was not received within the allowable time period.
2100	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals a maximum of 5 times.
61446	FAIL	Battery feed test failed. A loop current fault was detected. This is most probably an incoming CO-line problem. This failure code is only reported by the TN2139 Italian DID circuit pack. 1. Check the incoming CO-line for loop current. If none is detected refer the problem to the CO. 2. If the CO-line checks out OK, the failure must be on the DID port. Replace the circuit pack.
61456	FAIL	Battery feed test failed. An on-board problem was detected. This port is out-of-service. 1. Replace circuit pack.
61472	FAIL	Battery feed test failed. A problem with the incoming CO-line was detected. 1. Check the incoming CO-line for proper operation. If warranted, refer the problem to the CO. 2. If the CO-line checks out OK, the failure must be on the DID port. Replace the circuit pack.
	PASS	Current flow was detected for this port. 1. User-reported troubles on this port should be investigated using other port tests and by examining connections. 2. Refer problem to the CO.
0	NO BOARD	The test could not relate the internal ID to the port (no board). 1. Check to ensure that the board translations are correct. Translate the board, if necessary. 2. Issue the <b>busyout board</b> command. 3. Issue the <b>reset board</b> command. 4. Issue the <b>release busy board</b> command. 5. Issue the <b>test board</b> command. This should re-establish the linkage between the internal ID and the port.

**Port Audit Update Test (#36)**

This test sends updates of the DID port translation for all ports on the circuit pack that have been translated. The update is non-disruptive and guards against possible corruption of translation data contained on the circuit pack. No response message is expected from the circuit pack once it receives translation updates. The port translation data includes: wink or immediate start trunk, dial tone or rotary dialing trunk, rotary dialing inter-digit timing, Network balance R/RC, and disconnect timing.

**Table 5-197. TEST #36 Port Audit Update Test**

Error Code	Test Result	Description/ Recommendation
	ABORT	<p>Could not allocate the necessary system resources to run this test.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
1006	ABORT	<p>The port has been placed out of service, perhaps by craft busyout. Use the <b>display port PCSSpp</b> command to determine the trunk group/member number of the port. Use the <b>status trunk</b> command to determine the service state of the port. If the service state indicates that the port is out of service, then the port is unavailable for certain tests. You must wait until the port is in service and idle before retesting.</p> <ol style="list-style-type: none"> <li>1. If the port status is in service and idle, then retry the command at 1-minute intervals for a maximum of 5 times.</li> </ol>
2100	ABORT FAIL	<p>Could not allocate the necessary system resources to run the test.</p> <p>Internal system error</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
	PASS	<p>This test passed. Translation information was successfully updated on the circuit pack.</p> <ol style="list-style-type: none"> <li>1. If signaling troubles are reported (Error Types 1, 257, or 513 in Error Log table), verify translation information for this port.</li> <li>2. Refer problem to the CO. If the trunk is busied out, the test does not run, but returns PASS.</li> </ol> <p>To verify that the trunk is in-service:</p> <ol style="list-style-type: none"> <li>1. Enter <b>status-command</b> to verify that the trunk is in-service. If the trunk is in-service, no further action is necessary. If the trunk is out-of-service, continue to Step 2.</li> <li>2. Enter <b>release-trunk</b> command to put trunk back into in-service.</li> <li>3. Retry the test command.</li> </ol>

*Continued on next page*

Table 5-197. TEST #36 Port Audit Update Test — *Continued*

Error Code	Test Result	Description/ Recommendation
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board).</p> <ol style="list-style-type: none"> <li>1. Check to ensure that the board translations are correct. Translate the board, if necessary.</li> <li>2. Issue the <b>busyout board</b> command.</li> <li>3. Issue the <b>reset board</b> command.</li> <li>4. Issue the <b>release busy board</b> command.</li> <li>5. Issue the <b>test board</b> command. This should re-establish the linkage between the internal ID and the port.</li> </ol>

## DIG-BD (Digital Line Circuit Pack)

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run <sup>1</sup>	Full Name of MO
DIG-BD	MIN	test board PCSS sh	Digital Line Circuit Pack
DIG-BD	WRN	test board PCSS sh	Digital Line Circuit Pack

1. Where P is the port network number (1 for PPN); C is the carrier designation (for example, A, B, or C); and SS is the address of the slot in the carrier where the circuit pack is located (for example, 01, 02, ..., etc.).

Refer to [“XXX-BD \(Common Port Circuit Pack\)” on page 5-1343](#) for circuit pack level errors. See also [“DIG-LINE \(Digital Line\)” on page 5-502](#) for related line information.

## DIG-LINE (Digital Line)

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run <sup>1</sup>	Full Name of MO
DIG-LINE	MINOR	test port PCSSpp l	Digital Line
DIG-LINE	WARNING	test port PCSSpp sh	Digital Line

- Where P is the port network number (1 for PPN); C is the carrier designation (for example, A, B, or C); SS is the address of the slot in the carrier where the circuit pack is located (for example, 01, 02, ..., etc.); and pp is the 2-digit port number (for example, 01).

DIG-LINE maintenance monitors and tests ports on Digital Line circuit packs and the hardware connected to those ports for lines administered as a digital station. These include stations with just a digital voice terminal and stations with a digital voice terminal and a linked data module. Stand-alone data modules, and data adaptors in stand-alone mode, are covered by the PDMODULE and TDMODULE maintenance objects. Circuit pack-level maintenance is covered by DIG-BD whose strategy is described in the [“XXX-BD \(Common Port Circuit Pack\)” on page 5-1343](#). The following circuit packs support digital lines:

Table 5-198. Digital Line Circuit Packs

Code	Ports	Type	Companding	Endpoints
TN754	8	4-wire DCP	mu-law	7400 series digital voice terminals, attendant consoles, 510D personal terminals, MT515 BCTs, DCP data modules
TN754B	8	4-wire DCP	A-law/mu-law	
TN2181	16	2-wire IDCP	A-law/mu-law	
TN2224	24	2-wire IDCP	A-law/mu-law	
TN2136	8	2-Wire IDCP	A-law/mu-law	Data Adaptors (DA), Italtel Digital Telephone Models 1 and 2 (IDT1/2).
TN2181	16	2-wire IDCP	A-law/mu-law	
TN2224	24	2-wire IDCP	A-law/mu-law	

Each digital line port supports two 64 kbps information channels (primary and secondary) and one 8kbps signaling channel. Digital voice terminals always use the primary information channel. Thus only one voice terminal can be connected to each port. The secondary information channel can be used to connect a data terminal via a Digital Terminal Data Module (DTDM) or a Data Adaptor (DA). All other devices currently supported by Digital Line circuit packs communicate on the primary information channel. Figure 10-26 shows examples of digital line connectivity.

Only the TN754B or TN2136 should be used in out-of-building applications. For important information pertaining to protection required for out-of-building digital voice terminals, see *DEFINITY Enterprise Communications Server Release 8 Installation and Test for Single-Carrier Cabinet*, (555-230-894).

It should be noted that TN2181 and TN2224 support both modes as shown in [Figure 5-19](#) and [Figure 5-20](#).




Figure 5-19. Digital Line Connectivity




Figure 5-20. Digital Line Connections

Only 2-wire Italtel Digital Telephone Models 1 and 2 (IDT1/2) or DAs can be directly connected to a TN2136. Lucent DCP (4-wire) digital voice terminals and data modules can be connected to these circuit packs via Italtel's 2/4-wire adapter. DAs can operate in either of two modes which are covered by different maintenance objects:

DA Mode	Administered as:	Endpoint	Maintenance Object
Stand-alone	PDM	Data endpoint only	PDMODULE
Linked	DTDM	IDT1/2 and optional data terminal	DIG-LINE

Digital Line maintenance interacts with Digital Line circuit pack (DIG-BD) maintenance, and results of DIG-LINE testing can be affected by the health of the Digital Line circuit pack. Keep this in mind when investigating reported Digital Line problems.

There are instances where the service state of a station is mentioned. It is helpful to understand what is meant by the different service states that may exist. The different service states which apply to digital line station are explained as follows.:

Out-of-Service	The port, and thus the station, have been removed from service. Busyouts put the port in the out-of-service state.
Ready-for-Service	The port on the circuit pack has been put into service, but the voice terminal has not yet established signaling communications with the port.
In-Service	The voice terminal has established signaling communications with the port, and the system is ready to process calls to and from that station. A terminal in the ready-for-service state will progress to the in-service state if it is functioning normally. It can also be forced into the in-service state by going off-hook.

## Downloading of Terminal Parameters

---

### Programmable Terminals

The following information is presented as background information to help understand how maintenance software interacts with terminal parameter downloading.

#### Terminal Types:

The following terminals can be downloaded:

- a. 84xx multibutton digital voice terminals (8403D01A, 8410B, 8410D02A, 8434D01A) with optional expansion module.
- b. 603A1 and 603D1 Callmaster terminals for telemarketing applications.
- c. 302B1 attendant console.

### Circuit Packs

1. 8400x, 302B1 Terminals
  - a. TN754 (4-wire, Mu-law)  
**Minimum usable vintage for 8410D and 8434D terminals - V11**
  - b. TN754B (4-wire, A-law/Mu-law selectable)
  - c. TN2181 (2-wire, 16-port, A-law/Mu-law selectable)
  - d. TN2224 (2-wire, 24-port, A-law/mu-law selectable)
2. 603A1/D1 Terminals
  - a. TN754 (4-wire, Mu-law),
  - b. TN754B (4-wire, A-law/Mu-law selectable)

## Downloadable Terminal Parameters

The following parameters are downloaded to programmable terminals:

**Table 5-199. Downloadable Parameters**

Parameter	Scope	Terminal
International Flags (A-law/Mu-law, Display Mode, DLI Voltage level)	System level	84xx, 603x, 302B1
Primary Levels (Transmission & Sidetone)	System level	84xx, 603x, 302B1
Adjunct Levels (Transmission & Sidetone)	System level	84xx
Handset Expander Option	System level	84xx
Administrable Options (Speakerphone & Mute Button)	Per-terminal	84xx
Administrable Softkeys	Per-terminal, System level	8410D, 8434D

## Nonvolatile Memory

Nonvolatile memory is used to store downloadable parameters in programmable terminals. Therefore, once the terminal has been downloaded, it is not necessary to download it again, even if power is removed from the terminal.

If the nonvolatile memory fails with power still present, the terminal reverts to its default factory settings except for its A-law/mu-law companding settings which are stored in RAM. If power is removed after the nonvolatile memory fails, the terminal reverts to its factory default settings.

Mu-law companding is assigned as a default setting at the factory, so for domestic use, a programmable terminal can place calls, even though it has not been downloaded from the PBX.

## Download Actions

There are several different scenarios that cause a terminal to be downloaded. As described below, these can occur as part of background maintenance activity or on demand from the System Access Terminal or from a station.

For the background actions described below, the terminal will be downloaded automatically if a download retry flag for the terminal is set in software. This flag is set at the time translation is loaded at boot time, when translation which affects the parameters of a terminal is changed as part of system administration actions, and when a port is inserted in software as a result of board insertion or translation change.

## Automatic Download Actions

### 1. System Reboot/Restart

A global download action is started when periodic maintenance tests start after a system reboot/restart regardless of whether the parameters have been downloaded previously.

### 2. Periodic Tests

If the download flag is still set when periodic tests are run on a terminal, a download action will occur. This operation is required in case a terminal could not be downloaded previously because it was off-hook at the time the system first booted or because the terminal was off-hook at the time translation associated with downloadable parameters was changed.

Note that it may take more than an hour for periodic tests to reach the terminal that needs to be downloaded.

### 3. Terminal Administration

A downloadable terminal is automatically downloaded when translation changes associated with downloadable parameters are made as part of system administration. As shown in Table 10-128, these changes can be for a specified terminal or may be system-wide. If the change is for system-level parameter, a background global update request is made to download all programmable terminals.

This global update may take more than an hour for a system with several thousand programmable terminals.

### 4. Port Insertion

Whenever maintenance software initiates a request to place a port into service, a terminal download action is started on that terminal if that terminal is programmable. This port insertion action occurs under the following circumstances:

- a. A digital line circuit pack that is physically inserted into the system has ports currently administered for programmable terminals.

If more than 20 port insertion requests are received within a few seconds, a global download request is started up as a background task. This action updates all programmable terminals instead of just those being inserted. This is done to avoid system overload for situations where there is massive board insertion.

- b. A station port is added to the system by a “**add station**” or “**change station**” command.
- c. A TTI port is activated.

## 5. Audits

As part of periodic maintenance, the hardware status audit test queries programmable terminals to determine which levels and/or options are being used. If the reported values are not equal to the administered values, the system will initiate a terminal download action. This audit does NOT check the parameters used for softkeys.

## 6. Activation of TTI

A terminal is downloaded automatically when it is activated using the Terminal Translation Initialization feature. Therefore, no special user actions are required for TTI.

### NOTE:

Plugging the station cord into a terminal does not automatically cause the terminal to be downloaded. If this terminal has factory defaults or if the terminal has been previously downloaded with parameters different than those desired, use one of the demand download actions described below to download the terminal.

## Demand Download Actions

### 1. Busyout/Release Command

A maintenance demand busyout/release request for a station will cause the terminal to be downloaded regardless of its previous download status.

### 2. Feature Access Code

A Refresh Terminal Parameters Feature Access Code can be used to request a terminal download action. When this code is followed by a “#”, the programmable parameters for the current terminal are downloaded when the terminal goes on hook. When this code is followed by an extension, the programmable parameters for the specified station are downloaded.

This Refresh Terminal Parameters Feature Access Code is assigned on the second page of the “feature-access-codes” screen.

A confirmation is returned if the download request is accepted. A busy tone is returned if the request is made from a different station when the target station is off-hook.

The first three green call appearance LEDs on the 84xx 603x terminal will be turned on for three seconds if the station was successfully downloaded as a result of an entry of a Refresh Terminal Parameters Facility Access Code. This is not true for the 302B1 terminal.

There is no visible display on a station for the other background or demand download actions. As described below, the “status station” and “status attendant” screens can be used to check the download status of a specified terminal.

## Status of Parameter Downloads

The “status station” and “status attendant” screens display the current download status of individual 84xx, 603, and 301B1 terminals in the Download Status field. The possible download states are:

Table 5-200. Terminal Download Status

Status	Terminal Down Load State
Complete	Terminal successfully downloaded sometime in the past.
Pending	System waiting to download the terminal. This may require the execution of a background periodic test which could take more than an hour. A demand download as described above may also be used to initiate an immediate download.
Not Applicable	Not a programmable terminal.

Possible reasons for terminal being not downloaded include:

- Terminal is off-hook.
- Terminal detected a bad checksum.
- Terminal detected a bad or missing EEPROM (refer to hardware error log).
- Terminal is busy programming data from a previous PROGRAM message.
- Terminal is in the Programming Disabled state.
- Terminal is in the Local Program Options Mode.
- Terminal is disconnected or out of service (use **status station** command).

## Hardware Error Log Entries and Test to Clear Values

Table 5-201. DIG-LINE Error Log Entries

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
0 <sup>1</sup>	0	Any	Any	Any	test port PCSSpp sh r 1
1 (a)	40987	None	WARNING	OFF	
1 (b)	1 to 20	None	WARNING	OFF	
18 (c)	0	busyout port PCSSpp	WARNING	OFF	rel port PCSSpp
130 (d)		None	WARNING	ON	test port PCSSpp sh
257 (e)	40971	None			

Continued on next page

5 Maintenance Objects for DEFINITY ONE  
DIG-LINE (Digital Line)

5-510

Table 5-201. DIG-LINE Error Log Entries — *Continued*

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
513	0	Station (Digital) Audits Test (#17)	WARNING(o)	OFF	test port PCSSpp sh r 6
767 (f)	40964	None	WARNING	OFF	
769 (g)	40963 40988	None	WARNING	OFF	
1026(o)		NONE	WARNING	OFF	
1281	Any	Station (Digital) Audits Test (#17)	WARNING	OFF	test port PCSSpp sh r 4
1537 (h)	40968	None	WARNING	OFF	
1793		Voice & Ctrl. Local Loop Test (#13)	MINOR/ WARNING <sup>2</sup>	ON	test port PCSSpp l r 3
2049		NPE Crosstalk Test (#9)	MINOR/ WARNING <sup>3</sup>	ON	test port PCSSpp l r 3
2304 (n)		None			
2305 (i)	32770	None			
2305 (h)	40967	None			
2817 (p)	Any	None		OFF	
3840 (k)	40965	None			
3840 (l)	40989	None			
3841 (m)	41029	None			

1. Run the Short Test Sequence first. If all tests pass, run the Long Test Sequence. Refer to the appropriate test description and follow the recommended procedures.
2. Major alarms on this MO may be downgraded to Warning alarms based on the value used in the set options command.
3. Major alarms on this MO may be downgraded to Warning alarms based on the value used in the set options command.

Notes:

- a. Could experience a noisy port or link. This is an off-board problem detected by the port circuit. Check for defective wiring, a defective voice terminal, or move voice terminal closer to the switch (in terms of feet of wire from the jack to the switch). If the problem still exists, replace the circuit pack. Once the problem has been resolved, the alarm will be retired after a predetermined amount of time.
- b. This Error Type and Aux Data will occur when at least 15 off-board problems have been detected with the link to the terminal. When an error with the link is detected, an on-board counter is incremented.

The user could experience a noisy port or link. This is an off-board problem detected by the port circuit. Check for defective wiring, a defective voice terminal, or move voice terminal closer to the switch (in terms of feet of wire from the jack to the switch). If the problem still exists, replace the circuit pack. Once the problem has been resolved, the alarm will be retired after a predetermined amount of time.

- c. This error type is logged when the port in question is busied out by maintenance personnel. Make sure port is released from busyout via the **release port PCSSpp** command.
- d. This error type indicates that the circuit pack has been removed or has been insane for more than 21 minutes. To clear the error, reinsert or replace the circuit pack.
- e. Problems transmitting to the voice terminal. This problem can be caused by defective wiring. Defective wiring can cause varying degrees of problems on different types of sets. Sets such as the 7410 appear to be more susceptible to wiring problems than other sets. This is usually an on-board problem and can be ignored if no user complaints are received.
- f. This is an in-line event that produces this error type when a favorable response is received from running the Digital Line Electronic Power Feed Test (#11). No craft action is necessary. This alarm will be resolved with the passing of time.
- g. With Aux Data 40963, this error type is a result of an unfavorable response to the Electronic Power Feed/ Positive Temperature Coefficient Test (#11). With Aux Data 40988, this error type indicates that the EPF/PTC circuit has been turned off due to an overcurrent condition.

For TN754 vintage 13 or earlier, the EPF circuit senses an overcurrent condition at the voice terminal. Check for a short in the wiring, a damaged jack, an incorrect type of voice terminal, or a defective voice terminal.

For TN754 vintage 14 or later, TN754B and TN2136, the PTC will open if there is a short on the power line for 1/2 second or longer. The voice terminal is probably not operating properly. Unplug the voice terminal for 30 seconds and then plug it back in. If the voice terminal still does not operate, then check for a short in the wiring, a damaged jack, an incorrect type of voice terminal, or a defective voice terminal.

Once the problem has been resolved, it may take up to 1 hour for the alarm to clear due to "leaky bucket" strategy. If the problem cannot be resolved by one of the steps above, then replace the circuit pack.

- h. An in-line maintenance error has generated an off-board warning due to some problem with the link to the voice terminal. This can be ignored if no user complaints are received. Otherwise, make sure the voice terminal is connected, check for defective wiring, check for a defective voice terminal, and move voice terminal to a jack that is closer to the switch (in terms of feet of wiring between the jack and the switch). If the problem still exists, replace the circuit pack. Once the problem has been resolved, the alarm will be retired after a predetermined amount of time.

**5** Maintenance Objects for DEFINITY ONE  
*DIG-LINE (Digital Line)*

5-512

- i. This indicates that the station went off-hook while it was in the ready-for-service state. Use the **status station** command to determine the state of the station. The off-hook should have moved the station to ready-for-service. No craft action is necessary.
  - j. This is the code that is generated when the link between the circuit pack and the voice terminal is successfully reset. No craft action is necessary.
  - k. No terminal is connected to the Digital Line board. No maintenance action is required.
  - l. An uplink message has been logged indicating that the Electric Power Feed (EPF) is on with no load on it. No action is necessary.
  - m. The circuit pack's message buffer is full. This may be caused by having many display phones with heavy traffic connected to the circuit pack. No action is necessary.
  - n. Internal system error. No action is necessary.
  - o. There is a problem with the voice terminal EEPROM. When the voice terminal is repaired the alarm will be resolved with the passing of time.
  - p. Port Level Hyperactivity: 50 or more CCMS uplink messages received from Port within 10 seconds. The user is taken out of service for a short interval of time (default) 30 seconds).
- 

**System Technician-Demanded Tests: Descriptions  
and Error Codes**

---

Always investigate tests in the order presented in the table below when inspecting errors in the system. By clearing error codes associated with the *Voice and Control Channel Local Loop Around Test*, for example, you may also clear errors generated from other tests in the testing sequence.

Table 5-202. System Technician-Demanded Tests: DIG-LINE

Order of Investigation	Short Test Sequence	Long Test Sequence	D/ND <sup>1</sup>
Digital Terminal Remote Loop Around Test (#1201)		X	D
Voice and Control Channel Local Loop Around Test (#13)		X	ND
Digital Line NPE Crosstalk Test (#9)		X	ND
Digital Line Electronic Power Feed Test (#11)		X	ND
DIG-LINE Station Lamp Updates Test (#16)	X	X	ND
Station (Digital) Audits Test (#17)	X	X	ND

1. D = Destructive, ND = Non-destructive

### Digital Terminal Remote Loop Around Test (#1201)

This test checks the integrity of the connection between the SPE and the attached Digital Terminal and the ability of the terminal and the associated port to send and receive data. This test is based, in principal, on procedure 622 used in system 85 to help isolate digital terminal problems.

A request is presented to the terminal to go into loop back mode. Then data is sent to the terminal and when received back, checked for consistency. This test is run as a part of the craft command "test long" procedure. It is not included in any error recovery strategy and generates no Error Log entries or alarms. To begin the test, Maintenance will ask Call Processing to make the associated end point and port "Maintenance Busy". This test will succeed if the endpoint is "idle". If the reserve request fails then the test will abort. If the request succeeds then the SPE sends a message to loop around both information channels for the digital terminal. First the primary information (voice, Information Channel 1 or I1) channel loop back test is run. The test is performed by sending a digital count from the Tone/Clock circuit pack on the primary information channel time slot and receiving the same digital count with a general purpose tone detector.

If the primary information channel test is successful, the loop around test for the secondary information (data, Information Channel 2 or I2) channel is then performed. This test is the same as the primary information channel loop around test and is performed only if a DTDM is administered, which is also the case for a linked DA.

5 Maintenance Objects for DEFINITY ONE  
DIG-LINE (Digital Line)

5-514

Only one value (Pass, Fail, or Abort) is generated as a result of the two tests run. If any test fails aborts, the sequence is stopped. Upon completion of this test the associated endpoint and port are moved back into the previous service state.

Table 5-203. TEST #1201 Digital Terminal Remote Loop Around Test

Error Code	Test Result	Description/ Recommendation
	ABORT	Internal system error 1. Retry the command at 1-minute intervals a maximum of 5 times.
1000	ABORT	System resources required to run this test are not available. The port may be busy with a valid call. Use the <b>display port PCSSpp</b> command to determine the station extension or attendant number of the port. Use <b>status station</b> or <b>status attendant</b> to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain test. You must wait until the port is idle before re-testing. Attendants are always in use (off-hook) if the handset is plugged in and the port is not busied out. 1. If the port status is idle, then retry the command at 1-minute intervals a maximum of 5 times.
1001	ABORT	System resources required to run this test are not available. 1. If the port status is idle, then retry the command at 1-minute intervals a maximum of 5 times.
1002	ABORT	The system could not allocate time slots for the test. The system may be under heavy traffic conditions or it may have time slots out-of-service due to TDM-BUS errors. Refer to " <a href="#">TDM-BUS (TDM Bus)</a> " on page 5-1116 to diagnose any active TDM-BUS errors. 1. If the system has no TDM-BUS errors and is not handling heavy traffic, repeat test at 1-minute intervals a maximum of 5 times.
1003	ABORT	The system could not allocate a tone receiver for the test. The system may be oversized for the number of Tone Detectors present or some Tone Detectors may be out of service. 1. Look for TTR-LEV errors in the Error Log. If present refer to " <a href="#">TTR-LEV (TTR Level)</a> " on page 5-1223. 2. Look for TONE-PT errors in the Error Log. If present, refer to " <a href="#">TONE-PT (Tone Generator)</a> " on page 5-1204. 3. If neither condition exist, retry the command at 1-minute intervals a maximum of 5 times.

Continued on next page

Table 5-203. TEST #1201 Digital Terminal Remote Loop Around Test — *Continued*

Error Code	Test Result	Description/ Recommendation
1004	ABORT	The port was seized by a valid call during the test. The test has been aborted. Use the <b>display port</b> PCSSpp command to determine the station extension or attendant number of the port. Use <b>status station</b> or <b>status attendant</b> to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain test. You must wait until the port is idle before resetting. Attendants are always in use (off-hook) if the handset is plugged in and the port is not busied out. <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
1005	ABORT	The installed circuit pack does not support this operation.
2000	ABORT	Response to the test request was not received within the allowable time period. <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
2100	ABORT	System resources required to run this test are not available. <ol style="list-style-type: none"> <li>1. Make sure terminal is connected and repeat test.</li> <li>2. If test fails replace terminal and repeat test.</li> <li>3. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
14	FAIL	The primary channel (voice, Information Channel 1 or I1) is not operating properly. User impact may range from noticing nothing to not being able to use the port. Check the results of Voice and Control Channel Local Loop Test (#13). If that test fails, suspect the Digital Line circuit pack. If that test passes then replace the terminal. If both tests fail and component replacement does not change the results, then: <ol style="list-style-type: none"> <li>1. Run circuit pack tests to check the tone generator circuit pack and the Tone Detector circuit pack using the <b>test board PCSSpp</b> command.</li> <li>2. Resolve any problems that are detected on the Tone Generator circuit pack or Tone Detector circuit pack.</li> <li>3. If the Tone Generator and Tone Detector circuit pack are functioning properly, and the tests still fail, escalate the problem.</li> </ol>
1015	ABORT	The system will not allow this test to be run because the station is/has not been busied out. Busy out the station with the <b>busyout station</b> command.

*Continued on next page*

Table 5-203. TEST #1201 Digital Terminal Remote Loop Around Test — Continued

Error Code	Test Result	Description/ Recommendation
16	FAIL	<p>The secondary channel (data Information Channel 2 or I2 is not operating properly. User impact may range from noticing nothing to not being able to use this terminal. Check the results of Voice and Control Channel Local Loop Test (#13). If that test fails, suspect the Digital Line circuit pack. If that test passes then replace the terminal. If both test fail, and component replacement does not change the results, then:</p> <ol style="list-style-type: none"><li>1. Run circuit pack tests to check the tone generator circuit pack and the Tone Detector circuit pack using the <b>test board PCSSpp</b> command.</li><li>2. Resolve any problems that are detected on the Tone Generator circuit pack or Tone Detector circuit pack.</li><li>3. If the Tone Generator and Tone Detector circuit pack are functioning properly, and the tests still fail, escalate the problem.</li></ol>
	PASS	<p>Voice and Control Channel Local Loop test passed. All channels are transmitting properly.</p> <ol style="list-style-type: none"><li>1. To be sure that this is not an intermittent problem, repeat this test up to a maximum of ten times to make sure it continues to pass.</li><li>2. If complaints persist (noisy connections for voice, corrupted data transfer for data), examine the station, connections, and wiring.</li></ol>

### Digital Line NPE Crosstalk Test (#9)

One or more Network Processing Elements (NPEs) reside on each circuit pack with a TDM Bus interface. The NPE controls port connectivity and gain, and provides conferencing functions on a per-port basis. The NPE Crosstalk Test verifies that this port's NPE channel talks on the selected time slot and never crosses over to time slots reserved for other connections. If the NPE is not working correctly, one-way and noisy connections may be observed. This test is part of a port's Long Test Sequence and takes about 20 to 30 seconds to complete. Crosstalk testing is performed on both the primary information channel (voice) and the secondary information channel (data) associated with each digital station port. If this test fails on either channel, the station and the DTDM are taken out-of-service.

Table 5-204. TEST #9 Digital Line NPE Crosstalk Test

Error Code	Test Result	Description/Recommendation
1	ABORT	<p>During testing of the primary information channel, system resources may not have been available. Also, the port may have been busy during the test.</p> <ol style="list-style-type: none"> <li>1. Check the port status. Use the <b>display port PCSSpp</b> command to determine the station extension of the port. Use the <b>status station</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for this test. You will have to wait until the port is idle.</li> <li>2. If the port status is idle, then retry the command a 1-minute intervals a maximum of 5 times.</li> </ol>
2	ABORT	<p>During testing of DTDM, system resources may not have been available. Also, the port may have been busy during the test.</p> <ol style="list-style-type: none"> <li>1. Check if port is being used. If possible, disconnect by toggling disconnect button on DTDM. Retry command after 1 minute.</li> </ol> <p> <b>WARNING:</b> <i>This action will drop the call in progress.</i></p>
1000	ABORT	<p>System resources required to run this test are not available. The port may be busy with a valid call. Use <b>display port PCSSpp</b> to determine the station extension or attendant number of the port. Use <b>status station</b> or <b>status attendant</b> to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. You must wait until the port is idle before retesting. Attendants are always in use (off-hook) if the handset is plugged in and the port is not busied out.</p> <ol style="list-style-type: none"> <li>1. If the port status is idle, then retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
1001	ABORT	<p>System resources required to run this test are not available.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
1002	ABORT	<p>The system could not allocate time slots for the test. The system may be under heavy traffic conditions or it may have time slots out-of-service due to TDM-BUS errors. Refer to <a href="#">"TDM-BUS (TDM Bus)" on page 5-1116</a> to diagnose any active TDM-BUS errors.</p> <ol style="list-style-type: none"> <li>1. If system has no TDM-BUS errors and is not handling heavy traffic, repeat test at 1-minute intervals a maximum of 5 times.</li> </ol>

Continued on next page

5 Maintenance Objects for DEFINITY ONE  
DIG-LINE (Digital Line)

5-518

Table 5-204. TEST #9 Digital Line NPE Crosstalk Test — *Continued*

Error Code	Test Result	Description/Recommendation
1003	ABORT	<p>The system could not allocate a tone receiver for the test. The system may be oversized for the number of Tone Detectors present or some Tone Detectors may be out-of-service.</p> <ol style="list-style-type: none"> <li>1. Look for TTR-LEV errors in the Error Log. If present, refer to <a href="#">“TTR-LEV (TTR Level)” on page 5-1223</a>.</li> <li>2. Look for TONE-PT errors in the Error Log. If present, refer to <a href="#">“TONE-PT (Tone Generator)” on page 5-1204</a>.</li> <li>3. If neither condition exists, retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
1004	ABORT	<p>The port was seized by a valid call during the test. The test has been aborted. Use <b>display port PCSSpp</b> to determine the station extension or attendant number of the port. Use <b>status station</b> or <b>status attendant</b> to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. You must wait until the port is idle before retesting. Attendants are always in use (off-hook) if the handset is plugged in and the port is not busied out.</p>
1020	ABORT	<p>Test disabled via background testing. Use <b>status station</b> command to determine when station is available for testing.</p>
2000	ABORT	<p>Response to the test request was not received within the allowable time period.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
1 2	FAIL	<p>The Network Processing Element (NPE) of the tested port was found to be transmitting in error. This will cause noisy and unreliable connections. Failure code 1 indicates that the Crosstalk test failed on the primary channel. Failure code 2 indicates that the Crosstalk test failed on the secondary channel.</p> <ol style="list-style-type: none"> <li>1. Replace circuit pack.</li> </ol>
	PASS	<p>The port is correctly using its allocated time slots.</p> <ol style="list-style-type: none"> <li>1. To be sure that this is not an intermittent problem, repeat this test up to a maximum of 10 times to make sure it continues to pass.</li> <li>2. If complaints persist, examine the station, connections, and wiring.</li> </ol>

## Digital Line Electronic Power Feed/Positive Temperature Coefficient/PPF Test (#11)

For TN754 vintage 13 or earlier, this is an Electronic Power Feed (EPF) restoral test. In this test, the processor requests that the EPF be turned on for a given port, and an attempt is made to turn on the power supply to the station. If no current is drawn, the station is probably not connected. If an overcurrent condition is sensed, there may be a short in the loop. A message is returned reporting that either the EPF was successfully turned on, or that an overcurrent condition was sensed. This test is repeated again 5 seconds later.

For TN754 vintage 14 or later, TN754B and TN2136 this is a Positive Temperature Coefficient (PTC) restoral test. In this test, the processor requests that the PTC be turned on for a given port, and an attempt is made to turn on the power supply to the station. If an overcurrent condition is sensed, there is probably a short on the power line that causing the PTC to open and disconnect the voice terminal. Since the PTC does not have self-restoral capability, the voice terminal must be manually unplugged for 30 seconds and then plugged back in to restore the PTC. A message is returned reporting that either the PTC was successfully turned on successfully with no problem or an overcurrent condition was sensed. This test is repeated again 5 seconds later.

TN2181 and TN2224 boards carry a Protected Power Feed (PPF) relays, one for each port. Therefore this will be a Protected Power Feed restoral test. The test procedure and its response is same as that of EPF. One of differences between EFP and PPF is that, if the port goes into a overcurrent state, PPF does not report this change of state because it is a transient state which will not last more than 50ms. If the over current persists, the power shuts off automatically and an EPF\_off\_overcurrent message is sent uplink.

Table 5-205. TEST #11 Digital Line Electronic Power Feed Test

Error Code	Test Result	Description/ Recommendation
	ABORT	Internal System Error  1. Retry the command at 1-minute intervals a maximum of 5 times.
1000	ABORT	System resources required to run this test are not available. The port may be busy with a valid call. Use <b>display port PCSSpp</b> to determine the station extension or attendant number of the port. Use <b>status station</b> or <b>status attendant</b> to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. You must wait until the port is idle before retesting. Attendants are always in use (off-hook) if the handset is plugged in and the port is not busied out.  1. If the port status is idle, then retry the command at 1-minute intervals a maximum of 5 times.

Table 5-205. TEST #11 Digital Line Electronic Power Feed Test — *Continued*

Error Code	Test Result	Description/ Recommendation
	FAIL	Internal system error <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
	PASS	Electronic Power Feed Test passed. The message to turn on the power to the station was successfully sent to the port. <ol style="list-style-type: none"><li>1. Although this test will never actually return a FAIL result except for the Internal system error (naught/FAIL) described above, it will log an error indicating the real results of the test. Check the Error Log for any entries with Error Types 767 or 769 after the test completes.</li><li>2. If Error Type 767 appears in the Error Log, this should indicate that the test sensed no problems with the power to the station. To verify that the station is powered up correctly, run a self-test on the station, if available, and check that all the feature buttons are operating.</li><li>3. If Error Type 769 appears in the Error Log, this indicates some problem with the power to the station. Check for a short in the wiring, a damaged jack, a defective voice terminal, or an incorrect type of terminal.</li></ol>

### Voice and Control Channel Local Loop Test (#13)

These tests check the information and control channels between the Switch Processing Element (SPE) and the Digital Line port circuit. The SPE sends a message to loop around both the information and control channels for the port. First, the primary information (voice) channel loop back test is run. The test is performed by sending a digital count from the Tone-Clock circuit pack on the primary information channel time slot and receiving the same digital count with a general purpose Tone Detector.

While the primary information channel is still looped around, the Control Channel Loop Around Test is performed. This test consists of sending four different transparent patterns to the on-board microprocessor, receiving them back, and comparing them.

The Loop Around Test for the secondary information (data) channel is then performed. This test is the same as the primary information channel loop around test and is performed only if a DTDM is administered.

A Conference Test is done next for the primary information channel. This test is the same as Conference Test #6.

5 Maintenance Objects for DEFINITY ONE  
DIG-LINE (Digital Line)

5-521

Only one value (Pass, Fail, or Abort) is generated as a result of four tests run. If any test fails or aborts, the sequence is stopped.

Table 5-206. TEST #13 Voice and Control Channel Local Loop Test

Error Code	Test Result	Description/ Recommendation
	ABORT	Internal system error <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
1000	ABORT	System resources required to run this test are not available. The port may be busy with a valid call. Use <b>display port PCSSpp</b> to determine the station extension or attendant number of the port. Use <b>status station</b> or <b>status attendant</b> to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. You must wait until the port is idle before retesting. Attendants are always in use (off-hook) if the handset is plugged in and the port is not busied out. <ol style="list-style-type: none"><li>1. If the port status is idle, then retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
1001	ABORT	System resources required to run this test are not available. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
1002	ABORT	The system could not allocate time slots for the test. The system may be under heavy traffic conditions or it may have time slots out-of-service due to TDM-BUS errors. Refer to " <a href="#">TDM-BUS (TDM Bus)</a> " on page 5-1116 to diagnose any active TDM-BUS errors. <ol style="list-style-type: none"><li>1. If system has no TDM-BUS errors and is not handling heavy traffic, repeat test at 1-minute intervals a maximum of 5 times.</li></ol>
1003	ABORT	The system could not allocate a tone receiver for the test. The system may be oversized for the number of Tone Detectors present or some Tone Detectors may be out-of-service. <ol style="list-style-type: none"><li>1. Look for TTR-LEV errors in the Error Log. If present, refer to "<a href="#">TTR-LEV (TTR Level)</a>" on page 5-1223.</li><li>2. Look for TONE-PT errors in the Error Log. If present, refer to TONE-PT (Tone Generator) Maintenance documentation.</li><li>3. If neither condition exists, retry the command at 1-minute intervals a maximum of 5 times.</li></ol>

*Continued on next page*

Table 5-206. TEST #13 Voice and Control Channel Local Loop Test — *Continued*

Error Code	Test Result	Description/ Recommendation
1004	ABORT	<p>The port was seized by a valid call during the test. The test has been aborted. Use <b>display port PCSSpp</b> to determine the station extension or attendant number of the port. Use <b>status station</b> or <b>status attendant</b> to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. You must wait until the port is idle before retesting. Attendants are always in use (off-hook) if the handset is plugged in and the port is not busied out.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
2000	ABORT	Response to the test request was not received within the allowable time period.
2100	ABORT	<p>Could not allocate the necessary system resources to run this test.</p> <ol style="list-style-type: none"> <li>1. Rerun the test at 1-minute intervals a maximum of 5 times.</li> </ol>
7	FAIL	Conference Test failed on primary channel. In some cases, users may not notice disruption in service. In extreme cases, conferencing feature may not work at all.
14	FAIL	The primary voice channel is not transmitting properly. User impact may range from noticing nothing to not being able to use this port.
15	FAIL	The control channel between the processor and digital circuit pack is not transmitting properly. User impact may range from noticing nothing to not being able to use the port. Could also be disruptive to other users.
16	FAIL	<p>The secondary voice channel is not transmitting properly. User impact may range from noticing nothing to not being able to use this port.</p> <ol style="list-style-type: none"> <li>1. Run circuit pack tests to check the Tone Generator circuit pack and the Tone Detector circuit pack using the <b>test board PCSSpp</b> command.</li> <li>2. Resolve any problems that are detected on the Tone Generator circuit pack or Tone Detector circuit pack.</li> <li>3. If the Tone Generator and Tone Detector circuit packs are functioning properly, and the test still fails, replace the Digital Line circuit pack.</li> </ol>
	PASS	<p>Voice and Control Channel Local Loop test passed. All channels are transmitting properly.</p> <ol style="list-style-type: none"> <li>1. To be sure that this is not an intermittent problem, repeat this test up to a maximum of 10 times to make sure it continues to pass.</li> <li>2. If complaints persist (noisy connections for voice, corrupted data for data transfer), examine the station, connections, and wiring.</li> </ol>

## DIG-LINE Station Lamp Updates Test (#16)

This test lights all lamps on the terminal as specified. The lamp updates will run only if the station is in-service. The status of the station is checked and the lamp updates are blocked from taking place if the station is not in the in-service state. This test does not affect the status of the Message Waiting lamp.

Table 5-207. TEST #16 DIG-LINE Station Lamp Updates Test

Error Code	Test Result	Description/ Recommendation
	ABORT	Internal system error 1. Retry the command at 1-minute intervals a maximum of 5 times.
1	ABORT	This port may have been busied out by system technician. 1. Look in the Error Log for Error Type 18 (port busied out) for this port. If this error type is present, then release the port via the <b>release station &lt;extension&gt;</b> command and run the test again. 2. Make sure that the terminal is connected. 3. Retry the command at 1-minute intervals a maximum of 5 times.
3	ABORT	Station may be in ready-for-service or out-of-service state. 1. Use <b>status station</b> command to verify state of station. 2. Make sure the terminal is connected. 3. Retry the command at 1-minute intervals a maximum of 5 times.
1000	ABORT	System resources required to run this test are not available. The port may be busy with a valid call. Use <b>display port PCSSpp</b> to determine the station extension or attendant number of the port. Use <b>status station</b> or <b>status attendant</b> to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. You must wait until the port is idle before retesting. Attendants are always in use (off-hook) if the handset is plugged in and the port is not busied out. 1. If the port status is idle, then retry the command at 1-minute intervals a maximum of 5 times.
1392	ABORT	This port is currently a TTI port and the test will not execute on it. 1. Verify that the port is a TTI port using either the <b>display port</b> command (the display shows that the port is a TTI port) or the <b>list config</b> command (the display shows a $\tau$ for the port). 2. If either <b>list config</b> or <b>display port</b> indicates that the port is <i>not</i> a TTI port, escalate the problem. If both commands indicate that the port is a TTI port, the abort is correct, and no action is necessary.
	FAIL	Internal system error 1. Retry the command at 1-minute intervals a maximum of 5 times.

Continued on next page

Table 5-207. TEST #16 DIG-LINE Station Lamp Updates Test — *Continued*

Error Code	Test Result	Description/ Recommendation
	PASS	<p>The message to light all of the station lamps was sent successfully to the port.</p> <ol style="list-style-type: none"><li>1. Observe the station lamps being lit when running the test. If all lamps do not light successfully, the other Digital Line test results may indicate related problems that will not allow the lamps to light.</li><li>2. Investigate by using other Digital Line port tests, and by examining the station, wiring, and connections.</li></ol>

### Digital Station Audits Test (#17)

This is a series of six tests which are classified as audits. The SPE sends messages to the on-board microprocessor to perform the following tests. These audits run only if the station is in-service.

- Switchhook Inquiry Test — This is an update of the SPE records according to the circuit pack's records. This inquiry is sent all the way to the voice terminal.
- Bad Scan Inquiry Test — A message is sent uplink which contains a count that is generated due to certain events relating to the link conditions. This can be an indication of communications problems between the Processor and Digital Port circuit pack.
- EPF/PTC Inquiry Test — For a TN754 vintage 13 or earlier, the status of the Electronic Power Feed (EPF) is sent uplink. Possible conditions are: EPF-on-ok, EPF-off, and EPF-no-load. For TN754 vintage 14 or later, TN754B or TN2136, TN2181, TN2224, the status of the Positive Temperature Coefficient (PTC) is sent uplink. Possible conditions are: PTC-on-ok, PTC-off, and PTC-no-load.
- ID Request Test — A request is made to the station for its status. The station sends its configuration information and health information back. This information is checked and a pass/fail result is provided.
- Ringer Update Test — This updates the digital telephone ringer state according to the processor records.
- DTMF Administration Update Test — This is a message to the digital station to refresh the default value which causes the station to send touch-tones only in the primary information channel. This value is set initially when the station is put in-service and every time the station's state changes from other states to in-service.

5 Maintenance Objects for DEFINITY ONE  
DIG-LINE (Digital Line)

5-525

Table 5-208. TEST #17 Station (Digital) Audits Test

Error Code	Test Result	Description/ Recommendation
1	ABORT	Switchhook audit timed out.
2	ABORT	ID request fails, health bit returned from voice terminal is bad. <ol style="list-style-type: none"> <li>1. Make sure voice terminal is connected and repeat test.</li> <li>2. If test fails, replace voice terminal and repeat test.</li> </ol>
3	ABORT	The EPF/PTC has detected an overcurrent condition. <ol style="list-style-type: none"> <li>1. For a TN754 vintage 13 or earlier Digital Line circuit pack, issue the <b>test PCSSpp long</b> command. If Test #11 passes, then the EPF/PTC condition has been cleared. Rerun the Short Test Sequence. If Test #11 does not pass, follow the repair procedures described for Test #11.</li> <li>2. Look for Error Type 769 logged against DIG-LINE and follow the procedures in the associated footnote. If any additional problems are found after completion of maintenance procedures, rerun the test.</li> </ol>
4	ABORT	Internal system error <ol style="list-style-type: none"> <li>1. Resolve any outstanding circuit pack maintenance problems.</li> <li>2. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
5	ABORT	Ringer update aborted due to station being in ready-for-service or out-of-service state.
6	ABORT	This port may have been busied out by system technician. <ol style="list-style-type: none"> <li>1. Look in the Error Log for Error Type 18 (port busied out) for this port. If this error type is present, the release the port via the <b>release station</b></li> <li>2. Make sure that the terminal is connected.</li> <li>3. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
1000	ABORT	System resources required to run this test are not available.
1392	ABORT	This port is currently a TTI port and the test will not execute on it. <ol style="list-style-type: none"> <li>1. Verify that the port is a TTI port using either the <b>display port</b> command (the display shows that the port is a TTI port) or the <b>list config</b> command (the display shows a <math>\tau</math> for the port).</li> <li>2. If either <b>list config</b> or <b>display port</b> indicate that the port is <i>not</i> a TTI port, escalate the problem. If both commands indicate that the port is a TTI port, the abort is correct, and no action is necessary.</li> </ol>

Continued on next page

Table 5-208. TEST #17 Station (Digital) Audits Test — *Continued*

Error Code	Test Result	Description/ Recommendation
2000	ABORT	Response to the test request was not received within the allowable time period.
	FAIL	Internal system error 1. Retry the command at 1-minute intervals a maximum of 5 times.
	PASS	Station Audits passed. This Digital Port circuit pack is functioning properly. 1. If complaints persist, investigate by using other port tests, and by examining the station, wiring, and connections.

## DIOD-DS1 (DS1 DIOD Trunk)

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run	Full Name of MO
DIOD-DS1	MAJOR <sup>1</sup>	test trunk <i>group# member#l</i>	DS1 DIOD Trunk
DIOD-DS1	MINOR	test trunk <i>group# member#l</i>	DS1 DIOD Trunk
DIOD-DS1	WARNING	test trunk <i>group# member#</i>	DS1 DIOD Trunk

1. A Major alarm on a trunk indicates that alarms on these trunks are not downgraded by the **set options** command and that at least 75 percent of the trunks in this trunk group are alarmed.



**NOTE:**

Many trunk problems are caused by incorrect settings of parameters on the trunk group administration form. Settings must be compatible with the local environment and with parameter settings on the far-end. Refer to *DEFINITY Enterprise Communications Server Release 8 Administration and Feature Description*, (555-230-522), for information on how to administer trunks. The Application Notes section of that book shows the correct settings for administrable timers and other parameters on a country-by-country basis.

A DS1 DIOD trunk provides a link for digitized voice or data communications between the system and a central office switch. There are two types of DS1 interfaces:

- 24 DS0 channels on a 1.544 Mbps link
- 31 DS0 channels + 1 framing channel on a 2.048 Mbps link
- 32-channel mode is supported only on TN464 circuit packs and on V2 systems.

The DS1-DIOD maintenance object monitors and maintains a DIOD trunk port on a TN464 UDS1 Interface circuit pack. See "[UDS1-BD \(UDS1 Interface Circuit Pack\)](#)" on page 5-1227 for more information about this circuit pack. The DS1 circuit pack supports low level CO trunk signaling interfaces for both ground-start and loop-start trunks. This maintenance strategy covers the in-line errors log, initialization tests, periodic tests, scheduled tests, demand tests, and alarm resolution and escalation.

Three trunk service states are specified by DS1 DIOD trunk maintenance:

out-of-service	The trunk is in a deactivated state and cannot be used for either incoming or outgoing calls.
in-service	The trunk is in an activated state and can be used for both incoming and outgoing calls.
disconnect (ready-for-service)	The trunk is in an activated state but can only be used for an incoming call.

## Hardware Error Log Entries and Test to Clear Values

Table 5-209. DS1 DIOD Error Log Entries

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
0 <sup>1</sup>	0	Any	Any	Any	test trunk <grp>/<mbr>
1(a)	57408				
1(a)	57487 57476 57477 57485				
15(b)	Any	Port Audit and Update Test (#36)			
18(c)	0	busyout trunk <grp>/<mbr>	WARNING	OFF	release trunk <grp>/<mbr>

Continued on next page

Table 5-209. DS1 DIOD Error Log Entries — *Continued*

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
130(d)		None	WARNING	ON	test trunk <grp>/<mbr>
257(e)	57392	DS1 CO Dial Tone Seizure Test (#314)	MIN/MAJ <sup>2</sup>	OFF	
513(f)	57393	DS1 Tie Trunk Seizure Test (#136)	MIN/MAJ <sup>2</sup>	OFF	
769(g)	57484				
1025(h)	51200				
1025		DS1 CO Dial Tone Seizure Test (#314)	MIN/WRN <sup>3</sup>	OFF	test trunk <grp>/<mbr> r 2
1281		Conference Circuit Test (#7)	MIN/WRN <sup>3</sup>	ON	test trunk <grp>/<mbr> l r 4
1537		NPE Crosstalk Test (#6)	MIN/WRN <sup>3</sup>	ON	test trunk <grp>/<mbr> l r 3
1793(i)					test board PCSS I
2049(j)	57473 57474 57475				
2305(k)	50944				
2562(l)	16665				
2817(m)	52992				
3840(n)		Port Audit and Update Test (#36)			

1. Run the Short Test Sequence first. If all tests pass, run the Long Test Sequence. Refer to the appropriate test description and follow the recommended procedures.
2. This alarm will only be raised when the System-Parameter Country form has the Base Tone Generator field set to 4 (Italy). This alarm will be a MINOR alarm unless 75% or more trunks in this trunk group are out of service, then the alarm will be upgraded to a MAJOR alarm.
3. Major alarms on this MO may be downgraded to Warning alarms based on the value used in the set options command.

Notes:

- a. Error Type 1—Aux Data 57408—No tip ground is detected on an outgoing call.  
Aux Data 57476—Rotary Dial before Wink.  
Aux Data 57477—Rotary Dial pulse too early.  
Aux Data 57485—Wink too short for a valid signal.  
Aux Data 57487—PBX could not get “loop close” signal

The DS1 Interface circuit pack detected a hardware fault. These errors will cause the Dial Tone Test (#314) to run and are only considered a problem if the Dial Tone Test fails (in which case Error Type 1025 will also show up). In this case, the trunk may be put in the ready-for-service state (shown as “disconnected” by the status command), which allows only incoming calls. Run the Dial Tone Test (#314) and follow the procedures.

- b. Error Type 15—This is a software audit error that does not indicate any hardware malfunction. Run Short Test Sequence and investigate associated errors (if any).
- c. Error Type 18—System Technician has busied out the trunk to the out-of-service state. No calls can be made on this trunk except the Facility Access Test Call. For details on this feature, refer to “Facility Test Calls” section in Chapter 5, “Routine Maintenance Procedures”.
- d. Error Type 130—This error type indicates that the circuit pack has been removed or has been insane for more than 11 minutes. To clear the error, reinsert or replace the circuit pack.
- e. Error Type 257—The DS1 Interface circuit pack detects a hardware fault. Aux Data 57392 indicates no external release on PBX disconnect.
- f. Error Type 513—The DS1 Interface circuit pack detects a hardware fault. Aux Data 57393 indicates belated external release on PBX disconnect.
- g. Error Type 769—The DS1 Interface circuit pack detects a hardware fault. The Aux Data field contains the following error type:—57484, fault is detected on tip/ring.
- h. The DS1 Interface circuit pack detects a hardware fault, and the Aux Data field contains the following error type: 51200, port is unavailable. Run the Dial Tone Test (#314) and follow procedures.
- i. Error Type 1793—DS1 Interface circuit pack is out-of-service. Look for UDS1-BD errors in the Hardware Error Log if the port is on a TN464 UDS1 board. Refer to [“UDS1-BD \(UDS1 Interface Circuit Pack\)” on page 5-1227](#) for details.
- j. Error Type 2049—With the following Aux Data:
  - Aux Data 57473—Rotary dial rate below 8 pulses per second.
  - Aux Data 57474—Rotary dial rate above 12 pulses per second.
  - Aux Data 57475—Rotary Dial interdigit time is too short.

The DS1 interface circuit pack detects a hardware error on the DS1 DIOD trunk. The trunk can not communicate with the far-end because it is unable to interpret digits sent from the far-end switch. Check with the far-end switch or Operating Company for proper trunk connection.

- k. Error Type 2305—Recorder message, trunk could not be seized (Aux Data 50944). Run Test #314 and follow the outlined procedures.

5 Maintenance Objects for DEFINITY ONE  
DIOD-DS1 (DS1 DIOD Trunk)

5-530

- l. Error Type 2562—Retry Failure error. This error is logged only. It is not a hardware failure and hence does not start any testing or generate any alarms. This error comes from call processing and is generated when a second attempt (retry) to seize an outgoing trunk fails.
- m. Error Type 2817—Glare error. This error is logged only. It is not a hardware failure and hence does not start any testing or generate any alarms. This error is the result of a simultaneous seizure of a two-way trunk from both the near-end and the far-end. Attempt to place the call again. If the error persists, execute the Dial Tone Seizure Test (#314) and follow those procedures.
- n. Error Type 3840—Port Audit and Update Test (#36) failed due to an internal system error. Enter the **status trunk** command to verify the status of the trunk. If the trunk is out-of-service, then enter the **release trunk** command to put it back into in-service. Retry the test command.

## System Technician-Demanded Tests: Descriptions and Error Codes

Always investigate tests in the order they are presented in the table below when inspecting errors in the system. By clearing error codes associated with the *NPE Crosstalk Test*, for example, you may also clear errors generated from other tests in the testing sequence.

Order of Investigation	Short Test Sequence	Long Test Sequence	D/ND <sup>1</sup>
NPE Crosstalk Test (#6)		X	ND
Conference Circuit Test (#7)		X	ND
DS1 Dial Tone Test (#314)	X	X	ND
Port Audit and Update Test (#36)	X	X	ND

1. D = Destructive; ND = Nondestructive

### NPE Crosstalk Test (#6)

One or more Network Processing Elements (NPEs) resides on each circuit pack with a TDM Bus interface. (The TN464 UDS1 circuit pack has one SCOTCH-NPE chip instead of several NPE chips.) The NPE controls port connectivity and gain, and provides conferencing functions on a per-port basis. The NPE Crosstalk Test verifies that this port's NPE channel talks on the selected time slot and never crosses over to time slots reserved for other connections. If the NPE is not working correctly, one-way and noisy connections may be observed. This test is usually only part of a port's Long Test Sequence and takes about 20 to 30 seconds to complete.

5 Maintenance Objects for DEFINITY ONE  
DIOD-DS1 (DS1 DIOD Trunk)

5-531

Table 5-210. TEST #6 NPE Crosstalk Test

Error Code	Test Result	Description/ Recommendation
	ABORT	System resources required for this test are not available. 1. Retry the command at 1-minute intervals a maximum of 5 times.
1000	ABORT	System resources required to run this test are not available. The port may be in use on a valid call. Use the <b>status station</b> or <b>status trunk</b> command to determine when the port is available for testing. (Refer to <a href="#">"status station" on page 4-213</a> for a description of all possible states.) 1. Retry the command at 1-minute intervals a maximum of 5 times.
1001	ABORT	System resources required for this test are not available. 1. Retry the command at 1-minute intervals a maximum of 5 times.
1002	ABORT	The system could not allocate time slots for the test. The system may be under heavy traffic conditions or it may have time slots out-of-service due to TDM-BUS errors. The <b>status health</b> command can be used to determine if the system is experiencing heavy traffic. Refer to <a href="#">"TDM-BUS (TDM Bus)" on page 5-1116</a> to diagnose any active TDM-BUS errors. 1. If system has no TDM-BUS errors and is not handling heavy traffic, repeat test at 1-minute intervals a maximum of 5 times.
1003	ABORT	The system could not allocate a tone receiver for the test. The system may be oversized for the number of Tone Detectors present or some tone detectors may be out-of-service. The <b>list measurements tone-receiver</b> command will display information on the system's tone receivers. 1. Look for TTR-LEV errors in the Error Log. If present, refer to <a href="#">"TTR-LEV (TTR Level)" on page 5-1223</a> . 2. Look for TONE-PT errors in the Error Log. If present, refer to <a href="#">"TONE-PT (Tone Generator)" on page 5-1204</a> . 3. If neither condition exists, retry the test at 1-minute intervals a maximum of 5 times.
1004	ABORT	The port has been seized by a user for a valid call. Use the <b>status trunk</b> command to determine when the port is available for testing. 1. Retry the command at 1-minute intervals a maximum of 5 times.
1020	ABORT	The test did not run due to a previously existing error on the specific port or a more general circuit pack error. 1. Examine Error Log for existing errors against this port or the circuit pack and attempt to diagnose the already existing error.

Continued on next page

Table 5-210. TEST #6 NPE Crosstalk Test — *Continued*

Error Code	Test Result	Description/ Recommendation
2000	ABORT	Response to the test request was not received within the allowable time period.
2100	ABORT	System resources required for this test are not available. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
2053	ABORT	At least one of the following errors is found on the DS1 circuit pack: 1281—Loss of signal 1793—Blue Alarm 2049—Red Alarm 2305—Yellow Alarm 1537—Hyperactivity  Look for the above error types in the Hardware Error Log and follow the procedures given in the appropriate <a href="#">“DS1-BD (DS1 Interface Circuit Pack)” on page 5-548</a> or <a href="#">“UDS1-BD (UDS1 Interface Circuit Pack)” on page 5-1227</a> for the listed error types.
	FAIL	The NPE of the tested port was found to be transmitting in error. This will cause noisy and unreliable connections. <ol style="list-style-type: none"><li>1. Replace the circuit pack.</li></ol>
	PASS	The port is correctly using its allocated time slots. User-reported troubles on this port should be investigated using other port tests and examining station, trunk, or external wiring.

### Conference Circuit Test (#7)

One or more Network Processing Elements (NPEs) reside on each circuit pack with a TDM Bus interface. (The TN464 UDS1 circuit pack has one SCOTCH-NPE chip instead of several NPE chips). The NPE controls port connectivity and gain, and provides conferencing functions on a per-port basis. The Conference Circuit Test verifies that the NPE channel for the port being tested can correctly perform the conferencing function. The NPE is instructed to listen to several different tones and conference the tones together. The resulting signal is then measured by a tone detector port. If the level of the tone is within a certain range, the test passes.

Table 5-211. TEST #7 Conference Circuit Test

Error Code	Test Result	Description/ Recommendation
	ABORT	System resources required for this test are not available. 1. Retry the command at 1-minute intervals a maximum of 5 times.
1000	ABORT	System resources required to run this test are not available. The port may be in use on a valid call. Use the <b>status station</b> or <b>status trunk</b> command to determine when the port is available for testing.
1004	ABORT	The port has been seized by a user for a valid call. Use the <b>status station</b> or <b>status trunk</b> command to determine when the port is available for testing. 1. Retry the command at 1-minute intervals a maximum of 5 times.
1018	ABORT	Test disabled via administration. This only applies to analog stations. 1. To enable test, set the Test field on the station administration screen for the particular analog station being tested to "y." Use the <b>change station extension</b> command.
1020	ABORT	The test did not run due to a previously existing error on the specific port or a more general circuit pack error. 1. Examine Error Log for existing errors against this port or the circuit pack and attempt to diagnose the previously existing error.
2000	ABORT	Response to the test request was not received within the allowable time period.
2100	ABORT	System resources required for this test are not available. 1. Retry the command at 1-minute intervals a maximum of 5 times.
2053	ABORT	At least one of the following errors is found on the DS1 circuit pack: 1281—Loss of signal 1793—Blue Alarm 2049—Red Alarm 2305—Yellow Alarm 1537—Hyperactivity  Look for the above error types in the Hardware Error Log and follow the procedures given in the appropriate DS1-BD or UDS1-BD maintenance documentation for the listed error types.
	FAIL	The NPE of the tested port did not conference the tones correctly. This will cause noisy and unreliable connections. 1. Replace the circuit pack.
	PASS	The port can correctly conference multiple connections. User-reported troubles on this port should be investigated by using other port tests and by examining station, trunk, or external wiring.

## Port Audit and Update Test (#36)

This test sends port level translation data from switch processor to the DS1 Interface circuit pack to assure that the trunk's translation is correct. Translation updates include the following data: trunk type (in/out), dial type, timing parameters, and signaling bits enabled. The port audit operation verifies the consistency of the current state of trunk kept in the DS1 Interface circuit pack and in the switch software.

Table 5-212. TEST #36 Port Audit and Update Test

Error Code	Test Result	Description/Recommendation
	ABORT	Internal system error <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
2000	ABORT	Response to the test request was not received within the allowable time period.
2100	ABORT	Could not allocate the necessary system resources to run this test. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
	FAIL	Test failed due to internal system error. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
	PASS	Trunk translation has been updated successfully. The current trunk states kept in the DS1 Interface circuit pack and switch software are consistent. If the trunk is busied out, the test will not run but will return PASS. To verify that the trunk is in-service: <ol style="list-style-type: none"><li>1. Enter the <b>status trunk</b> command to verify that the trunk is in-service. If the trunk is in-service, no further action is necessary. If the trunk is out-of-service, continue to step 2.</li><li>2. Enter the <b>release trunk</b> command to put the trunk back into in-service.</li><li>3. Retry the test command.</li></ol>

**DS1 CO Dial Tone Seizure Test (#314)**

DS1 CO Dial Tone Seizure Test checks the trunk's signaling capability provided by the DS1 Interface circuit pack. The maintenance software initiates the test by sending a "seizure" message to the DS1 Interface circuit pack and expects an "active" reply from the DS1 interface circuit pack. If the "active" message is received, then the test passes. If no message is received and the timer expires, the test is aborted. If the DS1 Interface circuit pack sends a "reorder" message back to maintenance software, then the test fails.

This test cannot be run on a trunk in any of the following conditions:

- The trunk direction is administered as an incoming only trunk.
- The trunk has been seized by a normal trunk call.
- The trunk is administered with maintenance test disabled.

**Table 5-213. TEST #314 DS1 CO Dial Tone Seizure Test**

Error Code	Test Result	Description/Recommendation
	ABORT	Internal system error <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
1000	ABORT	System resources required to run this test are not available. The port may be in use on a valid call. Use the <b>status trunk</b> command to determine when the port is available for testing.
1004	ABORT	The port has been seized by a user for a valid call. Use the <b>status trunk</b> command to determine when the port is available for testing. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
1005	ABORT	Test failed due to incompatible configuration administered in trunk group form. <ol style="list-style-type: none"><li>1. Look at the trunk group administration form and see whether the trunk is incoming only, port 24 on a DS1 Interface with common control channel signaling, or an automatic CO type such as FX. Under any of these conditions this is a normal abort.</li></ol>
1018	ABORT	Test has been disabled via administration. <ol style="list-style-type: none"><li>1. Verify that the <code>Maintenance Tests</code> field on the Trunk Group Form is set to <b>n</b>. To enable the test, issue the <b>change trunk-group x</b> command where "x" equals the number of the trunk group to be tested. Then change the entry in the <code>Maintenance Tests</code> field on the form to <b>y</b>.</li><li>2. Repeat the test.</li></ol>

*Continued on next page*

Table 5-213. TEST #314 DS1 CO Dial Tone Seizure Test — *Continued*

Error Code	Test Result	Description/Recommendation
1020	ABORT	The DS1 Interface circuit pack is out-of-service. 1. Look for UDS1-BD errors in the Hardware Error Log. If present, refer to <a href="#">“UDS1-BD (UDS1 Interface Circuit Pack)” on page 5-1227</a> . 2. Retry the command.
2000	ABORT	Response to the test request was not received within the allowable time period.
2100	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals for a maximum of 5 times.
2053	ABORT	At least one of the following errors is found on the DS1 circuit pack: 1281—Loss of signal 1793—Blue Alarm 2049—Red Alarm 2305—Yellow Alarm 1537—Hyperactivity  Look for the above error types in the Hardware Error Log and follow the procedures given in the appropriate DS1-BD or UDS1-BD maintenance documentation for the listed error types.
	FAIL	The trunk cannot be seized for an outgoing call. 1. Verify that the Trunk Type field on the trunk administration screen form matches the trunk type administered on far end switch. 2. Look for UDS1-BD errors in Hardware Error Log. If present, refer to <a href="#">“UDS1-BD (UDS1 Interface Circuit Pack)” on page 5-1227</a> . 3. Retry the test at 1-minute intervals for a maximum of 5 times.
	PASS	The trunk can be seized for an outgoing call.

## DIOD-TRK (DIOD Trunk), DIOD-BD (DIOD Circuit Pack)

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run <sup>1</sup>	Full Name of MO
DIOD-BD <sup>2</sup>	MINOR	test port PCSS s	DIOD Circuit Pack

- Where P is the port network number (1 for PPN); C is the carrier designation (for example, A, B, or C); and SS is the address of the slot in the carrier where the circuit pack is located (for example, 01, 02, ...etc.)
- Where I is long, s is short, and r is repeat. Refer to the [“XXX-BD \(Common Port Circuit Pack\)” on page 5-1343](#).

## DIOD-TRK (DIOD Trunk)

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run <sup>1</sup>	Full Name of MO
DIOD-TRK	MAJOR <sup>2</sup>	test port PCSSpp l	DIOD Trunk
DIOD-TRK	MINOR	test port PCSSpp l	DIOD Trunk
DIOD-TRK	WARNING	test port PCSSpp l	DIOD Trunk

- Where P is the port network number (1 for PPN); C is the carrier designation (for example, A, B, or C); and SS is the address of the slot in the carrier where the circuit pack is located (for example, 01, 02, ...etc.).
- A MAJOR alarm on a trunk indicates that alarms on these trunks are not downgraded by the **set options** command and that at least 75 percent of the trunks in this trunk group are alarmed.

Direct Inward and Outward Dial (TN429 DIOD) trunks are 2-wire analog lines to the CO which support the following services:

- both incoming and outgoing CO calls
- DID trunk
- DID Trunk and 1-way Outgoing DIOD

The DIOD Trunk circuit pack provides eight ports for loop-start CO. The circuit pack is an interface between the 2-wire analog line from the CO and the system's (4-wire) TDM Bus.

## Loop start operation

---

Idle State - Tip = ground, Ring = CO Battery

### A. Outgoing Call

1. PBX Off-Hook (Seize Message): Closes the Tip-Ring Loop
  - a. CO Response: DC loop current + Dial tone
2. PBX On-Hook (Drop Message): Open Tip-Ring loop, no loop current
  - a. CO Response: CO goes to idle state (see Note)

### B. Incoming Call

1. CO Applies Ringing Voltage
  - a. PBX Response: Detect ringing current
2. PBX Off-Hook (Answer Message): Close loop
  - a. CO Response: Trip ringing, provide loop current
3. PBX On-Hook (Drop Message): Open Tip-Ring loop, no loop current
  - a. CO Response: CO goes to idle state (see Note)

### C. Direct Inward Dialing (DID)

1. CO Applies Ringing Voltage
  - a. PBX Response: Detect ringing current and close loop
  - b. CO Response: Send DTMF digits
  - c. PBX Response: Acknowledge of Number dialed and open loop
2. PBX Off-Hook (Answer Message): Close loop
  - a. CO Response: Trip ringing, provide loop current
3. PBX On-Hook (Drop Message): Open Tip-Ring loop, no loop current
  - a. CO Response: CO goes to idle state (see Note)



#### NOTE:

CO does not normally provide an On-Hook (Disconnect) signal.

## Hardware Error Log Entries and Test to Clear Values

Table 5-214. DIOD Trunk Error Log Entries

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
0 <sup>1</sup>	0	Any	Any	Any	test port PCSSpp sh r 1
15 (b)	any	Port Audit Update Test (#36)			
18	0	busyout trunk <grp>/<mbr>			
769 (a)	57392	None	MAJ/MIN/ WRN <sup>2</sup>	ON	
1537		Dial Tone Test (#0)	MAJ/MIN/ WRN <sup>2</sup>	ON	test port PCSS l r 2
1793		Loop Around and Conference Test (#33)	MAJ/MIN/ WRN <sup>2</sup>	ON	test port PCSS l r 3
2049		NPE Cross Talk Test (#6)	MAJ/MIN/ WRN <sup>2</sup>	ON	test port PCSS l r 3
2561 (a,d)	57345	None			
2817 (a,e)	57393	None			
3073 (a,c)	57376	None			
3073 (a,c)	57424	None			
3585 (a,c)	57424	None			

1. Run the Short Test Sequence first. If all tests pass, run the Long Test Sequence. Refer to the appropriate test description and follow the recommended procedures.
2. The Minor alarms on this MO may be downgraded to warning alarms based on the values used in the **set options** command. If the Minor alarm is not downgraded by the **set-options** values, the Minor alarm is upgraded to a Major alarm if 75 percent of the trunks in this trunk group are alarmed.

### Notes:

- a. These are in-line errors that have no specific test associated with them. Refer to [Table 5-215 on page 5-540](#) for an explanation and appropriate action.
- b. This is a software audit error that does not indicate any hardware malfunction. Run the Short Test Sequence and investigate associated errors (if any).

5 Maintenance Objects for DEFINITY ONE  
DIOD-TRK (DIOD Trunk)

5-540

- c. Aux data 57376 - No loop current on incoming call

Aux data 57424 - No loop current on outgoing call

These errors cause the Dial Tone Test (#0) to run and are only considered a problem if the Dial Tone Test fails (in which case Error Type 1537 also shows up). In this case, the trunk may be put in "Ready-for-Service" state (shown as "disconnected" by status command), which allows only incoming calls. Run the Dial Tone Test (#0) and follow its outlined procedures.

- d. Single polarity ringing current - This error results from abnormal ringing current, but does not prevent the incoming call from being accepted. This error code is only logged as an informational event and causes no other testing to occur.
- e. Late CO Trunk release - This error indicates that the CO releases the trunk at least four minutes after the PBX dropped the call. This error code is only logged as an informational event and causes no other testing to occur.

Table 5-215. DIOD Trunk Errors with NO Tests

Error Type	Aux Data	Description and System Action	System Technician Action
769	57392	CO not releasing after call is dropped from PBX end (TN747B), or the loop is not open after a disconnect (TN765). After several occurrences, an off-board (TN747B) or on-board (TN465) warning alarm is generated.	Refer problem to CO.
2561	57345	Single polarity ringing current. This error results from abnormal ringing current, but does not prevent the incoming call from being accepted. One cause could be that the reverse current detector associated with the port is failing. (Will not be detected by any tests.) The other cause could be that normal current is not detected. In this case, neither incoming nor outgoing calls can be completed, and the dial tone test also fails.	Check for other errors.

*Continued on next page*

Table 5-215. DIOD Trunk Errors with NO Tests — *Continued*

Error Type	Aux Data	Description and System Action	System Technician Action
2817	57393	CO released the trunk at least four minutes after the PBX dropped the call. This error code is log only and causes no other testing to occur. No alarm is generated.	Check for other errors.
3073	57376	No loop current on incoming call. The incoming destination has already answered and no loop current has been detected. If this is a hard fault, the dial tone test and all outgoing calls should also fail.	Check for other errors.
3585	57424	No loop current on outgoing call. This error occurs on attempt to seize a loop or ground-start trunk for an outgoing call. An error occurs if loop current is not detected or the caller hangs up before it is detected.	See Note at end of table.



**NOTE:**

At the administration terminal, busyout the affected port, and run a Long test. If Dial Tone Test #0 passes, ignore this error. Release the port.

**System Technician-Demanded Tests: Descriptions and Error Codes**

Always investigate tests in the order they are presented in the table below when inspecting errors in the system. By clearing error codes associated with the *NPE Crosstalk Test*, for example, you may also clear errors generated from other tests in the testing sequence.

For example, you may also clear errors generated from other tests in the testing sequence.

Order of Investigation	Short Test Sequence	Long Test Sequence	D/ND <sup>1</sup>
NPE Crosstalk Test (#6)		X	ND
Dial Tone Test (#0)		X	ND
Loop Around and Conference Test (#33)		X	ND
Audit Update Test (#36)	X	X	ND

1. D = Destructive; ND = Nondestructive

**Dial Tone Test (#0)**

This test attempts to seize a port and checks for the return of a dial tone.

**Table 5-216. TEST #0 Dial Tone Test**

Error Code	Test Result	Description/ Recommendation
	ABORT	Could not allocate system resources to run this test. 1. Retry the command at 1-minute intervals a maximum of 5 times.
1000	ABORT	System resources required to run this test are not available. The port may be busy with a valid call. Use the command <b>display port PCSSpp</b> to determine the trunk group/member number of the port. Use the <b>status trunk</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. You must wait until the port is idle before retesting. 1. If the port status is idle, then retry the command at 1-minute intervals a maximum of 5 times.
1001	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals a maximum of 5 times.
1002	ABORT	The system could not allocate time slots for the test. The system may be under heavy traffic conditions or it may have time slots out-of-service due to TDM-BUS errors. Refer to " <a href="#">TDM-BUS (TDM Bus)</a> " on page 5-1116 to diagnose any active TDM-BUS errors. 1. If the system has no TDM-BUS errors and is not handling heavy traffic, repeat test at 1-minute intervals a maximum of 5 times.
1004	ABORT	The port has been seized by a user for a valid call. Use the <b>status trunk</b> command to determine when the port is available for testing. 1. Retry the command at one minute intervals a maximum of 5 times.
1018	ABORT	Test has been disabled via administration. 1. Verify that the Maintenance Tests? field on the Trunk Group Form is set to <b>n</b> . To enable the test, issue the <b>change trunk-group x</b> command where "x" equals the number of the trunk group to be tested. Then change the entry in the Maintenance Tests? field on the form to <b>y</b> .
1005	ABORT	Trunk has been administered as incoming-only; or DID trunk group type; dial tone can only be obtained on outgoing trunks. This is a normal condition.
2000	ABORT	Response to the test was not received within the allowable time period. 1. Retry the command at 1-minute intervals a maximum of 5 times.

*Continued on next page*

Table 5-216. TEST #0 Dial Tone Test — *Continued*

Error Code	Test Result	Description/ Recommendation
	FAIL	Trunk was seized, but dial tone could not be detected. <ol style="list-style-type: none"> <li>1. Check for errors on TONE-BD or TONE-PT. Clear any errors found and repeat test.</li> <li>2. If error has still not cleared, refer problem to CO.</li> </ol>
2002	FAIL	Seizure portion of test failed due to hardware problem. Fault is usually caused by a disconnected trunk. <ol style="list-style-type: none"> <li>1. Check trunk wiring to ensure good connection; repeat test if wiring correction made.</li> <li>2. Locate another identical CO trunk and swap its wiring with one under test. Repeat test on both trunks and determine if problem follows trunk or remains at original port. If problem follows trunk, refer problem to CO. If problem remains at port, replace circuit pack and repeat test.</li> </ol>
1009	PASS	Detected tone was not pure dial tone. No action required.
	PASS	Trunk was seized, and dial tone was detected. User-reported troubles on this port should be investigated by using other port tests and by examining trunk or external wiring.

**NPE Crosstalk Test (#6)**

One or more NPEs reside on each circuit pack with a TDM Bus interface. The NPE controls port connectivity and gain, and provides conferencing functions on a per port basis. The NPE Crosstalk Test verifies that this port's NPE channel talks on the selected time slot and never crosses over to time slots reserved for other connections. If the NPE is not working correctly, one way and noisy connections may be observed. This test is usually only part of a port's long test sequence and takes approximately 20 to 30 seconds to complete.

**Table 5-217. TEST #6 NPE Crosstalk Test**

Error Code	Test Result	Description/ Recommendation
	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals a maximum of 5 times.
1000	ABORT	System resources required to run this test are not available. The port may be busy with a valid call. Use the <b>display port PCSSpp</b> command to determine the trunk group/member number of the port. Use the <b>status trunk</b> command to determine the service state of the port. (Refer to " <a href="#">status station</a> " on page 4-213 for a description of all possible states.) If the service state indicates that the port is in use, then the port is unavailable for certain tests. You must wait until the port is idle before retesting. 1. If the port status is idle, then retry the command at 1-minute intervals a maximum of 5 times.
1001	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals a maximum of 5 times.
1002	ABORT	The system could not allocate time slots for the test. The system may be under heavy traffic conditions or it may have time slots out-of-service due to TDM-BUS errors. Refer to " <a href="#">TDM-BUS (TDM Bus)</a> " on page 5-1116 to diagnose any active TDM-BUS errors. 1. If system has no TDM-BUS errors and is not handling heavy traffic, repeat test at 1-minute intervals a maximum of 5 times.
1003	ABORT	The system could not allocate a tone receiver for the test. The system may be oversized for the number of tone detectors present or some tone detectors may be out-of-service. 1. Look for TTR-LEV errors in the Error Log. If present, refer to " <a href="#">TTR-LEV (TTR Level)</a> " on page 5-1223. 2. Look for TONE-PT errors in the Error Log. If present, refer to " <a href="#">TONE-PT (Tone Generator)</a> " on page 5-1204. 3. If neither condition exists, retry the test at 1-minute intervals a maximum of 5 times.

*Continued on next page*

Table 5-217. TEST #6 NPE Crosstalk Test — *Continued*

Error Code	Test Result	Description/ Recommendation
1004	ABORT	The port was seized by a valid call during the test. The test has been aborted. Use the <b>display port PCSSpp</b> command to determine the trunk group/member number of the port. Use the <b>status trunk</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. You must wait until the port is idle before retesting.
2000	ABORT	Response to the test request was not received within the allowable time period.
2100	ABORT	Could not allocate the necessary system resources to run this test. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
Any	FAIL	The NPE of the tested port was found to be transmitting in error. This causes noisy and unreliable connections. <ol style="list-style-type: none"><li>1. Replace the circuit pack.</li></ol>
	PASS	The port is correctly using its allocated time slots. User-reported troubles on this port should be investigated by using other port tests and by examining trunk or external wiring.

## Loop Around and Conference Circuit Test (#33)

This test checks the reflective loop and conference abilities of a CO port circuit. The test uses 404 Hz, 1004 Hz, and 2804 Hz tones. Each tone is transmitted separately through the loop and checked.

Table 5-218. TEST #33 Loop Around and Conference Circuit Test

Error Code	Test Result	Description/ Recommendation
7 1000	ABORT	Could not allocate system resources to run this test.
	ABORT	Conference Circuit Test aborted.
	ABORT	System resources required to run this test are not available. The port may be busy with a valid call. Use the <b>display port PCSSpp</b> command to determine the trunk group/member number of the port. Use the <b>status trunk</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. You must wait until the port is idle before retesting. <ol style="list-style-type: none"> <li>1. If the port status is idle, then retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
1004	ABORT	The port has been seized by a user for a valid call. Use the <b>status trunk</b> command to determine when the port is available for testing. <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
2100	ABORT	Could not allocate the necessary system resources to run this test. <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
7	FAIL	<ol style="list-style-type: none"> <li>1. Check for errors on TONE-BD or TONE-PT. If there are errors, take the appropriate actions.</li> <li>2. If the Reflective Loop Around Test fails for all ports on a circuit pack, a -5 volt power problem is indicated.</li> <li>3. Rerun the test.</li> <li>4. If the test fails again, replace the circuit pack.</li> </ol>
	PASS	CO Trunk Loop Around and Conference Test is successful. User-reported troubles on this port should be investigated by using other port tests and by examining trunk or external wiring.

## Port Audit Update Test (#36)

This test sends updates of the CO port translation for all ports on the circuit pack which have been translated. The update is non-disruptive and guards against possible corruption of translation data contained on the circuit pack. No response message is expected from the circuit pack once it receives translation updates. The port translation data includes: ground or loop start trunk, tone or rotary dialing trunk, rotary dialing inter-digit timing, network balance R/RC, and disconnect timing.

Table 5-219. TEST #36 Port Audit Update Test

Error Code	Test Result	Description/ Recommendation
	ABORT	Could not allocate the necessary system resources to run this test. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
2100	ABORT FAIL	Could not allocate the necessary system resources to run the test. Internal system error <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
	PASS	This test passed. Translation information was successfully updated on the circuit pack. User-reported troubles on this port should be investigated by using other port tests and by examining trunk or external wiring. If the trunk is busied out, the test does not run, but returns PASS. To verify that the trunk is in-service: <ol style="list-style-type: none"><li>1. Enter <b>status-command</b> to verify that the trunk is in-service. If the trunk is in-service, no further action is necessary. If the trunk is out-of-service, continue to Step 2.</li><li>2. Enter <b>release-trunk</b> command to put trunk back into in-service.</li><li>3. Retry the test command.</li></ol>

## DLY-MTCE (MO-DAILY)

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run	Full Name of MO
DLY-MTCE	MINOR	NONE	DLY-MTCE
DLY-MTCE	MAJOR	NONE	DLY-MTCE

The DLY-MTCE maintenance object monitors daily translation saves. If a translation save times out or fails to run, an error is logged against this maintenance object. If the save fails three times in a row, a MINOR alarm is raised; if the save fails for seven consecutive attempts, a MAJOR alarm is raised.

## DS1-BD (DS1 Interface Circuit Pack)

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run <sup>1</sup>	Full Name of MO
DS1-BD	MAJOR	test board PCSS sh	DS1 Interface Circuit Pack
DS1-BD	MINOR	test board PCSS I	DS1 Interface Circuit Pack
DS1-BD	WARNING	test board PCSS sh	DS1 Interface Circuit Pack

1. P is the universal cabinet number (1 for PPN). C is the carrier designation (A, B, or C). SS is the number of the slot in which the circuit pack resides (01 to 21).

The DS1 Interface circuit pack provides an interface to an external DS1 facility and supports 24 DS0 channels carried on a 1.544 Mbps DS1 link. These DS0 channels can be administered as either trunks to other switches or lines to off-premises stations. The TN464C and later suffix Universal DS1 Interface also supports a 32-channel interface on a 2.048Mbps link. The functions and maintenance strategy for the TN464 circuit packs are covered under a separate maintenance object, UDS1-BD.

DS1-BD maintenance logs in-line errors reported by the DS1 Interface circuit pack, runs tests for error diagnosis and recovery, and raises and clears alarms. The following table shows the capabilities of each DS1 circuit pack.

Circuit Pack Code	24 Channel	32 Channel	Tie Trunk Signaling	CO Trunk Signaling	DID Trunk Signaling	OPS Line Signaling
TN767/B/C/D/E	x		x	x	x	x
TN464C/D/E/F	x	x	x	x	x	x (24-chl only)

ISDN-PRI Trunk signaling (for example, Q.921, Q.931) requires a TN464D and is handled by system software. The TN464 is covered in [“UDS1-BD \(UDS1 Interface Circuit Pack\)” on page 5-1227](#).

Each trunk and line have their own maintenance strategies. However, they all depend on the health of the DS1 Interface circuit pack. Refer to the following sections for details: [“TIE-DS1 \(DS1 Tie Trunk\)” on page 5-1144](#), [“CO-DS1 \(DS1 CO Trunk\)” on page 5-402](#), [“DID-DS1 \(DS1 DID Trunk\)” on page 5-475](#), [“OPS-LINE \(DS1 OPS Line\)” on page 5-882](#), [“ISDN-TRK \(DS1 ISDN Trunk\)” on page 5-722](#), and [“ISDN-PLK \(ISDN-PRI Signaling Link Port\)” on page 5-699](#). Signaling over the DS1 link must be synchronized between the transmitting and receiving ends to ensure error-free communication. Refer to [“SYNC \(Synchronization\)” on page 5-1063](#) for details.

The TN767E circuit pack combined with a 120A2 CSU Module forms an Enhanced Integrated CSU. The 120A2, when combined with the functionality provided by the TN767E hardware and firmware, and switch software, provides functionality equivalent to an external stand-alone ESF T1 CSU. The 120A2 CSU Module connects to the TN767E circuit pack on the I/O connector panel on the back of the port carrier. The new CSU Module, thus becomes an integrated part of the DEFINITY. system. Throughout the document, the term 120A will mean a 120A2 or later suffix CSU Module.

The Enhanced Integrated CSU is for use in the United States of America with 1.544 Mbps DS1 service. For further details on the 120A CSU Module see *DEFINITY Communications System Generic 1, Generic 2, and Generic 3 V1 and V2 - Integrated CSU Module Installation and Operation, 555-230-193*.

The TN767E and 120A CSU Module support on-demand loopback tests that assist in the detection of faults between the TN767E circuit pack and the CSU Module, between the Integrated CSU and the optional Customer Premises Loopback Jack, or between the Integrated CSU and remote CSU. These loopback tests are explained in detail later in this DS1-BD section, but [Figure 5-21](#) gives a high level overview of the loopback points.

The following list of acronym definitions are for [Figure 5-21](#):

- PLB = Payload Loopback
- BLB = Board Loopback
- ELB = Equipment Loopback
- LLB = Line Loopback
- RLB = Repeater Loopback
- CLJ = Loopback Jack Loopback
- R-LLB = Remote Line Loopback
- SMRT = Smart Jack
- LPBK = Loopback

For more information about DS1 interfaces, see the *DEFINITY Communications System DS1/CEPT1/ISDN-PRI Reference*, (555-025-107).




Figure 5-21. High Level Overview Of Loopback Points

## Error Log Entries and Test to Clear Values

Table 5-220. DS1 Interface Circuit Pack Maintenance Error Log Entries

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
0 <sup>1</sup>	0	Any	Any	Any	test board PCSS
1 (a)	0	Circuit pack removed or SAKI Test (#53)	MIN/WRN <sup>2</sup>	ON	
18 (b)	0	busy-out board PCSS	WARNING	OFF	release board PCSS

Continued on next page

5 Maintenance Objects for DEFINITY ONE  
DS1-BD (DS1 Interface Circuit Pack)

5-551

Table 5-220. DS1 Interface Circuit Pack Maintenance Error Log Entries — *Continued*

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
23 (c)	0		WARNING	OFF	add ds1 PCSS
12 5(d)		None	MINOR	ON	
257	65535	Control Channel Loop Test (#52)	MINOR	ON	test board PCSS l r 20
257 (e)	Any	None			
513 (f)	Any		MINOR	ON	
769 (g)	4358				
1025 (e)	4363	NPE Audit Test (#50)			
1281	Any	Loss of Signal Alarm Inquiry Test (#138)	MIN/WRN <sup>3</sup>	OFF	test board PCSS
1300 (h)	Any	Loss Of Signal Alarm Inquiry Test (#138)	WARNING	OFF	test board PCSS
1301 (i)	Any	Loss Of Signal Alarm Inquiry Test (#138)	WARNING	OFF	test board PCSS
1302 (j)	Any	Loss Of Signal Alarm Inquiry Test (#138)	MIN/WRN <sup>3</sup>	OFF	test board PCSS
1303 (k)	Any	Loss Of Signal Alarm Inquiry Test (#138)	MIN/WRN <sup>3</sup>	ON	test board PCSS
1310 (l)	Any	Board Loopback Test (#1209)	MINOR	ON	test ds1-loop PCSS ds1/csu-loopback-tests
1311 (m)	Any	Equipment Loopback Test (#1210)	MIN/WRN <sup>3</sup>	OFF	test ds1-loop PCSS ds1/csu-loopback-test
1312 (n)	Any	Repeater Loopback Test (#1211)	MIN/WRN <sup>3</sup>	OFF	test ds1-loop PCSS ds1/csu-loopback-tests
1313 (o)	Any	CPE Loopback Jack Test (#1212)	MIN/WRN <sup>3</sup>	OFF	test ds1-loop PCSS end-loopback/span-test
1314 (p)	Any	Far CSU Loopback Test (#1213)	MIN/WRN <sup>3</sup>	OFF	test ds1-loop PCSS end-loopback/span-test
1320	Any	Loss of Signal Alarm Inquiry Test (#138)	MIN/WRN <sup>3</sup>	OFF	test board PCSS
1321	Any	Loss of Signal Alarm Inquiry Test (#138)	MIN/WRN <sup>3</sup>	OFF	test board PCSS
1322	Any	Loss of Signal Alarm Inquiry Test (#138)	MINOR	ON	test board PCSS

*Continued on next page*

Table 5-220. DS1 Interface Circuit Pack Maintenance Error Log Entries — *Continued*

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
1323	Any	Loss of Signal Alarm Inquiry Test (#138)	MIN/WRN <sup>3</sup>	OFF	test board PCSS
1324	Any	Loss of Signal Alarm Inquiry Test (#138)	WARNING	OFF	test board PCSS
1538 (q)	Any		MINOR	ON	
1793	Any	Blue Alarm Inquiry Test (#139)	MAJ/MIN/WRN **	OFF	test board PCSS
1794	Any	Blue Alarm Inquiry Test (#139)	MAJ/MIN/WRN **	OFF	test board PCSS
1795	Any	Blue Alarm Inquiry Test (#139)	MAJ/MIN/WRN **	OFF	test board PCSS
2049	Any	Red Alarm Inquiry Test (#140)	MIN/WRN <sup>3</sup>	OFF	test board PCSS
2305	Any	Yellow Alarm Inquiry Test (#141)	MINOR	OFF	test board PCSS
2306	Any	Yellow Alarm Inquiry Test (#141)	MINOR	OFF	test board PCSS
2561	Any	Major Alarm Inquiry Test (#142)	MIN/WRN <sup>3</sup>	OFF	test board PCSS
2817		Minor Alarm Inquiry Test (#143)	MIN/WRN <sup>3</sup>	OFF	test board PCSS
3073 to 3160 (r)	Any	Slip Alarm Inquiry Test (#144)	MIN/WRN <sup>3</sup>	OFF	test board PCSS r 6
3329 to 3345 (s)	Any	Misframe Alarm Inquiry Test (#145)	MIN/WRN <sup>3</sup>	OFF	test board PCSS r 6
3840(t)	Any	None			
3900(u)	Any	CPE Loopback Jack Test (#1212)			

*Continued on next page*

Table 5-220. DS1 Interface Circuit Pack Maintenance Error Log Entries — *Continued*

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
3901(v)	Any	Far CSU Loopback Test (#1213)			
3902(w)	Any	One-Way Span Test (#1214)			
3999 (x)	Any	None			

1. Run the Short Test Sequence first. If all tests pass, run the Long Test Sequence. Refer to the appropriate test description and follow the recommended procedures.
2. If ports are assigned to the circuit pack, then a minor alarm is raised. If no ports are assigned to the circuit pack, then a warning alarm is raised. The alarm is raised after the circuit pack has been missing for 15 minutes. Warning alarms are also raised against any ports administered on the circuit pack.
3. Off-board minor alarms on this maintenance object may be downgraded to Warning alarms based on the values used in the **set options** command.

**Notes:**

- a. This error indicates that the circuit pack has stopped functioning or is not completely administered. The alarm is logged about 15 minutes after the circuit pack has been removed or 11 minutes after the SAKI Test (#53) fails.

To be completely administered, a DS1 circuit pack must meet all 3 of the following conditions:

1. Have an entry in the circuit plan via the **change circuit pack** command
2. Be administered via the **add ds1 PCSS** command
3. Be physically inserted in the appropriate slot

If the circuit pack has an entry in the circuit plan and either of the other two conditions are *not* met, a MINOR alarm is logged. To resolve the error either

1. Make sure all conditions for administration are met and that a functioning DS1 circuit pack is inserted in the correct slot.
2. Completely remove the DS1-BD from the system using the following steps:
  - a. Remove any administered DS1 trunks or access endpoints associated with the circuit pack from their trunk groups.
  - b. Execute the **remove ds1 PCSS** and **change circuit pack PCSS** commands.

If all the administration conditions are met for this circuit pack and the red LED is still on, follow the instructions for *LED Alarms with Error Type 1* in Chapter 7.

- b. The DS1 Interface circuit pack has been busied out by a **busy-out board** PCSS command.
- c. The DS1-BD circuit pack is not completely administered. A completely administered DS1-BD circuit pack should have an entry in the circuit plan via the **change circuit pack** command, should have been administered via the **add ds1 PCSS** command, and should have been inserted into the appropriate port slot.
- d. The circuit pack in the slot does not match the type administered to that position. Either replace the circuit pack with one of the type administered, or use **change circuit-pack** to readminister the slot. This error may also indicate that the 24/32-channel selection on the DS1 administration form does not match the configuration of the circuit pack.
- e. This error is associated with the Common Port Circuit Pack Maintenance Test. Refer to [“XXX-BD \(Common Port Circuit Pack\)” on page 5-1343](#) for details.
- f. The DS1 Interface circuit pack has detected a transient hardware problem (for example, external RAM failure, internal RAM failure, internal ROM failure, or instruction set failure). This error will disappear when no faults are detected for 30 minutes. The value in the Aux Data field indicates the type of hardware problem. However, when this error is reported with Aux Data in the range of 4352 to 4358, it indicates the circuit pack has reported a hardware failure such that the circuit pack should be replaced.
- g. The DS1 Interface circuit pack has detected a transient hardware logic error (for example, program logic inconsistency). This error will disappear when no faults are detected for 100 minutes. The value in Aux Data field indicates the type of hardware problem.
- h. CSU Module missing. The *Near-End CSU Type* field on the **add ds1** form has been administered as *integrated* but the 120A CSU Module is not physically connected (or is improperly connected) to the TN767E board on the back of the port carrier.

If using the 120A CSU Module, plug (or replug) the CSU Module into the TN767E circuit pack's connector on the I/O connector panel on back of the carrier. Otherwise, change the *Near-End CSU Type* field using the **change ds1** form to *other*.

If this error remains after plugging the CSU Module into the board's connector, there could be a problem with the I/O connector panel.

- i. CSU Module not expected. The 120A CSU Module is physically connected to the TN767E board on the back of the port carrier but the *Near-End CSU Type* field on the **add ds1** form has not been administered as *integrated*.

5 Maintenance Objects for DEFINITY ONE  
DS1-BD (DS1 Interface Circuit Pack)

5-555

If the 120A CSU Module is to be used, use the **change ds1** command to change the *Near-End CSU Type* field to *integrated*. Otherwise, physically remove the 120A CSU Module from the back of the port carrier.

- j. DS1 configuration error. Attempting to use the 120A CSU Module with a TN767E circuit pack that is configured for 32-channel (2.048 Mbps) operation. The CSU Module only works with a DS1 board configured for 24-channel (1.544 Mbps) operation in the United States of America.
- k. DS1 circuit pack suffix incorrect for CSU Module. The *Near-End CSU Type* field on the **add ds1** form has been administered as *integrated* but the DS1 circuit pack is not a TN767E or later suffix DS1 board.

If the 120A CSU Module is to be used, remove the circuit pack and replace it with a TN767E or later suffix board. Otherwise, use the **change ds1** command to change the *Near-End CSU Type* field to *other*.

- l. BLB failure. This error occurs when the DS1 Board Loopback (BLB) demand test fails. Repeat the test using the following commands: **busyout board PCSS, test ds1-loop PCSS ds1/csu-loopback-tests, release board PCSS**. If the BLB test continues to fail, then the TN767E circuit pack needs to be replaced.
- m. ELB failure. This error occurs when the Integrated CSU (I-CSU) Module Equipment Loopback (ELB) test fails. This test is executed by the I-CSU during I-CSU power-up/reset (i.e., TN767E board physically inserted and 120A CSU Module already installed) or when the 120A CSU Module is plugged on to an already initialized DS1 board. The ELB test is also executed as part of the command **test ds1-loop PCSS ds1/csu-loopback-tests**.

Attempt to clear the alarm via the following commands: **busyout board PCSS, test ds1-loop PCSS ds1/csu-loopback-tests, and release board PCSS**. If the ELB test continues to fail, then either the TN767E board, the CSU Module, or the I/O cable between the backplane and the CSU module (or any combination thereof) has failed. Attempt to isolate where the failure is occurring by re-executing the test by replacing one piece of hardware at a time.

- n. RLB failure. This error occurs when the Integrated CSU (I-CSU) Module Repeater Loopback (RLB) test fails. This test is executed by the I-CSU during I-CSU power-up/reset (i.e., TN767E board physically inserted and 120A CSU Module already installed) or when the 120A CSU Module is plugged on to an already initialized DS1 board. The RLB test is also executed as part of the command **test ds1-loop PCSS ds1/csu-loopback-tests**.

Attempt to clear the alarm via the following commands: **busyout board PCSS, test ds1-loop PCSS ds1/csu-loopback-tests, and release board PCSS**. If the RLB test continues to fail, then the CSU Module needs to be replaced.

- o. CPE Loopback Jack deactivation error. This error occurs when the TN767E circuit pack could not deactivate a CPE Loopback Jack loopback.

Attempt to clear the alarm via the following commands: **busyout board PCSS**, **test ds1-loop PCSS end-loopback/span-test**, and **release board PCSS**. If the attempt to deactivate the CPE Loopback Jack loopback continues to fail, other steps must be taken to deactivate the loopback.

- p. Far CSU Loopback deactivation error. This error occurs when the TN767E circuit pack could not deactivate a far-end CSU loopback on power-up/reset or upon software request.

Attempt to clear the alarm via the following commands: *busyout board PCSS*, *test ds1-loop PCSS end-loopback/span-test*, *release board PCSS*. If the attempt to deactivate the Far CSU loopback continues to fail, then escalate the problem.

- q. The hyperactive circuit pack is out-of-service and may exhibit one or more of the following symptoms:
  - 1. The common circuit pack level tests such as Test #51 and/or Test #220 are aborting with error code 2000.
  - 2. The tests run on the ports of this circuit pack are returning NO BOARD.
  - 3. A busy-out/release of the circuit pack has no affect on test results.
  - 4. A **list configuration** command shows that the circuit pack and ports are properly installed.

The circuit pack is isolated from the system and all trunks of this circuit pack are placed into the out-of-service state. The system will try to restore the circuit pack within 15 minutes. When no faults are detected for 15 minutes, the DS1 Interface circuit pack is restored to normal operation. All trunks of the DS1 Interface circuit pack are then returned to the in-service state. If the error recurs after 15 minutes, then replace the circuit pack.

- r. For later releases of G3V4 and beyond, only error 3073 will show that this board is receiving Slips and the AUX data shows the last Slip count that was reported.
- s. For later releases of G3V4 and beyond, only error 3329 will show that this board is receiving misframes and the AUX data shows the last misframe count that was reported.
- t. This error is not service-affecting and can be ignored.

- u. Error 3900 is used to give status information on a CPE Loopback Jack Test. The value in the Aux Data field indicates the status of the loopback test.
    - 1 — Test is currently running.
    - 2 — Test failed because loopback could not be activated.
    - 3 — Test failed because test pattern could not be detected.
    - 4 — Test has been terminated.
  - v. Error 3901 is used to give status information on a Far CSU Loopback Test. The value in the Aux Data field indicates the status of the loopback test.
    - 1 — Test is currently running.
    - 2 — Test failed because loopback could not be activated.
    - 3 — Test failed because test pattern could not be detected.
    - 4 — Test has been terminated.
  - w. Error 3902 is used to give status information on a One-Way Span Test. The value in the Aux Data field indicates the status of the span test.
    - 1 — Test is currently running.
    - 2 — Test has failed because test could not be activated.
    - 3 — Test pattern was not received from the far end.
    - 4 — Test has been terminated.
  - x. Error type 3999 indicates that the circuit pack sent a large number of control channel messages to the switch within a short period of time. If error type 1538 is also present, then the circuit pack was taken out-of-service due to hyperactivity. If error type 1538 is not present, then the circuit pack has not been taken out-of-service, but it has generated 50% of the messages necessary to be considered hyperactive. This may be completely normal during heavy traffic periods. However, if this error type is logged when the circuit pack is being lightly used, it may indicate a problem with the circuit pack or the equipment attached to it.
- 

## System Technician-Demanded Tests: Descriptions and Error Codes

---

Always investigate tests in the order they are presented in [“System Technician-Demanded Tests: Descriptions and Error Codes”](#). By clearing error codes associated with the *NPE Connection Audit Test*, for example, you may also clear errors generated from other tests in the testing sequence

5 Maintenance Objects for DEFINITY ONE  
DS1-BD (DS1 Interface Circuit Pack)

5-558

Table 5-221. System Technician-Demanded Tests: DS1-BD

Order of Investigation	Short Test Sequence	Long Test Sequence	Reset Board Sequence	test ds1-loop Command	D/ND <sup>1</sup>
NPE Connection Audit Test (#50)		X			ND
Control Channel Loop Test (#52)		X			ND
Loss of Signal Alarm Inquiry Test (#138)	X	X			ND
Blue Alarm Inquiry Test (#139)	X	X			ND
Red Alarm Inquiry Test (#140)	X	X			ND
Yellow Alarm Inquiry Test (#141)	X	X			ND
Major Alarm Inquiry Test (#142)	X	X			ND
Minor Alarm Inquiry Test (#143)	X	X			ND
Slip Alarm Inquiry Test (#144)	X	X			ND
Misframe Alarm Inquiry Test (#145)	X	X			ND
Translation Update Test (#146)	X	X			ND
ICSU Status LEDs Test (#1227)	X	X			ND
SAKI Sanity Test (#53)			X		D
Internal Looparound Test (#135)			X		D
DS1/CSU Loopback Tests				X	D
DS1 Board Loopback Test (#1209)				X	D
CSU Equipment Loopback Test (#1210)				X	D
CSU Repeater Loopback Test (#1211)				X	D
CPE Loopback Jack Test (#1212)				X	D
Far CSU Loopback Test (#1213)				X	D
One-Way Span Test (#1214)				X	D
Inject Single Bit Error (#1215)				X	D
End Loopback/Span Test (#1216)				X	D

1. D = Destructive, ND = Non-destructive

**NPE Connection Audit Test (#50):**

The system sends a message to the on-board microprocessor to update the network connectivity translation for all the Network Processing Elements (NPEs) on the circuit pack.

**Table 5-222. TEST #50 NPE Connection Audit Test**

Error Code	Test Result	Description/ Recommendation
None 2100	ABORT	System resources required for this test are not available.
1019	ABORT	Test already in progress.
	FAIL	Internal system error 1. Retry the command at 1-minute intervals a maximum of 5 times.
	PASS	The circuit pack's NPEs have been updated with their translation.
0	NO BOARD	The test could not relate the internal ID to the port (no board). This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted. 1. Check to ensure that the board translations are correct. Use the <b>add ds1 PCSS</b> command to administer the DS1 interface if it is not already administered. 2. If board was already administered correctly, check the error log to determine if the board is hyperactive. If this is the case, the board is shut down. Reseating the board will re-initialize the board. 3. Issue the <b>busyout board</b> command. 4. Issue the <b>reset board</b> command. 5. Issue the <b>release busy board</b> command. 6. Issue the <b>test board long</b> command. This should re-establish the linkage between the internal ID and the port.

## Control Channel Looparound Test (#52)

This test queries the circuit pack for its circuit pack code and vintage and verifies its records.

Table 5-223. TEST #52 Control Channel Looparound Test

Error Code	Test Result	Description/ Recommendation
None 2100	ABORT	System resources required for this test are not available. 1. Retry the command at 1-minute intervals a maximum of 5 times.
	FAIL	<p>The test failed because the circuit pack did not return the circuit pack code or vintage.</p> <p><b>⇒ NOTE:</b> Error type 1538 in the error log indicates hyperactivity. The hyperactive circuit pack is out of service and one or more of the following symptoms may be exhibited.</p> <ol style="list-style-type: none"> <li>1. The DS1-BD tests (such as Test 138 and Test 139) are aborting with error code 2000.</li> <li>2. The tests run on the ports of this circuit pack are returning a no board result.</li> <li>3. A <b>busyout</b> or a <b>release</b> command has no affect on the test result.</li> <li>4. A <b>list config</b> command shows that the circuit pack and the ports are properly installed.</li> </ol> <p>When hyperactivity occurs, the circuit pack is isolated from the system, and all of the trunks for this circuit pack are placed into the out of service state. The system will try to restore the circuit pack within 15 minutes. When no faults are detected for 15 minutes, the DS1 interface circuit pack is restored to normal operation. All of the trunks for the DS1 interface circuit pack are then returned to the in service state. Hyperactivity is often caused by the associated facility. In such a case, faults (such as slips, misframes, or blue alarms) would be entered in the error log. In addition, many hardware errors would be logged against the associated trunk circuits. If the facility is OK and the error occurs again after 15 minutes, replace the circuit pack.</p> <ol style="list-style-type: none"> <li>1. Retry the command for a maximum of 5 times.</li> <li>2. If the problem continues, check for hyperactivity. Resolve the problem, as appropriate.</li> <li>3. If there is no longer hyperactivity, retry the command for a maximum of 5 times.</li> <li>4. If the test continues to fail, replace the circuit pack.</li> </ol>
	PASS	Communication with this circuit pack is successful.

*Continued on next page*

Table 5-223. TEST #52 Control Channel Looparound Test — *Continued*

Error Code	Test Result	Description/ Recommendation
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board).</p> <p>This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"> <li>1. Check to ensure that the board translations are correct. Use the <b>add ds1 PCSS</b> command to administer the DS1 interface if it is not already administered.</li> <li>2. If board was already administered correctly, check the error log to determine if the board is hyperactive. If this is the case, the board is shut down. Reseating the board will re-initialize the board.</li> <li>3. If the board was found to be correctly inserted in step 1, issue the <b>busyout board</b> command.</li> <li>4. Issue the <b>reset board</b> command.</li> <li>5. Issue the <b>release busy board</b> command.</li> <li>6. Issue the <b>test board long</b> command.</li> </ol> <p>This should re-establish the linkage between the internal ID and the port.</p>

### SAKI Sanity Test (#53)

**This test is destructive. This test resets the circuit pack.**

Table 5-224. TEST #53 SAKI Sanity Test

Error Code	Test Result	Description/ Recommendation
None	ABORT	<p>System resources required for this test are not available.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
1005	ABORT	<p>Wrong circuit pack configuration to run this test. This error applies only to DS1 Interface circuit packs. It means the DS1 Interface circuit pack is providing timing for the system and, therefore, it cannot be reset without major system disruptions.</p> <ol style="list-style-type: none"> <li>1. If the circuit pack needs to be reset, then set synchronization to another DS1 Interface circuit pack or to the Tone-Clock circuit pack and try again. Refer to <a href="#">“SYNC (Synchronization)” on page 5-1063</a>.</li> </ol>

*Continued on next page*

Table 5-224. TEST #53 SAKI Sanity Test — *Continued*

Error Code	Test Result	Description/ Recommendation
1015	ABORT	Port is not out-of-service. <ol style="list-style-type: none"> <li>1. Busyout the circuit pack.</li> <li>2. Execute the command again.</li> </ol>
2100	ABORT	System resources required for this test are not available. <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
1	FAIL	The circuit pack failed to reset.
2	FAIL	The circuit pack failed to restart. <ol style="list-style-type: none"> <li>1. Execute the command again.</li> <li>2. If the problem persists, replace the circuit pack.</li> </ol>
	PASS	The circuit pack initializes correctly. <ol style="list-style-type: none"> <li>1. Run the Short Test Sequence.</li> </ol>
0	NO BOARD	The test could not relate the internal ID to the port (no board). This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted. <ol style="list-style-type: none"> <li>1. Check to ensure that the board translations are correct. Use the <b>add ds1 PCSS</b> command to administer the DS1 interface if it is not already administered.</li> <li>2. If board was already administered correctly, check the error log to determine if the board is hyperactive. If this is the case, the board is shut down. Reseating the board will re-initialize the board.</li> <li>3. If the board was found to be correctly inserted in step 1, issue the <b>busyout board</b> command.</li> <li>4. Issue the <b>reset board</b> command.</li> <li>5. Issue the <b>release busy board</b> command.</li> <li>6. Issue the <b>test board long</b> command.</li> </ol> This should re-establish the linkage between the internal ID and the port.

## Internal Looparound Test (#135)

**This test is destructive.**

The Internal Looparound Test is run by looping the transmitted DS1 bit stream back into the DS1's board receiver. The loop occurs just before the DS1 facility interface. The test is highly destructive and can only be initiated by a system technician-demanded **reset board PCSS** command.

All trunks on the DS1 Interface circuit pack must be busied out via the system technician **busy-out board** command before running the Internal Looparound Test. When the Internal Looparound Test is initiated, maintenance software sends appropriate messages to the DS1 Interface circuit pack to start the test. The test uses the Tone Generator and Tone Detector to exercise a bit pattern consistency test for all ports. If the transmitted and received bit patterns on a trunk are different, the test fails.

When the test is complete, the maintenance software sends a stop loop around message to the DS1 Interface circuit pack to put the circuit pack back into the normal operation mode. All trunks of the DS1 Interface circuit pack are restored to the in-service state after the **release board** command is entered

Table 5-225. TEST #135 Internal Looparound Test

Error Code	Test Result	Description/ Recommendation
2012	ABORT	Internal system error <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
1002	ABORT	The system could not allocate time slots for the test. The system may be under heavy traffic conditions or it may have time slots out-of-service due to TDM-BUS errors. Refer to <a href="#">"TDM-BUS (TDM Bus)" on page 5-1116</a> to diagnose TDM-BUS errors. <ol style="list-style-type: none"><li>1. If system has no TDM-BUS errors and is not handling heavy traffic, repeat test at 1-minute intervals a maximum of 5 times.</li></ol>
1003	ABORT	The system could not allocate a tone receiver for the test. The system may be oversized for the number of Tone Detectors present or some Tone Detectors may be out-of-service. <ol style="list-style-type: none"><li>1. Resolve any "TTR-LEV" errors in the Error Log.</li><li>2. Resolve any "TONE-PT" errors in the Error Log.</li><li>3. If neither condition exists, retry the test at 1-minute intervals a maximum of 5 times.</li></ol>

*Continued on next page*

Table 5-225. TEST #135 Internal Looparound Test — *Continued*

Error Code	Test Result	Description/ Recommendation
1004	ABORT	Received an incoming call on a port of the DS1 circuit pack during the test. <ol style="list-style-type: none"><li>1. Enter the <b>busy-out board PCSS</b> command to put all trunks of DS1 Interface circuit pack to out-of-service state.</li><li>2. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
1015	ABORT	Ports on DS1 Interface circuit pack have not been busied out. <ol style="list-style-type: none"><li>1. Enter the <b>busy-out board PCSS</b> command to put all trunks of the DS1 Interface circuit pack into out-of-service state.</li><li>2. Retry the command.</li></ol>
1039	ABORT	The DS1 Interface circuit pack is providing timing for the system. Therefore, it cannot be reset without major system disruption. <ol style="list-style-type: none"><li>1. If the DS1 Interface circuit pack needs to be tested, set the synchronization reference to another DS1 Interface circuit pack or to the Tone-Clock circuit pack via the following command sequence:<ul style="list-style-type: none"><li>■ Issue the <b>disable synchronization-switch</b> command.</li><li>■ Next, issue the <b>set synchronization PCSS</b> command.</li><li>■ Lastly, issue the <b>enable synchronization-switch</b> command.</li></ul></li></ol>

*Continued on next page*

Table 5-225. TEST #135 Internal Looparound Test — *Continued*

Error Code	Test Result	Description/ Recommendation
2000	ABORT	<p>The test was aborted. Response to the test was not received within the allowable time period. This may be due to hyperactivity. Error type 1538 in the error log indicates hyperactivity. The hyperactive circuit pack is out of service and one or more of the following symptoms may be exhibited.</p> <ol style="list-style-type: none"> <li>1. The DS1-BD tests (such as Test 139 and Test 140) are aborting with error code 2000.</li> <li>2. The tests run on the ports of this circuit pack are returning a no board result.</li> <li>3. A <b>busyout</b> or a <b>release</b> command has no affect on the test results.</li> <li>4. A <b>list config</b> command shows that the circuit pack and the ports are properly installed.</li> </ol> <p><b>⇒ NOTE:</b> When hyperactivity occurs, the circuit pack is isolated from the system, and all of the trunks for this circuit pack are placed into the out of service state. The system will try to restore the circuit pack within 15 minutes. When no faults are detected for 15 minutes, the DS1 interface circuit pack is restored to normal operation. All of the trunks for the DS1 interface circuit pack are then returned to the in service state. Hyperactivity is often caused by the associated facility. In such a case, faults (such as slips, misframes, or blue alarms) would be entered in the error log. In addition, many hardware errors would be logged against the associated trunk circuits. If the facility is OK and the error occurs again after 15 minutes, replace the circuit pack.</p>
2100	ABORT	<p>Could not allocate the necessary system resources to run this test.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals for a maximum of 5 times.</li> </ol>
	FAIL	<p>DS1 Interface circuit pack failed in the Internal Looparound Test.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> <li>2. If the DS1 Interface circuit pack is TN767, enter the <b>list measurement ds1-log PCSS</b> command to read the error seconds measurement. Otherwise, skip this step.</li> <li>3. Verify that both endpoints of the DS1 link are administered using the same signaling mode, framing mode, and line coding.</li> <li>4. Check the physical connectivity of DS1 Interface circuit packs and cable.</li> <li>5. If all of the above are OK, replace the local DS1 Interface circuit pack and repeat the test.</li> <li>6. Contact T1 Network Service to diagnose remote DS1 endpoint.</li> </ol>

*Continued on next page*

Table 5-225. TEST #135 Internal Looparound Test — *Continued*

Error Code	Test Result	Description/ Recommendation
	PASS	All administered trunks of DS1 Interface circuit pack pass the Internal Looparound Test. The bit pattern consistency test is executed successfully over the path that covers a DS1 port, cable, and the external NCTE device.
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board).</p> <p>This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"><li>1. Check to ensure that the board translations are correct. Use the <b>add ds1 PCSS</b> command to administer the DS1 interface if it is not already administered.</li><li>2. If board was already administered correctly, check the error log to determine if the board is hyperactive. If this is the case, the board is shut down. Reseating the board will re-initialize the board.</li><li>3. If the board was found to be correctly inserted in step 1, issue the <b>busyout board</b> command.</li><li>4. Issue the <b>reset board</b> command.</li><li>5. Issue the <b>release busy board</b> command.</li><li>6. Issue the <b>test board long</b> command.</li></ol> <p>This should re-establish the linkage between the internal ID and the port.</p>

## Loss of Signal Alarm Inquiry Test (#138)

This test verifies the synchronization status and continuity of the DS1 link. The Loss of Signal alarm indicates that the DS1 Interface circuit pack is unable to derive the synchronization clock from the DS1 facility. When the DS1 Interface circuit pack detects a Loss of Signal alarm, it stops providing the synchronization clock for the system if it is administered as a timing source and transmits a Yellow alarm to the remote DS1 endpoint.

When the Loss of Signal alarm is confirmed, the maintenance software places all trunks or ports of the DS1 Interface circuit pack into the out-of-service state. The inquiry test will run every 10 minutes until the loss of signal has been restored. The DS1 Interface circuit pack raises a Loss of Signal alarm after the signal has been lost for about 1second. It will not retire the alarm until the signal has returned for about 10 seconds.

This test is also used to maintain the new 120A CSU Module. This Module, when combined with the functionality provided by the TN767E circuit pack, provides functionality equivalent to an external standalone ESF T1 CSU.

If a TN767E circuit pack detects certain ICSU hardware errors, it will notify maintenance. When the maintenance subsystem receives notification of the I-CSU error, it will execute this Loss of Signal Inquiry test. The test, in addition to querying for a Loss Of Signal alarm condition, will also query the TN767E board to confirm the I-CSU error. A Minor or Warning alarm will be raised depending on the severity of the ICSU error. The trunks on the board may be taken out of service if the ICSU error is deemed serious.

If a Loss Of Signal alarm and an ICSU error co-exist, the Loss Of Signal alarm condition will take priority and the board and all trunks on the board will be put in the out-of-service state. Errors will be logged, however, for both.

When the maintenance subsystem receives notification that the ICSU hardware error condition no longer exists, maintenance will restore the board and all trunks to their previous service state if the alarm can be cleared (no other ICSU errors or Loss Of Signal alarm exist)

Table 5-226. TEST #138 Loss of Signal Alarm Inquiry Test

Error Code	Test Result	Description/ Recommendation
2100	ABORT	Internal system error
	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals a maximum of 5 times.

*Continued on next page*

Table 5-226. TEST #138 Loss of Signal Alarm Inquiry Test — Continued

Error Code	Test Result	Description/ Recommendation
2000	ABORT	<p>Response to the test was not received within the allowable time period. This may be due to hyperactivity. Error type 1538 in the error log indicates hyperactivity. The hyperactive circuit pack is out of service and one or more of the following symptoms may be exhibited.</p> <ol style="list-style-type: none"> <li>1. The DS1-BD tests (such as test 138 and test 139) are aborting with error code 2000.</li> <li>2. The tests run on the ports of this circuit pack are returning a no board result.</li> <li>3. A <b>busyout</b> or a <b>release</b> command has no affect on the test results.</li> <li>4. A <b>list config</b> command shows that the circuit pack and the ports are properly installed.</li> </ol> <p> <b>NOTE:</b> When hyperactivity occurs, the circuit pack is isolated from the system, and all of the trunks for this circuit pack are placed into the out of service state. The system will try to restore the circuit pack within 15 minutes. When no faults are detected for 15 minutes, the DS1 interface circuit pack is restored to normal operation. All of the trunks for the DS1 interface circuit pack are then returned to the in service state. Hyperactivity is often caused by the associated facility. In such a case, faults (such as slips, misframes, or blue alarms) would be entered in the error log. In addition, many hardware errors would be logged against the associated trunk circuits. If the facility is OK and the error occurs again after 15 minutes, replace the circuit pack.</p>
	FAIL	<p>DS1 Interface circuit pack detects a Loss of Signal alarm. The physical link is broken or the remote DS1 endpoint is down. All trunks or ports of this DS1 interface circuit pack are out-of-service. If the DS1 Interface circuit pack is designated as the supplier of the system synchronization source, then the system synchronization maintenance will adopt a source elsewhere. Refer to "SYNC (Synchronization)" section for details.</p> <ol style="list-style-type: none"> <li>1. If the DS1 Interface circuit pack connects to a T1 facility, call the vendor of the T1 carrier to diagnose the remote DS1 endpoint. If the DS1 Interface circuit pack connects directly to a switch, call the system technician of the remote switch to diagnose the DS1 endpoint.</li> <li>2. Check the physical connection of the DS1 Interface circuit pack and the cable. If a 120A CSU Module is physically connected to a TN767E board on the back of the port carrier, check the physical connection of the CSU Module and make sure the Network Interface cable is plugged into the CSU Module's NETWORK jack.</li> </ol>

Continued on next page

Table 5-226. TEST #138 Loss of Signal Alarm Inquiry Test — *Continued*

Error Code	Test Result	Description/ Recommendation
1300	FAIL	<p>The CSU Module is missing. The <i>Near-End CSU Type</i> field on the <i>add ds1</i> form has been administered as <i>integrated</i> but the 120A CSU Module is not physically connected to the TN767E board on the back of the port carrier.</p> <ol style="list-style-type: none"> <li>1. If using the 120A CSU Module, plug the CSU Module into the TN767E circuit pack's connector on the I/O connector panel on back of the carrier. Otherwise, change the <i>Near-End CSU Type</i> field using the <i>change ds1</i> form to <i>other</i>.</li> <li>2. Run the test again.</li> </ol>
1301	FAIL	<p>The 120A CSU Module is physically connected to the TN767E board on the back of the port carrier but the <i>Near-End CSU Type</i> field on the <i>add ds1</i> form has not been administered as <i>integrated</i>.</p> <ol style="list-style-type: none"> <li>1. If the 120A CSU Module is to be used, use the <i>change ds1</i> command to change the <i>Near-End CSU Type</i> field to <i>integrated</i>. Otherwise, physically remove the 120A CSU Module from the back of the port carrier.</li> <li>2. Run the test again.</li> </ol>
1302	FAIL	<p>Attempting to use the 120A CSU Module with a TN767E circuit pack that is configured for 32-channel (2.048 Mbps) operation. The CSU Module only works with a DS1 board configured for 24-channel (1.544 Mbps) operation in the United States of America.</p> <ol style="list-style-type: none"> <li>1. If the 120A CSU Module is to be used, physically remove the TN767E circuit pack and reconfigure for 24-channel (1.544 Mbps) operation.</li> <li>2. Reinsert the circuit pack and run the test again.</li> </ol>
1303	FAIL	<p>The DS1 circuit pack Suffix is incorrect for CSU Module administration. The <i>Near-End CSU Type</i> field on the <i>add ds1</i> form has been administered as <i>integrated</i> but the DS1 circuit pack is not a TN767E or later suffix DS1 board.</p> <ol style="list-style-type: none"> <li>1. If the CSU Module is to be used, and the <i>Near-End CSU Type</i> field is set to <i>integrated</i>, to allow for CSU module administration, remove the circuit pack and replace it with a TN767E or later suffix board. Otherwise use the <b>change ds1</b> command to change the <i>Near-End CSU Type</i> field to <b>other</b>.</li> </ol>
1310	FAIL	<p>The DS1 Board Loopback (BLB) demand test (#1209) failed.</p> <ol style="list-style-type: none"> <li>1. Repeat the test using the <b>test ds1-loop PCSS ds1/csu-loopback-tests</b> command.</li> <li>2. If the BLB test continues to fail, then replace the TN767E circuit pack.</li> <li>3. Run this test again.</li> </ol>

*Continued on next page*

5 Maintenance Objects for DEFINITY ONE  
DS1-BD (DS1 Interface Circuit Pack)

5-570

Table 5-226. TEST #138 Loss of Signal Alarm Inquiry Test — Continued

Error Code	Test Result	Description/ Recommendation
1311	FAIL	<p>The Integrated CSU (I-CSU) Module Equipment Loopback (ELB) test (#1210) failed. This test is executed by the ICSU during ICSU power-up/reset (TN767E board physically inserted and 120A CSU Module already installed) or when the 120A CSU Module is plugged on to an already initialized DS1 board. The ELB test is also executed as part of the command <b>test ds1-loop PCSS ds1/csu-loopback-tests</b>.</p> <ol style="list-style-type: none"> <li>1. Execute <b>test ds1-loop PCSS ds1/csu-loopback-tests</b>.</li> <li>2. If the ELB test continues to fail, then either the TN767E board, the CSU Module, or the I/O cable between the backplane and the CSU module (or any combination thereof) has failed. Attempt to isolate the problem to one of these areas. Begin by replacing the CSU Module and running the <b>test ds1-loop PCSS ds1/csu-loopback-tests</b> command again.</li> <li>3. If the ELB test continues to fail, then replace the TN767E board and run <b>test ds1-loop PCSS ds1/csu-loopback-tests</b> again.</li> <li>4. If the ELB test continues to fail, the problem could be in the I/O cable between the backplane and the CSU module.</li> </ol>
1312	FAIL	<p>The Integrated CSU (I-CSU) Module Repeater Loopback (RLB) test (#1211) failed. This test is executed by the ICSU during ICSU power-up/reset (TN767E board physically inserted and 120A CSU Module already installed) or when the 120A CSU Module is plugged on to an already initialized DS1 board. The RLB test is also executed as part of the command <b>test ds1-loop PCSS ds1/csu-loopback-tests</b>.</p> <ol style="list-style-type: none"> <li>1. Execute <b>test ds1-loop PCSS ds1/csu-loopback-tests</b>.</li> <li>2. If the RLB test continues to fail, then replace the CSU Module.</li> <li>3. Run this test again.</li> </ol>
1313	FAIL	<p>The TN767E circuit pack could not deactivate a CPE Loopback Jack loopback.</p> <ol style="list-style-type: none"> <li>1. Execute <b>test ds1-loop PCSS end-loopback/span-test</b>.</li> <li>2. If the attempt to deactivate the CPE Loopback Jack is not successful, check the cabling and investigate the problem at the CPE Loopback Jack.</li> <li>3. Run the test again.</li> </ol>
1314	FAIL	<p>The TN767E circuit pack could not deactivate a far-end CSU loopback.</p> <ol style="list-style-type: none"> <li>1. Execute <b>test ds1-loop PCSS end-loopback/span-test</b>.</li> </ol>

Continued on next page

Table 5-226. TEST #138 Loss of Signal Alarm Inquiry Test — Continued

Error Code	Test Result	Description/ Recommendation
1320	FAIL	<p>A 120A CSU module hardware failure or an ICSU serial interface audit failure was detected by the TN767E DS1 circuit pack.</p> <ol style="list-style-type: none"> <li>1. Replace the CSU module, and then run the test again.</li> <li>2. If the test continues to fail with this error code, replace the TN767E and run the test again.</li> <li>3. If the test continues to fail with this error code, the problem could be in the I/O cable between the backplane and the CSU module.</li> </ol>
1321	FAIL	<p>DTE LOS (loss of signal) was detected between the TN767E DS1 board and the 120A CSU Module. Either the TN767E board, the 120A CSU Module, or the I/O cable between the backplane and the CSU module (or any combination thereof) has failed. Attempt to isolate the problem to one of these areas.</p> <ol style="list-style-type: none"> <li>1. Replace the CSU Module and run the test again.</li> <li>2. If the test continues to fail with this error code, then replace the TN767E board and run the test again.</li> <li>3. If the test continues to fail with this error code, the problem could be in the I/O cable between the backplane and the CSU module.</li> </ol>
1322	FAIL	<p>No 5-volt power detected from the TN767E circuit pack to the 120A CSU Module. Problem probably due to an open fuse on the DS1 board or a faulty ICSU. <b>NOTE</b> <i>Do not swap DS1 boards as this may open the fuse on the new board.</i></p> <ol style="list-style-type: none"> <li>1. Remove the TN767E from the system and reinsert.</li> <li>2. Run the test again once the board has finished its reset.</li> <li>3. If the test continues to fail with this error code, then replace the CSU Module and run the test again.</li> <li>4. If the test continues to fail with this error code, then replace the TN767E board and run the test again.</li> <li>5. If the test continues to fail with this error code, the problem could be in the I/O cable between the backplane and the CSU module.</li> </ol>
1323	FAIL	<p>A service affecting CSU Module audit failure was detected by the TN767E DS1 circuit pack. All administered ports on the DS1 circuit pack are affected and maintenance software will place the ports into the out-of-service state.</p> <ol style="list-style-type: none"> <li>1. Replace the 120A CSU Module.</li> </ol>
1324	FAIL	<p>A non-service affecting CSU Module audit failure was detected by the TN767E DS1 circuit pack. No ports should be affected. No immediate action is required. These errors indicate that the CSU Module hardware may have a problem, and that it should be replaced when practical to avoid further deterioration.</p>

Continued on next page

Table 5-226. TEST #138 Loss of Signal Alarm Inquiry Test — *Continued*

Error Code	Test Result	Description/ Recommendation
	PASS	DS1 signal is present and the physical link is healthy. In addition, no Integrated CSU errors are detected.
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board).</p> <p>This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"><li>1. Check to ensure that the board translations are correct. Use the <b>add ds1 PCSS</b> command to administer the DS1 interface if it is not already administered.</li><li>2. If board was already administered correctly, check the error log to determine if the board is hyperactive. If this is the case, the board is shut down. Reseating the board will re-initialize the board.</li><li>3. If the board was found to be correctly inserted in step 1, issue the <b>busyout board</b> command.</li><li>4. Issue the <b>reset board</b> command.</li><li>5. Issue the <b>release busy board</b> command.</li><li>6. Issue the <b>test board long</b> command.</li></ol> <p>This should re-establish the link between the internal ID and the port.</p>

### Blue Alarm Inquiry Test (#139)

The Blue Alarm is a signal sent by the remote DS1 endpoint when it is out-of-service. The Blue Alarm Inquiry Test checks the blue alarm status of the remote DS1 endpoint.

When the DS1 Interface circuit pack detects a Blue Alarm signal from the remote DS1 endpoint, the circuit pack will transmit a Yellow alarm to the remote DS1 endpoint and send a BLUE ALARM message to the maintenance software. When the Blue alarm is confirmed, the maintenance software places all trunks of the DS1 Interface circuit pack into the out-of-service state. The inquiry test will be run every 10 minutes until the Blue alarm is cleared.

The DS1 Interface circuit pack takes 2 seconds to recognize and report a Blue alarm and 16 seconds to recognize and report the resolution of a Blue alarm. When the Blue alarm is cleared, the DS1 Interface circuit pack stops transmitting the Yellow alarm and places the trunks back into the service state before the Blue alarm occurs.

## Line Loopback Alarm

The Line Loopback (LLB) is used by the remote DS1 endpoint to put the ICSU or DS1 into a loopback mode. When the ICSU or DS1 Board is in the LLB mode, the arriving bit pattern is regenerated and sent back. Line Loopback (LLB) Alarm is activated when the in-band activate LLB bit pattern has been arriving continuously for 5 seconds on the DS1 line. LLB is deactivated when the in-band deactivate LLB bit pattern has been arriving continuously for 5 seconds on the DS1 line.

Since LLB is a maintenance condition rendering all DS0 channels unavailable for signaling or bearer traffic, maintenance software treats this the same as a Blue Alarm.

## Payload Loopback Alarm

The Payload Loopback (PLB) is used by the remote DS1 endpoint to put the switch DS1 into a loopback mode. PLB Alarm is activated when a network protocol activate bit pattern arrives over the 4-Kbps ESF data link on the DS1 line. PLB is deactivated when a network protocol deactivate bit pattern arrives over the 4-Kbps ESF data link on the DS1 line.

Since PLB is a maintenance condition rendering all DS0 channels unavailable for signaling or bearer traffic, maintenance software treats this the same as a Blue Alarm.

Table 5-227. TEST #139 Blue Alarm Inquiry Test

Error Code	Test Result	Description/ Recommendation
2100	ABORT	Internal system error
	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals a maximum of 5 times.

*Continued on next page*

Table 5-227. TEST #139 Blue Alarm Inquiry Test — *Continued*

Error Code	Test Result	Description/ Recommendation
2000	ABORT	<p>Response to the test was not received within the allowable time period. This may be due to hyperactivity. Error type 1538 in the error log indicates hyperactivity. The hyperactive circuit pack is out of service and one or more of the following symptoms may be exhibited.</p> <ol style="list-style-type: none"> <li>1. The DS1-BD tests (such as test 138 and test 139) are aborting with error code 2000.</li> <li>2. The tests run on the ports of this circuit pack are returning a no board result.</li> <li>3. A <b>busyout</b> or a <b>release</b> command has no affect on the test results.</li> <li>4. A <b>list config</b> command shows that the circuit pack and the ports are properly installed.</li> </ol> <p> <b>NOTE:</b> When hyperactivity occurs, the circuit pack is isolated from the system, and all of the trunks for this circuit pack are placed into the out of service state. The system will try to restore the circuit pack within 15 minutes. When no faults are detected for 15 minutes, the DS1 interface circuit pack is restored to normal operation. All of the trunks for the DS1 interface circuit pack are then returned to the in service state. Hyperactivity is often caused by the associated facility. In such a case, faults (such as slips, misframes, or blue alarms) would be entered in the error log. In addition, many hardware errors would be logged against the associated trunk circuits. If the facility is OK and the error occurs again after 15 minutes, replace the circuit pack.</p>
	FAIL	<p>The remote DS1 endpoint is out-of-service.</p> <ol style="list-style-type: none"> <li>1. If the DS1 interface circuit pack connects to a T1 facility, call the vendor of the T1 carrier to diagnose the remote endpoint.</li> <li>2. If the DS1 interface circuit pack connects directly to a switch, call the system technician of the remote switch to diagnose the DS1 endpoint.</li> </ol>
1794	FAIL	<p>The DS1 Interface circuit pack detects a Line Loopback Alarm (LLB).</p> <ol style="list-style-type: none"> <li>1. If the DS1 interface circuit pack connects to a T1 facility, call the vendor of the T1 carrier to diagnose the remote DS1 endpoint.</li> <li>2. If the DS1 interface circuit pack connects directly to a switch, call the system technician of the remote switch to diagnose the DS1 endpoint.</li> <li>3. If the DS1 interface circuit pack connects directly to a line-side terminating device (for example, a PRI terminal adapter), call the vendor of the terminating device to diagnose the equipment.</li> </ol>

*Continued on next page*

Table 5-227. TEST #139 Blue Alarm Inquiry Test — *Continued*

Error Code	Test Result	Description/ Recommendation
1795	FAIL	The DS1 Interface circuit pack detects a Payload Loopback Alarm (PLB). If the DS1 Interface circuit pack connects to a leased T1 facility, call the vendor of the T1 carrier to diagnose the remote DS1 endpoint. If the DS1 Interface circuit pack connects directly to another DS1 board, call the system technician of the remote switch to diagnose the DS1 endpoint.
	PASS	Remote DS1 endpoint is in-service. Neither a Blue alarm nor a Line Loopback alarm nor a Payload Loopback alarm is detected in the DS1 Interface circuit pack.
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board).</p> <p>This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"> <li>1. Check to ensure that the board translations are correct. Use the <b>add ds1 PCSS</b> command to administer the DS1 interface if it is not already administered.</li> <li>2. If board was already administered correctly, check the error log to determine if the board is hyperactive. If this is the case, the board is shut down. Reseating the board will re-initialize the board.</li> <li>3. If the board was found to be correctly inserted in step 1, issue the <b>busyout board</b> command.</li> <li>4. Issue the <b>reset board</b> command.</li> <li>5. Issue the <b>release busy board</b> command.</li> <li>6. Issue the <b>test board long</b> command.</li> </ol> <p>This should re-establish the link between the internal ID and the port.</p>

### Red Alarm Inquiry Test (#140)

DS1 Interface circuit pack raises a Red alarm when the framing pattern of the incoming DS1 bit stream has been lost. The Red Alarm Inquiry Test checks the framing status of a DS1 Interface circuit pack. DS1 Interface circuit pack takes 3 seconds to recognize and report a Red alarm and 10 seconds to recognize and report the resolution of a Red alarm.

When the DS1 Interface circuit pack detects a Red alarm, the circuit pack will transmit a Yellow alarm to the remote DS1 endpoint and send a RED ALARM message to the maintenance software. After the Red alarm is confirmed, the maintenance software places all trunks of the circuit pack into the out-of-service state. The inquiry test will be run every 10 minutes until the Red alarm is cleared.

When the Red alarm is cleared, the DS1 Interface circuit pack will stop transmitting the Yellow alarm to the remote DS1 endpoint. The maintenance software restores all trunks of the DS1 Interface circuit pack to the service state before the Red alarm occurs.

Loss of Multiframe Alarm: If the DS1 Interface circuit pack is administered using DMI-BOS signaling, the DS1 Interface circuit pack raises a Loss of Multiframe Alarm (LMA) when it cannot interpret the incoming signaling bits to synchronize to the multiframe pattern received in the 24th channel. Once DS1 Interface circuit pack detects an LMA, the circuit pack will transmit a Remote Multiframe Alarm (RMA) to the remote DS1 endpoint. Maintenance software handles both Red alarm and LMA alarm(s) using the same mechanism.

Table 5-228. TEST #140 Red Alarm Inquiry Test

Error Code	Test Result	Description/ Recommendation
2100	ABORT	Internal system error
	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals a maximum of 5 times.
2000	ABORT	Response to the test was not received within the allowable time period. This may be due to hyperactivity. Error type 1538 in the error log indicates hyperactivity. The hyperactive circuit pack is out of service and one or more of the following symptoms may be exhibited.  1. The DS1-BD tests (such as test 138 and test 139) are aborting with error code 2000.  2. The tests run on the ports of this circuit pack are returning a no board result.  3. A <b>busyout</b> or a <b>release</b> command has no affect on the test results.  4. A <b>list config</b> command shows that the circuit pack and the ports are properly installed.   <b>NOTE:</b> When hyperactivity occurs, the circuit pack is isolated from the system, and all of the trunks for this circuit pack are placed into the out of service state. The system will try to restore the circuit pack within 15 minutes. When no faults are detected for 15 minutes, the DS1 interface circuit pack is restored to normal operation. All of the trunks for the DS1 interface circuit pack are then returned to the in service state. Hyperactivity is often caused by the associated facility. In such a case, faults (such as slips, misframes, or blue alarms) would be entered in the error log. In addition, many hardware errors would be logged against the associated trunk circuits. If the facility is OK and the error occurs again after 15 minutes, replace the circuit pack.

Table 5-228. TEST #140 Red Alarm Inquiry Test — *Continued*

Error Code	Test Result	Description/ Recommendation
	FAIL	<p>The DS1 Interface circuit pack detects a Red alarm. An out-of-frame condition occurs on the DS1 Interface circuit pack. DS1 Interface circuit pack will transmit a Yellow alarm to the remote DS1 endpoint until the Red alarm is retired.</p> <ol style="list-style-type: none"><li>1. Verify that both endpoints of the DS1 link are administered using the same signaling mode, framing mode, and line coding. Likewise, verify that any intermediate CSU's are administered correctly.</li><li>2. If the DS1 interface circuit pack connects to a T1 facility, call the vendor of the T1 carrier to diagnose the remote DS1 endpoint. If the DS1 interface circuit pack connects directly to a switch, call the system technician of the remote switch to diagnose the DS1 endpoint.</li><li>3. Check the physical connectivity of the DS1 pack and of the cable.</li><li>4. Replace the local DS1 interface circuit pack, and repeat the test.</li></ol>
1	FAIL	<p>The DS1 interface circuit pack detected a loss of multiframe alarm (LMA). An out of frame condition occurred on the DS1 interface circuit pack. The DS1 interface circuit pack will transmit a remote multiframe alarm (RMA) to the remote DS1 endpoint until the LMA is retired.</p> <ol style="list-style-type: none"><li>1. Verify that both endpoints of the DS1 link are administered using the same signaling mode, framing mode, and line coding. Likewise, verify that any intermediate CSU's are administered correctly.</li><li>2. If the DS1 interface circuit pack connects to a T1 facility, call the vendor of the T1 carrier to diagnose the remote DS1 endpoint. If the DS1 interface circuit pack connects directly to a switch, call the system technician of the remote switch to diagnose the DS1 endpoint.</li><li>3. Check the physical connectivity of the DS1 pack and of the cable.</li><li>4. Replace the local DS1 interface circuit pack, and repeat the test.</li></ol>
	PASS	No Red alarm is detected on DS1 Interface circuit pack.

*Continued on next page*

Table 5-228. TEST #140 Red Alarm Inquiry Test — *Continued*

Error Code	Test Result	Description/ Recommendation
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board).</p> <p>This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"><li>1. Check to ensure that the board translations are correct. Use the <b>add ds1 PCSS</b> command to administer the DS1 interface if it is not already administered.</li><li>2. If board was already administered correctly, check the error log to determine if the board is hyperactive. If this is the case, the board is shut down. Reseating the board will re-initialize the board.</li><li>3. If the board was found to be correctly inserted in step 1, issue the <b>busyout board</b> command.</li><li>4. Issue the <b>reset board</b> command.</li><li>5. Issue the <b>release busy board</b> command.</li><li>6. Issue the <b>test board long</b> command.</li></ol> <p>This should re-establish the linkage between the internal ID and the port.</p>

### Yellow Alarm Inquiry Test (#141)

Receiving a Yellow alarm from remote DS1 endpoint indicates that the remote DS1 endpoint has an out-of-frame condition. The Yellow Alarm Inquiry Test is used to determine whether the remote DS1 endpoint is transmitting a Yellow alarm. The DS1 Interface circuit pack takes 500 msec to recognize and report a Yellow alarm and 500 msec to recognize and report that a Yellow alarm condition is cleared.

When the DS1 Interface circuit pack detects a Yellow alarm from the remote DS1 endpoint, it will send a YELLOW-ALARM uplink message to the maintenance software. After the maintenance software receives the YELLOW-ALARM message, the Yellow Alarm Inquiry Test is run to confirm the Yellow alarm. Once the Yellow alarm is confirmed, the maintenance software places all trunks on the circuit pack into the out-of-service state. The Inquiry Test will be run every 10 minutes until the Yellow alarm is cleared.

When the Yellow alarm is cleared, the maintenance software restores all trunks on the DS1 Interface circuit pack back to their previous service state before the Yellow alarm is raised.

This Yellow Alarm corresponds to the yellow F2 state documented in CCITT recommendation I.431.

Remote Multiframe Alarm: Remote Multiframe Alarm (RMA) indicates that the remote DS1 endpoint is in a Loss of Multiframe Alarm condition while the DS1 Interface circuit pack is administered using the DMI-BOS common channel signaling. The RMA is handled as a Yellow alarm.

Yellow F5 State Alarm: For 32-channel E1 operation with CRC4 on, the F5 fault state is defined as a fault in the user-network interface, specifically in the direction from the user (PBX) to the network. Refer to CCITT recommendation I.431

Table 5-229. TEST #141 Yellow Alarm Inquiry Test

Error Code	Test Result	Description/ Recommendation
2100	ABORT	Internal system error
	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals a maximum of 5 times.
2000	ABORT	Response to the test was not received within the allowable time period. This may be due to hyperactivity. Error type 1538 in the error log indicates hyperactivity. The hyperactive circuit pack is out of service and one or more of the following symptoms may appear.  1. The DS1-BD tests (such as test 138 and test 139) are aborting with error code 2000.  2. The tests run on the ports of this circuit pack are returning a no board result.  3. A <b>busyout</b> or a <b>release</b> command has no affect on the test results.  4. A <b>list config</b> command shows that the circuit pack and the ports are properly installed.   <b>NOTE:</b> When hyperactivity occurs, the circuit pack is isolated from the system, and all of the trunks for this circuit pack are placed into the out of service state. The system will try to restore the circuit pack within 15 minutes. When no faults are detected for 15 minutes, the DS1 interface circuit pack is restored to normal operation. All of the trunks for the DS1 interface circuit pack are then returned to the in service state. Hyperactivity is often caused by the associated facility. In such a case, faults (such as slips, misframes, or blue alarms) would be entered in the error log. In addition, many hardware errors would be logged against the associated trunk circuits. If the facility is OK and the error occurs again after 15 minutes, replace the circuit pack.

Continued on next page

Table 5-229. TEST #141 Yellow Alarm Inquiry Test — *Continued*

Error Code	Test Result	Description/ Recommendation
1	FAIL	The DS1 interface circuit pack detected a yellow alarm sent by the remote DS1 endpoint. An out of frame condition occurred at the DS1 endpoint.
	FAIL	The DS1 Interface circuit pack detects a Remote Multiframe Alarm sent by the remote DS1 endpoint. An out-of-frame condition occurs on the remote DS1 endpoint.
2	FAIL	<p>The DS1 Interface circuit pack is reporting a yellow F5 State alarm. There is a fault in the user-network interface from the user (PBX) to the network.</p> <ol style="list-style-type: none"> <li>1. Verify that both endpoints of the DS1 link are administered using the same signaling mode, framing mode, and line coding. Likewise, verify that any intermediate CSUs are administered correctly.</li> <li>2. If the DS1 interface circuit pack connects to a T1 facility, call the vendor of the T1 carrier to diagnose the remote DS1 endpoint. If the DS1 interface circuit pack connects directly to a switch, call the system technician of the remote switch to diagnose the DS1 endpoint.</li> <li>3. Check the physical connectivity of the DS1 pack and of the cable.</li> <li>4. Replace the local DS1 interface circuit pack, and repeat the test.</li> </ol>
	PASS	No Yellow alarm nor Remote Multiframe Alarm nor F5 State Alarm is received from the remote DS1 endpoint.
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board).</p> <p>This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"> <li>1. Check to ensure that the board translations are correct. Use the <b>add ds1 PCSS</b> command to administer the DS1 interface if it is not already administered.</li> <li>2. If board was already administered correctly, check the error log to determine if the board is hyperactive. If this is the case, the board is shut down. Reseating the board will re-initialize the board.</li> <li>3. If the board was found to be correctly inserted in step 1, issue the <b>busyout board</b> command.</li> <li>4. Issue the <b>reset board</b> command.</li> <li>5. Issue the <b>release busy board</b> command.</li> <li>6. Issue the <b>test board long</b> command.</li> </ol> <p>This should re-establish the linkage between the internal ID and the port.</p>

## Major Alarm Inquiry Test (#142)

The Major alarm raised by a DS1 Interface circuit pack indicates that the average bit error rate on the DS1 facility is greater than 1/1000. The Major Alarm Inquiry Test is used to determine that the received DS1 bit error rate is greater than 1/1000. When D4 framing mode is selected, the DS1 Interface circuit pack takes 16 seconds to recognize and report a Major alarm and 16 seconds to recognize and report that a Major alarm condition is cleared. If ESF framing mode is selected, the DS1 Interface circuit pack takes 10 seconds to recognize and report a Major alarm and 10 seconds to recognize and report that a Major alarm condition is cleared.

When the DS1 Interface circuit pack detects a Major alarm, it will send a MAJOR-ALARM message to the maintenance software. After the maintenance software receives a MAJOR-ALARM message, the Major Alarm Inquiry Test is initiated to confirm the Major alarm on the DS1 Interface circuit pack. The Inquiry Test will be run every 10 minutes until the Major alarm is cleared. The maintenance software places all trunks on the circuit pack in the out-of-service state if the Major alarm persists for more than 20 minutes.

When the Major alarm is cleared, the maintenance software restores all trunks on the circuit pack to their previous service state before a Major alarm occurs.

Table 5-230. TEST #142 Major Alarm Inquiry Test

Error Code	Test Result	Description/ Recommendation
2100	ABORT	Internal system error
	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals a maximum of 5 times.

*Continued on next page*

Table 5-230. TEST #142 Major Alarm Inquiry Test — *Continued*

Error Code	Test Result	Description/ Recommendation
2000	ABORT	<p>Response to the test was not received within the allowable time period. This may be due to hyperactivity. Error type 1538 in the error log indicates hyperactivity. The hyperactive circuit pack is out of service and one or more of the following symptoms may be exhibited.</p> <ol style="list-style-type: none"> <li>1. The DS1-BD tests (such as test 138 and test 139) are aborting with error code 2000.</li> <li>2. The tests run on the ports of this circuit pack are returning a no board result.</li> <li>3. A <b>busyout</b> or a <b>release</b> command has no affect on the test results.</li> <li>4. A <b>list config</b> command shows that the circuit pack and the ports are properly installed.</li> </ol> <p> <b>NOTE:</b> When hyperactivity occurs, the circuit pack is isolated from the system, and all of the trunks for this circuit pack are placed into the out of service state. The system will try to restore the circuit pack within 15 minutes. When no faults are detected for 15 minutes, the DS1 interface circuit pack is restored to normal operation. All of the trunks for the DS1 interface circuit pack are then returned to the in service state. Hyperactivity is often caused by the associated facility. In such a case, faults (such as slips, misframes, or blue alarms) would be entered in the error log. In addition, many hardware errors would be logged against the associated trunk circuits. If the facility is OK and the error occurs again after 15 minutes, replace the circuit pack.</p>
	FAIL	<p>The DS1 Interface circuit pack detects a Major alarm. The DS1 bit error rate is greater than 1/1000.</p> <ol style="list-style-type: none"> <li>1. The performance of DS1 link between DS1 Interface circuit pack and remote DS1 endpoint is very poor. If the DS1 Interface circuit pack is TN767, enter <b>list measurement ds1-log PCSS</b> command to read the error seconds measurement.</li> <li>2. Verify that both endpoints of the DS1 link are administered using the same signaling mode, framing mode, and line coding.</li> <li>3. If the DS1 interface circuit pack connects to a T1 facility, call the vendor of the T1 carrier to diagnose the remote DS1 endpoint. If the DS1 interface circuit pack connects directly to a switch, call the system technician of the remote switch to diagnose the DS1 endpoint.</li> <li>4. Check the physical connectivity of the DS1 pack and of the cable.</li> <li>5. Replace the local DS1 interface circuit pack, and repeat the test.</li> </ol>
	PASS	No Major alarm is detected in DS1 Interface circuit pack.

*Continued on next page*

Table 5-230. TEST #142 Major Alarm Inquiry Test — *Continued*

Error Code	Test Result	Description/ Recommendation
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board).</p> <p>This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"> <li>1. Check to ensure that the board translations are correct. Use the <b>add ds1 PCSS</b> command to administer the DS1 interface if it is not already administered.</li> <li>2. If board was already administered correctly, check the error log to determine if the board is hyperactive. If this is the case, the board is shut down. Reseating the board will re-initialize the board.</li> <li>3. If the board was found to be correctly inserted in step 1, issue the <b>busyout board</b> command.</li> <li>4. Issue the <b>reset board</b> command.</li> <li>5. Issue the <b>release busy board</b> command.</li> <li>6. Issue the <b>test board long</b> command.</li> </ol> <p>This should re-establish the link between the internal ID and the port.</p>

### Minor Alarm Inquiry Test (#143)

The Minor alarm raised by a DS1 Interface circuit pack indicates that the average bit error rate on the DS1 facility is greater than 1/1,000,000, but less than 1/1000. The Minor Alarm Inquiry Test is used to determine that the received DS1 bit error rate is greater than 1/1,000,000 and less than 1/1000. When D4 framing mode is selected, the DS1 Interface circuit pack takes 41 minutes to recognize and report a Minor alarm and 41 minutes to recognize and report that a Minor alarm condition is cleared. If ESF framing mode is selected, the DS1 Interface circuit pack takes 10 minutes to recognize and report a Minor alarm and 10 minutes to recognize and report that a Minor alarm condition is cleared.

When the DS1 Interface circuit pack detects a Minor alarm condition, it will send a MINOR-ALARM message to the maintenance software. After the maintenance software receives a MINOR-ALARM message, the Minor Alarm Inquiry Test is initiated to confirm the Minor alarm. All trunks on the circuit pack are kept in the in-service state after the Minor alarm is confirmed. The Minor Alarm Inquiry Test is run every 10 minutes until the Minor alarm is cleared.

Table 5-231. TEST #143 Minor Alarm Inquiry Test

Error Code	Test Result	Description/ Recommendation
2100	ABORT	Internal system error
	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals a maximum of 5 times.
2000	ABORT	<p>Response to the test was not received within the allowable time period. This may be due to hyperactivity. Error type 1538 in the error log indicates hyperactivity. The hyperactive circuit pack is out of service and one or more of the following symptoms may be exhibited.</p> <ol style="list-style-type: none"> <li>1. The DS1-BD tests (such as test 138 and test 139) are aborting with error code 2000.</li> <li>2. The tests run on the ports of this circuit pack are returning a no board result.</li> <li>3. A <b>busyout</b> or a <b>release</b> command has no affect on the test results.</li> <li>4. A <b>list config</b> command shows that the circuit pack and the ports are properly installed.</li> </ol> <p><b>⇒ NOTE:</b>                      When hyperactivity occurs, the circuit pack is isolated from the system, and all of the trunks for this circuit pack are placed into the out of service state. The system will try to restore the circuit pack within 15 minutes. When no faults are detected for 15 minutes, the DS1 interface circuit pack is restored to normal operation. All of the trunks for the DS1 interface circuit pack are then returned to the in service state. Hyperactivity is often caused by the associated facility. In such a case, faults (such as slips, misframes, or blue alarms) would be entered in the error log. In addition, many hardware errors would be logged against the associated trunk circuits. If the facility is OK and the error occurs again after 15 minutes, replace the circuit pack.</p>

*Continued on next page*

Table 5-231. TEST #143 Minor Alarm Inquiry Test — *Continued*

Error Code	Test Result	Description/ Recommendation
	FAIL	<p>The DS1 Interface circuit pack detects a Minor alarm. The DS1 bit error rate is greater than 1/1,000,000 and less than 1/1000.</p> <ol style="list-style-type: none"> <li>1. The performance of DS1 link between DS1 Interface circuit pack and remote DS1 endpoint is poor. If DS1 Interface circuit pack is TN767, enter <b>list measurement ds1-log PCSS</b> command to read the error seconds measurement.</li> <li>2. Verify that both endpoints of the DS1 link are administered using the same signaling mode, framing mode, and line coding.</li> <li>3. If the DS1 interface circuit pack connects to a T1 facility, call the vendor of the T1 carrier to diagnose the remote DS1 endpoint. If the DS1 interface circuit pack connects directly to a switch, call the system technician of the remote switch to diagnose the DS1 endpoint.</li> <li>4. Check the physical connection of the DS1 pack and of the cable.</li> <li>5. Replace the local DS1 interface circuit pack, and repeat the test.</li> </ol>
	PASS	No Minor alarm is detected in DS1 Interface circuit pack.
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board).</p> <p>This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"> <li>1. Check to ensure that the board translations are correct. Use the <b>add ds1 PCSS</b> command to administer the DS1 interface if it is not already administered.</li> <li>2. If board was already administered correctly, check the error log to determine if the board is hyperactive. If this is the case, the board is shut down. Reseating the board will re-initialize the board.</li> <li>3. If the board was found to be correctly inserted in step 1, issue the <b>busyout board</b> command.</li> <li>4. Issue the <b>reset board</b> command.</li> <li>5. Issue the <b>release busy board</b> command.</li> <li>6. Issue the <b>test board long</b> command.</li> </ol> <p>This should re-establish the link between the internal ID and the port.</p>

## Slip Alarm Inquiry Test (144)

Slips occur when transmitter and receiver are not running at precisely the same clock rate. The DS1 Interface circuit pack can detect both positive and negative slips on the DS1 facility. The Slip Alarm Inquiry Test is used to acquire the total number of slips occurred on a DS1 link.

When the DS1 Interface circuit pack detects a slip condition, the circuit pack will increase the on-board slip counter by 1. A SLIP-COUNT message is spontaneously sent to the system software after the counter reaches a threshold (for example, 88). When the maintenance software receives the SLIP-COUNT message, the Slip Alarm Inquiry Test is initiated to query the slip counters on DS1 Interface circuit pack and total the slip counts in the maintenance software.

If the count of slips is over the threshold, a Minor alarm is raised against the DS1 Interface circuit pack. All trunks of the DS1 Interface circuit pack are still in the in-service state. If the DS1 Interface circuit pack is used to supply the system synchronization source, the MINOR alarm will initiate a synchronization source switch. See "TDM-BUS" and "SYNC (Synchronization)" for details.

Table 5-232. TEST #144 Slip Alarm Inquiry Test

Error Code	Test Result	Description/ Recommendation
2100	ABORT	Internal system error
	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals a maximum of 5 times.

*Continued on next page*

Table 5-232. TEST #144 Slip Alarm Inquiry Test — *Continued*

Error Code	Test Result	Description/ Recommendation
2000	ABORT	<p>Response to the test was not received within the allowable time period. This may be due to hyperactivity. Error type 1538 in the error log indicates hyperactivity. The hyperactive circuit pack is out of service and one or more of the following symptoms may be exhibited.</p> <ol style="list-style-type: none"><li>1. The DS1-BD tests (such as test 138 and test 139) are aborting with error code 2000.</li><li>2. The tests run on the ports of this circuit pack are returning a no board result.</li><li>3. A <b>busyout</b> or a <b>release</b> command has no affect on the test results.</li><li>4. A <b>list config</b> command shows that the circuit pack and the ports are properly installed.</li></ol> <p> <b>NOTE:</b> When hyperactivity occurs, the circuit pack is isolated from the system, and all of the trunks for this circuit pack are placed into the out of service state. The system will try to restore the circuit pack within 15 minutes. When no faults are detected for 15 minutes, the DS1 interface circuit pack is restored to normal operation. All of the trunks for the DS1 interface circuit pack are then returned to the in service state. Hyperactivity is often caused by the associated facility. In such a case, faults (such as slips, misframes, or blue alarms) would be entered in the error log. In addition, many hardware errors would be logged against the associated trunk circuits. If the facility is OK and the error occurs again after 15 minutes, replace the circuit pack.</p>

*Continued on next page*

Table 5-232. TEST #144 Slip Alarm Inquiry Test — *Continued*

Error Code	Test Result	Description/ Recommendation
1 to 88	FAIL	<p>The DS1 interface circuit pack detected a slip alarm. The error code equals the number of slips detected by the DS1 interface circuit pack since the last slip alarm inquiry test.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> <li>2. If the DS1 interface circuit pack is a TN767, enter the <b>list measurement ds1-log PCSS</b> command to read the error seconds measurement.</li> <li>3. Verify that both endpoints and all intermediate equipment of the DS1 link are administered using the same signaling mode, framing mode, and line coding.</li> <li>4. If the DS1 interface circuit pack connects to a T1 facility, call the vendor of the T1 carrier to diagnose the remote DS1 endpoint. If the DS1 interface circuit pack connects directly to a switch, call the system technician of the remote switch to diagnose the DS1 endpoint.</li> <li>5. Check the active alarm and error logs for recent alarms and errors against the synchronization (SYNC). Follow the suggested repair procedure for these errors.</li> <li>6. Check the physical connectivity of the DS1 pack and of the cable.</li> <li>7. Replace the local DS1 interface circuit pack and repeat the test.</li> </ol>
	PASS	No Slip alarm is detected on the DS1 Interface circuit pack.
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board).</p> <p>This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"> <li>1. Check to ensure that the board translations are correct. Use the <b>add ds1 PCSS</b> command to administer the DS1 interface if it is not already administered.</li> <li>2. If board was already administered correctly, check the error log to determine if the board is hyperactive. If this is the case, the board is shut down. Reseating the board will re-initialize the board.</li> <li>3. If the board was found to be correctly inserted in step 1, issue the <b>busyout board</b> command.</li> <li>4. Issue the <b>reset board</b> command.</li> <li>5. Issue the <b>release busy board</b> command.</li> <li>6. Issue the <b>test board long</b> command.</li> </ol> <p>This should re-establish the link between the internal ID and the port.</p>

## Misframe Alarm Inquiry Test (#145)

Misframe Alarm indicates that framing bits observed on a DS1 Interface circuit pack are in error. Misframe Alarm Inquiry Test queries the total number of misframes that occurred on a DS1 Interface circuit pack since the last inquiry.

When the DS1 Interface circuit pack detects a misframe error, it will increase its misframe counter by 1. If the counter reaches the threshold, a MISFRAME-COUNT message is automatically sent to the switch maintenance software. After the maintenance software receives the MISFRAME-COUNT message, the Misframe Alarm Inquiry Test is initiated to collect the misframe counts from the DS1 Interface circuit pack.

When the threshold of misframes is reached, if the DS1 Interface circuit pack is supplying the system synchronization source, then a switching synchronization source message is sent to the TDM Bus Clock. See TDM-BUS (TDM Bus) Maintenance documentation for details. A Minor alarm against the DS1 Interface circuit pack is raised, but all trunks of the DS1 Interface circuit pack are still in the in-service state.

Table 5-233. TEST #145 Misframe Alarm Inquiry Test

Error Code	Test Result	Description/ Recommendation
2100	ABORT	Internal system error
	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals a maximum of 5 times.

*Continued on next page*

Table 5-233. TEST #145 Misframe Alarm Inquiry Test — *Continued*

Error Code	Test Result	Description/ Recommendation
2000	ABORT	<p>Response to the test was not received within the allowable time period. This may be due to hyperactivity. Error type 1538 in the error log indicates hyperactivity. The hyperactive circuit pack is out of service and one or more of the following symptoms may appear.</p> <ol style="list-style-type: none"><li>1. The DS1-BD tests (such as test 138 and test 139) are aborting with error code 2000.</li><li>2. The tests run on the ports of this circuit pack are returning a no board result.</li><li>3. A <b>busyout</b> or a <b>release</b> command has no affect on the test results.</li><li>4. A <b>list config</b> command shows that the circuit pack and the ports are properly installed.</li></ol> <p> <b>NOTE:</b> When hyperactivity occurs, the circuit pack is isolated from the system, and all of the trunks for this circuit pack are placed into the out of service state. The system will try to restore the circuit pack within 15 minutes. When no faults are detected for 15 minutes, the DS1 interface circuit pack is restored to normal operation. All of the trunks for the DS1 interface circuit pack are then returned to the in service state. Hyperactivity is often caused by the associated facility. In such a case, faults (such as slips, misframes, or blue alarms) would be entered in the error log. In addition, many hardware errors would be logged against the associated trunk circuits. If the facility is OK and the error occurs again after 15 minutes, replace the circuit pack.</p>

*Continued on next page*

Table 5-233. TEST #145 Misframe Alarm Inquiry Test — Continued

Error Code	Test Result	Description/ Recommendation
ANY	FAIL	<p>The test failed because the DS1 interface circuit pack detected errors in the received framing bits pattern. The error code equals the number of misframes detected by the DS1 interface circuit pack since the last misframe alarm inquiry test. Major bit and minor bit error rate (error types 2561 and 2817) error logs often accompany misframe alarms. Clearing the cause of these error logs may clear the misframes which are occurring.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> <li>2. If the DS1 interface circuit pack is a TN767, enter the <b>list measurement ds1-log PCSS</b> command to read the error seconds measurement.</li> <li>3. Verify that both endpoints and all intermediate equipment of the DS1 link are administered using the same signaling mode, framing mode, and line coding.</li> <li>4. If the DS1 interface circuit pack connects to a T1 facility, call the vendor of the T1 carrier to diagnose the remote DS1 endpoint. If the DS1 interface circuit pack connects directly to a switch, call the system technician of the remote switch to diagnose the DS1 endpoint.</li> <li>5. Check the active alarm and error logs for recent alarms and errors against the synchronization (SYNC). Follow the suggested repair procedure for these errors.</li> <li>6. Check the physical connection of the DS1 pack and of the cable.</li> <li>7. Replace the local DS1 interface circuit pack, and repeat the test.</li> </ol>
	PASS	No Misframe alarm is detected on the DS1 Interface circuit pack.
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board).</p> <p>This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"> <li>1. Check to ensure that the board translations are correct. Use the <b>add ds1 PCSS</b> command to administer the DS1 interface if it is not already administered.</li> <li>2. If board was already administered correctly, check the error log to determine if the board is hyperactive. If this is the case, the board is shut down. Reseating the board will re-initialize the board.</li> <li>3. If the board was found to be correctly inserted in step 1, issue the <b>busyout board</b> command.</li> <li>4. Issue the <b>reset board</b> command.</li> <li>5. Issue the <b>release busy board</b> command.</li> <li>6. Issue the <b>test board long</b> command.</li> </ol> <p>This should re-establish the link between the internal ID and the port.</p>

## Translation Update Test (#146)

The Translation Update Test sends the circuit-pack-level information specified by System Administration to the DS1 Interface circuit pack. Translation includes the following data administered for a DS1 Interface circuit pack (see output of **display ds1 PCSS** command): DS1 Link Length between two DS1 endpoints, Synchronization Source Control, All Zero Suppression, Framing Mode, Signaling Mode, Time Slot Number of 697-Hz Tone, Time Slot Number of 700-Hz Tone, etc.

If a TN767E or later DS1 circuit pack is combined with a 120A CSU Module to form an Integrated CSU Module, this test will also send the administration for this Integrated CSU to the circuit pack to assure the board's translations are correct. The administration of the CSU Module is done using the DS1 circuit pack administration form. Translation for the CSU Module includes the following data: Transmit LBO, Receive ALBO, Supply CPE Loopback Jack Power?, and so forth.

Table 5-234. TEST #146 Translation Update Test

Error Code	Test Result	Description/ Recommendation
	ABORT	Internal system error  1. Retry the command at 1-minute intervals a maximum of 5 times.
	FAIL	Internal system software error.  1. Enter the <b>display ds1 PCSS</b> command to verify the DS1 Interface circuit pack translation.
	PASS	Translation data has been downloaded to the DS1 Interface circuit pack successfully.
0	NO BOARD	The test could not relate the internal ID to the port (no board).  This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.  1. Check to ensure that the board translations are correct. Use the <b>add ds1 PCSS</b> command to administer the DS1 interface if it is not already administered.  2. If board was already administered correctly, check the error log to determine if the board is hyperactive. If this is the case, the board is shut down. Reseating the board will re-initialize the board.  3. If the board was found to be correctly inserted in step 1, issue the <b>busyout board</b> command.  4. Issue the <b>reset board</b> command.  5. Issue the <b>release busy board</b> command.  6. Issue the <b>test board long</b> command.  This should re-establish the link between the internal ID and the port.

## DS1 Board Loopback Test (#1209)

**This test is destructive.**

The DS1 Board Loopback (BLB) Test causes a loopback at the TN767E DS1 board edge and tests DS1 board internal circuitry.

The test is destructive and can only be initiated by a system technician demanded **test ds1-loop PCSS ds1/csu-loopback-tests** command.

All trunks or ports on the DS1 Interface circuit pack must be busied out via the system technician **busyout board** command before running the BLB Test.

When the BLB Test is initiated, maintenance software sends an appropriate message to the TN767E DS1 Interface circuit pack to start the test. The board will set up the BLB loopback, transmit a test pattern, and verify that the pattern is received unaltered through the loopback. If the transmitted and received pattern is different, the test fails.

When the test is complete, all trunks or ports on the TN767E DS1 Interface circuit pack are restored to the in-service state after the **release board** command is entered

Table 5-235. TEST #1209 DS1 Board Loopback Test

Error Code	Test Result	Description/ Recommendation
	ABORT	Internal system error  1. Retry <b>test ds1-loop PCSS ds1/csu-loopback-tests</b> at 1-minute intervals a maximum of 5 times.
1005	ABORT	DS1 Board Loopback Test cannot be executed in the current configuration. To run this Test, the TN767E or later suffix DS1 must be administered for 24-channel operation. The <b>Bit Rate</b> field on the DS1 circuit pack administration form must be set to <b>1.544</b> for 24-channel operation.
1015	ABORT	Ports on the DS1 Interface circuit pack have not been busied out to out-of-service.  1. Enter <b>busyout board PCSS</b> to put all trunks or ports of the DS1 Interface circuit pack into the out-of-service state.  2. Retry the command.

*Continued on next page*

Table 5-235. TEST #1209 DS1 Board Loopback Test — *Continued*

Error Code	Test Result	Description/ Recommendation
1039	ABORT	<p>The DS1 Interface circuit pack is providing timing for the system. Executing this test could cause major system disruption.</p> <p>If the DS1 Interface circuit pack needs to be tested, set the synchronization reference to another DS1 Interface circuit pack or to the Tone-Clock circuit pack via the following command sequence:</p> <ol style="list-style-type: none"><li>1. Issue the <b>disable synchronization-switch</b> command.</li><li>2. Next, issue the <b>set synchronization PCSS</b> command.</li><li>3. Lastly, issue the <b>enable synchronization-switch</b> command.</li></ol>
1950	ABORT	<p>Another loopback/span test is already executing on the DS1 board or the board is in a network requested loopback mode (Line loopback or Payload loopback). The hardware error log will indicate whether a Customer Loopback Jack Test, Far CSU Loopback Test, or the One-Way Span Test is executing or if the board is in line loopback or payload loopback mode. Only one long-duration loopback/span test can be active at a given time. Thus, if a loopback/span test is already active, that test must be terminated via the <i>test ds1-loop PCSS end-loopback/span-test</i> command in order to execute this test.</p>
2100	ABORT ABORT	<p>Internal system error</p> <p>Could not allocate the necessary system resources to run this test.</p> <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals for a maximum of 5 times.</li></ol>

*Continued on next page*

Table 5-235. TEST #1209 DS1 Board Loopback Test — *Continued*

Error Code	Test Result	Description/ Recommendation
2000	ABORT	<p>Response to the test was not received within the allowable time period. This may be due to hyperactivity. Error type 1538 in the error log indicates hyperactivity. The hyperactive circuit pack is out of service and one or more of the following symptoms may be exhibited.</p> <ol style="list-style-type: none"> <li>1. The DS1-BD tests (such as test 138 and test 139) are aborting with error code 2000.</li> <li>2. The tests run on the ports of this circuit pack are returning a no board result.</li> <li>3. A <b>busyout</b> or a <b>release</b> command has no affect on the test results.</li> <li>4. A <b>list config</b> command shows that the circuit pack and the ports are properly installed.</li> </ol> <p> <b>NOTE:</b> When hyperactivity occurs, the circuit pack is isolated from the system, and all of the trunks for this circuit pack are placed into the out of service state. The system will try to restore the circuit pack within 15 minutes. When no faults are detected for 15 minutes, the DS1 interface circuit pack is restored to normal operation. All of the trunks for the DS1 interface circuit pack are then returned to the in service state. Hyperactivity is often caused by the associated facility. In such a case, faults (such as slips, misframes, or blue alarms) would be entered in the error log. In addition, many hardware errors would be logged against the associated trunk circuits. If the facility is OK and the error occurs again after 15 minutes, replace the circuit pack.</p>
	FAIL	<p>DS1 Interface circuit pack failed the DS1 Board Loopback Test.</p> <ol style="list-style-type: none"> <li>1. Retry <b>test ds1-loop PCSS ds1/csu-loopback-tests</b>.</li> <li>2. If the BLB test continues to fail, then replace the DS1 circuit pack.</li> </ol>
	PASS	<p>The BLB test executed successfully. The test pattern was transmitted and received successfully up to the TN767E DS1 board edge.</p>

*Continued on next page*

Table 5-235. TEST #1209 DS1 Board Loopback Test — *Continued*

Error Code	Test Result	Description/ Recommendation
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board).</p> <p>This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"><li>1. Check to ensure that the board translations are correct. Use the <b>add ds1 PCSS</b> command to administer the DS1 interface if it is not already administered.</li><li>2. If board was already administered correctly, check the error log to determine if the board is hyperactive. If this is the case, the board is shut down. Reseating the board will re-initialize the board.</li><li>3. If the board was found to be correctly inserted in step 1, issue the <b>busyout board</b> command.</li><li>4. Issue the <b>reset board</b> command.</li><li>5. Issue the <b>release busy board</b> command.</li><li>6. Issue the <b>test board long</b> command.</li></ol> <p>This should re-establish the link between the internal ID and the port.</p>

## CSU Equipment Loopback Test (#1210)

**This test is destructive.**

The CSU Equipment Loopback (ELB) Test causes a loopback at the near-edge of the local 120A CSU Module and tests the connection from the TN767E DS1 board to the CSU Module (DS1 board edge interconnecting cable, and CSU Module edge). This test will only be performed if the 120A CSU Module is present, administered, and connected to a 1.544Mbps TN767E DS1 circuit pack on the back of the port carrier.

The test is destructive and can only be initiated by a system technician demanded **test ds1-loop PCSS ds1/csu-loopback-tests** command.

All trunks or ports on the DS1 Interface circuit pack must be busied out via the system technician **busyout board** command before running the ELB Test.

When the ELB Test is initiated, maintenance software sends an appropriate message to the TN767E DS1 Interface circuit pack to start the test. The board sets up the ELB loopback, transmit a test pattern, and verify that the pattern is received unaltered through the loopback. If the transmitted and received pattern is different, the test fails.

5 Maintenance Objects for DEFINITY ONE  
DS1-BD (DS1 Interface Circuit Pack)

5-597

In addition, the DS1 circuit pack hardware applies a DC current while the test is running in order to detect any broken wires which may not be detected by the loopback pattern.

When the test is complete, all trunks or ports on the TN767E DS1 Interface circuit pack are restored to the in-service state after the **release board** command is entered.

Table 5-236. TEST #1210 CSU Equipment Loopback Test

Error Code	Test Result	Description/ Recommendation
	ABORT	Internal system error 1. Retry <b>test ds1-loop PCSS ds1/csu-loopback-tests</b> at 1-minute intervals a maximum of 5 times.
1005	ABORT	CSU Equipment Loopback Test cannot be executed in the current configuration. To run this test, the <i>Near-End CSU Type</i> field on the DS1 circuit pack administration form must be set to <b>integrated</b> and the <i>Bit Rate</i> field must be set to <b>1.544</b> (24-channel operation). 1. Use the <b>change ds1 PCSS</b> command to set the <i>Near-End CSU Type</i> field on the DS1 circuit pack administration form to <b>integrated</b> , and/or change the <i>Bit Rate</i> field to <b>1.544</b> if the board is to be used in the 24-channel configuration. 2. Retry <b>test ds1-loop PCSS ds1/csu-loopback-tests</b> .
1015	ABORT	Ports on the DS1 Interface circuit pack have not been busied out to out-of-service. 1. Enter the <b>busyout board PCSS</b> command to put all trunks or ports of the DS1 Interface circuit pack into the out-of-service state. 2. Retry the command.
1039	ABORT	The DS1 Interface circuit pack is providing timing for the system. Executing this test could cause major system disruption. If the DS1 Interface circuit pack needs to be tested, set the synchronization reference to another DS1 Interface circuit pack or to the Tone-Clock circuit pack via the following command sequence: 1. Issue the <b>disable synchronization-switch</b> command. 2. Next, issue the <b>set synchronization PCSS</b> command. 3. Lastly, issue the <b>enable synchronization-switch</b> command.

Continued on next page

Table 5-236. TEST #1210 CSU Equipment Loopback Test — *Continued*

Error Code	Test Result	Description/ Recommendation
1950	ABORT	Another loopback/span test is already executing on the DS1 board or the board is in a network requested loopback mode (Line loopback or Payload loopback). The hardware error log will indicate whether a Customer Loopback Jack Test, Far CSU Loopback Test, or the One-Way Span Test is executing or if the board is in line loopback or payload loopback mode. Only one long-duration loopback/span test can be active at a given time. Thus, if a loopback/span test is already active, that test must be terminated via the <b>test ds1-loop PCSS end-loopback/span-test</b> command in order to execute this test.
1951	ABORT	The CSU Equipment Loopback Test could not be executed because the 120A CSU Module was not physically installed. Physically connect the 120A CSU Module to the TN767E board on the back of the port carrier.
	ABORT	Internal system error
2100	ABORT	Could not allocate the necessary system resources to run this test. <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
2000	ABORT	<p>Response to the test was not received within the allowable time period. This may be due to hyperactivity. Error type 1538 in the error log indicates hyperactivity. The hyperactive circuit pack is out of service and one or more of the following symptoms may be exhibited.</p> <ol style="list-style-type: none"> <li>1. The DS1-BD tests (such as test 138 and test 139) are aborting with error code 2000.</li> <li>2. The tests run on the ports of this circuit pack are returning a no board result.</li> <li>3. A <b>busyout</b> or a <b>release</b> command has no affect on the test results.</li> <li>4. A <b>list config</b> command shows that the circuit pack and the ports are properly installed.</li> </ol> <p><b>⇒ NOTE:</b></p> <p>When hyperactivity occurs, the circuit pack is isolated from the system, and all of the trunks for this circuit pack are placed into the out of service state. The system will try to restore the circuit pack within 15 minutes. When no faults are detected for 15 minutes, the DS1 interface circuit pack is restored to normal operation. All of the trunks for the DS1 interface circuit pack are then returned to the in service state. Hyperactivity is often caused by the associated facility. In such a case, faults (such as slips, misframes, or blue alarms) would be entered in the error log. In addition, many hardware errors would be logged against the associated trunk circuits. If the facility is OK and the error occurs again after 15 minutes, replace the circuit pack.</p>

*Continued on next page*

Table 5-236. TEST #1210 CSU Equipment Loopback Test — *Continued*

Error Code	Test Result	Description/ Recommendation
	FAIL	<p>DS1 Interface circuit pack failed the CSU Equipment Loopback Test.</p> <ol style="list-style-type: none"> <li>1. Retry <b>test ds1-loop PCSS ds1/csu-loopback-tests</b>.</li> <li>2. If the ELB test continues to fail, then either the TN767E board, the CSU Module, or the I/O cable between the backplane and the CSU module (or any combination thereof) has failed. Attempt to isolate the problem to one of these areas. Replace the CSU Module and running <b>test ds1-loop PCSS ds1/csu-loopback-tests</b> again.</li> <li>3. If the ELB test continues to fail, then replace the TN767E board and run <b>test ds1-loop PCSS ds1/csu-loopback-tests</b> again.</li> <li>4. If the ELB test continues to fail, the problem could be in the I/O cable between the backplane and the CSU module.</li> </ol>
	PASS	<p>The ELB test executed successfully. The test pattern was transmitted and received successfully over the connection from the TN767E DS1 board to the near-edge of the 120A CSU Module.</p>
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board). This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"> <li>1. Check to ensure that the board translations are correct. Use the <b>add ds1 PCSS</b> command to administer the DS1 interface if it is not already administered.</li> <li>2. If board was already administered correctly, check the error log to determine if the board is hyperactive. If this is the case, the board is shut down. Reseating the board will re-initialize the board.</li> <li>3. If the board was found to be correctly inserted in step 1, issue the <b>busyout board</b> command.</li> <li>4. Issue the <b>reset board</b> command.</li> <li>5. Issue the <b>release busy board</b> command.</li> <li>6. Issue the <b>test board long</b> command.</li> </ol> <p>This should re-establish the link between the internal ID and the port.</p>

## CSU Repeater Loopback Test (#1211)

**This test is destructive.**

The CSU Repeater Loopback (RLB) Test causes a loopback at the far-edge of the local 120A CSU Module and tests the connection from the TN767E DS1 board to and including the CSU Module circuitry. This test will only be performed if the 120A CSU Module is present, administered, and connected to a 1.544 Mbps TN767E DS1 circuit pack on the back of the port carrier.

The test is destructive and can only be initiated by a system technician demanded **test ds1-loop PCSS ds1/csu-loopback-tests** command.

All trunks or ports on the DS1 Interface circuit pack must be busied out via the system technician **busyout board** command before running the RLB Test.

When the RLB Test is initiated, maintenance software sends an appropriate message to the TN767E DS1 Interface circuit pack to start the test. The board will set up the RLB loopback, transmit a test pattern, and verify that the pattern is received unaltered through the loopback. If the transmitted and received pattern is different, the test fails.

In addition, the DS1 circuit pack hardware applies a DC current while the test is running in order to detect any broken wires which may not be detected by the loopback pattern.

When the test is complete, all trunks or ports on the TN767E DS1 Interface circuit pack are restored to the in-service state after the **release board** command is entered

Table 5-237. TEST #1211 CSU Repeater Loopback Test

Error Code	Test Result	Description/ Recommendation
	ABORT	Internal system error  1. Retry <b>test ds1-loop PCSS ds1/csu-loopback-tests</b> at 1-minute intervals a maximum of 5 times.
1005	ABORT	CSU Equipment Loopback Test cannot be executed in the current configuration. To run this test, the <i>Near-End CSU Type</i> field on the DS1 circuit pack administration form must be set to <b>integrated</b> and the <i>Bit Rate</i> field must be set to <b>1.544</b> (24-channel operation).  1. Use the <b>change ds1 PCSS</b> command to set the <i>Near-End CSU Type</i> field on the DS1 circuit pack administration form to <b>integrated</b> , and/or change the <i>Bit Rate</i> field to <b>1.544</b> if the board is to be used in the 24-channel configuration.  2. Retry <b>test ds1-loop PCSS ds1/csu-loopback-tests</b> .

Table 5-237. TEST #1211 CSU Repeater Loopback Test — *Continued*

Error Code	Test Result	Description/ Recommendation
1015	ABORT	<p>Ports on the DS1 Interface circuit pack have not been busied out to out-of-service.</p> <ol style="list-style-type: none"><li>1. Enter the <b>busyout board PCSS</b> command to put all trunks or ports of the DS1 Interface circuit pack into the out-of-service state.</li><li>2. Retry the command.</li></ol>
1039	ABORT	<p>The DS1 Interface circuit pack is providing timing for the system. Executing this test could cause major system disruption.</p> <p>If the DS1 Interface circuit pack needs to be tested, set the synchronization reference to another DS1 Interface circuit pack or to the Tone-Clock circuit pack via the following command sequence:</p> <ol style="list-style-type: none"><li>1. Issue the <b>disable synchronization-switch</b> command.</li><li>2. Next, issue the <b>set synchronization PCSS</b> command.</li><li>3. Lastly, issue the <b>enable synchronization-switch</b> command.</li></ol>
1950	ABORT	<p>Another loopback/span test is already executing on the DS1 board or the board is in a network requested loopback mode (Line loopback or Payload loopback). The hardware error log indicates whether a Customer Loopback Jack Test, Far CSU Loopback Test, or the One-Way Span Test is executing or if the board is in line loopback or payload loopback mode. Only one long-duration loopback/span test can be active at a given time. Thus, if a loopback/span test is already active, that test must be terminated via the <b>test ds1-loop PCSS end-loopback/span-test</b> command in order to execute this test.</p>
1951	ABORT	<p>The CSU Repeater Loopback Test could not be executed because the 120A CSU Module was not physically installed. Physically connect the 120A CSU Module to the TN767E board on the back of the port carrier.</p>

*Continued on next page*

Table 5-237. TEST #1211 CSU Repeater Loopback Test — *Continued*

Error Code	Test Result	Description/ Recommendation
2100	ABORT	Internal system error
	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals a maximum of 5 times.
2000	ABORT	Response to the test was not received within the allowable time period. This may be due to hyperactivity. Error type 1538 in the error log indicates hyperactivity. The hyperactive circuit pack is out of service and one or more of the following symptoms may be exhibited. 1. The DS1-BD tests (such as test 138 and test 139) are aborting with error code 2000. 2. The tests run on the ports of this circuit pack are returning a no board result. 3. A <b>busyout</b> or a <b>release</b> command has no affect on the test results. 4. A <b>list config</b> command shows that the circuit pack and the ports are properly installed.  <b>⇒ NOTE:</b> When hyperactivity occurs, the circuit pack is isolated from the system, and all of the trunks for this circuit pack are placed into the out of service state. The system will try to restore the circuit pack within 15 minutes. When no faults are detected for 15 minutes, the DS1 interface circuit pack is restored to normal operation. All of the trunks for the DS1 interface circuit pack are then returned to the in service state. Hyperactivity is often caused by the associated facility. In such a case, faults (such as slips, misframes, or blue alarms) would be entered in the error log. In addition, many hardware errors would be logged against the associated trunk circuits. If the facility is OK and the error occurs again after 15 minutes, replace the circuit pack.
	FAIL	DS1 Interface circuit pack failed the CSU Repeater Loopback Test. 1. Retry <b>test ds1-loop PCSS ds1/csu-loopback-tests</b> . 2. If the RLB test continues to fail, and the CSU Equipment Loopback Test (#1210) passed, then replace the CSU Module.
	PASS	The RLB test executed successfully. The test pattern was transmitted and received successfully over the connection from the TN767E DS1 board to the far-edge of the 120A CSU Module.

*Continued on next page*

Table 5-237. TEST #1211 CSU Repeater Loopback Test — *Continued*

Error Code	Test Result	Description/ Recommendation
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board).</p> <p>This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"><li>1. Check to ensure that the board translations are correct. Use the <b>add ds1 PCSS</b> command to administer the DS1 interface if it is not already administered.</li><li>2. If board was already administered correctly, check the error log to determine if the board is hyperactive. If this is the case, the board is shut down. Reseating the board will re-initialize the board.</li><li>3. If the board was found to be correctly inserted in step 1, issue the <b>busyout board</b> command.</li><li>4. Issue the <b>reset board</b> command.</li><li>5. Issue the <b>release busy board</b> command.</li><li>6. Issue the <b>test board long</b> command.</li></ol> <p>This should re-establish the link between the internal ID and the port.</p>

## CPE Loopback Jack Test (#1212)

**This test is destructive.**

The CPE Loopback Jack (CLJ-LB) Test causes a loopback at the CPE Loopback Jack and tests the building wiring connection between the TN767E DS1 board and the CPE Loopback Jack.

The test is highly destructive and can only be initiated by a system technician demanded **test ds1-loop PCSS cpe-loopback-jack-test-begin [number-of-bits bit-pattern]** command. The System technician has the choice of entering a loopback activation code on the command line or using the default code (0x47F).

All trunks or ports on the DS1 Interface circuit pack must be busied out via the system technician **busyout board** command before running the CPE Loopback Jack Test.

5 Maintenance Objects for DEFINITY ONE  
DS1-BD (DS1 Interface Circuit Pack)

5-604

The CPE Loopback Jack Test has the TN767E DS1 Interface circuit pack transmit a loopback activation code to the CPE Loopback Jack, waits up to 10 seconds for return of the code to verify the loopback has been established, transmits a framed 3-in-24 test pattern, begins counting bit errors in the received test pattern, and returns a PASS result to indicate that the pattern was successfully sent. If the loopback is not established within the 10 seconds, the test returns FAIL.

The status of the CPE Loopback Jack test will be available in the hardware error log via error type 3900. Several distinct aux values will be used to give the user information of the status of the test.

The **list measurements ds1 summary** command will display the length of time the test has been running (*Test Duration* field) and number of bit errors detected (*Loopback/Span Test Bit-Error Count* field). If the test pattern is being passed through the loopback cleanly, the number of bit errors should be very low. The command will also display the type of loopback/span test executing (*Test* field), the type of pattern generated for the loopback/span test (*Pattern* field), and whether the pattern (*3-in-24 Pattern*) is synchronized (*Synchronized Field*).

To terminate the test, enter **test ds1-loop PCSS end-loopback/span-test** command or the **release board**. Using the **release board** command restores all trunks or ports on the TN767E DS1 Interface circuit pack to the in-service state.

Table 5-238. TEST #1212 CPE Loopback Jack Test

Error Code	Test Result	Description/ Recommendation
	ABORT	Internal system error 1. Retry <b>test ds1-loop PCSS cpe-loopback-jack-test-begin</b> at 1-minute intervals a maximum of 5 times.
1005	ABORT	CPE Loopback Jack Test cannot be executed in the current configuration. To run this Test, the TN767E or later suffix DS1 must be administered for 24-channel operation. The <i>Bit Rate</i> field on the DS1 circuit pack administration form must be set to <b>1.544</b> for 24-channel operation.
1015	ABORT	Ports on the DS1 Interface circuit pack have not been busied out to out-of-service. 1. Enter the <b>busyout board PCSS</b> command to put all trunks or ports of the DS1 Interface circuit pack into the out-of-service state. 2. Retry the command.

Continued on next page

Table 5-238. TEST #1212 CPE Loopback Jack Test — *Continued*

Error Code	Test Result	Description/ Recommendation
1039	ABORT	<p>The DS1 Interface circuit pack is providing timing for the system. Executing this test could cause major system disruption.</p> <p>If the DS1 Interface circuit pack needs to be tested, set the synchronization reference to another DS1 Interface circuit pack or to the Tone-Clock circuit pack via the following command sequence:</p> <ol style="list-style-type: none"><li>1. Issue the <b>disable synchronization-switch</b> command.</li><li>2. Next, issue the <b>set synchronization PCSS</b> command.</li><li>3. Lastly, issue the <b>enable synchronization-switch</b> command.</li></ol>
1950	ABORT	<p>Another loopback/span test is already executing on the DS1 board or the board is in a network requested loopback mode (Line loopback or Payload loopback). The hardware error log will indicate whether a Customer Loopback Jack Test, Far CSU Loopback Test, or the One-Way Span Test is executing or if the board is in line loopback or payload loopback mode. Only one long-duration loopback/span test can be active at a given time. Thus, if a loopback/span test is already active, that test must be terminated via the <b>test ds1-loop PCSS end-loopback/span-test</b> command in order to execute this test.</p>
2100	ABORT ABORT	<p>Internal system error</p> <p>Could not allocate the necessary system resources to run this test.</p> <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals for a maximum of 5 times.</li></ol>

*Continued on next page*

Table 5-238. TEST #1212 CPE Loopback Jack Test — Continued

Error Code	Test Result	Description/ Recommendation
2000	ABORT	<p>Response to the test was not received within the allowable time period. This may be due to hyperactivity. Error type 1538 in the error log indicates hyperactivity. The hyperactive circuit pack is out of service and one or more of the following symptoms may be exhibited.</p> <ol style="list-style-type: none"> <li>1. The DS1-BD tests (such as test 138 and test 139) are aborting with error code 2000.</li> <li>2. The tests run on the ports of this circuit pack are returning a no board result.</li> <li>3. A <b>busyout</b> or a <b>release</b> command has no affect on the test results.</li> <li>4. A <b>list config</b> command shows that the circuit pack and the ports are properly installed.</li> </ol> <p><b>⇒ NOTE:</b> When hyperactivity occurs, the circuit pack is isolated from the system, and all of the trunks for this circuit pack are placed into the out of service state. The system will try to restore the circuit pack within 15 minutes. When no faults are detected for 15 minutes, the DS1 interface circuit pack is restored to normal operation. All of the trunks for the DS1 interface circuit pack are then returned to the in service state. Hyperactivity is often caused by the associated facility. In such a case, faults (such as slips, misframes, or blue alarms) would be entered in the error log. In addition, many hardware errors would be logged against the associated trunk circuits. If the facility is OK and the error occurs again after 15 minutes, replace the circuit pack.</p>
2	FAIL	<p>The CLJ-LB test failed because it was not set up properly. The DS1 interface pack could not successfully put the CPE loopback jack into loopback mode.</p> <ol style="list-style-type: none"> <li>1. Rerun the <b>test ds1-loop PCSS cpe-loopback-jack-test-begin</b> command.</li> <li>2. If the test continues to fail, the problem could be with the TN767E board, the CPE loopback jack equipment, or somewhere between. Run the <b>test ds1-loop PCSS ds1/csu-loopback-tests</b> command to determine if the loopback tests that are closer to the TN767E board are successful. If any of these tests fail, follow the maintenance strategy that is associated with the test that fails.</li> </ol>

Continued on next page

Table 5-238. TEST #1212 CPE Loopback Jack Test — *Continued*

Error Code	Test Result	Description/ Recommendation
3	FAIL	<p>The CPE Loopback Jack Test was not set up properly. The framed 3-in-24 test pattern, generated by the DS1 Interface circuit pack and looped back through the CPE Loopback Jack, could not be detected properly by the DS1 circuit pack.</p> <ol style="list-style-type: none"> <li>1. Retry <b>test ds1-loop PCSS cpe-loopback-jack-test-begin</b>.</li> <li>2. If the CPE Loopback test continues to fail, the problem could be with the TN767E board, the CPE Loopback Jack equipment, or somewhere in between. Run <b>test ds1-loop PCSS ds1/csu-loopback-tests</b> to see if the loopback tests closer to the TN767E board are successful. If any of those loopback tests fail, follow the maintenance strategy associated with those loopbacks.</li> </ol>
	PASS	<p>The CPE Loopback Jack test has successfully began executing. The test will continue to run until the system technician enters the <b>test ds1-loop PCSS end-loopback/span-test</b> command or the <b>release board PCSS</b> command.</p>
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board).</p> <p>This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"> <li>1. Check to ensure that the board translations are correct. Use the <b>add ds1 PCSS</b> command to administer the DS1 interface if it is not already administered.</li> <li>2. If board was already administered correctly, check the error log to determine if the board is hyperactive. If this is the case, the board is shut down. Reseating the board will re-initialize the board.</li> <li>3. If the board was found to be correctly inserted in step 1, issue the <b>busyout board</b> command.</li> <li>4. Issue the <b>reset board</b> command.</li> <li>5. Issue the <b>release busy board</b> command.</li> <li>6. Issue the <b>test board long</b> command.</li> </ol> <p>This should re-establish the link between the internal ID and the port.</p>

## Far CSU Loopback Test (#1213)

**This test is destructive.**

The Far CSU Loopback (R-LLB) Test causes a loopback at the far-end CSU and tests all circuitry and facilities from the local TN767E DS1 board to the far-end CSU.

The test is destructive and can only be initiated by a system technician demanded **test ds1-loop PCSS far-csu-loopback-test-begin** command.

All trunks or ports on the DS1 Interface circuit pack must be busied out via the system technician **busyout board** command before running the Far CSU Loopback Test.

If the far-end CSU is not a 120A CSU Module, and the DS1 is administered for ami-zcs line coding, one's density protection must be disabled on the CSU during the test due to the large number of zero's in the 3-in-24 test pattern.

The Far CSU Loopback Test has the TN767E DS1 Interface circuit pack transmit a loopback activation code to the remote CSU, waits up to 15 seconds for return of the code to verify the loopback has been established, transmits a framed 3-in-24 test pattern, begins counting bit errors in the received test pattern, and returns a PASS result. If the loopback is not established within the 15 seconds, the test fails.

The status of the Far CSU Loopback test will be available in the hardware error log via error type 3901. Several distinct aux values will be used to give the user information of the status of the test.

The *list measurements ds1 summary* command will display the length of time the test has been running (*Test Duration* field) and number of bit errors detected (*Loopback/Span Test Bit-Error Count* field). If the test pattern is being passed through the loopback cleanly, the number of bit errors should be very low. The command will also display the type of loopback/span test executing (*Test* field), the type of pattern generated for the loopback/span test (*Pattern* field), and whether the pattern (*i.e. 3-in-24 Pattern*) is synchronized (*Synchronized* field).

To terminate the test, enter **test ds1-loop PCSS end-loopback/span-test** or the **release board** command. Using the **release board** command will restore all trunks or ports on the TN767E DS1 Interface circuit pack to the in-service state.

Table 5-239. TEST #1213 Far CSU Loopback Test

Error Code	Test Result	Description/ Recommendation
	ABORT	Internal system error  1. Retry <b>test ds1-loop PCSS far-csu-loopback-test-begin</b> at 1-minute intervals a maximum of 5 times.
1005	ABORT	Far CSU Loopback Test cannot be executed in the current configuration. To run this, the TN767E or later suffix DS1 must be administered for 24-channel operation. The "Bit Rate" field on the DS1 circuit pack administration form must be set to "1.544" for 24-channel operation.
1015	ABORT	Ports on the DS1 Interface circuit pack have not been busied out to out-of-service.  1. Enter the <b>busyout board PCSS</b> command to put all trunks or ports of the DS1 Interface circuit pack into the out-of-service state.  2. Retry the command.
1039	ABORT	The DS1 Interface circuit pack is providing timing for the system. Executing this test could cause major system disruption.  If the DS1 Interface circuit pack needs to be tested, set the synchronization reference to another DS1 Interface circuit pack or to the Tone-Clock circuit pack via the following command sequence:  1. Issue the <b>disable synchronization-switch</b> command.  2. Next, issue the <b>set synchronization PCSS</b> command.  3. Lastly, issue the <b>enable synchronization-switch</b> command.
1950	ABORT	Another loopback/span test is already executing on the DS1 board or the board is in a network requested loopback mode (Line loopback or Payload loopback). The hardware error log will indicate whether a Customer Loopback Jack Test, Far CSU Loopback Test, or the One-Way Span Test is executing or if the board is in line loopback or payload loopback mode. Only one long-duration loopback/span test can be active at a given time. Thus, if a loopback/span test is already active, that test must be terminated via the <b>test ds1-loop PCSS end-loopback/span-test</b> command in order to execute this test.
2100	ABORT ABORT	Internal system error  Could not allocate the necessary system resources to run this test.  1. Retry the command at 1-minute intervals for a maximum of 5 times.

*Continued on next page*

Table 5-239. TEST #1213 Far CSU Loopback Test — *Continued*

Error Code	Test Result	Description/ Recommendation
2000	ABORT	<p>Response to the test was not received within the allowable time period. This may be due to hyperactivity. Error type 1538 in the error log indicates hyperactivity. The hyperactive circuit pack is out of service and one or more of the following symptoms may be exhibited.</p> <ol style="list-style-type: none"><li>1. The DS1-BD tests (such as test 138 and test 139) are aborting with error code 2000.</li><li>2. The tests run on the ports of this circuit pack are returning a no board result.</li><li>3. A <b>busyout</b> or a <b>release</b> command has no affect on the test results.</li><li>4. A <b>list config</b> command shows that the circuit pack and the ports are properly installed.</li></ol> <p> <b>NOTE:</b> When hyperactivity occurs, the circuit pack is isolated from the system, and all of the trunks for this circuit pack are placed into the out of service state. The system will try to restore the circuit pack within 15 minutes. When no faults are detected for 15 minutes, the DS1 interface circuit pack is restored to normal operation. All of the trunks for the DS1 interface circuit pack are then returned to the in service state. Hyperactivity is often caused by the associated facility. In such a case, faults (such as slips, misframes, or blue alarms) would be entered in the error log. In addition, many hardware errors would be logged against the associated trunk circuits. If the facility is OK and the error occurs again after 15 minutes, replace the circuit pack.</p>

*Continued on next page*

Table 5-239. TEST #1213 Far CSU Loopback Test — *Continued*

Error Code	Test Result	Description/ Recommendation
2	FAIL	The far CSU Loopback Test was not set up properly. The DS1 Interface circuit pack could not put the far-end CSU into loopback mode.
3	FAIL	<p>The far CSU Loopback Test was not set up properly. The framed 3-in-24 test pattern, generated by the DS1 Interface circuit pack and looped back through the far-end CSU, could not be detected by the DS1 circuit pack.</p> <ol style="list-style-type: none"> <li>1. Retry <b>test ds1-loop PCSS far-csu-loopback-test-begin</b>.</li> <li>2. If the Far CSU Loopback test continues to fail with this error code, the problem could be with the TN767E board, the far-end CSU equipment, or somewhere in between. Run <b>test ds1-loop PCSS cpe-loopback-jack-test-begin</b> to see if the CPE Loopback Jack test which is closer to the TN767E board is successful. (If a CPE Loopback Jack device is not being used, then run <b>test ds1-loop PCSS ds1/csu-loopback-tests</b> to see if these even closer loopback tests succeed). If the closer loopback test fails, follow the maintenance strategy associated with that loopback</li> </ol>
	PASS	The Far CSU Loopback test has successfully began executing. The test will continue to run until the system technician enters <b>test ds1-loop PCSS end-loopback/span-test</b> or the <b>release board PCSS</b> .
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board).</p> <p>This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"> <li>1. Check to ensure that the board translations are correct. Use the <b>add ds1 PCSS</b> command to administer the DS1 interface if it is not already administered.</li> <li>2. If board was already administered correctly, check the error log to determine if the board is hyperactive. If this is the case, the board is shut down. Reseating the board will re-initialize the board.</li> <li>3. If the board was found to be correctly inserted in step 1, issue the <b>busyout board</b> command.</li> <li>4. Issue the <b>reset board</b> command.</li> <li>5. Issue the <b>release busy board</b> command.</li> <li>6. Issue the <b>test board long</b> command.</li> </ol> <p>This should re-establish the link between the internal ID and the port.</p>

## One-Way Span Test (#1214)

**This test is destructive.**

The One-Way Span Test allows one-way span testing to and from remote test equipment or another DEFINITY communications system. This will test all circuitry and facilities from the local TN767E DS1 board to the remote test equipment or other DEFINITY communications system.

The test is destructive and can only be initiated by a system technician demanded *test ds1-loop PCSS one-way-span-test-begin* command.

All trunks or ports on the DS1 Interface circuit pack must be busied out via the system technician **busyout board** command before running the One-Way Span Test.

The One-Way Span Test has the TN767E DS1 Interface circuit pack transmit a framed 3-in-24 test pattern and attempt to receive and verify the pattern. If the TN767E board receives a framed 3-in-24 test pattern sent from another DEFINITY G3V3 or test equipment at the far-end of the DS1, it will begin counting bit errors within the received pattern.

The status of the One-Way Span test will be available in the hardware error log via error type 3902. Several distinct aux values will be used to give the user information of the status of the test.

The *list measurements ds1 summary* command will display the length of time the test has been running (*Test Duration* field) and number of bit errors detected (*Loopback/Span Test Bit-Error Count* field). If the test pattern is being sent cleanly over the span from the far-end, the number of bit errors should be very low. The *Test Duration* field will show 0 until the test pattern is received from the far-end. Upon receiving the test pattern, the board will begin calculating the test duration and number of bit errors. The command will also display the type of loopback/span test executing (*Test* field), the type of pattern generated for the loopback/span test (*Pattern* field), and whether the pattern (*i.e. 3-in-24 Pattern*) is synchronized (*Synchronized* field).

To terminate the test, enter the **test ds1-loop PCSS end-loopback/span-test** command or the **release board** command. Using the **release board** command will restore all trunks or ports on the TN767E DS1 Interface circuit pack to the in-service state.

Table 5-240. TEST #1214 One-Way Span Test

Error Code	Test Result	Description/ Recommendation
	ABORT	Internal system error  1. Retry the <b>test ds1-loop PCSS one-way-span-test-begin</b> command at 1-minute intervals a maximum of 5 times.
1005	ABORT	One-Way Span Test cannot be executed in the current configuration. To run this, the TN767E or later suffix DS1 must be administered for 24-channel operation. The <b>Bit Rate</b> field on the DS1 circuit pack administration form must be set to <b>1.544</b> for 24-channel operation.
1015	ABORT	Ports on the DS1 Interface circuit pack have not been busied out to out-of-service.  1. Enter the <b>busyout board PCSS</b> command to put all trunks or ports of the DS1 Interface circuit pack into the out-of-service state.  2. Retry the command.
1039	ABORT	The DS1 Interface circuit pack is providing timing for the system. Executing this test could cause major system disruption.  If the DS1 Interface circuit pack needs to be tested, set the synchronization reference to another DS1 Interface circuit pack or to the Tone-Clock circuit pack via the following command sequence:  1. Issue the <b>disable synchronization-switch</b> command.  2. Next, issue the <b>set synchronization PCSS</b> command.  3. Lastly, issue the <b>enable synchronization-switch</b> command.
1950	ABORT	Another loopback/span test is already executing on the DS1 board or the board is in a network requested loopback mode (Line loopback or Payload loopback). The hardware error log will indicate whether a Customer Loopback Jack Test, Far CSU Loopback Test, or the One-Way Span Test is executing or if the board is in line loopback or payload loopback mode. Only one long-duration loopback/span test can be active at a given time. Thus, if a loopback/span test is already active, that test must be terminated via the <b>test ds1-loop PCSS end-loopback/span-test</b> command in order to execute this test.
2100	ABORT ABORT	Internal system error  Could not allocate the necessary system resources to run this test.  1. Retry the command at 1-minute intervals for a maximum of 5 times.

*Continued on next page*

Table 5-240. TEST #1214 One-Way Span Test — *Continued*

Error Code	Test Result	Description/ Recommendation
2000	ABORT	<p>Response to the test was not received within the allowable time period. This may be due to hyperactivity. Error type 1538 in the error log indicates hyperactivity. The hyperactive circuit pack is out of service and one or more of the following symptoms may be exhibited.</p> <ol style="list-style-type: none"> <li>1. The DS1-BD tests (such as test 138 and test 139) are aborting with error code 2000.</li> <li>2. The tests run on the ports of this circuit pack are returning a no board result.</li> <li>3. A <b>busyout</b> or a <b>release</b> command has no affect on the test results.</li> <li>4. A <b>list config</b> command shows that the circuit pack and the ports are properly installed.</li> </ol> <p> <b>NOTE:</b> When hyperactivity occurs, the circuit pack is isolated from the system, and all of the trunks for this circuit pack are placed into the out of service state. The system will try to restore the circuit pack within 15 minutes. When no faults are detected for 15 minutes, the DS1 interface circuit pack is restored to normal operation. All of the trunks for the DS1 interface circuit pack are then returned to the in service state. Hyperactivity is often caused by the associated facility. In such a case, faults (such as slips, misframes, or blue alarms) would be entered in the error log. In addition, many hardware errors would be logged against the associated trunk circuits. If the facility is OK and the error occurs again after 15 minutes, replace the circuit pack.</p>
	PASS	<p>The One-Way Span test has successfully began transmitting a framed 3-in-24 test pattern. The test will continue to run until the system technician enters the <b>test ds1-loop PCSS end-loopback/span-test</b> command or the <b>release board PCSS</b> command.</p>

*Continued on next page*

Table 5-240. TEST #1214 One-Way Span Test — *Continued*

Error Code	Test Result	Description/ Recommendation
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board).</p> <p>This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"><li>1. Check to ensure that the board translations are correct. Use the <b>add ds1 PCSS</b> command to administer the DS1 interface if it is not already administered.</li><li>2. If board was already administered correctly, check the error log to determine if the board is hyperactive. If this is the case, the board is shut down. Reseating the board will re-initialize the board.</li><li>3. If the board was found to be correctly inserted in step 1, issue the <b>busyout board</b> command.</li><li>4. Issue the <b>reset board</b> command.</li><li>5. Issue the <b>release busy board</b> command.</li><li>6. Issue the <b>test board long</b> command.</li></ol> <p>This should re-establish the link between the internal ID and the port.</p>

**Inject Single Bit Error Test (#1215)**

**This test is destructive.**

The Inject Single Bit Error Test causes a single bit error to be sent within an active framed 3-in-24 test pattern.

The test is highly destructive and can only be initiated by a system technician demanded **test ds1-loop PCSS inject-single-bit-error** command. An attempt to use this command will be rejected if none of the three long-duration DS1 loopback/span tests (CPE Loopback Jack Test, Far CSU Loopback Test, One-Way Span Test) are active on a TN767E circuit pack.

All trunks or ports on the DS1 Interface circuit pack must be busied out via the system technician **busyout board** command before running the Inject Single Bit Error Test.

The **list measurements ds1 summary** command displays the number of bit errors detected (Loopback/Span Test Bit-Error Count field). Injecting this single bit error should increment the bit error count of the loopback/span test by one.

Table 5-241. TEST #1215 Inject Single Bit Error Test

Error Code	Test Result	Description/ Recommendation
	ABORT	Internal system error 1. Retry the test <code>ds1-loop PCSS inject-single-bit-error</code> command at 1-minute intervals a maximum of 5 times.
1015	ABORT	Ports on the DS1 Interface circuit pack have not been busied out to out-of-service. 1. Enter the <b>busyout board PCSS</b> command to put all trunks or ports of the DS1 Interface circuit pack into the out-of-service state. 2. Retry the command.
2100	ABORT ABORT	Internal system error Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals for a maximum of 5 times.

*Continued on next page*

Table 5-241. TEST #1215 Inject Single Bit Error Test — *Continued*

Error Code	Test Result	Description/ Recommendation
2000	ABORT	<p>Response to the test was not received within the allowable time period. This may be due to hyperactivity. Error type 1538 in the error log indicates hyperactivity. The hyperactive circuit pack is out of service and one or more of the following symptoms may be exhibited.</p> <ol style="list-style-type: none"><li>1. The DS1-BD tests (such as test 138 and test 139) are aborting with error code 2000.</li><li>2. The tests run on the ports of this circuit pack are returning a no board result.</li><li>3. A <b>busyout</b> or a <b>release</b> command has no affect on the test results.</li><li>4. A <b>list config</b> command shows that the circuit pack and the ports are properly installed.</li></ol> <p> <b>NOTE:</b> When hyperactivity occurs, the circuit pack is isolated from the system, and all of the trunks for this circuit pack are placed into the out of service state. The system will try to restore the circuit pack within 15 minutes. When no faults are detected for 15 minutes, the DS1 interface circuit pack is restored to normal operation. All of the trunks for the DS1 interface circuit pack are then returned to the in service state. Hyperactivity is often caused by the associated facility. In such a case, faults (such as slips, misframes, or blue alarms) would be entered in the error log. In addition, many hardware errors would be logged against the associated trunk circuits. If the facility is OK and the error occurs again after 15 minutes, replace the circuit pack.</p>

*Continued on next page*

Table 5-241. TEST #1215 Inject Single Bit Error Test — *Continued*

Error Code	Test Result	Description/ Recommendation
	PASS	A single bit error has been successfully injected into an active framed 3-in-24 test pattern.
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board).</p> <p>This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"><li>1. Check to ensure that the board translations are correct. Use the <b>add ds1 PCSS</b> command to administer the DS1 interface if it is not already administered.</li><li>2. If board was already administered correctly, check the error log to determine if the board is hyperactive. If this is the case, the board is shut down. Reseating the board will re-initialize the board.</li><li>3. If the board was found to be correctly inserted in step 1, issue the <b>busyout board</b> command.</li><li>4. Issue the <b>reset board</b> command.</li><li>5. Issue the <b>release busy board</b> command.</li><li>6. Issue the <b>test board long</b> command.</li></ol> <p>This should re-establish the link between the internal ID and the port.</p>

## End Loopback/Span Test (#1216)

**This test is destructive.**

The End Loopback/Span Test terminates an active loopback or span test on a TN767E DS1 circuit pack. Bit error counting against the received test pattern stream is terminated and sending of the framed 3-in-24 test pattern is halted. If either the CPE Loopback Jack or the far-end CSU is looped, the appropriate loopback deactivate code is sent. If the loopback could not be deactivated, then the test will FAIL and a MINOR alarm will be noted in the alarm log until the loopback is cleared.

The test is highly destructive and can only be initiated by a system technician demanded **test ds1-loop PCSS end-loopback/span-test** command. Since only one of these three different long-duration loopback/span tests can be active at a time, the TN767E circuit pack knows which loopback/span test to terminate.

All trunks or ports on the DS1 Interface circuit pack must be busied out via the system technician **busyout board** command before running this End Loopback/Span Test.

The **list measurements ds1 summary** command displays the length of time the test ran (Test Duration field) and number of bit errors detected (Loopback/Span Test Bit-Error Count field).

To restore the trunks or ports on the TN767E DS1 Interface circuit pack to the in-service state, execute the **release board** command.

Table 5-242. TEST #1216 End Loopback/Span Test

Error Code	Test Result	Description/ Recommendation
	ABORT	Internal system error  1. Retry the <b>test ds1-loop PCSS end-loopback/span-test</b> command at 1-minute intervals a maximum of 5 times.
1005	ABORT	End Loopback/Span Test cannot be executed in the current configuration. To run this, the TN767E or later suffix DS1 must be administered for 24-channel operation. The Bit Rate field on the DS1 circuit pack administration form must be set to <b>1.544</b> for 24-channel operation.
1015	ABORT	Ports on the DS1 Interface circuit pack have not been busied out to out-of-service.  1. Enter the <b>busyout board PCSS</b> command to put all trunks or ports of the DS1 Interface circuit pack into the out-of-service state.  2. Retry the command.
	ABORT	Internal system error

*Continued on next page*

Table 5-242. TEST #1216 End Loopback/Span Test — *Continued*

Error Code	Test Result	Description/ Recommendation
2100	ABORT	<p>Could not allocate the necessary system resources to run this test.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals for a maximum of 5 times.</li> </ol>
2000	ABORT	<p>Response to the test was not received within the allowable time period. This may be due to hyperactivity. Error type 1538 in the error log indicates hyperactivity. The hyperactive circuit pack is out of service and one or more of the following symptoms may be exhibited.</p> <ol style="list-style-type: none"> <li>1. The DS1-BD tests (such as test 138 and test 139) are aborting with error code 2000.</li> <li>2. The tests run on the ports of this circuit pack are returning a no board result.</li> <li>3. A <b>busyout</b> or a <b>release</b> command has no affect on the test results.</li> <li>4. A <b>list config</b> command shows that the circuit pack and the ports are properly installed.</li> </ol> <p><b>⇒ NOTE:</b></p> <p>When hyperactivity occurs, the circuit pack is isolated from the system, and all of the trunks for this circuit pack are placed into the out of service state. The system will try to restore the circuit pack within 15 minutes. When no faults are detected for 15 minutes, the DS1 interface circuit pack is restored to normal operation. All of the trunks for the DS1 interface circuit pack are then returned to the in service state. Hyperactivity is often caused by the associated facility. In such a case, faults (such as slips, misframes, or blue alarms) would be entered in the error log. In addition, many hardware errors would be logged against the associated trunk circuits. If the facility is OK and the error occurs again after 15 minutes, replace the circuit pack.</p>
1313	FAIL	<p>The TN767E DS1 circuit pack could not deactivate the loopback through the Customer Loopback Jack.</p> <ol style="list-style-type: none"> <li>1. Retry the <b>test ds1-loop PCSS end-loopback/span-test</b> command at 1-minute intervals for a maximum of 5 times.</li> </ol>
1314	FAIL	<p>The TN767E DS1 circuit pack could not deactivate the loopback through the far-end CSU.</p> <ol style="list-style-type: none"> <li>1. Make sure that the far-end DS1 is installed if the far-end CSU is a 120A CSU Module.</li> <li>2. Retry the command at 1-minute intervals for a maximum of 5 times.</li> </ol>
	PASS	<p>The active long-duration loopback or span test on the TN767E circuit pack was successfully terminated.</p>

*Continued on next page*

Table 5-242. TEST #1216 End Loopback/Span Test — *Continued*

Error Code	Test Result	Description/ Recommendation
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board).</p> <p>This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"><li>1. Check to ensure that the board translations are correct. Use the <b>add ds1 PCSS</b> command to administer the DS1 interface if it is not already administered.</li><li>2. If board was already administered correctly, check the error log to determine if the board is hyperactive. If this is the case, the board is shut down. Reseating the board will re-initialize the board.</li><li>3. If the board was found to be correctly inserted in step 1, issue the <b>busyout board</b> command.</li><li>4. Issue the <b>reset board</b> command.</li><li>5. Issue the <b>release busy board</b> command.</li><li>6. Issue the <b>test board long</b> command.</li></ol> <p>This should re-establish the link between the internal ID and the port.</p>

### ICSU Status LEDs Test (#1227)

The TN767E DS1 circuit pack has four status LEDs on the faceplate in addition to the three standard faceplate LEDs. These four status LEDs are associated with the 120A Channel Service Unit (CSU) Module that can be connected to the TN767E board via the I/O connector panel on the back of the port carrier.

This test is a visual test. It will light the four status LEDs red for 5 seconds, then light them green for 5 seconds, then light them yellow for 5 seconds, then turn the LEDs off and returns control of the status LEDs to the circuit pack.

This test will only be executed on TN767E or later suffix DS1 circuit packs administered for 24-channel operation (1.544 bit rate).

If the 1201 CSU Module is not installed, the status LEDs are always off and this test aborts.

Table 5-243. TEST #1227 ICUSU Status LEDs Test

Error Code	Test Result	Description/ Recommendation
	ABORT	Internal system error 1. Retry the command at 1-minute intervals a maximum of 5 times.
1005	ABORT	The ICUSU Status LEDs test can not be executed for the current configuration. The test applies only to TN767E or later DS1 circuit packs administered for 24-channel operation (1.544 bit rate). 1. If the circuit pack is a TN767E or later suffix DS1 circuit pack, then retry the command.
1951	ABORT	The ICUSU Status LEDs Test can not be executed because a 120A or later suffix CSU Module is not physically installed. If using a 120A CSU Module, physically connect it to the TN767E board on the back of the port carrier otherwise, ignore this abort.
2100	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals for a maximum of 5 times.
2500	ABORT	Internal system error. 1. Retry the command.

*Continued on next page*

Table 5-243. TEST #1227 ICSU Status LEDs Test — *Continued*

Error Code	Test Result	Description/ Recommendation
	PASS	The ICSU Status LEDs test executed successfully. A PASS result, however, does not necessarily mean that the status LEDs behaved properly. It only means that the software successfully attempted to light the status LEDs. This is a visual test. The service technician must visually exam the behavior of the LEDs while the test is running. The LEDs are functioning properly if the four status LEDs are lit red for 5 seconds, then lit green for 5 seconds, then lit yellow for 5 seconds. If the LEDs behave differently, the board should be replaced at the customer's convenience.
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board).</p> <p>This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"><li>1. Check to ensure that the board translations are correct. Use the <b>add ds1 PCSS</b> command to administer the DS1 interface if it is not already administered.</li><li>2. If board was already administered correctly, check the error log to determine if the board is hyperactive. If this is the case, the board is shut down. Reseating the board will re-initialize the board.</li><li>3. If the board was found to be correctly inserted in step 1, issue the <b>busyout board</b> command.</li><li>4. Issue the <b>reset board</b> command.</li><li>5. Issue the <b>release busy board</b> command.</li><li>6. Issue the <b>test board long</b> command.</li></ol> <p>This should re-establish the linkage between the internal ID and the port.</p>

## DT-LN-BD (Data Line Circuit Pack)

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run <sup>1</sup>	Full Name of MO
DT-LN-BD	MIN	test board PCSS sh	Data Line Circuit Pack
DT-LN-BD	WRN	test board PCSS sh	Data Line Circuit Pack

- Where P is the port network number (1 for PPN); C is the carrier designation (for example, A, B, or C); and SS is the address of the slot in the carrier where the circuit pack is located (for example, 01, 02, ..., etc.).

Refer to [“XXX-BD \(Common Port Circuit Pack\)” on page 5-1343](#) for circuit pack level errors. See also [“DAT-LINE \(Data Line\)” on page 5-466](#) for related line information.

## DTMR-PT [Dual Tone Multifrequency Port (TTR)]

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run <sup>1</sup>	Full Name of MO
DTMR-PT	MAJOR	test port PCSSpp sh	Dual Tone Multifrequency Receiver Port (TTR)
DTMR-PT	MINOR	test port PCSSpp sh	Dual Tone Multifrequency Receiver Port (TTR)
DTMR-PT	WARNING	release port PCSSpp	Dual Tone Multifrequency Receiver Port (TTR)

- Where P is the port network number (1 for PPN); C is the carrier designation (for example, A, B, or C); SS is the address of the slot in the carrier where the circuit pack is located (for example, 01, 02, ..., etc.); and pp is the 2-digit port number (for example, 01).

The Dual Tone Multifrequency Receiver Port (DTMR), also known as the Touch-Tone Receiver (TTR), resides on the Tone Detector circuit pack (TN748, TN420) or the TN756 Tone-Clock circuit pack. There are four Dual Tone Multifrequency Receiver (DTMR-PT) ports and two General Purpose Tone Detector (GPTD-PT) ports on a Tone Detector circuit pack. The DTMR port is used to detect touch-tone digits that are placed on the TDM bus. Examples of touch-tone digits are digits 0 through 9, #, and \*. The ability of the DTMR port to detect touch-tone digits is essential for maintenance of other circuit packs (for example, Tone-Clock circuit pack) and in placing a station-to-station call. Calls originating from a hybrid station **do not** require a DTMR port.

5 Maintenance Objects for DEFINITY ONE  
DTMR-PT [Dual Tone Multifrequency Port (TTR)]

5-625

The Dual Tone Multifrequency Receiver Port maintenance object defines a set of tests to verify that the DTMF digits detection capability of the DTMR port is functioning properly. For all Tone Detector circuit pack level errors (DETR-BD), refer to [“XXX-BD \(Common Port Circuit Pack\)” on page 5-1343](#).

## Hardware Error Log Entries and Test to Clear Values

Dual Tone Multifrequency Receiver Port (TTR) Error Log Entries

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
0 <sup>1</sup>	0	Any	Any	Any	test port PCSSpp sh r 1
1 (b)	17664	Tone Detector Audit/Update Test (#43)	MAJOR/ MINOR (a)	ON	test port PCSSpp r 2
18	0	busyout port PCSSpp	WARNING	ON	release port PCSSpp
130 (d)		None	WARNING	ON	test port PCSSpp sh r 2
257 (c)	17666	Tone Detector Audit/Update Test (#43)	MAJOR/ MINOR (a)	ON	test port PCSSpp r 3
513	Any	Tone Detection Verification Test (#42)	MAJOR/ MINOR (a)	ON	test port PCSSpp r 3

- Run the Short Test Sequence first. If all tests pass, run the Long Test Sequence. Refer to the appropriate test description and follow the recommended procedures.

### Notes:

- There are two possible alarm levels for this error: Major alarm and Minor alarm. A Major alarm is raised if the total number of DTMR ports currently in service is less than or equal to one half of the administered threshold number. Otherwise, a Minor alarm is raised. In either case, run the Short Test Sequence against the DTMR port and follow the error code procedures for the individual tests.

The threshold number of DTMR ports for service is administered using the **change system-parameters maintenance** command.

- This error indicates the DTMR port is having problems detecting touch-tone digits. If this error is being constantly logged, then the Tone Detector circuit pack containing the defective DTMR port should be replaced.

**5 Maintenance Objects for DEFINITY ONE**  
*DTMR-PT [Dual Tone Multifrequency Port (TTR)]*

5-626

- c. The DTMR port lost its translation. Testing the DTMR port is sufficient to reload its translation. If testing the DTMR port does not clear the error, then the Tone Detector circuit pack containing the defective DTMR port should be replaced.
  - d. This error type indicates that the circuit pack has been removed or has been insane for at least 11 minutes. To clear the error, reinsert or replace the circuit pack.
- 

**System Technician-Demanded Tests: Descriptions  
and Error Codes**

---

Always investigate tests in the order presented in the table below when inspecting errors in the system. By clearing error codes associated with the *Tone Detection Verification Test*, for example, you may also clear errors generated from other tests in the testing sequence.

Order of Investigation	Short Test Sequence	Long Test Sequence	D/ND <sup>1</sup>
Tone Detection Verification Test (#42)	X	X	ND
Tone Detector Audit/Update Test (#43)	X	X	ND

---

1. D = Destructive; ND = Nondestructive

---

## Tone Detection Verification Test (#42)

This test verifies the "touch-tone digits detection" capability of the DTMR port is functioning properly.

Table 5-244. TEST #42 Tone Detection Verification Test

Error Code	Test Result	Description/ Recommendation
none	ABORT	The system was not able to allocate all the resources needed for this test or there was an internal system error.
1	ABORT	The system could not allocate all the resources needed to test the DTMR port.
1001	ABORT	The system was unable to put the DTMR port in the appropriate mode to test it.
1002	ABORT	The system could not allocate time slots for the test connection. This could happen when the system is heavily loaded. If the system is not heavily loaded, then test the TDM Bus via the <b>test tdm [a b]</b> command. Refer to the <a href="#">"TDM-BUS (TDM Bus)" on page 5-1116</a> for details. <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
1003	ABORT	The system could not allocate a Tone Generator for the test connection. This could happen when the system is heavily loaded or there is not a Tone-Clock circuit pack in the port network when this test is being executed. <ol style="list-style-type: none"> <li>1. Make sure there is a Tone-Clock circuit pack in the same port network.</li> <li>2. If a Tone-Clock circuit pack is missing, install one in the same port network.</li> <li>3. Allow about 1 minute for the Tone-Clock maintenance to run on the newly inserted Tone-Clock circuit pack.</li> <li>4. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
2000	ABORT	Response to the test request was not received within the allowable time period.
2100	ABORT	Could not allocate the necessary system resources to run this test. <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
2006	ABORT	DTMF detection failed. This could be caused by the administered companding mode of the system not matching that of the Tone Detector circuit pack. <ol style="list-style-type: none"> <li>1. Make sure that companding mode of the system matches that of the Tone Detector.</li> </ol>

*Continued on next page*

Table 5-244. TEST #42 Tone Detection Verification Test — Continued

Error Code	Test Result	Description/ Recommendation
1-3	FAIL	DTMF digits were not correctly detected. <ol style="list-style-type: none"><li>1. Run the Short Test Sequence: <b>test port PCSSpp sh r 1</b>.</li><li>2. If the problem persists, the system is still operating properly but system capacity will be reduced. In order to restore the system performance to normal, replace the Tone Detector circuit pack containing the defective DTMR port.</li></ol>
	PASS	The DTMR port is able to detect all the touch-tone digits.

### Tone Detector Audit/Update Test (#43)

The DTMR port is refreshed with all time slot information and sanity audit is performed on the DTMR port.

Table 5-245. TEST #43 Tone Detector Audit/Update Test

Error Code	Test Result	Description/ Recommendation
	ABORT	The system was not able to allocate all the resources needed for this test. <ol style="list-style-type: none"><li>1. Wait one minute and try again.</li></ol>
2000	ABORT	Response to the test request was not received within the allowable time period.
2100	ABORT	Could not allocate the necessary system resources to run this test. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals for a maximum of 5 times.</li></ol>
	FAIL	Hardware audit failed. <ol style="list-style-type: none"><li>1. Run the Short Test Sequence: <b>test port PCSSpp sh r 1</b>.</li><li>2. If the problem persists, the system is still operating properly but system capacity is reduced. In order to restore the system performance to normal, replace the Tone Detector circuit pack containing the defective DTMR port.</li></ol>
	PASS	The DTMR port has been successfully refreshed with its translation.

## E-DIG-BD (Multi Application Platform Board)

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run <sup>1</sup>	Full Name of MO
DIG800-BD	MIN	test board PCSS sh	MO800DIG-BD
DIG800-BD	WRN	test board PCSS sh	MO800DIG-BD

- Where P is the port network number (1 for PPN); C is the carrier designation (for example, A, B, or C); and SS is the address of the slot in the carrier where the circuit pack is located (for example, 01, 02, ...).

The maintenance strategy for DIG800-BD is the same as the one described for MO-COMBD (MO-XXX-BD). Maintenance testing of the common circuit pack is handled by on-board firmware and SPE-controlled tests. Maintenance software queries the firmware for error and alarm information, status, and test results. The firmware automatically reports error conditions that will result in SPE-controlled testing.

### Board Insertion

The switch makes an additional board query if any of the following circuit packs are inserted:

Circuit Pack	Vintage
TN754	49

For any of the above initial board up-links, the switch sends queries requesting additional data from the board for administration purposes, while also telling the board the switch software release and the system type.

For the native mode, the response to the board query downlink messages consists of several CCMS uplink messages that identify the true board code, vintage, suffix, emulation type, and the number of reserved slots it needs.

### Hyperactivity

The common circuit pack is considered "hyperactive" if the service dispatcher receives 200 up-link messages from the circuit pack in a 10-second period. Since MAPD has 32 ports, the hyperactivity limit is increased to 500 up-link messages per 10seconds. An alarm is issued and the board taken out of service when the limit reaches 400 or when it hits 500 up-link messages in 10 seconds.

## LED Use

The LED Control message 038x requests the Angel to drive the Red, Yellow, and Green LEDs on the face plate of typical port board on or off. On the MAPD, only the Red LED is controlled by this message. Yellow and Green change requests received from the switch by the MAPD drive LCD behavior rather than LED behavior. The switch continues to send the same LED control messages to the MAPD that it currently sends to all other port boards. The MAPD will handle proper interpretation of these messages. You should note that the PC on the MAPD, as well as the switch itself, can control the LEDs and the LCD on the MAPD.

## Port Administration

In administration without hardware, the switch allows administration of up to 32 MAPD ports of any port type. If the port type later reported by the board does not match the existing type, the switch assumes the board is a MAPD board with a different configuration and rejects the board. MAPD\_DCP\_STA and MAPD\_ASAL\_STA are the only two types of terminals are allowed on a MAPD board. Therefore, while administering ports on MAPD using **add station form**, it will allow only the terminals mentioned above.



### NOTE:

Refer to [“XXX-BD \(Common Port Circuit Pack\)” on page 5-1343](#) for circuit pack level errors. See also DIG-LINE maintenance documentation for related line information.

## E-DIG-STA (Emulated Digital Line)

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run <sup>1</sup>	Full Name of MO
E-DIG-STA	MINOR	test port PCSSpp l	Emulated Digital St.
E-DIG-STA	WARNING	test port PCSSpp sh	Emulated Digital St.

- Where P is the port network number (1 for PPN); C is the carrier designation (for example, A, B, or C); and SS is the address of the slot in the carrier where the circuit pack is located (for example, 01, 02, ...).

There are 4 tests in the Emulated Digital Line station maintenance test sequence and only one test path in the test sequence. Once the test sequence is started, all tests in the test sequence are executed.

E-DIG-ST maintenance monitors and tests ports on the TN800 MAPD circuit pack and the hardware connected to those ports for lines administered as a digital station. These include stations with an emulated digital voice terminal and stations with an emulated digital voice terminal and a linked data module. Stand-alone data modules and data adaptors in stand-alone mode are not supported by the TN800 circuit pack. Circuit pack maintenance is covered by E-DIG-BD.

## Hardware Error Log Entries and Test to Clear Values

Table 5-246. Digital Line Error Log Entries

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
0 <sup>1</sup>	0	Any	Any	Any	test port PCSSpp sh r 1
18 (a)	0	busyout port PCSSpp	WNG	OFF	rel port PCSSpp
130 (b)		None	WNG	ON	test port PCSSpp sh
1793 (c)		Voice and Control Local Loop Test (#13)	MIN/ WNG <sup>2</sup>	ON	test port PCSSpp l r 3
2049 (d)		NPE Crosstalk Test (#9)	MIN/ WNG <sup>2</sup>	ON	test port PCSSpp l r 3
2305 (e)	32770	None			

*Continued on next page*

Table 5-246. Digital Line Error Log Entries — Continued

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
3840 (f)	40965	None			
3841 (g)	41029	None			
2304 (h)		None			

1. Run the Short Test Sequence first. If all tests pass, run the Long Test Sequence. Refer to the appropriate test description and follow the recommended procedures.
2. Major alarms may be downgraded to Warning alarms based on the value used in the **set options** command.

## Notes:

- a. Maintenance personnel has busied out the port in question. Make sure that the port is released from busyout by using the **release port PCSSpp** command.
- b. The circuit pack has been removed or has been insane for more than 21 minutes. To clear the error, reinsert or replace the circuit pack.
- c. The local loop test failed. Each failure increments the counter by 1 when the local loop test fails. The counter is decremented when the loop test passes. When the counter reaches a threshold of 3, an on-board MINOR alarm is raised. This is the code that is generated when the link between the circuit pack and the voice terminal is successfully reset. No technician action is necessary.
- d. The NPE Cross talk test failed. The counter is incremented by 1 when the NPE Cross talk test fails. The counter is decremented by 1 when the NPE Cross talk test passes. When the counter reaches a threshold of 3, an on-board MINOR alarm is raised and the board is taken out of service.
- e. The station went off-hook while it was in the ready-for-service state. Use the **status station** command to determine the state of the station. The off-hook should have moved the station to ready-for-service. No technician action is necessary.
- f. No terminal is connected to the Digital Line board. No maintenance action is required.
- g. The circuit pack's message buffer is full. This may be caused by having many display phones with heavy traffic connected to the circuit pack. No action is necessary.
- h. Internal system error; no action is necessary. The error counters 1, 2, 3, 4, 5, 6, 10, 11, 12, 13, 14, 15, and 16 do not have any significance for this MO.

## System Technician-Demanded Tests: Descriptions and Error Codes

Always investigate tests in the order presented in the table below when inspecting errors in the system. By clearing error codes associated with the Voice and Control Channel Local Loop Around Test, for example, you may also clear errors generated from other tests in the testing sequence.

Order of Investigation	Short Test Sequence	Long Test Sequence	D/ND <sup>1</sup>
Voice and Control Channel Local Loop Around Test (#13)		X	D
NPE Crosstalk Test (#9)		X	ND
Station Lamp Updates Test (#16)		X	ND

1. D = Destructive; ND = Nondestructive

### Digital Line NPE Crosstalk Test (#9)

One or more Network Processing Elements (NPEs) reside on each circuit pack with a TDM Bus interface. The NPE controls port connectivity and gain and provides conferencing functions on a per-port basis. The NPE Crosstalk Test verifies that this port's NPE channel talks on the selected time slot and never crosses over to time slots reserved for other connections. If the NPE is not working correctly, one-way and noisy connections may be observed. This test is part of a port's Long Test Sequence and takes about 20 to 30 seconds to complete. Crosstalk testing occurs on both the primary information channel (voice) and the secondary information channel (data) associated with each digital station port. If this test fails on either channel, the station and the DTDM are taken out-of-service.

Table 5-247. TEST #9 Digital Line NPE Crosstalk Test

Error Code	Test Result	Description/Recommendation
1	ABORT	<p>During testing of the primary information channel, system resources may not have been available or the port was busy during the test.</p> <ol style="list-style-type: none"> <li>1. Check the port status. Use the <b>display port PCSSpp</b> command to determine the station extension of the port. Use the <b>status station</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for this test. You will have to wait until the port is idle.</li> <li>2. If the port status is idle, then retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>

Continued on next page

Table 5-247. TEST #9 Digital Line NPE Crosstalk Test — *Continued*

Error Code	Test Result	Description/Recommendation
2	ABORT	<p>During testing of DTDM, system resources may not have been available or the port was busy during the test.</p> <ol style="list-style-type: none"> <li>1. Check if port is being used. If possible, disconnect by toggling the disconnect button on DTDM. Retry the command after 1 minute.</li> </ol> <p><b>⚠ WARNING:</b> <i>This action drops the call in progress.</i></p>
1000	ABORT	<p>System resources required to run this test are not available. The port may be busy with a valid call. Use <b>display port PCSSpp</b> to determine the station extension or attendant number of the port. Use <b>status station</b> or <b>status attendant</b> to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. You must wait until the port is idle before retesting. Attendants are always in use (off-hook) if the handset is plugged in and the port is not busied out.</p> <ol style="list-style-type: none"> <li>1. If the port status is idle, then retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
1001	ABORT	<p>System resources required to run this test are not available.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
1002	ABORT	<p>The system could not allocate time slots for the test. The system is under heavy traffic conditions or has time slots out-of-service due to TDM-BUS errors. Refer to "<a href="#">TDM-BUS (TDM Bus)</a>" on page 5-1116 to diagnose any active TDM-BUS errors.</p> <ol style="list-style-type: none"> <li>1. If system has no TDM-BUS errors and is not handling heavy traffic, repeat test at 1-minute intervals a maximum of 5 times.</li> </ol>
1003	ABORT	<p>The system could not allocate a tone receiver for the test. The system is oversized for the number of Tone Detectors present, or some Tone Detectors are out-of-service.</p> <ol style="list-style-type: none"> <li>1. Look for TTR-LEV errors in the Error Log. If present, refer to "<a href="#">TTR-LEV (TTR Level)</a>" on page 5-1223.</li> <li>2. Look for TONE-PT errors in the Error Log. If present, refer to "<a href="#">TONE-PT (Tone Generator)</a>" on page 5-1204.</li> <li>3. If neither condition exists, retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>

*Continued on next page*

Table 5-247. TEST #9 Digital Line NPE Crosstalk Test — *Continued*

Error Code	Test Result	Description/Recommendation
1004	ABORT	<p>The port was seized by a valid call during the test.</p> <ol style="list-style-type: none"> <li>1. Use <b>display port PCSSpp</b> to determine the station extension or attendant number of the port.</li> <li>2. Use <b>status station</b> or <b>status attendant</b> to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests.</li> <li>3. Wait until the port is idle before retesting. Attendants are always in use (off-hook) if the handset is plugged in and the port is not busied out.</li> </ol>
1020	ABORT	<p>Test disabled by background testing. Use the <b>status station</b> command to determine when the station is available for testing.</p>
2000	ABORT	<p>Response to the test request was not received within the allowable time period.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times..</li> </ol>
1 2	FAIL	<p>The Network Processing Element (NPE) of the tested port is transmitting in error. This causes noisy and unreliable connections.</p> <p>Failure code 1 indicates that the Crosstalk test failed on the primary channel.</p> <p>Failure code 2 indicates that the Crosstalk test failed on the secondary channel.</p> <ol style="list-style-type: none"> <li>1. Replace the circuit pack.</li> </ol>
	PASS	<p>The port is correctly using its allocated time slots.</p> <ol style="list-style-type: none"> <li>1. To ensure that this is not an intermittent problem, repeat this test a maximum of 10 times.</li> <li>2. If complaints persist, examine the station, connections, and wiring.</li> </ol>

**Voice and Control Channel Local Loop Test (#13)**

These tests check the information and control channels between the Switch Processing Element (SPE) and the Digital Line port circuit. The SPE sends a message to loop around both the information and control channels for the port. First, the primary information (voice) channel loopback test sends a digital count from the Tone-Clock circuit pack on the primary information channel time slot and receives the same digital count with a general purpose tone detector.

While the primary information channel is still looped around, the Control Channel Loop Around Test sends four different transparent patterns to the on-board microprocessor, receives them back, and compares them.

The Loop Around Test for the secondary information (data) channel is the same as the primary information channel loop around test and is performed only if a DTDM is administered.

Next, a Conference Test checks the primary information channel. This test is the same as Conference Test #6.

The four tests will generate only one resulting value (Pass, Fail, or Abort). If any test fails or aborts, the test sequence stops.

**Table 5-248. TEST #13 Voice and Control Channel Local Loop Test**

Error Code	Test Result	Description/ Recommendation
	ABORT	Internal system error 1. Retry the command at 1-minute intervals a maximum of 5 times.
1000	ABORT	System resources required to run this test are not available. The port may be busy with a valid call. Use <b>display port PCSSpp</b> to determine the station extension or attendant number of the port. Use <b>status station</b> or <b>status attendant</b> to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. Wait until the port is idle before retesting. Attendants are always in use (off-hook) if the handset is plugged in and the port is not busied out. 1. If the port status is idle, then retry the command at 1-minute intervals a maximum of 5 times.
1001	ABORT	System resources required to run this test are not available. 1. Retry the command at 1-minute intervals a maximum of 5 times.

*Continued on next page*

Table 5-248. TEST #13 Voice and Control Channel Local Loop Test — *Continued*

Error Code	Test Result	Description/ Recommendation
1002	ABORT	<p>The system could not allocate time slots for the test. The system is under heavy traffic conditions or it has time slots out-of-service due to TDM-BUS errors. Refer to <a href="#">“TDM-BUS (TDM Bus)” on page 5-1116</a> to diagnose any active TDM-BUS errors.</p> <ol style="list-style-type: none"><li>1. If system has no TDM-BUS errors and is not handling heavy traffic, repeat test at 1-minute intervals a maximum of 5 times.</li></ol>
1003	ABORT	<p>The system could not allocate a tone receiver for the test. The system is oversized for the number of Tone Detectors present, or some Tone Detectors are out-of-service.</p> <ol style="list-style-type: none"><li>1. Look for TTR-LEV errors in the Error Log. If present, refer to <a href="#">“TTR-LEV (TTR Level)” on page 5-1223</a>.</li><li>2. Look for TONE-PT errors in the Error Log. If present, refer to <a href="#">“TONE-PT (Tone Generator)” on page 5-1204</a>.</li><li>3. If neither condition exists, retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
1004	ABORT	<p>The port was seized by a valid call during the test. The test has been aborted. Use the <b>display port PCSSpp</b> command to determine the station extension or attendant number of the port. Use <b>status station</b> or <b>status attendant</b> to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. Wait until the port is idle before retesting. Attendants are always in use (off-hook) if the handset is plugged in and the port is not busied out.</p> <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
2000	ABORT	<p>Response to the test request was not received within the allowable time period.</p>
2100	ABORT	<p>Could not allocate the necessary system resources to run this test.</p> <ol style="list-style-type: none"><li>1. Rerun the test at 1-minute intervals a maximum of 5 times.</li></ol>

*Continued on next page*

Table 5-248. TEST #13 Voice and Control Channel Local Loop Test — *Continued*

Error Code	Test Result	Description/ Recommendation
7	FAIL	Conference Test failed on primary channel. In some cases, users may not notice disruption in service. In extreme cases, conferencing feature may not work at all.
14	FAIL	The primary voice channel is not transmitting properly. User impact may range from noticing nothing to not being able to use this port.
15	FAIL	The control channel between the processor and digital circuit pack is not transmitting properly. User impact may range from noticing nothing to not being able to use the port. This could disrupt other users.
16	FAIL	The secondary voice channel is not transmitting properly. User impact may range from noticing nothing to not being able to use this port. <ol style="list-style-type: none"><li>1. Run circuit pack tests to check the Tone Generator circuit pack and the Tone Detector circuit pack using the <b>test board PCSSpp</b> command.</li><li>2. Resolve any problems that are detected on the Tone Generator circuit pack or Tone Detector circuit pack.</li><li>3. If the Tone Generator and Tone Detector circuit packs are functioning properly and the test still fails, replace the Digital Line circuit pack.</li></ol>
	PASS	The test passed, and all channels are transmitting properly. <ol style="list-style-type: none"><li>1. To ensure that this is not an intermittent problem, repeat this test up to 10 times.</li><li>2. If noisy connections for voice or corrupted data for data transfer persist, examine the station, connections, and wiring.</li></ol>

**Station Lamp Updates Test (#16)**

This test lights all lamps on the terminal as specified. The lamp updates will run only if the station is in-service. The status of the station is checked and the lamp updates are blocked from taking place if the station is not in the in-service state. This test does not affect the status of the Message Waiting lamp.

**Table 5-249. TEST #16 DIG-LINE Station Lamp Updates Test**

Error Code	Test Result	Description/ Recommendation
	ABORT	Internal system error 1. Retry the command at 1-minute intervals a maximum of 5 times.
1	ABORT	System technician may have busied out the port. 1. Look in the Error Log for Error Type 18 (port busied out) for this port. If this error type is present, then release the port with the <b>release station &lt;extension&gt;</b> command and run the test again. 2. Make sure that the terminal is connected. 3. Retry the command at 1-minute intervals a maximum of 5 times.
3	ABORT	Station may be in ready-for-service or out-of-service state. 1. Use the <b>status station</b> command to verify state of station. 2. Make sure the terminal is connected. 3. Retry the command at 1-minute intervals a maximum of 5 times.
1000	ABORT	System resources required to run this test are not available. The port is busy with a valid call. Use <b>display port PCSSpp</b> to determine the station extension or attendant number of the port. Use <b>status station</b> or <b>status attendant</b> to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. Wait until the port is idle before retesting. Attendants are always in use (off-hook) if the handset is plugged in and the port is not busied out. 1. If the port status is idle, then retry the command at 1-minute intervals a maximum of 5 times.
1392	ABORT	This is currently a TTI port, and the test cannot execute on it. 1. Verify that the port is a TTI port using either the <b>display port</b> command (the display shows that the port is a TTI port) or the <b>list config</b> command (the display shows a $\tau$ for the port). 2. If either <b>list config</b> or <b>display port</b> indicates that the port is <i>not</i> a TTI port, escalate the problem. If both commands indicate that the port is a TTI port, the abort is correct, and no action is necessary.

*Continued on next page*

Table 5-249. TEST #16 DIG-LINE Station Lamp Updates Test — *Continued*

Error Code	Test Result	Description/ Recommendation
	FAIL	Internal system error <ol style="list-style-type: none"><li data-bbox="299 360 1089 396">1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
	PASS	The message to light all of the station lamps was sent successfully to the port. <ol style="list-style-type: none"><li data-bbox="299 476 1089 566">1. Observe the station lamps being lit when running the test. If all lamps do not light successfully, the other Digital Line test results may indicate related problems that will not allow the lamps to light.</li><li data-bbox="299 580 1089 634">2. Investigate by using other Digital Line port tests and by examining the station, wiring, and connections.</li></ol>

## EMG-XFER

---

### Emergency Transfer (SCC Cabinets)

---

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run	Full Name of MO
EMG-XFER	MAJOR	test environment	Emergency Transfer
EMG-XFER	WARNING	test environment	Emergency Transfer

The system provides the ability to cut designated analog phones through to CO trunks if the switch cannot provide even minimal phone service. This ability is known as Emergency Transfer. The EMG-XFER MO tracks the control of Emergency Transfer. There is one EMG-XFER MO for the port network. Emergency Transfer can be controlled by the system or can be manually controlled via the Emergency Transfer switch located on the Processor circuit pack. A manual ON position (up) generates a Major alarm. A manual OFF position (down) generates a Warning alarm. Unless a technician is currently working on the system, the switch should be left in the auto position.

### Error Log Entries and Test to Clear Values

---

Table 5-250. Emergency Transfer Error Log Entries

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
0	0	Any	Any	Any	test environment sh r 1
1 (a)	0	Emergency Transfer Query (#124)	MAJOR	ON	test environment r 3
257 (b)	0	Emergency Transfer Query (#124)	WARNING	ON	test environment r 3

**Notes:**

- a. Error Type: 1 - This error type indicates that the Emergency Transfer switch located on the Processor circuit pack is set to the manual ON position (up). When the Emergency Transfer switch is in this position it generates a Major alarm.
  - b. Error Type: 257 - This error type indicates that the Emergency Transfer switch located on the Processor circuit pack is set to the manual OFF position (down). When the Emergency Transfer switch is in this position it generates a Warning alarm.
-

## System Technician-Demanded Tests: Descriptions and Error Codes

---

Always investigate tests in the order presented in the following tables. By clearing error codes associated with the *Cabinet Query Test*, for example, you may also clear errors generated from other tests in the testing sequence. For example, you may also clear errors generated from other tests in the testing sequence.

### Single Carrier System

Order of Investigation	Short Test Sequence	Long Test Sequence	D/ND <sup>1</sup>
Cabinet Query Test (#122) (a)	X	X	ND
Emergency Transfer Query Test (#124)	X	X	ND
External Alarm Lead Query Test (#120) (b)	X	X	ND
Analog Ring Generator Initialization Test (#117) (c)	X	X	ND
Analog Ring Generator Query Test (#118) (c)	X	X	ND

---

1. D = Destructive; ND = Nondestructive

#### Notes:

- a. Refer to [“CABINET \(Cabinet Sensors\)” on page 5-363](#) for a description of this test.
  - b. Refer to “EXT-DEV” for a description of this test.
  - c. Refer to [“RING-GEN \(Analog Ring Generator\)” on page 5-1036](#) for a description of this test.
- 

### Emergency Transfer Query Test (#124)

This test queries the hardware for the state of the Emergency Transfer switch and reports the result. If the switch is in a position where the system software can control Emergency Transfer, then the test passes. If the switch is in a position where the system software cannot control Emergency Transfer, then the test fails. The Processor controls Emergency Transfer. The system software does not have control of Emergency Transfer within a cabinet if the switch is in the manual ON or manual OFF state.

Table 5-251. TEST #124 Emergency Transfer Query Test

Error Code	Test Result	Description/Recommendation
1000	ABORT	System resources required to run this test are not available. 1. Retry the command at 1-minute intervals a maximum of 5 times.
2000	ABORT	Response to the test request was not received within the allowable time period. 1. Retry the command at 1-minute intervals a maximum of 5 times. 2. If the test continues to ABORT with error code 2000, check for system powering problems with the A carrier. Resolve all CABINET alarms. Then, repeat the test.
2029	ABORT	Internal system error 1. Retry the command at 1-minute intervals a maximum of 5 times.
1	FAIL	Emergency Transfer is manually turned OFF via the Emergency Transfer switch. 1. Place the switch in the AUTO position.
2	FAIL	Emergency Transfer is manually turned ON via the Emergency Transfer switch. 1. Place the switch in the AUTO position.
	PASS	The system software has control of Emergency Transfer. If Emergency Transfer is invoked, then there can be a Major alarm in the system that is invoking Emergency Transfer. <a href="#">Table 5-252</a> lists the error types and MOs that may cause Emergency Transfer. If any or all of these errors appear in the log, then refer to the appropriate Maintenance documentation and resolve those problems first.  If none of these errors appear in the log, then check the Emergency Transfer hardware.

Table 5-252. Test #124 Error Log Entries That Cause Emergency Transfer

MO Name	Error Type	Aux Data
SW-CTL	1	
SW-CTL	2	
TONE-BD	1	0
TONE-BD	2305	0

## ERR-LOG (Error Log)

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run	Full Name of MO
ERR-LOG	none	none	Error Log

### Functional Description

The ERR-LOG MO is responsible for the sanity of the Alarm Log, the Hardware Error Log, and the Software Error Log. If an inconsistency is detected in any one of these logs, all logs are re-initialized and a hardware error is logged against ERR-LOG indicating the time of inconsistency. There are no tests and no alarms for the Error Log MO. This MO exists solely for the purpose of allowing errors to be logged against it.

### Hardware Error Log Entries and Test to Clear Values

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
0 <sup>1</sup>	Any	Any	Any	Any	none
510 (a)	Any	none	none	none	none

1. Run the Short Test Sequence first. If all tests pass, run the Long Test Sequence. Refer to the appropriate test description and follow the recommended procedures.

#### Notes:

- a. This error indicates that an inconsistency was detected in either the Alarm Log, the Hardware Error Log, or the Software Error Log. To recover from this error, all of the logs were cleared and re-initialized. Any alarms that were active at the time of this error have been cleared. There is no associated test for this error.

The Aux data value indicates when the inconsistency was found:

0	Found during a periodic audit of the Error Log
1	Found after an extended reboot
2	Found after a reboot
3	Found after a Reset System 3 (Cold_1)
4	Found after a Reset System 2 (Cold_2)
16	Found after a Warm Start
100	Found after an internal software audit

## ETH-PT (Control LAN Ethernet)

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run <sup>1</sup>	Full Name of MO
ETH-PT	MAJOR	test port UUCSSpp long	MO_ETH_PT
ETH-PT	MINOR	test port UUCSSpp long	MO_ETH_PT
ETH-PT	WARNING	test port UUCSSpp	MO_ETH_PT

1. *UU* is the universal cabinet number (1 for PPN, 2 - 44 for EPNs). *C* is the carrier designation (A, B, C, D, or E). *SS* is the number of the slot in which the circuit pack resides (01 to 21). *pp* is the two digit port number (01, 02, ...).

The TN799 Control LAN (C-LAN) packet port circuit pack provides TCP/IP connection to adjuncts applications such as CMS, INTUITY, and DCS Networking. The C-LAN circuit pack has one 10baseT Ethernet connection and up to 16 DS0 physical interfaces for PPP connections. Multiple C-LAN circuit packs in a system gives additional TCP/IP capacity.

A remote socket control link (RSCL) links the C-LAN and the SPE to pass call control and other management information. Since one link serves all the ports on the circuit pack, maintenance of the RSCL is part of the C-LAN circuit pack maintenance.

### NOTE:

The C-LAN TN799 circuit pack replaces the PGATE and PI circuit packs in the G3si/G3vs systems. The PGATE or PI can be used with the C-LAN to create an X.25-to-TCP/IP bridge for adjunct and DCS connections.

## Control LAN Congestion Controls

The switch activates congestion controls on C-LAN when it detects buffers exceeding the threshold. The switch releases the congestion controls when the C-LAN reports that its buffer level has returned to normal levels.

If congestion:	Then the switch:
Persists for a 14-minute interval,	Raises MINOR alarm.
Exhausts buffers,	Raises MINOR alarm.
Ceases for 12 minutes,	Retires MINOR alarm.

## Error Log Entries and Test to Clear Value

Table 5-253. ETH-PT Error Log Entries

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
0 <sup>1</sup>	0	Any	Any	Any	test port UUCSSpp s
1 (a)	0	Ethernet Local Looparound Test (#1278)	MINOR	ON	test port UUCSSpp l r 3
513 (b)	0	Link Integrity Inquiry (#1282)	MINOR	OFF	test port UUCSSpp r 2
769 (c)	0		WNG	OFF	
1281 (d)	0				
1537, 1538 (e)		Session Status Test (#1286)	MINOR	OFF	
1793-1920 (f)					
2305-2560 (g)					
2561-2816 (g)					
3329 (h)		TCP/IP Ping Test (#1281)	WNG	OFF	

- Run the Short Test Sequence first. If all tests pass, run the Long Test Sequence. Refer to the appropriate test description and follow the recommended procedures.

### Notes:

- Error Type 1:** Ethernet Local Looparound Test (#1278) failed.
  - Test the port (**test port UUCSSpp long**).
  - Refer to repair procedures for Test #1278.
- Error Type 513:** Link Integrity Inquiry Test (#1282) failed or C-LAN port detected loss of Ethernet link integrity.

### Possible causes:

- Cabling
  - Ethernet transceiver
- Test the port (**test port UUCSSpp long**).
  - If the Link Integrity Inquiry Test (#1282) fails, refer to its repair procedure.

c. **Error Type 769:** Port received invalid frame.

Invalid Ethernet frame errors occur when the frame

- Contains a bad Cyclic Redundancy Check (CRC)
  - Is misaligned
1. Isolate the problem with the Ethernet Local Looparound Test (#1278).
  2. Test the port (**test port UUCSSpp long**).
  3. Verify the repair with the Ethernet Local Looparound Test (#1278).
  4. Clear the alarm (**test port UUCSSpp long clear**).

d. **Error Type 1281:** System software received an indication that the far-end has requested a disconnect of a session on this link. This is a log-only error.

e. **Error Type 1537-1538:** Some or all sessions on a port are down.

If:	Then the switch:
Some sessions are down	Raises WARNING alarm on circuit pack
All sessions are down	Raises MINOR alarm on circuit pack

1. Test the port (**test port UUCSSpp short**).
2. Refer to Session Status Test (#1286) repair procedure to verify repair.

f. **Error Type 1793-1920:** system software received an indication that a socket was closed due to an error. Error Type indicates the application associated with this socket.

Error Type	Application
1793	Unused
1794	DCS
1795	AUDIX
1796	CMS
1797	ISDN Gateway
1798-1920	Reserved for future

Aux Data indicates the internal application number.

g. **Error Type 2305-2816:** System software detected a session is down. Aux Data indicates the session number. These are log only errors. Error types 2305-2560 are for session numbers 1-256. Error types 2561-2816 are for session numbers 257-512.

h. **Error Type 3329:** TCP/IP Ping Test failed.

1. Test port (**test port UUCSSpp short**).
2. Refer to TCP/IP Ping Test (#1281) repair procedures.

**System Technician-Demanded Tests:  
Descriptions and Error Codes**

Investigate errors in the order they appear in the table below.

Table 5-254. System Technician-Demanded Tests: ETH-PT

Order of Investigation	Short Test Sequence	Long Test Sequence	D/ND <sup>1</sup>
Ethernet Local Loop-Around Test (#1278)		X	D
TCP/IP Ping Test (#1281)	X	X	ND
Session Status Test (#1286)	X	X	ND
Link Integrity Inquiry Test (#1282)	X	X	ND

1. D = Destructive, ND = Non-destructive

**Ethernet Local Looparound Test (#1278)**

**This test is destructive.**

Use this test to check circuitry in the data path for an Ethernet call (from the on-board processor to the Ethernet Transceiver). This test fails if the data it receives does not match the data it transmits.

Table 5-255. TEST #1278 Ethernet Local Looparound Test

Error Code	Test Result	Description/ Recommendation
1000	ABORT	<p>The port is in use.</p> <ol style="list-style-type: none"> <li>Determine status of port (<b>status clan-port UUCSSpp</b>).</li> <li>Retry the command when the port is idle. The port may be forced to the idle state by executing a <b>busyout port UUCSS</b> command.</li> </ol> <p><b>⇒ NOTE:</b> The busyout port command is destructive, causing all calls and links associated with the port to be torn down.</p>
2000	ABORT	<p>Did not receive circuit pack test response within the allowable time period.</p> <ol style="list-style-type: none"> <li>If the problem persists, reset the circuit pack (<b>busyout board UUCSS</b>, <b>reset board UUCSS</b>, and <b>release board UUCSS</b>).</li> <li>If the problem persists, replace the circuit pack.</li> </ol>

*Continued on next page*

Table 5-255. TEST #1278 Ethernet Local Looparound Test — *Continued*

Error Code	Test Result	Description/ Recommendation
2012	ABORT	Internal system error. 1. Retry the command at 1-minute intervals, up to 3 times. 2. If the problem persists, escalate the problem.
2100	ABORT	Could not allocate the necessary resources to run test. 1. Retry the command at 1-minute intervals, up to 5 times. 2. If the problem persists, escalate the problem.
1	FAIL	Circuit pack detected failure in the Ethernet Local Looparound Test (#1278). 1. If the problem persists, reset the circuit pack ( <b>busyout board UUCSS</b> , <b>reset board UUCSS</b> , and <b>reset board UUCSS</b> ). 2. If the problem persists, replace the circuit pack.
	PASS	The circuitry tests properly.

### TCP/IP PING Test (#1281)

This non-destructive test fails if all the endpoints fail to respond. Use this test to check the circuitry in the data path for a peer-to-peer IP layer connection.

Table 5-256. TEST #1281 TCP/IP PING Test

Error Code	Test Result	Description/ Recommendation
1, 2, 11	ABORT	Internal error 1. Retry the command at 1-minute intervals a maximum of 3 times. 2. If the problem persists, escalate the problem.
7	ABORT	Destination unreachable. 1. Verify that there is a destination to ping in the routing table (list ip-route and look for destinations reachable through this ethernet port). 2. If there are no reachable destinations from this port (i.e., no routes administered on ethernet), administer a route and retry. 3. Escalate if the problem persists.

*Continued on next page*

Table 5-256. TEST #1281 TCP/IP PING Test — *Continued*

Error Code	Test Result	Description/ Recommendation
1005	ABORT	<p>Incorrect test configuration.</p> <ol style="list-style-type: none"> <li>1. Verify Ethernet link is in service (<b>status port UUCSSpp</b> or <b>status link n</b>).</li> <li>2. Verify that Ethernet link is enabled (<b>status port UUCSSpp</b> or <b>status link n</b> or <b>display data-module</b>).</li> <li>3. Verify routing table has reachable destinations.</li> <li>4. Repeat the test.</li> <li>5. If problem persists while the Ethernet link is in service and enabled, escalate the problem.</li> </ol>
1124	ABORT	<p>Ethernet link is not enabled.</p> <ol style="list-style-type: none"> <li>1. Verify that the Ethernet link is enabled (<b>status port UUCSSpp</b>, <b>status link n</b>, or <b>display data-module</b>).</li> <li>2. If the link is not enabled, enable the link (<b>change data-module</b>).</li> <li>3. Repeat the test.</li> <li>4. Escalate if the problem persists.</li> </ol>
1125	ABORT	<p>Ethernet link not in service.</p> <ol style="list-style-type: none"> <li>1. Verify Ethernet link is in service (<b>status port UUCSSpp</b> or <b>status link n</b>).</li> <li>2. If the link is not in service, release the link using (<b>release link n</b> or <b>release port UUCSSpp</b>).</li> <li>3. Repeat the test.</li> <li>4. Escalate if the problem persists.</li> </ol>
2000	ABORT	<p>Did not receive circuit pack test response within the allowable time period.</p> <ol style="list-style-type: none"> <li>1. Reset the circuit pack (<b>busyout board UUCSS</b>, <b>reset board UUCSS</b>, and <b>release board UUCSS</b>).</li> <li>2. If the test fails again, replace the circuit pack.</li> </ol>
2012	ABORT	<p>Internal system error.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals, up to 3 times.</li> <li>2. Escalate if the problem persists.</li> </ol>
2100	ABORT	<p>Could not locate the necessary system resources to run this test.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals, up to 5 times.</li> <li>2. Escalate if the problem persists.</li> </ol>

*Continued on next page*

Table 5-256. TEST #1281 TCP/IP PING Test — *Continued*

Error Code	Test Result	Description/ Recommendation
2500	ABORT	Internal system error. <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals, up to 3 times.</li> <li>2. Escalate if the problem persists.</li> </ol>
1003	FAIL	Ping to the destination failed due to on-board problem. <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals, up to 3 times.</li> <li>2. If the problem persists, reset the circuit pack (<b>busyout board UUCSS</b>, <b>reset board UUCSS</b>, and <b>release board UUCSS</b>).</li> <li>3. If the problem persists, re-administer the ethernet connection through a different ethernet port, if available.</li> <li>4. If the problem still persists, or if there are no other available ethernet ports, replace the circuit pack.</li> </ol>
1007	FAIL	Ping to the destination failed due to the destination down. <ol style="list-style-type: none"> <li>1. Verify that at least one destination reachable through this port is up. Ping this destination (ping ip-address xxx.xxx.xxx.xxx).</li> <li>2. If the ping to any destination is successful through this port, the link is up, although some destinations are unreachable. Ignore the failure.</li> <li>3. If ping to all destinations fail, test this port (<b>test port UUCSSpp short</b>) and follow repair procedures for Session Status Test (#1286) failures.</li> </ol>
	PASS	TCP/IP Ping Test (#1281) is successful.

### Link Integrity Inquiry Test (#1282)

This non-destructive test queries the C-LAN Ethernet port's physical connections.

If:	Then the test:
C-LAN connection is present,	Passes.
C-LAN connection is absent,	Fails.
There is no response,	Aborts.

Table 5-257. TEST #1282 Link Integrity Inquiry Test

Error Code	Test Result	Description/ Recommendation
1124	ABORT	Ethernet link is not enabled. <ol style="list-style-type: none"><li>1. Verify that the Ethernet link is enabled (<b>status port UUCSSpp</b>, <b>status link n</b>, or <b>display data-module</b>).</li><li>2. If the link is not enabled, enable the link (<b>change data-module</b>).</li><li>3. Repeat the test.</li><li>4. Escalate if the problem persists.</li></ol>
1125	ABORT	Ethernet link not in service. <ol style="list-style-type: none"><li>1. Verify whether Ethernet link is in service (<b>status port UUCSSpp</b> or <b>status link n</b>).</li><li>2. If the Ethernet link is not in service, release the link (<b>release link n</b> or <b>release port UUCSSpp</b>).</li><li>3. Repeat the test.</li><li>4. Escalate if the problem persists.</li></ol>
1959	ABORT	Downlink message error. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals, up to 3 times.</li><li>2. Escalate if the problem persists.</li></ol>
2012	ABORT	Internal system error. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals, up to 3 times.</li><li>2. Escalate if the problem persists.</li></ol>
2100	ABORT	Could not locate the necessary system resources to run this test. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals, up to 5 times.</li><li>2. Escalate if the problem persists.</li></ol>
2500	ABORT	Internal system error. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals, up to 3 times.</li><li>2. Escalate if the problem persists.</li></ol>

*Continued on next page*

Table 5-257. TEST #1282 Link Integrity Inquiry Test — *Continued*

Error Code	Test Result	Description/ Recommendation
	FAIL	<p>Link integrity lost due to problem with attachment of Ethernet cable to the port.</p> <ol style="list-style-type: none"> <li>1. Repeat the test.</li> <li>2. If the test fails, verify that the cable properly is secured to Ethernet port and to the bus.</li> <li>3. Verify the C-LAN circuit pack link integrity LED is glowing.</li> <li>4. Retry the test.</li> <li>5. If problem persists, refer to Ethernet Local Looparound Test (#1278) repair procedures.</li> </ol>
	PASS	The Ethernet Link Integrity Test (#1282) detects good connections.

### Session Status Test (#1286)

This non-destructive test determines the status of all Ethernet port sessions. This test queries the system software on port session status.

If the system software indicates that:	Then the switch:
All port sessions are up (ALL UP)	Raises no alarm, or retires alarm
Some port sessions are up (SOME UP)	Raises WARNING alarm
All port sessions are down (ALL DOWN)	Raises MINOR alarm

Table 5-258. TEST #1286 Session Status Test

Error Code	Test Result	Description/ Recommendation
1124	ABORT	<p>Ethernet link is not enabled.</p> <ol style="list-style-type: none"> <li>1. Verify that the Ethernet link is enabled (<b>status port UUCSSpp, status link n, or display data-module</b>).</li> <li>2. If the link is not enabled, enable the link (<b>change data-module</b>).</li> <li>3. Repeat the test.</li> <li>4. Escalate if the problem persists.</li> </ol>

*Continued on next page*

Table 5-258. TEST #1286 Session Status Test — *Continued*

Error Code	Test Result	Description/ Recommendation
1125	ABORT	Ethernet link not in service. <ol style="list-style-type: none"> <li>1. Verify whether Ethernet link is in service (<b>status port UUCSSpp</b> or <b>status link n</b>).</li> <li>2. If the Ethernet link is not in service, release the link (<b>release link n</b> or <b>release port UUCSSpp</b>).</li> <li>3. Repeat the test.</li> <li>4. Escalate if the problem persists.</li> </ol>
2000	ABORT	Did not receive circuit pack test response within the allowable time period. <ol style="list-style-type: none"> <li>1. If the problem persists, reset the circuit pack (<b>busyout board UUCSSpp</b>, <b>reset board UUCSS</b>, and <b>release board UUCSS</b>).</li> <li>2. If the problem persists, replace the circuit pack.</li> </ol>
2100	ABORT	Could not locate the necessary system resources to run this test. <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals, up to 5 times.</li> <li>2. Escalate if the problem persists.</li> </ol>
2500	ABORT	Internal system error. <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals, up to 3 times.</li> <li>2. Escalate if the problem persists.</li> </ol>
1	FAIL	System software indicates at least one Ethernet link session is down (SOME UP). <ol style="list-style-type: none"> <li>1. Isolate downed sessions (<b>status port UUCSSpp</b> or <b>status link n</b>).</li> <li>2. Follow actions based on session information.</li> </ol>
2	FAIL	System software indicates all Ethernet sessions are down (ALL DOWN). <ol style="list-style-type: none"> <li>1. Test the port (<b>test port UUCSSpp</b>) to verify the Ethernet Local Looparound Test (#1278) result.</li> <li>2. If test passes, wait for system software to indicate ALL UP.</li> <li>3. If the test fails, check the destination and other components in the path.</li> <li>4. If the destination and other components in the path are in-service, take action based on session information.</li> </ol>
	PASS	All sessions are up.

## ETR-PT (Enhanced Tone Receiver Port)

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run <sup>1</sup>	Full Name of MO
ETR-PT(a)	MAJOR	test port PCSSpp sh	Enhanced Tone Receiver Port
ETR-PT	MINOR	test port PCSSpp sh	Enhanced Tone Receiver Port
ETR-PT	WARNING	test port PCSSpp sh	Enhanced Tone Receiver Port

1. P is the port network number (1 for PPN). C is the carrier designation (A, B, or C). SS is the number of the slot in which the circuit pack resides (01 to 21).

For the first release of DEFINITY ONE, the TN744D Call Classifier circuit pack is used to provide 8 Enhanced Tone receiver (ETR) ports. Each of these ports provides the functions previously found individually on DTMR-PTs, GPTD-PTs and CLAS-PTs ports. Thus, each port on the TN744D can be used for any tone detection function that was previously done by TN748 and TN420 Tone Detection boards.

The TN744D provides mu-law or A-law tone detection capability.

The TN744D circuit pack is the only tone detector board used in the DEFINITY ONE CMC.

## Hardware Error Log Entries and Test to Clear Values

Table 5-259. Enhanced Tone Receiver Port (ETR-PT) Error Log Entries

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
1	any	Tone Detector Audit/Update Test (#43)	MAJOR/ MINOR (a)	ON	test port PCSSpp r 2
18		busyout port	WARNING	OFF	release port PCSSpp
257 (b)	17666	Tone Detection Audit Update Test (#43)	MAJOR/ MINOR (a)	ON	test port PCSSpp r 3
513 (c)	any	Tone Detection Verification Test (#42)	MAJOR/ MINOR (a)	ON	test port PCSSpp r 3

Notes:

- a. There are two possible alarm levels for this error type: major alarm and minor alarm. These alarm levels are dependent on the administered thresholds for TTR, CPTR and CCTR. Each ETR port is capable of operating any of these.

A major alarm is raised if the total number of ports capable of TTR, CPTR or CCTR detection currently in-service is less than or equal to 1/2 of the administered TTR, CPTR or CCTR threshold number. Otherwise, a minor alarm is raised.

1. Run the short test sequence against the port (ETR-PT) and follow the error code procedures for the individual tests. If the problem persists, proceed to 2.
2. Execute 3 commands: busyout board UUCSS, reset board UUCSS, and release board UUCSS. Reset is required to reload RAM associated with the TN744's DPS. This will take all 8 tone detector ports out of service for a few seconds. Only 4 of 8 will be out of service due to the alarm. (There are 4 tone detectors on each of the two DSPs.) Other than the unlikely potential of running out of tone detector resources in the switch, there is no other effect when the board is reset.
3. Test the board (test board UUCSS long)
4. If the test passes, terminate the repair process. If the test fails, replace the board containing the ETR-PT.

The threshold number of ports for service is administered using the **change system-parameters maintenance** command

- b. The ETR-PT lost its translation. Testing the ETR-PT is sufficient to reload its translation. If testing the ETR port does not clear the error, then the TN744 circuit pack containing the defective ETR port should be replaced at a time when it is convenient t.
  - c. This error indicates the (ETR-PT) Enhanced Tone Receiver port is having problems detecting touch tones, call progress or MFC tones. If this error type is persistently logged, then the TN744 circuit pack containing the defective ETR-PT should be replaced.
-

## System Technician-Demanded Tests: Descriptions and Error Codes

Always investigate tests in the order presented in the following tables when inspecting errors in the system. By clearing error codes associated with the *Tone Detection Verification Test*, for example, you may also clear errors generated from other tests in the testing sequence.

Order of Investigation	Short Test Sequence	Long Test Sequence	D/ND <sup>1</sup>
Tone Detection Verification Test (#42)	X	X	ND
Tone Detection Audit/Update Test (#43)	X	X	ND

1. D = Destructive; ND = Nondestructive

### Tone Detection Verification Test (#42)

This test checks out a single ETR port in the touch-tone receiver mode MFC tone detection/generation mode and general purpose tone detection mode. During the first portion of the test, the touch-tone receiver mode is tested. Then general purpose call progress and maintenance tones are tested and lastly MFC tones are tested.

Table 5-260. TEST #42 Tone Detection Verification Test

Error Code	Test Result	Description/ Recommendation
none	ABORT	The system was not able to allocate all the resources needed for this test OR there was an Internal System Error.
1	ABORT	The system could not allocate all the resources needed to test the tones.
1001	ABORT	The system was unable to put the ETR-PT in the appropriate mode to test it.
1002	ABORT	The system could not allocate time slots for the test connection. This situation could occur when the system is heavily loaded. If the system is not heavily loaded, then test the TDM-BUS via the <b>test tdm</b> command. Refer to <a href="#">“TDM-BUS (TDM Bus)” on page 5-1116</a> for details.  1. Retry the command at 1-minute intervals a maximum of 5 times.
1003	ABORT	The system could not allocate a Tone-Clock for the test connection. This may be caused by a heavy load on the system or by a faulted Tone-Clock.  1. Check to see if there are any alarms against the Tone-Clock. If so refer to the recommended procedures for TONE-BD or <a href="#">“TONE-PT (Tone Generator)” on page 5-1204</a> .  2. If a new Processor/Tone-Clock has been inserted, allow about 1 minute for maintenance to run on the newly inserted circuit pack.  3. Retry the command at 1-minute intervals a maximum of 5 times.

Continued on next page

Table 5-260. TEST #42 Tone Detection Verification Test — *Continued*

Error Code	Test Result	Description/ Recommendation
2000	ABORT	Circuit Pack's response to the test request was not received within the allowable time period. 1. Retry the command at 1-minute intervals a maximum of 5 times.
2006	ABORT	This abort code indicates that the active Tone-Clock circuit pack or a Tone Detector circuit pack may not be functioning properly. 1. Test the active Processor/Tone-Clock circuit pack in the port network with the <b>test tone-clock</b> PC command and refer to <a href="#">"TONE-BD (Tone-Clock Circuit Pack)" on page 5-1184</a> for failures. 2. Retry the command at 1-minute intervals a maximum of 5 times.
2100	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals a maximum of 5 times.
1-12 2	FAIL	DTMF digits were not detected correctly. 1. Run the short test sequence via the <b>test port PCSSpp sh r 1</b> command. 2. If the problem persists, the system is still operating properly but capacity will be reduced. To restore performance to normal, replace the circuit pack containing the defective ETR-PT (Enhanced Tone Receiver Port).
102	FAIL	2225 Hz Modem Answer Tone was not detected correctly. This will impact call-classification operation. 1. Run the short test sequence via the <b>test port PCSSpp sh r 1</b> command. 2. If the problem persists, the system can still operate properly but capacity will be reduced. In order to restore performance to normal, replace the circuit pack containing the defective port.
130	FAIL	Forward or Backward MFC signals were not correctly generated or detected. This will impact MFC calls. 1. Run the short test sequence via the <b>test port PCSSpp sh r 1</b> command. 2. If the problem persists, the system can still operate properly but capacity will be reduced. In order to restore performance to normal, replace the TN744 circuit pack containing the defective ETR-PT.
	PASS	Tone Detection Verification is successful. The ETR Port is able to detect/generate all necessary tones.

**Tone Detector Audit/Update Test (#43)**

A Digital Signal Processor sanity audit is performed on the ETR-PT.

**Table 5-261. TEST #43 Tone Detector Audit/Update Test**

Error Code	Test Result	Description/ Recommendation
none	ABORT	The system was not able to allocate all the resources needed for this test. 1. Wait 1 minute, and repeat the command a maximum of 5 times.
2000	ABORT	Response to the test request was not received within the allowable time period.
2100	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals a maximum of 5 times.
	FAIL	Hardware audit failed. 1. Run the short test sequence via the <b>test port PCSSpp sh r 1</b> command. If the test continues to fail, proceeds to Step 2. 2. Execute 3 commands: busyout board UUCSS, reset board UUCSS, and release board UUCSS. Reset is required to reload RAM associated with the TN744's DPS. This will take all 8 tone detector ports out of service for a few seconds. Only 4 of 8 will be out of service due to the alarm. (There are 4 tone detectors on each of the two DSPs.) Other than the unlikely potential of running out of tone detector resources in the switch, there is no other effect when the board is reset. 3. Test the board (test board UUCSS long) 4. If the test passes, terminate the repair process. If the test fails, replace the board containing the ETR-PT
	PASS	The ETR Port has passed the sanity inquiry.

## EXT-DEV ADMIN? N (External Device Alarm)

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run <sup>1</sup>	Full Name of MO
EXT-DEV	MAJOR	test environment P	External Device Alarm
EXT-DEV	MINOR	test environment P	External Device Alarm

1. Where P is an appropriate cabinet number determined via the PORT field from the Alarm or Error Log.



### NOTE:

Use this Maintenance Object when the External Device Alarm Admin? field on the *change system-parameters customer-options* form is set to **n**.

The Processor in carrier A monitors the EXT-DEV alarm leads. The system only recognizes pairs connected to the 1M and 1m (ALARM MONITOR) leads. Refer to the *DEFINITY Communications System Generic 1 and Generic 3i Wiring*, 555-204-111, for more details.

## Hardware Error Log Entries and Test to Clear Values

Table 5-262. Hardware Error Log Entries and Test to Clear Values

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
0 <sup>1</sup>	0	Any	Any	Any	test environment UU r2 or 6
1 or 5	Any	External Device Alarm Test (#120)	MAJOR MINOR <sup>2</sup>	OFF	test environment UU r 2 or 6

1. Run the Short Test Sequence first. If all tests pass, run the Long Test Sequence. Refer to the appropriate test description and follow the recommended procedures.
2. One port generates a MAJOR alarm; the other port generates a MINOR alarm.

## System Technician-Demanded Tests: Descriptions and Error Codes

---

Always investigate tests in the order presented in the table below when inspecting errors in the system. By clearing error codes associated with the *Cabinet Query Test*, you may also clear errors generated from other tests in the testing sequence.

Order of Investigation	Short Test Sequence	Long Test Sequence	D/ND <sup>1</sup>
Cabinet Query Test (#79)	X	X	ND
Emergency Transfer Query Test (#124) (a)	X	X	ND
External Device Alarm Test (MAJOR port) (#120)	X	X	ND
External Device Alarm Test (MINOR port) (#120)	X	X	ND
Analog Ring Generator Initialization Test (#117) (b)	X	X	ND
Analog Ring Generator Query Test (#118) (b)	X	X	ND

---

1. D = Destructive; ND = Nondestructive

### Notes:

- a. Refer to ["EMG-XFER" on page 5-641](#) for a description of this test.
  - b. Refer to ["RING-GEN \(Analog Ring Generator\)" on page 5-1036](#) for a description of this test.
-

**External Device Alarm Test (#120)**

The External Device Alarm Test requests the state of the External Device Alarm from the Maintenance circuit pack and reports the results. The test has no effect on the external device itself.

**Table 5-263. TEST #120 External Device Alarm Test**

Error Code	Test Result	Description/ Recommendation
1000	ABORT	System resources required to run this test are not available. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
2000	ABORT	Response to the test request was not received within the allowable time period. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li><li>2. If the test continues to ABORT with error code 2000, check for system powering problems with the A carrier. Look for and resolve all AC-POWER alarms. Then, repeat the test.</li><li>3. If the test continues to ABORT with a 2000 error code, check for and resolve all SYSAM errors. Then, repeat the test.</li></ol>
2029 2319 2320 2500	ABORT	Internal system error <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
ANY	FAIL	The External Device Alarm has been activated by the external device. <ol style="list-style-type: none"><li>1. Clear the major alarm on the external device, and rerun the test.</li><li>2. If the test still fails, then disconnect the External Device Alarms from the Maintenance circuit pack and rerun the test.</li><li>3. If the test still fails, then there is a problem with the Maintenance circuit pack that is reporting the alarm. This circuit pack should be replaced. There are failures that can occur on Maintenance circuit pack's that <i>will not</i> be detected by their respective maintenance, but which will cause many environment tests to fail. If many environment tests are failing, the suspect circuit pack should be replaced and the test rerun.</li></ol>
	PASS	If there is a problem with the external device, but the Maintenance circuit pack connected to the device reports no alarm, then the External Device may not be properly reporting the problems or the External Device may not be properly connected to the External Device.

## EXT-DEV ADMIN? Y (External Device Alarm)

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run	Full Name of MO
EXT-DEV	MAJOR	test eda-external-device-alm physical location	External Device Alarm
EXT-DEV	MINOR	test eda-external-device-alm physical location	External Device Alarm
EXT-DEV	WARNING	test eda-external-device-alm physical location	External Device Alarm

**NOTE:**

For this application the `External Device Alarm Admin?` field on the *change system-parameters customer-options* form is always set to **y**.

**NOTE:**

An un-administered external device alarm port, that is sensing a contact closure will have an entry in the Error Log and in the Alarm Log. INADS will not receive warning alarms.

For DEFINITY ONE, an EXT-DEV alarm can be generated from a contact closure on an analog station port on a Virtual Alarm board plugged into the virtual port location 1A11, from an analog station port administered for External Device Alarms (EDA), or from a contact closure on the Major or Minor alarm leads on the TN795.

The Virtual Alarm board is used to pass PC and AUDIX alarm information between the Global Alarm Manager (GAM) software and the DEFINITY maintenance software. These virtual alarm leads are administered on the *add eda* screen, when the ALT Name field is set to ECSPLAT. An OFF HOOK generates an alarm condition (Alarm LED on the Attendant console and the CMC cabinet are on), an ON HOOK is a non-alarm condition (Alarm LED on the Attendant console and the CMC cabinet are off). The alarm is not forwarded to INADS.

**NOTE:**

For DEFINITY ONE, the PR-AL-BD MO is used for board insertion of the virtual alarm board. There is no hardware associated with this MO. The virtual board is required in order to assign external device alarm ports for non-DEFINITY alarms (e.g. PC level alarms or AUDIX alarms) in order to enter non-DEFINITY alarms in the DEFINITY alarm log.

The external name used by maintenance for the virtual alarm board is PR-AL-BD. This appears on the screen displayed for the results of the *test board* command. The external name used by administration for the board is VIRTUAL ALARM BD. This appears on the screen for the *list configuration* and *change circuit pack* commands. The TN number assigned to this board is VIRALM.

**5** Maintenance Objects for DEFINITY ONE  
EXT-DEV ADMIN? Y (External Device Alarm)

5-664

Alarm leads can be connected to external devices such as Uninterruptible Power Supplies (UPS) or adjuncts. Certain conditions on the external device close the contacts on the alarm leads to notify the switch which in turn originates an EXT-DEV alarm.

The special locations *major* and *minor* are used to designate the major or minor processor board alarm connection. The major/minor designation specifies the port, not the alarm level associated with the connection; for example, the “major” port can be administered as a major, minor, or warning alarm, and the “minor” port can be administered as a major, minor or warning alarm. In addition Analog line ports can also be administered as external device alarms.

**⇒** NOTE:

For DEFINITY ONE, the major lead is always assigned to an external Uninterruptible Power Supply even if a UPS is not provided since that lead also causes a system shutdown after one minute.

**Hardware Error Log Entries and Test to Clear Values**

Table 5-264. EXT-DEV ADMIN? Error Log Entries

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
0	0	Any	Any	Any	test eda-external-device-alm physical location r 2 or 6
1 or 5	Any	External Device Alarm Test (#120)	Any	OFF	test eda-external-device-alm physical location r 2 or 6

**⇒** NOTE:

The loss of -48 volt power will prevent detection of an external device alarm. AC-POWER and DC-POWER alarms could indicate the loss of the external device alarm -48 volt power source. ALARM-PT alarms may also indicate a loss of power. When analog line ports are administered as analog line external device alarms loss of -48 volts will prevent detection of an external device alarm.

**System Technician-Demanded Tests: Descriptions  
and Error Codes**

Always investigate tests in the order presented in the table below when inspecting errors in the system. By clearing error codes associated with the *External Device Alarm Test*, you may also clear errors generated from other tests in the testing sequence.

Order of Investigation	Short Test Sequence	Long Test Sequence	D/ND <sup>1</sup>
External Device Alarm Test (MAJOR port) (#120)	X	X	ND
External Device Alarm Test (MINOR port) (#120)	X	X	ND
External Device Alarm Test (WARNING port) (#120)	X	X	ND

1. D = Destructive; ND = Nondestructive

**External Device Alarm Test (#120)**

The External Device Alarm Test requests the state of the External Device Alarm from the Processor circuit pack and reports the results. The test has no effect on the external device itself.

Table 5-265. TEST #120 External Device Alarm Test

Error Code	Test Result	Description/ Recommendation
1000	ABORT	System resources required to run this test are not available. 1. Retry the command at 1-minute intervals a maximum of 5 time.
2000	ABORT	Response to the test request was not received within the allowable time period. 1. Retry the command at 1-minute intervals a maximum of 5 time. 2. If the test is being run on a analog port circuit and it continues to ABORT with a 2000 error code, check for and resolve all circuit pack errors. Then, repeat the test. 3. Follow normal escalation procedures.
2029 2100 2319 2320 2500	ABORT	Internal system error 1. Retry the command at 1-minute intervals a maximum of 5 times. 2. If the test continues to abort, follow normal escalation procedures.

*Continued on next page*

5 Maintenance Objects for DEFINITY ONE  
EXT-DEV ADMIN? Y (External Device Alarm)

5-666

Table 5-265. TEST #120 External Device Alarm Test — *Continued*

Error Code	Test Result	Description/ Recommendation
ANY	FAIL	<p>The External Device Alarm has been activated by the external device.</p> <p>If this is a DEFINITY ONE system and the port location is 1A1101 or 1A1102, the failure is associated with a non-DEFINITY alarm generated by AUDIX or the Global Alarm Manager (GAM). Follow the steps below:</p> <ol style="list-style-type: none"> <li>1. Start up a bash session and enter the <i>alarmstat</i> command to determine which subsystem generated the alarm. See <a href="#">Table 6-7 on page 6-14</a> and <a href="#">Table 6-3 on page 6-4</a> for more information.</li> <li>2. If the alarm is from the GAM, use the <i>gamalarmstat</i> command to identify the source of the problem. Follow the procedures presented in <a href="#">Chapter 6, "DEFINITY ONE NT Log Events and Alarms"</a> to identify and clear the problem.</li> <li>3. If the alarm is from AUDIX, start up an AUDIX terminal session using DSA, enter the <i>display alarm</i> command, and follow the AUDIX maintenance procedures to identify and clear the problem.</li> </ol> <p>If this is a DEFINITY ONE system and the port location is NOT 1A1101 or 1A1102 or if this is not a DEFINITY ONE system, the failure is associated with an external device. Follow the steps below:</p> <ol style="list-style-type: none"> <li>1. Clear the major alarm on the external device, and rerun the test.</li> <li>2. If the test still fails, then disconnect the External Device Alarm Leads from the Processor board or the analog port circuit pack and rerun the test.</li> <li>3. If the test still fails, then there is a problem with the analog external device alarm port or the circuit pack that is reporting the alarm. This circuit pack should be replaced. There are failures that can occur on the Processor circuit pack that <i>will not</i> be detected by EDA maintenance, but which will cause many environment tests to fail. If many environment tests are failing, the suspect circuit pack should be replaced and the test rerun.</li> </ol>
	PASS	<p>If there is a problem with the external device, but the administered analog line external device alarm, or the administered Processor circuit pack EDA leads connected to the device reports no alarm, then the External Device may not be properly reporting the problems or the External Device may not be properly connected to the External Device Alarm Lead.</p>

## GPTD-PT [General Purpose Tone Detector Port (CPTR)]

---

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run <sup>1</sup>	Full Name of MO
GPTD-PT	MAJOR	test port PCSSpp sh	General Purpose Tone Detector Port (CPTR)
GPTD-PT	MINOR	test port PCSSpp sh	General Purpose Tone Detector Port (CPTR)
GPTD-PT	WARNING	release port PCSSpp	General Purpose Tone Detector Port (CPTR)

1. Where P is the port network number (1 for PPN); C is the carrier designation (for example, A, B, or C); SS is the address of the slot in the carrier where the circuit pack is located (for example, 01, 02, ..., etc.); and pp is the 2-digit port number (for example, 01).

The General Purpose Tone Detector (GPTD) Port, also known as Call Progress Tone Receiver (CPTR), combined tone detector and tone clock circuit pack. (The TN744 is used for additional ports.) There are two GPTD ports and four Dual Tone Multifrequency Receiver (DTMR) ports on a Tone Detector circuit pack. The GPTD port is used to perform level measurements of test tones and to detect call progress tones. Examples of call progress tones are dial tone, ring back, busy, alert, confirmation, and recall dial. The abilities of the GPTD port to perform level measurements of test tones and to detect call progress tones are essential for maintenance of other circuit packs (for example, Tone-Clock).

The GPTD maintenance feature defines a set of tests to ensure that the general purpose tone detection capability of the GPTD port is functioning properly. For all Tone Detector circuit pack level errors (DETR-BD), refer to [“XXX-BD \(Common Port Circuit Pack\)” on page 5-1343](#).

## H323-SGRP (H.323 Signaling Group)

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run	Full Name of MO
H323-SGRP	MINOR	test sig-group <i>grp#</i> <sup>1</sup>	H323 Signaling Group
H323-SGRP	WARNING	test sig-group <i>grp#</i> <sup>1</sup>	H323 Signaling Group

- grp#* is the signaling group number (1-166); the test sequence can be either short or long.

The H.323 Signaling Group (H323-SGRP) maintenance object supports a signaling channel for H.323 Trunk connections. The Media Processor (MedPro) TN802B circuit pack provides audio connectivity, working in concert with a C-LAN (TN799B) circuit pack that provides control signaling to support an H.323 connection.

The H.323 signaling group (323-SGRP) is a signaling channel that physically rides on a C-LAN ethernet port (socket) and the IP network. Unlike ISDN D-channels, the H.323 channel may actually come up and down on a call by call basis. The H.323 channel is actually a TCP/IP signaling channel. Layers 1 and 2 of this signaling channel are monitored by IP PING testing.

### Error Log Entries and Test to Clear Values

Table 5-266. 323-SGRP Signaling Group Error Log Entries

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
0	0	Any	Any		test sig-group <i>grp#</i>
1 (a)	Any	Ethernet Port Status Test #1386	MINOR	OFF	test sig-group <i>grp#</i>
257 (b)	Any	H.323 SGRP PING Test #1387	MINOR	OFF	test sig-group <i>grp#</i>
513(c)	Any	H.323 SGRP PING Test #1387	WARNING	OFF	test sig-group <i>grp#</i>
769(d)	Any		WARNING	OFF	
1025(e)	Any		MINOR	OFF	
1281(f)	Any	MEDPRO Status Test #1392	NONE		test sig-group <i>grp#</i>
1537(g)	Any		NONE		

## Notes:

- a. **Error Type 1:** this error indicates that the C-LAN ethernet port used to carry the signaling for this H.323 signaling group is out of service. To determine which C-LAN had been administered for this signaling group, find the near-end node name on the **signaling group** form; then find the C-LAN with the same node name on the **ip-interfaces form**. Check for errors on this C-LAN board.
- b. **Error Type 257:** this error tracks failures of the H.323 signaling-group PING test. See H.323 signaling-group PING test failures documented later in this maintenance object.
- c. **Error Type 513:** this error tracks excessive round trip delay of the H.323 signaling-group PING test (if the round-trip delay exceeds 4 seconds).
- d. **Error Type:769:** this error indicates that test packets sent from a media processor circuit pack to the far-end ip address specified on the **signaling-group** form have exceeded the IP latency and loss thresholds, as administered on the **system-parameters maintenance** form. Exceeding these thresholds indicates that the IP network may not be providing sufficient quality service for adequate transmission of voice. If the signaling group has been administered to enable BYPASS, then error type 1025 should also occur.
- e. **Error Type 1025:** this error indicates that the signaling group has been placed into a BYPASS condition due to IP network congestion. The signaling group accepts incoming calls, but all outgoing calls are denied. The system routes these calls over a secondary route if one has been administered.
- f. **Error Type 1281:** this error implies that no MedPro resources are in-service to provide media connections for the trunk members of the signaling group. Check for errors against the MEDPRO and MEDPROPT maintenance objects. This error causes all H323 B Channels to be in an out-of-service near-end state.
- g. **Error Type 1537:** this error indicates that the far end of the signaling group is not ready to handle audio bearer. If the other end of this signaling group is also a DEFINITY, this error means the DEFINITY on the other end does not have MEDPRO in-service for its signaling group.

In the absence of error 1281, this error will place the H323 B Channels into an out-of-service far-end state.

---

## System Technician-Demanded Tests: Descriptions and Error Codes

---

Always investigate tests in the order presented in the table below when inspecting errors in the system. By clearing error codes associated with the *C-LAN Ethernet Status Test (#1386)*, for example, you may also clear errors generated from other tests in the testing sequence.

Order of Investigation	Short Test Sequence	Long Test Sequence	D/ND <sup>1</sup>
C-LAN Ethernet Status Test (#1386)	X	X	ND
MedPro Status Test (#1392)	X	X	ND
H.323 Signaling Group Ping Test (#1387)	X	X	ND

---

1. D = Destructive; ND = Nondestructive

### C-LAN Ethernet Status Test (#1386)

This test is non-destructive.

This test checks the status of the C-LAN ethernet port that originated this signaling group. If the C-LAN ethernet port is in-service, the test passes, if it is out of service the test fails.

**NOTE:**

Failure of this test puts the SIG-GRP in the OOS state.

Table 5-267. TEST #1386 C-LAN Ethernet Status Test

Error Code	Test Result	Description/ Recommendation
2500	ABORT	Internal system Error.  1. Retry the command at 1-minute intervals a maximum of 3 times
2800	ABORT	A C-LAN ethernet port that corresponds to the near-end address of the signaling group has not been administered.
	FAIL	The C-LAN ethernet port that corresponds to the near-end address of this signaling group and all trunk members controlled by this signaling group are out of service.  1. Check the system for errors against the out of service C-LAN board.
	PASS	The C-LAN ethernet port that corresponds to the near-end address of this signaling group is in-service.

### H.323 Signaling Group Ping Test (#1387)

This test is nondestructive.

This test is only run for those signaling groups that have an administered far-end IP address. If the H.323 signaling group does not have an administered far-end IP address the test aborts.

The test determines the local C-LAN through which the signaling originates and the far-end terminating IP address. It then requests the local C-LAN to execute a PING on the far-end address. If the ping is successful, the test passes, if the PING is not successful, the test fails.

#### NOTE:

Multiple failures of this test can take the H.323 signaling group out of service.

If the PING is successful, this test looks at the PING round trip delay. If a round trip delay of greater than 4 seconds is reported, a separate error is logged. Excessive round trip delays within the signaling group do not take the signaling group out of service.

Services can execute the standard **ping** command using the C-LAN board address and far-end IP address from the signaling group form to see the actual round-trip delay.

**5 Maintenance Objects for DEFINITY ONE**  
*H323-SGRP (H.323 Signaling Group)*

5-672

This test checks the circuitry involved in the data path of a peer-to-peer IP layer connection.

This nondestructive test runs due to in-line errors, during periodic and schedule maintenance, and on demand.

**Table 5-268. TEST #1387 H.323 Signaling Group Ping Test**

<b>Error Code</b>	<b>Test Result</b>	<b>Description/ Recommendation</b>
1005	ABORT	This signaling group has no administered far-end address. The test does not apply to this configuration.
2800	ABORT	A C-LAN ethernet port that corresponds to the near-end address of the signaling group has not been administered.
ANY	ABORT	Refer to the C-LAN port PING test in <a href="#">Table 5-256 on page 5-649</a> for a more detailed description of the reasons for the abort.
ANY	FAIL	The far-end of the signaling group could not be reached. <ol style="list-style-type: none"><li>1. Refer to the C-LAN port PING test in for a more detailed description of the reasons for the failure.</li></ol>
	PASS	The system can PING the administered far-end address of the H323 signaling group.

**MedPro Status Test (#1392)**

This test is non-destructive.

Voice calls over H.323 signaling groups are carried by media processor resources. If there are no media processor resources in-service for the specified signaling group, the H323 B Channels are placed into out-of-service near-end, so that calls may flow to other trunk groups controlled by different signaling groups.

On the **ip-interfaces form**, the field `Inter-region IP connectivity allowed?` may be set to **y** or **n**. If the field is set to **n**, only media processors in the same region as the signaling group can carry calls.

This test determines if a media processor is in-service in the same region as the C-LAN that carries this signaling group. If the field is set to **y**, any media processor in the system can carry calls. This test determines if a media processor is in-service in any region.

5 Maintenance Objects for DEFINITY ONE  
HYB-BD (Hybrid Line Circuit Pack)

5-673

Table 5-269. TEST #1392 MedPro Status Test

Error Code	Test Result	Description/ Recommendation
ANY	ABORT	Internal system Error.
	FAIL	No in-service Medpro ports exist for use by this signalling group. The H323 B Channels are placed into OOS-NE.  1. Check the system for errors against MEDPRO and MEDPROPT maintenance objects.
	PASS	In-service Medpro ports exist for use by this signaling group.

## HYB-BD (Hybrid Line Circuit Pack)

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run <sup>1</sup>	Full Name of MO
HYB-BD	MIN	test board PCSS sh	Hybrid Line Circuit Pack
HYB-BD	WRN	test board PCSS sh	Hybrid Line Circuit Pack

- Where P is the port network number (1 for PPN); C is the carrier designation (for example, A, B, or C); and SS is the address of the slot in the carrier where the circuit pack is located (for example, 01, 02, ..., etc.).

Refer to [“XXX-BD \(Common Port Circuit Pack\)” on page 5-1343](#) for circuit pack level errors. See also [“HYB-LINE \(Hybrid Line\)” on page 5-674](#) for related line information.

## HYB-LINE (Hybrid Line)

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run <sup>1</sup>	Full Name of MO
HYB-LINE	Minor	test port PCSSpp l	Hybrid Line
HYB-LINE	Warning	test port PCSSpp l	Hybrid Line

- Where P is the port network number (1 for PPN); C is the carrier designation (for example, A, B, or C); SS is the address of the slot in the carrier where the circuit pack is located (for example, 01, 02, ..., etc.); and pp is the 2-digit port number (for example, 01).

Hybrid Line is the user-friendly name for Hybrid Line, which was previously used to denote the Multifunction Analog Telephone. The Hybrid Line set is also known as an SCS (Small Communications System).

The TN762B Hybrid Line circuit pack supports eight of these multifunction analog telephone sets, as shown in the following figure. The Hybrid Line sets use three pairs of wires: an analog voice pair, a transmit/receive pair, and a power pair.




Figure 5-22. Hybrid Station Interactions

This section refers only to the HYB-LINE (Hybrid Line) maintenance that is performed. Please note that the HYB-LINE (Hybrid Line) maintenance is closely related to, and interacts with, the HYB-BD (Hybrid Line circuit pack) maintenance in some instances. Some of the results of maintenance testing of the Hybrid Line may be affected by the health of the Hybrid Line circuit pack. This interaction should be kept in mind when investigating the cause of reported Hybrid Line problems.

There are instances in this section where "service states" of a station are mentioned. It is helpful to understand what is meant by the different service states that may exist. An explanation of these service states follows:

- **Out-of-Service**—The port, and thus the station, have been removed from service. A busyout of a port causes it to be out-of-service.
- **Ready-for-Service**—Once a port on the circuit pack has been put into service, the voice terminal must communicate that it is present. The time between these two events is the time when the terminal is in the ready-for-service state.
- **In-Service**—Once the system has received a message from the voice terminal communicating that it is present, the station is put into the in-service state. The terminal can also be forced into the in-service state if it goes off-hook while it is in the ready-for-service state.

When the **status station** command has been run, and the status screen appears, the status is reported as either out-of-service or in-service, which mean exactly as stated in the above list, or disconnect, which means the station is in the ready-for-service state.

## Hardware Error Log Entries and Test to Clear Values

Table 5-270. Hybrid Line Error Log Entries

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
0 <sup>1</sup>	0	Any	Any	Any	test port PCSSpp sh r 1
1 (a)	Any	None	WARNING	OFF	
15 (b)	Any	Hybrid Audits Test (#61)			
18 (c)	0	busyout port PCSSpp	WARNING	OFF	release port PCSSpp
130 (d)		None	WARNING	ON	test port PCSSpp sh
257 (e)	40988	None	MIN/WRN <sup>2</sup>	OFF	

Continued on next page

5 Maintenance Objects for DEFINITY ONE  
HYB-LINE (Hybrid Line)

5-676

Table 5-270. Hybrid Line Error Log Entries — Continued

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
513 (f)	40965	Hybrid Line Audits Test (#61)	WARNING	OFF	test port PCSSpp sh r 4
769 (g)		Remote Dig Loop Around Test (#59)	WARNING	OFF	test port PCSSpp sh r 3
1025		Hybrid & Conf. Circuits Test (#57)	MIN/WRN <sup>2</sup>	ON	test port PCSSpp l r 3
1281 (h)		Local Digital Loop Around Test (#58)	WARNING	ON	test port PCSSpp l r 3
1537 (i)	40968	None	WARNING	OFF	
1793		TDMNPE Crosstalk Test (#6)	MIN/WRN <sup>2</sup>	ON	test port PCSSpp l r 3
2049 (j)	32770	None			
2049 (k)	40967	None			

1. Run the Short Test Sequence first. If all tests pass, run the Long Test Sequence. Refer to the appropriate test description and follow the recommended procedures.
2. Major or Minor alarms on this MO may be downgraded to Warning alarms based on the values used in the **set options** command.

## Notes:

- a. Indicates a defective data link. An off-board problem was detected by port circuit. Verify that the Hybrid set is connected and that the EPF test passes. If data transmission problems are experienced, check for defective wiring or a defective voice terminal, or move terminal closer to the switch (in terms of feet of wire from the jack to the switch). If the problem still exists, replace the circuit pack. Once the problem has been resolved, the alarm is retired after a predetermined period of time.
- b. This is a software audit error that does not indicate any hardware malfunction. Run Short Test Sequence and investigate associated errors (if any).
- c. This error type is logged when the port in question is busied out by maintenance personnel. Make sure port is released from busyout via the **release port PCSSpp** command.
- d. This error type indicates that the circuit pack has been removed or has been insane for more than 11 minutes. To clear the error, reinsert or replace the circuit pack.

5 Maintenance Objects for DEFINITY ONE  
HYB-LINE (Hybrid Line)

5-677

- e. This indicates that the EPF has been turned off due to an overcurrent condition at the voice terminal. Check for defective wiring or a damaged jack, and make sure the voice terminal is a Hybrid set. Once the problem has been resolved, the alarm is retired after a predetermined period of time.
  - f. This indicates that the voice terminal has probably been disconnected or that there is a problem in the wiring to the terminal. Make sure that the voice terminal is connected or check for defective wiring to the voice terminal.
  - g. Note that Error Types 769 and 1281 by themselves create Warning alarms only, but if both are present, a Minor alarm is logged.
  - h. This indicates that there is something wrong with the data link to the voice terminal. An in-line maintenance error has generated an off-board warning. Ignore it if there are no complaints. Otherwise, make sure the voice terminal is connected, check for defective wiring, check for a defective voice terminal, and move voice terminal closer to the switch (in terms of feet of wire from the jack to the switch). If the problem still exists, replace the circuit pack.
  - i. This indicates that the station went off-hook while in the disconnect state. Use the **status station** command to determine the state of the station. The off-hook should have moved the station to in-service. No system technician action is necessary.
  - j. This is the code that is generated when the link between the circuit pack and the voice terminal is successfully reset. No system technician action is necessary.
-

## System Technician-Demanded Tests: Descriptions and Error Codes

---

Always investigate tests in the order presented in the table below when inspecting errors in the system. By clearing error codes associated with the *Local Digital Loop Around Test*, for example, you may also clear errors generated from other tests in the testing sequence.

Table 5-271. System Technician-Demanded Tests: HYB-LINE

Order of Investigation	Short Test Sequence	Long Test Sequence	D/ND <sup>1</sup>
Local Digital Loop Around Test (#58)		X	ND
NPE Crosstalk Test (#6)		X	ND
Hybrid Electronic Power Feed Test (#56)		X	ND
Hybrid Circuit and Conference Circuit Test (#57)		X	ND
Remote Digital Loop Around Test (#59)	X	X	ND
Station Lamp Update Test (#60)	X	X	ND
Station Audits Test (#61)	X	X	ND
Ringer Update Test (#62)	X	X	ND

---

1. D = Destructive, ND = Non-destructive

---

**NPE Crosstalk Test (#6)**

One or more NPEs reside on each circuit pack with a TDM Bus interface. The NPE controls port connectivity and gain, and provides conferencing functions on a per port basis. The NPE Crosstalk Test verifies that this port's NPE channel talks on the selected time slot and never crosses over to time slots reserved for other connections. If the NPE is not working correctly, one-way and noisy connections may be observed. This test is part of a port's Long Test Sequence and takes about 20 to 30 seconds to complete.

**Table 5-272. TEST #6 NPE Crosstalk Test**

Error Code	Test Result	Description/ Recommendation
	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals a maximum of 5 times.
1000	ABORT	System resources required to run this test are not available. The port may be busy with a valid call. Use the <b>display port PCSSpp</b> command to determine the station extension number of the port. Use the <b>status station</b> command to determine the service state of the port. (Refer to " <a href="#">status station</a> " on page 4-213 for a description of all possible states.) If the service state indicates that the port is in use, then the port is unavailable for certain tests. You must wait until the port is idle before retesting. Attendants are always in use (off-hook) if the handset is plugged in and the port is not busied out. 1. If the port status is idle, then retry the command at 1-minute intervals a maximum of 5 times.
1001	ABORT	Could not allocate the necessary system resources to run this test. This could be due to a failure to seize the port. 1. Retry the command at 1-minute intervals a maximum of 5 times.
1002	ABORT	The system could not allocate time slots for the test. The system may be under heavy traffic conditions or it may have time slots out-of-service due to TDM-BUS errors. Refer to " <a href="#">TDM-BUS (TDM Bus)</a> " on page 5-1116 to diagnose any active TDM-BUS errors. 1. If system has no TDM-BUS errors and is not handling heavy traffic, repeat test at 1-minute intervals a maximum of 5 times.

*Continued on next page*

5 Maintenance Objects for DEFINITY ONE  
HYB-LINE (Hybrid Line)

5-680

Table 5-272. TEST #6 NPE Crosstalk Test — *Continued*

Error Code	Test Result	Description/ Recommendation
1003	ABORT	<p>The system could not allocate a tone receiver for the test. The system may be oversized for the number of Tone Detectors present or some Tone Detectors may be out-of-service.</p> <ol style="list-style-type: none"> <li>1. Look for TTR-LEV errors in the Error Log. If present, refer to "<a href="#">TTR-LEV (TTR Level)</a>" on page 5-1223.</li> <li>2. Look for TONE-PT errors in the Error Log. If present, refer to "<a href="#">TONE-PT (Tone Generator)</a>" on page 5-1204.</li> <li>3. If neither condition exists, retry the test at 1-minute intervals a maximum of 5 times.</li> </ol>
1004	ABORT	<p>The port was seized by a valid call during the test. The test has been aborted. Use the <b>display port PCSSpp</b> command to determine the station extension number of the port. Use the <b>status station</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. You must wait until the port is idle before retesting. Attendants are always in use (off-hook) if the handset is plugged in and the port is not busied out.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
1018	ABORT	<p>Test disabled via administration. This only applies to analog stations. The default for this field is 'y,' so you may want to determine why it has been turned off for this station.</p> <ol style="list-style-type: none"> <li>1. To enable test, set the <b>Test</b> field on the station administration screen for the particular analog station being tested to <b>y</b>. Use the <b>change station &lt;extension&gt;</b> command.</li> </ol>
2000	ABORT	<p>Response to the test request was not received within the allowable time period.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
2020	ABORT	<p>The test did not run due to an already existing error on the specific port or a more general circuit pack error.</p> <ol style="list-style-type: none"> <li>1. Examine Error Log for existing errors against this port or the circuit pack and attempt to diagnose the already existing error.</li> </ol>
2100	ABORT	<p>Could not allocate the necessary system resources to run this test. This could be due to a failure to seize the port.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>

*Continued on next page*

Table 5-272. TEST #6 NPE Crosstalk Test — *Continued*

Error Code	Test Result	Description/ Recommendation
Any	FAIL	<p>This test can fail due to on-board or off-board problems. Off-board problems of concern include EXP-INTF faults, TDM-BUS faults, and faults associated with the tone detectors/tone generators. Clear all off-board problems before replacing the board. Keep in mind that a TDM-BUS problem is usually the result of a faulty board connected to the backplane or bent pins on the backplane.</p> <ol style="list-style-type: none"><li>1. Look for EXP-INTF errors in the error log. If present, refer to the EXP-INTF Maintenance documentation.</li><li>2. Look for TDM-BUS errors in the error log. If present, refer to <a href="#">“TDM-BUS (TDM Bus)” on page 5-1116</a>.</li><li>3. Retest the board when the faults from steps 1 and 2 are cleared.</li></ol>
	PASS	<p>The port is correctly using its allocated time slots. User-reported troubles on this port should be investigated using other port tests and examining station, trunk, or external wiring.</p>
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board). This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"><li>1. Check to ensure that the board translations are correct. Use the <b>list config</b> command, and resolve any problems that are found.</li><li>2. If the board was found to be correctly inserted in step 1, issue the <b>busyout board</b> command.</li><li>3. Issue the <b>reset board</b> command.</li><li>4. Issue the <b>release busy board</b> command.</li><li>5. Issue the <b>test board long</b> command. This should re-establish the linkage between the internal ID and the port. If this is not the case, dispatch to check to ensure that there is a valid board inserted.</li></ol>

## Hybrid Electronic Power Feed Test (#56)

In this test, the software requests that the EPF be turned on for a given port. An attempt is made to turn on the power unit from the station. If no current is being drawn, this probably indicates that the station is not connected. If an overcurrent condition is sensed (that is, too much current is being drawn), this may indicate a short in the loop or a defective voice terminal. Depending on what condition is sensed, a message is returned stating that either the EPF was turned on successfully with no problems or that an overcurrent condition is sensed. This test is repeated once more five seconds later. If either test is not successful, the test aborts (see first ABORT entry in the table below).

Table 5-273. TEST #56 Hybrid Electronic Power Feed Test

Error Code	Test Result	Description/ Recommendation
	ABORT	Internal system error <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
1000	ABORT	System resources required to run this test are not available. The port may be busy with a valid call. Use the <b>display port PCSSpp</b> command to determine the station extension number of the port. Use the <b>status station</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. You must wait until the port is idle before retesting. Attendants are always in use (off-hook) if the handset is plugged in and the port is not busied out. <ol style="list-style-type: none"><li>1. If the port status is idle, then retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
	FAIL	Internal system error <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
	PASS	EPF test passed. The message to turn on the power to the station was successfully sent to the port. <ol style="list-style-type: none"><li>1. Although this test never returns a FAIL result, after running this test, the Error Log should be checked for any entries with Error Type 257 to examine the real results of this test.</li><li>2. If Error Type 257 does not appear in the Error Log within 10 seconds after completion of this test, it is safe to assume that the test sensed no problems with the power to the station. To verify that the station is powered up correctly, run a self-test on the station, if available, and check that all the feature buttons are operating.</li><li>3. If Error Type 257 appears in the Error Log, this indicates some problem with the power to the station. The system technician should check for a short in the wiring, a damaged jack, a defective voice terminal, or an incorrect type of terminal.</li></ol>

*Continued on next page*

Table 5-273. TEST #56 Hybrid Electronic Power Feed Test — *Continued*

Error Code	Test Result	Description/ Recommendation
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board). This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"><li>1. Check to ensure that the board translations are correct. Use the <b>list config</b> command, and resolve any problems that are found.</li><li>2. If the board was found to be correctly inserted in step 1, issue the <b>busyout board</b> command.</li><li>3. Issue the <b>reset board</b> command.</li><li>4. Issue the <b>release busy board</b> command.</li><li>5. Issue the <b>test board long</b> command. This should re-establish the linkage between the internal ID and the port. If this is not the case, dispatch to check to ensure that there is a valid board inserted.</li></ol>

### Hybrid Circuit and Conference Circuit Test (#57)

This test checks the amount of reflection from the Hybrid loop around circuitry and a Conference Test. Please be aware that if no station is connected to the port being tested, the results of the test are not valid. The Tone-Clock circuit pack places a 1004-Hz tone on a time slot that the port circuit is listening on. A GPTD is connected to another time slot that the same port circuit is talking on. The on-board microprocessor places the port in the loop around mode and the GPTD measures the level of the reflected signal.

The Conference Test is performed after the Circuit Test. The Conference Circuit Test verifies that the NPE is able to listen to several test tones and correctly conference them together. The test is executed in two parts. The first half of the test checks the operation of the NPE's first three conference channels. The NPE is put in the loop around mode and instructed to talk on a selected time slot and listen to the 1004-Hz tone using the first three Conference Channels. The signal level and noise level of the conferenced output are then measured using a GPTD and checked to verify that they are within an acceptable range.

The second half of the Conference Test checks the operation of the NPE's remaining four Conference Channels and follows the same procedure as the preceding paragraph.

5 Maintenance Objects for DEFINITY ONE  
HYB-LINE (Hybrid Line)

5-684

Table 5-274. TEST #57 Hybrid Circuit and Conference Circuit Test

Error Code	Test Result	Description/ Recommendation
	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals a maximum of 5 times.
1000	ABORT	System resources required to run this test are not available. The port may be busy with a valid call. Use the <b>display port PCSSpp</b> command to determine the station extension number of the port. Use the <b>status station</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. You must wait until the port is idle before retesting. Attendants are always in use (off-hook) if the handset is plugged in and the port is not busied out. 1. If the port status is idle, then retry the command at 1-minute intervals a maximum of 5 times.
1001	ABORT	Could not allocate the necessary system resources to run this test. This could be due to a failure to seize the port. 1. Retry the command at 1-minute intervals a maximum of 5 times.
1002	ABORT	The system could not allocate time slots for the test. The system may be under heavy traffic conditions or it may have time slots out-of-service due to TDM-BUS errors. Refer to " <a href="#">TDM-BUS (TDM Bus)</a> " on page 5-1116 to diagnose any active TDM-BUS errors. 1. If the system has no TDM-BUS errors and is not handling heavy traffic, repeat test at 1-minute intervals a maximum of 5 times.
1003	ABORT	The system could not allocate a tone receiver for the test. The system may be oversized for the number of Tone Detectors present or some Tone Detectors may be out-of-service. 1. Look for TTR-LEV errors in the Error Log. If present, refer to " <a href="#">TTR-LEV (TTR Level)</a> " on page 5-1223. 2. Look for TONE-PT errors in the Error Log. If present, refer to " <a href="#">TONE-PT (Tone Generator)</a> " on page 5-1204. 3. If neither condition exists, retry the test at 1-minute intervals a maximum of 5 times.
1004	ABORT	The port was seized by a valid call during the test. The test has been aborted. Use the <b>display port PCSSpp</b> command to determine the station extension number of the port. Use the <b>status station</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. You must wait until the port is idle before retesting. Attendants are always in use (off-hook) if the handset is plugged in and the port is not busied out. 1. Retry the command at 1-minute intervals a maximum of 5 times.

*Continued on next page*

Table 5-274. TEST #57 Hybrid Circuit and Conference Circuit Test — *Continued*

Error Code	Test Result	Description/ Recommendation
2000	ABORT	<p>Response to the test request was not received within the allowable time period.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
7	FAIL	<p>Conference Test failed. User may be able to use conference circuit without difficulty in some cases. In other extreme cases, conference calling will be totally restricted.</p> <p>The failure may be due to off-board circumstances, the most common of which is an off-hook occurring during the test. Also, check the error logs against the GPTD-BD, the TONE-BD, and the TONE-PT.</p> <ol style="list-style-type: none"> <li>1. This error can be caused by a disconnected terminal. First, ensure that the terminal is connected and the wiring is OK.</li> <li>2. Then, issue the <b>display port</b> and the <b>status station</b> commands to determine if the station is idle. If it is idle, issue the <b>test port</b> command for this port.</li> <li>3. If test continues to fail, issue the <b>busyout port</b> and the <b>release port</b> commands, and then retest the port.</li> <li>4. It is possible that the port may still be functional from a user's point of view.</li> </ol>
57	FAIL	<p>Hybrid Circuit Test failed. This could result in noisy or bad connections.</p> <ol style="list-style-type: none"> <li>1. This error can be caused by a disconnected terminal. First, ensure that the terminal is connected and the wiring is OK.</li> <li>2. Run circuit pack tests to check the Tone Generator circuit pack and the Tone Detector circuit pack using the <b>test board PCSS short</b> command.</li> <li>3. Resolve any problems that are detected on the Tone Generator circuit pack or Tone Detector circuit pack.</li> <li>4. If the Tone Generator and Tone Detector circuit packs are functioning properly, and the test still fails, replace the Hybrid Line circuit pack.</li> </ol> <p><b>⇒ NOTE:</b> If the Hybrid Circuit and Conference Circuit Test fails for all ports on a circuit pack, a -5 volt power problem is indicated.</p>
	PASS	<p>Hybrid Circuit and Conference Circuit Test passed. The hybrid circuitry is transmitting properly.</p> <ol style="list-style-type: none"> <li>1. If complaints still exist, investigate by using other port tests, and by examining the station, wiring, and connections.</li> </ol>

*Continued on next page*

Table 5-274. TEST #57 Hybrid Circuit and Conference Circuit Test — *Continued*

Error Code	Test Result	Description/ Recommendation
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board). This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"> <li>1. Check to ensure that the board translations are correct. Use the <b>list config</b> command, and resolve any problems that are found.</li> <li>2. If the board was found to be correctly inserted in step 1, issue the <b>busyout board</b> command.</li> <li>3. Issue the <b>reset board</b> command.</li> <li>4. Issue the <b>release busy board</b> command.</li> <li>5. Issue the <b>test board long</b> command. This should re-establish the linkage between the internal ID and the port. If this is not the case, dispatch to check to ensure that there is a valid board inserted.</li> </ol>

### Hybrid Line Local Digital Loop Around Test (#58)

This test checks the control channel between the SPE and the port's digital circuitry. The SPE sends transparent data to the on-board microprocessor and compares the data echoed back. This test is repeated three times.

Table 5-275. TEST #58 Hybrid Line Local Digital Loop Around Test

Error Code	Test Result	Description/ Recommendation
	ABORT	<p>Internal system error</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
1000	ABORT	<p>System resources required to run this test are not available. The port may be busy with a valid call. Use the <b>display port PCSSpp</b> command to determine the station extension number of the port. Use the <b>status station</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. You must wait until the port is idle before retesting. Attendants are always in use (off-hook) if the handset is plugged in and the port is not busied out.</p> <ol style="list-style-type: none"> <li>1. If the port status is idle, then retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>

*Continued on next page*

Table 5-275. TEST #58 Hybrid Line Local Digital Loop Around Test — *Continued*

Error Code	Test Result	Description/ Recommendation
1004	ABORT	<p>The port was seized by a valid call during the test. The test has been aborted. Use the <b>display port PCSSpp</b> command to determine the station extension number of the port. Use the <b>status station</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. You must wait until the port is idle before retesting. Attendants are always in use (off-hook) if the handset is plugged in and the port is not busied out.</p> <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
2000	ABORT	<p>Response to the test request was not received within the allowable time period.</p> <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
1,2,3	FAIL	<p>The control channel between the processor and the port is not transmitting properly. This port is not operable.</p> <ol style="list-style-type: none"><li>1. Retry the test.</li><li>2. If the failure still occurs, issue the <b>busyout</b> and the <b>release busy</b> commands, and then retest.</li><li>3. If the failure is occurring on more than one port on the board, suspect the board.</li><li>4. If the failure is occurring on several boards in the same carrier, escalate the problem.</li><li>5. If the failure still occurs and appears to be isolated to one port, check all wiring to the set and all set connections.</li><li>6. Replace the circuit pack as a last resort.</li></ol>
	PASS	<p>Hybrid Line Local Digital Loop Around Test passed. The control channel is transmitting properly.</p> <ol style="list-style-type: none"><li>1. If complaints still exist, investigate by using other circuit pack tests, and by examining the station, wiring, and connections.</li></ol>

*Continued on next page*

Table 5-275. TEST #58 Hybrid Line Local Digital Loop Around Test — *Continued*

Error Code	Test Result	Description/ Recommendation
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board). This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"><li>1. Check to ensure that the board translations are correct. Use the <b>list config</b> command, and resolve any problems that are found.</li><li>2. If the board was found to be correctly inserted in step 1, issue the <b>busyout board</b> command.</li><li>3. Issue the <b>reset board</b> command.</li><li>4. Issue the <b>release busy board</b> command.</li><li>5. Issue the <b>test board long</b> command. This should re-establish the linkage between the internal ID and the port. If this is not the case, dispatch to check to ensure that there is a valid board inserted.</li></ol>

### Hybrid Line Remote Digital Loop Around Test (#59)

This test checks the digital control pair from the port circuit to the terminal. The on-board microprocessor sends a message to the terminal and checks for a proper return message. This test is repeated three times, with two out of the three attempts passing being sufficient for this test to pass. This test runs if the station is in-service or out-of-service.

Table 5-276. TEST #59 Hybrid Line Remote Digital Loop Around Test

Error Code	Test Result	Description/ Recommendation
	ABORT	Internal system error 1. Retry the command at 1-minute intervals for a maximum of 5 times.
1	ABORT	A request for a remote station audit aborted even though all internal resources were correctly allocated. 1. Look in the error log for error type 18 (port busied out) for this port. If this error type is present, release the port via the <b>release port PCSSpp</b> command or the <b>release station extension</b> command, and then run the test again. 2. Make sure that the terminal is connected. 3. Retry the command at 1-minute intervals for a maximum of 5 times.
1000	ABORT	System resources required to run this test are not available. The port may be busy with a valid call. Use the <b>display port PCSSpp</b> command to determine the station extension number of the port. Use the <b>status station</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. You must wait until the port is idle before retesting. Attendants are always in use (off-hook) if the handset is plugged in and the port is not busied out. 1. If the port status is idle, then retry the command at 1-minute intervals a maximum of 5 times.
2000	ABORT	Response to the test request was not received within the allowable time period. 1. Retry the command at 1-minute intervals a maximum of 5 times.
1,2,3	FAIL	No response was received within the allowable time period on one of the transmissions to the terminal. This indicates that something is wrong with the data link to the voice terminal. This could be a sleeping set problem or it may be due to wiring or an unplugged or defective set. 1. Check for errors in the error log, for example, error 1537. 2. Remotely issue the <b>busyout</b> and <b>release busy</b> commands, and run the short test sequence on the port to check for other errors associated with the port or terminal. 3. Check the wiring to the set if it appears that the terminal is not responding to any tests; otherwise, replace the terminal and rerun the test. 4. If the test still fails, replace the circuit pack and reconnect the original terminal.

Continued on next page

5 Maintenance Objects for DEFINITY ONE  
HYB-LINE (Hybrid Line)

5-690

Table 5-276. TEST #59 Hybrid Line Remote Digital Loop Around Test — *Continued*

Error Code	Test Result	Description/ Recommendation
	PASS	Hybrid Line Remote Digital Loop Around Test passed. The hybrid circuit pack is sending and receiving proper messages to and from the voice terminal. <ol style="list-style-type: none"><li>1. If problems still exist, investigate using other circuit pack tests and by examining the station, wiring, and connections.</li></ol>
0	NO BOARD	The test could not relate the internal ID to the port (no board). This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted. <ol style="list-style-type: none"><li>1. Check to ensure that the board translations are correct. Use the <b>list config</b> command, and resolve any problems that are found.</li><li>2. If the board was found to be correctly inserted in step 1, issue the <b>busyout board</b> command.</li><li>3. Issue the <b>reset board</b> command.</li><li>4. Issue the <b>release busy board</b> command.</li><li>5. Issue the <b>test board long</b> command. This should re-establish the linkage between the internal ID and the port. If this is not the case, dispatch to check to ensure that there is a valid board inserted.</li></ol>

**Hybrid Line Lamp Updates Test (#60)**

For this test, the software lights the lamps on the terminal based on the status record contained in the processor. The lamp updates run only if the station is in-service.

**Table 5-277. TEST #60 Hybrid Line Lamp Updates Test**

Error Code	Test Result	Description/ Recommendation
1	ABORT	<p>A request for a remote station lamp update aborted even though all internal resources were correctly allocated.</p> <ol style="list-style-type: none"> <li>1. Look in the error log for error type 18 (port busied out) for this port. If this error type is present, release the port via the <b>release port PCSSpp</b> command or the <b>release station extension</b> command, and then run the test again.</li> <li>2. Make sure that the terminal is connected.</li> <li>3. Retry the command at 1-minute intervals for a maximum of 5 times.</li> </ol>
2	ABORT	<p>Internal system error</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
3	ABORT	<p>The station is in a ready for service or an out of service state. This may be due to wiring or an unplugged or defective set.</p> <ol style="list-style-type: none"> <li>1. Make sure terminal is connected and the wiring is correct.</li> <li>2. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
1000	ABORT	<p>System resources required to run this test are not available. The port may be busy with a valid call. Use the <b>display port PCSSpp</b> command to determine the station extension number of the port. Use the <b>status station</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. You must wait until the port is idle before retesting. Attendants are always in use (off-hook) if the handset is plugged in and the port is not busied out.</p> <ol style="list-style-type: none"> <li>1. If the port status is idle, then retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
	FAIL	<p>Internal system error</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>

*Continued on next page*

Table 5-277. TEST #60 Hybrid Line Lamp Updates Test — *Continued*

Error Code	Test Result	Description/ Recommendation
	PASS	Hybrid Line Lamp Updates completed successfully. <ol style="list-style-type: none"><li>1. If complaints still exist, investigate by using other circuit pack tests, and by examining the station, wiring, and connections.</li></ol>
0	NO BOARD	The test could not relate the internal ID to the port (no board). This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted. <ol style="list-style-type: none"><li>1. Check to ensure that the board translations are correct. Use the <b>list config</b> command, and resolve any problems that are found.</li><li>2. If the board was found to be correctly inserted in step 1, issue the <b>busyout board</b> command.</li><li>3. Issue the <b>reset board</b> command.</li><li>4. Issue the <b>release busy board</b> command.</li><li>5. Issue the <b>test board long</b> command. This should re-establish the linkage between the internal ID and the port. If this is not the case, dispatch to check to ensure that there is a valid board inserted.</li></ol>

**Hybrid Line Audits Test (#61)**

This is a series of three tests that are classified as audits. These audits abort if attempted on an out-of-service station. The tests are as follows:

- Switchhook Audit - This is an update of the SPE records according to the circuit packs' records.
- Bad Scan Inquiry - A message is sent uplink that contains a count that is generated due to certain events relating to the data link conditions. This is an indication of data transmission problems between the Hybrid circuit pack and the voice terminal.
- EPF Inquiry - The status of the Electronic Power Feed is sent uplink. Possible conditions are: EPF-on-ok, EPF-off, EPF-no-load, and EPF-on-overcurrent.

Table 5-278. TEST #61 Hybrid Line Audits Test

Error Code	Test Result	Description/ Recommendation
1	ABORT	Internal System Error
	ABORT	The test was aborted due to an internal system error during the switchhook audit.
2	ABORT	Internal System Error occurred during bad scan inquiry audit.
		<ol style="list-style-type: none"> <li>1. Make sure that the station is not in an out of service state.</li> <li>2. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
3	ABORT	This port may have been busied out by system technician.
		<ol style="list-style-type: none"> <li>1. Look in the Error Log for Error Type 18 (port busied out) for this port. If this error type is present, the release the port via the <b>release station &lt;extension&gt;</b> command and run the test again.</li> <li>2. Make sure that the terminal is connected.</li> <li>3. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
1000	ABORT	System resources required to run this test are not available. The port may be busy with a valid call. Use the <b>display port PCSSpp</b> to determine the station extension number of the port. Use the <b>status station</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. You must wait until the port is idle before retesting. Attendants are always in use (off-hook), if the handset is plugged in and the port is not busied out.
		<ol style="list-style-type: none"> <li>1. If the port status is idle, then retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>

*Continued on next page*

Table 5-278. TEST #61 Hybrid Line Audits Test — Continued

Error Code	Test Result	Description/ Recommendation
1004	ABORT	<p>The port was seized by a valid call during the test. The test has been aborted. Use the <b>display port PCSSpp</b> command to determine the station extension number of the port. Use the <b>status station</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. You must wait until the port is idle before retesting. Attendants are always in use (off-hook), if the handset is plugged in and the port is not busied out.</p> <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
2000	ABORT	<p>Response to the test request was not received within the allowable time period.</p>
	FAIL	<p>Internal system error</p> <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
	PASS	<p>Hybrid Line Audits Test passed.</p> <ol style="list-style-type: none"><li>1. Although this test always return a PASS result, it may enter Error Types 257 or 513 into the Error Log. To determine if there are any problems that don't show up in the test result, look for these error types in the Error Log.</li><li>2. If these errors appear in the Error Log, or if user complaints still exist, investigate by using other circuit pack tests, and by examining the station, wiring, and connections.</li></ol>
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board). This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"><li>1. Check to ensure that the board translations are correct. Use the <b>list config</b> command, and resolve any problems that are found.</li><li>2. If the board was found to be correctly inserted in step 1, issue the <b>busyout board</b> command.</li><li>3. Issue the <b>reset board</b> command.</li><li>4. Issue the <b>release busy board</b> command.</li><li>5. Issue the <b>test board long</b> command. This should re-establish the linkage between the internal ID and the port. If this is not the case, dispatch to check to ensure that there is a valid board inserted.</li></ol>

## Hybrid Line Ringer Update Test (#62)

In this update, a “ringer on” or a “ringer off” message is sent to the firmware to start and stop the ringer on the set.

Table 5-279. TEST #62 Hybrid Line Ringer Update Test

Error Code	Test Result	Description/ Recommendation
3	ABORT	<p>This port may have been busied out by system technician.</p> <ol style="list-style-type: none"> <li>1. Look in the Error Log for Error Type 18 (port busied out) for this port. If this Error Type is present, the release the port via the <b>release station &lt;extension&gt;</b> command and run the test again.</li> <li>2. Make sure that the terminal is connected.</li> <li>3. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
1000	ABORT	<p>System resources required to run this test are not available. The port may be busy with a valid call. Use the <b>display port PCSSpp</b> command to determine the station extension number of the port. Use the <b>status station</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. You must wait until the port is idle before retesting. Attendants are always in use (off-hook), if the handset is plugged in and the port is not busied out.</p> <ol style="list-style-type: none"> <li>1. If the port status is idle, then retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
	FAIL	<p>Internal system error</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
	PASS	<p>Hybrid Station Ringer Update passed</p> <ol style="list-style-type: none"> <li>1. If complaints still exist, investigate using other circuit pack tests on this circuit pack, and by examining the terminal, wiring, and connections.</li> </ol>
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board). This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"> <li>1. Check to ensure that the board translations are correct. Use the <b>list config</b> command, and resolve any problems that are found.</li> <li>2. If the board was found to be correctly inserted in step 1, issue the <b>busyout board</b> command.</li> <li>3. Issue the <b>reset board</b> command.</li> <li>4. Issue the <b>release busy board</b> command.</li> <li>5. Issue the <b>test board long</b> command. This should re-establish the linkage between the internal ID and the port. If this is not the case, dispatch to check to ensure that there is a valid board inserted.</li> </ol>

## INADS (INADS Link)

---

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run	Full Name of MO
INADS	none	test inads-link	INADS Link

The INADS Link MO represents the software and communications link required by the switch to make a call to the Initialization and Administration System (INADS). The purpose of the INADS Link MO is to check the communications link between the DEFINITY Generic 1 and INADS and verify that the alarm notification process works correctly. An INADS technician can test the process remotely to verify that alarms are reported to INADS, or a system technician may want to test the connection while on-site at installation time or during subsequent service calls.

Although the INADS Link MO is never alarmed, the errors are logged. The errors are only logged as a result of the **test inads-link** command being issued.

### Error Log Entries and Test to Clear Values

---

The Hardware Error Log entries are described as part of the INADS Link Test description.

### Short and Long Test Sequences

---

The **test inads-link** command is different from other test commands. This command does not have a long or short option, and the test on the INADS Link does not have an associated test number. When the **test inads-link** command is issued, the user immediately sees either the `Command successfully completed` or `Command failed` message.

### INADS Link Test (no test number)

The INADS Link Test attempts to place a call to INADS (in the background) to verify the communications link to INADS. When the **test inads-link** command is issued, the user immediately sees either the `Command successfully completed` or `Command failed` message. When a previously run command is entered, the user immediately sees either `Command successfully completed` or `Command failed`. The `Command failed` message appears when a previously run **test inads-link** command is in progress or the system has active alarms which must be reported to INADS. The `Command successfully completed` means the switch will start the attempt to call INADS in two minutes (the test still runs even if Alarm Origination is disabled). The two-minute delay allows a remote INADS technician time enough to hang up the call and thus free up the INADS line so that the switch can call INADS back. As error conditions are

encountered, errors are logged against INADS. Error codes 1 through 9 can be logged if the test result was `Command successfully completed` and Error Codes 10 and 11 can be logged if the test result was `Command failed`. An error is also logged against INADS if the call to INADS finally succeeds. The INADS software (release 3.2 or later) recognizes this special "test inads" type of alarm and automatically opens and then closes a trouble ticket which indicates that the reason for the trouble ticket is a command is in progress or the system has active alarms which must be reported to INADS. The `Command successfully completed` means the switch will start the attempt to call INADS in two minutes (the test still runs even if Alarm Origination is disabled). The two-minute delay allows a remote INADS technician time enough to hang up the call and thus free up the INADS line so that the switch can call INADS back. As error conditions are encountered, errors are logged against INADS. Error codes 1 through 9 can be logged if the test result was `Command successfully completed` and Error Codes 10 and 11 can be logged if the test result was `Command failed`. An error is also logged against INADS if the call to INADS finally succeeds. The INADS software (release 3.2 or later) recognizes this special "test inads" type of alarm and automatically opens and then closes a trouble ticket which indicates that the reason for the trouble ticket is a **test inads-link** command. The trouble ticket alarm contains a `TESTING INADS LINK` description field.

After entering the command, it may take as long a nine minutes for the switch to place the call and for INADS to respond. The Error Log should be examined (use the category **inads**) 10 minutes after successfully entering the command to determine if the call was successful.

Use [Table 5-280](#) to interpret the Error Log entries.

Table 5-280. INADS Link Error Log Entries Test

Error Code	Test Result	Description/ Recommendation
1	0	The call was successfully placed to INADS. No trouble found.
2	0	Informative error indicating that alarm origination was disabled at the time of the test. The test runs even if alarm origination is disabled. <ol style="list-style-type: none"><li>1. If Alarm Origination is desired, then enable this feature with the Maintenance-Related System Parameters Form.</li><li>2. Repeat the test.</li></ol>
3	0	The INADS connection is currently in use. <ol style="list-style-type: none"><li>1. Wait 10 minutes and retry this command.</li></ol>

*Continued on next page*

Table 5-280. INADS Link Error Log Entries Test — *Continued*

Error Code	Test Result	Description/ Recommendation
4	0	<p>INADS did not answer the alarm origination call.</p> <ol style="list-style-type: none"> <li>1. Verify INADS is up and running.</li> <li>2. Verify the INADS phone number and switch product ID are correct via the Maintenance-Related System Parameters Form.</li> <li>3. Enable alarm origination via the Maintenance-Related System Parameters Form and test the PR-MAINT (Maintenance/Tape Processor) by issuing the <b>test processor a b</b> command. If PR-MAINT Tests #102 and #103 do not pass, then refer to "<a href="#">PR-MAINT (Maintenance Processor)</a>" on page 5-1000.</li> <li>4. Retry the command.</li> </ol>
5	0	<p>No INADS phone number administered.</p> <ol style="list-style-type: none"> <li>1. Administer the INADS phone number via the Maintenance-Related System Parameters Form.</li> <li>2. Retry the command.</li> </ol>
6	0	<p>INADS did not send the acknowledgment message to the "test inads alarm" message.</p> <ol style="list-style-type: none"> <li>1. Verify the INADS phone number and switch product id are correct via the Maintenance-Related System Parameters Form.</li> <li>2. Verify INADS is up and running.</li> <li>3. Retry the command.</li> </ol>
7	0	<p>INADS sent a negative acknowledgment to the "test inads alarm" message.</p>
8	0	<p>Internal system error; system received an invalid return code.</p>
9	0	<p>Internal system error</p> <ol style="list-style-type: none"> <li>1. Try the command again at 1-minute intervals up to 5 times.</li> </ol>
10	0	<p>There is already a <b>test inads-link</b> command in progress.</p> <ol style="list-style-type: none"> <li>1. Wait 10 minutes for the present command to finish.</li> <li>2. Review the results of the present command by viewing the Error Log and selecting the category "inads-link."</li> </ol>
11	0	<p>The switch is trying to report alarms to INADS. The test cannot be run at this time.</p> <ol style="list-style-type: none"> <li>1. Wait 10 minutes and retry the command.</li> </ol>

## ISDN-PLK (ISDN-PRI Signaling Link Port)

---


MO Name (in Alarm Log)	Alarm Level	Initial Command to Run <sup>1</sup>	Full Name of MO
ISDN-PLK <sup>2</sup>	MINOR	test port PCSSpp l	ISDN-PRI Signaling Link Port
ISDN-PLK	WARNING	test port PCSSpp sh	ISDN-PRI Signaling Link Port

1. Where 'pp' is '24' for 24-channel interfaces, and '16' for 32-channel interfaces.
  2. For additional repair information, see also PKT-CTRL (Packet Control), [“DS1-BD \(DS1 Interface Circuit Pack\)” on page 5-548](#) or [“UDS1-BD \(UDS1 Interface Circuit Pack\)” on page 5-1227](#).
- 

The ISDN-PRI Signaling Link Port is the port on a TN464C or later UDS1 Interface circuit pack that carries D-channel messages to the processor. The ISDN-PRI interface uses out-of-band signaling as opposed to robbed-bit, in-band signaling. This port can be used as an interface to the TDM bus or to the Packet bus.

The B-channels associated with a ISDN-PRI D-channel can use ports on the same circuit pack or ports on other TN464C or later or TN767 DS1 Interface circuit packs (The TN722 cannot be used for this application.)

In a 32-channel system (see [Figure 5-23 on page 5-700](#)), the DS1 ISDN Trunk or PRI endpoint port (B-channels) may use any of the ports 1-15 or 17-31, but the ISDN-PRI Signaling Link Port must be the 16th port on the TN464C (or higher) circuit pack. In certain configurations (NFAS), the 16th port may be used as a B-channel. Refer to [“ISDN-SGR \(ISDN-PRI Signaling Group\)” on page 5-705](#) for further details.



cydfisd2 RPY 061297


**Figure Notes**

1. B- and D-channel messages are routed over the TDM Bus. For additional reliability, a duplex D-channel can be administered for a signaling group and located on a different TN464C (or higher) circuit pack.
2. TN464C or higher

**Figure 5-23. ISDN-PRI Signaling Link Port Interactions (32-Channel - TN464)**

The TN767 DS1 interface is used for 24 channel 1.544 Mbps systems. The TN464C or later can be used for either 24 or 32 channel systems. The 32-channel (31 DS0 channels + 1 framing channel on a 2.048 Mbps link) are only supported on TN464 series circuit packs. A description of these circuit packs appears in DS1-BD or UDS1-BD maintenance documentation.

In a 24-channel system, the DS1 ISDN Trunk or PRI endpoint port (B-channels) may use any of the first 23 ports. The ISDN-PRI Signaling Link Port must be the 24th port (See [Figure 5-24 on page 5-701](#)). In certain configurations (NFAS), the 24th port may be used as a B-channel. Refer to ["ISDN-SGR \(ISDN-PRI Signaling Group\)" on page 5-705](#) for further details.



**Figure Notes**

1. B- and D-channel messages are routed over the TDM Bus. For additional reliability, a duplex D-channel can be administered for a signaling group and located on a different TN464C (or higher) circuit pack.
2. TN767B (or higher) or TN464C (or higher)

**Figure 5-24. ISDN-PRI Signaling Link Port Interactions (24 Channel - TN767/464C)**

ISDN-PLK handles maintenance and recovery for the D-channel port on the DS1 carrying the signaling link. A problem with the ISDN-PRI Signaling Link Port (D-channel) has an effect on all of the associated DS1 ISDN Trunks or PRI endpoint ports (B-channels) since no call control information can be conveyed to the far-end switch or Terminal Adapter without it. Stable calls may remain operational, but no new calls can be made.

If there are problems with the ISDN-PLK, also investigate the TN464 UDS1 interface circuit pack (UDS1-BD).

## Error Log Entries and Test to Clear Values

Table 5-281. ISDN-PRI Signaling Link Port Error Log Entries

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
0 <sup>1</sup>	0	Any	Any	Any	test port PCSSpp <sup>2</sup>
18(a)	0	busyout port PCSSpp*	WARNING	OFF	release port PCSSpp <sup>2</sup>
130 (b)		None	WARNING	ON	test port PCSSpp <sup>2</sup>
1537 (c)	46210		WARNING	OFF	
1793 (d)					test board PCSSpp <sup>2</sup> 1
3585 (e)	46222		MINOR	ON	
3841 (f)	46211				
3842 (g)	46223				

1. Run the short test sequence first. If all tests pass, run the long test sequence. Refer to the appropriate test description and follow the recommended procedures.
2. pp is 24-channel interfaces and 16 for 32-channel interfaces.

### Notes:

- a. The D-channel is demand busied out. No calls can be made over this D-channel.
- b. This error type indicates that the circuit pack has been removed or has been insane for more than 11 minutes. To clear the error, reinsert or replace the circuit pack.
- c. Link error. This error occurs when the port receives an invalid frame over the D-channel. This error normally indicates an off-board problem usually related to transmission errors on the DS1 facility. Execute the **list measurements ds1-log** command for the UDS1 TN464 circuit pack on which the D-channel resides. If the UDS1 is reporting some errors, then the DS1 facility has experienced transmission problems which could have caused the ISDN-PLK to report a Link Error. If the UDS1 is not reporting errors, execute the long test sequence for the D-channel (ISDN-SGR). Investigate any errors, if there are none execute a long test sequence for the UDS1 circuit pack (UDS1-BD) and investigate any errors.

If no errors are reported, the Link Error is probably not affecting service.

- d. The UDS1 Interface circuit pack is out-of-service. Look for and resolve UDS1-BD errors in the Hardware Error Log.

5 Maintenance Objects for DEFINITY ONE  
ISDN-PLK (ISDN-PRI Signaling Link Port)

5-703

- e. Transmit FIFO Overflow error. This error indicates that the circuit pack is having problems transmitting signaling information over the D-channel. This condition probably indicates a hardware problem.

The actual alarming level depends on the options chosen via the **set options** command on the G3-MT terminal. ISDN-PRI Signaling Link Port alarms are treated as Station alarms, and their default alarming option is to downgrade all alarms to Warning. The value shown in the preceding table indicates the normal, unfiltered case (option "y" on the *Set Options* form).

- f. Bad DLCI error. This error occurs when a LAPD frame is received across the DS1 facility which contains a DLCI which does not have a valid entry in the on-board translation memory. This error normally indicates an off-board problem usually related to a broken endpoint or a state mismatch between a remote endpoint and the local call processing software. Maintenance will not start any testing or generate any alarms in response to this error.
- g. Receive FIFO Overflow error. This error occurs when the circuit pack detects an overflow of its receive buffers. If it occurs frequently, it may indicate a LAPD parameter mismatch between the two endpoints. Maintenance does not start any testing or generate any alarms in response to this error.

### System Technician-Demanded Tests: Descriptions and Error Codes

Always investigate tests in the order presented in the table below when inspecting errors in the system.



**NOTE:**

The command line entry to test the ISDN-PLK MO is: **test port PCSSpp (sh or l)**, where 'pp' is '24' for 24-channel interfaces, and '16' for 32-channel interfaces.

Order of Investigation	Short Test Sequence	Long Test Sequence	D/ND <sup>1</sup>
Signaling Link Board Check (#643)	X	X	ND

1. D = Destructive; ND = Nondestructive

## Signaling Link Board Check (#643)

---

This test checks the state of the UDS1 Interface circuit pack (TN464C or later) transporting the ISDN-PRI Signaling Link.

Table 5-282. TEST #643 Signaling Link Board Check

Error Code	Test Result	Description/ Recommendation
	ABORT	Internal system error <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
1700	ABORT	Rollabout video abort. The PRI terminal adapter associated with this D-channel port is detached from the circuit pack. This is a normal abort when the rollabout video feature is enabled. To complete test on this port, either: <ol style="list-style-type: none"><li>1. Re-attach the disconnected PRI terminal adapter and retry test command, or</li><li>2. Disable the rollabout video feature on this circuit pack by entering <b>change ds1 PCCSS</b> and set the field <i>Alarm when PRI Endpoint Detached?</i> to <b>y</b>.</li></ol>
8	FAIL	The UDS1 circuit pack (TN464C or later) is not in-service. <ol style="list-style-type: none"><li>1. Check the Hardware Error Log for entries logged against UDS1-BD and consult the UDS1-BD (UDS1 Interface Circuit Pack) Maintenance documentation for repair procedures.</li></ol>
	PASS	The UDS1 Interface circuit pack transporting the ISDN-PRI Signaling Link Port is in-service.

## ISDN-SGR (ISDN-PRI Signaling Group)

---

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run <sup>1</sup>	Full Name of MO
ISDN-SGR	MINOR	test sig-group <group>	ISDN-PRI Signaling Group
ISDN-SGR	WARNING	test sig-group <group>	ISDN-PRI Signaling Group

---

1. Where <group> is a number 1-8 and the test sequence can be either s (short) or l (long).

---


An ISDN-PRI Signaling Group is a collection of DS1/UDS1 ISDN Trunks or PRI endpoint ports (B-channels) for which a given ISDN-PRI Signaling Link Port (D-channel) carries signaling information. ISDN-PRI requires the use of one of the following DS1 interface circuit packs:

TN767B or later    24-channel with ISDN-PRI D-channel over PI-BD

TN464C or later    24- or 32-channel with ISDN-PRI D-channel over PI-BD

See [“DS1-BD \(DS1 Interface Circuit Pack\)” on page 5-548](#) and [“UDS1-BD \(UDS1 Interface Circuit Pack\)” on page 5-1227](#) for a description of these circuit packs. See *DS1/CEPT1/ISDN-PRI Reference*, (555-025-101), for more information on ISDN.

For 24-channel interfaces, the first 23 ports on the circuit pack are used as B-channels. The 24th port may be used as a B-channel or as a D-channel depending on the type of Signaling Group used (see [Figure 5-25](#)).




**Figure Notes**

1. B- and D-channel messages are routed over the TDM Bus. For additional reliability, a duplex D-channel can be administered for a signaling group and located on a different TN464C (or higher) circuit pack.
2. TN767B (or higher) or TN464C (or higher)

**Figure 5-25. ISDN-PRI Signaling Link Port Interactions (24 Channel - TN767/464C)**

For 32-channel interfaces, ports 1-15 and 17-31 on the circuit pack are used as B-channels. The 16th port may be used as a B-channel or as a D-channel depending on the type of Signaling Group used (see [Figure 5-26](#)).



**Figure Notes**

1. B- and D-channel messages are routed over the TDM Bus. For additional reliability, a duplex D-channel can be administered for a signaling group and located on a different TN464C (or higher) circuit pack.
2. TN464C or higher

**Figure 5-26. ISDN-PRI Signaling Link Port Interactions (32-Channel - TN464)**

There are two types of Signaling Groups:

- Facility Associated Signaling (FAS) (supported by all country protocols)
- Non-Facility Associated Signaling (NFAS) (supported by country protocol 1 only)

In an FAS Signaling Group, the 24th port of the DS1 Interface circuit pack (for 24 channel interfaces) or the 16th port of the DS1 Interface circuit pack (for 32 channel interfaces) is always the D-channel that carries signaling information for the other ports (B-channels) on the circuit pack. If a Packet Control circuit pack is used then only the TN464C or later circuit pack may be used.

**5** Maintenance Objects for DEFINITY ONE  
*ISDN-SGR (ISDN-PRI Signaling Group)*

5-708

In an NFAS Signaling Group, the 24th port of a DS1 Interface circuit pack (for 24 channel interfaces) or the 16th port of a DS1 Interface circuit pack (for 32 channel interfaces) is administered as a D-channel. The D-channel carries signaling information for the other ports (B-channels) on that circuit pack. That D-channel can also carry signaling information for any of the ports on other DS1 Interface circuit packs in the NFAS Signaling Group. As a result, the 24th port on other 24-channel DS1 Interface circuit packs and the 16th port on other 32-channel DS1 Interface circuit packs can be used as B-channels. A D-channel in an NFAS Group can signal for B-channels on a total of 20 DS1 Interface circuit packs. This configuration is known as NFAS Simplex.

In addition to NFAS Simplex, there is another type of NFAS Group called NFAS Duplex. This provides the user with more reliability, which is desirable because NFAS permits the D-channel to signal for so many B-channels. NFAS Duplex allows the administration of a backup D-channel, which remains in a Standby state until the Active D-channel goes down. If the Active D-channel does go down, the backup D-channel takes over and provides signaling for all the B-channels in the signaling group.

The ISDN-PRI Signaling Group itself depends on three other entities: the DS1 Interface circuit pack on which the D-channel(s) resides, the ISDN-PRI Signaling Link Port(s), and the Processor Interface Link that provides connectivity to the processor. If there are any problems with the ISDN-PRI Signaling Group, also investigate the ISDN-PRI Signaling Link Port(s), the DS1 Interface circuit pack(s).

**Error Log Entries and Test to Clear Values**

Table 5-283. ISDN-PRI Signaling Group Error Log Entries

Error Codes	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
0 <sup>1</sup>	0	Any	Any		test sig-group <group>
1 (a)	Any	none			
257 (b)	Any	none			test sig-group <group>
513 (c)	Any	none			test sig-group <group>
769	Any	Primary Signaling Link Hardware Check (#636)			test sig-group <group>
1025	Any	Secondary Signaling Link Hardware Check (#639)			test sig-group <group>
1793 (d)	Any	Layer 2 Status (Test #647)	WARNING	OFF	test sig-group <group>
2049 (e)	Any	Layer 2 Status (Test #647)	WARNING	OFF	test sig-group <group>
2305 (f)	Any	Remote Layer 3 Query (Test #637)	MINOR	OFF	test sig-group <group>
3585 (g)	port number	none			none
3840- 3928 (h)	port number				none

1. Run the Short or Long Test Sequence. Refer to the appropriate test description and follow the recommended procedures.

**Notes:**

- a. This switch sent a message to the far-end switch or terminal adapter, and the far-end did not respond in the allotted time. Possible causes include link failure and congestion or outage at the far-end. The Aux Data field contains Layer 3 protocol information used by internal counters.

If no other symptoms are not present, no action is required. If Layer 3 communication is down, there should be indications in the form of alarms and errors for link components. Check out other errors against ISDN-SGR, ISDN-TRK, and other hardware components on the link.

There is no test to clear these errors. The error counter is decremented by 1 every 15 minutes.

5 Maintenance Objects for DEFINITY ONE  
ISDN-SGR (ISDN-PRI Signaling Group)

5-710

- b. This error indicates that the primary signaling channel connection has been lost for more than 90 seconds. If a secondary signaling channel does not exist or is not in-service, the associated B-channels will be placed in the ISDN Maintenance/Far-End state. The B-channels will not be usable for outgoing calls, although incoming calls will still be accepted. The switch will automatically attempt to recover the signaling link. Pay particular attention to the results of Test #636 (Primary Signaling Link Hardware Check) in the test sequence. When the link does recover, the B-channels will be negotiated back to the In-Service state and their alarms will be retired.

When this error occurs, the state of the Signaling Group is changed to out-of-service (verify using the **status sig-group** command).

- c. This error indicates that the secondary signaling channel connection has been lost for more than 90 seconds. If the primary signaling channel is not in-service, B-channels will be placed in the ISDN Maintenance/Far-End state. The B-channels will not be usable for outgoing calls, although incoming calls will still be accepted. The switch will automatically attempt to recover the signaling link. Pay particular attention to the results of Test #639 (Secondary Signaling Link Hardware Check) in the test sequence. When the link does recover, the B-channels will be negotiated back to the In-Service state and their alarms will be retired.

When this error occurs, the state of the Signaling Group is changed to out-of-service (verify using the **status sig-group** command).

- d. This error indicates a failure of the Layer 2 Status Query Test for the primary signaling channel
- e. This error indicates a failure of the Layer 2 Status Query Test for the secondary signaling channel.
- f. A specific message was sent to the far-end switch, and it did not respond within the allotted time. Investigate elements of the ISDN PRI D-channel(s) (ISDN-LNK, ISDN-PLK, ISDN-SGRP, PKT-INT, PKT-CTRL) for both this switch and the Far-end switch. If Test #637 fails twice in a row, the B-channels will be alarmed and made unavailable for outgoing calls (although incoming calls will still be accepted). When Test #637 succeeds and the Far-end switch starts responding properly, the DS1 ISDN Trunk (B-channels) will be placed back into normal operation and their alarms will be retired.
- g. A SERV or SERV ACK ISDN D-channel message has been received by a non-US-type interface (country option other than 1 on the DS1 administration form). However, these messages are used only for duplex NFAS signaling which is supported only by country protocol 1.

Thus, there may be a mismatch in administration between the local and far-end switches. Consult with the customer's network provider to determine whether the D-channel is set up correctly on the far-end switch.

- h. These error codes are used to report certain error messages received by the ISDN-PRI Signaling Group for one of its associated B-channels. The aux data field shows for which B-channel (port number) the message was received.

The error code generated equals 3840+x, where x is a Cause Value defined by the ISDN PRI Specification. Note that there is no Test to Clear Value for these error types; selected ISDN cause values are placed in the log when they are received, but no direct action or alarming is performed solely in response to receiving them. They provide added data that may prove useful when tracking down obscure networking and routing problems. [Table 5-284](#) provides more information:

Table 5-284. Descriptions of Error Codes 3840-3928

Error Code	Description	Recommendation
3842	A request has been made to use a transit network or common carrier that cannot be accessed.	<ol style="list-style-type: none"> <li>1. From the circuit pack and port number (in the Aux Data field), determine the trunk group against which the error was reported.</li> <li>2. Check all routing patterns containing this trunk group for validity of interexchange carriers requested (IXC field).</li> </ol>
3846	The far-end switch has indicated that the B-channel (trunk) is not acceptable for use in the call for which it was requested.	<p>This could indicate an administration problem (for example, the local switch and the far-end switch have different B-channels administered), or could reflect the occurrence of a normal race condition (for example, the local switch has requested use of a B-channel which the far-end switch had just reserved for use on another call).</p> <ol style="list-style-type: none"> <li>1. From the circuit pack and port number (in the Aux Data field), determine the trunk group against which the error was reported.</li> <li>2. Issue the <b>status trunk</b> command for the indicated trunk.</li> <li>3. Refer to <a href="#">"DS1 ISDN Trunk Service States" on page 5-725</a> and <a href="#">"ISDN-PRI Trunk Service States" on page 5-728</a> for recovery suggestions.</li> </ol>
3858	The switch sent an ISDN message to the far-end switch or terminal adapter which did not respond in the allotted time.	Possible causes include link failure and congestion or outage at the far-end.

Continued on next page

Table 5-284. Descriptions of Error Codes 3840-3928 — *Continued*

Error Code	Description	Recommendation
3878	The far-end switch has indicated that the network is not functioning correctly and that the condition may last a relatively long period of time (for example, immediately re-attempting the call may not be successful).	<ol style="list-style-type: none"> <li>1. From the circuit pack and port number (in the Aux Data field, determine the trunk group against which the error was reported.</li> <li>2. Consult with the network provider to determine the nature and expected duration of the out of service condition.</li> <li>3. Consider modifying all routing patterns containing this trunk group, to route calls around the network which is out of service.</li> </ol>
3890	A request to use a network service (e.g., SDN) has been denied. Administration somewhere on the network has indicated that the requested service has not been subscribed to or purchased for this trunk.	<p>This could be a local administration problem only, or a mismatch between the local administration and that of the network provider.</p> <ol style="list-style-type: none"> <li>1. From the circuit pack and port number (in the Aux Data field), determine the trunk group against which the error was reported.</li> <li>2. Display the trunk group form: If the trunk group is Call-by-Call (Service Type is "cbc"), check all routing pattern forms containing this trunk group to see if the Service/Feature fields contain the correct network services purchased for this trunk. If the trunk group is not Call-by-Call, check that the Service Type field contains the single network service purchased for this trunk.</li> <li>3. If local administration appears correct, consult with the customer and/or the network provider to determine the services that the customer has subscribed to for this trunk group.</li> </ol>
3892	Protocol detail; may offer a clue if customer is having ISDN calls denied with an unexpected intercept tone.	If customer is complaining of unexpected intercept tones when accessing ISDN trunks or PRI endpoints and no other cause can be found, provide the next tier with this Error Log information.
3894	Protocol detail; may offer a clue if customer is having ISDN calls denied with an unexpected intercept tone.	First, eliminate any transitory state mismatch problems by issuing the <b>test port PCSSpp</b> command for the trunk port shown in the aux data field. Test #256 (Service State Audit) is the important test in the sequence. If this passes satisfactorily, yet the customer continues to complain of unexpected intercept tones when accessing ISDN trunks or PRI endpoints and no other cause can be found, provide the next tier with this Error Log information.

*Continued on next page*

Table 5-284. Descriptions of Error Codes 3840-3928 — *Continued*

Error Code	Description	Recommendation
3905	Protocol detail; may offer a clue if customer is having ISDN calls denied with an unexpected intercept tone.	If customer is complaining of unexpected intercept tones when accessing ISDN trunks or PRI endpoints and no other cause can be found, provide the next tier with this Error Log information.
3906	Protocol detail; may offer a clue if customer is having ISDN calls denied with an unexpected intercept tone.	If customer is complaining of unexpected intercept tones when accessing ISDN trunks or PRI endpoints and no other cause can be found, provide the next tier with this Error Log information.
3909	A request to use a network service has been made, but the network has rejected the request because the requested service is not implemented.	Follow the recommendations listed above for error type 3890.
3928	A call was denied because of a basic incompatibility between the type of call and either the facilities selected by the routing pattern or the called user itself.	This error might be helpful as a clue if the customer complains of receiving unexpected intercept tone after accessing ISDN trunks or PRI endpoints. Determine the trunk group from the circuit pack and port number (in the aux data field) and then check the BCC fields of the pertinent routing patterns. Also, investigate whether or not the calling and called endpoints are compatible (for example, some ISDN switches may not allow a voice station to call a data extension).

## System Technician-Demanded Tests: Descriptions and Error Codes

---

Always investigate tests in the order presented in the table below. By clearing error codes associated with the *Primary Signaling Link Hardware Check*, for example, you may also clear errors generated from other tests in the testing sequence.

Table 5-285. System Technician-Demanded Tests: ISDN-SGR

---

Order of Investigation	Short Test Sequence	Long Test Sequence	D/ND <sup>1</sup>
Primary Signaling Link Hardware Check (#636)	X	X	ND
Secondary Signaling Link Hardware Check (#639)	X	X	ND
Layer 2 Query Test (#647)	X	X	ND
Remote Layer 3 Query Test (#637)	X	X	ND

---

---

1. D = Destructive, ND = Non-destructive

---

## Primary Signaling Link Hardware Check (#636)

The ISDN-PRI Signaling Link Port itself depends on the health of the DS1/UDS1 Interface circuit pack on which it resides. This test will fail if there are problems with either the ISDN-PRI Primary D-channel port or the DS1/UDS1 circuit pack. See [Figure 5-25](#) for DS1 connections, [Figure 5-26](#) for UDS1 connections.

If there are problems with the ISDN-PRI Signaling Link, also investigate the DS1/UDS1 circuit pack (DS1-BD/UDS1-BD).

Table 5-286. TEST #636 Primary Signaling Link Hardware Check

Error Code	Test Result	Description/ Recommendation
	ABORT	Internal system error <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
1700	ABORT	Rollabout video abort. The PRI terminal adapter associated with this D-channel port is detached from the circuit pack. This is a normal abort when the rollabout video feature is enabled. To complete test on this port, either: <ol style="list-style-type: none"><li>1. Re-attach the disconnected PRI terminal adapter and retry test command, or</li><li>2. Disable the rollabout video feature on this circuit pack by entering <b>change ds1 PCSS</b> and set the field Alarm when PRI Endpoint Detached? to <b>y</b>.</li></ol>
8	FAIL	There is a problem with the DS1/UDS1 Circuit Pack, or the ISDN-PRI Signaling Channel (D-channel). No DS1 ISDN Trunk (B-channel) or wideband PRI Endpoint calls can be made until the problem is resolved. <ol style="list-style-type: none"><li>1. Consult the procedures for DS1/UDS1 Circuit Pack and the ISDN-PRI Signaling Channel (ISDN-LNK/ISDN-PLK).</li></ol>
	PASS	The basic physical connectivity of the primary D-channel is intact and functional. Try this test repeatedly to ensure the link is up and to uncover any transitory problems.

## Remote Layer 3 Query (#637)

---

This test will query the far-end switch or terminal adapter to determine if the signaling connection is functioning properly at Layer 3. It will select a B-channel in the in-service or maintenance service state and send an ISDN Layer 3 SERVICE message, which requires a response from the far end (similar to performing Test #256 on an ISDN trunk. The test will not be performed if there are no B-channels in an appropriate ISDN service state (as when none are administered or they are all out of service).

### NOTE:

The service state can be displayed by using the **status trunk <trunk group/trunk member>** or **status pri-endpoint** command.

As is the case with Test #256 for an ISDN trunk, a PASS only indicates that a message was composed and sent to the far-end switch or terminal adapter. The ISDN PRI Specification allows up to 2 minutes for a response. Check the Error Log for ISDN-SGR (ISDN-PRI Signaling Group) errors of type 2305 for evidence of a Remote Layer 3 Query failure.

Tests #639 and #636 check the health of the D-channels and DS1/UDS1 Interface Circuit Packs. As shown in the figures below, Test #637 goes one step further by checking the communication path from the processor over the TDM Bus, through the DS1/UDS1 Interface circuit pack, and on to the far-end switch or terminal adapter. A special ISDN message is sent to the far-end switch or terminal adapter, which must respond within a specified amount of time. This test is designed to ensure that the communication path between the switch and the far-end is up and operational, and that the two endpoints can properly exchange ISDN control messages.

See [Figure 5-25](#) for DS1 connections, [Figure 5-26](#) for UDS1 connections.

Table 5-287. TEST #637 Remote Layer 3 Query

Error Code	Test Result	Description/Recommendation
	ABORT	Internal system error 1. Retry the command at 1-minute intervals a maximum of 5 times.

*Continued on next page*

Table 5-287. TEST #637 Remote Layer 3 Query — *Continued*

Error Code	Test Result	Description/Recommendation
1006	ABORT	<p>This is a NORMAL ABORT. For country protocol 1 interfaces (including the USA), either there are no B-channels administered in this signaling group, or all B-channels in this signaling group are either out-of-service or are in a "pending" state (PINS or PMTC, indicating that a B-channel maintenance message for that B-channel has been sent and not yet acknowledged).</p> <ol style="list-style-type: none"> <li>1. Administer an ISDN Trunk or PRI Endpoint Port (B-channel) in this signaling group, or use the <b>status trunk TRK-GRP/TRK</b> or <b>status pri-endpoint &lt;extension&gt;</b> command to check the state of the ISDN Trunks or PRI Endpoint Ports associated with this signaling group. Refer to "<a href="#">ISDN-TRK (DS1 ISDN Trunk)</a>" on page 5-722 or "<a href="#">PE-BCHL (PRI Endpoint Port)</a>" on page 5-913 for further details regarding service state definitions and transitions. For systems not using country protocol 1 interfaces, there are no B-channels administered in this signaling group.</li> </ol>
1019	ABORT	<p>There is already a Remote Layer 3 Query in progress. This is a normal ABORT.</p> <ol style="list-style-type: none"> <li>1. Wait two minutes, then follow the procedures for when this test passes.</li> </ol>
1113	ABORT	<p>The Signaling Link is down. Therefore no messages can be sent to the Far-end switch.</p> <ol style="list-style-type: none"> <li>1. Examine the results of Tests #636 and #639 and follow recommendations provided there.</li> <li>2. If either test passes, it may be because the signaling link was disabled by system technician. Verify this by using the <b>display comm link</b> command. Tests #636 and #639 pass if the signaling link is not enabled.</li> </ol>
2100	ABORT	<p>Could not allocate the necessary system resources to run this test.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
2500	ABORT	<p>Same as ABORT with no error code.</p> <ol style="list-style-type: none"> <li>1. Follow the recommendations for ABORT with no error code.</li> </ol>
2500	FAIL	<p>Same as ABORT with no error code.</p> <ol style="list-style-type: none"> <li>1. Follow the recommendations for ABORT with no error code.</li> </ol>

*Continued on next page*

Table 5-287. TEST #637 Remote Layer 3 Query — *Continued*

Error Code	Test Result	Description/Recommendation
	PASS	<p>A message was composed and sent to the Far-end switch. The ISDN PRI specification allows up to two minutes for a reply.</p> <ol style="list-style-type: none"> <li>1. Check the Error Log for ISDN-SGR (ISDN-PRI Signaling Group) for errors of type 2305 for evidence of a Remote Layer 3 Query failure. If no new errors were logged since this test was run, then this switch and the Far-end switch processor can exchange call control messages.</li> <li>2. If there is still a problem with a particular DS1 ISDN Trunk or PRI Endpoint Port (B-channel), busyout the trunk or port and run the long test sequence, paying particular attention to the results of Test #258 (ISDN Test Call).</li> </ol>

### Secondary Signaling Link Hardware Check (#639)

The ISDN-PRI Signaling Group D-Channel port depends on the health of the DS1/UDS1 Interface circuit pack on which it resides. This test will fail if there are problems with either the ISDN-PRI Primary D-channel port or the DS1/UDS1 circuit pack. If there are problems with the ISDN-PRI Secondary Signaling Channel port (ISDN-PLK), also investigate the DS1/UDS1 circuit pack.

See [Figure 5-25](#) for DS1 connections, [Figure 5-26](#) for UDS1 connections.

Table 5-288. TEST #639 Secondary Signaling Link Hardware Check

Error Code	Test Result	Description/ Recommendation
	ABORT	<p>Internal system error</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
1132	ABORT	The Secondary D-channel is not administered for this Signaling Group. This is a NORMAL ABORT. Only a Primary D-channel must be administered for a Signaling Group.

*Continued on next page*

Table 5-288. TEST #639 Secondary Signaling Link Hardware Check — *Continued*

Error Code	Test Result	Description/ Recommendation
4	FAIL	<p>There is a problem with the Processor Interface Link. No DS1 ISDN Trunk (B-channel) or Wideband PRI Endpoint calls can be made until the problem is resolved.</p> <ol style="list-style-type: none"><li>1. Display the Communication-Interface Links Form via the <b>display communication-interface</b> command to determine which link is down (find the one that matches the DS1 Interface circuit pack on which this ISDN-PRI Signaling Link Port resides) and then refer to <a href="#">“PKT-INT (Packet Interface)” on page 5-958</a>.</li></ol>
8	FAIL	<p>There is a problem with the DS1/UDS1 Interface circuit pack or the ISDN-PRI Secondary Signaling channel (D-channel). No ISDN Trunk (B-channel) or Wideband PRI Endpoint calls can be made until the problem is resolved.</p> <ol style="list-style-type: none"><li>1. Refer to <a href="#">“DS1-BD (DS1 Interface Circuit Pack)” on page 5-548</a>, <a href="#">“UDS1-BD (UDS1 Interface Circuit Pack)” on page 5-1227</a> and the ISDN-PRI Signaling channel (ISDN-LNK/ISDN-PLK) Maintenance documentation.</li></ol>
	PASS	<p>The basic physical connectivity of the Signaling Group’s Secondary D-channel is intact and functional. Try this test repeatedly to ensure the link is up and to uncover any transitory problems.</p>

## Layer 2 Status Test (#647)

---

The Layer 2 Status Test checks the layer 2 status of the ISDN-PRI Signaling Channel (D-channel). This test will fail if there is a hardware failure or a facility problem, or if the primary and secondary ISDN-PRI D-channels are not administered correctly.

The Primary and Secondary Signaling Link Hardware tests (test 636 and 639) and the Remote Layer 3 Query test (test 637) will detect most problems caused by hardware failures or incorrect administration. However, the Layer 3 test (test 637) cannot detect end-to-end transmission problems with the Standby D-channel since Layer 3 messages are not sent on the standby channel.

The SYS-LINK Maintenance Object reports Layer 2 ISDN-PRI D-channel problems and for G3i/s/vs, the PKT-INT Maintenance Object reports Layer 2 ISDN-PRI D-channel problems (if the D-channel is connected to the Processor Interface circuit pack). However, the PKT-INT Maintenance Object does not monitor the Layer 2 status of the ISDN-PRI D-channel when the D-channel is connected to the Packet Control circuit pack for the ISDN-PRI over PACCON feature. The Layer 2 Query test is provided to detect D-Channel Layer 2 failures and generate an associated Warning alarm independent of the hardware configuration used for the D-channels.

Table 5-289. TEST #647 Layer 2 Status Query Test

Error Code	Test Result	Description/ Recommendation
1132	ABORT	Internal system error  The port location for the primary ISDN-PRI D-channel is not known. This condition should not be possible since an administered DS1 circuit pack must be specified when a Signaling Group is administered:  1. Retry the command at 1-minute intervals a maximum of 5 times.
1134	ABORT	Internal system error  The associated DS1 circuit pack is not administered. This condition should not be possible since an administered DS1 circuit pack must be specified when a Signaling Group is administered.  1. Retry the command at 1-minute intervals a maximum of 5 times.
2500	ABORT	Internal system error  1. Retry the command at 1-minute intervals a maximum of 5 times.

*Continued on next page*

Table 5-289. TEST #647 Layer 2 Status Query Test — *Continued*

Error Code	Test Result	Description/ Recommendation
1	FAIL	<p>Layer 2 of the primary signaling channel is down:</p> <ol style="list-style-type: none"> <li>1. Examine the results of the Primary Signaling Link Hardware Test (#636) and follow recommendations provided there.</li> <li>2. If test #636 passes, the Layer 2 Query test may still fail if the Signaling Channel at the far end has not been administered correctly or if it has been busied out. Verify that the Primary Signaling Channel (D-channel) at the far end has been administered correctly. Verify that the DS1 port used for the Primary D-channel has not been busied out at the far end.</li> </ol>
2	FAIL	<p>Layer 2 of the secondary signaling channel is down.</p> <ol style="list-style-type: none"> <li>1. Examine the results of Secondary Signaling Link Hardware Test (#639) and follow recommendations provided there.</li> <li>2. If tests #639 passes, the Layer 2 Query test may still fail if the Signaling Channel at the far end has not been administered correctly or if the Signaling Channel has been busied out. Verify that the Secondary Signaling Channel (D-channel) at the far end has been administered correctly. Verify that the DS1 port used for the Secondary D-channel has not been busied out at the far end.</li> </ol>
3	FAIL	<p>Both the primary and secondary Channels are down.</p> <ol style="list-style-type: none"> <li>1. Examine the results of the Primary and Secondary Signaling Link Hardware Tests (#636 and #639) and follow recommendations provided there.</li> <li>2. If tests #636 and #639 pass, the Layer 2 Query test may still fail if the Signaling Channels at the far end has not been administered correctly or if the Signaling Channels have been busied out. Verify that the Primary and Secondary Signaling Channel (D-channels) at the far end have been administered correctly. Verify that the DS1 ports used for the Primary and Secondary D-channels have not been busied out at the far end.</li> </ol>
	PASS	<p>The Primary Signaling Channel is up and, if administered the Secondary Channel is up.</p>

## ISDN-TRK (DS1 ISDN Trunk)


---

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run	Full Name of MO
ISDN-TRK <sup>1</sup>	MAJOR <sup>2</sup>	test port PCSSpp l	DS1 ISDN Trunk
ISDN-TRK	MINOR	test port PCSSpp l	DS1 ISDN Trunk
ISDN-TRK	WARNING	test port PCSSpp sh	DS1 ISDN Trunk

1. For additional repair information, refer to ["DS1-BD \(DS1 Interface Circuit Pack\)" on page 5-548](#).
  2. A MAJOR alarm on a trunk indicates that alarms on these trunks are not downgraded by the **set options** command and that at least 75 percent of the trunks in this trunk group are alarmed.
- 

A DS1 ISDN Trunk is known as a B-channel. It is a 64 kbps Bearer channel that can be used to transmit digital traffic, be it voice or data. These trunks use a separate channel for signaling (for example, for call setup); this mode of operation is known as out-of-band signaling, as opposed to in-band, robbed-bit signaling, where the signaling traffic flows over the same channel as the voice or data traffic. The separate signaling channel is called a D-channel in ISDN terminology, and it carries all the call control signaling messages for the DS1 ISDN Trunk B-channels. The D-channel for these B-channels is an ISDN-PRI (Primary Rate Interface) Signaling Link Port (ISDN-LNK/ISDN-PLK).

On 24-channel interfaces, any of the first 23 ports on the DS1/UDS1 interface circuit pack can be a B-channel. The 24th port may be used as a B-channel or as a D-channel depending on the type of ISDN-PRI Signaling Group (ISDN-SGR) to which it belongs.




**Figure Notes**

1. B- and D-channel messages are routed over the TDM Bus. For additional reliability, a duplex D-channel can be administered for a signaling group and located on a different TN464C (or higher) circuit pack.
2. TN767B (or higher) for DS1; TN464C (or higher) for UDS1

**Figure 5-27. DS1 ISDN Trunk Interactions (24 Channel - TN767/464C)**

On 32 channel interfaces, any of ports 1-15 and 17-31 on the DS1 interface circuit pack can be a B-channel. The 16th port may be used as a B-channel or as a D-channel depending on the type of ISDN-PRI Signaling Group (ISDN-SGR) to which it belongs. For more details, refer to ["ISDN-SGR \(ISDN-PRI Signaling Group\)" on page 5-705](#), ["DS1-BD \(DS1 Interface Circuit Pack\)" on page 5-548](#), and ["UDS1-BD \(UDS1 Interface Circuit Pack\)" on page 5-1227](#).



**Figure Notes**

1. B- and D-channel messages are routed over the TDM Bus. For additional reliability, a duplex D-channel can be administered for a signaling group and located on a different TN464C (or higher) circuit pack.
2. TN464C or higher

**Figure 5-28. ISDN-PRI Signaling Link Port Interactions (32-Channel - TN464)**

For interfaces using country protocol 1 on the DS1 Circuit Pack administration form (including US), the signaling protocol used for the maintenance of the B-channel is defined by the Lucent ISDN-PRI Specification.

For interfaces using country protocols other than 1, the signaling protocol used for the maintenance of the B-channel is defined by the CCITT ISDN-PRI Specification.

There are five possible Service States for a B-channel. The service state is negotiated with the far-end switch, changes over time, and may have a far-end or near-end component. The service state is initialized to Out-Of-Service/Far-End state and an attempt is made to negotiate it to In-Service.

**⇒ NOTE:**

The service state of a particular DS1 ISDN Trunk B-channel can be displayed by issuing the **status trunk <trunk\_group/trunk\_member>** system technician command.

If a call is present, the Specification defines the permissible Call States as well. There are tests in the Short and Long Test Sequences for DS1 ISDN Trunk designed to audit these states and ensure agreement between both ends of the PRI connection.

## Alarming Based on Service States

A warning alarm is logged against a DS1 ISDN B-channel trunk when it is placed in the Maintenance/Far-End or Out-Of-Service/Far-End states, during which the trunk is unusable for outgoing calls. When a warning alarm is present, use **status trunk group#/member#** command to determine the exact state. Other alarms can be diagnosed by using the short and/or long test sequences. Note that an ISDN B-channel trunk can be placed in a Far-End service state by either action taken by the far-end switch or by failure of the far-end switch to respond. For example, if the far-end does not respond to a Remote Layer 3 Query (Test #637 for ISDN-SGR), the associated DS1 ISDN trunk B-channels is placed in the Maintenance/Far-End service state.

As a port on a DS1 circuit pack (DS1-BD or UDS1-BD), and as part of a signaling group dependent on a D-channel (ISDN-PLK) for signaling, operation of the ISDN-TRK is dependent on the health of these other maintenance objects.

## DS1 ISDN Trunk Service States

This section defines the possible service states of a DS1 ISDN trunk, explains the reason for each service state, and provides the recommended recovery procedures (when required).

## Service States

- In-Service (INS)

The B-channel is in its normal operating state.

- Out-of-Service/Far-end (OOS/FE)

A B-channel is initialized to this state when administered and it may also be in this state if there is a failure on the B-channel attributed to a problem on the far-end switch. The switch sends messages to the far-end to negotiate the B-channel into service. If the far-end does not respond to the messages within a certain time period, then the service state remains out-of-service and maintenance will periodically resend the messages. The trunk is unusable for outgoing calls. On US interfaces, the trunk is unusable for incoming calls, but on non-US interfaces, incoming calls will be accepted.

- Out-of-Service/Near-end (OOS/NE)

This is the state of the trunk when a hardware failure exists on the link, the NPE Crosstalk Test fails, or when the trunk is busied out by system technician. In this state, the trunk is unusable for incoming or outgoing calls. No messages are sent to the far-end until the signaling link comes back into service or the trunk is released by system technician.

- Maintenance/Far-end (MTC/FE)

This state is reached when the far-end does not respond to messages sent over the signaling link for a particular trunk after a certain amount of time. This state is different from OOS/FE since the signaling link must have initially been up and the B-channels in-service. The switch will periodically send messages to the far-end to try to negotiate the trunk (B-channel) into service. The trunk is unusable for outgoing calls but will service incoming call requests from the far-end. Note that transitions into MTC/FE do not drop stable calls. Therefore, if the service state changes from in-service to MTC/FE, then stable calls are unaffected.

- Maintenance/Near-end (MTC/NE)

The trunk (B-channel) is in this state if the signaling link (PKT-INT) is busied out by system technician. The trunk (B-channel) is also temporarily in this state if system technician has issued a **test trunk trunk\_group/trunk\_member long** command. This command will execute the ISDN-PRI test call. This test will change the state of the trunk member to MTC/NE for the duration of the test unless a call request comes in from the far-end. In that case, the test would abort. Note that transitions into MTC/NE do not drop stable calls. Therefore, a system technician-demanded **busyout link lnk-no** command will not drop stable trunk calls. In this state, the B-channel is not usable for new outgoing calls, but is available for incoming calls and outgoing test calls.

- Pending States

If the near-end is expecting a timed response from the far-end for a request to change the service state of a trunk, then the state of the trunk reflects a Pending State.

- Pending-in-service (PINS)

The near-end has sent a B-channel maintenance message to the far-end, requesting that the B-channel service state be transitioned to in-service. The far-end has a certain amount of time to respond to the message. The service state will be PINS until either a response is received or the timer expires.

- Pending-maintenance (PMTTC)

This state is supported only by systems using country protocol 1 (including US). The near-end has sent a B-channel maintenance message to the far-end, requesting that the B-channel service state be transitioned to maintenance. The far-end has a certain amount of time to respond to the message. The service state will be PMTTC until either a response is received or the timer expires.

- Call Activity States

In addition to the service and pending state, the state of a B-channel also reflects its call activity. If a call is connected over the B-channel, then the state of the trunk will reflect the "active" call state, for example, "in-service/active." If there is no call on the B-channel, then the trunk will reflect the "idle" call state, for example, "OOS/FE-idle."

The following diagram of the DS1 ISDN Trunk service states shows the common progression from one service state to another and the event that caused the change of state.




Figure 5-29. Common Progressions in Service States

## ISDN-PRI Trunk Service States

The following chart summarizes each of the different DS1 ISDN Trunk service states that can result when the **status trunk <trunk\_group/trunk\_member>** command is issued.



**NOTE:**

Refer to [“Troubleshooting ISDN-PRI problems”](#) on page 2-32 for a layered approach to processing ISDN-PRI problems.

5 Maintenance Objects for DEFINITY ONE  
ISDN-TRK (DS1 ISDN Trunk)

5-729

Table 5-290. ISDN-PRI Trunk Service States (Test #161 Loop Around Test)

Service State	Alarm*	Possible Cause	Possible Solution
<b>out-of-service/NE</b>	Warning	Trunk is demand busied out.	Enter <b>release trunk grp#/mbr#</b> .
	Minor	NPE Crosstalk Test (#6) failed.	Replace DS1/UDS1 circuit pack.
	None	DS1 or UDS1 circuit pack lost its signal.	Is the DS1/UDS1 circuit pack or cable removed? Is the far-end switch restarting? Check circuit pack using procedures in DS1-BD or UDS1-BD.
<b>out-of-service/FE</b>	Warning	Unadministered far-end	Administer corresponding trunk on far-end switch.
	Warning	The far-end trunk is busied out.	Check the status of the far-end switch.
<b>pending-in-service, pending-maint</b>	None	Maintenance message was sent and the switch is waiting up to 2 min. for a reply from the far-end.	Wait 2 minutes and check service state after the pending state has cleared.
<b>maint-NE</b>	None	ISDN test call in progress ( <b>test trunk long</b> and <b>test isdn-testcall</b> commands)	Wait several minutes for test to finish and check status again.
<b>maint-FE</b>	None	System link has been busied out by command.	Check link status. Release link with <b>release link link#</b> .
	Warning	Signaling channel has been down for over 90 sec.	Consult ISDN-SGR and/or ISDN-LNK. Far-end signaling channel may be busied out, or the far-end switch may currently be restarting.
	Warning	Repeated failure of far end to respond to messages.	Maintenance software will periodically try to resend messages. You can speed the process with <b>test trunk grp#/mbr#</b> and/or <b>test signaling-gr #</b> .
	Warning	The far-end trunk is being tested.	Check status of the far-end switch. Wait for testing to finish.
<b>in-service</b>	None	Normal operating state	

## Error Log Entries and Test to Clear Values

Table 5-291. DS1 ISDN Trunk Error Log Entries

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
0 <sup>1</sup>	0	Any	Any	Any	test port PCSSpp sh r 1
1 (a)	Any	None			test port PCSSpp sh r 1
15 (b)	Any	Audit and Update Test (#36)			
18	0	busyout trunk <grp>/<mbr>			release trunk <grp>/<mbr>
129 (c)		None	WARNING	OFF	test port PCSSpp
130 (d)		None	WARNING	ON	test port PCSSpp
257 (e)	Any	None			test port PCSSpp
513 (f)	Any	None	WARNING	OFF	test port PCSSpp
769 (e)	Any	None			test port PCSSpp
1281	Any	Conference Circuit Test (#7)	MIN/ WRN <sup>2</sup>	ON	test port PCSSpp l r 4
1537	Any	NPE Crosstalk Test (#6)	MIN/WRN <sup>2</sup>	ON	test port PCSSpp l r 3
1793 (g)	Any	None			test port PCSSpp
3073 (h)	Any	Service State Audit (#256)			test port PCSSpp
3585 (i)	Any	None			None
3841 (j)	Any	None			None

1. Run the Short Test Sequence first. If all tests pass, run the Long Test Sequence. Refer to the appropriate test description and follow the recommended procedures.
2. Minor alarms on this MO may be downgraded to Warning alarms based on the values used in the **set options** command. If the Minor alarm is not downgraded by the **set options** values, then the Minor alarm will be upgraded to a Major alarm if 75 percent of the trunks in this trunk group are alarmed.

### Notes:

- a. These error types indicate a disagreement between this switch and the switch at the other end of the trunk connection with regard to the ISDN *call* state of the DS1 ISDN Trunk. This switch will automatically try to recover by clearing the call, (that is, the call will be torn down). You can use the **status trunk <trunk\_group/trunk\_member>** command to determine the state of the trunk.

When running the Short Test Sequence of tests, pay close attention to the results of the Call State Audit Test (#257).

5 Maintenance Objects for DEFINITY ONE  
ISDN-TRK (DS1 ISDN Trunk)

5-731

- b. This is a software audit error that does not indicate any hardware malfunction. Run the Short Test Sequence and investigate associated errors (if any).
- c. The far-end switch changed its ISDN *service* state to either out-of-service or maintenance. This may be a temporary condition due to testing of that trunk by the far-end *or* a hardware problem with the trunk. Outgoing calls will not be allowed over the trunk. To investigate the status of the trunk, issue the **status trunk <trunk\_group/trunk\_member>** command.
- d. This error type indicates that the circuit pack has been removed or has been insane for more than 11 minutes. To clear the error, reinsert or replace the circuit pack.
- e. These error types indicate a disagreement between this switch and the switch at the other end of the trunk connection with regard to the ISDN service state of the DS1 ISDN Trunk. This switch will automatically try to recover by performing a service state audit. You can use the **status trunk <trunk\_group/trunk\_member>** command to determine the state of the trunk.

When running the Short Test Sequence, pay close attention to the results of the Service State Audit Test (#256).

- f. This trunk is not recognized by the far-end switch. Investigate the trunk administration for both switches and make changes as necessary.
- g. This error indicates a failure of the DS1/UDS1 Interface circuit pack. When running the Short Test Sequence, the results of the Signaling Link State Check Test (#255) are important.
- h. Two Service State Audit attempts have failed (see Test #256). The trunks will not be usable for any outgoing calls (although incoming calls will be accepted) until the test passes and the trunk state is changed to in-service (use **status trunk trunk\_group/trunk\_member** to investigate trunk status).
- i. Error Type 3585 appears when the switch receives an ISDN RESTART message for an ISDN trunk. Calls are cleared with the RESTART message. Therefore, this error type may be associated with a dropped call report from a user.

The following Aux Data values for Error Type 3585 represent the trunk's ISDN call state at the time the unexpected request to restart the channel was received from the remote switch. This information can be useful if dropped calls (cutoffs) are being reported by users of the ISDN-PRI trunks. The meanings of the various Aux Data values are shown below; any others can be ignored.

5 Maintenance Objects for DEFINITY ONE  
ISDN-TRK (DS1 ISDN Trunk)

5-732

Aux Data	Explanation
0	A idle trunk received a restart.
10	A call in a stable, talking state was cleared unexpectedly by the far-end with an ISDN RESTART message. This state is called the "active" state.
4, 7, 8 260, 263	A call that has not reached the active state, but has at least reached a ringing state, was cleared unexpectedly by the far-end with an ISDN RESTART message.
1, 3, 6 9, 265	A call that has not yet reached a ringing state was cleared unexpectedly by the far-end with an ISDN RESTART message.
11, 12 19, 531, 267, 268	A call that was in the process of clearing anyway has been cleared by the far-end with an ISDN RESTART message. If this condition occurs frequently, it may mean that the far-end is attempting to clear trunks that it thinks are in a "hung" state. The RESTART message brings the trunk to an idle condition.

- j. An ISDN trunk selected by the near-end has been rejected 10 times by the far-end without a successful call. This may indicate a service state mismatch between the near-end and far-end for this trunk that is effecting the end user (that is, customer receives unexpected intercept tones when accessing ISDN trunks). This may indicate that the ISDN trunk is not administered on the far-end.

The Aux field contains the physical name of the ISDN trunk in decimal. Then, verify that the far-end has this trunk administered. If problems persist, then busy-out the ISDN trunk to take it out of the hunt group.

The Warning alarm will be retired automatically whenever an outgoing or incoming call that uses this trunk is answered by the called endpoint. If problems persist, then busy-out the ISDN trunk to take it out of the hunt group.

---

## System Technician-Demanded Tests: Descriptions and Error Codes

---

Always investigate tests in the order presented in the table below when inspecting errors in the system. By clearing error codes associated with the *NPE Crosstalk Test*, for example, you may also clear errors generated from other tests in the testing sequence.

Table 5-292. System Technician-Demanded Tests: ISDN-TRK

Order of Investigation	Short Test Sequence	Long Test Sequence	D/ND <sup>1</sup>
NPE Crosstalk Test (#6)		X	ND
Conference Circuit Test (#7)		X	ND
Audit and Update Test (#36)	X	X	ND
Signaling Link State Check Test (#255)	X	X	ND
Service State Audit Test (#256)	X	X	ND
Call State Audit Test (#257)	X	X	ND
ISDN Test Call Test (#258)		X	ND

---

1. D = Destructive, ND = Non-destructive

---

### NPE Crosstalk Test (#6)

The NPE Crosstalk Test verifies that this port's NPE channel talks on the selected time slot and never crosses over to time slots reserved for other connections. If the NPE is not working correctly, one-way and noisy connections may be observed. This test is usually only part of a port's Long Test Sequence and takes about 20 to 30 seconds to complete.



#### NOTE:

The TN464C or later UDS1 circuit pack has one SCOTCH-NPE chip instead of several NPE chips.

5 Maintenance Objects for DEFINITY ONE  
ISDN-TRK (DS1 ISDN Trunk)

5-734

Table 5-293. TEST #6 NPE Crosstalk Test

Error Code	Test Result	Description/ Recommendation
	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals a maximum of 5 times.
1000	ABORT	System resources required for this test are not available. The port may be in use on a valid call. Use <b>status station</b> or <b>status trunk</b> commands to determine when the port is available for testing. (Refer to <a href="#">"status station" on page 4-213</a> for a description of all possible states.) 1. Retry the command at 1-minute intervals a maximum of 5 times.
1001	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals a maximum of 5 times.
1002	ABORT	The system could not allocate time slots for the test. The system may be under heavy traffic conditions or it may have time slots out-of-service due to TDM-Bus errors. Refer to <a href="#">"TDM-BUS (TDM Bus)" on page 5-1116</a> to diagnose any active TDM-Bus errors. 1. If the system has no TDM-Bus errors and is not handling heavy traffic, repeat the test at 1-minute intervals a maximum of 5 times.
1003	ABORT	The system could not allocate a tone receiver for the test. The system may be oversized for the number of tone detectors present or some tone detectors may be out-of-service. 1. Look for TTR-LEV errors in the Error Log. If present, refer to <a href="#">"TTR-LEV (TTR Level)" on page 5-1223</a> . 2. Look for TONE-PT errors in the Error Log. If present, refer to <a href="#">"TONE-PT (Tone Generator)" on page 5-1204</a> . 3. If neither condition exists, retry the test at 1-minute intervals a maximum of 5 times.
1004	ABORT	The port has been seized by a user for a valid call. Use <b>status station</b> or <b>status trunk</b> commands to determine when the port is available for testing. 1. Retry the command at 1-minute intervals a maximum of 5 times.
1018	ABORT	Maintenance is disable on this trunk. 1. Enable maintenance by entering "y" in the "Maintenance Tests?" field on page 2 of the <b>change trunk-group</b> form.
1117	ABORT	A service state audit message is outstanding. 1. Wait 2 minutes and then try again.
2000	ABORT	Response to the test request was not received within the allowable time period. 1. Retry the command at 1-minute intervals a maximum of 5 times.

Continued on next page

Table 5-293. TEST #6 NPE Crosstalk Test — *Continued*

Error Code	Test Result	Description/ Recommendation
2020	ABORT	The test did not run due to an already existing error on the specific port or a more general circuit pack error.  1. Examine Error Log for existing errors against this port or the circuit pack and attempt to diagnose the already existing error.
2100	ABORT	Could not allocate the necessary system resources to run this test.  1. Retry the command at 1-minute intervals a maximum of 5 times.
Any	FAIL	The NPE of the tested port was found to be transmitting in error. This will cause noisy and unreliable connections. The ISDN-TRK is moved to out-of-service/near-end state.  1. Replace the circuit pack.
	PASS	The port is able to communicate over the TDM Bus.

### Conference Circuit Test (#7)

The Conference Circuit test verifies that the NPE channel for the port being tested can correctly perform the conferencing function. The NPE is instructed to listen to several different tones and conference the tones together. The resulting signal is then measured by a tone detector port. If the level of the tone is within a certain range, the test passes.



#### NOTE:

The TN464C or later UDS1 circuit pack has one SCOTCH-NPE chip instead of several NPE chips.

Table 5-294. TEST #7 Conference Circuit Test

Error Code	Test Result	Description/ Recommendation
	ABORT	Could not allocate the necessary system resources to run this test.  1. Retry the command at 1-minute intervals a maximum of 5 times.
1000	ABORT	System resources required to run this test are not available. The port may be in use on a valid call. Use <b>status station</b> or <b>status trunk</b> commands to determine when the port is available for testing.

*Continued on next page*

Table 5-294. TEST #7 Conference Circuit Test — *Continued*

Error Code	Test Result	Description/ Recommendation
1004	ABORT	The port has been seized by a user for a valid call. Use status station or status trunk to determine when the port is available for testing. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
1018	ABORT	Maintenance is disabled on this trunk. <ol style="list-style-type: none"><li>1. Enable maintenance by entering <b>y</b> in the Maintenance Tests? field on page 2 of the <b>change trunk-group</b> form.</li></ol>
1020	ABORT	The test did not run due to an already existing error on the specific port or a more general circuit pack error.  Examine Error Log for existing errors against this port or the circuit pack and attempt to diagnose the already existing error.
2000	ABORT	Response to the test request was not received within the allowable time period.
2100	ABORT	Could not allocate the necessary system resources to run this test. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
Any	FAIL	The NPE of the tested port did not conference the tones correctly. This will cause noisy and unreliable connections. <ol style="list-style-type: none"><li>1. Replace the circuit pack.</li></ol>
	PASS	The port can correctly conference multiple connections. User-reported troubles on this port should be investigated using other port tests and examining station, trunk, or external wiring.

## Audit and Update Test (#36)

This test sends port level translation data from switch processor to the DS1 interface circuit pack to assure that the trunk's translation is correct. The port audit operation verifies the consistency of the current state of trunk kept in the DS1 interface circuit pack and in the switch software.

Table 5-295. TEST #36 Audit and Update Test

Error Code	Test Result	Description/ Recommendation
1018	ABORT	Internal system error
	ABORT	Maintenance is disabled on this trunk. <ol style="list-style-type: none"><li>1. Enable maintenance by entering <b>y</b> in the <code>Maintenance Tests?</code> field on page 2 of the <b>change trunk-group</b> form.</li></ol>
2000	ABORT	Response to the test request was not received within the allowable time period.
2100	ABORT	Could not allocate the necessary system resources to run this test. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times</li></ol>
	FAIL	Test failed due to Internal system error. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
	PASS	Trunk translation has been updated successfully. The current trunk states kept in the DS1 interface circuit pack and switch software are consistent. If the trunk is busied out, the test will not run, but will return PASS. To verify that the trunk is in-service: <ol style="list-style-type: none"><li>1. Enter <b>status-command</b> to verify that the trunk is in-service. If the trunk is in-service, no further action is necessary. If the trunk is out-of-service, continue to Step 2.</li><li>2. Enter <b>release-trunk</b> command to put trunk back into in-service.</li><li>3. Retry the test command.</li></ol>

## Signaling Link State Check Test (#255)

As noted in the general description for a DS1 ISDN Trunk, it depends on the health of the DS1/UDS1 interface circuit pack and the ISDN-PRI D-channel (ISDN-LNK/ISDN-PLK) trunk for proper operation. This test checks the status of those critical elements.

Table 5-296. TEST #255 Signaling Link State Check Test

Error Code	Test Result	Description/ Recommendation
	ABORT	Internal system error
1018	ABORT	Maintenance is disable on this trunk. <ol style="list-style-type: none"><li>1. Enable maintenance by entering <b>y</b> in the Maintenance Tests? field on page 2 of the <b>change trunk-group</b> form.</li></ol>
1114	ABORT	The signaling link is in a transitional state. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
4	FAIL	There is a problem with the Signaling Channel. <ol style="list-style-type: none"><li>1. If the Packet Control circuit pack is used consult the procedures for the ISDN-PRI Signaling Group (ISDN-SGR). Further information may also be obtained by consulting the procedures for the ISDN-PRI Signaling Channel (ISDN-PLK).</li><li>2. If the Packet Interface is used, consult the procedures for PKT-INT.</li></ol>
8	FAIL	There is a problem with the DS1 interface circuit pack. <ol style="list-style-type: none"><li>1. Consult the procedures for DS1 interface circuit pack (DS1-BD/UDS1-BD).</li></ol>
	PASS	The signaling link hardware is OK.

## Service State Audit (#256)

These trunks may be in one of several service states. This test performs a Service State Audit with the far-end switch.

For interfaces using country protocol 1 (including US), the Service State Audit executes in all trunk service states. A message is sent to the far-end switch to ensure that both sides agree on the service state. A PASS for this test simply means that the message has been successfully sent. Two minutes are allowed for a reply. If no reply is received within that 2 minute window, the message is sent out again. If that attempt fails, an error is logged (Error Type 3073) and the switch then attempts another Service State Audit every 15 minutes. If the trunk was initially INS (in-service), it is then placed in the MTC/FE (maintenance state, far-end problem) state. No outgoing calls are placed over this trunk, but incoming calls are accepted. If an incoming call is presented while in such a state, a Service State Audit attempt is immediately attempted (that is, the switch does not wait for the 15-minute cycle, but tries to recover immediately).

For interfaces not using country protocol 1, the Service State Audit executes only if the trunk is in the OOF/FE state. A message is sent to the far-end switch to attempt to bring the trunk back into the in-service state. A PASS for this test simply means that the message has been successfully sent. Two minutes are allowed for a reply. If no reply is received within that two minute window, the message is sent out once again. If no response is received in the next two minute window, then the trunk remains in the OOS/FE state. The switch will attempt another Service State Audit in another hour.

To investigate the service state of the DS1 ISDN Trunk, issue the **status trunk trunk-group/trunk-member** command.

Table 5-297. TEST #256 Service State Audit Test

Error Code	Test Result	Description/ Recommendation
1000	ABORT	System resources required to run this test are not available. The port may be on a valid call. Use <b>status station</b> or <b>status trunk</b> to determine when trunk is available for testing.  1. Check the results of Test #255 (Signaling Link State Check).
1018	ABORT	Maintenance is disabled on this trunk.  1. Enable maintenance by entering <b>y</b> in the Maintenance Tests? field on page 2 of the <b>change trunk-group</b> form.
1113	ABORT	The signaling link has failed, so the system cannot send any messages on behalf of this trunk.  1. Check the results of Test #255 (Signaling Link State Check).

*Continued on next page*

Table 5-297. TEST #256 Service State Audit Test — *Continued*

Error Code	Test Result	Description/ Recommendation
1114	ABORT	The signaling link is in a transitional state. 1. Retry the command at 1-minute intervals a maximum of 5 times.
1116	ABORT	The trunk is not in a service state which is appropriate for running the test. This test is only performed in the OOS/FE state.
1117	ABORT	A service state audit message is outstanding. 1. Wait two minutes and then try again.
2100	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals a maximum of 5 times.
1113	FAIL	The signaling link has failed, so the system cannot send any messages on behalf of this trunk. 1. Consult the procedures for ISDN-LNK (ISDN-PRI Signaling Link Port) and PKT-INT (Packet Interface).
	FAIL	Internal system error 1. Retry the command at 1-minute intervals a maximum of 5 times.
	PASS	Wait 4 minutes and then check the Error Log for any new errors of type 3073. If there are none, then both sides of the ISDN connection agree on the service state; the negotiation succeeded. If there is a new 3073 error, then the negotiation failed (the far-end switch twice failed to respond within 2 minutes). The switch will automatically retry every 15 minutes. If the trunk was initially in-service, it is now placed in the maintenance/far-end state. Incoming calls will be accepted, but no outgoing calls can be originated. If an incoming call is presented, another Service State Audit will be immediately performed in an attempt to put the DS1 ISDN Trunk in the proper state.

**Call State Audit Test (#257)**

If a call is active on the trunk, the switches on both sides of the connection should agree on the ISDN state of the call, as defined in the ISDN Protocol Specification. This test audits internal call state data by querying the far-end switch as to the ISDN state of the call. It can be helpful when trying to clear a hung call. If the internal call state data on the near-end switch is different than that of the far-end switch, then **the call will be torn down.**

As with Test #256 (Service State Audit), a PASS simply means that an appropriate message was composed and sent to the far-end switch. The ISDN Specification allows up to two minutes for a reply. If a reply is not received within the two minute window, a protocol time-out violation will be recorded in the error log against the associated signaling channel (ISDN-PRI Signaling Link Port, which is listed in the Error Log as ISDN-LNK/ISDN-PLK; the Error Type is 1).

Table 5-298. TEST #257 Call State Audit Test

Error Code	Test Result	Description/ Recommendation
1018	ABORT	Maintenance is disable on this trunk. 1. Enable maintenance by entering <b>y</b> in the <code>Maintenance Tests?</code> field on page 2 of the <b>change trunk-group</b> form.
1019	ABORT	An audit is already in progress. 1. Wait two minutes and try again.
1113	ABORT	The signaling link has failed, so the system cannot send any messages on behalf of this trunk. 1. Check the results of Test #255 (Signaling Link State Check).
1114	ABORT	The signaling link is in a transitional state. 1. Retry the command at 1-minute intervals a maximum of 5 times.
1116	ABORT	The trunk is in an out-of-service ISDN service state. 1. A call cannot be present if the trunk is in an ISDN out-of-service state, so a call state audit would be inappropriate. No action necessary. (Use the <b>status trunk</b>
2100	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals a maximum of 5 times.
	FAIL	Internal system error 1. Retry the command at 1-minute intervals a maximum of 5 times.
	PASS	This switch sent a call state auditing message to the far-end switch to verify the state of the call active on this trunk. If a call state mismatch is found, then the call will be torn down within two minutes. If no call was active, then no message was sent.

## ISDN Test Call Test (#258)

This test performs a far-end loop around to a far-end switch over an ISDN trunk. The trunk's service state must be in-service, maint-NE, or out-of-service/NE, and no call can be active on the trunk. The test call can be initiated as part of a long test sequence, or as an individual test, as described below. This test is valid only for systems using country protocol 1 (including US), or when the far end has loop-around capability.

A test call connection is established to a far-end switch over the ISDN trunk to be tested. The digital port on a TN711D Maintenance/Test circuit pack generates a test-pattern bit stream which is sent to the far-end switch and echoed back. The received pattern is then compared to the sent pattern and checked for errors that indicate a loss of integrity on the communications path.

If a test call is running when scheduled maintenance starts, the green LED is turned off. To determine if a test call is still running, use the **list isdn-testcall** and **status isdn-testcall** commands. A lit yellow LED on the Maintenance/Test circuit pack also indicates that a test call is running.

There are two methods available to place an outgoing ISDN-PRI test call.

In the first method, the test call connection is established over the TDM Bus of the transmit and receive sides of the ISDN-PRI trunk to a data channel. This method is selected when no Maintenance/Test circuit pack resides in the system.

In the second method, the test call connection is established over the TDM Bus of the transmit and receive sides of the ISDN-PRI trunk to a digital trunk testing port on the Maintenance/Test circuit pack. The Maintenance/Test Digital Port generates a pseudo bit stream. A pictorial description of the outgoing ISDN-PRI test call connectivity is contained in [Figure 5-30](#).




Figure 5-30. ISDN-PRI Outgoing Test Call

### Synchronous Commands

You can demand a synchronous outgoing test call by using the following maintenance commands:

- **test trunk trunk-group-no/member-no long [repeat number]**
- **test board board-location long [repeat number]**
- **test port port-location long [repeat number]**

Whenever a circuit translates to an ISDN-PRI trunk during a Long Test Sequence, an outgoing test call is invoked. If the B-channel is unrestricted (B8ZS or HDB3) the default duration of the test call is 8.6 seconds. Otherwise, if the B-channel is restricted (ZCS) the default duration of the test call is 9.4 seconds. Once the test call completes, the bit error rate is retrieved from the Maintenance/Test Digital Port. A bit error rate greater than zero is reported as a failure to the Manager I terminal (MGRI). A failure indicates the need to run further diagnostics, such as the **test isdn-testcall** command.

If no Maintenance/Test circuit pack exists, the outgoing ISDN-PRI test call is established over a high speed data channel on the Network Control (NETCON) circuit pack (DATA-BD).

## Asynchronous Commands

You can start, query, and stop an outgoing test call by using the following maintenance commands:

- **test isdn-testcall trunk-group-no/member-no [minutes]**

This command enables you to start an outgoing ISDN-PRI test call for a maximum of two hours (120 minutes).

- **status isdn-testcall trunk-group-no/member-no**

This command displays the progress of the outgoing test call by reporting the bit and block error rates of the tested B-channel specified by the "trunk group no/member no" identifier.

- **clear isdn-testcall trunk-group-no/member-no**

This command enables you to stop an outgoing test call already in progress. The **trunk-group-no/member-no** identifier specifies the B-channel used to stop the test call. The measurements are not cleared until the next test call begins.



### NOTE:

Only one trunk can be tested in a given port network, until the test call is canceled or completes.

Table 5-299. TEST #258 ISDN TEST Call

Error Code	Test Result	Description/ Recommendation
4	ABORT	There is a problem with the Processor Interface Link. 1. Refer to <a href="#">"PKT-INT (Packet Interface)" on page 5-958.</a>
8	ABORT	There is a problem with the DS1 interface circuit pack. 1. Refer to <a href="#">"DS1-BD (DS1 Interface Circuit Pack)" on page 5-548.</a>
1004	ABORT	B channel in use. 1. Determine if a call is active on this DS1 ISDN Trunk via the <b>status trunk</b> 2. When the service state indicates in-service/idle, retry the test.
1005	ABORT	Bad Configuration (that is, no Maintenance/Test circuit pack) Issue the <b>test trunk &lt;trunk Group/trunk member&gt;</b> command and make sure there is a DATA-CHL (NETCON channel) administered.
1018	ABORT	Test call is disabled. 1. Enable Maintenance on the Trunk Group form.

*Continued on next page*

5 Maintenance Objects for DEFINITY ONE  
ISDN-TRK (DS1 ISDN Trunk)

5-745

Table 5-299. TEST #258 ISDN TEST Call — *Continued*

Error Code	Test Result	Description/ Recommendation
1019	ABORT	Another Test call is in progress. <ol style="list-style-type: none"><li>1. Issue the <b>list isdn-testcall</b> command to locate the test call.</li><li>2. Issue the <b>status isdn-testcall</b> command to find out the duration and start time of the test call.</li><li>3. Issue the <b>clear isdn-testcall</b> command to stop the test call from running.</li></ol>
1020	ABORT	There is a problem with DS1 Interface Circuit Pack. <ol style="list-style-type: none"><li>1. Refer to <a href="#">“DS1-BD (DS1 Interface Circuit Pack)” on page 5-548</a>.</li></ol>
1024	ABORT	Maintenance/Test Digital Port in use. <ol style="list-style-type: none"><li>1. Wait until yellow and green LEDs are turned off on the Maintenance/Test circuit pack.</li><li>2. Retry the test.</li></ol>
1113	ABORT	The signaling link has failed. Therefore, the system cannot send any messages on behalf of this trunk. <ol style="list-style-type: none"><li>1. Check the results of Test #255 (Signaling Link State Check Test).</li></ol>
1114	ABORT	The signaling link is in a transitional state. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
1116	ABORT	The switch could not appropriately change the ISDN service state. <ol style="list-style-type: none"><li>1. Determine if a call is active on this DS1 ISDN Trunk (use the <b>status trunk</b></li><li>2. If not, check the Error and Alarm Logs for problems with this ISDN-TRK (DS1 ISDN Trunk) MO.</li></ol>
1117	ABORT	ISDN B-channel maintenance message is already outstanding. <ol style="list-style-type: none"><li>1. Wait two minutes. Then try again.</li></ol>
1118	ABORT	Far-end of ISDN trunk is not administered. <ol style="list-style-type: none"><li>1. Check the administration of the far-end ISDN trunk.</li><li>2. Issue the <b>status trunk</b></li><li>3. Try the test again.</li></ol>
1119	ABORT	The test call was aborted due to a normal call attempt on this trunk. The test call is performed only if the trunk is idle. <ol style="list-style-type: none"><li>1. Either wait for the normal call to terminate normally, or force it to be dropped by using the <b>busyout trunk</b></li></ol>

*Continued on next page*

5 Maintenance Objects for DEFINITY ONE  
ISDN-TRK (DS1 ISDN Trunk)

5-746

Table 5-299. TEST #258 ISDN TEST Call — *Continued*

Error Code	Test Result	Description/ Recommendation
1120	ABORT	The DS1 ISDN Trunk is in the ISDN out-of-service/far-end state. 1. Try to change the service state via Test #256 (Service State Audit Test). Then retry this test. <b>However, the trunk may be in the out-of-service/far-end state due to problems at the far-end switch. If that is the case, no remedial action can be taken at this end.</b>
1122	ABORT	There is no test line number for the far-end switch. 1. Check the Trunk Group Administration form.
1123	ABORT	There is no Feature Access Code administration for this Facility Test. 1. Check the Dial Plan and Feature Administration forms.
None 2012 2000	ABORT	Internal system error 1. Retry the command at 1-minute intervals a maximum of 5 times.
2035	ABORT	The call has timed out, perhaps because of a lack of system resources. 1. Wait 1 minute and try again.
2036 2037	ABORT	Internal system error 1. Follow the recommendation for ABORT code 2012.
2038 2039	ABORT	A problem occurred while trying to read the test data. 1. Wait 1 minute and then try again.
2040	ABORT	Internal system error 1. Follow the recommendations for ABORT code 2012.
2041	ABORT	The call has timed out, perhaps because of a lack of system resources. 1. Follow the recommendations for ABORT code 2035.
2066	ABORT	Could not establish test call. 1. Retry the command at 1-minute intervals a maximum of 5 times.
2067	ABORT	The call has timed out, perhaps because of a lack of system resources. 1. Follow the recommendations for ABORT code 2035.
2074	ABORT	Bit and Block Error query failed. 1. Retry the command at 1-minute intervals a maximum of 5 times. 2. If the test continues to abort, there may be a serious internal problem with Maintenance/Test Digital Port.
2075	ABORT	Internal system error 1. Follow the recommendations for ABORT code 2012.

*Continued on next page*

Table 5-299. TEST #258 ISDN TEST Call — *Continued*

Error Code	Test Result	Description/ Recommendation
2100	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals a maximum of 5 times.
2104	ABORT	Call dropped or could not be originated. 1. Make sure service is provisioned by the network. 2. Check the administration of the far-end test line extension on the trunk group administration form. 3. Check the administration of the test call BCC (Bearer Capability Class) on the trunk group administration form. 4. Check the reason for termination with <b>status isdn-testcall</b> . 5. For further instructions see "Troubleshooting ISDN-PRI Test Call Problems" in Chapter 5, "Routine Maintenance Procedures". 6. Try the test again.
2201 2202 2203 2204 2205	ABORT	Internal system error 1. Follow the recommendations for ABORT code 2012.
2206	ABORT	Could not allocate the necessary system resources to run this test. 1. Follow the recommendations for ABORT code 2100.
2208	ABORT	Internal system error 1. Follow the recommendations for ABORT code 2012.
2209 2210	ABORT	Could not allocate the necessary system resources to run this test. 1. Follow the recommendations for ABORT code 2100.
2211	ABORT	Internal system error 1. Follow the recommendations for ABORT code 2012.
2212	ABORT	Call terminated by unexpected disconnect. 1. Wait 1 minute and then try again.
2213	ABORT	The call has timed-out, perhaps because of a lack of system resources. 1. Follow the recommendations for ABORT code 2035.
2214	ABORT	Call terminated by unexpected disconnect. 1. Wait 1 minute and then try again.

*Continued on next page*

Table 5-299. TEST #258 ISDN TEST Call — *Continued*

Error Code	Test Result	Description/ Recommendation
2215 2216 2217 2218 2219	ABORT	Internal system error 1. Follow recommendations for ABORT code 2012.
2220	ABORT	Call terminated prematurely. 1. Wait 1 minute and try again.
2221 2222 2223 2224 2225 2226	ABORT	Internal system error 1. Follow recommendations for ABORT code 2012.
2227	ABORT	Could not allocate the necessary system resources to run this test. 1. Follow the recommendations for ABORT code 2100.
2042	FAIL	<b>This is the main purpose of the test.</b> The comparison of the data sent with the data received indicates a loss of integrity on the communications path. 1. The trunk should be taken out-of-service and the quality of the DS1 line should be investigated. The investigation should include an in-depth analysis of the DS1 facility including the transmission facility and any external equipment such as DACs, CSUs, etc. If the <b>test isdn-testcall</b> command is invoked, then the investigation should include getting the bit and block error rates by invoking the <b>status isdn-testcall</b> command.
	PASS	The call worked. A test pattern was sent and received properly; the communications path is OK if the synchronous test call command was issued. If the <b>test isdn-testcall</b> command was issued, a PASS indicates that the test call was established. A <b>status isdn-testcall</b> command must be invoked to query the bit and block error rates to determine if the test call passed. An in-depth analysis of the DS1 facility including the transmission facility and any external equipment such as DACs, CSUs, etc., should take place if the bit and block error rates are not acceptable.

## **LGATE-AJ**

---

See [“BRI-SET, ASAI-ADJ, BRI-DAT” on page 5-334](#)

## **LGATE-BD**

---

See [“BRI-BD/LGATE-BD \(ISDN-BRI Line Circuit Pack\)” on page 5-305](#)

## **LGATE-PT**

---

See BRI-PT

## **LOG-SVN (Login Security Violation)**

---

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run <sup>1</sup>	Full Name of MO
LOG-SVN	MAJOR	enable login <login ID>	Login Security Violation

- Where <login ID> is the services login ID for which the security violation was detected. The `Alt Name` field indicates the login ID associated with the security violation and the major alarm.

The Security Violation Notification (SVN) feature provides notification when the number of failed attempts to access the system administration/maintenance interface meets or exceeds customer administered threshold parameters.

A major alarm is logged whenever a security violation is detected involving a services login ID and that login ID has been disabled as a result of the security violation. The capability to disable a login ID following detection of a security violation involving that login ID is administrable on a per login ID basis.

Refer to *DEFINITY Enterprise Communications System Release 8 Administration and Feature Description* (555-230-522) for information on administration required for the Security Violation Notification feature and the option to disable a login ID following detection of a security violation involving the affected login ID.

## Hardware Error Log Entries and Test to Clear Values

---

Table 5-300. Hardware Error Log Entries and Test to Clear Value

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
1-15	None	None	Major	OFF	enable login <login ID>

---

## General Information about log-svn Error Log Entries

---

- a. The number (1 - 15), that appears in the error type field, corresponds to the location the login in the internal login data structure.
- b. The `Alt Name` field on the alarm report indicates the login ID associated with the security violation and major alarm.
- c. These errors/alarms are associated with a number of failed attempts to access the system management/maintenance interface using a services login ID that meet or exceed the customer administered threshold parameters. The associated alarm is immediately raised as a major alarm.
- d. The affected login ID will be disabled as a result of detection of the security violation, unless it is the last enabled INADS type login on the system. The provision to disable a login ID following detection of a security violation involving that login ID is administrable on a login ID basis.
- e. The **enable login** command is used to both enable a login that has been disabled, and to retire any login security violation alarms associated with the login ID.
- f. Use of the **enable login** command to enable a login and/or retire alarms must be executed using a login ID with greater service level hierarchy permissions.
- g. Access to the **enable login** command is controlled through the `Administer Permissions` field on the Command Permission Categories form. This field (Administer Permissions) must be set to **y** to access the enable login command.

- h. The `Port` alarm report field will be set to the port where the final invalid login attempt, involving the alarmed login ID, was detected. Valid port values for the CMC include:
  - MGR1 — Dedicated manager 1 or G3 management terminal connection
  - NET-n — Network controller dial up port
  - INADS — INADS port
  - EPN — EPN maintenance EIA port
  - EIA — Other EIA port
- i. The `Svc State` alarm report field will be set to OUT if the login ID is in the disabled state as a result of detection of a security violation involving the login ID. Once the login ID has been enabled, the field is set to **IN**.
- j. The source or reason of the failed login attempts should be identified and the cause corrected prior to re-enabling a login ID and/or retiring any alarms associated with the login ID. The cause may be something as innocuous as the failure of the services automatic login software, to something as insidious as a hacker attempting to gain access to the switch system management interface.

---

The login ID associated with that alarm is displayed in the `Alt Name` field of the alarm report.

Prior to retiring an SVN alarm and enabling the associated login ID, the **monitor security-violations login** command can be used to access information about the invalid login attempts that caused the security violation. This information can be useful in determining the source of the invalid attempts and analyzing why they occurred.

The **list logins** command provides status information about logins on the system. If a login has been disabled as a result of a security violation, the status will be `svn-disabled`.

## Procedure to Retire an SVN Alarm

To retire a SVN alarm:

1. Enter the command **enable login <login ID>**.

The login ID associated with that alarm is displayed in the `Alt Name` field of the alarm report and the alarm is retired.

## MAPD-BD (MAPD Interface Circuit Pack TN802)

---

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run <sup>1</sup>	Full Name of MO
MAPD-BD	MAJOR	test board UUCSS sh	MAPD Interface Circuit Pack
MAPD-BD	MINOR	test board UUCSS I	MAPD Interface Circuit Pack
MAPD-BD	WARNING	test board UUCSS sh	MAPD Interface Circuit Pack

- 
1. UU is the universal cabinet number (1 for PPN, 2 - 44 for EPNs). C is the carrier designation (A, B, C, D, or E). SS is the number of the slot in which the circuit pack resides (01 to 21).
- 

The TN802 Multiple Application Platform for DEFINITY (MAPD) circuit pack allows sending voice and fax from DEFINITY ECS through the Internet to another DEFINITY also having this feature or to other PBXs that are equipped with the Internet Telephony Server (ITS-E).

Throughout this section the term TN802 means the MAPD IP trunk circuit pack.

Be sure to observe these special considerations for the TN802:

- Port alarms on this circuit pack display as "TIE-DS1" in the Alarm and Error logs.
- The **reset board** command reboots the MAPD PC CPU, but **busyout board** only busys out all of the emulated ports on the board.
- Switch resets that take the switch out of service for more than 20 seconds also cause the MAPD's PC to reboot, which takes several minutes to complete.

### Switch-demanded tests

---

Switch-demanded diagnostic tests on the TN802 do not run unless the Internet trunking application is running on Windows NT<sup>TM</sup>, located on the circuit pack.

## Feature limitations

The Internet trunking application relies on the single call scenario, or a direct, point-to-point call that does not terminate at multiple DEFINITY nodes through call processing. [Table 5-301](#) describes the feature limitations for DEFINITY ECS.

**Table 5-301. DEFINITY ECS IP trunk feature/performance limitations**

Feature/ Performance	Description	Recommendation
Abbreviated Dialing	Abbreviated Dial strings with embedded pauses lose digits after the pause	Most calls work. Do not create Abbreviated dial strings with embedded pauses.
Compression limitations	All IP trunk calls go through A/D conversion, which uses compression to reduce bandwidth. Each compression degrades the voice signal and creates call processing delay.	No more than 3 compression/decompression cycles for any call.   <b>NOTE:</b> The compression/decompression that most voice mail systems use must be counted as 1 cycle.
Call Classifier	IP trunk's compression/decompression cycle makes ringback, busy and voice detection	Do not administer these features: <ul style="list-style-type: none"> <li>■ Call Coverage Redirected Off-Net (CCRON)</li> <li>■ Certain wireless phone coverage</li> </ul>
Call Coverage Call Forwarding Call Transfer	Calls extended across multiple DEFINITY ECS nodes require multiple call paths. Significant voice quality degradation is likely.	Multiple call paths not recommended

*Continued on next page*

Table 5-301. DEFINITY ECS IP trunk feature/performance limitations — *Continued*

Feature/ Performance	Description	Recommendation
Conferencing	Voice quality and delay problems if the party controlling the conference is on the IP trunk (voice paths from external callers come in on the IP trunk, are conferenced, then sent out to other external parties across an IP trunk)	Avoid conference calls where at least two other parties are on the other side of the IP trunk.   <b>NOTE:</b> The following conferences work OK: <ul style="list-style-type: none"> <li>■ Conferences of parties on the local DEFINITY ECS</li> <li>■ Conferences controlled by the local DEFINITY ECS, involving local parties and only 1 party on the other side of an IP trunk</li> </ul>
DCS	Know limitations: <ul style="list-style-type: none"> <li>■ Auto Callback</li> </ul>	Coordinate specific administration and between the IP trunk and DEFINITY ECS for any DCS functionality. Some limitations on routing flexibility may apply.
ISDN	IP trunking has no signalling capability.	ISDN not supported. This includes: <ul style="list-style-type: none"> <li>■ 10-digit number display</li> <li>■ QSIG</li> <li>■ Path replacement</li> </ul>
Voice mail	Calls that have terminated at one location and then cover to a second site for voice mail coverage can have voice quality degradation.	Centralized voice mail through an IP network is not recommended.

## Backing up to the PCMCIA disk

---

[Table 5-302](#) details how to back up administration data for the IP trunk application to and restored from the local PCMCIA disk and the Ethernet port. Before backing up, be sure to shut down the application running on the circuit pack, following the procedures in the [“Shutting down NT on the TN802” on page 5-773](#) section.

**Table 5-302. Backing up TN802 administration data**

Step	Description	Comments
1.	Busyout circuit pack	At the DEFINITY ECS terminal type <b>busyout board UUCSS</b> (the address of the TN802 circuit pack) and press Enter.
2.	Backup administration TN802 to disk	At the Windows NT desktop, double-click on the <b>IP Trunk Backup Restore</b> icon. The IP Trunk Backup/Restore Utility screen appears.
3.	Select utility	In the IP Trunk Backup/Restore Utility dialog screen, click on <b>Files, Backup</b> . The IP Trunk Backup screen appears.
4.	Select backup	In the IP Trunk Backup screen, click on the <b>Backup</b> button
5.	Wait	Backup can take as much as 20 minutes to complete.
6.	Release circuit pack	At the DEFINITY ECS terminal type <b>release board UUCss</b> (the address of the TN802 circuit pack) and press Enter.

### NOTE:

Local restore of a complete system from the PCMCIA disk should not require more than 20 minutes assuming that a replacement MAPD pack is available and pre-loaded with the IP trunk application software.

## Restoring data from the PCMCIA disk

---

### Before you start

1. Shut down the application running on the circuit pack. See [“Shutting down NT on the TN802” on page 5-773](#).
2. Remove the defective IP Trunk circuit pack from the switch (if applicable).
3. Install the replacement IP Trunk circuit pack in the switch (if applicable).
4. Insert the backup diskette into the IP Trunk circuit pack.

Table 5-303. Restore TN802 administration data

Step	Description	Comments
1.	Restore IP Trunk administration	At the Windows NT desktop, double-click on the IP Trunk Back UP Restore icon.  The IP Trunk Backup/Restore Utility screen appears.
2.	Select utility	In the IP Trunk Backup/Restore Utility dialog screen, click <b>Files, Restore</b> .  The IP Trunk Backup screen appears
3.	Select restore	In the IP Trunk Backup screen, click on the <b>Restore</b> button.
4.	Wait	Wait until the yellow Disk-In-Use LED (Note 5 in <a href="#">Figure 5-31</a> ) light is out.

## PSTN fallback feature

---

The Public Switched Telephone Network (PSTN) fallback feature is available on the Internet trunk application software, which periodically pings the remote destinations that the software calls. When the far end returns a poor response time to the ping, DEFINITY's ARS or AAR network routing patterns bypass those ports and direct the call to another port, typically on a PSTN trunk.

When the remote destinations show acceptable response times to subsequent pings, the corresponding ports are returned to "idle," where they are available for service.

## Cabinet configuration

---

Because of overheating, the TN802 circuit pack should not be placed directly above or below another MAPD circuit pack.

## UPS protection

---


Because Windows NT is more vulnerable to damage from a power interruption than the DEFINITY ECS, uninterrupted power supply (UPS) protection is strongly recommended for systems using the TN802 circuit pack.

## Faceplate

---

[Figure 5-31](#) shows the TN802 faceplate.

---



### Figure Notes:

- |   |                                  |
|---|----------------------------------|
| 1. LCD display (see <a href="#">Table 5-304</a> ) | 4. PCMCIA card slot              |
| 2. Reset button (recessed)                        | 5. Yellow PCMCIA disk-in-use LED |
| 3. Red board status LED                           |                                  |

---

Figure 5-31. TN802 faceplate

[Table 5-304](#) lists the TN802 LCD messages that you might see if installing or servicing an IP Trunk.

**Table 5-304. TN802 LCD messages for IP trunks**

Display	Explanation
PC BOOT	The TN802 MAPD PC is booting up.
IP TRK #	IP Trunk application is running (# character blinks)
IML DWN #	Internal error on the IP Trunk. System shuts down and sends an error message to the board.
MSHUT # where both MSHUT and # are blinking	The system is in the process of shutting down due to a front panel button press. DO NOT attempt to remove board.
MSHUT #, where # is blinking	The system has shut down gracefully.

## Support for laptop PCs

Field technicians can access the TN802 circuit pack through:

1. [“pcAnywhere client software”](#)
2. [“Directly-connected keyboard, monitor, and mouse”](#)

### pcAnywhere client software


1. Attach a male-to-male serial cable and a NULL modem connector (if not built into the cable you use) to the COM2 connector (Note 8 in [Figure 5-32](#)) Attach the other end to the serial port of your laptop.
2. Launch the pcAnywhere application.
3. Click on Add Remote Control Item.
4. In the Properties window, choose the communication port to which you connected the cable in Step 1.

- Click on Details and configure the settings ([Table 5-305](#)):

**Table 5-305. Remote connection settings**

Field	Value
Speed	38,400
Parity	None (default)
Flow Control	RTS/CTS
Started by	Carrier detect (DCD)
Ended by	Carrier detect (DCD)

- Click on the new item icon and the laptop connects to the host pCAnywhere application on the TN802 circuit pack.



**Figure Notes:**

- |                               |                            |
|-------------------------------|----------------------------|
| 1. To TN802 cabinet backplane | 5. Mouse                   |
| 2. VGA monitor                | 6. Ethernet                |
| 3. USB (Universal Serial Bus) | 7. 25-pin modem connection |
| 4. Keyboard                   | 8. 25-pin COM2 connection  |

**Figure 5-32. TN802 external cable assembly**

## Directly-connected keyboard, monitor, and mouse



### NOTE:

You need 2 power sources for the monitor and the modem in order to complete this procedure.



### NOTE:

The TN802 circuit pack must be booted with a local mouse and keyboard connected to it for these devices to work.

1. Connect the VGA monitor to the VGA connector of the TN802 external cable.
2. Plug the monitor into an AC power receptacle, and turn it on.
3. Attach the keyboard to the keyboard connector of the TN802 external cable assembly.
4. Attach the mouse to the mouse connector of the TN802 external cable assembly.
5. Insert the circuit pack to cause it to boot.

## Troubleshooting LAN connections

This section contains information for troubleshooting

- [“External connections to the LAN”](#)
- [“Internal connections to the LAN”](#)

### External connections to the LAN

Test the external connections to the LAN by pinging the

- local host
  - external IP trunk server
  - another device connected to the network:
1. Click Start in Windows (lower left hand corner), then select Programs, then Command Prompt.

This starts a DOS command line session.

5 Maintenance Objects for DEFINITY ONE  
MAPD-BD (MAPD Interface Circuit Pack TN802)

5-761

2. At the command prompt, type **ping 127.0.0.1** (the local host default address) and press Enter.

If configured correctly, the system displays:

```
Reply from nnn.nn.nn.nn: bytes=32 time <##ms TTL=###
```

If there is no reply:

- a. Escalate the problem or replace the circuit pack. The problem is not with the external network but within the circuit pack.
3. At the command prompt, type **ping nnn.nn.nn.nn** (the external IP trunk server address) and press Enter.

If configured correctly, the system displays:

```
Reply from nnn.nn.nn.nn: bytes=32 time <##ms TTL=###
```

If there is no reply, verify the IP address and check the physical connections to and from the TN802 circuit pack.

4. At the command prompt, type **ping nnn.nn.nn.nn** (the IP address of another computer on the network) and press Enter.

If configured correctly, the system displays:

```
Reply from nnn.nn.nn.nn: bytes=32 time <##ms TTL=###
```

If there is no reply

- a. Verify the IP address
  - b. Check the physical connections to and from the TN802 circuit pack.
  - c. Check the internal cables on the TN802 circuit pack (Notes 4 and 6 in [Figure 5-34](#)).
  - d. Try pinging another device on the same subnet.
  - e. Try pinging the gateway to the rest of the network from the subnet.
  - f. Try pinging a device not on the local subnet but on the network or another subnet.
5. When finished, at the command prompt type **exit** and press Enter.

## Internal connections to the LAN

Test the internal connections to the LAN by pinging the

- local host
  - internal IP trunk server
  - another device connected to the network:
1. Click Start in Windows (lower left hand corner), then select Programs, then Command Prompt.

This starts a DOS command line session.

2. At the command prompt, type **ping 127.0.0.1** (the local host default address) and press Enter.

If configured correctly, the system displays:

```
Reply from nnn.nn.nn.nn: bytes=32 time <##ms TTL=###
```

If there is no reply:

- a. Check that the internal cables on the TN802 circuit pack (Notes 4 and 6 in [Figure 5-34](#)) have not worked loose.
  - b. Otherwise, replace the circuit pack.
3. At the command prompt, type **ping 10.32.64.97** (the internal IP trunk server address) and press Enter.

If configured correctly, the system displays:

```
Reply from nnn.nn.nn.nn: bytes=32 time <##ms TTL=###
```

If there is no reply:

- a. Check that the internal cables on the TN802 circuit pack (Notes 4 and 6 in [Figure 5-34](#)) have not worked loose.
  - b. Otherwise, replace the circuit pack.
4. At the command prompt, type **ping 10.32.64.96** (the IP address of the internal Motorola MPC860 processor) and press Enter.

If configured correctly, the system displays:


```
Reply from nnn.nn.nn.nn: bytes=32 time <##ms TTL=###
```

If there is no reply:

- a. Check that the internal cables on the TN802 circuit pack (Notes 4 and 6 in [Figure 5-34](#)) have not worked loose.
  - b. Otherwise, replace the circuit pack.
5. Ping the gateway: at the command prompt, type **ping XX.XXX.XXX.XXX** (the IP address of the gateway) and press Enter.
  6. When finished, at the command prompt type **exit** and press Enter.

## Board assembly and cables

[Figure 5-33](#) shows the circuit pack with the two additional boards connected through the side plane.




### Figure Notes:

- |  |   |
|--|---|
| 1. Main TN802 board                    | 4. Side plane   |
| 2. Texas Microsystems Inc. (TMI) board | 5. SCSA (Signal Computing System Architecture) ribbon cable |
| 3. Analogic board                      |   |

Figure 5-33. TN802 board assembly

Figure 5-34 shows a side view of the three boards and interconnecting cables that make up the TN802.




**Figure Notes:**

- |                     |   |
|---------------------|---|
| 1. Main TN802 board | 4. SCSA (Signal Computing System Architecture) ribbon cable |
| 2. Side plane       | 5. Hard drive   |
| 3. Analogic board   | 6. Processor I/O ribbon cable                               |

Figure 5-34. TN802 board assembly and cables (side view)

Figure 5-35 shows the end view of the three boards and interconnecting cables on the TN802.



**Figure Notes:**

- |  |   |
|--|---|
| 1. Analogic board                      | 3. SIMMs (memory) <sup>1</sup>                              |
| 2. Texas Microsystems Inc. (TMI) board | 4. SCSA (Signal Computing System Architecture) ribbon cable |

- 
1. If the board is seated and you hear fast beeping, it means that one of the small boards containing the memory chips is dislodged. Secure the memory board firmly in the receptacle and reseat the circuit pack.
- 

Figure 5-35. TN802 board assembly and cables (end view)

## Replacing the hard disk

---

The TN802 hard drive (Note 5 in [Figure 5-34](#)) is field-replaceable.

Table 5-306. Replacing the TN802 hard drive

---

Step	Description	Comments
1.	Shut down NT	Shut down Windows NT by either method described in the " <a href="#">Shutting down NT on the TN802</a> " section.
2.	Remove the circuit pack	Unlatch the circuit pack and remove it from the carrier.
3.	Remove the hard drive	Remove the 2 screws and lift the hard drive out of its mounting bracket.
4.	Replace the hard drive	Position the new hard drive in the mounting bracket and replace the 2 screws (Step 3).
5.	Replace the circuit pack	Slide the circuit pack into the slot and lock the latching lever.
6.	Wait for initialization	Wait for <ul style="list-style-type: none"><li>■ the circuit pack to reseal (faceplate LEDs light then go out)</li><li>■ Windows NT boots (PC BOOT displays on the faceplate LCD)</li><li>■ IP Trunk application to run (IP TRK # displays on the faceplate LCD)</li></ul>

---

## Error Log Entries and Test to Clear Values

Table 5-307. MAPD (TN802) Error Log entries

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
0 <sup>1</sup>	0	Any	Any	Any	test board UUCSS
1 (a)	0	Circuit pack removed or SAKI Test (#53)	MIN/ WRN <sup>2</sup>	ON	
2 (b)					
18 (c)	0	busyout board UUCSS	WRN	OFF	release board UUCSS
23 (d)	0		WRN	OFF	add ds1 UUCSS
125 (e)	none 3	None	MIN/ WRN <sup>3</sup>	ON	
257	65535	Control Channel Loop Test (#52)	MIN	ON	test board UUCSS I r 20
257 (f)	Any	None			
513 (g)	Any		MIN/ WRN <sup>3</sup>	ON	
514 (h)	46086		MIN/ WRN <sup>3</sup>	ON	
769 (i)	46085		MIN/ WRN <sup>3</sup>	ON	
770 (j)	46096		MIN/ WRN <sup>3</sup>	ON	
1025 (d)	4363	NPE Audit Test (#50)			
1281	Any	Loss of Signal Alarm Inquiry Test (#138)	MIN/ WRN <sup>3</sup>	OFF	test board UUCSS
1537 (k)	46082		MIN/ WRN <sup>3</sup>	ON	
1538 (l)	Any		MIN/ WRN <sup>3</sup>	ON	
1793	Any	Blue Alarm Inquiry Test (#139)	MAJ/ MIN/ WRN <sup>4</sup>	OFF	test board UUCSS
2049	Any	Red Alarm Inquiry Test (#140)	MIN/WR N <sup>3</sup>	OFF	test board UUCSS
2305	Any	Yellow Alarm Inquiry Test (#141)	MIN/ WRN <sup>3</sup>	OFF	test board UUCSS

Continued on next page

Table 5-307. MAPD (TN802) Error Log entries — *Continued*

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
2306	Any	Yellow Alarm Inquiry Test (#141)	MIN/ WRN <sup>3</sup>	OFF	test Board UUCSS
2561	Any	Major Alarm Inquiry Test (#142)	MIN/ WRN <sup>3</sup>	OFF	test board UUCSS
2817		Minor Alarm Inquiry Test (#143)	MIN/ WRN <sup>3</sup>	OFF	test board UUCSS
3073 to 3160 (m)	Any	Slip Alarm Inquiry Test (#144)	MIN/ WRN <sup>3</sup>	OFF	test board UUCSS r 6
3330 (n)	46083		MIN/ WRN <sup>3</sup>	ON	
3585 to 3601 (o)	Any	Misframe Alarm Inquiry Test (#145)	MIN/ WRN <sup>3</sup>	OFF	test board UUCSS r 6
3840 (p)	Any	None			
3841 (q)	4358				
3842 (r)	46097				
3843 (s)	46081				
3999 (t)	Any	None			

*Continued on next page*

1. Run the Short Test Sequence first. If all tests pass, run the appropriate test description and follow the recommendations.
2. If ports are assigned to the circuit pack, then a minor alarm is raised. If no ports are assigned to the circuit pack, then a warning alarm is raised. The alarm is raised after the circuit pack has been missing for a period of 15 minutes. Warning alarms are also raised against any ports administered on the circuit pack.
3. Minor alarms on this MO may be downgraded to warning alarms based on values set in the **set options** command.
4. Major alarms on this MO may be downgraded to minor or warning alarms based on values set in the **set options** command.

Notes:

- a. Error Type 1: indicates that the circuit pack has totally stopped functioning or is not fully administered. The alarm is logged about 15 minutes after the circuit pack has been removed or 11 minutes after the SAKI Test (#53) fails.

To be fully administered, a MAPD circuit pack must meet all of these conditions:

- Have an entry in the circuit plan (**change circuit pack**)
- Be administered (**add ds1 UUCSS**)
- Be physically inserted into the correct slot

If the circuit pack has an entry in the circuit plan and either of the other two conditions are *not* met, a MINOR alarm is logged. To resolve the error, either:

1. Make sure the circuit pack is properly administered and that a functioning MAPD circuit pack is inserted in the correct slot, OR
2. Completely remove the MAPD-BD from the system:
  - a. Shut down NT (see [“Shutting down NT on the TN802”](#))
  - b. Remove any administered DS1 trunks, access endpoints, or PRI endpoints associated with the circuit pack from their respective trunk groups.
  - c. Remove the DS1 (**remove ds1 UUCSS**) and circuit pack (**change circuit pack UUCSS**) administration.

If the circuit pack is properly administered and the red LED is still on, follow the instructions for LED Alarms with Error Type 1 in Chapter 7.

- b. Error Type 2: NT is down and the system attempts to reset the board. If the reset fails, the board is probably bad.
  1. Replace the circuit pack.
- c. Error Type 18: the circuit pack has been busied out.
  1. Release the board (**release board UUCSS**).
- d. Error Type 23 and 1025: the MAPD-BD circuit pack is not completely administered. In addition to insertion, the MAPD circuit pack must have all of the following administration:
  - Have an entry in the circuit plan (**change circuit pack**)
  - Be administered as DS1 (**add ds1 UUCSS**)

The MAPD circuit pack differs from others in that inserting it into the switch backplane is not enough to make the board usable.

- e. Error Type 125, no Aux Data: A wrong circuit pack is inserted in the slot where this circuit pack is logically administered. To resolve this problem, either:
  1. Remove the wrong circuit pack and insert the logically administered circuit pack, OR
  2. Re-administer this slot (**change circuit-pack**) to match the circuit pack inserted.

5 Maintenance Objects for DEFINITY ONE  
MAPD-BD (MAPD Interface Circuit Pack TN802)

5-770

- f. Error Type 257: this error is associated with the Common Port Circuit Pack Maintenance Test. Refer to [“XXX-BD \(Common Port Circuit Pack\)” on page 5-1343](#) for details.
- g. Error Type 513: transient hardware problem.

Aux Data:

- 4352 External RAM failure
- 4353 Internal RAM failure
- 4355 Internal ROM failure

- 1. If the same Error Type/Aux Data value occurs more than once in a 24 hour period, the circuit pack should be replaced. See [“Shutting down NT on the TN802” on page 5-773](#) before removing the circuit pack.

If the MAPD board detects only one of these hardware problems, then the error is resolved when none of these faults are detected for 10 minutes.

- h. Error Type 514: LAN External RAM Error; hardware fault in the PPE external RAM, used for message buffering to and from the Packet Bus. This error should not occur regularly.
  - 1. If this error occurs 10 times within 30 minutes, replace the circuit pack. See [“Shutting down NT on the TN802” on page 5-773](#) before removing the circuit pack.
- i. Error Type 769: Transmit FIFO Underflow (threshold is 3 errors within 10 minutes); the circuit pack cannot find the “end of frame” bit when transmitting a frame to Packet Bus.
  - 1. Clear the alarm using the following command sequence:
    - a. **busyout board UUCSS**
    - b. **reset board UUCSS**
    - c. **test board UUCSS long clear**
    - d. **release board UUCSS**
  - 2. If the error recurs within 10 minutes, replace the circuit pack. See [“Shutting down NT on the TN802” on page 5-773](#) before removing the circuit pack.

- j. Error Type 770: unable to Write LAN Translation RAM (threshold is 2 errors within 10 minutes); a call is aborted because there are no available translation RAM locations for the call connection attempt.
1. Clear the alarm using the following command sequence:
    - a. **busyout board UUCSS**
    - b. **reset board UUCSS**
    - c. **test board UUCSS long clear**
    - d. **release board UUCSS**
  2. If the error recurs within 10 minutes, replace the circuit pack. See [“Shutting down NT on the TN802” on page 5-773](#) before removing the circuit pack.
- k. Error Type 1537: LAN Bus Timeout; the circuit pack transmitted too many bytes on the LAN bus for a single frame. This condition may be caused by:
- an on-board fault
  - faulty data received on one of the circuit pack’s external ports. If any of the ports on this circuit pack are alarmed, refer to the repair procedures for those maintenance objects.

If the error occurs 3 times within 10 minutes, the system raises the board alarm and isolates it from the Packet Bus.

1. Clear the alarm and restore the board to the Packet Bus using the following command sequence:
    - a. **busyout board UUCSS**
    - b. **reset board UUCSS**
    - c. **test board UUCSS long clear**
    - d. **release board UUCSS**
  2. If the problem persists, and there are no PKT-BUS alarms or port alarms, then replace the circuit pack. See [“Shutting down NT on the TN802” on page 5-773](#) before removing the circuit pack.
- l. Error Type 1538: hyperactive circuit pack is out-of-service and may exhibit one or more of the following symptoms:
- The common circuit pack tests (for example, Test #50 and/or Test #52) abort with Error Code 2000.
  - Port tests on this circuit pack return NO-BOARD.
  - A busyout/release of the circuit pack has no affect on test results.
  - A **list configuration** command shows that the circuit pack and ports are properly installed.

The circuit pack is isolated from the system and all trunks or ports on this circuit pack are placed into the out-of-service state. The system attempts to restore the circuit pack within 20-30 minutes. When no faults are detected for 20-30 minutes, the MAPD Interface circuit pack is restored to normal operation and all trunks or ports on the MAPD Interface circuit pack return to the in-service state.

1. If the board is not restored to normal operation, or the error recurs after the board is restored to normal operation, escalate the problem.
- m. Error Type 3073 - 3160: board is reporting slip errors. Aux Data shows the last reported slip count.
- n. Error Type 3330: LAN Critical error; critical failure in the Packet Bus interface to the circuit pack. This failure may be due to an on-board or a Packet Bus fault.
1. If the Packet Bus is alarmed, refer to the [“PKT-BUS \(Packet Bus\)”](#) Maintenance documentation for recommended repair procedures.
  2. If the Packet Bus is not alarmed, clear the alarm and restore the board to the Packet Bus using the following command sequence:
    - a. **busyout board UUCSS**
    - b. **reset board UUCSS**
    - c. **test board UUCSS clear**
    - d. **release board UUCSS**
  3. If the problem persists, and there are no PKT-BUS alarms, then replace the circuit pack. See [“Shutting down NT on the TN802” on page 5-773](#) before removing the circuit pack.
- o. Error Type 3585 - 3601: the board received misframe errors; the Aux Data shows the last reported misframe count.
- p. Error Type 3840: the circuit pack received a bad control channel message from the switch. This error is not service-affecting, and requires no action. The Aux Data describes the following error events:
- |      |                     |
|------|---------------------|
| 4096 | Bad major heading   |
| 4097 | Bad port number     |
| 4098 | Bad data            |
| 4099 | Bad sub-qualifier   |
| 4100 | State inconsistency |
| 4101 | Bad logical link    |
- q. Error Type 3841: the circuit pack detected a transient hardware logic error (for example, program logic inconsistency). This error resolves when no faults are detected for 100 minutes. The value in Aux Data field (4358) indicates the type of hardware problem.

- r. Error Type 3842: Bad Translation RAM Location Found error; the call continues by using another translation location. This error is not service-affecting and requires no action.
- s. Error Type 3843: LAN Receive Parity error; the circuit pack detected an error in a received frame from the Packet Bus. These errors are most likely caused by a Packet Bus problem, but may be due to a circuit pack fault.
  - 1. Determine whether the problem is isolated to this circuit pack or if the problem is caused by Packet Bus faults (see [“PKT-BUS \(Packet Bus\)”](#)).
- t. Error Type 3999: the circuit pack sent a large number of control channel messages to the switch within a short period of time.

Error Type 1538 (hyperactivity) also present?	Then the switch:
Y	Takes the circuit pack out-of-service due to hyperactivity
N	Does not take the circuit pack out-of-service, but the circuit pack has generated 50% of the messages necessary to be considered hyperactive. This may be normal during heavy traffic periods.

### Shutting down NT on the TN802

Before removing the TN802 circuit pack from the carrier, shut Windows NT™ down first by *following either procedure* described in [Table 5-308](#):

Table 5-308. Windows NT shutdown procedures

Step	Faceplate button	PC interface
1.	Push the recessed button on the front faceplate and hold it in.	Click on the “Start” button in the lower, lefthand corner.
2.	“M shut” flashes on the LCD display	Click on “Shut Down.”
3.	When shutdown is complete, “MSHUT #” displays (“#” is blinking).	Choose the “Shut down the computer?” radio button.
4.	Remove the circuit pack.	Click on “OK.”
5.		Wait for the message indicating that shutdown is complete.
6.		Remove the circuit pack.

## System Technician-Demanded Tests: Descriptions and Error Codes

Investigate tests in the order they are presented in [Table 5-309](#). By clearing error codes associated with the NPE Connection Audit Test, for example, you may also clear errors generated from other tests in the testing sequence.

Table 5-309. System Technician-Demanded Tests

Order of Investigation	Apply to TN802 <sup>1</sup>	Short Test Sequence	Long Test Sequence	Reset Board Sequence	D/ND <sup>2</sup>
NPE Connection Audit Test (#50)	Y		X		ND
Control Channel Loop Test (#52)	Y		X		ND
Loss of Signal Alarm Inquiry Test (#138)	N	X	X		ND
Blue Alarm Inquiry Test (#139)	N	X	X		ND
Red Alarm Inquiry Test (#140)	N	X	X		ND
Yellow Alarm Inquiry Test (#141)	N	X	X		ND
Major Alarm Inquiry Test (#142)	N	X	X		ND
Minor Alarm Inquiry Test (#143)	N	X	X		ND
Slip Alarm Inquiry Test (#144)	N	X	X		ND
Misframe Alarm Inquiry Test (#145)	N	X	X		ND
Translation Update Test (#146)	N	X	X		ND
SAKI Sanity Test (#53)	Y			X	D

1. N = No; this test either passes or ABORTS with Error Code 2000 (problem with NT)
2. D = Destructive; ND = Nondestructive

## NPE Connection Audit Test (#50)

The system sends a message to the on-board microprocessor to update the network connectivity translation for the SCOTCH-NPE chip on the circuit pack.

Table 5-310. TEST #50 NPE Connection Audit Test

Error Code	Test Result	Description/ Recommendation
None 2100	ABORT	System resources required for this test are not available. 1. Retry the command at 1-minute intervals a maximum of 5 times.
1019	ABORT	The test aborted because a test was already running on the port. 1. Retry the command at 1-minute intervals for a maximum of 5 times.
	FAIL	Internal system error 1. Retry the command at 1-minute intervals a maximum of 5 times.
	PASS	The circuit pack's SCOTCH-NPE chip has been updated with its translation.
0	NO BOARD	The test could not relate the internal ID to the port (no board). This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted. 1. Ensure that the board translations are correct. Execute the <b>add ds1 UUCSS</b> command to administer the MAPD interface if it is not already administered. 2. If the board was already administered correctly, check the error log to determine whether the board is hyperactive. If this is the case, the board is shut down. Reseating the board re-initializes the board. 3. If the board was found to be correctly inserted in Step 1, then issue the <b>busyout board</b> command. 4. Issue the <b>reset board</b> command. 5. Issue the <b>release busy board</b> command. 6. Issue the <b>test board long</b> command.  This should re-establish the linkage between the internal ID and the port.

## Control Channel Looparound Test (#52)

This test queries the circuit pack for its circuit pack code and vintage and verifies its records.

Table 5-311. TEST #52 Control Channel Looparound Test

Error Code	Test Result	Description/ Recommendation
None 2100	ABORT	System resources required for this test are not available. 1. Retry the command at 1-minute intervals a maximum of 5 times.
	FAIL	The circuit pack failed to return the circuit pack code or vintage. 1. Retry the command a maximum of 5 times. 2. If the problem continues, and if the circuit pack is one of the Port circuit packs, replace the circuit pack. 3. Otherwise, if the circuit pack is part of the SPE, use the procedure described in <i>Replacing SPE Circuit Packs</i> in Chapter 5.
	PASS	Communication with this circuit pack is successful.
0	NO BOARD	The test could not relate the internal ID to the port (no board). This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted. 1. Ensure that the board translations are correct. Execute the <b>add ds1 UUCSS</b> command to administer the MAPD interface if it is not already administered. 2. If the board was already administered correctly, check the error log to determine whether the board is hyperactive. If this is the case, the board is shut down. Reseating the board re-initializes the board. 3. If the board was found to be correctly inserted in step 1, then issue the <b>busyout board</b> command. 4. Issue the <b>reset board</b> command. 5. Issue the <b>release busy board</b> command. 6. Issue the <b>test board long</b> command.  This should re-establish the linkage between the internal ID and the port.

## SAKI Sanity Test (#53)

**This test is destructive.**

This test resets the circuit pack. The test is highly destructive and can only be initiated by a system technician-demanded **reset board UUCSS** command.

Table 5-312. TEST #53 SAKI Sanity Test

Error Code	Test Result	Description/ Recommendation
None	ABORT	System resources required for this test are not available. 1. Retry the <b>reset board</b> command at 1-minute intervals a maximum of 5 times.
1015	ABORT	Port is not out-of-service. 1. Busyout the circuit pack ( <b>busyout board UUCSS</b> ). 2. Execute the <b>reset board</b> command again.
2100	ABORT	System resources required for this test are not available. 1. Retry the <b>reset board</b> command at 1-minute intervals a maximum of 5 times.
1	FAIL	The circuit pack failed to reset.
2	FAIL	The circuit pack failed to restart. 1. Execute the <b>reset board</b> command again. 2. If the problem persists, replace the circuit pack.
	PASS	The circuit pack initializes correctly. 1. Run the Short Test Sequence.
0	NO BOARD	The test could not relate the internal ID to the port (no board). This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted. 1. Ensure that the board translations are correct. Execute the <b>add ds1 UUCSS</b> command to administer the MAPD interface if it is not already administered. 2. If the board was already administered correctly, check the error log to determine whether the board is hyperactive. If this is the case, the board is shut down. Reseating the board re-initializes the board. 3. If the board was found to be correctly inserted in step 1, then issue the <b>busyout board</b> command. 4. Issue the <b>reset board</b> command. 5. Issue the <b>release busy board</b> command. 6. Issue the <b>test board long</b> command.  This should re-establish the linkage between the internal ID and the port.

### Loss of Signal Alarm Inquiry Test (#138)

This test is meaningless for the TN802 MAPD circuit pack. [Table 5-313](#) details the test results.

**Table 5-313. Loss of Signal Inquiry Test (#138) results**

Windows NT up on the TN802?	Then	Cause
Y	Test passes	
Y	Test aborts with ABORT 2000 Error Code.	Windows NT is not communicating with the angel firmware.
N	Test aborts with ABORT 2000 Error Code.	Windows NT down.

### Blue Alarm Inquiry Test (#139)

This test is meaningless for the TN802 MAPD circuit pack. [Table 5-314](#) details the test results.

**Table 5-314. Blue Alarm Inquiry Test (#139) results**

Windows NT up on the TN802?	Then	Cause
Y	Test passes	
Y	Test aborts with ABORT 2000 Error Code.	Windows NT is not communicating with the angel firmware.
N	Test aborts with ABORT 2000 Error Code.	Windows NT down.

### Red Alarm Inquiry Test (#140)

This test is meaningless for the TN802 MAPD circuit pack. [Table 5-315](#) details the test results.

**Table 5-315. Red Alarm Inquiry Test (#140) results**

If Windows NT is up on the TN802	When the switch confirms Red alarm:
Y	Test passes
N	Test aborts with ABORT 2000 Error Code.

### Yellow Alarm Inquiry Test (#141)

This test is meaningless for the TN802 MAPD circuit pack. [Table 5-316](#) details the test results.

**Table 5-316. Yellow Alarm Inquiry Test (#141) results**

If Windows NT is up on the TN802	When the switch confirms Yellow alarm:
Y	Test passes
N	Test aborts with ABORT 2000 Error Code.

### Major Alarm Inquiry Test (#142)

This test is meaningless for the TN802 MAPD circuit pack. [Table 5-317](#) details the test results.

**Table 5-317. Major Alarm Inquiry Test (#142) results**

If Windows NT is up on the TN802	When the switch confirms Major alarm:
Y	Test passes
N	Test aborts with ABORT 2000 Error Code.

### Minor Alarm Inquiry Test (#143)

This test is meaningless for the TN802 MAPD circuit pack. [Table 5-318](#) details the test results.

**Table 5-318. Minor Alarm Inquiry Test (#142) results**

If Windows NT is up on the TN802	When the switch confirms Minor alarm:
Y	Test passes
N	Test aborts with ABORT 2000 Error Code.

## Slip Alarm Inquiry Test (#144)

This test is meaningless for the TN802 MAPD circuit pack. [Table 5-319](#) details the test results.

**NOTE:**

The query for slips always returns a 0 count.

Table 5-319. Slip Alarm Inquiry Test (#144) results

If Windows NT is up on the TN802	When the switch confirms Slip alarm:
Y	Test passes
N	Test aborts with ABORT 2000 Error Code.

## Misframe Alarm Inquiry Test (#145)

This test is meaningless for the TN802 MAPD circuit pack. [Table 5-320](#) details the test results.

**NOTE:**

The query for misframes always returns a 0 count.

Table 5-320. Misframe Alarm Inquiry Test (#145) results

If Windows NT is up on the TN802	When the switch confirms Misframe alarm:
Y	Test passes
N	Test aborts with ABORT 2000 Error Code.

## Translation Update Test (#146)

The Translation Update Test sends the circuit-pack-level information to the MAPD Interface circuit pack. Translation includes the following data administered for a MAPD Interface circuit pack (report from **display ds1 UUCSS** command):

- DS1 Link Length between two DS1 endpoints
- Synchronization Source Control
- All Zero Suppression
- Framing Mode
- Signaling Mode
- Time Slot Number of the 697-Hz tone
- Time Slot Number of the 700-Hz tone

Table 5-321. TEST #146 Translation Update Test

Error Code	Test Result	Description/ Recommendation
	ABORT	Internal system error 1. Retry the command at 1-minute intervals a maximum of 5 times.
	FAIL	Internal system software error. 1. Verify the MAPD Interface circuit pack translation ( <b>display ds1 UUCSS</b> ).
	PASS	Translation data has been downloaded to the MAPD Interface circuit pack successfully.
0	NO BOARD	The test could not relate the internal ID to the port (no board). This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.  1. Ensure that the board translations are correct. Execute the <b>add ds1 UUCSS</b> command to administer the MAPD interface if it is not already administered.  2. If the board was already administered correctly, check the error log to determine whether the board is hyperactive. If this is the case, the board is shut down. Reseating the board re-initializes the board.  3. If the board was found to be correctly inserted in step 1, then issue the <b>busyout board</b> command.  4. Issue the <b>reset board</b> command.  5. Issue the <b>release busy board</b> command.  6. Issue the <b>test board long</b> command.  This should re-establish the linkage between the internal ID and the port.

## MEDPROPT (TN802 MED PRO DSP PORT)

---

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run	Full Name of MO
MEDPROPT	MINOR/WARNING	test port UUCSS or PCSS [short/long] [repeat#]   [clear]	TN802 MED PRO DSP PT

The MEDPROPT maintenance object monitors the health of the MEDPRO digital signal processors (DSPs).

The TN802B MAPD (Multi-Application Platform for DEFINITY) Media Processor circuit pack provides the audio bearer channels for H.323 voice over IP calls. One TN802B circuit pack has one MEDPROPT media processing resource. Based on system administration of audio codecs, a MEDPROPT can handle either 31 or 22 simultaneous channels of H.323 audio processing. If the **ip-parameters** form specifies only G.711 Mulaw or G.711 Alaw as the audio codecs, the MEDPROPT can service 31 channels. If any other codec type (G.723-5.3K, G.723-6.3K, or G.729) is administered, the MEDPROPT can only service 22 channels.

The MEDPROPT is physically made up of 11 individual DSPs, but is treated logically as one port. If individual DSPs on the TN802B MAPD fail, the MEDPROPT remains in-service at lower capacity.

The MEDPROPT is a shared service circuit. It is shared between H.323 trunk channels and H.323 stations. An idle channel is allocated to an H.323 trunk/station on a call-by-call basis.

## Error Log Entries and Test to Clear Values

---

Table 5-322. MEDPROPT Error Log Entries

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
0 <sup>1</sup>	0	Any	Any	Any	test board UUCCSS
1(a)		DSP Capacity Test (#1382)		ON	test board UUCCSS   r5
258(b)		DSP Capacity Test (#1382)	WARNING	ON	test board UUCCSS   r5
515(c)		DSP Capacity Query Test (##1382)	MINOR	ON	test board UUCCSS   r5
18(d)	0	busyout port UUCSS	WARNING	OFF	release port UUCCSS
769	Any	TDM NIC Looparound Test (#1380)	MIN	ON	test port UUCCSS   r10

1. Run the Short Test Sequence first. If all tests pass, run the Long Test Sequence. Refer to the appropriate test description and follow the recommended procedures.

### Notes:

- a. **Error Type 1** - this error type indicates that less than three DSPs are out of service (OOS), and no alarm is raised. The Aux Data field contains the number of DSPs that are Out of Service (OOS).
- b. **Error Type 258** - this error type indicates that more than three, but less than 9 DSPs are out of service (OOS), and a WARNING alarm is raised. The Aux Data field contains the number of DSPs that are Out Of Service (OOS).
- c. **Error Type 515** - this error type indicates that all DSPs are out of service (OOS), and a MINOR alarm is raised. The Aux Data field contains the number of DSPs that are Out Of Service (OOS).
- d. **Error Type 18** - the MEDPRO has been busied out by a **busyout port UUCSS** command.
  1. Release the port (**release port UUCSS**).

**System Technician-Demanded Tests:  
Descriptions and Error Codes**

---

Investigate tests in the order they are presented in [Table 5-323](#). By clearing error codes associated with the *DSP Capacity Query Test*, for example, you may also clear errors generated from the other test in the testing sequence.

**Table 5-323. System Technician-Demanded Tests**

Order of Investigation	Short Test Sequence	Long Test Sequence	Reset Board Sequence	test ds1-loop	D/ND <sup>1</sup>
DSP Capacity Query (#1382)	X	X			ND
TDM NIC Looparound Test (#1380)	X	X			ND

---

1. D = Destructive; ND = Nondestructive

---

**DSP Capacity Query Test (#1382)**

This test is non-destructive

This test polls the circuit pack for the number of failed DSPs. If all DSPs are functional, the test passes and the board is operating at maximum capacity. If any DSPs have failed, the test fails and reports the number of failed DSPs.

A failure of 3 or fewer DSPs does not result in an alarm. A failure of more than 3 up to 8 DSPs results in a warning alarm. A failure of more than 8 DSPs results in a minor alarm. In all cases, except all DSPs failing, the MEDPROPT continues to provide reduced capacity.

**Table 5-324. DSP Capacity Query Test (#1382)**

<b>Error Code</b>	<b>Test Result</b>	<b>Description/ Recommendation</b>
2000	ABORT	Response to the test was not received within the allowable time period.
2100	ABORT	Could not allocate the necessary system resources to run this test.
2500	ABORT	Internal system error 1. Retry the command at 1-minute intervals a maximum of 3 times.
1-11	FAIL	Some DSPs on the circuit pack have failed. The FAIL code is the number of bad DSPs reported.
	PASS	All 11 DSPs are functioning and in-service.
0	NO BOARD	No board was detected by the test. 1. Check the Error Log for wrong board (Error Type 125) or no board (Error Type 131). Resolve either of these issues, if applicable. 2. Check that the board is properly translated and inserted. If so, check for hyperactivity. If hyperactive, use the <b>reset board UUCSS</b> command. 3. Run the test again. If it fails, the circuit pack may be bad. Replace the circuit pack and retest.

**TDM NIC Looparound Test (#1380)****This test is non-destructive**

This test sets up a loopback path from the TDM bus out to the NIC edge of the Media processor and back to the TDM bus. The loopback is established by setting up the outbound IP connection to send IP packets to the MedPro's own IP address. The tone generator places a test tone (440Hz) onto a timeslot. The timeslot is listened to by the Media processor board. The tone is routed through the TAP802 DSP farm, where it may undergo transcoding to G.723, etc. The tone is looped back at the Network interface and back through the TAP802 where it is converted back into standard PCM. The tone is placed onto a TDM timeslot and detected by a tone detector port. The test passes if 440Hz is reported by the tone detector

**Table 5-325. TDM NIC Looparound Test (#1380)**

Error Code	Test Result	Description/ Recommendation
1002	ABORT	<p>The system could not allocate timeslots for the test. The system may be under heavy traffic conditions or it may have timeslots out of service due to TDM-BUS errors.</p> <ol style="list-style-type: none"> <li>1. If system has no TDM-BUS errors and is not handling heavy traffic, retry the command at 1-minute intervals a maximum of 3 times.</li> <li>2. If system has TDM-BUS errors, clear any errors, and retry the command at 1-minute intervals a maximum of 3 times.</li> <li>3. If the command continues to abort, escalate the problem.</li> </ol>
1003	ABORT	<p>The system could not allocate a tone receiver for the test. The system may be oversized for the number of Tone Detectors present or some Tone Detectors may be out of service.</p> <ol style="list-style-type: none"> <li>1. Resolve any TTR-LEV errors. Even if there are no TTR-LEV errors, there may not be a Tone Detector available on the network that contains the circuit pack being tested. Verify that there is at least one Tone Detector on this network. This does not harm the system.</li> <li>2. Resolve any TONE-PT errors.</li> <li>3. If neither condition exists, retry the command at 1-minute intervals a maximum of 3 times.</li> </ol>
2000	ABORT	<p>Response to the test was not received in the allowable time period.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 3 times.</li> </ol>
2100	ABORT	<p>Could not allocate the necessary system resources to run this test.</p>
2500	ABORT	<p>Internal system error.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 3 times.</li> </ol>

*Continued on next page*

Table 5-325. TDM NIC Looparound Test (#1380) — *Continued*

Error Code	Test Result	Description/ Recommendation
2801	ABORT	The TN802B Media Processor board has not been administered on the <b>ip-interfaces</b> form.
ANY	FAIL	<p>The test did not detect the test tone through the looparound connection.</p> <ol style="list-style-type: none"> <li>1. Test the tone-clock in the port network that contains the media processor under test.</li> <li>2. If the tone-clock is healthy, test the media processor board again.</li> <li>3. If the test continues to fail, replace the media processor board.</li> </ol>
	PASS	The board is functioning properly.
0	NO BOARD	<p>No board was detected by the test.</p> <ol style="list-style-type: none"> <li>1. Resolve either wrong board (Error 125) or no board (Error 131) issues, if applicable.</li> <li>2. Check that the board is properly translated and inserted. If so, check for hyperactivity (Error 1538). If hyperactive, use the <b>reset board UUCSS</b> command.</li> <li>3. Run the test again. If it fails, the NCE chip on board may be bad. Replace the board and retest.</li> </ol>

## MEM-BD (Memory)

---

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run	Full Name of MO
MEM-BD	MAJOR	test memory l c	Memory
MEM-BD (a)	WARNING	test memory sh c	Memory
MEMORY (b)	MAJOR	test memory a/b sh c	Memory

### NOTE:

For memory problems on systems with a TN790 RISC processor circuit pack, see "PR-MEM."

### Notes:

- Non-TN790 is on the processor circuit pack and not on a separate memory circuit pack. The maintenance object is "MEMORY" and not "MEM-BD." However, all references to MEM-BD in this section are applicable to "MEMORY" as well.

The Memory contains the DEFINITY software and firmware. The Processor circuit pack is the most critical component of all system operations.

- Non-TN790 systems contain memory that is integrated with the processor. For testing purposes, the circuit pack is logically separated into PR-MAINT, PROCR, and MEMORY. This means that a memory problem on 386 systems requires that the Processor be replaced. 386 systems contain two types of memory: Flash ROM and DRAM. Flash ROM is permanent memory that contains the boot image, PI firmware, and PACCON firmware. This type of memory is not erased during circuit pack resets. It can be reprogrammed only via the **upgrade software** command. DRAM is used for software data storage, and it changes constantly. DRAM loses its value during circuit pack resets. Both types of memory are present on the Processor circuit pack. The diagnostics run appropriate tests on both memories.

For all system activity, the Processor must be able to access the Memory. If the Processor cannot do this, the system goes into SPE-down mode. In SPE-down mode, fatal Memory errors may show up as Processor errors. This merely indicates that the Processor and the Memory are very closely linked as a matter of course.

If the initialization diagnostics fail, refer to the "Procedure for SPE-Down Mode" section in Chapter 4, "Initialization and Recovery".

Memory faults usually indict the Processor circuit pack (TN790) or the CPP1 circuit pack, however the problem may be on the TN786B.

---

## Error Log Entries and Test to Clear Values

---

Table 5-326. MEM-BD (Memory) Memory Error Log Entries

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
0 <sup>1</sup>	0	Any	Any	Any	test memory a/b l r 1
1-256	Any	Read All Memory Test (#85)	MAJOR	ON	test memory a/b l r 5
257-512 (b)	Any	Read All Memory Test (#85)	MAJOR	ON	test memory a/b l r 1
513 (c)	0	Memory Detection/ Test (#87)	MAJOR	ON	test memory a/b r 3
769 (d)	Any	Text Checksum Test (#86)	MAJOR	OFF/ON	test memory a/b l r 2
1025 (e)	Any	Memory Functional Test (#332)	MAJOR	ON	test memory a/b l r 1

1. Run the Short Test Sequence first. If all tests pass, run the Long Test Sequence. Refer to the appropriate test description and follow the recommended procedures.

### Notes:

- a. The “clear” option can replace the “repeat” option in a **test memory** command. For a High or Critical Reliability system, the carrier (a or b) must be specified. In all other systems, there is no need to specify the carrier.
- b. The Read All Memory Test (#85) failed. Refer to the FAIL section of this test. The error is associated with MEM-BD 1.
- c. The Memory Error Detection Test (#87) failed. Refer to the FAIL section of this test. The error is associated with MEM-BD 1.
- d. The Text Checksum Test (#86) failed. Refer to the FAIL section of this test. The error is associated with MEM-BD 1 and is an ON board alarm.
- e. There are Functional Test errors against both the Processor circuit pack and Memory. This test is run only on the Standby SPE in a High or Critical Reliability system. On other systems or on the Active SPE, the test is run only via a [reset system 4](#) command or a [reset system 5](#) command.

## System Technician-Demanded Tests: Descriptions and Error Codes

Always investigate errors in the order in which they are presented in [Table 5-327](#). By clearing error codes associated with the *Read All Memory Test*, for example, you may also clear errors generated from other tests in the testing sequence.

Table 5-327. MEM-BD (Memory) Order of Investigation

Order of Investigation	Short Test Sequence	Long Test Sequence	D/ND <sup>1</sup>
Processor Non-maskable Interrupt Test (#82)(a)	X	X	ND
Processor ROM Checksum Test (#80) (a)	X	X	ND
Processor Software Initiated Interrupt Test (#77) (a)	X	X	ND
Processor Sanity Timer Test (#83) (a)		X	D
MTP Outpulse Relay Test (#102) (b)	X	X	ND
MTP Analog Loop Around Test (#103) (b)	X	X	ND
MTP Sanity Handshake Test (#106) (b)	X	X	ND
MTPSAT Loop Around Test (#228) (b)	X	X	ND
MTP Aux Loop Around Test (#229) (b)	X	X	ND
MTP Reset Test (#101) (b)		X	D
MTP Dual Port Ram Test (#104) (b)		X	D
Read All Memory Test (#85)		X	ND
Memory Error Detection Test (#87)	X	X	ND
Text Checksum Test (#86)		X	ND
Memory Functional Test (#332) (c)		X	D
Memory Board Check Test (#631)	X	X	ND

1. D = Destructive; ND = Nondestructive

### Notes:

- Refer to [“PROCR \(Processor Circuit Pack\)” on page 5-1008](#) for a description of these tests [386 systems only].
- Refer to [“PR-MAINT \(Maintenance Processor\)” on page 5-1000](#) for a description of these tests [386 systems only].
- This test is run only on the Standby SPE in a High or Critical Reliability system. On other systems or on the Active SPE, the test is run only via a [reset system 4](#) command or a [reset system 5](#) command.

## Read All Memory Test (#85)

This test is a nondestructive test. The test reads every memory location in memory and writes it back. A failure of this test indicates a failure in the Processor or Memory circuit pack.

Table 5-328. TEST #85 Read All Memory Test

Error Code	Test Result	Description/Recommendation
1029 2014 2015 2016 2017 2018 2020 2022 2024 2025 2051	ABORT	Refer to STBY-SPE for a description of these error codes.
1	FAIL	<p>If the system can still provide service, this indicates that the Processor circuit pack or Memory has a problem, but can still function. The error code "1" indicates that MEM-BD 1 is failing the test.</p> <ol style="list-style-type: none"> <li>1. Replace the PROCR (Processor circuit pack).</li> </ol> <p><b>⚠ WARNING:</b></p> <p><i>If the Processor circuit pack must be replaced, and if there is a blank in the Expansion Memory circuit pack slot (that is, in the slot immediately to the right of the Processor circuit pack), remove the blank before removing the circuit pack. Otherwise, the circuit pack and/or the two connectors that are used to connect the Expansion Memory circuit pack (if available) might become damaged.</i></p>
	PASS	The Memory is healthy.

## Text Checksum Test (#86)

This test is a nondestructive test. The test computes the checksum of the DEFINITY software text module, and it validates the operation of the flash ROM. A failure of this test indicates corruption of the Text.

Table 5-329. TEST #86 Text Checksum Test

Error Code	Test Result	Description/Recommendation
1029 2014 2015 2016 2017 2018 2020 2022 2024 2025 2051	ABORT	Refer to "STBY-SPE (Standby SPE)" for a description of these error codes.
	FAIL	<p>The system may or may not continue to operate correctly. The system may fail later when some action requires access to the corrupted area of the Text.</p> <ol style="list-style-type: none"><li>2. For a 386 system, the flash ROM should be reprogrammed by</li><li>3. the <b>upgrade software</b> command. The memory card should contain the same vintage software that is currently in the system. Refer to the "Software Upgrade" section in Chapter 5, "Routine Maintenance Procedures".</li></ol>
2058	FAIL	<b>(G3iV1.1-286 system only).</b>
	PASS	The checksum is correct.

### Memory Error Detection Test (#87)

This test is a nondestructive test. This test determines if the parity circuitry is working. Accordingly, the test determines if parity errors can be detected. The parity circuitry is used to detect DRAM memory failures.

## Memory Functional Test (#332)

**This test is destructive.**

This test ensures that every DRAM memory location can be accessed and changed independently. Running this test wipes out all data in DRAM memory. This test is performed during a **reset system 4** or **reset system 5**. If the test fails during a **reset system** command, refer to the “Procedure for SPE-Down Mode” section of Chapter 4, “Initialization and Recovery”, for the recommended maintenance strategy.

Table 5-330. TEST #332 Memory Functional Test

Error Code	Test Result	Description/Recommendation
1000	ABORT	System resources required to run this test are not available. 1. Repeat the command at 1-minute intervals a maximum of three times.
1029 2014 2015 2016 2017 2018 2020 2022 2024 2025 2051	ABORT	Refer to “STBY-SPE (Standby SPE)” for a description of these error codes.
	FAIL	The Standby SPE Memory is defective. 1. Repeat the command at 1-minute intervals a maximum of 5 times. 2. The Processor circuit pack should be replaced.
	PASS	The Standby SPE Memory circuit pack(s) is healthy.

## Memory Board Check Test (#631)

This test always passes.

## MEMORY

---

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run	Full Name of MO
MEMORY	MAJOR	test memory a/b l c	memory

Refer to [“MEM-BD \(Memory\)” on page 5-788](#) for circuit pack level errors.

## MET-BD (MET Line Circuit Pack)

---

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run <sup>1</sup>	Full Name of MO
MET-BD	MIN	test board PCSS sh	MET Line Circuit Pack
MET-BD	WRN	test board PCSS sh	MET Line Circuit Pack

- 
- Where P is the port network number (1); C is the carrier designation (for example, A, B, or C); and SS is the address of the slot in the carrier where the circuit pack is located (for example, 01, 02, ..., etc.).
- 

Refer to [“XXX-BD \(Common Port Circuit Pack\)” on page 5-1343](#) for circuit pack level errors. See also [“MET-LINE \(MET Line\)” on page 5-795](#) for related line information.

## MET-LINE (MET Line)

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run <sup>1</sup>	Full Name of MO
MET-LINE	MINOR	test port PCSSpp l	MET Line
MET-LINE	WARNING	test port PCSSpp sh	MET Line

- Where P is the port network number (1); C is the carrier designation (for example, A, B, or C); SS is the address of the slot in the carrier where the circuit pack is located (for example, 01, 02, ..., etc.); and pp is the 2-digit port number (for example, 01).

Electronic Station is the user-friendly term to denote the MET (Multibutton Electronic Telephone) Station Set. The MET sets were originally introduced for use in earlier PBX systems but can now be used in Generic 1 switches.

The TN735 MET Line circuit pack supports four of these METsets. Each MET set uses three pairs of wires: an analog voice pair, a transmit pair, and a receive pair. Power is sent over the transmit and receive pairs. The MET Line circuit pack supports all 10-, 20-, and 30-button sets.

MET Line interactions are shown in [Figure 5-36](#).




Figure 5-36. MET Line Interactions

The Recall button is used in this system as a self-test button, and, when pressed, lights all of the lamps on the MET set and runs the ringer update.

This section refers only to the MET-LINE maintenance that is performed. Note that MET-LINE maintenance is closely related to, and interacts with, the MET-BD (MET line circuit pack) maintenance in some instances. Some of the results of maintenance testing of the MET line may be affected by the health of the MET Line circuit pack. This interaction should be kept in mind when investigating the cause of reports of MET line problems.

There are instances in this section where service states of a station are mentioned. An explanation of these service states follows:

- **Out-of-Service**—The port (and station) have been removed from service. A busyout of a port causes it to be out-of-service.
- **Ready-for-Service**—Once a port on the circuit pack has been put into service, the voice terminal must communicate that it is present. The time between these two events is the time when the terminal is in the ready-for-service state.
- **In Service**—Once the system receives a message from the voice terminal communicating that it is present, the station is put into the in-service state. The terminal can also be forced into the in-service state if it goes off-hook while it is in the ready-for-service state.

After running the **status station** command, the status is reported as either out-of-service, in-service (as stated in the preceding list), or disconnect (the station is in the ready-for-service state).

## Hardware Error Log Entries and Test to Clear Values

Table 5-331. MET Line Error Log Entries

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
0 <sup>1</sup>	0	Any	Any	Any	test port PCSSpp sh r 1
1 (a)	40987	None			
18 (b)	0	busyout port PCSSpp	WARNING	OFF	release port PCSSpp
130 (c)		None	WARNING	ON	test port PCSSpp sh
257 (d)	40988	None	MIN/WRN <sup>2</sup>	OFF	
513 (e)	40965	Hybrid Line Station Audits Test (#61)	WARNING	OFF	test port PCSSpp sh r 4

*Continued on next page*

Table 5-331. MET Line Error Log Entries — *Continued*

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
769		Port Diagnostic Test (#35)	MIN/WRN <sup>2</sup>	ON	test port PCSSpp l r 3
1025		Hybrid & Conf. Circuits Test (#57)	MIN/WRN <sup>2</sup>	ON	test port PCSSpp l r 3
1537 (f)	40968	None	MIN/WRN <sup>2</sup>	OFF	
1793		TDMNPE Crosstalk Test (#6)	MIN/WRN <sup>2</sup>	ON	test port PCSSpp l r 3
2049(g)	32770				
2049(h)	40967				
3840(i)	40989				

1. Run the Short Test Sequence first. If all tests pass, run the Long Test Sequence. Refer to the appropriate test description and follow the recommended procedures.
2. Major or Minor alarms on this MO may be downgraded to Warning alarms based on the values used in the **set options** command.

## Notes:

- a. Indicates a defective data link. An off-board problem detected by port circuit. Make sure the MET set is connected, and that the EPF test passes. If data transmission problems are experienced, check for defective wiring, check for a defective voice terminal, and move voice terminal closer to the switch (in terms of feet of wire from the jack to the switch). If problem still exists, replace the circuit pack. Once the problem has been resolved, the alarm is retired due to the passing of time.
- b. This error is logged when the port in question is busied out by maintenance personnel. Make sure port is released from busyout.
- c. This error type indicates that the circuit pack has been removed or has been insane for more than 11 minutes. To clear the error, reinsert or replace the circuit pack.
- d. This indicates that the EPF has been turned off due to the overcurrent condition at the voice terminal. Check for defective wiring, check for a damaged jack, and make sure the voice terminal is a MET set. Once the problem has been resolved, the alarm is retired due to the passing of time.

- e. The particular station audit that causes this error type to be produced is the EPF inquiry audit. If the EPF inquiry receives an "epf-no-load" message a certain number of times, this error occurs and, if the EPF inquiry receives an "epf-on-ok" or an "epf-off-ok" message, it contributes to the resolution of this alarm.

This indicates that the voice terminal has probably been disconnected or that there is a problem in the wiring to the terminal. Make sure that the voice terminal is connected or check for defective wiring to the voice terminal.

- f. This indicates that something is wrong with the link to the voice terminal. An in-line maintenance error has generated an off-board Minor alarm. Ignore if there are no complaints. Otherwise, verify that the voice terminal is connected, check for defective wiring, check for a defective voice terminal, and move voice terminal closer to the switch (in terms of feet of wire from the jack to the switch). If the problem still exists, replace the circuit pack.
  - g. This indicates that the station went off-hook while it was in the ready-for-service state. Use the **status system** command to determine the state of the station. The off-hook should have moved the station to ready-for-service. No action is necessary.
  - h. This is the code that is generated when the link between the circuit pack and the voice terminal is successfully reset. No action is necessary.
  - i. An uplink message being logged that the EPF is one with no load on it. No action is necessary.
-

## System Technician-Demanded Tests: Descriptions and Error Codes

---

Always investigate tests in the order presented in the table below when inspecting errors in the system. By clearing error codes associated with the *Port Diagnostic Test*, for example, you may also clear errors generated from other tests in the testing sequence.

Order of Investigation	Short Test Sequence	Long Test Sequence	D/ND <sup>1</sup>
NPE Crosstalk Test (#6)		X	ND
Port Diagnostic Test (#35)		X	ND
MFAT Electronic Power Feed Test (#56)		X	ND
Hybrid Circuit and Conference Circuit Test (#57)		X	ND
Station Lamp Update Test (#60)	X	X	ND
Station Audits Test (#61)	X	X	ND
Ringer Update Test (#62)	X	X	ND

---

1. D = Destructive; ND = Nondestructive

---

**NPE Crosstalk Test (#6)**

One or more NPEs reside on each circuit pack with a TDM Bus interface. The NPE controls port connectivity and gain, and provides conferencing functions on a per port basis. The NPE Crosstalk Test verifies that this port's NPE channel talks on the selected time slot and never crosses over to time slots reserved for other connections. If the NPE is not working correctly, one-way and noisy connections may be observed. This test is part of a port's Long Test Sequence and takes about 20 to 30 seconds to complete.

**Table 5-332. TEST #6 NPE Crosstalk Test**

Error Code	Test Result	Description/ Recommendation
	ABORT	<p>Could not allocate the necessary system resources to run this test.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
1000	ABORT	<p>System resources required to run this test are not available. The port may be busy with a valid call. Use the <b>display port PCSSpp</b> command to determine the station extension, attendant number, or trunk group/member number of the port. Use the <b>status station</b>, <b>status attendant</b>, or <b>status trunk</b> command to determine the service state of the port. (Refer to "<a href="#">status station</a>" on page 4-213 for a description of all possible states.) If the service state indicates that the port is in use, then the port is unavailable for certain tests. You must wait until the port is idle before retesting. Attendants are always in use (off-hook) if the handset is plugged in and the port is not busied out.</p> <ol style="list-style-type: none"> <li>1. If the port status is idle, then retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
1001	ABORT	<p>System resources required to run this test are not available. This could be due to a failure to seize the port.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
1002	ABORT	<p>The system could not allocate time slots for the test. The system may be under heavy traffic conditions or it may have time slots out-of-service due to TDM-BUS errors. Refer to "<a href="#">TDM-BUS (TDM Bus)</a>" on page 5-1116 to diagnose any active TDM-BUS errors.</p> <ol style="list-style-type: none"> <li>1. If system has no TDM-BUS errors and is not handling heavy traffic, repeat test at 1-minute intervals a maximum of 5 times.</li> </ol>

*Continued on next page*

Table 5-332. TEST #6 NPE Crosstalk Test — *Continued*

Error Code	Test Result	Description/ Recommendation
1003	ABORT	<p>The system could not allocate a tone receiver for the test. The system may be oversized for the number of Tone Detectors present or some Tone Detectors may be out-of-service.</p> <ol style="list-style-type: none"> <li>1. Look for TTR-LEV errors in the Error Log. If present, refer to <a href="#">“TTR-LEV (TTR Level)” on page 5-1223</a>.</li> <li>2. Look for TONE-PT errors in the Error Log. If present, refer to <a href="#">“TONE-PT (Tone Generator)” on page 5-1204</a>.</li> <li>3. If neither condition exists, retry the test at 1-minute intervals a maximum of 5 times.</li> </ol>
1004	ABORT	<p>The port was seized by a valid call during the test. The test has been aborted. Use the <b>display port PCSSpp</b> command to determine the station extension, attendant number, or trunk group/member number of the port. Use the <b>status station</b>, <b>status attendant</b>, or <b>status trunk</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. You must wait until the port is idle before retesting. Attendants are always in use (off-hook) if the handset is plugged in and the port is not busied out.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
1018	ABORT	<p>Test disabled via administration. This only applies to analog stations. The default for this field is ‘y,’ so you may want to determine why it has been turned off on this station.</p> <ol style="list-style-type: none"> <li>1. To enable the test for the particular analog station being tested, enter the <b>change station extension</b> command and change the Test field on the Station form from ‘n’ to <b>y</b>.</li> </ol>
2000	ABORT	<p>Response to the test request was not received within the allowable time period.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
2100	ABORT	<p>System resources required to run this test are not available. This could be due to a failure to seize the port.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
2020	ABORT	<p>The test did not run due to an already existing error on the specific port or a more general circuit pack error.</p> <ol style="list-style-type: none"> <li>1. Examine Error Log for existing errors against this port or the circuit pack and attempt to diagnose the already existing error.</li> </ol>

*Continued on next page*

Table 5-332. TEST #6 NPE Crosstalk Test — *Continued*

Error Code	Test Result	Description/ Recommendation
Any	FAIL	<p>This test can fail due to on-board or off-board problems. Off-board problems of concern include EXP-INTF faults, TDM-BUS faults, and faults associated with the tone detectors/tone generators. Clear all off-board problems before replacing the board. Keep in mind that a TDM-BUS problem is usually the result of a faulty board connected to the backplane or bent pins on the backplane.</p> <ol style="list-style-type: none"><li>1. Look for TDM-BUS errors in the error log. If present, refer to <a href="#">“TDM-BUS (TDM Bus)” on page 5-1116</a>.</li><li>2. Look for TONE-BD and/or TONE-PT errors in the error log. If present, refer to the TONE-BD Maintenance documentation and <a href="#">“TONE-PT (Tone Generator)” on page 5-1204</a>.</li><li>3. Test the board when the faults from steps 1 and 2 are cleared. Replace the board only if the test fails.</li></ol>
	PASS	<p>The port is correctly using its allocated time slots. User-reported troubles on this port should be investigated using other port tests and examining station, trunk, or external wiring.</p>
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board). This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"><li>1. Check to ensure that the board translations are correct. Use the <b>list config</b> command, and resolve any problems that are found.</li><li>2. If the board was found to be correctly inserted in step 1, issue the <b>busyout board</b> command.</li><li>3. Issue the <b>reset board</b> command.</li><li>4. Issue the <b>release busy board</b> command.</li><li>5. Issue the <b>test board long</b> command. This should re-establish the linkage between the internal ID and the port. If this is not the case, check to ensure that there is a valid board inserted.</li></ol>

**Port Diagnostic Test (#35)**

This test checks a port's battery feed circuitry. The battery feed circuitry is tested for proper battery voltage by testing the switchhook state. In response to the test message, the on-board firmware terminates the line and checks for switch-hook presence. The termination is then removed, and a check is made for no switch-hook presence. The MET set must be on-hook for the test to execute.

**Table 5-333. TEST #35 Port Diagnostic Test**

Error Code	Test Result	Description/ Recommendation
	ABORT	Internal system error.  1. Retry the command at 1-minute intervals a maximum of 5 times.
1000	ABORT	System resources required to run this test are not available. The port may be busy with a valid call. Use the <b>display port PCSSpp</b> command to determine the station extension, attendant number, or trunk group/member number of the port. Use the <b>status station</b> , <b>status attendant</b> , or <b>status trunk</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. You must wait until the port is idle before retesting. Attendants are always in use (off-hook) if the handset is plugged in and the port is not busied out.  1. If the port status is idle, then retry the command at 1-minute intervals a maximum of 5 times.
1004	ABORT	The port was seized by a valid call during the test. The test has been aborted. Use the <b>display port PCSSpp</b> command to determine the station extension of the port. Use the <b>status station</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. You must wait until the port is idle before retesting.  <b>⇒ NOTE:</b> The battery feed circuitry is tested for proper battery voltage by testing the switchhook state. In response to the test message, the on-board firmware terminates the line and checks for switch-hook presence. The termination is then removed, and a check is made for no switch-hook presence. The MET set must be on-hook for the test to execute.  1. If the port status is idle, then retry the command at 1-minute intervals a maximum of 5 times.
1018	ABORT	Test disabled via software patch.

*Continued on next page*

Table 5-333. TEST #35 Port Diagnostic Test — Continued

Error Code	Test Result	Description/ Recommendation
2000	ABORT	<p>This port may have been busied out by system technician.</p> <ol style="list-style-type: none"><li>1. Look in the Error Log for Error Type 18 (port busied out) for this port. If this error type is present, then release the port via the <b>release station &lt;extension&gt;</b> command and run the test again.</li><li>2. Make sure that the terminal is connected.</li><li>3. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
2100	ABORT	<p>Could not allocate the necessary system resources to run this test. This could be due to a failure to seize the port.</p> <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
	FAIL	<p>Battery Feed Test failed. This port is out-of-service.</p> <ol style="list-style-type: none"><li>1. Other ports on this circuit pack are not affected. Place user on a different port, if available, until a replacement circuit pack can be obtained.</li><li>2. Replace circuit pack when available.</li></ol>
	PASS	<p>Battery Feed Test passed. Current flow is properly detected for this port.</p> <ol style="list-style-type: none"><li>1. If users are reporting problems, examine connections to the port.</li></ol>
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board). This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"><li>1. Check to ensure that the board translations are correct. Use the <b>list config</b> command, and resolve any problems that are found.</li><li>2. If the board was found to be correctly inserted in step 1, issue the <b>busyout board</b> command.</li><li>3. Issue the <b>reset board</b> command.</li><li>4. Issue the <b>release busy board</b> command.</li><li>5. Issue the <b>test board long</b> command. This should re-establish the linkage between the internal ID and the port. If this is not the case, check to ensure that there is a valid board inserted.</li></ol>

**MET Electronic Power Feed (#56)**

In this test, the software requests that the EPF be turned on for a given port. An attempt is made to turn on the power unit to the station. If no current is being drawn, this probably indicates that the station is not connected. If an overcurrent condition is sensed (that is, too much current is being drawn), this may indicate a short in the loop or a defective voice terminal. Depending on what condition is sensed, a message is returned stating that either the EPF was turned on successfully with no problems or that an overcurrent condition is sensed. This test is repeated once more five seconds later. If either test is not successful, the test aborts.

Although this test will never actually return a fail result (except for the internal system error), an error type 257 entry will be made in the error log when the test has completed if the overcurrent case is detected by the hardware.

**Table 5-334. TEST #56 MET Electronic Power Feed Test**

Error Code	Test Result	Description/ Recommendation
	ABORT	The test was aborted due to an internal system error on a software request to the board.  1. Retry the command at 1-minute intervals a maximum of 5 times.
1000	ABORT	System resources required to run this test are not available. The port may be busy with a valid call. Use the <b>display port PCSSpp</b> command to determine the station extension, attendant number, or trunk group/member number of the port. Use the <b>status station</b> , <b>status attendant</b> , or <b>status trunk</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. You must wait until the port is idle before retesting. Attendants are always in use (off-hook) if the handset is plugged in and the port is not busied out.  1. If the port status is idle, then retry the command at 1-minute intervals a maximum of 5 times.
	FAIL	The test failed with an internal error while it was attempting to turn on the EPF.  1. Retry the command at 1-minute intervals a maximum of 5 times.

*Continued on next page*

Table 5-334. TEST #56 MET Electronic Power Feed Test — *Continued*

Error Code	Test Result	Description/ Recommendation
	PASS	<p>EAF Test passed. The message to turn on the power to the station was successfully sent to the port.</p> <ol style="list-style-type: none"><li>1. Although this test never returns a FAIL result, after running this test, the Error Log should be checked for any entries with Error Type 257 to examine the real results of this test.</li><li>2. If Error Type 257 does not appear in the Error Log within 10 seconds after completion of this test, it is safe to assume that the test sensed no problems with the power to the station. To verify that the station is powered up correctly, run a self-test on the station, if available, and check that all the feature buttons are operating.</li><li>3. If Error Type 257 appears in the Error Log, this indicates some problem with the power to the station. The system technician should check for a short in the wiring, a damaged jack, a defective voice terminal, or an incorrect type of terminal.</li></ol>
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board). This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"><li>1. Check to ensure that the board translations are correct. Use the <b>list config</b> command, and resolve any problems that are found.</li><li>2. If the board was found to be correctly inserted in step 1, issue the <b>busyout board</b> command.</li><li>3. Issue the <b>reset board</b> command.</li><li>4. Issue the <b>release busy board</b> command.</li><li>5. Issue the <b>test board long</b> command. This should re-establish the linkage between the internal ID and the port. If this is not the case, check to ensure that there is a valid board inserted.</li></ol>

**MET Circuit and Conference Circuit Test (#57)**

The MET Circuit Test checks the amount of reflection from the MET loop around circuitry and a Conference Test. The Tone-Clock circuit pack places a 1004-Hz tone on a time slot that the port circuit is listening on. A General Purpose Tone Detector (GPTD) is connected to another time slot that the same port circuit is talking on. The on-board microprocessor places the port in the loop around mode and the GPTD measures the level of the reflected signal.

The Conference Test is performed after the Circuit Test. The Conference Circuit Test verifies that the NPE is able to listen to several test tones and correctly conference them together, and the test is executed in two parts. The first half of the test checks the operation of the NPE's first three conference channels. The NPE is put in the loop around mode and instructed to talk on a selected time slot and to listen to the 1004-Hz tone using the first three conference channels. The signal level and noise level of the conferenced output are then measured using a GPTD and checked to verify that they are within an acceptable range.

The second half of the Conference Test checks the operation of the NPE's remaining four conference channels and follows the same procedure as above.

Table 5-335. TEST #57 MET Circuit and Conference Circuit Test

Error Code	Test Result	Description/ Recommendation
	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals a maximum of 5 times.
1000	ABORT	System resources required to run this test are not available. The port may be busy with a valid call. Use the <b>display port PCSSpp</b> command to determine the station extension, attendant number, or trunk group/member number of the port. Use the <b>status station</b> , <b>status attendant</b> , or <b>status trunk</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. You must wait until the port is idle before retesting. Attendants are always in use (off-hook) if the handset is plugged in and the port is not busied out. 1. If the port status is idle, then retry the command at 1-minute intervals a maximum of 5 times.
1001	ABORT	System resources required to run this test were not available. This could be due to a failure to seize the port. 1. Retry the command at 1-minute intervals a maximum of 5 times.

*Continued on next page*

Table 5-335. TEST #57 MET Circuit and Conference Circuit Test — *Continued*

Error Code	Test Result	Description/ Recommendation
1002	ABORT	<p>The system could not allocate time slots for the test. The system may be under heavy traffic conditions or it may have time slots out-of-service due to TDM-BUS errors. Refer to <a href="#">“TDM-BUS (TDM Bus)” on page 5-1116</a> to diagnose any active TDM-BUS errors.</p> <ol style="list-style-type: none"> <li>1. If system has no TDM-BUS errors and is not handling heavy traffic, repeat test at 1-minute intervals a maximum of 5 times.</li> </ol>
1003	ABORT	<p>The system could not allocate a tone receiver for the test. The system may be oversized for the number of Tone Detectors present or some Tone Detectors may be out-of-service.</p> <ol style="list-style-type: none"> <li>1. Look for TTR-LEV errors in the Error Log. If present, refer to <a href="#">“TTR-LEV (TTR Level)” on page 5-1223</a>.</li> <li>2. Look for TONE-PT errors in the Error Log. If present, refer to <a href="#">“TONE-PT (Tone Generator)” on page 5-1204</a>.</li> <li>3. If neither condition exists, retry the test at 1-minute intervals a maximum of 5 times.</li> </ol>
1004	ABORT	<p>The port was seized by a valid call during the test. The test has been aborted. Use the <b>display port PCSSpp</b> command to determine the station extension, attendant number, or trunk group/member number of the port. Use the <b>status station</b>, <b>status attendant</b>, or <b>status trunk</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. You must wait until the port is idle before retesting. Attendants are always in use (off-hook) if the handset is plugged in and the port is not busied out.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
2000	ABORT	<p>Response to the test request was not received within the allowable time period.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
2012	ABORT	Internal System Error.
2103	ABORT	<p>The system could not make the conference connection for the test.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>

*Continued on next page*

Table 5-335. TEST #57 MET Circuit and Conference Circuit Test — *Continued*

Error Code	Test Result	Description/ Recommendation
7	FAIL	<p>The conference circuit test failed. The conference circuit test is performed only if the hybrid test passes. The conference circuit test verifies that the network processing element (NPE) is able to correctly conference several test tones together. The test is executed in two parts. The first half of the test verifies the operation of the NPE's first three conference channels, while the second half verifies the NPE's remaining four conference channels. The test puts the NPE in loop around mode and instructs it to talk on a specified time slot while listening to a 1004 Hz tone, using the conference channels. A GPTD then measures the signal and noise levels of the conferenced output and reports whether or not these are within an acceptable range. The failure may be due to off-board circumstances, the most common of which is an off-hook occurring during the test. It is possible that the port may still be functional from a user's point of view. Also, check the error logs against the GPTD-BD, the TONE-BD, and the TONE-PT.</p> <ol style="list-style-type: none"> <li>1. This error can be caused by a disconnected terminal. First, ensure that the terminal is connected and the wiring is OK.</li> <li>2. Then, issue the <b>display port</b> and the <b>station status</b> commands to determine if the station is idle. If it is idle, issue the <b>test port</b> command for this port.</li> <li>3. If test continues to fail, issue the <b>busyout port</b> and the <b>release port</b> commands, and then retest the port.</li> </ol>
57	FAIL	<p>Hybrid Circuit Test failed. This could result in noisy or bad connections.</p> <ol style="list-style-type: none"> <li>1. Run circuit pack tests to check the Tone Generator circuit pack and the Tone Detector circuit pack, using <b>test board PCSS short</b> command.</li> <li>2. Resolve any problems that are detected on the Tone Generator circuit pack or Tone Detector circuit pack.</li> <li>3. If the Tone Generator and Tone Detector circuit packs are functioning properly, and the test still fails, replace the MET Line circuit pack.</li> </ol> <p> <b>NOTE:</b> If the MET Circuit and Conference Circuit Test fails for all ports on a circuit pack, a -5 volt power problem is indicated.</p>
	PASS	<p>Hybrid Circuit and Conference Circuit Test passed. The hybrid circuitry is transmitting properly.</p> <ol style="list-style-type: none"> <li>1. If complaints still exist, investigate by using other port tests, and by examining the station, wiring, and connections.</li> </ol>

*Continued on next page*

Table 5-335. TEST #57 MET Circuit and Conference Circuit Test — *Continued*

Error Code	Test Result	Description/ Recommendation
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board). This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"> <li>1. Check to ensure that the board translations are correct. Use the <b>list config</b> command, and resolve any problems that are found.</li> <li>2. If the board was found to be correctly inserted in step 1, issue the <b>busyout board</b> command.</li> <li>3. Issue the <b>reset board</b> command.</li> <li>4. Issue the <b>release busy board</b> command.</li> <li>5. Issue the <b>test board long</b> command. This should re-establish the linkage between the internal ID and the port. If this is not the case, check to ensure that there is a valid board inserted.</li> </ol>

**MET Line Station Lamp Updates Test (#60)**

For this test, the software lights the lamps on the terminal based on the status record contained in the processor. The lamp updates run only if the station is in-service.

Table 5-336. TEST #60 MET Line Station Lamp Updates Test

Error Code	Test Result	Description/ Recommendation
1	ABORT	<p>This port may have been busied out by system technician.</p> <ol style="list-style-type: none"> <li>1. Look in the Error Log for Error Type 18 (port busied out) for this port. If this error type is present, then release the port via the <b>release station &lt;extension&gt;</b> command and run the test again.</li> <li>2. Make sure that the terminal is connected.</li> <li>3. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
2	ABORT	<p>Internal System Error.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>

*Continued on next page*

Table 5-336. TEST #60 MET Line Station Lamp Updates Test — *Continued*

Error Code	Test Result	Description/ Recommendation
3	ABORT	Station is in ready-for-service or out-of-service state. This may be due to wiring or an unplugged or defective set. <ol style="list-style-type: none"><li>1. Make sure terminal is connected and the wiring is correct.</li><li>2. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
1000	ABORT	System resources required to run this test are not available. The port may be busy with a valid call. Use the <b>display port PCSSpp</b> command to determine the station extension, attendant number, or trunk group/member number of the port. Use the <b>status station</b> , <b>status attendant</b> , or <b>status trunk</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. You must wait until the port is idle before retesting. Attendants are always in use (off-hook) if the handset is plugged in and the port is not busied out. <ol style="list-style-type: none"><li>1. If the port status is idle, then retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
	FAIL	Internal System Error. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
	PASS	MET Line Station Lamp Updates completed successfully. <ol style="list-style-type: none"><li>1. If complaints still exist, investigate by using other circuit pack tests, and by examining the station, wiring, and connections.</li></ol>
0	NO BOARD	The test could not relate the internal ID to the port (no board). This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted. <ol style="list-style-type: none"><li>1. Check to ensure that the board translations are correct. Use the <b>list config</b> command, and resolve any problems that are found.</li><li>2. If the board was found to be correctly inserted in step 1, issue the <b>busyout board</b> command.</li><li>3. Issue the <b>reset board</b> command.</li><li>4. Issue the <b>release busy board</b> command.</li><li>5. Issue the <b>test board long</b> command. This should re-establish the linkage between the internal ID and the port. If this is not the case, check to ensure that there is a valid board inserted.</li></ol>

**MET Line Station Audits Test (#61)**

This is a series of three tests that are classified as audits. These audits abort if attempted on an out-of-service station. The tests are as follows:

- Switchhook Audit—This is an update of the SPE records according to the circuit packs' records.
- Bad Scan Inquiry—A message is sent uplink that contains a count that is generated due to certain events relating to the link conditions. This is an indication of data transmission problems between the MET Line circuit pack and the voice terminal.
- EPF Inquiry—The status of the EPF is sent uplink. Possible conditions are: EPF-on-ok, EPF-off, EPF-no-load, and EPF-on-overcurrent.

Although this test will never actually return a fail result (except for the internal system error), it is possible that it will enter error types 257 (over current) or 513 (open circuit) into the error log. To determine if there are any problems that do not show up in the test result, look for these error types in the error log. If these errors appear in the error log or if user complaints still exist, investigate by using other circuit pack tests and by examining the station, the wiring, and the connections.

Table 5-337. TEST #61 MET Line Station Audits Test

Error Code	Test Result	Description/ Recommendation
1	ABORT	Internal System Error.
2	ABORT	The test was aborted due to an internal system error during the switchhook audit.
3		The test was aborted due to an internal system error during the bad scan inquiry.
		The test was aborted due to an internal system error during the EPF audit inquiry. <ol style="list-style-type: none"> <li>1. Make sure that the station is not in an out-of-service state.</li> <li>2. Retry the command at 1-minute intervals for a maximum of 5 times.</li> </ol>
1000	ABORT	System resources required to run this test are not available. The port may be busy with a valid call. Use the <b>display port PCSSpp</b> command to determine the station extension, attendant number, or trunk group/member number of the port. Use the <b>status station</b> , <b>status attendant</b> , or <b>status trunk</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. You must wait until the port is idle before retesting. Attendants are always in use (off-hook) if the handset is plugged in and the port is not busied out. <ol style="list-style-type: none"> <li>1. If the port status is idle, then retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>

Table 5-337. TEST #61 MET Line Station Audits Test — *Continued*

Error Code	Test Result	Description/ Recommendation
1004	ABORT	<p>The port was seized by a valid call during the test. The test has been aborted. Use the <b>display port PCSSpp</b> command to determine the station extension, attendant number, or trunk group/member number of the port. Use the <b>status station</b>, <b>status attendant</b>, or <b>status trunk</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. You must wait until the port is idle before retesting. Attendants are always in use (off-hook) if the handset is plugged in and the port is not busied out.</p> <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
2000	ABORT	<p>Response to the test request was not received within the allowable time period.</p> <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
	FAIL	<p>The test failed due to an internal system error.</p> <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
	PASS	<p>Hybrid Line Station Audits passed.</p> <ol style="list-style-type: none"><li>1. Although this test always returns a PASS result, it may enter Error Types 257 or 513 into the Error Log. To determine if there are any problems that don't show up in the test result, look for these error types in the Error Log.</li><li>2. If these errors appear in the Error Log, or if user complaints still exist, investigate by using other circuit pack tests, and by examining the station, wiring, and connections.</li></ol>
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board). This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"><li>1. Check to ensure that the board translations are correct. Use the <b>list config</b> command, and resolve any problems that are found.</li><li>2. If the board was found to be correctly inserted in step 1, issue the <b>busyout board</b> command.</li><li>3. Issue the <b>reset board</b> command.</li><li>4. Issue the <b>release busy board</b> command.</li><li>5. Issue the <b>test board long</b> command. This should re-establish the linkage between the internal ID and the port. If this is not the case, check to ensure that there is a valid board inserted.</li></ol>

**MET Line Ringer Update Test (#62)**

In this update, a "ringer on" or a "ringer off" message is sent to the firmware to start and stop the ringer on the set.

Table 5-338. TEST #62 MET Line Ringer Update Test

Error Code	Test Result	Description/ Recommendation
3	ABORT	<p>This port may have been busied out by system technician.</p> <ol style="list-style-type: none"> <li>1. Look in the Error Log for Error Type 18 (port busied out) for this port. If this error type is present, then release the port via the <b>release station &lt;extension&gt;</b> command and run the test again.</li> <li>2. Make sure that the terminal is connected.</li> <li>3. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
1000	ABORT	<p>System resources required to run this test are not available. The port may be busy with a valid call. Use the <b>display port PCSSpp</b> command to determine the station extension, attendant number, or trunk group/member number of the port. Use the <b>status station</b>, <b>status attendant</b>, or <b>status trunk</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. You must wait until the port is idle before retesting. Attendants are always in use (off-hook) if the handset is plugged in and the port is not busied out.</p> <ol style="list-style-type: none"> <li>1. If the port status is idle, then retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
	FAIL	<p>Internal System Error.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
	PASS	<p>Hybrid Station Ringer Update passed.</p> <ol style="list-style-type: none"> <li>1. If complaints still exist, investigate using other circuit pack tests, and by examining the terminal, wiring, and connections.</li> </ol>
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board). This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"> <li>1. Check to ensure that the board translations are correct. Use the <b>list config</b> command, and resolve any problems that are found.</li> <li>2. If the board was found to be correctly inserted in step 1, issue the <b>busyout board</b> command.</li> <li>3. Issue the <b>reset board</b> command.</li> <li>4. Issue the <b>release busy board</b> command.</li> <li>5. Issue the <b>test board long</b> command. This should re-establish the linkage between the internal ID and the port. If this is not the case, check to ensure that there is a valid board inserted.</li> </ol>

## MIS (Management Information System)

---

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run	Full Name of MO
MIS	WRN	release mis	Management Information System

The Management Information System (MIS)/Call Management System (CMS) MO is used only for administering MIS translations, such as trunks and stations. There are no hardware failures associated with this MO.

**NOTE:**

To diagnose MIS link hardware errors and alarms, see PKT-INT (Packet Interface).

The MIS/CMS is an adjunct processor that collects ACD data sent from the system. To change MIS translations, a system administrator must first enter a **busyout mis** command at the terminal. When the MIS is busied out, the system stops sending ACD data to the MIS, and a Warning alarm is raised. When finished, a **release mis** command should be entered at the terminal. This clears the Warning alarm and allows the switch to send ACD data to the MIS.

### Error Log Entries and Test to Clear Values

---

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
0 <sup>1</sup>	0	Any	Any	Any	release mis
18(a)	0	busyout mis	WARNING	ON	release mis

1. Run the Short Test Sequence first. If all tests pass, run the Long Test Sequence. Refer to the appropriate test description and follow the recommended procedures.

**Note:**

- a. When the **busyout MIS** command is issued, no data is sent to the MIS/CMS regardless of the link state. To allow data to be sent to MIS/CMS, a **release mis** command must be issued from the terminal.
-

**MMI Synchronization Status Test (#1122 and 1123)**

This test is non-destructive. To support applications involving multiple MMI circuit packs, the appropriate MMI circuit packs must be synchronized with one another. One such circuit pack is designated as the master sync source, which provides the synchronization signal onto the TDM bus. The other MMI circuit packs in the system listen to this signal.

This test monitors this synchronization state. The test fails if the MMI circuit pack is not in sync. The test passes with auxiliary code 1100 if the MMI circuit pack is in sync and is providing the synchronization signal for the system. The test also passes with an auxiliary code of 1101 if the MMI circuit pack is in sync and listening to the sync signal. MMI circuit packs do not lose the synchronization signal unless an MMI circuit pack is either pulled out of the system or reset by using a technician command.

Test #1122 runs when the **long** option of the **test board** command is entered, initiating the recovery of synchronization. Test #1123 runs when the **short** option of the **test board** command is entered, giving the status of the synchronization. You need not necessarily run the **long** option since synchronization signal recovery should be taking place within software running in the background. Use the **long** option only if synchronization is not established within 5 minutes of investigating the problem.

**Table 5-339. TEST #1122/1123 MMI Synchronization Status Test**

Error Code	Test Result	Description/Recommendation
	ABORT	Internal system error. This is an abnormal abort.  1. Retry the command at 1-minute intervals a maximum of 5 times.
2000	ABORT	A response to the test was not received from the MMI circuit pack within the allowable time period.  1. If this result occurs repeatedly and the MMI circuit pack is idle, reset the circuit pack using <b>busyout board PCSS</b> , then <b>reset board PCSS</b> , followed by <b>release board PCSS</b> .  2. Rerun the test; if the same result occurs again, replace the MMI circuit pack.
2012	ABORT	Internal system error
2100	ABORT	Could not allocate the necessary resources to run this test. This is an abnormal abort.  1. Retry the command at 1-minute intervals a maximum of 5 times.

*Continued on next page*

Table 5-339. TEST #1122/1123 MMI Synchronization Status Test — *Continued*

Error Code	Test Result	Description/Recommendation
	FAIL	The MMI circuit pack is out of MMI synchronization. Run the <b>long</b> option of the <b>test board</b> command. <ol style="list-style-type: none"><li>1. Wait up to 5 minutes, and then reset the circuit pack with these commands: <b>busyout board PCSS</b>, then <b>reset board PCSS</b>, followed by <b>release board PCSS</b>.</li><li>2. Rerun the test; if the same result occurs again, replace the circuit pack.</li></ol>
1100	PASS	The MMI circuit pack is providing the synchronization correctly. This MMI circuit pack is designated as the Master Sync source.
1101	PASS	The MMI circuit pack is listening to the synchronization signal correctly.

### Control Channel Looparound Test (#52)

Refer to the repair procedure in [“Control Channel Looparound Test \(#52\)” on page 5-560](#).

### SAKI Sanity Test (#53)

Refer to the repair procedure in [“SAKI Sanity Test \(#53\)” on page 5-1245](#).

## MMI-BD

---

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run <sup>1</sup>	Full Name of MO
MMI-BD	MAJOR	test board PCSS l r#	Multimedia Interface Circuit Pack
MMI-BD	MINOR	test board PCSS l r#	Multimedia Interface Circuit Pack
MMI-BD <sup>2</sup>	WARNING	test board PCSS s r#	Multimedia Interface Circuit Pack

- Where P is the port network number (1 for PPN and 2 or 3 for EPN); C is the carrier designation (for example, A, B, C, or D); and SS is the address of the slot in the carrier where the circuit pack is located (for example, 01, 02, ..., and so forth).
- Refer to [“XXX-BD \(Common Port Circuit Pack\)” on page 5-1343](#).

Two circuit packs can be used for multimedia connections:

- [“TN787D \(or later\)”](#)
- [“TN2207 and the Expansion Services Module”](#)

### TN787D (or later)

The Multimedia Interface Circuit Pack (TN787D or later), also called the MMI pack, provides a number of H.221 protocol terminations for bit streams received from the TDM bus. The Multimedia Interface demultiplexes the H.221 bit stream (audio, video, data, control, and indication signals) and transmits the bit streams onto the TDM bus so that the appropriate circuit packs can process them.

Other resources on the MMI pack are:

- 32 ports
- 4 digital signal processors that manage the 32 resources




#### NOTE:

Refer to “Troubleshooting MMCH” in Chapter 5, “Routine Maintenance Procedures” in *DEFINITY Enterprise Communications Server Release 8.2 Maintenance for R8.2si* (555-233-123) for MMCH troubleshooting information.

## TN2207 and the Expansion Services Module

The TN2207 circuit pack permits connecting an Expansion Services Module (ESM) shown in [Figure 5-37](#).

- Provides T.120 data sharing capability on a MMCH multipoint H.320 video conference
- Each conference participant must have endpoints administered and a personal computer with the H.320 video application installed.
- The DEFINITY ECS must have the ESM installed. See the “status ism” command in Chapter 8, “Maintenance Commands and Trouble-Clearing Aids” in DEFINITY Enterprise Communications Server Release 8.2 Maintenance for R8.2si (555-233-123).




### Figure Notes

1. Port B Y-cable connector to a TN787 Multimedia Interface (MMI) circuit pack
2. Port A Y-cable connector to a TN2207 PRI circuit pack
3. 25-pair Y-cable
4. 356A adapter
5. D8W cord connected to 356A adapter port 1
6. Expansion Service Module (ESM)
7. Port B on compatible primary rate interface (PRI) card

Figure 5-37. Typical ESM connections

### ⚠ CAUTION:

*The TN2207 circuit pack is the only pack allowing connection of an ESM to the DEFINITY ECS switch.*



cydfmmi PDH 112596

Figure 5-38. TN787 Multimedia Interface (MMI) Circuit Pack

## Error Log Entries and Test to Clear Values

Table 5-340. MMI-BD Error Log Entries

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
0 <sup>1</sup>	0	Any	Any	Any	test board PCSS sh r 1
1 (a)	Any	None	MIN	ON	
18 (b)	0	Busyout board PCSS	WNG	OFF	release board PCSS
217 (c)	0	None	WNG	ON	
257 (d)	65535	Control Channel Loop Test (#52)	MIN	ON	test board PCSS r 3
513 (e)	4352 to 4357	Uplink error from pack			
769 (f)	Any	MMI Synchronization Status Test (#1123)	None		
1281 (g)	Any	Circuit Pack Restart Test (#594)	MAJ	ON	
1538 (h)	Any	Software detected error	MIN	ON	
1793 (i)	ANY	TSI XTalk (#6)	MIN	ON	test board PCSS l r 3
2049 (j)	Any	TSI Loop (#1108)	MAJ	ON	test board PCSS l r 3

1. Run the short test sequence first. If all tests pass, run the long test sequence. Refer to the appropriate test description and follow the recommended procedures.

### Notes:

- a. The circuit pack stopped functioning or it was physically removed from the system. The alarm logs approximately 11 minutes after the circuit pack has been removed and/or the SAKI Sanity Test (#53) fails.

If the circuit pack is in the system and the red LED is on, follow the instructions for a red alarm in "Control and port circuit pack status LEDs" in Chapter 7, "LED Interpretation". Also, see "Handling Common Port Circuit Packs" in *DEFINITY Enterprise Communications Server Release 8.2 Maintenance for R8.2si* (555-233-123).

- b. This circuit pack has been busied out using the [busyout board PCSS](#) command.
- c. There are more than four MMI circuit packs in the system. Remove the circuit pack that generated the error in the error log by locating the slot indicated by the error.

- d. Indicates transient communication problems between the switch and this circuit pack. Execute the [test board PCSS](#) command and refer to the repair procedures for the Control Channel Looparound Test (#52) in [“XXX-BD \(Common Port Circuit Pack\)” on page 5-1343](#).
- e. The circuit pack detected an Angel on-board hardware failure. The reported aux data values correspond to the following detected errors:

- 4352 - External RAM error
- 4253 - Internal RAM error
- 4355 - ROM Checksum error
- 4357 - Instruction set error

Reset the circuit pack by using the [busyout board PCSS](#), [reset board PCSS](#), and [release board PCSS](#) commands. When reset, the circuit pack executes a set of tests to detect the presence of any of the above faults. The detection of one these errors during initialization causes the circuit pack to lock up and appear insane to the system. See the repair procedures in note b for Error Type 1.

- f. This MMI circuit pack reported a loss of MMI synchronization. Refer to Test (#1123) for repair procedures.
  - g. A failure of the time slot interchanger has been detected. Reset the circuit pack using the [busyout board PCSS](#), [reset board PCSS](#), and [release board PCSS](#) commands. If the reset passes, then the on-board circuitry is healthy. Retire the alarm using the [test board PCSS long clear](#) command followed by [release board PCSS](#).
  - h. The circuit pack is hyperactive; that is, it is flooding the switch with messages sent over the control channel. The circuit pack is taken out of service when a threshold number of these errors is reported to the switch. Clear the alarm using the following commands: [busyout board PCSS](#), [reset board PCSS](#), [test board PCSS long clear](#), [release board PCSS](#). If the error recurs within 10 minutes, replace the circuit pack.
  - i. The TSI Cross Talk Test (#6) failed. See the description of this test and follow the repair procedures.
  - j. The TSI Looparound Test (#1108) failed. See the description of this test and follow the repair procedures.
-

## System Technician-Demanded Tests: Descriptions and Error Code

---

Always investigate tests in the order presented in the table below when inspecting errors in the system. By clearing error codes associated with the TSI Crosstalk Test (#6), for example, you may also clear errors generated from other tests in the testing sequence.

Table 5-341. System Technician-Demanded Tests: MMI-BD

Order of Investigation	Short Test Sequence	Long Test Sequence	Reset Board Sequence	D/ND <sup>1</sup>
TSI Crosstalk (#6)		X		ND
TSI Looparound Test (#1108)		X		ND
MMI SYNC Status Test (#1123)	X			ND
MMI SYNC Status Test (#1122)		X		ND
Control Channel Looparound Test (#52) <sup>2</sup>	X	X		ND
SAKI Sanity Test (#53) <sup>b</sup>			X	D

---

1. D = Destructive, ND = Non-destructive

2. Refer to the repair procedure described in [“XXX-BD \(Common Port Circuit Pack\)” on page 5-1343](#) for a description of this test.

---

### TSI Crosstalk Test (#6)

This test is non-destructive.

The Time Slot Interchanger (TSI) chip controls connectivity to the TDM bus. The TSI Cross Talk Test verifies that this TSI talks on the selected TDM bus time slot and never crosses over to time slots reserved for other connections. If the TSI is not working correctly, one-way and noisy connections may occur. If the test passes, then the TSI is able to communicate over the TDM bus. This test is part of the circuit pack's demand and scheduled long test sequence, and takes approximately 20 to 30 seconds to complete.

Table 5-342. TEST #6 TSI Crosstalk Test

Error Code	Test Result	Description/Recommendation
	ABORT	Internal system error. This is an abnormal abort. 1. Retry the command at 1-minute intervals a maximum of 5 times.
1002	ABORT	The system could not allocate time slots for the test, the traffic load on the system is very high, or the time slots are out-of-service due to TDM-BUS errors. Refer to " <a href="#">TDM-BUS (TDM Bus)</a> " on page 5-1116 to diagnose any active TDM Bus errors. 1. If the system has no TDM-BUS errors and is not handling heavy traffic, repeat the test at 1-minute intervals a maximum of 5 times.
1003	ABORT	The system could not allocate a tone detector for the test. The system is oversized for the number of tone detectors present, or some tone detectors are out-of-service. 1. Resolve any "TTR-LEV" errors in the Error Log. See " <a href="#">TTR-LEV (TTR Level)</a> " on page 5-1223. 2. Resolve any "TONE-PT" errors in the Error Log. See " <a href="#">TONE-PT (Tone Generator)</a> " on page 5-1204. 3. If neither condition exists, retry the test at 1-minute intervals a maximum of 5 times.
2000	ABORT	Response to the test was not received from the MMI-BD circuit pack within the allowable time period. 1. If this result occurs repeatedly, attempt to reset the circuit pack if the other ports are not in use. Reset the circuit pack by issuing the <a href="#">busyout board PCSS</a> , <a href="#">reset board PCSS</a> , followed by the <a href="#">release board PCSS</a> commands. 2. If this result occurs again, replace the circuit pack.
2012	ABORT	Internal system error. This is an abnormal abort.
2100	ABORT	Could not allocate the necessary resources to run this test. This is an abnormal abort. 1. Retry the command at 1-minute intervals a maximum of 5 times.
	FAIL	The TSI was found to be transmitting in error. This causes noisy and unreliable connections. 1. Replace the circuit pack.
	PASS	The TSI is correctly using its allocated time slots.

**TSI Looparound Test (#1108)**

This test is non-destructive.

During this test, the MMI's Time Slot Interchanger (TSI) listens to a TDM timeslot. A digital count tone loops back in the TSI and onto another TDM timeslot without passing through any resource hardware. A tone detector port verifies the looped data. If the digital count is correct, then the test passes. The test is done for both TDM buses. Failures indicate that the TSI is unreliable.

**Table 5-343. TEST #1108 TSI Looparound Test**

Error Code	Test Result	Description/Recommendation
	ABORT	Internal system error. This is an abnormal abort.  1. Retry the command at 1-minute intervals a maximum of 5 times.
1002	ABORT	The system could not allocate time slots for the test. Either the traffic load on the system is very high or time slots is out-of-service due to TDM-BUS errors. Refer to <a href="#">"TDM-BUS (TDM Bus)" on page 5-1116</a> to diagnose any active TDM Bus errors.  1. If the system has no TDM-BUS errors and is not handling heavy traffic, repeat the test at 1-minute intervals a maximum of 5 times.
1003	ABORT	The system could not allocate a tone detector for the test. The system may be oversized for the number of Tone Detectors present, or some Tone Detectors may be out-of-service.  1. Resolve any "TTR-LEV" errors in the Error Log. See <a href="#">"TTR-LEV (TTR Level)" on page 5-1223</a> .  2. Resolve any "TONE-PT" errors in the Error Log. See <a href="#">"TONE-PT (Tone Generator)" on page 5-1204</a> .  3. If neither condition exists, retry the test at 1-minute intervals a maximum of 5 times.
2000	ABORT	Response to the test was not received from the Tone Detector circuit pack within the allowable time period.  1. If this result occurs repeatedly, attempt to reset the circuit pack (if the other ports are not in use). Reset the circuit pack by issuing the <a href="#">busyout board PCSSpp</a> and the <a href="#">reset board PCSSpp</a> commands followed by the <a href="#">release board PCSS</a> command.  2. If this result occurs again, replace the circuit pack.
2012	ABORT	Internal system error. This is an abnormal abort.
2100	ABORT	Could not allocate the necessary resources to run this test. This is an abnormal abort.  1. Retry the command at 1-minute intervals a maximum of 5 times.

*Continued on next page*

Table 5-343. TEST #1108 TSI Looparound Test — *Continued*

Error Code	Test Result	Description/Recommendation
	FAIL	The TSI was found to be transmitting in error, causing noisy and unreliable connections. <ol style="list-style-type: none"><li>1. Replace the circuit pack.</li></ol>
	PASS	The TSI is correctly using its allocated time slots.

## MMI Synchronization Status Test (#1122 and 1123)

This test is non-destructive.

To support applications involving multiple MMI circuit packs, the appropriate MMI circuit packs must be synchronized with one another. One such circuit pack is designated as the master sync source, which provides the synchronization signal onto the TDM bus. The other MMI circuit packs in the system listen to this signal.

This test monitors this synchronization state. The test fails if the MMI circuit pack is not in sync. The test passes with auxiliary code 1100 if the MMI circuit pack is in sync and is providing the synchronization signal for the system. The test also passes with an auxiliary code of 1101 if the MMI circuit pack is in sync and listening to the sync signal. MMI circuit packs do not lose the synchronization signal unless an MMI circuit pack is either pulled out of the system or reset by using a technician command.

Test #1122 runs when the **long** option of the [test board](#) command is entered, initiating the recovery of synchronization. Test #1123 runs when the **short** option of the [test board](#) command is entered, giving the status of the synchronization. You need not necessarily run the **long** option since synchronization signal recovery should be taking place within software running in the background. Use the **long** option only if synchronization is not established within 5 minutes of investigating the problem.

Table 5-344. TEST #1122/1123 MMI Synchronization Status Test

Error Code	Test Result	Description/Recommendation
	ABORT	Internal system error. This is an abnormal abort. 1. Retry the command at 1-minute intervals a maximum of 5 times.
2000	ABORT	A response to the test was not received from the MMI circuit pack within the allowable time period. 1. If this result occurs repeatedly and the MMI circuit pack is idle, reset the circuit pack using <a href="#">busyout board PCSS</a> , then <a href="#">reset board PCSS</a> , followed by <a href="#">release board PCSS</a> . 2. Rerun the test; if the same result occurs again, replace the MMI circuit pack.
2012	ABORT	Internal system error
2100	ABORT	Could not allocate the necessary resources to run this test. This is an abnormal abort. 1. Retry the command at 1-minute intervals a maximum of 5 times.
	FAIL	The MMI circuit pack is out of MMI synchronization. Run the <b>long</b> option of the <b>test board</b> command. 1. Wait up to 5 minutes, and then reset the circuit pack with these commands: <a href="#">busyout board PCSS</a> , then <a href="#">reset board PCSS</a> , followed by <a href="#">release board PCSS</a> . 2. Rerun the test; if the same result occurs again, replace the circuit pack.
1100	PASS	The MMI circuit pack is providing the synchronization correctly. This MMI circuit pack is designated as the Master Sync source.
1101	PASS	The MMI circuit pack is listening to the synchronization signal correctly.

**Control Channel Looparound Test (#52)**

Refer to the repair procedure described in [“XXX-BD \(Common Port Circuit Pack\)” on page 5-1343](#) as Control Channel Looparound Test (#52).

**SAKI Sanity Test (#53)**

Refer to the repair procedure described in the [“XXX-BD \(Common Port Circuit Pack\)” on page 5-1343](#) as SAKI Sanity Test (#53).

## MMI-LEV (Multimedia Interface Resource Level)

---

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run	Full Name of MO
MMI-LEV	MAJOR	See <a href="#">"Resolving MMI-LEV Errors/Alarms"</a> (below)	MMI-LEV

The Multimedia Interface Resource Level MO monitors MMI efficiency by tracking the number of MMI ports that are in-service, and then comparing that number with the value entered in the `MMI_S` field on the System-Parameters Maintenance form. This `MMI_S` field is located under the Minimum Maintenance Threshold section. The `MMI_S` field contains the minimum number of MMI ports needed for the Multimedia Call Handling (MMCH) feature to run efficiently and is an administrable field. This field must contain a minimum threshold number for MMI port capacity of between 0-128. The MMCH feature must be enabled on the System-Parameters Customer-Options form before the `MMI_S` field can be changed to a number greater than zero. The algorithm for determining that a low level of MMI resources exists uses the value entered in the `MMI_S` field, and the number of MMI ports that are in-service in the system.

Each MMI circuit pack contains a maximum of 32 ports. If the number of in-service MMI ports falls below the minimum port capacity (value entered on the System Parameters Maintenance form under the Minimum Maintenance Threshold section and in the `MMI` field), a MMI-LEV error is logged. If this outage continues for 15 minutes, a MAJOR alarm is raised.

### Resolving MMI-LEV Errors/Alarms

---

MMI ports are a key part of the MMCH feature, and any loss in the number of ports available for use degrades the MMCH customer-defined service level.

If a MMI circuit pack or port is busied out using the [busyout board](#) or [busyout port](#) commands, these out-of-service ports are not included in the MMI level calculation, thus allowing a technician to busy out a MMI circuit pack for maintenance reasons without causing a MAJOR alarm to be raised. However, if all of the ports on the MMI circuit pack are not made busy and the circuit pack is removed, an alarm is raised.

#### NOTE:

When diagnosing a MMI-LEV problem, begin by resolving any alarms raised against MMI-BD or MMI-PT maintenance objects. Clearing MMI-BD or MMI-PT alarms may clear the MMI-LEV alarm.

The MMI circuit pack is maintained by the software like the Tone Detector circuit pack, which can be removed and reinserted in any port board slot without administration. Similarly, if a MMI circuit pack is removed from service logically by failing the Archangel sanity scan test or is removed from service physically by removing the circuit pack from the carrier, no error/alarm is raised against either the MMI-BD or the MMI-PT maintenance objects. Therefore, if a MMI-LEV error/alarm exists, yet no alarms have been raised against MMI-BD or MMI-PT maintenance objects, a MMI circuit pack may have been removed from service causing the MMI-LEV error/alarm. To resolve a MMI-LEV MAJOR alarm, restore the number of MMI ports available for service to be equal to or greater than the calculated port capacity.

To determine how many MMI circuit packs are needed for the MMCH feature:

1. Using the [display system-parameters maintenance](#) command, locate the number listed in the `Minimum Maintenance Thresholds (MMIs)` field and record this number.
2. Use the [list configuration](#) command to verify the number of MMI ports.
3. Compare this number with the value listed in the `MMI` field on the System-Parameters Maintenance form (number listed in step 1 a minimum thresholds number for MMI ports of between 0-128). Each MMI circuit pack contains a maximum of 32 ports. If the number in the `MMIs` field is less than or equal to 32, one MMI circuit pack is needed. If this number is 64, then two MMI circuit pack are needed.
4. Use the [list configuration](#) command to verify that the number of MMI circuit packs listed agrees with the required minimum port capacity (from step 1). If the number of MMI circuit packs listed in the step 2 differs from the calculated number, restore the number of MMI circuit packs to the correct value, in order to resolve the MMI-LEV alarm.

## Error Log Entries and Test to Clear Values

---

Table 5-345. MMI-LEV Error Log Entries

Error Type	Aux Data	Associated Test	Alarm Level	On/ Off Board	Test to Clear Value
1 <sup>1</sup>	Any	None	MAJOR	OFF	

1. The number of MMI resources in the system that are in service has fallen below the calculated minimum value. If the number of in-service MMI ports falls below the MMCH port capacity (value entered in the Minimum Maintenance Thresholds for MMIs field) on the System-Parameters Maintenance form, a MMI-LEV error is logged. If this outage continues for 15 minutes, a MAJOR alarm is raised.

To resolve this alarm, correct the out-of-service problem by following these procedures:

1. See [“MMI-PT” on page 5-831](#) and “MMI-BD” and resolve any associated alarms.
2. If a MMI-LEV error/alarm exist and none has been raised against MMI-BD or MMI-PT maintenance objects, an MMI circuit pack may have been removed from service causing the MMI-LEV error/alarm. To resolve a MMI-LEV MAJOR alarm, restore the number of MMI ports available for service to be equal to or more than the calculated port capacity. See the [“Resolving MMI-LEV Errors/Alarms”](#) section above for details.
3. If the error continues to alarm, escalate the problem.

### System Technician-Demanded Tests: Descriptions and Error Code

---

There are no System Technician-Demanded tests for MMI-LEV.

## MMI-PT

---

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run <sup>1</sup>	Full Name of MO
MMI-PT	MAJOR	test port PCSSpp l r#	Multimedia Interface Port
MMI-PT	MINOR	test port PCSSpp l r#	Multimedia Interface Port
MMI-PT	WARNING	test port PCSSpp l r#	Multimedia Interface Port

1. Where P is the port network number (1 for PPN and 2 or 3 for EPN); C is the carrier designation (for example, A, B, C, or D); and SS is the address of the slot in the carrier where the circuit pack is located (for example, 01, 02, ..., and so forth).

**NOTE:**

Refer to “Troubleshooting MMCH” in Chapter 5 for MMCH troubleshooting information.

The Multimedia Interface Circuit Pack provides a number of H.221 protocol terminations for bit streams received from the TDM bus. The Multimedia Interface demultiplexes the H.221 bit stream (audio, video, data, control, and indication signals) and transmits the bit streams onto the TDM bus to be processed by the appropriate circuit packs.

Each Multimedia Interface Circuit Pack contains 32 separately maintained “ports,” more commonly referred to as “resources.” MMI-PT represents one of these 32 resources. At system boot or when the circuit pack is inserted, 32 resources are inserted into the system.

The MMI circuit pack contains 4 Digital Signal Processors (DSPs) which manage the 32 resources. These resources are directly mapped to DSPs:

Resource	Direct Map
1-8	DSP1
9-16	DSP2
17-24	DSP3
25-32	DSP4

All 8 resources that the circuit pack controls may be placed out of service by the failure of one of these DSPs.




Figure 5-39. TN787 MULTIMEDIA INTERFACE (MMI) CIRCUIT PACK

## Error Log Entries and Test to Clear Values

Table 5-346. MMI-PT Error Log Entries

Error Type	Aux Data	Associated Test	Alarm Level	On/ Off Board	Test to Clear Value
0 <sup>1</sup>	0	Any	Any	Any	test port PCSSpp sh r 1
1 (a)	Any	Uplink error from pack			
18 (b)	0	Busyout port PCSSpp	WNG	OFF	release port PCSSpp
130 (c)	Any	Software generated	WNG	ON	
257 (d)	Any	None	MAJ/ MIN	ON	
513 (e)	Any	Resource Loopback Test (#1111)	MIN	ON	test port PCSSpp sh r 3
1025 (f)	Any	Uplink error from pack			
3841 - 3844 (g)	Any	Uplink error from pack			

1. Run the short test sequence first. If all tests pass, run the Long Test Sequence. Refer to the appropriate test description and follow the recommended procedures.

### Notes:

- a. The customer endpoint connected on a conference sent too many messages to the VSP-MCU in a specified amount of time. Check the "status conference" forms to correlate which customer had the problem. This is a customer endpoint problem and not a VSP-MCU problem.
- b. This port has been busied out by the [busyout port PCSSpp](#) command.
- c. Indicates that the circuit pack has been removed or has been insane for more than 11 minutes. To clear the error, replace or reseal the circuit pack.
- d. This error occurs if the MMI circuit pack detects a DSP Error. Maintenance software will reset the DSP when this error is received. This error is logged for all 8 resources connected to this particular DSP. If this DSP continues to fail sanity, a Minor alarm is raised. Replace the circuit pack.
- e. This error occurs when the Resource Looparound Test (#1111) fails. Run the Long Test Sequence and note the results of Test #1111.

- f. This error occurs if either the MMI or Voice Conditioner (VC) circuit packs reports a loss of framing on the service channel between these two circuit packs. When a customer endpoint establishes a call to the VSP-MCU, a channel is established between the MMI resource and the VC port. If this channel is detected to go down by either circuit pack, an uplink message is sent. This error is then forwarded to maintenance for both circuit packs. Run the Long Test Sequence for this MMI resource, and if any of the tests fail, follow the repair procedures for that test. If all tests pass, the cause of the problem might be with the VC pack. See [“VC-DSPPT” on page 5-1319](#) for repair procedures.
- g. These errors are not related to VSP-MCU. They could be caused by network problems or from the customer endpoints. They are presented here for logging purposes only:

Code	Description
3841	CRC4 Error (Frame checksum error)
3842	Correctable BAS (Control msg single or double bit error, but correctable)
3843	Uncorrectable BAS (Control msg bit error -three or more bit, uncorrectable)
3844	Protocol Error (H.221 Protocol error from endpoint detected)

### System Technician-Demanded Tests: Descriptions and Error Codes

Order of Investigation	Short Test Sequence	Long Test Sequence	D/ND <sup>1</sup>
Resource Looparound Test (#1111)	X	X	D

1. D = Destructive; ND = Nondestructive

#### Resource Looparound Test (#1111)

**This test is destructive.**

This test checks the connectivity of the resource within MMI circuit pack and out to the TDM bus. The object is to test the circuitry that an H.221 bit stream comes in contact with when that stream is demultiplexed, pre-processed, written to the TDM bus and then reread (looped in the TSI), post-processed, multiplexed, and then written back to the TDM bus for verification. The video, audio, and data components of the bit stream are tested separately. If any one of these tests fails, then the resource is taken out of service.

Table 5-347. TEST #1111 Resource Looparound Test

Error Code	Test Result	Description/Recommendation
1000	ABORT	<p>System resources required to run this test are not available. The port may be busy with a valid call.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> <li>2. Use the <a href="#">status conference</a> command to determine if there is an active conference. If a call is active, the test cannot be run until the conference call terminates.</li> </ol>
1002	ABORT	<p>The system could not allocate time slots for the test. The traffic load on the system may be very high or time slots may be out-of-service due to TDM-Bus errors. Refer to <a href="#">"TDM-BUS (TDM Bus)" on page 5-1116</a> to diagnose any active TDM Bus errors.</p> <ol style="list-style-type: none"> <li>1. If the system has no TDM-BUS errors and is not handling heavy traffic, repeat the test at 1-minute intervals a maximum of 5 times.</li> </ol>
1003	ABORT	<p>The system could not allocate a tone detector for the test. The system is oversized for the number of tone detectors present or some tone detectors are out-of-service.</p> <ol style="list-style-type: none"> <li>1. Look for TTR-LEV errors in the Error Log. If present, refer to <a href="#">"TTR-LEV (TTR Level)" on page 5-1223</a>.</li> <li>2. Look for TONE-PT errors in the Error Log. If present, refer to <a href="#">"TONE-PT (Tone Generator)" on page 5-1204</a>.</li> <li>3. If neither condition exists, retry the test at 1-minute intervals a maximum of 5 times.</li> </ol>
1004	ABORT	<p>The resource has been seized by a user for a valid call. Refer to <a href="#">"status conference" on page 4-159</a> to verify that there is a conference call active.</p> <ol style="list-style-type: none"> <li>1. If there are no conference calls, retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
2000	ABORT	<p>Response to the test was not received from the Tone Detector circuit pack within the allowable time period.</p> <ol style="list-style-type: none"> <li>1. If this result occurs repeatedly, reset the circuit pack, if the other ports are not in use. Reset the circuit pack by issuing the <b>busyout board PCSSpp</b> (see <a href="#">"busyout board" on page 4-6</a>) and the <b>reset board PCSSpp</b> (see <a href="#">"reset board" on page 4-123</a> commands, followed by the <b>release board PCSS</b> (see <a href="#">"release board" on page 4-112</a>) command.</li> <li>2. If this result occurs again, replace the circuit pack.</li> </ol>
2012	ABORT	Internal system error
2100	ABORT	<p>Could not allocate the necessary resources to run this test. Abnormal abort.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>

Continued on next page

Table 5-347. TEST #1111 Resource Looparound Test — *Continued*

Error Code	Test Result	Description/Recommendation
0, 1, 2	FAIL	This resource cannot guarantee data integrity and is out-of-service. The following error codes indicate failure of a particular media loop: 0 = video 1 = audio 2 = low-speed data 1. Replace the circuit pack
	PASS	The resource is functioning normally.

## MMI-SYNC

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run <sup>1</sup>	Full Name of MO
MMI-SYNC	MINOR	test board PCSS I r#	Multimedia Interface Circuit Pack

- Where P is the port network number (1 for PPN and 2 or 3 for EPN); C is the carrier designation (for example, A, B, C, or D); and SS is the address of the slot in the carrier where the circuit pack is located (for example, 01, 02, ..., and so forth).



### NOTE:

Refer to “Troubleshooting MMCH” in Chapter 5 for MMCH troubleshooting information.

Each Port Network (PN) must have a TN787D or later MMI circuit pack assigned as the Multimedia Interface (MMI) master synchronization source for that PN. If one or more MMI circuit pack is administered in a PN, one MMI circuit pack is designated as the master synchronization source for all MMI circuit packs within that PN.

The MMI circuit pack generates a synchronization signal and puts that signal on the TDM bus. Other MMI packs or any other circuit pack within a PN can listen to this signal and “synchronize up” to it. The first MMI circuit pack inserted in a PN is normally designated as the master. As subsequent MMI packs are inserted, they are instructed to listen and synchronize to the time-slot of the master MMI. In the unlikely case of an MMI losing this reference, an uplink message is sent from the MMI circuit pack that lost the signal to maintenance, which also clears the “event” counter on this MMI with a downlink message. This forces the MMI circuit

pack to return the current state of the synchronization signal. If the signal is still lost, then the recovery algorithm is entered. Note that during this time, the MMI circuit pack synchronizes to its internal clock, and there should be no service disruption. A loss of synchronization is usually the result of a circuit pack failure. The maintenance strategy is to switch the master source away from the bad pack to another healthy MMI circuit pack within the PN.

A synchronization switch takes place if half or more of the MMI circuit packs in a PN report a loss of synchronization. For example, a PN with two MMIs reporting a loss of sync source switches immediately, three and four MMIs switch if two report the loss, and so forth. A healthy MMI circuit pack becomes the master synchronization source providing the signal on a new timeslot. The other MMI circuit packs within the PN are instructed to listen to this new signal, and the old master stops providing the signal and now listens to the new master MMI. If an MMI is physically removed from the system, then the remaining MMIs report the loss of synchronization. The first MMI with no alarms present becomes the new master of that PN. Once a synchronization switch has occurred, another switch is not allowed for 15 minutes to avoid hyperactive switching. If all the MMIs have alarms, then no switch is made.

If the MMI circuit pack that provides synchronization is craft busied out, it will not affect the PN synchronization. The signal is still provided by the busied-out pack. There is no affect on synchronization if the technician issues a release of the busied-out MMI. Synchronization is not affected by a warm start of the system (reset system 1). For all other restarts (reboot through cold 2), MMI synchronization recovers during board insertion.

## Error Log Entries and Test to Clear Values

Table 5-348. MMI-SYNC Error Log Entries

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
1	Any	None			See note <sup>1</sup>
257	Any	None	MINOR	OFF	See note <sup>2</sup>

1. An MMI synchronization switch was successful. Refer to ["MMI-BD"](#) errors for the reason for the switch.
2. The requested MMI synchronization switch failed. Resolve all MMI-BD alarms.

## System Technician-Demanded Tests: Descriptions and Error Codes

There are no system technician-demanded tests for MMI-SYNC.

## MODEM-BD (Modem Pool Circuit Pack)

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run <sup>1</sup>	Full Name of MO
MODEM-BD	MIN	test board PCSS sh	Modem Pool Circuit Pack
MODEM-BD	WRN	test board PCSS sh	Modem Pool Circuit Pack

1. Where P is the port network number (1 for PPN and 2 or 3 for EPN); C is the carrier designation (for example, A, B, C, D, or E); and SS is the address of the slot in the carrier where the circuit pack is located (for example, 01, 02, ..., etc.).

Refer to [“XXX-BD \(Common Port Circuit Pack\)” on page 5-1343](#) for circuit pack level errors. See also [“MODEM-PT \(Modem Pool Port\)” on page 5-838](#) for related port information.

## MODEM-PT (Modem Pool Port)

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run <sup>1</sup>	Full Name of MO
MODEM-PT	MINOR	test port PCSSpp sh	Modem Pool Port

1. Where P is the port network number (1 for PPN and 2 or 3 for EPN); C is the carrier designation (for example, A, B, C, D, or E); SS is the address of the slot in the carrier where the circuit pack is located (for example, 01, 02, ..., etc.); and pp is the 2-digit port number (for example, 01).

The Modem Pool Port provides an interface for digital and analog data communication devices or ports connected to the PBX. It may be thought of as a PBX data communications “conversion resource” because it converts analog modem signals typically used in the telephone network into digital signals that are compatible with the internal PBX network and vice versa.

There may be a number of these conversion resources available in the PBX, each assigned to one of five available Modem Pool Groups. Only one conversion resource is used per data connection. The PBX software usually adds the conversion resource into a data connection if it determines that it is necessary for the call. Typical connections that include Modem Pool conversion resources include data calls from Analog Line or Central Office Trunk ports to any digital port or Digital Line or Trunk ports to any analog port. An example of a Data Module to Central Office Trunk connection using a Modem Pool conversion resource is shown in [Figure 5-40 on page 5-840](#). When a local data call originates from an analog port normally used for voice service only and

terminates on a digital port, a Data Origination access code must be dialed before the extension number for the Modem Pool conversion resource to be included in the connection.

 **NOTE:**

Refer to [Figure 5-40 on page 5-840](#) while reading the following paragraph.

Each Modem Pool conversion resource contains two ports. One of these, an Analog Line Port, is connected (via the PBX network) to the Analog Line or Central Office Trunk Port that is the source of the modem signal. The second port is referred to as the digital port and is connected (again through the PBX network) to the Digital Line or Trunk port associated with the Data Module in the connection. The analog modem signals enter the analog port of the conversion resource in standard Pulse Code Modulation (PCM) format but are converted into Data Communications Protocol (DCP) format before going to the Digital Line or trunk in the connection.

There are two primary types of Modem Pool conversion resources available: an Integrated Pooled Modem and a Combined Modem Pool. The integrated TN758 Pooled Modem circuit pack contains two independent 300 or 1200 baud conversion resources. Each conversion resource contains two interfaces to the PBX digital network: an analog port and a digital port. The analog port is connected through the PBX network to the analog line or trunk port containing the analog modem signals. The digital port connects through the PBX network to the digital line or trunk port in the call. [Figure 5-40](#) shows a typical end-to-end connection using a conversion resource on the integrated Pooled Modem circuit pack.




Figure 5-40. Typical Modem Pool Switched Connection with Integrated Pooled Modem

The Combined Modem Pool conversion resource is the second type available. The function served by the Combined Modem Pool is similar to that of the integrated Pooled Modem circuit pack, but the physical implementation is much different. It has the advantage of supporting any speed the external modem can support. The integrated Pooled Modem circuit pack can only support 300 or 1200 baud transmission rates. The Combined Modem Pool conversion resource consists of a port on a TN742 or TN746 Analog Line circuit pack, an external modem, a Data Module, and a port on a TN754 Digital Line circuit pack. The tip and ring interface of the Analog Line is connected to the modem, the EIA 232C interface of the modem connects to the Data Module, and the DCP interface on the Data Module is connected to the Digital Line port.

The analog modem signals pass through the Analog Line port to the modem. The modem converts these to EIA 232C signals which are passed on to the Data Module. The Data Module further converts the signals to the DCP protocol for the Digital Line port which passes the signals on to the PBX network. See [Figure 5-41 on page 5-842](#).

Certain customer-reported troubles may provide important information for troubleshooting Modem Pool problems. For example, if the customer tries to make a data call requiring a Modem Pool conversion resource, and the Modem Pool and Data Module speeds or other options don't match, they receive a "CHECK OPTIONS" error message on the terminal. If this happens, the Modem Pool administration and customer Data Module option settings should be checked. In addition, if the Modem Pool is a Combined type, option settings should be checked on the external Modem and Data Module making up the Combined Modem Pool. The cabling and connections between the Digital Line port, Data Module, Analog Line port, and Modem should be checked between the Combined Modem Pool components.

There are three types of commands that can be used to test Modem Pool circuits: [test port](#), [test modem-pool #](#), and [test board](#). The **test port** command is generally the first test to run after the Error Log is evaluated and an entry is found for a Modem Pool port. The **test modem-pool #** command runs the same tests as the **test port short** command performed on a Modem Pool port. However, the **test modem-pool #** command can automatically test all ports in the Modem Pool group number specified in #. The **test board** command performs the same tests as **test port** and **test modem-pool #** plus additional tests for circuits common to the entire circuit pack. Refer to "[XXX-BD \(Common Port Circuit Pack\)](#)" on [page 5-1343](#) for information on additional tests performed with **test board** (#50, #52, and #53).

If the Modem Pool port or group being tested with [test modem-pool #](#) contains Combined Modem Pools, the ports on the associated TN742 or TN746 Analog Line circuit pack and the TN754 Digital Line circuit pack are tested as a group. Note, however, that Combined Modem Pools are not tested with the tests described in this section and the repair information related to Tests # 96, 97, 98, and 99 is not applicable. The Analog port of the Combined Modem port is tested with Analog port tests (that is, Tests #6, #47, #35, #48 and #36), and the Digital port of the Combined Modem port is tested with TDMODULE/PDMODULE tests

(that is, Tests #9, #13, #17 and #175). Therefore, use the repair procedures outlined in [“ANL-LINE \(8-port analog line\), ANL-NE-L \(8-port neon analog line\)” on page 5-65](#), [“ANL-16-L \(16-Port Neon Analog Line\)” on page 5-26](#), and [“PDMODULE, TDMODULE \(Data Module\)” on page 5-894](#) when interpreting the results of the execution of the **test modem-pool #** command on Combined Modem Pools.




Figure 5-41. Typical Modem Pool Switched Connection with Combined Modem Pool

**Hardware Error Log Entries and Test to Clear Values**

---

**Modem Pool Port Error Log Entries**

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
0 <sup>1</sup>	0	Any	Any	Any	test port PCSSpp sh r 1
18	0	busyout PCSS	WARNING	OFF	release port PCSSpp
130 (a)		None	WARNING	ON	test port PCSSpp sh
257		Conversion Resource Loop Test (#98)	MINOR	ON	test port PCSSpp sh r 3
513		Modem Conference Test(#97)	MINOR	ON	test port PCSSpp l r 3
769		Modem NPE Crosstalk Test (#96)	MINOR	ON	test port PCSSpp l r 3

1. Run the Short Test Sequence first. If all tests pass, run the Long Test Sequence. Refer to the appropriate test description and follow the recommended procedures.

**Note:**

- a. This error type indicates that the circuit pack has been removed or has been insane for more than 21 minutes. To clear the error, reinsert or replace the circuit pack.

**System Technician-Demanded Tests: Descriptions and Error Codes**

---

Always investigate tests in the order presented in the table below when inspecting errors in the system. By clearing error codes associated with the *Modem Pool Conference Test*, for example, you may also clear errors generated from other tests in the testing sequence. The tests in this section do not apply to Combined Modem Pool conversion resources. The standard Digital Line and/or Analog Line port tests are run on the ports associated with the Combined Modem Pool. The test descriptions for those maintenance objects (MOs) should be consulted when repairing Combined Modem Pool arrangements.

5 Maintenance Objects for DEFINITY ONE  
MODEM-PT (Modem Pool Port)

5-844

For example, you may also clear errors generated from other tests in the testing sequence. The tests in this section do not apply to Combined Modem Pool conversion resources. The standard Digital Line and/or Analog Line port tests are run on the ports associated with the Combined Modem Pool. The test descriptions for those maintenance objects (MOs) should be consulted when repairing Combined Modem Pool arrangements.

Order of Investigation	Short Test Sequence	Long Test Sequence	D/ND <sup>1</sup>
Modem Pool NPE Crosstalk Test (#96)		X	D
Modem Pool Conference Test (#97)		X	D
Modem Pool Conversion Resource Loop Around Test (#98)	X	X	ND
Modem Pool Audits Test (#99)	X	X	ND

1. D = Destructive; ND = Nondestructive

**Modem Pool NPE Crosstalk Test (#96)**

**This test is destructive.**

This NPE Crosstalk Test verifies that the NPE is connected only to the desired time slot and is not crosstalking on other time slots. This test operates exactly like Test #6 for other types of port circuits but is performed twice in order to test both NPEs in the Modem Pool Port.

Table 5-349. TEST #96 Modem Pool NPE Crosstalk Test

Error Code	Test Result	Description/ Recommendation
	ABORT	System resources required for this test are not available. 1. Retry the command at 1-minute intervals a maximum of 5 times.
1000	ABORT	System resources required to run this test are not available. The port may be in use on a valid call. Determine whether the port is available for testing. 1. Retry the command at 1-minute intervals a maximum of 5 times.
1001	ABORT	System resources required to run this test are not available. 1. Retry the command at 1-minute intervals a maximum of 5 times.

*Continued on next page*

Table 5-349. TEST #96 Modem Pool NPE Crosstalk Test — *Continued*

Error Code	Test Result	Description/ Recommendation
1002	ABORT	<p>The system could not allocate time slots for the test. The system may be under heavy traffic conditions or it may have time slots out-of-service due to TDM-BUS errors. Refer to <a href="#">“TDM-BUS (TDM Bus)” on page 5-1116</a> to diagnose any active TDM-BUS errors.</p> <ol style="list-style-type: none"><li>1. If the system has no TDM-BUS errors and is not handling heavy traffic, repeat the test at 1-minute intervals a maximum of 5 times.</li></ol>
1003	ABORT	<p>The system could not allocate a tone receiver for the test. The system may be oversized for the number of Tone Detectors present or some Tone Detectors may be out-of-service.</p> <ol style="list-style-type: none"><li>1. Look for TTR-LEV errors in the Hardware Error Log. If present, refer to <a href="#">“TTR-LEV (TTR Level)” on page 5-1223</a>.</li><li>2. Look for TONE-PT errors in the Hardware Error Log. If present, refer to <a href="#">“TONE-PT (Tone Generator)” on page 5-1204</a>.</li><li>3. If neither condition exists, retry the test at 1-minute intervals a maximum of 5 times.</li></ol>
1004	ABORT	<p>The port has been seized by a user for a valid call. Determine whether the port is available for testing.</p> <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
1020	ABORT	<p>The test did not run due to a previously existing error on the specific port or because of a more general circuit pack error.</p> <ol style="list-style-type: none"><li>1. Examine the Hardware Error Log for existing errors against this port or the circuit pack, and attempt to diagnose the previously existing errors.</li></ol>
2000	ABORT	<p>A response to the test request was not received within the allowable time period.</p> <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
2100	ABORT	<p>System resources required for this test are not available.</p> <ol style="list-style-type: none"><li>1. Retry the command at one-minute intervals a maximum of 5 times.</li></ol>

*Continued on next page*

Table 5-349. TEST #96 Modem Pool NPE Crosstalk Test — *Continued*

Error Code	Test Result	Description/ Recommendation
6000	ABORT	<p>System resources needed to complete the test could not be allocated for the digital section of the Modem Pool conversion resource. Ordinarily, this means the conversion resource or other hardware used during the test was in use.</p> <ol style="list-style-type: none"> <li>1. Wait one minute and attempt the test again.</li> <li>2. If it is absolutely necessary to test the conversion resource, the call must be dropped by issuing a <b>busyout port PCSS</b> command against the conversion resource. Issue the <b>release port PCSS</b> command. The busyout and release of the port drop any existing calls on that port.</li> <li>3. Run the test again.</li> <li>4. If the same error occurs while the conversion resource is idle, busyout and release both Modem Pool conversion resources on the TN758 Pooled Modem circuit pack containing the conversion resource under test. This action drops any existing calls on that circuit pack.</li> <li>5. If the test continues to abort, replace the Pooled Modem circuit pack and retest.</li> <li>6. If the test continues to abort with this error code after circuit pack replacement, escalate the problem.</li> </ol>
6001	ABORT	<p>System resources needed to complete the test could not be allocated for the analog section of the Modem Pool conversion resource.</p> <ol style="list-style-type: none"> <li>1. Follow the test procedures for the previous error code.</li> </ol>
NONE	FAIL	<p>The test failed. This error is internal to the Pooled Modem circuit pack and does not involve external equipment or interfaces.</p> <ol style="list-style-type: none"> <li>1. Busyout both of the TN758 Pooled Modem conversion resources on the circuit pack containing the failing conversion resource.</li> <li>2. If the test continues to fail, replace the Pooled Modem circuit pack and retest.</li> <li>3. If the circuit pack fails after replacement, escalate the problem.</li> </ol>
ANY	FAIL	<p>The NPE of the tested port was found to be transmitting in error. This condition causes noisy and unreliable connections.</p> <ol style="list-style-type: none"> <li>1. If the remaining ports are currently not in use (that is, yellow LED is off), attempt to reset the circuit pack. Then repeat the test.</li> <li>2. If the test fails again, replace the circuit pack.</li> </ol>
	PASS	<p>The port is correctly using its allocated time slots. User-reported troubles on this port should be investigated using other port tests and by examining station, trunk, or external wiring.</p>

## Modem Pool Conference Test (#97)

**This test is destructive.**

This test checks most of the switching and gain control functions provided by the NPE circuit in the analog section of the conversion resource. This test conferences a 1004-Hz tone through the NPE, looping it back so that it can be verified with a Tone Detector circuit.

Table 5-350. TEST #97 Modem Pool Conference Test

Error Code	Test Result	Description/ Recommendation
1000	ABORT	System resources required for this test are not available.
1002	ABORT	System resources required to run this test are not available. The port may be in use on a valid call. Determine whether the port is available for testing.
1003	ABORT	The system could not allocate time slots for the test. The system may be under heavy traffic conditions or it may have time slots out-of-service due to TDM-BUS errors. Refer to <a href="#">"TDM-BUS (TDM Bus)" on page 5-1116</a> to diagnose any active TDM Bus errors. <ol style="list-style-type: none"> <li>1. If the system has no TDM-BUS errors and is not handling heavy traffic, repeat the test at one-minute intervals a maximum of 5 times.</li> </ol>
1004	ABORT	The system could not allocate a tone receiver for the test. The system may be oversized for the number of Tone Detectors present or some Tone Detectors may be out-of-service. <ol style="list-style-type: none"> <li>1. Look for TTR-LEV errors in the Error Log. If present, refer to <a href="#">"TTR-LEV (TTR Level)" on page 5-1223</a>.</li> <li>2. Look for TONE-PT errors in the Error Log. If present, refer to <a href="#">"TONE-PT (Tone Generator)" on page 5-1204</a>.</li> <li>3. If neither condition exists, retry the test at one-minute intervals a maximum of 5 times.</li> </ol>
1020	ABORT	The port has been seized by a user for a valid call. Determine whether the port is available for testing. <ol style="list-style-type: none"> <li>1. Retry the command at one-minute intervals a maximum of 5 times.</li> </ol>
1020	ABORT	The test did not run due to a previously existing error on the specific port or because of a more general circuit pack error. <ol style="list-style-type: none"> <li>1. Examine the Hardware Error Log for existing errors against this port or the circuit pack, and attempt to diagnose the previously existing errors.</li> </ol>

*Continued on next page*

Table 5-350. TEST #97 Modem Pool Conference Test — *Continued*

Error Code	Test Result	Description/ Recommendation
2000	ABORT	The response to the test request was not received within the allowable time period.
2012	ABORT	Internal System Error.
2100	ABORT	System resources required for this test are not available.
2103	ABORT	The system could not make the conference connection for the test. <ol style="list-style-type: none"><li>1. Retry the command at one-minute intervals a maximum of 5 times.</li></ol>
4000	ABORT	System resources needed to complete the test could not be allocated. Ordinarily, this means the conversion resource or other hardware used during the test was in use. <ol style="list-style-type: none"><li>1. Wait one minute and attempt the test again.</li><li>2. If it is absolutely necessary to test the conversion resource, the call must be dropped by issuing a <a href="#">busyout port PCSS</a> command against the conversion resource. Issue the <a href="#">release port PCSS</a> command. The busyout and release of the port drop any existing calls on that port.</li><li>3. Run the test again.</li><li>4. If the same error occurs while the conversion resource is idle, busyout and release both Modem Pool conversion resources on the TN758 Pooled Modem circuit pack containing the conversion resource under the test. This action drops any existing calls on that circuit pack.</li><li>5. If the test continues to abort, replace the Pooled Modem circuit pack and retest.</li><li>6. If the test continues to abort with this error code after circuit pack replacement, escalate the problem.</li></ol>
65515	ABORT	System resources required for this test are not available. <ol style="list-style-type: none"><li>1. Retry the command at one-minute intervals a maximum of 5 times.</li><li>2. Issue the <a href="#">test port long</a> command on the port on which the test aborted. If any test aborted or failed, follow recommended maintenance strategy for the appropriate port type (for example, <a href="#">“ANL-LINE (8-port analog line), ANL-NE-L (8-port neon analog line)”</a> on page 5-65, or <a href="#">“DIG-LINE (Digital Line)”</a> on page 5-502).</li></ol>

*Continued on next page*

Table 5-350. TEST #97 Modem Pool Conference Test — *Continued*

Error Code	Test Result	Description/ Recommendation
NONE	FAIL	<p>The test failed. This error is internal to the Pooled Modem circuit pack and does not involve external equipment or interfaces.</p> <ol style="list-style-type: none"> <li>1. Busyout both of the TN758 Pooled Modem conversion resources on the circuit pack containing the failing conversion resource.</li> <li>2. If the test continues to fail, replace the Pooled Modem circuit pack and retest.</li> <li>3. If the circuit pack fails after replacement, escalate the problem.</li> </ol>
ANY	FAIL	<p>The Network Processing Element (NPE) of the tested port did not conference the tones correctly. This causes noisy and unreliable connections.</p> <ol style="list-style-type: none"> <li>1. If the remaining ports are currently not in use (that is, yellow LED is off), attempt to reset the circuit pack. Then repeat the test.</li> <li>2. If the test fails again, replace the circuit pack.</li> </ol>
	PASS	<p>The port can correctly conference multiple connections. User-reported troubles on this port should be investigated using other port tests and by examining station, trunk, or external wiring.</p>

### Modem Pool Conversion Resource Loop Around Test (#98)

The Modem Pool Conversion Resource Loop Around Test is set up as follows:




Figure 5-42. Modem Pool Conversion Resource Loop Around Test Set-up

Test data patterns are transmitted from the Network Control Channels 1 or 3 over network time slot A through the digital port, looped around through the analog port via time slot C back to the Network Control Channel circuit via time slot B where the patterns are checked for accuracy. Finally, the test forces a disconnect by breaking the connection between the Data Channel and Modem Pool Port (time slot A) and verifying that the Data Channel and Modem Pool Port go on-hook within the proper time.

This test attempts to allocate a Network Control Channel, Modem Pool Port, and other internal resources. If any of these allocation attempts fail, the test cannot be completed and a specific abort error is reported.

Table 5-351. TEST #98 Modem Pool Conversion Resource Loop Around Test

Error Code	Test Result	Description/ Recommendation
NONE	ABORT	Internal System Error. 1. Wait one-minute and try the test again.
5000	ABORT	System resources needed to complete the test could not be allocated for the digital section of the Modem Pool conversion resource. Ordinarily, this means the conversion resource or other hardware used during the test was in use. 1. Wait one minute and attempt the test again. 2. If it is absolutely necessary to test the conversion resource, the call must be dropped by issuing a <b>busyout port PCSS</b> command against the conversion resource. Issue the <b>release port PCSS</b> command. The busyout and release of the port drop any existing calls on that port. 3. Run the test again. 4. If the same error occurs while the conversion resource is idle, busyout and release both Modem Pool conversion resources on the TN758 Pooled Modem circuit pack containing the conversion resource under test. This action drops any existing calls on that circuit pack. 5. If the test continues to abort, replace the Pooled Modem circuit pack and retest. 6. If the test continues to abort with this error code after circuit pack replacement, escalate the problem.

*Continued on next page*

Table 5-351. TEST #98 Modem Pool Conversion Resource Loop Around Test — *Continued*

Error Code	Test Result	Description/ Recommendation
5001	ABORT	<p>A Network Control Channel could not be allocated for this test. This error is more closely related to the Data Channels (1 or 3 only) on the DATA-CHL circuit pack used for this test than the TN758 Pooled Modem circuit pack itself. Therefore, any hardware testing or replacement activities focus on the DATA-CHL circuit pack. However, the Data Channels on the DATA-CHL circuit pack normally should not be busied out, tested with the <a href="#">"test data-module"</a> command, or reseated in the carrier to clear this error, since this may drop other data calls that may be active at the time. The administration of Data Channels 1 and 3 should be checked if this error occurs.</p> <ol style="list-style-type: none"><li>1. Wait one minute and attempt the test again.</li><li>2. If the same error persists after five attempts at one-minute intervals, escalate the problem.</li></ol>
5002	ABORT	<p>The Network Control Channel allocated for this test could not be set to "maintenance busy" status.</p> <ol style="list-style-type: none"><li>1. Follow the repair procedures for Error Code 5001.</li></ol>
5003	ABORT	<p>The test was not able to establish a connection for the digital portion of the Modem Pool Port.</p> <ol style="list-style-type: none"><li>1. Follow the repair procedures for Error Code 5000.</li></ol>
5004	ABORT	<p>The test was not able to allocate the analog portion of the Modem Pool Port.</p> <ol style="list-style-type: none"><li>1. Follow the repair procedures for Error Code 5000.</li></ol>
5005	ABORT	<p>The test was not able to establish a connection for the analog portion of the Modem Pool Port.</p> <ol style="list-style-type: none"><li>1. Follow the repair procedures for Error Code 5000.</li></ol>
5006	FIL	<p>The Modem Pool Port did not respond to the "maintenance activate" message. This error is internal to the Modem Pool circuit pack and does not involve external equipment or interfaces. The test failed. This error is internal to the Pooled Modem circuit pack and does not involve external equipment or interfaces.</p> <ol style="list-style-type: none"><li>1. Busyout both of the TN758 Pooled Modem conversion resources on the circuit pack containing the failing conversion resource.</li><li>2. If the test continues to fail, replace the Pooled Modem circuit pack and retest.</li><li>3. If the circuit pack fails after replacement, escalate the problem.</li></ol>
5007	ABORT	<p>The Network Control Channel allocated for this test did not respond to the incoming call indication.</p> <ol style="list-style-type: none"><li>1. Follow the repair procedures for Error Code 5001.</li></ol>

*Continued on next page*

Table 5-351. TEST #98 Modem Pool Conversion Resource Loop Around Test — *Continued*

Error Code	Test Result	Description/ Recommendation
5009	ABORT	The Network Control Channel allocated for this test did not handshake correctly. <ol style="list-style-type: none"><li>1. Attempt the test again.</li><li>2. If the same error occurs, test the DATA-CHL circuit pack using the <a href="#">test data-module</a> command (refer to the DATA-CHL maintenance strategy).</li><li>3. If the DATA-CHL circuit pack tests pass, escalate the trouble report.</li></ol>
5010	FAIL	The Data Loop Around Test failed, indicating a probable problem with the TN758 Pooled Modem circuit pack. <ol style="list-style-type: none"><li>1. Follow the repair procedure for Error Code 5006.</li></ol>
5011	ABORT	The Network Control Channel allocated for this test did not disconnect properly. <ol style="list-style-type: none"><li>1. Follow the repair procedures for Error Code 5001.</li></ol>
5012	ABORT	The digital portion of the tested Modem Pool Port did not disconnect properly. <ol style="list-style-type: none"><li>1. Follow the repair procedures for Error Code 5000.</li></ol>
5013	FAIL	The Modem Pool Port did not respond with an on-hook message when the connection to the Data Channel was broken, indicating a likely problem with the TN758 Pooled Modem circuit pack. <ol style="list-style-type: none"><li>1. Follow the repair procedure for Error Code 5006.</li></ol>
5014	ABORT	The Network Control Channel allocated for this test did not respond correctly to the setup message sent to it after the connection was established. <ol style="list-style-type: none"><li>1. Attempt the test again.</li><li>2. If the same error occurs, test the DATA-CHL circuit pack using the <a href="#">test data-module</a> command (refer to the DATA-CHL maintenance strategy).</li><li>3. If the DATA-CHL circuit pack tests pass, escalate the problem.</li></ol>
5015	ABORT	Data Channels 1 and/or 3 have not been administered. <ol style="list-style-type: none"><li>1. Administer the Data Channels and retest.</li></ol>

**Modem Pool Audit Test (#99)**

This audit updates the Modem Pool conversion resource status contained in the TN758 Pooled Modem circuit pack's microprocessor. It does not actually test the Pooled Modem circuit pack; therefore, there are no FAIL codes. The audit can only be performed on idle conversion resources. If the conversion resource is in use, the audit aborts.

**Table 5-352. TEST #99 Modem Pool Audit Test**

Error Code	Test Result	Description/ Recommendation
NONE	ABORT	<p>The system was not able to allocate all the necessary resources to execute this test. An ABORT simply indicates that the conversion resource was in use when the audit was performed. No repair action is necessary unless it was known that the conversion resource was actually idle during the test (yellow in-use LED was off) or was busied out before the test was run. If this is the case, a TN758 failure condition may exist and the following procedure should be used:</p> <ol style="list-style-type: none"><li data-bbox="303 766 1059 826">1. Busyout both of the TN758 Pooled Modem conversion resources on the circuit pack containing the failing conversion resource.</li><li data-bbox="303 838 1059 897">2. If the test continues to abort, replace the Pooled Modem circuit pack and retest.</li><li data-bbox="303 910 1059 946">3. If the circuit pack fails after replacement, escalate the problem.</li></ol>

## M/T-ANL (Maintenance/Test Analog Port)

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run <sup>1</sup>	Full Name of MO
M/T-ANL	Minor	test port PCSSpp I	Maintenance/Test Analog Port
M/T-ANL	Warning	release port PCSSpp	Maintenance/Test Analog Port

- Where P is the port network number (1 for PPN and 2 or 3 for EPN); C is the carrier designation (for example, A, B, C, D, or E); and SS is the address of the slot in the carrier where the circuit pack is located (for example, 01, 02, ..., etc.).

The Maintenance/Test Analog Port is port number 1 on the TN771 Maintenance/Test circuit pack. This port is used by the Automatic Transmission Measurement System (ATMS) as an Originating Test Line (OTL) or Terminating Test Line (TTL) for test calls over analog trunks. [Figure 5-43](#) shows a typical ATMS configuration.

M/T-ANL maintenance ensures that the analog trunk's testing function is operating correctly. An alarm against M/T-ANL can reduce service, but it will not block it. To accurately measure performance and health of analog trunks, the TN771 should be replaced when a new circuit pack is available.




Figure 5-43. ATMS Tie Trunk Test Call

**Hardware Error Log Entries and Test to Clear Values****M/T-ANL Error Log Entries**

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
0 <sup>1</sup> (a)	0	Any	Any	Any	test port PCSSpp
1 (b)	41018	none	MINOR	ON	test port PCSSpp l r 3
18	0	busyout port PCSSpp	WARNING	OFF	release port PCSSpp
257	Any	NPE Crosstalk test (#9)	MINOR	ON	test port PCSSpp l r 3
513	Any	Analog Port Sanity Test (#963)	MINOR	ON	test port PCSS01 r 2
769	Any	Analog Port Digital Loop Around Test (#13)	MINOR	ON	test port PCSSpp r 3
3840(c)	Any	Hook State Inquiry test (#566)			

1. Run the Short Test Sequence first. If all tests pass, run the Long Test Sequence. Refer to the appropriate test description and follow the recommended procedures.

**Notes:**

- a. This error code appears in the Error Log only if the MTB circuit pack has been removed since the Error Log was last cleared. Verify that the circuit pack has been reinserted.
- b. This error indicates a hardware failure on the Analog Port circuitry. Replace the Maintenance/Test circuit pack if the alarm is not resolved by the command above.
- c. This error indicates that call processing records did not agree with on-board records for the hook state (on-/off-hook) of the Maintenance/Test Analog Port. This error is not service-affecting and no action is required.

## System Technician-Demanded Tests: Descriptions and Error Codes

Always investigate tests in the order presented in the following tables when inspecting errors in the system. By clearing error codes associated with the *Analog Port Sanity Test*, for example, you may also clear errors generated from other tests in the testing sequence.

Order of Investigation	Short Test Sequence	Long Test Sequence	D/ND <sup>1</sup>
Analog Port Sanity Test (#963)	X	X	ND
Digital Loop Around Test (#13)	X	X	ND
NPE Crosstalk Test (#9)		X	ND
Hook State Inquiry (#566)	X	X	ND
Clear Error Counters (#270)		X	ND

1. D = Destructive; ND = Nondestructive

### NPE Crosstalk Test (#9)

The NPE Crosstalk Test verifies that this port's NPE channel talks on the selected time slot and never crosses over to time slots reserved for other connections.

One or more Network Processing Elements (NPE) reside on each circuit pack with a TDM Bus interface. The NPE controls port connectivity, gain, and provides conferencing functions on a per port basis. If the NPE is not working correctly, one way and/or noisy connections may be observed. This test is part of a port's long test sequence and takes approximately 10 to 20 seconds to complete

Table 5-353. TEST #9 NPE Cross Talk Test

Error Code	Test Result	Description/ Recommendation
1000	ABORT	System resources required to run this test are not available. The port may be in use on a valid ATMS trunk test call. <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 3 times.</li> <li>2. If the test continues to abort and the port is not in use, escalate the problem.</li> </ol>
1001	ABORT	System resources required to run this test are not available. <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 3 times.</li> </ol>

*Continued on next page*

Table 5-353. TEST #9 NPE Cross Talk Test — *Continued*

Error Code	Test Result	Description/ Recommendation
1002	ABORT	<p>The system could not allocate time slots for the test. The system may be under heavy traffic conditions or it may have time slots out of service due to TDM-BUS errors. Refer to <a href="#">“TDM-BUS (TDM Bus)” on page 5-1116</a> to diagnose any active TDM-BUS errors. A system is considered under heavy traffic when the Call Processing Occupancy is greater than 50% or when the System Management and the Call Processing Occupancies together exceed 65%. To view the system occupancy measurements enter the command <b>status system health</b> on the system technician terminal.</p> <ol style="list-style-type: none"> <li>1. If system has no TDM-BUS errors and is not handling heavy traffic, repeat test at 1-minute intervals a maximum of 3 times.</li> <li>2. If the test continues to abort, escalate the problem.</li> </ol>
1003	ABORT	<p>The system could not allocate a tone receiver for the test. The system may be oversized for the number of tone detectors present or some tone detectors may be out-of-service.</p> <ol style="list-style-type: none"> <li>1. Look for TTR-LEV errors in the Error Log. If present, refer to <a href="#">“TTR-LEV (TTR Level)” on page 5-1223</a>.</li> <li>2. Look for TONE-PT errors in the Error Log. If present, refer to <a href="#">“TONE-PT (Tone Generator)” on page 5-1204</a>.</li> <li>3. If neither condition exists, retry the test at 1-minute intervals a maximum of 3 times.</li> </ol>
1004	ABORT	<p>The port has been seized by a valid ATMS test call.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 3 times.</li> <li>2. If the test continues to abort and the port is not in use on a valid ATMS Test Call, escalate the problem. To determine whether the port is in use by an ATMS Test Call enter <b>status station ext</b> where <b>ext</b> is the assigned ATMS station number. For more information, refer to <a href="#">“status station” on page 4-213</a>.</li> </ol>
2000	ABORT	<p>Response to the test request was not received within the allowable time period.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 3 times.</li> </ol>
2100	ABORT	<p>System resources required to run this test are not available.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 3 times.</li> </ol>

*Continued on next page*

Table 5-353. TEST #9 NPE Cross Talk Test — *Continued*

Error Code	Test Result	Description/ Recommendation
Any	FAIL	<p>The NPE of the tested port was found to be transmitting in error. This will cause noisy and unreliable connections.</p> <ol style="list-style-type: none"><li>1. If the remaining ports are currently not in use (yellow LED is off), try to reset the circuit pack via the <b>busyout board PCSS, reset board PCSS, release board PCSS</b> command sequence. For more information, see <a href="#">“busyout board” on page 4-6</a>, <a href="#">“reset board” on page 4-123</a> and <a href="#">“release board” on page 4-112</a>. Then repeat the test.</li><li>2. If the test fails again, replace circuit pack.</li></ol>
	PASS	<p>The port is correctly using its allocated time slots. User-reported troubles on this port should be investigated by examining station, trunk, or external wiring.</p>

### Analog Port Digital Loop Around Test (#13)

This test is a modification of the Voice and Control Channel Local Loop Test used by Digital Station (DIG-LINE) maintenance. This test does not perform the control channel and secondary information channel loop around tests as described for DIG-LINE, as these data paths do not exist for the Maintenance/Test Analog Port. The primary information channel is tested by first looping back the data channel onto the TDM Bus, and then sending a digital count from the Tone-Clock circuit pack and receiving the same digital count with a general purpose tone detector. A conference test is done next for the primary information channel. This test is the same as Conference Test (#6).

Only one value (Pass, Fail, or Abort) is generated as a result of the two tests. If either fails or aborts, the sequence is stopped.

Table 5-354. TEST #13 Analog Port Digital Loop Around Test

Error Code	Test Result	Description/ Recommendation
	ABORT	Internal System Error 1. Retry the command at 1-minute intervals a maximum of 3 times.
1000	ABORT	The port is in use on a valid ATMS Test Call. 1. Retry the command at 1-minute intervals a maximum of 3 times. 2. If the test continues to abort and the port is not in use on a valid ATMS Test Call, escalate the problem. To determine whether the port is in use by an ATMS Test Call enter <b>status station ext</b> where <b>ext</b> is the assigned ATMS station number.
1001	ABORT	System resources required to run this test are not available. 1. Retry the command at 1-minute intervals a maximum of 3 times.
1002	ABORT	The system could not allocate time slots for the test. The system may be under heavy traffic conditions, or it may have time slots out-of-service due to TDM-BUS errors. Refer to <a href="#">“TDM-BUS (TDM Bus)” on page 5-1116</a> to diagnose any active TDM-BUS errors. A system is considered under heavy traffic when the Call Processing Occupancy is greater than 50% or when the System Management and the Call Processing Occupancies together exceed 65%. To view the system occupancy measurements enter the command <b>status system health</b> on the system technician terminal. 1. If the system has no TDM-BUS errors and is not handling heavy traffic, repeat the test at 1-minute intervals a maximum of 3 times.
1003	ABORT	The system could not allocate a tone receiver for the test. The system may be oversized for the number of tone detectors present, or some tone detectors may be out-of-service. 1. Look for TTR-LEV errors in the Error Log. If present, refer to <a href="#">“TTR-LEV (TTR Level)” on page 5-1223</a> . 2. Look for TONE-PT errors in the Error Log. If present, refer to <a href="#">“TONE-PT (Tone Generator)” on page 5-1204</a> . 3. If neither condition exists, retry the command at 1-minute intervals a maximum of 3 times.
1004	ABORT	The port was seized by a valid ATMS Test Call. 1. Retry the command at 1-minute intervals a maximum of 3 times. 2. If the test continues to abort and the port is not in use on a valid ATMS Test Call, escalate the problem. To determine whether the port is in use by an ATMS Test Call enter <b>status station ext</b> where <b>ext</b> is the assigned ATMS station number. For more information, refer to <a href="#">“status station” on page 4-213</a> .

Continued on next page

Table 5-354. TEST #13 Analog Port Digital Loop Around Test — *Continued*

Error Code	Test Result	Description/ Recommendation
2000	ABORT	<p>Response to the test request was not received within the allowable time period.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 3 times.</li> </ol>
7	FAIL	<p>Conference test failed on the primary information channel.</p> <ol style="list-style-type: none"> <li>1. Run the circuit pack tests to check the Tone/Clock (TONE-BD) circuit pack and the Tone Detector circuit pack via the <b>test board PCSS</b> command. For more information, refer to <a href="#">“test board” on page 4-237</a>.</li> <li>2. Resolve any problems that are detected on the Tone/Clock (TONE-BD) circuit pack or Tone Detector circuit pack. For more information, refer to <a href="#">“TONE-PT (Tone Generator)” on page 5-1204</a>.</li> <li>3. If the Tone/Clock and Tone Detector circuit packs are functioning properly, and the test still fails, replace the Maintenance/Test circuit pack.</li> </ol>
14	FAIL	<p>The primary information channel is not transmitting properly. User may not notice any interruption in service or may not be able to use this port.</p> <ol style="list-style-type: none"> <li>1. Run the circuit pack tests to check the Tone Generator circuit pack and the Tone Detector circuit pack using <b>test board PCSS</b>. For more information, refer to <a href="#">“test board” on page 4-237</a>.</li> <li>2. Resolve any problems that are detected on the Tone Generator circuit pack or Tone Detector circuit pack. For more information, refer to <a href="#">“TONE-PT (Tone Generator)” on page 5-1204</a>.</li> <li>3. If the Tone Generator and Tone Detector circuit packs are functioning properly, and the test still fails, replace the Maintenance/Test Circuit Pack.</li> </ol>
	PASS	<p>The Maintenance/Test Analog Port analog trunk testing capability is operating correctly.</p>

## Clear Error Counters (#270)

The ports on the Maintenance/Test circuit pack continually run self-tests, whenever the port is idle. The Angel uses a counter so that the Background Maintenance Failure message is only sent uplink once (this keeps a failed port/circuit pack from flooding the SPE with a string of messages). Many circuit packs have counters in the Angel firmware. These counters are used so that Control Channel Message Set (CCMS) messages are not continuously sent uplink. Using this method, the message will be sent once, when the counter reaches some preset threshold, and then not sent again until the counter is cleared. This test is used to clear the counter, so that if the port continues to fail during or after SPE-demanded testing, the Angel will send a message to indicate that fact.

This test is only used to send a message to the Angel on the Maintenance/Test Circuit Pack. Therefore, this test should never abort or fail.

Table 5-355. TEST #270 Clear Error Counters

Error Code	Test Result	Description/ Recommendation
	PASS	The message to clear the Maintenance/Test circuit pack's counter for Background Maintenance Failures has been sent.

## Hook State Inquiry (#566)

This test ensures that the Maintenance/Test Analog Port maintenance software and call processing agree on the on-/off-hook status of the Maintenance/Test Analog Port.

Table 5-356. TEST #566 Hook State Inquiry

Error Code	Test Result	Description/ Recommendation
1	ABORT	Switch hook audit timed out. No response was received from the circuit pack for information about the switch hook state. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 3 times.</li><li>2. If the test continues to abort, replace the circuit pack and repeat the test.</li></ol>
2100	ABORT	System resources required to run this test are not available. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 3 times.</li></ol>
Any	FAIL	Internal System Error <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 3 times.</li><li>2. If the test continues to fail reset the circuit pack via the <b>busyout board PCSS, reset board PCSS, release board PCSS</b> command sequence. For more information, refer to "<a href="#">busyout board</a>" on page 4-6, "<a href="#">reset board</a>" on page 4-123, and "<a href="#">release board</a>" on page 4-112.</li><li>3. Retry the command at 1-minute intervals a maximum of 3 times.</li></ol>
	PASS	Call processing and Maintenance/Test Analog Port maintenance software agree on the Maintenance/Test Analog Port hook state.

## Analog Port Sanity Test (#963)

This test verifies that the port circuitry involved in the analog trunk testing on the Maintenance/Test Analog Port is functioning properly.

This test will abort if an ATMS Test Call is in progress on the Maintenance/Test Analog Port when the test is requested.

Table 5-357. TEST #963 Analog Port Sanity Test

Error Code	Test Result	Description/ Recommendation
2000	ABORT	Response to the test request was not received within the allowable time period.
2100	ABORT	System resources required to run this test are not available.
2500	ABORT	An internal operation failed; the test could not be completed. 1. Retry the command at 1-minute intervals a maximum of 3 times.
50	FAIL	The switch was unable to communicate with the port circuitry used for analog trunk testing. 1. Reset the circuit pack via the <b>busyout board PCSS, reset board PCSS, release board PCSS</b> command sequence. For more information, refer to " <a href="#">busyout board</a> " on page 4-6, " <a href="#">reset board</a> " on page 4-123 and " <a href="#">release board</a> " on page 4-112. 2. Test the port again via the <b>test port PCSS01 I</b> command. See " <a href="#">test port</a> " on page 4-264. 3. If the test fails again, replace the circuit pack.
	PASS	The Maintenance/Test Analog Port analog trunk testing capability is operating correctly.

## M/T-BD (Maintenance/Test Circuit Pack)

---

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run <sup>1</sup>	Full Name of MO
M/T-BD	MIN	test board PCSS I	Maintenance Test Circuit Pack
M/T-BD	WRN	release board PCSS	Maintenance/Test Circuit Pack

- 
1. Where P is the port network number (1 for PPN and 2 or 3 for EPN); C is the carrier designation (for example, A, B, C, D, or E); and SS is the address of the slot in the carrier where the circuit pack is located (for example, 01, 02, ..., etc.).

**CAUTION:**

*In G3iV1.1-286 and G3iV2-386, a TN771D (or later vintage) Maintenance/Test circuit pack must be used.*

Refer to [“XXX-BD \(Common Port Circuit Pack\)” on page 5-1343](#) for circuit pack level errors. See also [“M/T-DIG \(Maintenance/Test Digital Port\) \[G3iV1-1.286, G3iV2-386\]” on page 5-865](#) and [“M/T-PKT \(Maintenance/Test Packet Bus Port\)” on page 5-877](#) for related digital port and Packet Bus port information, respectively.

## 5 Maintenance Objects for DEFINITY ONE

*M/T-DIG (Maintenance/Test Digital Port) [G3iV1-1.286, G3iV2-386]*

5-865

**M/T-DIG (Maintenance/Test Digital Port) [G3iV1-1.286, G3iV2-386]**

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run <sup>1</sup>	Full Name of MO
M/T-DIG	Minor	test port PCSSpp l	Maintenance/Test Digital Port
M/T-DIG	Warning	release port PCSSpp	Maintenance/Test Digital Port

1. Where P is the port network number (1 for PPN, 2 or, 3 for EPN-1 and 3 for EPN-2); C is the carrier designation (A, B, C, D, or E); SS is the address of the slot in the carrier where the circuit pack is located (01, 02, ..., etc.); and pp is the 2-digit port number (for example, 01).

The Maintenance/Test Digital Port is a port on the TN771D (or later vintage) Maintenance/Test circuit pack, which is required for G3iV1.1-286 or G3iV2-386. Ports 2 and 3 are Digital Ports. The Maintenance/Test Digital Port provides the ability to perform digital (that is, ISDN-PRI) trunk testing via the TDM Bus. For an ISDN-PRI test call, connections are set up in the system as shown in [Figure 5-44 on page 5-866](#).

When the Maintenance/Test Digital Port is participating in an ISDN-PRI test call, the port sends a stream of pseudo-random data along the connected B-channel. The far end loops back this data, and the Maintenance/Test Digital Port compares the data to that which was sent. Errors are recorded on a bit and block basis. Refer to [“ISDN-TRK \(DS1 ISDN Trunk\)” on page 5-722](#) for more information on ISDN-PRI test calls.

The Maintenance/Test Digital Port maintenance ensures that the digital trunk testing function is operating correctly. The Maintenance/Test Digital Port is alarmed if maintenance determines that the digital port is operating incorrectly.

**⇒ NOTE:**

An alarm on the Maintenance/Test Digital Port reduces service, but does not block it since the ISDN-TRK has other means to determine the health of the ISDN-PRI trunk facility. However, to accurately measure the error performance and to ensure accuracy of the health of the ISDN-PRI trunk, the Maintenance/Test circuit pack should be replaced when a new circuit pack is available.




Figure 5-44. ISDN-PRI Outgoing Test Call

## 5 Maintenance Objects for DEFINITY ONE

M/T-DIG (Maintenance/Test Digital Port) [G3iV1-1.286, G3iV2-386]

5-867

**Hardware Error Log Entries and Test to Clear Values**

M/T-DIG Error Log Entries

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
0 <sup>1</sup>	0	Any	Any	Any	test port PCSSpp
1 (a)	41018	none	MINOR	ON	test port PCSSpp l r 3
18 (b)	0	busyout port PCSSpp	WARNING	OFF	release port PCSSpp
257 (c)	Any	NPE Crosstalk Test (#9)	MINOR	ON	test port PCSSpp l r 3
513 (d)	Any	Digital Port Sanity Test (#565)	MINOR	ON	test port PCSS02 r 2
769 (e)	Any	Digital Port Loop Around Test (#13)	MINOR	ON	test port PCSSpp r 3
3840 (f)	Any	Hook State Inquiry Test (#566)			

1. Run the Short Test Sequence first. If all tests pass, run the Long Test Sequence. Refer to the appropriate test description and follow the recommended procedures.

**Notes:**

- a. This error indicates a hardware failure on the Digital Port circuitry. Replace the Maintenance/Test circuit pack if the alarm is not resolved by the command above.
- b. The port has been busied out via the **busyout port PCSSpp** command. (See ["busyout port" on page 4-12.](#))
- c. This error indicates that Maintenance/Test Digital Port is talking on more than just its assigned time slot. Replace the Maintenance/Test circuit pack.
- d. This error indicates that the Maintenance/Test Digital Port has failed its self-test. Since the Digital Port Sanity Test runs only on Port 2, but tests both Ports 2 and 3, both ports are alarmed when the test fails. Note that the command above indicates to test Port 2, even if the error is logged against Port 3.
- e. This error indicates that the Maintenance/Test Digital Port has been unable to successfully loop data from a tone generator to a tone detector.
- f. This error indicated that call processing records did not agree with on-board records for the hook state (on-/off-hook) of the Maintenance/Test Digital Port. This error is not service-affecting and no action is required.

## System Technician-Demanded Tests: Descriptions and Error Codes

---

Always investigate tests in the order presented in the following tables when inspecting errors in the system. By clearing error codes associated with the *Digital Port Sanity Test*, for example, you may also clear errors generated from other tests in the testing sequence.

Order of Investigation	Short Test Sequence	Long Test Sequence	D/ND <sup>1</sup>
Digital Port Sanity Test (#565)	X	X	ND
Digital Port Loop Around Test (#13)	X	X	ND
NPE Crosstalk Test (#9)		X	ND
Hook State Inquiry (#566)	X	X	ND
Clear Error Counters (#270)		X	ND

---

1. D = Destructive; ND = Nondestructive

### NPE Crosstalk Test (#9)

This test is a modified version of the Digital Line NPE Crosstalk Test used by DIG-LINE maintenance.

One or more NPE reside on each circuit pack with a TDM Bus interface. The NPE controls port connectivity, gain, and provides conferencing functions on a per port basis. The NPE Crosstalk Test verifies that this port's NPE channel talks on the selected time slot and never crosses over to time slots reserved for other connections. If the NPE is not working correctly, one way and/or noisy connections may be observed. This test is part of a port's long test sequence and takes approximately 10 to 20 seconds to complete. This test is a modified version of the Digital Line NPE Crosstalk Test used by DIG-LINE maintenance.

## 5 Maintenance Objects for DEFINITY ONE

M/T-DIG (Maintenance/Test Digital Port) [G3iV1-1.286, G3iV2-386]

5-869

Table 5-358. TEST #9 NPE Cross Talk Test

Error Code	Test Result	Description/ Recommendation
1000	ABORT	<p>System resources required to run this test are not available. The port may be in use on a valid ISDN-PRI test call. Use the <b>list isdn-testcall</b> command to determine if the port is in use (if the port is listed in the M/T Port column). (See <a href="#">"list isdn-testcall" on page 4-79</a>.) If it is in use, either wait for the test call to complete (as indicated in the Start Time and Duration fields in the above display), or abort the test call with the <b>clear isdn-testcall tg/mem</b> command, where <b>tg/mem</b> is determined from the B-channel field of the above display.</p> <ol style="list-style-type: none"> <li>1. Retry the command at one-minute intervals a maximum of 5 times.</li> <li>2. If the test continues to abort and the port is not in use, escalate the problem.</li> </ol>
1001	ABORT	<p>System resources required to run this test are not available.</p> <ol style="list-style-type: none"> <li>1. Retry the command at one-minute intervals a maximum of 5 times.</li> </ol>
1002	ABORT	<p>The system could not allocate time slots for the test. The system may be under heavy traffic conditions or it may have time slots out of service due to TDM-BUS errors. Refer to <a href="#">"TDM-BUS (TDM Bus)" on page 5-1116</a> to diagnose any active TDM-BUS errors.</p> <ol style="list-style-type: none"> <li>1. If system has no TDM-BUS errors and is not handling heavy traffic, repeat test at one-minute intervals a maximum of 5 times.</li> </ol>
1003	ABORT	<p>The system could not allocate a tone receiver for the test. The system may be oversized for the number of tone detectors present or some tone detectors may be out-of-service.</p> <ol style="list-style-type: none"> <li>1. Look for TTR-LEV errors in the Error Log. If present, refer to <a href="#">"TTR-LEV (TTR Level)" on page 5-1223</a>.</li> <li>2. Look for TONE-PT errors in the Error Log. If present, refer to <a href="#">"TONE-PT (Tone Generator)" on page 5-1204</a>.</li> <li>3. If neither condition exists, retry the test at one-minute intervals a maximum of 5 times.</li> </ol>
1004	ABORT	<p>The port has been seized by a valid ISDN-PRI test call. Use the <b>list isdn-testcall</b> command to determine which call is using the port (from the M/T Port column). See <a href="#">"list isdn-testcall" on page 4-79</a>. Either wait for the test call to complete (as indicated in the Start Time and Duration fields of the above display), or abort the test call with the <b>clear isdn-testcall tg/mem</b> command, where <b>tg/mem</b> is determined from the B-channel field of the above display.</p> <ol style="list-style-type: none"> <li>1. Retry the command at one-minute intervals a maximum of 5 times.</li> <li>2. If the test continues to abort and the port is not in use, escalate the problem.</li> </ol>

Continued on next page

Table 5-358. TEST #9 NPE Cross Talk Test — *Continued*

Error Code	Test Result	Description/ Recommendation
2000	ABORT	Response to the test request was not received within the allowable time period.
2100	ABORT	System resources required to run this test are not available. <ol style="list-style-type: none"><li>1. Retry the command at one-minute intervals a maximum of 5 times.</li></ol>
Any	FAIL	The NPE of the tested port was found to be transmitting in error. This causes noisy and unreliable connections. <ol style="list-style-type: none"><li>1. If the remaining ports are currently not in use (yellow LED is off), try to reset the circuit pack. Then repeat the test.</li><li>2. If the test fails again, replace the circuit pack.</li></ol>
	PASS	The port is correctly using its allocated time slots. User-reported troubles on this port should be investigated using other port tests and by examining station, trunk, or external wiring.

### Digital Port Loop Around Test (#13)

This test is a modification of the Voice and Control Channel Local Loop Test used by Digital Station (DIG-LINE) maintenance. This test does not perform the control channel and secondary information channel loop around tests as described for DIG-LINE, as these data paths do not exist for the Maintenance/Test Digital Port. The primary information channel is tested by first looping back the data channel onto the TDM Bus, and then sending a digital count from the Tone-Clock circuit pack and receiving the same digital count with a general purpose tone detector. A conference test is done next for the primary information channel. This test is the same as Conference Test #6.

Only one value (Pass, Fail, or Abort) is generated as a result of the two tests. If either fails or aborts, the sequence is stopped.

5 Maintenance Objects for DEFINITY ONE

M/T-DIG (Maintenance/Test Digital Port) [G3iV1-1.286, G3iV2-386]

5-871

Table 5-359. TEST #13 Digital Port Loop Around Test

Error Code	Test Result	Description/ Recommendation
	ABORT	Internal System Error. 1. Retry the command at one-minute intervals a maximum of 5 times.
1000	ABORT	The port is in use on a valid ISDN-PRI Test Call. Use the <a href="#">list isdn-testcall</a> command on page <a href="#">4-79</a> to determine which call is using the port (from the M/T Port column). Either wait for the test call to complete (as indicated in the Start Time and Duration fields in the above display), or abort the test call with the <b>clear isdn-testcall tg/mem</b> command, where tg/mem is determined from the B-channel field of the above display. 1. Retry the command at one-minute intervals a maximum of 5 times. 2. If the test continues to abort and the port is not in use, escalate the problem.
1001	ABORT	System resources required to run this test are not available. 1. Retry the command at one-minute intervals a maximum of 5 times.
1002	ABORT	The system could not allocate time slots for the test. The system may be under heavy traffic conditions, or it may have time slots out-of-service due to TDM-BUS errors. Refer to <a href="#">"TDM-BUS (TDM Bus)" on page 5-1116</a> to diagnose any active TDM-BUS errors. 1. If the system has no TDM-BUS errors and is not handling heavy traffic, repeat the test at one-minute intervals a maximum of 5 times.
1003	ABORT	The system could not allocate a tone receiver for the test. The system may be oversized for the number of tone detectors present, or some tone detectors may be out-of-service. 1. Look for TTR-LEV errors in the Error Log. If present, refer to <a href="#">"TTR-LEV (TTR Level)" on page 5-1223</a> . 2. Look for TONE-PT errors in the Error Log. If present, refer to <a href="#">"TONE-PT (Tone Generator)" on page 5-1204</a> . 3. If neither condition exists, retry the command at one-minute intervals a maximum of 5 times.
1004	ABORT	The port was seized by a valid ISDN-PRI Test Call. Use the <a href="#">list isdn-testcall</a> command on page <a href="#">4-79</a> to determine which call is using the port (from the M/T Port column). Either wait for the test call to complete (as indicated in the Start Time and Duration fields of the above display), or abort the test call with the <b>clear isdn-testcall tg/mem</b> command, where tg/mem is determined from the B-channel field of the above display. 1. Retry the command at one-minute intervals a maximum of 5 times. 2. If the test continues to abort and the port is not in use, escalate the problem.

Continued on next page

Table 5-359. TEST #13 Digital Port Loop Around Test — Continued

Error Code	Test Result	Description/ Recommendation
2000	ABORT	Response to the test request was not received within the allowable time period. <ol style="list-style-type: none"><li>1. Retry the command at one-minute intervals a maximum of 5 times.</li></ol>
2100	ABORT	System resources required to run this test are not available. <ol style="list-style-type: none"><li>1. Retry the test at one-minute intervals a maximum of 5 times.</li></ol>
7	FAIL	Conference test failed on the primary information channel. In most cases, the user may not notice a disruption in service. <ol style="list-style-type: none"><li>1. Run the circuit pack tests to check the Tone Generator circuit pack and the Tone Detector circuit pack via the <a href="#">test board PCSS</a> command on page <a href="#">4-237</a>.</li><li>2. Resolve any problems that are detected on the Tone Generator circuit pack or Tone Detector circuit pack.</li><li>3. If the Tone Generator and Tone Detector circuit packs are functioning properly, and the test still fails, replace the Maintenance/Test circuit pack.</li></ol>
14	FAIL	The primary information channel is not transmitting properly. User impact may range from nothing to not being able to use this port. <ol style="list-style-type: none"><li>1. Run the circuit pack tests to check the Tone Generator circuit pack and the Tone Detector circuit pack using <a href="#">test board PCSS</a>.</li><li>2. Resolve any problems that are detected on the Tone Generator circuit pack or Tone Detector circuit pack.</li><li>3. If the Tone Generator and Tone Detector circuit packs are functioning properly, and the test still fails, replace the Maintenance/Test Circuit Pack.</li></ol>
	PASS	The Maintenance/Test Digital Port digital trunk testing capability is operating correctly.

## Clear Error Counters (#270)

This test is not an actual test in the strict sense of the word. Many circuit packs have counters in the Angel firmware. These counters are used so that Control Channel Message Set (CCMS) messages are not continuously sent uplink. Using this method, the message is sent once, when the counter reaches some preset threshold, and then not sent again until the counter is cleared.

The ports on the Maintenance/Test circuit pack continually run self-tests, whenever the port is idle. The Angel uses a counter so that the Background Maintenance Failure message is only sent uplink once (this keeps a failed port/circuit pack from flooding the SPE with a string of messages). This test is used to clear the counter, so that if the port continues to fail during or after SPE-demanded testing, the Angel sends a message to indicate that fact.

This test is only used to send a message to the Angel on the Maintenance/Test Circuit Pack. Therefore, this test should never abort or fail.

Table 5-360. TEST #270 Clear Error Counters

Error Code	Test Result	Description/ Recommendation
Any	ABORT	This test should never abort.
Any	FAIL	This test should never fail. 1. Retry the command at one-minute intervals a maximum of 5 times.
	PASS	The message to clear the Maintenance/Test circuit pack's counter for Background Maintenance Failures has been sent.

## Digital Port Sanity Test (#565)

This test verifies that the port circuitry involved in the digital trunk testing on the Maintenance/Test Digital Port is functioning properly. This circuitry is common to both Maintenance/Test Digital Ports on the Maintenance/Test circuit pack. Therefore, this test is only run for Port 2. The test aborts when run on Port 3, as described in [Table 5-361 on page 5-874](#).

This test operates by connecting the two Maintenance/Test Digital Ports on the TDM Bus so that they talk and listen to each other. Then four self-tests are attempted: (a) sending data from Port 2 to Port 3 in asynchronous mode; (b) sending data from Port 3 to Port 2 in asynchronous mode; (c) sending data from Port 2 to Port 3 in synchronous mode; and (d) sending data from Port 3 to Port 2 in synchronous mode. The test passes if all four of these self-tests are successful. The test stops as soon as any one of these self-tests fails.

This test aborts if an ISDN Test Call is in progress on either Maintenance/Test Digital Port when the test is requested, or if an ISDN Test Call is initiated while the Digital Port Sanity Test is in progress.

Table 5-361. TEST #565 Digital Port Sanity Test

Error Code	Test Result	Description/ Recommendation
1000	ABORT	<p>One of the Maintenance/Test Digital Ports is busy with background maintenance.</p> <ol style="list-style-type: none"> <li>1. Either wait for the port to become idle, or busyout both Maintenance/Test Digital Ports on the Maintenance/Test circuit pack via the <a href="#">busyout port PCSS02</a> and <a href="#">busyout port PCSS03</a> commands, respectively.</li> <li>2. Release the ports (if they were busyed out) via the <a href="#">release port PCSS02</a> and <a href="#">release port PCSS03</a> commands, respectively.</li> <li>3. Retry the command at one-minute intervals a maximum of 5 times.</li> </ol>
1002	ABORT	<p>The system could not allocate time slots for the test. The system may be under heavy traffic conditions, or it may have time slots out-of-service due to TDM-BUS errors. Refer to the <a href="#">"TDM-BUS (TDM Bus)" on page 5-1116</a> to diagnose any active TDM Bus errors.</p> <ol style="list-style-type: none"> <li>1. If the system has no TDM-BUS errors, and if not handling heavy traffic, repeat the test at one-minute intervals a maximum of 5 times.</li> </ol>
1004	ABORT	<p>The port was seized by a valid ISDN-PRI Test Call. Use the <a href="#">list isdn-testcall</a> command on page <a href="#">4-79</a> to determine which call is using the port (from the M/T Port column). Either wait for the test call to complete (as indicated in the Start Time and Duration fields of the above display), or abort the test call with the <b>clear isdn-testcall tg/mem</b> command, where <b>tg/mem</b> is determined from the B-channel field of the above display.</p>
1019	ABORT	<p>An ISDN Test Call is in progress using this Maintenance/Test circuit pack. The Maintenance/Test circuit pack cannot perform a self-test on one of its Digital Ports while an ISDN Test Call is using either of the Digital Ports. Use the <a href="#">list isdn-testcall</a> command to determine which call is using the port (form the M/T Port column). Either wait for the test call to complete (as indicated in the Start Time and Duration fields of the above display), or abort the test call with the <b>clear isdn-testcall tg/mem</b> command, where <b>tg/mem</b> is determined from the B-channel field of the above display.</p> <ol style="list-style-type: none"> <li>1. Retry the command at one-minute intervals a maximum of 5 times.</li> <li>2. If the test continues to abort and the port is not in use, escalate the problem.</li> </ol>

Continued on next page

5 Maintenance Objects for DEFINITY ONE

M/T-DIG (Maintenance/Test Digital Port) [G3iV1-1.286, G3iV2-386]

5-875

Table 5-361. TEST #565 Digital Port Sanity Test — Continued

Error Code	Test Result	Description/ Recommendation
1138	ABORT	<p>This test does not run on Port 3 of the Maintenance/Test circuit pack. This test runs only on Port 2. Look at the results of the Digital Port Sanity Test for Port 2.</p> <ol style="list-style-type: none"> <li>1. Run the command again for Port 2 via the <a href="#">test port PCSS02</a> or <a href="#">test port PCSS02 I</a> command.</li> </ol>
2000	ABORT	<p>Response to the test request was not received within the allowable time period.</p>
2100	ABORT	<p>System resources required to run this test are not available.</p>
2500	ABORT	<p>An internal operation failed; the test could not be completed.</p> <ol style="list-style-type: none"> <li>1. Retry the command at one-minute intervals a maximum of 5 times.</li> </ol>
50	FAIL	<p>The switch was unable to communicate with the port circuitry used for digital trunk testing.</p>
100	FAIL	<p>Data was not sent from Port 2 to Port 3 successfully in asynchronous mode.</p>
101	FAIL	<p>Data was not sent from Port 3 to Port 2 successfully in asynchronous mode.</p>
102	FAIL	<p>Data was not sent from Port 2 to Port 3 successfully in synchronous mode.</p>
103	FAIL	<p>Data was not sent from Port 3 to Port 2 successfully in synchronous mode.</p> <ol style="list-style-type: none"> <li>1. Reset the circuit pack via the <a href="#">busyout board PCSS</a>, <a href="#">reset board PCSS</a>, <a href="#">release board PCSS</a> command sequence.</li> <li>2. Test the port again via the <a href="#">test port PCSS02 I</a> command.</li> <li>3. If the test fails again, replace the circuit pack.</li> </ol>
	PASS	<p>The Maintenance/Test Digital Port digital trunk testing capability is operating correctly.</p>

## Hook State Inquiry (#566)

This test ensures that the Maintenance/Test Digital Port maintenance software and call processing agree on the on-/off-hook status of the Maintenance/Test Digital Port.

Table 5-362. TEST #566 Hook State Inquiry Test

Error Code	Test Result	Description/ Recommendation
1	ABORT	Switch hook audit timed out. No response was received from the circuit pack for information about the switch hook state. <ol style="list-style-type: none"> <li>1. Retry the command at one-minute intervals a maximum of 5 times.</li> <li>2. If the test continues to abort, replace the circuit pack and repeat the test.</li> </ol>
2100	ABORT	System resources required to run this test are not available. <ol style="list-style-type: none"> <li>1. Retry the command at one-minute intervals a maximum of 5 times.</li> </ol>
Any	FAIL	Internal System Error. This test should never return a failure. <ol style="list-style-type: none"> <li>1. Retry the command at one-minute intervals a maximum of 5 times.</li> <li>2. If the test continues to fail reset the circuit pack via the <a href="#">busyout board PCSS</a>, <a href="#">reset board PCSS</a>, <a href="#">release board PCSS</a> command sequence.</li> <li>3. Retry the command at one-minute intervals a maximum of 5 times.</li> </ol>
	PASS	Call processing and Maintenance/Test Digital Port maintenance software agree on the Maintenance/Test Digital Port hook state.

## M/T-PKT (Maintenance/Test Packet Bus Port)

---

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run <sup>1</sup>	Full Name of MO
M/T-PKT	Minor	test port PCSSpp I	Maintenance/Test Packet Bus Port
M/T-PKT	Warning	release port PCSSpp	Maintenance/Test Packet Bus Port

1. Where P is the port network number (1 for PPN and 2 or 3 for EPN); C is the carrier designation (A, B, C, D, or E); SS is the address of the slot in the carrier where the circuit pack is located (01, 02, ..., etc.); and pp is the 2-digit port number (for example, 01).

The Maintenance/Test Packet Bus Port is a port (always Port #4) on the TN771D (or later vintage) Maintenance/Test circuit pack, which is required for G3iV1.1-286 or G3iV2-386. The Packet Bus port provides the following Packet Bus maintenance functions:

- Packet Bus fault detection - the ability to detect faults (for example, shorts, open leads) on the Packet Bus autonomously (that is, without SPE involvement).
- Packet Bus reconfiguration - the ability to swap faulty leads with spare leads autonomously so that the Packet Bus remains operational. This is accomplished by sending messages to all Packet circuit packs [for example, ISDN-BRI (TN556)] telling them which spare leads to use on the Packet Bus.

Maintenance/Test Packet Bus Port maintenance ensures that these maintenance functions are operating correctly. The Maintenance/Test Packet Bus Port is alarmed if maintenance determines that the port's maintenance functions are operating incorrectly.

When Maintenance/Test Packet Bus Port maintenance determines that the Packet Bus Port is defective, the Packet Bus fault detection and Packet Bus reconfiguration functions provided by the port are turned off.

Maintenance/Test Packet Bus Port maintenance interacts with Packet Bus maintenance. Therefore, there may be alarms on the Packet Bus when there is a fault on the Maintenance/Test Packet Bus Port. Refer to [“PKT-BUS \(Packet Bus\)” on page 5-950](#) for further information.

## Hardware Error Log Entries and Test to Clear Values

M/T-PKT Error Log Entries

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
0 <sup>1</sup>	0	Any	Any	Any	test port PCSSpp
1 (a)	41018	none	MINOR	ON	test port PCSSpp l r 3
18 (b)	0	busyout port PCSSpp	WARNING	OFF	release port PCSSpp
257 (c)	Any	none	MINOR	ON	
513 (d)	Any	Packet Bus Port Health Inquiry Test (#567)	MINOR	ON	test port PCSSpp r 3

1. Run the Short Test Sequence first. If all tests pass, run the Long Test Sequence. Refer to the appropriate test description and follow the recommended procedures.

### Notes:

- a. This error indicates a hardware failure with the port circuitry which provides the Packet Bus maintenance functions. Replace the Maintenance/Test circuit pack if the alarm is not resolved by the test command above.
- b. The port has been busied out via the [busyout port PCSSpp](#) command.
- c. This error indicates that the Maintenance/Test Packet Bus Port has reconfigured the Packet Bus (that is, swapped a bad lead to a spare). Note that this error is sent up whenever the Maintenance/Test Packet Bus Port is initialized (since the Packet Bus Port reconfigures the Packet Bus to whatever state it determines the Packet Bus is in). This occurs if the circuit pack is inserted, if the system is restarted, or if the port is released from a busyout state. Therefore, it is normal for this error to be present in the error log.

If the Maintenance/Test Packet Bus Port reconfigures the Packet Bus 12 times within 15 minutes, a Minor alarm is raised. When the Minor alarm is raised, this is an indication that the Packet Bus maintenance functions are not operating correctly, or that many changes are taking place on the Packet Bus (that is, circuit pack insertion or removal). If the system has been in a stable state for more than 15 minutes, try the following procedures:

1. Reset the Maintenance/Test circuit pack from the Manager I terminal, as follows:
  - Enter the [busyout board](#) PCSS command.
  - Enter the [reset board](#) PCSS command.
  - Enter the [release board](#) PCSS command.
2. Wait 15 minutes.
3. If the error recurs, replace the Maintenance/Test circuit pack.

When this alarm is active, the yellow LED is in one of three states:

- If there is no activity on the Maintenance/Test circuit pack, the yellow LED is off. It is OK to replace the Maintenance/Test circuit pack.
  - If there is an indication of an uncorrectable fault on the Packet Bus, the yellow LED will be blinking at a rate of 1 Hz. It is OK to replace the Maintenance/Test circuit pack. Ignore the Packet Bus error indication, since the Maintenance/Test circuit pack has been determined to be defective.
  - If there is other activity on the Maintenance/Test circuit pack (that is, ISDN Test Call), or if there is an indication of a correctable fault on the Packet Bus, the yellow LED will be on steady. If there is an ISDN Test Call in progress, it must be halted via the [clear isdnpri-testcall grp/member](#) command prior to replacing the circuit pack. Ignore the Packet Bus error indication, since the Maintenance/Test circuit pack has been determined to be defective.
- d. This error indicates a failure of the Packet Bus Port Health Inquiry Test. Either the Packet Bus Port has reported a self-test failure, or the SPE is able to communicate with the Maintenance/Test Circuit Pack but not with the Maintenance/Test Circuit Pack Packet Bus Port. Refer to the description of the Packet Bus Port Health Inquiry Test, and follow the instructions indicated for the failure code that matches the Aux Data field.
-

## System Technician-Demanded Tests: Descriptions and Error Codes

Always investigate tests in the order presented in the following tables when inspecting errors in the system. By clearing error codes associated with the *Packet Bus Port Health Inquiry Test*, for example, you may also clear errors generated from other tests in the testing sequence.

Order of Investigation	Short Test Sequence	Long Test Sequence	D/ND <sup>1</sup>
Packet Bus Port Health Inquiry Test (#567)	X	X	ND
Clear Error Counters (#270)		X	ND

1. D = Destructive; ND = Nondestructive

### Clear Error Counters (#270)

This test is not an actual test in the strict sense of the word. Many circuit packs have counters in the Angel firmware. These counters are used so that CCMS (Control Channel Message Set) messages are not continuously sent uplink. Using this method, the message are sent once, when the counter reaches some preset threshold, and then not sent again until the counter is cleared.

The ports on the Maintenance/Test circuit pack continually run self-tests, whenever the port is idle. The Angel uses a counter so that the Background Maintenance Failure message is only sent uplink once (this keeps a failed port/circuit pack from flooding the SPE with a string of messages). This test is used to clear the counter, so that if the port continues to fail during or after SPE-demanded testing, the Angel sends a message to indicate that fact.

This test is only used to send a message to the Angel on the Maintenance/Test circuit pack. Therefore, this test should never abort or fail.

Table 5-363. TEST #270 Clear Error Counters

Error Code	Test Result	Description/ Recommendation
Any	ABORT	This test should never abort.
Any	FAIL	This test should never fail. 1. Retry the command at one-minute intervals a maximum of 5 times.
	PASS	The message to clear the Maintenance/Test circuit pack's counter for Background Maintenance Failures has been sent.

## Packet Bus Port Health Inquiry Test (#567)

This test verifies that the Packet Bus fault detection maintenance function of the Maintenance/Test Packet Bus Port is functioning properly. This is done by having the Maintenance/Test Packet Bus Port perform a self-test. If this self-test passes, then the Packet Bus Port Health Inquiry Test passes. If the self-test fails, or the SPE cannot communicate with the Maintenance/Test Packet Bus Port, then the test fails.

Table 5-364. TEST #567 Packet Bus Port Health Inquiry Test

Error Code	Test Result	Description/ Recommendation
2000	ABORT	Response to the test request was not received within the allowable time period.
2100	ABORT	System resources necessary to run this test are not available.
2500	ABORT	An internal operation failed; the test could not be completed. 1. Retry the command at one-minute intervals a maximum of 5 times.
2059	FAIL	The Maintenance/Test Packet Bus Port has reported a failure of the on-board self-test.
2060	FAIL	The Maintenance/Test Packet Bus Port has reported an invalid state for the Packet Bus.
2061	FAIL	The SPE cannot communicate with the Maintenance/Test Packet Bus Port, but is able to communicate with the Maintenance/Test Circuit Pack. 1. Retry the command. 2. If the test continues to fail, replace the Maintenance/Test circuit pack and retry the command. 3. If the test continues to fail, refer to " <a href="#">PKT-BUS (Packet Bus)</a> " on page <a href="#">5-950</a> to determine if the M/T-PKT failure is being caused by a Packet Bus fault.
	PASS	The Maintenance/Test Packet Bus Port Packet Bus fault detection capability is operating correctly.

## OPS-LINE (DS1 OPS Line)

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run	Full Name of MO
OPS-LINE	MINOR	test station <ext> l	DS1OPS Line
OPS-LINE	WARNING	test station <ext>	DS1OPS Line

An analog Off-Premises Station (OPS) can be connected to the system through a DS1 link. A TN767 DS1 Interface circuit pack supports up to 24 DS1OPSs. Since the DS1OPS is an analog telephone set, a channel multiplexer is necessary as the remote DS1 endpoint that converts the digital signal of a DS1 port to the OPS Line and vice versa. See [Figure 5-45](#) for details.

The DS1OPS Line Maintenance provides a strategy to maintain an OPS Line via a port of the DS1 Interface circuit pack. The strategy covers initialization tests, periodic tests, system technician-demanded tests, and alarm resolution and escalation. Two service states are specified in a DS1OPS Line maintenance. They are: *out-of-service* in which the line is in a deactivated state and cannot be used for either incoming or outgoing calls; *in-service* in which the line is in an activated state and can be used for both incoming and outgoing calls. If the DS1 Interface circuit pack is out-of-service, then all lines on the DS1 Interface circuit pack are put into the out-of-service state, and a Warning alarm is raised.

For maintenance of the remote DS1 endpoint (for example, Channel Division Multiplexer, D4 Channel Bank), refer to the maintenance documentation from its vendor for details.




Figure 5-45. DS1 OPS Line Interactions

## Hardware Error Log Entries and Test to Clear Values

Table 5-365. DS1 OPS Maintenance Error Log Entries

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
0 <sup>1</sup>	0	Any	Any	Any	test station <ext> sh r 1
15 (a)	Any	Audit and Update Test (#36)			
18 (b)	0	busyout station <ext>	WARNING	OFF	release station <ext>
130 (c)		None	WARNING	ON	test station <ext>
1281		Conference Circuit Test (#7)	MINOR	ON	test station <ext> l
1537		NPE Crosstalk Test (#6)	MINOR	ON	test station <ext> l
1793 (d)					test circuit pack PCSS l

1. Run the Short Test Sequence first. If all tests pass, run the Long Test Sequence. Refer to the appropriate test description and follow the recommended procedures.

### Notes:

- a. This is a software audit error that does not indicate any hardware malfunction. Run the Short Test Sequence and investigate associated errors (if any).
- b. The DS1OPS Line has been busied out by a **busyout station <ext>** command. No calls can be made on this line.
- c. This error type indicates that the circuit pack has been removed or has been insane for more than 11 minutes. To clear the error, reinsert or replace the circuit pack.
- d. Error Type 1793 indicates a problem with the DS1 Interface circuit pack. Since there is no error against the OPS-LINE port, no alarm is raised against the OPS-LINE port. However, there should be errors logged against the DS1 Interface circuit pack. Look for DS1-BD errors in the Hardware Error Log and follow procedures provided in the DS1-BD (DS1 Interface Circuit Pack) Maintenance documentation.

## System Technician-Demanded Tests: Descriptions and Error Codes

Always investigate tests in the order presented in the table below when inspecting errors in the system. By clearing error codes associated with the *NPE Crosstalk Test*, for example, you may also clear errors generated from other tests in the testing sequence.

Order of Investigation	Short Test Sequence	Long Test Sequence	D/ND <sup>1</sup>
NPE Crosstalk Test (#6)		X	ND
Conference Circuit Test (#7)		X	ND
DS1OPS Switchhook Inquiry Test (#312)	X	X	ND
Audit and Update Test (#36)	X	X	ND

1. D = Destructive; ND = Nondestructive

### NPE Crosstalk Test (#6)

One or more NPEs reside on each circuit pack with a TDM Bus interface. The NPE controls port connectivity and gain, and provides conferencing functions on a per-port basis. The NPE Crosstalk Test verifies that this port's NPE channel talks on the selected time slot and never crosses over to time slots reserved for other connections. If the NPE is not working correctly, one-way and noisy connections may be observed. This test is usually only part of a port's Long Test Sequence and takes about 20 to 30 seconds to complete.

Table 5-366. TEST #6 NPE Crosstalk Test

Error Code	Test Result	Description/ Recommendation
	ABORT	Could not allocate system resources to run this test or an internal system error (software) occurred. 1. Retry the command at 1-minute intervals a maximum of 5 times.
1000	ABORT	System resources required to run this test are not available. The port may be in use on a valid call. Use <b>status station</b> or <b>status trunk</b> command to determine when the port is available for testing. (Refer to <a href="#">"status station" on page 4-213</a> for a description of all possible states.) 1. Retry the command at 1-minute intervals a maximum of 5 times.
1001	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals a maximum of 5 times.

Continued on next page

Table 5-366. TEST #6 NPE Crosstalk Test — *Continued*

Error Code	Test Result	Description/ Recommendation
1002	ABORT	<p>The system could not allocate time slots for the test. The system may be under heavy traffic conditions or it may have time slots out-of-service due to TDM-BUS errors. Refer to "<a href="#">TDM-BUS (TDM Bus)</a>" on page 5-1116 to diagnose any active TDM-BUS errors.</p> <ol style="list-style-type: none"> <li>1. If the system has no TDM-BUS errors and is not handling heavy traffic, repeat the test at 1-minute intervals a maximum of 5 times.</li> </ol>
1003	ABORT	<p>The system could not allocate a tone receiver for the test. The system may be oversized for the number of Tone Detectors present or some Tone Detectors may be out-of-service.</p> <ol style="list-style-type: none"> <li>1. Look for TTR-LEV errors in the Error Log. If present, refer to "<a href="#">TTR-LEV (TTR Level)</a>" on page 5-1223.</li> <li>2. Look for TONE-PT errors in the Error Log. If present, refer to "<a href="#">TONE-PT (Tone Generator)</a>" on page 5-1204.</li> <li>3. If neither condition exists, retry the test at 1-minute intervals a maximum of 5 times.</li> </ol>
1004	ABORT	<p>The test was aborted because the port was seized by a user for a valid call. Use <b>status station</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. You must wait until the port is idle before retesting.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
1020	ABORT	<p>The test did not run due to an already existing error on the specific port or due to a more general error on the circuit pack.</p> <ol style="list-style-type: none"> <li>1. Examine the error log for existing errors against this port or the circuit pack and attempt to diagnose the already existing error. (Error code 1793 indicates a problem with the DS1 interface board, and any problems on the associated DS1-BD or UDS1-BD should be resolved first.)</li> </ol>
2000	ABORT	<p>Response to the test request was not received within the allowable time period.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> <li>2. If the test aborts with error code 2000 again, run short test sequence on the associated DS1-BD or UDS1-BD. If tests 138 through 145 on the associated DS1-BD or UDS1-BD are also aborting with error code 2000, hyperactivity on the board or facility is indicated. In this case, the hyperactivity problem should be dealt with first.</li> </ol>
2100	ABORT	<p>System resources required for this test are not available.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>

*Continued on next page*

Table 5-366. TEST #6 NPE Crosstalk Test — *Continued*

Error Code	Test Result	Description/ Recommendation
Any	FAIL	<p>The test failed. This can be due to on-board or off-board problems. Off-board problems of concern include EXP-INTF faults, TDM-BUS faults, and faults associated with the tone detectors/tone generators. Clear all off-board problems before replacing the board. Keep in mind that a TDM-BUS problem is usually the result of a faulty board connected to the backplane or bent pins on the backplane.</p> <ol style="list-style-type: none"><li>1. Look for TONE-BD and/or TONE-PT errors in the error log. If present, refer to the TONE-BD Maintenance documentation and to <a href="#">“TONE-PT (Tone Generator)” on page 5-1204</a>.</li><li>2. Retest when the faults from step 1 are cleared.</li></ol>
	PASS	<p>The port is correctly using its allocated time slots. User-reported troubles on this port should be investigated using other port tests and by examining station, trunk, or external wiring.</p>
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board). This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"><li>1. Check to ensure that the board translations are correct. Use the <b>list config</b> command, and resolve any problems that are found.</li><li>2. If the board was found to be correctly inserted in step 1, issue the <b>busyout board</b> command.</li><li>3. Issue the <b>reset board</b> command.</li><li>4. Issue the <b>release busy board</b> command.</li><li>5. Issue the <b>test board long</b> command. This should re-establish the linkage between the internal ID and the port. If this is not the case, dispatch to check to ensure that there is a valid board inserted.</li></ol>

**Conference Circuit Test (#7)**

One or more NPEs reside on each circuit pack with a TDM Bus interface. The NPE controls port connectivity and gain, and provides conferencing functions on a per-port basis. The Conference Circuit Test verifies that the NPE channel for the port being tested can correctly perform the conferencing function. The NPE is instructed to listen to several different tones and conference the tones together. The resulting signal is then measured by a Tone Detector port. If the level of the tone is within a certain range, the test passes.

**Table 5-367. TEST #7 Conference Circuit Test**

Error Code	Test Result	Description/ Recommendation
	ABORT	System resources required for this test are not available.  1. Retry the command at 1-minute intervals a maximum of 5 times.
1000	ABORT	System resources required to run this test are not available. The port may be in use on a valid call. Use the <b>status station</b> or <b>status trunk</b> command to determine when the port is available for testing.  1. Retry the command at 1-minute intervals a maximum of 5 times.
1002	ABORT	The test was aborted because the system could not allocate time slots for the test. The system might be under heavy traffic conditions, or it might have time slots out of service due to TDM-BUS errors. (The <b>status health</b> command may be used to determine whether the system is experiencing heavy traffic.) Refer to <a href="#">“TDM-BUS (TDM Bus)” on page 5-1116</a> to diagnose any active TDM-BUS errors.  1. If the system has no TDM-BUS errors, is not handling heavy traffic, and the port status is idle, retry the command at 1-minute intervals for a maximum of 5 times.
1003	ABORT	The system could not allocate a tone receiver for the test. The system may be oversized for the number of tone detectors present or some of the tone detectors may be out of service. Issue the <b>list measurements tone-receiver</b> command to display basic information about the system's tone receivers.  1. Look for TTR-LEV errors in the error log. If present, refer to <a href="#">“TTR-LEV (TTR Level)” on page 5-1223</a> . 2. Look for TONE-PT errors in the error log. If present, refer to <a href="#">“TONE-PT (Tone Generator)” on page 5-1204</a> . 3. If neither condition exists, retry the test at 1-minute intervals for a maximum of 5 times.
1004	ABORT	The port has been seized by a user for a valid call. Use <b>status station</b> or <b>status trunk</b> command to determine when the port is available for testing.  1. Retry the command at 1-minute intervals a maximum of 5 times.

*Continued on next page*

Table 5-367. TEST #7 Conference Circuit Test — *Continued*

Error Code	Test Result	Description/ Recommendation
1018	ABORT	<p>The test was disabled via translation.</p> <ol style="list-style-type: none"><li>1. You may want to determine why the test has been disabled before you enable it.</li><li>2. To enable the test for the particular analog station being tested, enter the <b>change station extension</b> command, and then change the <code>Test</code> field on the Station form to <b>y</b>.</li></ol>
1020	ABORT	<p>The test did not run due to an already existing error on the specific port or due to a more general error on the circuit pack.</p> <ol style="list-style-type: none"><li>1. Examine the error log for existing errors against this port or the circuit pack and attempt to diagnose the already existing error. (Error code 1793 indicates a problem with the DS1 interface board, and any problems on the associated DS1-BD or UDS1-BD should be resolved first.)</li></ol>
2000	ABORT	<p>The test was aborted because response to the test was not received within the allowable time period.</p> <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals for a maximum of 5 times.</li><li>2. If the test aborts with error code 2000 again, run short test sequence on the associated DS1-BD or UDS1-BD. If tests 138 through 145 on the associated DS1-BD or UDS1-BD are also aborting with error code 2000, hyperactivity on the board or facility is indicated. In this case, the hyperactivity problem should be dealt with first.</li></ol>
2100	ABORT	<p>System resources required for this test are not available.</p> <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>

*Continued on next page*

Table 5-367. TEST #7 Conference Circuit Test — *Continued*

Error Code	Test Result	Description/ Recommendation
	FAIL	<p>The NPE of the tested port did not conference the tones correctly. This can cause noisy and unreliable connections.</p> <ol style="list-style-type: none"> <li>1. Enter the <b>list configuration board PCSS</b> command. If the circuit pack is a TN767B vintage 8 or 9, replace the circuit pack with a TN767C V3 or later. The error log may have error type 1281 entries.</li> <li>2. Test all administered trunks on the board. If one fails, this could be an off-board problem (such as an incoming seizure or an off-hook port seizure during the test). Retest the board.</li> <li>3. If all of the ports fail, check the CARR-POW (see note below).</li> <li>4. If several ports fail, check the error log for TONE-BD or TONE-PT errors. If there are such errors, take the appropriate action. When the TONE errors have cleared, rerun the test.</li> <li>5. If the retry passes and troubles have been reported, coordinate isolation with the far-end PBX. Make sure that the near-end and far-end switches and any NTCE equipment (the CSUs) have the correct administration.</li> <li>6. Replace the circuit pack.</li> </ol> <p><b>⇒ NOTE:</b> If the conference circuit test fails for all ports on a circuit pack, a -5 volt power problem is indicated.</p>
	PASS	<p>The port can correctly conference multiple connections. User-reported troubles on this port should be investigated using other port tests and by examining station, trunk, or external wiring.</p>
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board). This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"> <li>1. Check to ensure that the board translations are correct. Use the <b>list config</b> command, and resolve any problems that are found.</li> <li>2. If the board was found to be correctly inserted in step 1, issue the <b>busyout board</b> command.</li> <li>3. Issue the <b>reset board</b> command.</li> <li>4. Issue the <b>release busy board</b> command.</li> <li>5. Issue the <b>test board long</b> command. This should re-establish the linkage between the internal ID and the port. If this is not the case, dispatch to check to ensure that there is a valid board inserted.</li> </ol>

**Audit and Update Test (#36)**

This test sends port level translation data from switch processor to the DS1 Interface circuit pack to assure that the trunk's translation is correct. Translation updates include the following data: trunk type (in/out), dial type, timing parameters, and signaling bits enabled. The port audit operation verifies the consistency of the current state of the trunk as kept in the DS1 Interface circuit pack and in the switch software.

**Table 5-368. TEST #36 Audit and Update Test**

Error Code	Test Result	Description/ Recommendation
	ABORT	Internal System Error.  1. Retry the command at 1-minute intervals a maximum of 5 times.
1000	ABORT	The test was aborted because system resources required to run this test were not available. The port may be busy with a valid call. Use the <b>display port PCSSpp</b> command to determine the station extension of the port. Use the <b>status station</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. You must wait until the port is idle before retesting.  1. If the port is idle, retry the command at 1-minute intervals a maximum of 5 times.
1006	ABORT	The test was aborted because the station is out of service. This condition may be accompanied by an error type 18 entry in the error log. You may want to determine why the station was taken out of service. (When stations are taken out of service by maintenance software, the problems that preceded that point must be cleared.)  1. Use the <b>status station</b> command to check the service state of the port. If the port is indeed out of service, enter the <b>release station</b> command to bring the station back into service.  2. Retry the command at 1-minute intervals a maximum of 5 times.  3. If the test continues to abort, and the service state indicates that the station is in service and idle, escalate the problem.
2000	ABORT	The test was aborted because response to the test was not received within the allowable time period.  1. Retry the command at 1-minute intervals for a maximum of 5 times.  2. If the test aborts with error code 2000 again, run short test sequence on the associated DS1-BD or UDS1-BD. If tests 138 through 145 on the associated DS1-BD or UDS1-BD are also aborting with error code 2000, hyperactivity on the board or facility is indicated. In this case, the hyperactivity problem should be dealt with first.

*Continued on next page*

Table 5-368. TEST #36 Audit and Update Test — *Continued*

Error Code	Test Result	Description/ Recommendation
2100	ABORT	System resources required for this test are not available. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
7 or 8	FAIL	Test failed due to internal system error. Do not replace port board. <ul style="list-style-type: none"><li>■ Error code 7: the failure occurred during station translation download (to DS1 Interface circuit pack).</li><li>■ Error code 8: the failure occurred during station ringer update.</li></ul> <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
	PASS	Trunk translation has been updated successfully. The current trunk states kept in the DS1 Interface circuit pack and switch software are consistent.
0	NO BOARD	The test could not relate the internal ID to the port (no board). This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted. <ol style="list-style-type: none"><li>1. Check to ensure that the board translations are correct. Use the <b>list config</b> command, and resolve any problems that are found.</li><li>2. If the board was found to be correctly inserted in step 1, issue the <b>busyout board</b> command.</li><li>3. Issue the <b>reset board</b> command.</li><li>4. Issue the <b>release busy board</b> command.</li><li>5. Issue the <b>test board long</b> command. This should re-establish the linkage between the internal ID and the port. If this is not the case, dispatch to check to ensure that there is a valid board inserted.</li></ol>

**DS1 OPS Switchhook Inquiry Test (#312)**

This test initiates the Switchhook Audit Test. The test queries the switchhook state of the Off-Premises-Station in switch software. If the state in switch software disagrees with the state on the DS1 Interface circuit pack. The state in the switch software is updated to match the state on the DS1 Interface circuit pack.

**Table 5-369. TEST #312 DS1OPS Switchhook Inquiry Test**

Error Code	Test Result	Description/ Recommendation
	ABORT	Internal System Error.  1. Retry the command at 1-minute intervals a maximum of 5 times.
1004	ABORT	The port has been seized by a user for a valid call. Use the <b>status station</b> command to determine when the port is available for testing.  1. Retry the command at 1-minute intervals a maximum of 5 times.
1005	ABORT	Test failed due to incompatible configuration administered in station administration.  1. Verify the station administration is the station assigned to Port 24 of the DS1 Interface circuit pack while common channel signaling is specified.
1006	ABORT	The test was aborted because the station is out of service. This condition may be accompanied by an error type 18 entry in the error log. You may want to determine why the station was taken out of service. (When stations are taken out of service by maintenance software, the problems that led up to that must be cleared.)  1. Use the <b>status station</b> command to check the state of the port. If the port is indeed out of service, enter the <b>release station</b> command to bring the station back into service.  2. Retry the command at 1-minute intervals a maximum of 5 times.  3. If the test continues to abort, and the station is in the in-service/idle state, escalate the problem.
1020	ABORT	The DS1 Interface circuit pack is out-of-service.  1. Look for DS1-BD errors in Hardware Error Log. If present, refer to <a href="#">"DS1-BD (DS1 Interface Circuit Pack)" on page 5-548</a> .  2. Retry the command.
2000	ABORT	The test was aborted because response to the test was not received within the allowable time period.  1. Retry the command at 1-minute intervals for a maximum of 5 times.  2. If the test aborts with error code 2000 again, run short test sequence on the associated DS1-BD or UDS1-BD. If tests 138 through 145 on the associated DS1-BD or UDS1-BD are also aborting with error code 2000, hyperactivity on the board or facility is indicated. In this case, the hyperactivity problem should be dealt with first.

Table 5-369. TEST #312 DS1OPS Switchhook Inquiry Test — *Continued*

Error Code	Test Result	Description/ Recommendation
2012	ABORT	The test was aborted due to a system error.
2100	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals for a maximum of 5 times.
1	FAIL	Internal System Error. 1. Look for DS1-BD errors in the Hardware Error Log. If present, refer to <a href="#">"DS1-BD (DS1 Interface Circuit Pack)" on page 5-548.</a> 2. If a channel multiplexer is used as the remote DS1 endpoint to which the station connects, refer to the multiplexer vendor's maintenance document for diagnosis. 3. Retry the command at 1-minute intervals a maximum of 5 times
	PASS	The station hook states in both switch software and DS1 Interface circuit pack are consistent.
0 2012	NO BOARD	The test could not relate the internal ID to the port (no board). This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted. 1. Check to ensure that the board translations are correct. Use the <b>list config</b> command, and resolve any problems that are found. 2. If the board was found to be correctly inserted in step 1, issue the <b>busyout board</b> command. 3. Issue the <b>reset board</b> command. 4. Issue the <b>release busy board</b> command. 5. Issue the <b>test board long</b> command. This should re-establish the linkage between the internal ID and the port. If this is not the case, dispatch to check to ensure that there is a valid board inserted.


## PDMODULE, TDMODULE (Data Module)

---

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run <sup>1</sup>	Full Name of MO
PDMODULE <sup>2,3</sup>	MINOR	test port PCSSpp l	Processor Data Module
PDMODULE	WARNING	test port PCSSpp sh	Processor Data Module
TDMODULE <sup>2,3</sup>	MINOR	test port PCSSpp l	Trunk Data Module
TDMODULE	WARNING	test port PCSSpp sh	Trunk Data Module

1. Where P is the port network number (1 for PPN and 2 or 3 for EPN); C is the carrier designation (for example, A, B, C, D, or E); SS is the address of the slot in the carrier where the circuit pack is located (for example, 01, 02, ..., etc.); and pp is the 2-digit port number (for example, 01).
2. The DTDM is considered to be part of the DIG-LINE MO. Refer to the Digital Line testing section for DTDM or linked Data Adapter (DA) failures.
3. Some of the alarms that are logged due to PDMODULE and TDMODULE test failures may be related to circuit pack problems reported during the Common Port Circuit Pack testing phase. Refer to [“XXX-BD \(Common Port Circuit Pack\)” on page 5-1343](#) for information about testing the Digital Line circuit packs.

As illustrated in [Figure 5-46](#), data modules provide an interface between the system TN754, TN784, TN413 [G3iV2-386], or TN754 [G3iV2-386] Digital Line circuit pack and data equipment such as terminals, host computers, and modems. Data modules are used for both dial-up and permanent circuit-switched data calls. DA data modules provide this interface when the system uses a TN2136 [G3iV2-386] Digital Line circuit pack.



**Figure 5-46. Typical Data Module Application**

The MPDM provides an interface for Data Terminal Equipment (terminals), and the MTDM (see Note) provides an interface for Data Communications Equipment (transmission equipment such as modems).

**⇒ NOTE:**

Early versions of these data modules were referred to as PDMs and TDMs, respectively. Later models are designed to provide various customer interfaces through the use of interchangeable interface modules and, therefore, are called modular data modules. Both versions are supported by the tests described in this section.

The PBX loop or digital link between a data module and the Digital Line port supports two logical information channels and one signaling channel. MPDMs and MTDMs use the primary information channel for data communications and the signaling channel for dialing and call supervision. The secondary information channel can be used to support a second data module on a shared digital port.

Data modules are not only used for data calls between terminals, computers, and data communications equipment, but are also used as interfaces to equipment associated with system features such as System Administration, CDR, MCS, ACD, DCS, and AUDIX. Maintenance tests for data modules associated with those services are covered by tests other than those described here. (See PI-LINK, PMS-PRNT/JNL-PRNT, and PMS-LINK Maintenance documentation.)

Maintenance of MPDMs and MTDMs is closely related to, and interacts with, the Digital Line circuit pack maintenance in some instances and some of the results of testing MPDMs and MTDMs may be affected by the health of the Digital Line circuit pack. This interaction should be kept in mind when investigating the cause of reported data module problems.

Data modules provide a variety of option switches to allow the customer to select data rates, parity, keyboard dialing, local, and remote loop back, etc. An incorrect setting of those switches does not affect error and alarm information or test results described in this section, but it may result in an inoperable condition. Refer to the Installation Manual provided with the data module for more information about those options.

The DA data module provides an AT (Hayes) type interface that allows the customer to select data rates, parity, local, interface mode (**linked** to digital phone or **stand-alone**), and remote loop back, etc. An incorrect selection does not affect error and alarm information or test results described in this section, but it may result in an inoperable condition.

There are instances in this document where the service state of a data module is mentioned. It is helpful to understand what is meant by the different service states that may exist. An explanation of these service states follows:

- **Out-of-Service**—The port, and thus the data module, have been removed from service. A busyout of a port or removal of the associated Digital Line circuit pack causes the data module to be placed in the out-of-service state. Failure of the NPE Crosstalk Test (Test #9) also takes a port out-of-service.
- **Disconnected**—The port is administered but the associated digital link does not respond. An administered port is put in a disconnected state after system booting or circuit pack insertion, until a “link reset pass” message is received from firmware on the associated circuit pack.
- **In-Service**—Once the PBX software has received a “link reset pass” message from the Digital Line port, the port is placed in the in-service state. In case the “link reset pass” message is missed, and an off-hook message is received while the port is in the disconnected state, maintenance software runs an ID request test and the port is put back in service if a correct response is received.

If the link is disconnected, the port returns to the disconnect state. Note that it takes a few minutes (less than five) for the state of a data module port to change from in-service to disconnected after the data module is disconnected from the local PBX loop.

## Hardware Error Log Entries and Test to Clear Values

PDMODULE and TDMODULE Error Log Entries

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
0 <sup>1</sup>	0	Any	Any	Any	test port PCSSpp sh r 1
1 (a)	40987	None	WARNING	OFF	
1 (b)	1 to 20	None	WARNING	OFF	
15 (c)	Any	None			
18 (d)	0	busyout port PCSSpp	WARNING	OFF	release port PCSSpp
257 (e)	40971	None			
513 <sup>2</sup>	0	Data Module Audits Test (#17)	WARNING (j)	OFF	test port PCSSpp sh r 6
769 (f)	40988	None	WARNING	OFF	
1281	Any	Data Module Audits Test (#17)	WARNING	OFF	test port PCSSpp sh r 4
1537 (g)	40968	None	WARNING	OFF	
1793		Information Channel and Control Channel Loop Around Test (#13)	MINOR	ON	test port PCSSpp l r 3
2049		NPE Crosstalk Test (#9)	MINOR	ON	test port PCSSpp l r 3
2305 (h)	32770	None			
2305 (i)	40967	None			
2561		Data Module Internal Loop Around Test (#175)	WARNING	OFF	test port PCSSpp l r 5
2817 (k)		Link GPP Loop (183) Against Links	MAJOR	ON	
3841 (l)		NONE			

1. Run the Short Test Sequence first. If all tests pass, run the Long Test Sequence. Refer to the appropriate test description and follow the recommended procedures.
2. G3iV1.1-286 and G3iV2-386 only.

## Notes:

- a. Could experience a noisy port or link. This is an off-board problem detected by the port circuit. Check for faulty wiring, check for a defective data module, or reduce the cabling distance between the data module and the PBX (5000 feet for 24-gauge wire and 4000 feet for 26-gauge wire; see Note). If the problem still exists, replace the circuit pack. Once the problem has been resolved, the alarm is retired automatically within 60 minutes.

The DA module is not phantom-powered from the port and hence its range is limited by the Italtel digital phone's limit (0.7 km, 2300 feet, on 26-gauge wire or 1.8 km, 5900 feet, on 22-gauge, 0.6 mm, wire) if in **linked mode**, or by the maximum length of loop allowed from the Digital Line Interface (DLI) component (up to 3.5 km, about 2 miles, with 22-gauge, 0.6 mm, wire) if in **stand-alone mode**.

 NOTE:

Refer to the *DEFINITY Communications System Generic 1 and Generic 3i Wiring*, (555-204-111).

- b. This error type and auxiliary data occur when at least 15 off-board problems have been detected with the link to the data module. When an error with the link is detected, an on-board counter is incremented.

The user could experience a noisy port or link. This is an off-board problem detected by the port circuit. Check for faulty wiring, check for a faulty data module, or reduce the cabling distance between the data module and the PBX (5000 feet for 24-gauge wire and 4000 feet for 26-gauge wire; see the next Note). If the problem still exists, replace the circuit pack. Once the problem has been resolved, the alarm is retired automatically within 60 minutes.

The DA module is not phantom-powered from the port and hence its range is limited by the Italtel digital phone's limit (0.7 km, 2300 feet, on 26-gauge wire or 1.8 km, 5900 feet, on 22-gauge, 0.6 mm, wire) if in **linked mode**, or by the maximum length of loop allowed from the Digital Line Interface (DLI) component (up to 3.5 km, about 2 miles, with 22-gauge, 0.6 mm, wire) if in **stand-alone mode**.

 NOTE:

Refer to the *DEFINITY Communications System Generic 1 and Generic 3i Wiring*, 555-204-111.

- c. This is an internal type error that occurs when an audit request fails.
- d. This error type is logged when the port in question is busied out by maintenance personnel. Make sure that the port is released from busyout.
- e. There are problems with transmitting to the data module. This is usually an on-board problem and can be ignored if no user complaints are received. Otherwise, check for faulty wiring.

- f. This error indicates that EPF has been turned off due to the overcurrent condition at the data module. Make sure that the data module is connected. Look for faulty wiring or a defective data module, or reduce the cabling distance between the data module and the PBX (5000 feet for 24-gauge wire and 4000 feet for 26-gauge wire; see Note). If the problem still exists, it may be due to the fact that the PTC is in the “tripped” position due to a short on the power line. This can be corrected by removing the short, unplugging the data module from the wall for about 30 seconds, and plugging it back in. If the problem persists, replace the Digital Line circuit pack. Once the problem has been resolved, the alarm is retired after a predetermined period of time since this counter uses a “leaky bucket” strategy.

The DA module is not phantom-powered from the port and hence its range is limited by the Italtel digital phone’s limit (0.7 km, 2300 feet, on 26-gauge wire or 1.8 km, 5900 feet, on 22-gauge, 0.6 mm, wire) if in **linked mode**, or by the maximum length of loop allowed from the Digital Line Interface (DLI) component (up to 3.5 km, about 2 miles, with 22-gauge, 0.6 mm, wire) if in **stand-alone mode**.

**NOTE:**

Refer to the *DEFINITY Communications System Generic 1 and Generic 3i Wiring*, 555-204-111.

- g. An in-line maintenance error has generated an off-board warning due to some problem with the link to the data module. This can be ignored if no user complaints are received. Otherwise, make sure the data module is connected, check for faulty wiring, check for a defective data module, or reduce the cabling distance between the data module and the PBX (5000 feet for 24-gauge wire and 4000 feet for 26-gauge wire, see Note). If the problem still exists, replace the circuit pack. Once the problem has been resolved, the alarm is retired automatically within 90 minutes.

The DA module is not phantom-powered from the port and hence its range is limited by the Italtel digital phone’s limit (0.7 km, 2300 feet, on 26-gauge wire or 1.8 km, 5900 feet, on 22-gauge, 0.6 mm, wire) if in **linked mode**, or by the maximum length of loop allowed from the Digital Line Interface (DLI) component (up to 3.5 km, about 2 miles, with 22-gauge, 0.6 mm, wire) if in **stand-alone mode**.

**NOTE:**

Refer to the *DEFINITY Communications System Generic 1 and Generic 3i Wiring*, 555-204-111.

- h. This indicates that the data equipment went off-hook while the associated link was being initialized (in a disconnected state). Use the [status data-module](#) command on page [4-195](#) to determine the state of the data module. The off-hook should have changed the service state to in-service. No system technician action is necessary.

5 Maintenance Objects for DEFINITY ONE  
PDMODULE, TDMODULE (Data Module)

5-900

- i. This is the resulting code that is generated when the link between the circuit pack and the data module is successfully reset. The link is normally reset when the circuit pack associated with an administered port is first plugged in (assuming that the data module is already in place and connected to the associated port), when a port is first administered (assuming the associated circuit pack is plugged in and that the data module is connected to the associated port), or when a data module is first connected to an administered port. No system technician action is necessary.
- j. This warning off-board alarm occurs only for G3iV1.1-286 or G3iV2-386. The alarm occurs when it appears to the system that a DCP endpoint has been disconnected.
- k. A DCP endpoint may have been disconnected.
- l. This endpoint is part of processor link. Link initialization has failed (or demand test for #183 for PI links has failed) and is indicating the associated PDM as the cause. Check the PDM, the wiring to the PDM and the link to the far end (i.e. AUDIX DCS, etc.) to resolve the problem.

## System Technician-Demanded Tests: Descriptions and Error Codes

Always investigate tests in the order presented in the table below when inspecting errors in the system. By clearing error codes associated with the *Data Module Internal Loop Around Test*, for example, you may also clear errors generated from other tests in the testing sequence.

For example, you may also clear errors generated from other tests in the testing sequence.

Order of Investigation	Short Test Sequence	Long Test Sequence	D/ND <sup>1</sup>
Data Module Internal Loop Around Test (#175)		X	ND
Network Processing Element Crosstalk Test (#9)		X	ND
Information and Control Channel Loop Around Test (#13)		X	ND
Data Module Audits Test (#17)	X	X	ND

1. D = Destructive; ND = Nondestructive

**NPE Crosstalk Test (#9)**

One or more NPEs reside on each circuit pack with a TDM Bus interface. The NPE controls port connectivity and gain, and provides conferencing functions on a per-port basis. The NPE Crosstalk Test verifies that this port's NPE channel talks on the selected time slot and never crosses over to time slots reserved for other connections. If the NPE is not working correctly, one-way and noisy connections may be observed. If a secondary data module is assigned, it is tested after the primary data module. If either test fails, both data modules are taken out of service. This test usually runs only during the Long Test Sequence and takes about 20 to 30 seconds to complete.

**Table 5-370. TEST #9 NPE Crosstalk Test**

Error Code	Test Result	Description/ Recommendation
1	ABORT	<p>During testing of the primary information channel, system resources may not have been available.</p> <ol style="list-style-type: none"> <li>1. Check the port status. Use the <a href="#">display port PCSSpp</a> command on page <a href="#">4-59</a> to determine the station extension of the port. Use the <a href="#">status station</a> command on page <a href="#">4-213</a> to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for this test. You must wait until the port is idle.</li> <li>2. If the port status is idle, then retry the command at one-minute intervals a maximum of 5 times.</li> </ol>
1000	ABORT	<p>System resources required to run this test are not available. The port may be busy with a valid call. Use the <a href="#">display port PCSSpp</a> command on page <a href="#">4-59</a> to determine the extension of the data module port. Use the <a href="#">status data-module</a> command on page <a href="#">4-195</a> to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. (Refer to the "status commands" sections in <a href="#">Chapter 4, "Maintenance Commands for DEFINITY ONE"</a> for a full description of all possible states). You must wait until the port is idle before retesting.</p> <ol style="list-style-type: none"> <li>1. If the port status is idle, retry the command at one-minute intervals a maximum of 5 times.</li> </ol>
1001	ABORT	<p>System resources to run this test are not available.</p> <ol style="list-style-type: none"> <li>1. Retry the command at one-minute intervals a maximum of 5 times.</li> </ol>
1002	ABORT	<p>The system could not allocate time slots for the test. The system may be under heavy traffic conditions or it may have time slots out-of-service due to TDM-BUS errors. Refer to <a href="#">"TDM-BUS (TDM Bus)" on page 5-1116</a> to diagnose any active TDM-BUS errors.</p> <ol style="list-style-type: none"> <li>1. If the system has no TDM-BUS errors and is not handling heavy traffic, repeat the test at one-minute intervals a maximum of 5 times.</li> </ol>

*Continued on next page*

Table 5-370. TEST #9 NPE Crosstalk Test — *Continued*

Error Code	Test Result	Description/ Recommendation
1003	ABORT	<p>The system could not allocate a tone receiver for the test. The system may be oversized for the number of Tone Detectors present or some Tone Detectors may be out-of-service.</p> <ol style="list-style-type: none"> <li>1. Look for TTR-LEV errors in the Error Log. If present, refer to <a href="#">“TTR-LEV (TTR Level)” on page 5-1223</a>.</li> <li>2. Look for TONE-PT errors in the Error Log. If present, refer to <a href="#">“TONE-PT (Tone Generator)” on page 5-1204</a>.</li> <li>3. If neither condition exists, retry the test at one-minute intervals a maximum of 5 times.</li> </ol>
1004	ABORT	<p>The port may be busy with a valid call. Use the <a href="#">display port PCSSpp</a> command on page <a href="#">4-59</a> to determine the extension of the data module port. Use the <a href="#">status data-module</a> command on page <a href="#">4-195</a> to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. (Refer to the “status commands” sections in <a href="#">Chapter 4, “Maintenance Commands for DEFINITY ONE”</a> for a full description of all possible states). You must wait until the port is idle before retesting.</p> <ol style="list-style-type: none"> <li>1. Retry the command at one-minute intervals a maximum of 5 times.</li> <li>2. If the test continues to abort and the port is not in use, escalate the problem.</li> </ol>
1020	ABORT	<p>Test disabled via background testing. Use <a href="#">status data-module</a> command on page <a href="#">4-195</a> to determine when the data module is available for testing.</p>
2000	ABORT	<p>Response to the test request was not received within the allowable time period.</p> <ol style="list-style-type: none"> <li>1. Retry the command at one-minute intervals a maximum of 5 times.</li> </ol>
2020	ABORT	<p>The test did not run due to a previously existing error on the specific port or a more general circuit pack error.</p> <ol style="list-style-type: none"> <li>1. Examine Error Log for existing errors against this port or the circuit pack and attempt to diagnose the previously existing error.</li> </ol>
2100	ABORT	<p>Could not allocate the necessary system resources to run this test.</p> <ol style="list-style-type: none"> <li>1. Retry the command at one-minute intervals a maximum of 5 times.</li> </ol>
2500	ABORT	<p>Internal System Error.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>

*Continued on next page*

Table 5-370. TEST #9 NPE Crosstalk Test — *Continued*

Error Code	Test Result	Description/ Recommendation
1,2	FAIL	The NPE of the tested port was found to be transmitting in Error Log. This causes noisy and unreliable connections. Failure Code 1 indicates that the Crosstalk Test failed on the primary channel. Failure Code 2 indicates that the Crosstalk Test failed on the secondary channel.  1. Replace the circuit pack.
	PASS	The port is correctly using its allocated time slots.  1. To be sure that this is not an intermittent problem, repeat this test up to a maximum of 10 times and verify that it continues to pass.  2. If complaints still exist, examine the data module, connections, and wiring.

## Information and Control Channel Local Loop Test (#13)

This is a set of four tests that check the operation of the information and control channels used between the SPE and the Digital Line port circuit.

### NOTE:

This is an Internal Loop Around test only and does not check building wiring. Use Test #175 for external loop around tests to the data module.

1. The SPE first sends a message to the on-board microprocessor to loop around both the information and control channels for the port. Then, the primary information channel loop back test is run. The test is performed by sending a digital count from the Tone-Clock circuit pack on the primary channel time slot and receiving the same digital count with a GPTD. The digital count looks like transparent data to the on-board microprocessor.
2. With the port still in loop around mode, the S channel Loop Around Test is performed next. This test consists of sending four different transparent patterns to the on-board microprocessor, receiving them back, and comparing them.
3. The third test is a Loop Around Test for the secondary (alternate) channel. It is not performed for data modules since this channel is not used by MPDMs, MTDMs, and stand-alone DA's [G3iV2-386].
4. A Conference Test is done next for the primary channel. This test is the same as the Analog Line Terminal/Port Conference Test (#6).

Only one value (Pass, Fail, or Abort) is generated as a result of four tests run. If any test fails or aborts, the sequence is stopped.

5 Maintenance Objects for DEFINITY ONE  
PDMODULE, TDMODULE (Data Module)

5-904

Table 5-371. TEST #13 Information and Control Channel Local Loop Test

Error Code	Test Result	Description/ Recommendation
	ABORT	Internal System Error. 1. Retry the command at one-minute intervals a maximum of 5 times.
1000	ABORT	System resources required to run test are not available. Port may be busy with a valid call. Use <a href="#">display port PCSSpp</a> command on page <a href="#">4-59</a> to determine the data module extension. Then use <a href="#">status data-module</a> command on page <a href="#">4-195</a> with the extension number to determine the service state of the data module. If the service state indicates that the data module is in use, then port is unavailable for certain tests. Wait until port is idle before retesting. 1. If the port status is idle, retry the command at one-minute intervals a maximum of 5 times.
1001	ABORT	System resources required to run this test are not available. 1. Retry the command at one-minute intervals a maximum of 5 times.
1002	ABORT	The system could not allocate time slots for the test. The system may be under heavy traffic conditions or it may have time slots out-of-service due to TDM-BUS errors. Refer to <a href="#">"TDM-BUS (TDM Bus)" on page 5-1116</a> to diagnose any active TDM-BUS errors. 1. If the system has no TDM-BUS errors and is not handling heavy traffic, repeat the test at one-minute intervals a maximum of 5 times.
1003	ABORT	The system could not allocate a tone receiver for the test. The system may be oversized for the number of Tone Detectors present or some Tone Detectors may be out-of-service. 1. Look for TTR-LEV errors in the Error Log. If present, refer to <a href="#">"TTR-LEV (TTR Level)" on page 5-1223</a> . 2. Look for TONE-PT errors in the Error Log. If present, refer to <a href="#">"TONE-PT (Tone Generator)" on page 5-1204</a> . 3. If neither condition exists, retry the command at one-minute intervals for a maximum of 5 times.
1004	ABORT	The port was seized by a valid call during the test. The test has been aborted. Use the <a href="#">display port PCSSpp</a> command on page <a href="#">4-59</a> to determine the data module extension. Then use the <a href="#">status data-module</a> command on page <a href="#">4-195</a> with the extension number to determine the service state of the data module. If the service state indicates that the data module is in use, then the port is unavailable for certain tests. You must wait until the port is idle before retesting.
2000	ABORT	Response to the test request was not received within the allowable time period. 1. Retry the command at one-minute intervals a maximum of 5 times.

Continued on next page

Table 5-371. TEST #13 Information and Control Channel Local Loop Test — Continued

Error Code	Test Result	Description/ Recommendation
2001	ABORT	System resources required to run this test are not available. 1. Retry the test at one-minute intervals a maximum of 5 times.
2100	ABORT	Could not allocate the necessary system resources to run this test. 1. Rerun the test at one-minute intervals a maximum of 5 times.
2500	ABORT	Internal System Error 1. Retry the command at 1-minute intervals a maximum of 5 times.
15	FAIL	The control channel between the processor and Digital Line circuit pack is not transmitting properly. This can cause a wide range of effects. The user may notice nothing or the port may be totally unusable. This could also disrupt other users. 1. Run circuit pack tests to check the Tone Generator and the Tone Detector circuit packs using the <a href="#">test board UUCSS short</a> command on page <a href="#">4-237</a> . 2. Resolve any problems that are detected on the Tone Generator circuit pack or Tone Detector circuit pack. 3. If the Tone Generator and Tone Detector circuit packs are functioning properly, and the test still fails, replace the Digital Line circuit pack.
7	FAIL	Conference test failed on the primary information channel. In some cases, user may not notice disruption in service. In extreme cases, conferencing feature may not work at all.
14	FAIL	The primary information channel is not transmitting properly. User impact may range from noticing nothing to not being able to use this port.
15	FAIL	The control channel between the processor and Digital Line circuit pack is not transmitting properly. This can cause a wide range of effects. The user may notice nothing or the port may be totally unusable. This could also disrupt other users. 1. Run circuit pack tests to check the Tone Generator and the Tone Detector circuit packs using the <a href="#">test board UUCSS short</a> command on page <a href="#">4-237</a> . 2. Resolve any problems that are detected on the Tone Generator circuit pack or Tone Detector circuit pack. 3. If the Tone Generator and Tone Detector circuit packs are functioning properly, and the test still fails, replace the Digital Line circuit pack.

Continued on next page

Table 5-371. TEST #13 Information and Control Channel Local Loop Test — *Continued*

Error Code	Test Result	Description/ Recommendation
16	FAIL	The secondary information is not transmitting properly. This can cause a wide range of effects. The user may notice nothing or the port may be totally unusable. <ol style="list-style-type: none"><li>1. To be sure that this is not an intermittent problem, repeat this test up to a maximum of 10 times to make sure it continues to pass.</li><li>2. If complaints still exist (poor data transmission), examine the data module, connections, and wiring.</li></ol>
	PASS	Information and Control Channel Local Loop Test passed. All channels are transmitting properly.

### Data Module Audits Test (#17)

This is a series of six tests that are classified as hardware audits. The processor sends messages to the on-board microprocessor to perform the following tests. [G1] The audits run only if the station is in-service.

- Switchhook Inquiry — This is an update of the processor's software records based on the on-hook/off-hook status of the data module.
- Bad Scan Inquiry — A message is sent uplink that contains a count generated by certain events relating to the digital loop's (link) conditions. This could be an indication of communication problems between the processor and digital port circuit pack.
- EPF inquiry — The status of the EPF is sent uplink. EPF is not used for data modules.
- ID Request — A request is made to the data module for its status. The data module sends its configuration information and health information back. This information is checked and a pass/fail result is provided.
- Ringer Update — This updates the data module's ringer state according to processor records.
- Translation Update — This is a message normally used with digital stations to refresh the default value that causes the station to send touch-tones only in the primary information channel. This test is not used with data modules.

Table 5-372. TEST #17 Data Module Audits Test

Error Code	Test Result	Description/ Recommendation
1	ABORT	<p>Switchhook audit timed out.</p> <ol style="list-style-type: none"> <li>1. Verify the data module is connected to the PBX and repeat the test.</li> <li>2. If the test aborts, replace the data module and repeat the test.</li> <li>3. If the test continues to abort, replace the circuit pack and repeat the test.</li> </ol>
2	ABORT	<p>ID request fails, health bit is defective, or no response from on-board microprocessor.</p> <ol style="list-style-type: none"> <li>1. Verify that the correct data module type (PDM versus TDM) is administered.</li> <li>2. If the test aborts, replace the data module and repeat the test.</li> <li>3. If the test aborts, replace the circuit pack and repeat the test.</li> </ol>
3	ABORT	No response from EPF audit.
4	ABORT	<p>Internal System Error.</p> <ol style="list-style-type: none"> <li>1. Resolve any outstanding circuit pack maintenance problems.</li> <li>2. Retry the command at one-minute intervals a maximum of 5 times.</li> </ol>
5	ABORT	<p>Ringer update aborted (data module not in the in-service state).</p> <ol style="list-style-type: none"> <li>1. Verify that the data module is powered (power LED on).</li> <li>2. Make sure data module is connected to the building wiring, check for faulty wiring, check for faulty data module.</li> <li>3. Retry the command at one-minute intervals a maximum of 5 times.</li> <li>4. Replace the Data Module and repeat the test.</li> <li>5. If the test continues to abort, replace the Digital Line circuit pack and repeat the test.</li> </ol>
6	ABORT	<p>Data module translation update aborted.</p> <ol style="list-style-type: none"> <li>1. Verify the data module is connected to the PBX.</li> <li>2. Retry the command at one-minute intervals a maximum of 5 times.</li> </ol>
1000	ABORT	System resources required to run this test are not available.
2000	ABORT	Response to the test request was not received within the allowable time period.
	FAIL	<p>Internal System Error.</p> <ol style="list-style-type: none"> <li>1. Retry the command at one-minute intervals a maximum of 5 times.</li> </ol>

*Continued on next page*

Table 5-372. TEST #17 Data Module Audits Test — Continued

Error Code	Test Result	Description/ Recommendation
	PASS	Data Module Audits passed. This digital port circuit pack is functioning properly.  1. If complaints still exist, investigate by using other port tests, and by examining the data module options, wiring, and connections.

### Data Module Internal Loop Around Test (#175)

This test verifies that a data message can be sent from the PBX, through the building wiring, through an internal looparound path in the data module under test, and back to the PBX. [Figure 5-47](#) shows the hardware configuration used for this test.




Figure 5-47. Internal Loop Around Test

A signaling message is sent through the digital port circuit pack to the data module under test to request it to enter loop around mode. A test pattern is then sent from the SPE through the Network Control circuit pack (Netcon), over the TDM Bus, through the digital port circuit pack, to the data module where the message is looped around, and sent back through the digital port circuit pack, the TDM Bus, the Network Control circuit pack, and to the SPE where it is checked for consistency.

This test aborts if no terminal or communications equipment is connected to the data module. It also aborts if a number of local PBX resources are not available. These resources include a network control channel from the Network Control circuit pack (there are a maximum of four channels administered as Netcon-type data modules), two TDM time slots (one for each direction of the loop around message), and an idle digital port circuit associated with the data module under test. Failure to allocate any of these resources causes the test to abort with a specific error code for that resource.

A "yes/no" parameter on each data module (MPDM, MTDM, or stand-alone DA only) administration form is required to specify if the Data Module remote Loop Around Test is supported by the data module endpoint. If the parameter is "n" (no), the test does not run.

**Table 5-373. TEST #175 Data Module Internal Loop Around Test**

Error Code	Test Result	Description/ Recommendation
1000	ABORT	Could not get translation information for port. <ol style="list-style-type: none"><li>1. Verify that port circuit is administered.</li><li>2. Wait one minute and attempt the test again.</li><li>3. If the test continues to abort and the port is not in use, escalate the problem.</li></ol>
1005	ABORT	This test is not applicable to the given hardware configuration. <ol style="list-style-type: none"><li>1. This abort message can be ignored.</li></ol>
1020	ABORT	Internal Software Error. <ol style="list-style-type: none"><li>1. Retry the command at one-minute intervals a maximum of 5 times.</li></ol>
1030	ABORT	Internal software group identifier for data module not valid. <ol style="list-style-type: none"><li>1. Verify that port circuit is administered correctly.</li><li>2. If administration data correct, escalate the problem.</li></ol>

*Continued on next page*

Table 5-373. TEST #175 Data Module Internal Loop Around Test — *Continued*

Error Code	Test Result	Description/ Recommendation
1031	ABORT	Extension number not valid.
1032	ABORT	Extension number not correct length. <ol style="list-style-type: none"> <li>1. Verify that the data module extension is administered correctly.</li> <li>2. If the administration data is correct, escalate the problem.</li> </ol>
1071	ABORT	No auxiliary port on Netcon circuit pack available to test with. <ol style="list-style-type: none"> <li>1. Check that the Netcon data channels are administered (the <b>list data-modules</b> command should show at least one Netcon-type data module).</li> <li>2. Test the Network Control (Netcon) circuit pack using the <a href="#">test data-module</a> command on page <a href="#">4-243</a> for the Netcon circuit pack.</li> <li>3. If administration data is correct, escalate the problem.</li> </ol>
2000	ABORT	Data module disconnected. <ol style="list-style-type: none"> <li>1. Verify that the data module is powered (power LED on).</li> <li>2. Make sure data module is connected to the building wiring. Check for faulty wiring and faulty data module.</li> <li>3. Retry the command at one-minute intervals a maximum of 5 times.</li> <li>4. Replace the Data Module and repeat the test.</li> <li>5. If the test continues to abort, replace the Digital Line circuit pack and repeat the test.</li> </ol>
2500	ABORT	Internal System Error. <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
3004	ABORT	<ol style="list-style-type: none"> <li>1. This error could be caused by the switch setting of the PDM. Verify that the switch on the PDM is set to the "remote loop" position. When the remote loop around test is completed, return the switch to the "off" position.</li> <li>2. This error could be caused by the Network Control Data Channel. Look for DATA-CHL errors in the Hardware Error Log.</li> <li>3. This error could also result if no data equipment is connected to the data module. Verify that (a) the data equipment is properly connected to the data module, (b) that power is available to the data equipment, and that (c) the data equipment is powered on.</li> <li>4. This error could also occur if the baud rate of the data module is set to 19.2 Kbps since the Network Control circuit pack used by this test does not support baud rates greater than 9600 bps. Verify that the baud rate of the data module is set to 9600 bps or less.</li> </ol>

*Continued on next page*

Table 5-373. TEST #175 Data Module Internal Loop Around Test — *Continued*

Error Code	Test Result	Description/ Recommendation
1040	FAIL	Data received from remote loop back does not match data sent. <ol style="list-style-type: none"><li>1. Check for faulty wiring.</li><li>2. Replace the data module and repeat the test.</li><li>3. If the test fails, replace the Digital Line circuit pack associated with the data module and repeat the test.</li></ol>
1070	FAIL	Internal software response. <ol style="list-style-type: none"><li>1. Wait one minute and attempt the test again.</li><li>2. If the same error persists after five attempts in one-minute intervals, escalate the problem.</li></ol>
1072	FAIL	Poor response from auxiliary channel. <ol style="list-style-type: none"><li>1. Test the Network Control (Netcon) circuit pack using the <a href="#">test data-module</a> command on page <a href="#">4-243</a>.</li><li>2. If the test fails, replace the Digital Line circuit pack.</li></ol>
1073	FAIL	Internal System Error. <ol style="list-style-type: none"><li>1. Wait one minute and attempt the test again.</li><li>2. If the same error persists after five attempts in one-minute intervals, escalate the problem.</li></ol>
1074	FAIL	Internal System Error. <ol style="list-style-type: none"><li>1. Make sure that the data equipment connected to the data module is powered.</li><li>2. For an (M)PDM, verify that the Data Terminal "Ready" LED is ON, or for an (M)TDM, verify that the Data Set Ready LED is ON. If it is not on, check the cable from the data equipment to the data module.</li></ol>
1075	FAIL	Unknown message received during test. <ol style="list-style-type: none"><li>1. Attempt the test again.</li><li>2. If the same error occurs, test the Network Control Data Channel using the <a href="#">test data-module</a> command on page <a href="#">4-243</a> and a known working data module.</li><li>3. Replace the Digital Line circuit pack and repeat the test.</li><li>4. If the test continues to fail, escalate the problem.</li></ol>

*Continued on next page*

5 Maintenance Objects for DEFINITY ONE  
PDMODULE, TDMODULE (Data Module)

5-912

Table 5-373. TEST #175 Data Module Internal Loop Around Test — *Continued*

Error Code	Test Result	Description/ Recommendation
2040	FAIL	Internal System Error.
2095	FAIL	Internal System Error. 1. Repeat the test.
	PASS	Data Module Loop Around Test passed. This digital port circuit pack is functioning properly. 1. If problems persist, investigate by using other port tests and by examining the data module options, wiring, and connections.

## PE-BCHL (PRI Endpoint Port)

---

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run	Full Name of MO
PE-BCHL <sup>1</sup>	MINOR	test port PCSSpp l	PRI Endpoint Port
PE-BCHL	WARNING	test port PCSSpp sh	PRI Endpoint Port

1. For additional repair information, see also UDS1-BD (UDS1 Interface Circuit Pack) maintenance documentation and ["Troubleshooting PRI endpoint problems"](#) in [Chapter 1, "Maintenance Concepts for DEFINITY ONE"](#).

A PRI Endpoint provides ISDN-PRI (Primary Rate Interface) connections for customers with application equipment or terminal adapters that terminate ISDN-PRI. The equipment or terminal adapters are connected to the switch via the UDS1 interface circuit pack. PRI Endpoint Port (PE-BCHL) maintenance provides a strategy to maintain PRI Endpoint Port hardware circuitry on the UDS1 circuit pack. The maintenance strategy involves logging PRI Endpoint Port hardware errors, running tests for port initialization, periodic and scheduled maintenance, system technician-demanded tests, and alarm escalation and resolution.

## Wideband Switching

---

The Wideband Switching capability supports end-to-end connectivity between customer endpoints at data rates from 128 to 1536 kbps over T1 facilities and to 1984 kbps over E1 facilities. DEFINITY switching capabilities are extended to support wideband calls comprised of multiple DS0s that are switched end-to-end as a single entity.

The Wideband Switching capability is designed for ISDN application equipment (for example, ISDN video codecs), but it retains provisions for non-ISDN application equipment by using PRI terminal adapters. In the same sense that a DEFINITY data module acts as a DCP or BRI terminal adapter between endpoint data (for example, V.35) and dialing (for example, RS-366) interfaces and a DCP interface, a PRI terminal adapter acts as a wideband terminal adapter between endpoint data and dialing interfaces and DEFINITY's line-side ISDN PRI interface.

The Wideband Switching Capability introduces PRI Endpoints on DEFINITY line-side interfaces. A PRI Endpoint consists of one or more contiguous B-channels on a line-side T1 or E1 ISDN PRI facility, and it has an extension number. Endpoints initiate and receive calls using ISDN SETUP messages that indicate the data rate and specific B-channels to be used, and they communicate all other call status information via standard ISDN messages. Any DEFINITY ISDN signaling set (for example, AT&T, CCITT, ECMA) may be used for a line-side ISDNPRI facility.

Multiple PRI Endpoints on a one line-side facility are separate and distinct within the facility. Non-overlapping contiguous sets of B-channels are associated with each PRI Endpoint, and the endpoint equipment is expected to initiate calls within these boundaries.

The endpoint application equipment must be able to do the following: use standard ISDN-PRI signaling, adhere to the PRI Endpoint boundaries as administered on DEFINITY when initiating calls, and handle incoming calls appropriately based on the PRI Endpoint.

## Signaling and B-channel States

These ports use a separate channel for signaling (for example, for call setup). This mode of operation is known as out-of-band signaling. The separate signaling channel is called a D-channel in ISDN terminology, and it carries all the call control signaling messages for the PRI Endpoint Port B-channels. The D-channel for these B-channels is an ISDN-PRI Signaling Link Port (ISDN-LNK). The signaling protocol used on the ISDN-PRI Signaling Link Port D-channel is defined by one of the four selectable ISDN-PRI Specifications: AT&T, CCITT, ECMA, and ANSI.

The ISDN-PRI Specification defines the possible SERVICE STATES for a B-channel. The service state is negotiated with the far-end terminal adapter, and it changes over time. Also, the service state may have a far-end or near-end component, and it is initialized to the Out-Of-Service/Far-End state. An attempt is made to negotiate the service state to In-Service.

### NOTE:

The service state of a particular PRI Endpoint Port B-channel can be displayed by issuing the **status pri-endpoint <extension>** system technician command.

If a call is present, the ISDN-PRI Specification defines the permissible CALL STATES as well. There are tests in the short and long test sequences for PRI Endpoint Port that are designed to audit these states and to ensure agreement between both ends of the PRI wideband connection.

## Alarming Based on Service States:

A PRI Endpoint Port B-channel is alarmed with a WARNING if it is placed into a Maintenance/Far-End or Out-Of-Service/Far-End state. While in such a state, the port is unusable for calls to the terminal adapter. However, the user can still use the other remaining ports in the PRI Endpoint to make calls to and from the terminal adapter. When a WARNING alarm is raised, the **status pri-endpoint <extension>** command should be used to determine the exact state of the port. Other alarms can be diagnosed by using the short and/or long test sequences. Note that a PRI Endpoint Port B-channel can be placed into a Far-End Service State either by direct action of the far-end terminal adapter or by inaction of the far-end terminal adapter. For example, if they do not respond to a Remote Layer 3 Query (see Test #260 for ISDN-PRI Signaling Link Port), the associated PRI Endpoint Port B-channels are placed into the Maintenance/Far-End service state.

A PRI Endpoint Port is a port on a UDS1 interface circuit pack. Therefore, this port depends on the health of the UDS1 interface circuit pack for proper operation (see [Figure 5-48](#)). As noted earlier, a PRI Endpoint Port B-channel also depends on an ISDN-PRI Signaling Link Port D-channel (ISDN-LNK) to carry the signaling traffic. If there is a problem with the ISDN-PRI Signaling Link Port, the PRI Endpoint Port is affected. The ISDN-PRI Signaling Link Port, in turn, depends on the PKT-INT (Packet Interface).




Figure 5-48. PRI Endpoint Port Interactions [INTEL]

## PRI Endpoint Port Service States

---

This section defines the possible service states of a PRI Endpoint Port, and it explains the reason for each service state. This section also provides the recommended recovery procedures (when required).

### Service States

- **In-Service (INS)**

The B-channel is in its normal operating state.
- **Out-of-Service/Far-end (OOS/FE)**

A B-channel is initialized to this state when administered. The switch sends messages to the far-end terminal adapter to negotiate the B-channel into service. If the far-end terminal adapter does not respond to the messages within a certain time period, the service state remains out-of-service, and maintenance periodically resends the messages. The port is unusable for calls incoming to the switch and outgoing to the terminal adapter (although other ports in the PRI Endpoint can still be used for incoming and outgoing calls).
- **Out-of-Service/Near-end (OOS/NE)**

This is the state of the port whenever one of the following is true: a hardware failure exists on the signaling link, the NPE Crosstalk Test fails, or the port is busied out by system technician. In this state, the port is unusable for calls incoming to the switch or outgoing to the terminal adapter (although other ports in the PRI Endpoint can still be used for incoming and outgoing calls). No messages are sent to the far-end terminal adapter until the signaling link comes back into service or until the port is released by system technician.
- **Maintenance/Far-end (MTC/FE)**

This state is reached when the far-end terminal adapter does not respond to messages sent over the signaling link for a particular port after a certain amount of time. This state is different from OOS/FE inasmuch as the signaling link must be up initially and the B-channels must be in-service. The switch periodically sends messages to the far-end terminal adapter in an attempt to negotiate the port (B-channel) into service. The port is unusable for calls outgoing to the terminal adapter. However, the port services incoming call requests from the far-end (although other ports of the PRI Endpoint can still be used to answer calls incoming to the switch or to place outgoing calls to the terminal adapter). Note that transitions into MTC/FE do not drop stable calls. Therefore, if the service state changes from in-service to MTC/FE, stable calls are unaffected.

## 5 Maintenance Objects for DEFINITY ONE

### PE-BCHL (PRI Endpoint Port)

5-917

#### ■ Maintenance/Near-end (MTC/NE)

The port (B-channel) is in this state if the signaling link (PKT-INT) is busied out by system technician. The port (B-channel) is also temporarily in this state if the system technician has issued a **test port PCSSpp I** or a **test pri-endpoint <extension> I** command. Note that transitions into MTC/NE do not drop stable calls. Therefore, a system technician-demanded **busyout link lnk-no** command does not drop stable wideband calls. In this state, the B-channel is not usable either for new calls incoming to the switch or for new calls outgoing to the terminal adapter.

#### ■ Pending States (PEND)

If the near-end is expecting a timed response from the far-end for a request to change the service state of a port, the state of the port reflects a Pending state. For example, if the port is out-of-service/far-end and if an in-service message is sent to the far-end, the service state of the port is OOS/FE-PEND/INS (that is, out-of-service/far-end-Pending/in-service). The far-end has a certain amount of time to respond to the message. The service state reflects this pending state until the timer expires.

The following diagram of the PRI Endpoint Port service states shows the common progression from one service state to another and the event that caused the change of state.




Figure 5-49. Common Progressions in Service States

### PRI Endpoint Port Service States

The following table summarizes each of the different PRI Endpoint Port service states that can result when the **status pri-endpoint <extension>** command is issued. From the results of the status command, match the service state to the corresponding column. Proceed down the column until an “X” is found. The left column indicates possible reasons why the port is in this state, and the right column suggests possible recovery mechanisms. If an alarm against PE-BCHL is present, it is indicated below the “X.”

**⇒ NOTE:**

Refer to [“Troubleshooting PRI endpoint problems” on page 2-33](#) for a layered approach to the processing of PRI Endpoint problems.

5 Maintenance Objects for DEFINITY ONE  
PE-BCHL (PRI Endpoint Port)

5-919

Table 5-374. PRI Endpoint Port Service States

Possible Problem Source	O/S-NE	O/S-FE	O/S- FE Pend- ins	maint-NE	maint- FE	maint-FE Pend- ins	INS	Possible Recovery Route
ISDN wideband calls being completed.							X	Normal Operation.
Port busied out by system technician ?	X Warn Alarm							Release port by the <b>release pri-endpoint extension</b> or <b>release port PCSSpp</b> .
NPE Crosstalk Test failed?	X Minor Alarm							Replace UDS1 Interface CP.
DS1 circuit pack lost signal?	X							UDS1 Interface CP removed? DS1 cable disconnected? Terminal adapter problems? Far-end terminal adapter restarting? Faulty UDS1 Interface CP?
Check UDS1-BD.								Refer to " <a href="#">UDS1-BD (UDS1 Interface Circuit Pack)</a> " on <a href="#">page 5-1227</a> for repair procedures.

Continued on next page

5 Maintenance Objects for DEFINITY ONE  
PE-BCHL (PRI Endpoint Port)

5-920

Table 5-374. PRI Endpoint Port Service States — *Continued*

Possible Problem Source	O/S-NE	O/S-FE	O/S- FE Pend- ins	maint-NE	maint- FE	maint-FE Pend- ins	INS	Possible Recovery Route
Far-end problems?		X Warn Alarm						Check administration and the status of the corresponding port on the far-end terminal adapter.
Service Message sent, waiting for reply from far-end terminal adapter (2 minutes).			X			X		Wait a couple minutes until Pending State not present, check service state.
Processor Interface Link busied out by system technician ? Check link status. [MIPS only].				X				Release link by the <b>release link lnk-no.</b>

*Continued on next page*

5 Maintenance Objects for DEFINITY ONE  
PE-BCHL (PRI Endpoint Port)

5-921

Table 5-374. PRI Endpoint Port Service States — *Continued*

Possible Problem Source	O/S-NE	O/S-FE	O/S- FE Pend- ins	maint-NE	maint- FE	maint-FE Pend- ins	INS	Possible Recovery Route
Signaling link has been down for over 90 seconds?					X Warn Alarm			See ISDN-SGRP, ISDN-LNK, PKT-INT and/or SYS-LINK and follow repair procedures. Is far-end terminal adapter currently restarting?
Repeated failure of far-end to respond to messaging ?					X Warn Alarm			Periodically Maintenance will try to resend messages. To speed process, run system technician-demand ed test <b>test port PCSSpp</b> (Test #256).
Far-end port busied out (OOS/FE). Far-end port being tested (MTCE/FE)		X Warn Alarm			X Warn Alarm			Check status of far-end terminal adapter.

## Error Log Entries and Test to Clear Values

Table 5-375. PRI Endpoint Port Error Log Entries

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
0 <sup>1</sup>	0	Any	Any	Any	test port PCSSpp sh r 1
1 (a)	Any	None			test port PCSSpp sh r 1
15 (b)	Any	Audit and Update Test (#36)			
18 (c)	0	busyout pri-endpoint <extension> busyout port <PCSSpp>	WARNING	OFF	release pri-endpoint <extension> release port <PCSSpp>
129 (d)		None	WARNING	OFF	test port PCSSpp sh r 1
130 (e)		None	WARNING	ON	test port PCSSpp sh
257 (f)	Any	None			test port PCSSpp sh r 1
513 (g)	Any	None	WARNING	OFF	test port PCSSpp sh r 1
76 9 (f)	Any	None			test port PCSSpp sh r 1
1281 (h)	Any	Conference Circuit Test (#7)	MINOR	ON	test port PCSSpp l r 4
1537 (i)	Any	NPE Crosstalk Test (#6)	MINOR	ON	test port PCSSpp l r 3
1793 (j)	Any	None			test port PCSSpp sh r 1
3073 (k)	Any	Service State Audit (#256)			test port PCSSpp sh r 2
3585 (l)	Any	None			None

1. Run the Short Test Sequence first. If all tests pass, run the Long Test Sequence. Refer to the appropriate test description and follow the recommended procedures.

## Notes:

- a. This error type indicates a disagreement between the switch and the terminal adapter at the other end of the connection with regard to the ISDN *call* state of the PRI Endpoint Port. This switch automatically tries to recover by clearing the call (that is, the call is torn down). The **status pri-endpoint <extension>** command can be used to determine the state of the port.

When running the Short Test Sequence of tests, pay close attention to the results of the Call State Audit Test (#257).

- b. This is a software audit error that does not indicate any hardware malfunction. Run the Short Test Sequence and investigate the associated errors (if any).
- c. The PRI Endpoint Port has been busied out by a **busyout pri-endpoint <extension>** command or by a **busyout port <PCSSpp>** command. No wideband calls can be made to this port (although wideband calls can still be made to other ports within this PRI Endpoint if others ports are in service).
- d. The far-end terminal adapter changed its ISDN *service* state to either "out-of-service" or "maintenance." This may be a temporary condition due to the testing of this port by the far-end terminal adapter *or* by a hardware problem with the port. Outgoing calls to the terminal adapter are not allowed over the port (although calls can still be made to other ports that are in service within the same PRI Endpoint). To investigate the status of the port, issue the **status pri-endpoint <extension>** command.
- e. This error type indicates that the circuit pack has been removed or has been insane for more than 11 minutes. To clear the error, reinsert or replace the circuit pack.

- f. This error type indicates a disagreement between this switch and the terminal adapter at the other end of the connection with regard to the ISDN *service* state of the PRI Endpoint Port. This switch tries to recover by performing a service state audit. The **status pri-endpoint <extension>** command can be used to determine the state of the port.

When running the Short Test Sequence, pay close attention to the results of the Service State Audit Test (#256).

- g. This port is not recognized by the far-end terminal adapter. Investigate the PRI Endpoint administration for both the switch and the terminal adapter and make changes as necessary.
- h. The Conference Circuit Test (#7) failed on this port. See Test #7 for the repair procedures.
- i. The NPE Crosstalk Test (#6) failed on this port. See Test #6 for the repair procedures.
- j. This error indicates a failure of the UDS1 Interface circuit pack. When running the Short Test Sequence, the results of the Signaling Link State Check Test (#255) are important.

- k. Two Service State Audit attempts have failed (see Test #256). The port is not usable for any outgoing calls to the terminal adapter (although incoming calls from the terminal adapter are accepted over this port, other ports in the PRI Endpoint can still be used for both incoming and outgoing calls to and from the terminal adapter) until the test passes and the port state is changed to in-service (use the **status pri-endpoint <extension>** command to investigate the port status).
- l. This error type appears when the switch receives an ISDN RESTART message for an ISDN port that is not idle. Usually, calls are not cleared via the RESTART message. Therefore, this error type may be associated with a dropped call report from a user.

The following Aux Data values for Error Type 3585 represent the port's ISDN call state at the time that the unexpected request to restart the channel is received from the remote terminal adapter. This information can be useful if dropped calls (cutoffs) are being reported by users of the PRI Endpoint.

The following list contains important Aux values. Any other such values can be ignored.

- 10      A call in a stable, talking state was cleared unexpectedly by the far-end terminal adapter with an ISDN RESTART message. This state is called the "active" state.
- 4,  
7,  
8,  
260,  
263      A call that did not reach the active state but at least reached a ringing state was cleared unexpectedly by the far-end terminal adapter with an ISDN RESTART message.
- 1,  
3,  
6,  
9,  
265      A call that has not yet reached a ringing state was cleared unexpectedly by the far-end terminal adapter with an ISDN RESTART message.
- 11,  
12,  
19,  
531,  
267,  
268      A call that was in the process of clearing has been nonetheless cleared by the far-end terminal adapter with an ISDN RESTART message. If this condition occurs frequently, it may mean that the far-end terminal adapter is attempting to clear ports that it thinks are in a "hung" state. The RESTART message brings the port to an idle condition.
-

## System Technician-Demanded Tests: Descriptions and Error Codes

---

Always investigate tests in the order presented in the table below when inspecting errors in the system. By clearing error codes associated with the *NPE Crosstalk Test*, for example, you may also clear errors generated from other tests in the testing sequence.

Table 5-376. System Technician-Demanded Tests: DS1-BD

Order of Investigation	Short Test Sequence	Long Test Sequence	D/ND <sup>1</sup>
NPE Crosstalk Test (#6)		X	ND
Conference Circuit Test (#7)		X	ND
Audit and Update Test (#36)	X	X	ND
Signaling Link State Check Test (#255)	X	X	ND
Service State Audit Test (#256)	X	X	ND
Call State Audit Test (#257)	X	X	ND

---

1. D = Destructive, ND = Non-destructive

---

**NPE Crosstalk Test (#6)**

The NPE Crosstalk Test verifies that this port's NPE channel talks on the selected time slot and that it never crosses over to time slots that are reserved for other connections. If the NPE is not working correctly, one-way and noisy connections may be observed. This test is usually only part of a port's long test sequence, and takes about 20 to 30 seconds to complete.

**Table 5-377. TEST #6 NPE Crosstalk Test**

Error Code	Test Result	Description/Recommendation
	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals a maximum of 5 times.
1000	ABORT	System resources required to run this test are not available. The port may be in use on a valid call. Use <b>status pri-endpoint &lt;extension&gt;</b> commands to determine when the port is available for testing. 1. Retry the command at 1-minute intervals a maximum of 5 times. (Refer to <a href="#">"status station" on page 4-213</a> for a description of all possible states.)
1001	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals a maximum of 5 times.
1002	ABORT	The system could not allocate time slots for the test. The system may be under heavy traffic conditions or it may have time slots out-of-service due to TDM Bus errors. The <b>status health</b> command can be used to determine if the system is experiencing heavy traffic. Refer to <a href="#">"TDM-BUS (TDM Bus)" on page 5-1116</a> to diagnose any active TDM Bus errors. 1. If system has no TDM Bus errors, and if it is not handling heavy traffic, repeat the test at 1-minute intervals a maximum of 5 times.
1003	ABORT	The system could not allocate a tone receiver for the test. The system may be oversized for the number of tone detectors present, or some tone detectors may be out-of-service. The <b>list measurements tone-receiver</b> command displays information on the system's tone receiver. 1. Look for TTR-LEV errors in the Error Log. If errors are present, refer to <a href="#">"TTR-LEV (TTR Level)" on page 5-1223</a> . 2. Look for TONE-PT errors in the Error Log. If errors are present, refer to <a href="#">"TONE-PT (Tone Generator)" on page 5-1204</a> . 3. If neither condition exists, retry the test at 1-minute intervals a maximum of 5 times.
1004	ABORT	The port has been seized by a user for a valid call. Use <b>status pri-endpoint &lt;extension&gt;</b> commands to determine when the port is available for testing. 1. Retry the command at 1-minute intervals a maximum of 5 times.

*Continued on next page*

Table 5-377. TEST #6 NPE Crosstalk Test — *Continued*

Error Code	Test Result	Description/Recommendation
1117	ABORT	A service state audit message is outstanding. 1. Wait 2 minutes and then try again.
2000	ABORT	Response to the test request was not received within the allowable time period. 1. Retry the command at 1-minute intervals a maximum of 5 times.
2020	ABORT	The test did not run due either to an already existing error on the specific port or to a more general circuit pack error. 1. Examine the Error Log for existing errors against this port or the circuit pack and attempt to diagnose the already existing error.
2100	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals a maximum of 5 times.
Any	FAIL	The NPE of the tested port was found to be transmitting in error. This causes noisy and unreliable connections. The PE-BCHL is moved to the out-of-service/near-end state. 1. Replace the circuit pack.
	PASS	The port is able to communicate over the TDM Bus.

**Conference Circuit Test (#7)**

One or more Network Processing Elements (NPEs) reside on each circuit pack with a TDM Bus interface. (The TN464C UDS1 circuit pack has one SCOTCH-NPE chip instead of several NPE chips.) The NPE controls port connectivity and gain, and it provides conferencing functions on a per port basis. The Conference Circuit test verifies that the NPE channel for the port being tested can correctly perform the conferencing function. The NPE is instructed to listen to several different tones and to conference the tones together. The resulting signal is then measured by a tone detector port. If the level of the tone is within a certain range, the test passes.

**Table 5-378. TEST #7 Conference Circuit Test**

Error Code	Test Result	Description/Recommendation
	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals a maximum of 5 times.
1000	ABORT	System resources required to run this test are not available. The port may be in use on a valid call. Use the <b>status pri-endpoint &lt;extension&gt;</b> command to determine when the port is available for testing.
1004	ABORT	The port has been seized by a user for a valid call. Use the <b>status pri-endpoint &lt;extension&gt;</b> command to determine when the port is available for testing. 1. Retry the command at 1-minute intervals a maximum of 5 times.
1020	ABORT	The test did not run due either to an already existing error on the specific port or to a more general circuit pack error. 1. Examine Error Log for existing errors against this port or against the circuit pack, and attempt to diagnose the already existing error.
2000	ABORT	Response to the test request was not received within the allowable time period.
2100	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals a maximum of 5 times.
Any	FAIL	The NPE of the tested port did not conference the tones correctly. This causes noisy and unreliable connections. 1. Replace the circuit pack. Even though wideband calls do not use the conferencing feature on the NPE, this failure indicates problems with the circuit pack hardware.
	PASS	The port can correctly conference multiple connections. User-reported troubles on this port should be investigated by using the other port tests and by examining the terminal adapter or the external wiring.

## Audit and Update Test (#36)

This test sends port level translation data from the switch processor to the UDS1 interface circuit pack to ensure that the port's translation is correct. The port audit operation verifies the consistency of the current state of the port that is kept in the UDS1 interface circuit pack and in the switch software.

Table 5-379. TEST #36 Audit and Update Test

Error Code	Test Result	Description/Recommendation
2000	ABORT	Internal system error
	ABORT	Response to the test request was not received within the allowable time period.
2100	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals a maximum of 5 times.
		FAIL
	PASS	The port translation has been updated successfully. The current port states kept in the UDS1 interface circuit pack and in the switch software are consistent. If the port is busied out, the test does not run, but returns PASS. To verify that the port is in-service: 1. Enter <b>status pri-endpoint &lt;extension&gt;</b> to verify that the port is in-service. If the port is in-service, no further action is necessary. If the port is out-of-service, go to Step 2. 2. Enter the <b>release pri-endpoint &lt;extension&gt;</b> command or the <b>release port &lt;PCSSpp&gt;</b> command to put the port back into in-service. 3. Retry the test command.

## Signaling Link State Check Test (#255)

As is noted in the general description for a PRI Endpoint Port, the operation of the PRI Endpoint Port depends on the health of the UDS1 interface circuit pack and of the TN765 Processor Interface Link. This test checks the status of those critical elements.

Table 5-380. TEST #255 Signaling Link State Check Test

Error Code	Test Result	Description/Recommendation
	ABORT	Internal system error <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
1700	ABORT	Rollabout video abort. The PRI terminal adapter associated with this PRI endpoint extension is detached from the circuit pack. This is a normal abort when the rollabout video feature is enabled. To complete the test on this port, do one of the following: <ol style="list-style-type: none"><li>1. Re-attach the disconnected PRI terminal adapter, or</li><li>2. Disable the rollabout video feature on this circuit pack by entering the <b>change ds1 PCSS</b> command, and set the field <code>Alarm when PRI Endpoint Detached?</code> to <b>y</b>.</li></ol>
4	FAIL	There is a problem with the Signaling Channel and/or with the Processor Interface Link. <ol style="list-style-type: none"><li>1. Consult the procedure for the ISDN-PRI Signaling Group (ISDN-GRP) and/or the procedures for Packet Interface (PKT-INT). Further information may also be obtained by consulting the procedures for the ISDN-PRI Signaling Channel (ISDN-LNK).</li></ol>
8	FAIL	There is a problem with the UDS1 interface circuit pack. <ol style="list-style-type: none"><li>1. Consult the procedures for UDS1 interface circuit pack (UDS1-BD).</li></ol>
	PASS	The signaling link hardware is okay.

**Service State Audit (#256)**

As is noted in the general description for PRI Endpoint Port, these ports may be in one of several service states as defined by the ISDN-PRI Specification. This test performs a service state audit with the far-end terminal adapter to ensure that both sides agree on the service state.

A PASS for this test simply means that an audit message was successfully composed and sent out to the far-end terminal adapter. The ISDN Specification allows up to two minutes for a reply. If no reply is received within that two minute window, this switch automatically tries once again. If that attempt fails, an error is logged (Error Type 3073), and the switch attempts a recovery by automatically retrying approximately every 15 minutes. If the port was initially in the INS (in-service) state, it is now placed into the MTC/FE (maintenance state, far-end problem) state. Until a Service State Audit attempt is successful, no outgoing calls are placed over this port, but incoming calls are be accepted. The service state of this port does not affect the service state of other ports in the PRI Endpoint. If an incoming call that uses this port is presented while in such a state, a Service State Audit attempt is immediately attempted (that is, the switch does not wait for the 15 minute cycle, but instead tries to recover immediately). To investigate the status of this PRI Endpoint Port, issue the **status pri-endpoint <extension>** command.

Table 5-381. TEST #256 Service State Audit Test

Error Code	Test Result	Description/Recommendation
1113	ABORT	The signaling link has failed. As a result, the system cannot send any messages on behalf of this port.  1. Check the results of Test #255 (Signaling Link State Check).
1117	ABORT	A service state audit message is outstanding.  1. Wait two minutes and try again.
1700	ABORT	Rollabout video abort. The PRI terminal adapter associated with this PRI endpoint extension is detached from the circuit pack. This is a normal abort when the rollabout video feature is enabled. To complete the test on this port, do one of the following:  1. Re-attach the disconnected PRI terminal adapter, or  2. Disable the rollabout video feature on this circuit pack by entering the <b>change ds1 PCSS</b> command, and set the field "Alarm when PRI Endpoint Detached?" to "y."
2100	ABORT	Could not allocate the necessary system resources to run this test.  1. Retry the command at 1-minute intervals a maximum of 5 times.
	FAIL	Internal system error  1. Retry the command at 1-minute intervals a maximum of 5 times.

Table 5-381. TEST #256 Service State Audit Test — *Continued*

Error Code	Test Result	Description/Recommendation
	PASS	<p>Wait 4 minutes and then check the Error Log for any new occurrences of Errors Type 3073.</p> <p>If there are no occurrences of this error, both sides of the ISDN connection agree on the service state, and the negotiation succeeded. If there is a new occurrence of Error Type 3073, the negotiation failed (that is, the far-end terminal adapter twice failed to respond within the mandatory two minute window). This switch automatically retries approximately every 15 minutes. If the port was initially in the INS (in-service) state, it is now be placed into the MTC/FE (maintenance, far-end problem) state. Incoming calls are accepted, but no outgoing calls are originated from this port. If an incoming call is presented, another Service State Audit is immediately performed in an attempt to bring the PRI Endpoint Port to the proper state.</p>

### Call State Audit Test (#257)

If a call is active on the port, the switches on both sides of the connection should agree on the ISDN state of the call as defined in the ISDN Protocol Specification. This test audits internal call state data by querying the far-end terminal adapter about the ISDN state of the call. It can be helpful when trying to clear a hung call. If the internal call state data on the near-end switch is different than that of the far-end terminal adapter, **the call is torn down.**

As with Test #256 (Service State Audit), a PASS simply means that an appropriate message was composed and sent to the far-end terminal adapter. The ISDN Specification allows up to two minutes for a reply. If a reply is not received within the two minute window, a protocol time-out violation is recorded in the error log against the associated signaling channel (ISDN-PRI Signaling Link Port, which is listed in the Error Log as ISDN-LNK; the Error Type is 1).

Table 5-382. TEST #257 Call State Audit Test

Error Code	Test Result	Description/Recommendation
1019	ABORT	<p>An audit is already in progress.</p> <ol style="list-style-type: none"> <li>1. Wait two minutes and try again.</li> </ol>
1113	ABORT	<p>The signaling link has failed. As a result, the system cannot send any messages on behalf of this port.</p> <ol style="list-style-type: none"> <li>1. Check the results of Test #255 (Signaling Link State Check).</li> </ol>

*Continued on next page*

Table 5-382. TEST #257 Call State Audit Test — *Continued*

Error Code	Test Result	Description/Recommendation
1116	ABORT	The port is in an out-of-service ISDN service state. <ol style="list-style-type: none"><li>1. A call cannot be present if the port is in an ISDN out-of-service state. As a result, a call state audit would be inappropriate, and no action is necessary. (Use the <b>status pri-endpoint &lt;extension&gt;</b> command to investigate the ISDN state of the port).</li></ol>
1700	ABORT	Rollabout video abort. The PRI terminal adapter associated with this PRI endpoint extension is detached from the circuit pack. This is a normal abort when the rollabout video feature is enabled.  To complete the test on this port, do one of the following: <ol style="list-style-type: none"><li>1. Re-attach the disconnected PRI terminal adapter, or</li><li>2. Disable the rollabout video feature on this circuit pack by entering the <b>change ds1 PCSS</b> command, and set the field "Alarm when PRI Endpoint Detached?" to "y."</li></ol>
2100	ABORT	Could not allocate the necessary system resources to run this test. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
	FAIL	Internal system error <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals for a maximum of 5 times.</li></ol>
	PASS	This switch sent a call state auditing message to the far-end terminal adapter to verify the state of the call active on this port. If a call state mismatch is found, the call is torn down within two minutes. If no call was active, no message was sent.

## PI-LINK (Processor Interface Link)

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run	Full Name of MO
PI-LINK	MAJOR	test link lnk-no l	Processor Interface Link
PI-LINK	MINOR	test link lnk-no l	Processor Interface Link
PI-LINK	WARNING	test link lnk-no l	Processor Interface Link

**NOTE:**

Reference lnk-no using the **display communication-interface links** command.

The Processor Interface (PI) Communication Link is the physical link that connects DEFINITY to an adjunct such as AUDIX, another node in a DCS network, or an ISDN-PRI connection. These links are either X.25 (DCS, AUDIX, or MIS) or ISDN (ISDN-PRI). The system supports up to four of these links per TN765 Processor Interface circuit pack. PI-LINK maintenance actually monitors several hardware devices: Processor Interface ports, TN754 or TN784 Digital Line ports, PDMs, TDMs, MTDMs, MPDMs, and DS1 facilities. Henceforth, “data module” refers to either PDM, TDM, MPDM, or MTDM. **In much of the following link documentation, the repair procedures described mention various hardware configurations. Choose the procedure appropriate to your configuration.**

The Processor Interface circuit pack provides an EIA connection. This connection can be administered only on Link 1 in a system without High or Critical Reliability. The EIA port is used when an adjunct (AUDIX, for example) is near (less than 25 feet) or further if a modem is used. The EIA port can also be used to connect two PBXs together via DCS. The EIA port cannot be used in a High or Critical Reliability system.

The Processor Interface Link can be in three different states. These states can be seen using the **status link lnk-no** system technician command. If the link is in a *maintenance busy* state, then the system technician had instructed the Processor Interface to be in maintenance busy by entering the **busyout link lnk-no** command or the Processor Interface Link is not established and maintenance is trying to bring it up. This probably means that an error condition is occurring somewhere on the link that keeps the link from being logically connected and carrying data. If the link is busied out, then it can be put back into service by issuing a **release link lnk-no** command. This restarts the link. If the link is for DCS, then it may speed the recovery of the link if **busyout link lnk-no** and **release link lnk-no** are executed on the switch that is establishing the connection (see the Communication-Interface Links form). The link can be in a *disconnected* state if the link cannot be started up. In this case, maintenance tries to establish the link periodically. If the link is up and data is being sent successfully, then the link is in the *in-service* state.

**⇒ NOTE:**

When an ISDN-PRI link is busied out via a system technician command, the associated B-channels (ISDN-TRK) are moved to the maintenance and/or far-end state. As a result, stable calls are NOT dropped, but the trunks are removed from the trunk hunt group to prevent them from being selected for outgoing calls. See ISDN-TRK Maintenance documentation.

Up to two Processor Interface circuit packs can be active on the same carrier in the system. Thus, there can be a maximum of eight Processor Interface links in service at any one time. If an error or alarm is detected by PI-LINK that can be associated with a physical port on the Processor Interface circuit pack, then the Processor Interface Port MO is alarmed, which indicates a defective port on the circuit pack. Refer to the PI-PT (Processor Interface Port) Maintenance documentation for details.

It is useful to use the **status processor-channel channel-no** command when troubleshooting the PI-LINK. A processor channel corresponds to a processor application (also called a session) and more than one may be using the same physical link (only for X.25 links). The relevant field of the status screen is the "channel status:" which can be in 1 of 7 different states (see the following table). State 6 is normal state for the processor channel for X.25 links and state 10 is normal state for ISDN links. States 9 and 10 are only applicable to ISDN links.

States	Description
1	Incorrect translations or channel not assigned.
3	Attempting to reset the channel but no response from the other end. Getting stuck in this state may be caused by hardware problems, a DS1 synchronization problem or a DCE/DTE conflict in the Communication-Interface Link Form (one end of the link must be DCE and the other must be DTE).
4	The other end acknowledged the channel reset (the two ends are physically connected) but a processor channel connection has not occurred yet. Getting stuck in this state may indicate that translations are incorrect, such as remote processor channel mismatch. To recover from this situation, execute the <b>busyout link lnk-no</b> and <b>release link lnk-no</b> commands. If this is unsuccessful, then use the <b>reset interface</b> command (note that this is a <b>destructive</b> command that tears down all four links). This problem may also be caused by a noisy link or DS1 synchronization problems.
6	This is the normal state of the channel. The link is in the data transfer state which means that the application is able to send data over the link.
7	One or more unexpected messages have arrived; software is attempting to resynchronize the two ends. Usually it takes up to five minutes for the software to recover once it is in this state.
9	ISDN-PRI link is currently down. It is periodically restarted or can be forced to restart via <b>busyout/release link lnk-no</b> .
10	ISDN-PRI link is up. This is the normal state of the channel. The link is in data transfer state, which means that ISDN data can be sent over the link.

Table 5-50 shows the Processor Interface Communications Link (PI-LINK) Interactions.




Figure 5-50. Processor Interface Link Interactions

## Error Log Entries and Test to Clear Values

Table 5-383. PI-LINK (Processor Interface Link) Error Log Entries

Error Code	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
0 <sup>1</sup>	0	Any	Any	Any	test link <lnk-no> sh
1 (a)	Any	none	MAJOR/ WARNING <sup>2</sup>	OFF	busyout/release link lnk-no
18	0	busyout link lnk-no	WARNING	OFF	release link lnk-no
257 (b)	Any	none	MINOR/ WARNING <sup>b</sup>	OFF	busyout/release link lnk-no
263 (c)	Any	none	MAJOR/ WARNING <sup>b</sup>	OFF	busyout/release link lnk-no
513 (d)	Any	none	MAJOR/ WARNING <sup>b</sup>	OFF	busyout/release link lnk-no

Continued on next page

Table 5-383. PI-LINK (Processor Interface Link) Error Log Entries — *Continued*

Error Code	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
769	Any	PI Loop Around Test (#182)	WARNING	ON	test link lnk-no l r 2
1025	Any	TDM Loop Around Test (#183)	WARNING	OFF	test link lnk-no l r 2
1281 (n)	Any	none	WARNING/ MAJOR <sup>3</sup>	OFF	test link lnk-no sh r 2
1537 (e)	Any	none	WARNING/ MAJOR <sup>c</sup>	OFF	busyout/release link lnk-no
1793 (f)	Any	none	WARNING	OFF	busyout/release link link no.
2049 (g)	Any	none	WARNING/ MAJOR <sup>c</sup>	OFF	test link lnk-no sh r 9
2305 (h)	Any	none	WARNING	OFF	test link lnk-no sh r 9
2561 (i)	Any	none	WARNING/ MAJOR	OFF	busyout/release link lnk-no
2817 (j)	Any	none	NONE	OFF	busyout/release link lnk-no
3073 (k)	Any	none	WARNING	OFF	test link lnk-no sh r 9
3585 (l)	Any	none	MAJOR/ WARNING <sup>2</sup>	OFF	busyout/release link lnk-no
3841 (m)	Any	none	MINOR/ WARNING <sup>2</sup>	OFF	busyout/release link lnk-no

1. Run the Short Test Sequence first. If all tests pass, run the Long Test Sequence. Refer to the appropriate test description and follow the recommended procedures.
2. Major and Minor alarms on this MO may be downgraded to Warning alarms based on the value used in the **set options** command.
3. This error type initially raises a warning alarm. If this error type persists, and alarms are not downgraded on this MO due to the values of **set options**, then, after a period of time, a Major alarm is raised.

## Notes:

- a. A permanent switched call was dropped. Check the "Link Recovery" section.
- b. The TN765 Processor Interface circuit pack detected an error on a specific link via background maintenance. If the link is down, busyout and then release the link. If this fails, check all connections. If the error reappears consistently, see "Link Recovery" section.

5 Maintenance Objects for DEFINITY ONE  
PI-LINK (Processor Interface Link)

5-938

- c. Processor Interface software or firmware detected an error condition on this link. Internal software should initiate the recovery for the link. If the link is still down, see the “Link Recovery” section.

Aux values of concern; any others can be ignored.

- 0 Processor Interface circuit pack indicates that the ISDN-PRI link is down.
- 1 An internal software audit indicates that this link has been in overload for at least 20 seconds and is hung.
- 2 No internal software buffers are available to process a link transition (that is, down to up, or up to down). The transition is lost.
- 17 The allocation of a new software write buffer to the Processor Interface circuit pack failed.

- d. Translation Error—check all administration for the link. Possibly the destination DS1-BD or DIG-BD is not inserted. Busyout and then release the link to restart it. This is not a Processor Interface hardware problem.

Aux values of concern; any others can be ignored.

- 2 Link translation error. If the communication-processor link form indicates this link’s destination is a tac+extension, then bring up the dial plan form. If an extension exists with the same first digit as the tac, then this PI link will not establish. To alleviate this problem, either remove the extension on the dial plan form, or change the destination field on the communication-processor link form to use a UDP extension to dial the far-end.
- 8 Port not administered in software.

- e. This error occurs when the Processor Interface link fails to be established. Check all connections and administration. This could also occur as a result of another error, the failure of Test #182, for example. If the other error on the link can be cleared, then this error may also clear. See the “Link Recovery” section

5 Maintenance Objects for DEFINITY ONE  
PI-LINK (Processor Interface Link)

5-939

- 1, 2 System error.
- 7 System error. If this error is occurring on all administered links with the same Aux Data and all links are alarmed, then execute the **reset interface** command to restore all the links.
- 12 One of the two Loop Around Tests failed (#182 or #183). See the "Link Recovery" section.
- 13 Hardware problem with DS1 facility is affecting ISDN links. Refer to DS1-BD Maintenance documentation.
- 19 A transient state associated with the D-channel backup protocol. The link is being held in the busy state until call control can be moved to the new active link. No action needs to be taken.
- 32771 The remote endpoint indicates that the call is up and the  
32772 local PBX cannot complete the call. Check trunk status (on the remote end and local end) if a DS1 trunk is used, or check the status of the data module if a data module is used in the link. The commands are **status trunk trk-grp/member** or **status data-module <ext>**. If the destination is in-service/active, then the commands are **busyout trunk trk-grp/member** and **release trunk trk-grp/member** (on both sides of the link if this is a DCS link). If a data module is used in the link, then use a **busyout data-module <ext>** command followed by a **release data-module <ext>** command. Busy out the Processor Interface Link prior to busying the trunk or data module. Release the Processor Interface Link via **release link lnk-no** command and the Processor Interface Link re-starts. If this fails, check the status of the TN765 port using **status data <ext>** where **<ext>** is the extension of the port from the interface extension in the Display Communication Link form; if the state is "in-service/idle" then manually call the TN765 port and transfer the call to appropriate destination, either a DS1 Trunk Access Code or the data module extension. See "Link Recovery" if error still occurs. See "Link Recovery" if error still occurs and link does not establish.
- 32779 Administration problem; check that the Processor Interface  
32782 data module extension exists via the **status data-module**  
32801 **<ext-no>** command. Verify that the destination extension exists and that the correct routing pattern is used. In addition, check that the Processor Interface data module and the destination extension are administered on the COS and/or COR forms.

5 Maintenance Objects for DEFINITY ONE  
PI-LINK (Processor Interface Link)

5-940

32813	Administration problem; check all administration.
32815	The off-premise call timed-out. Check the "Off-Premises Tone Detect Timeout Interval" on the Feature-Related System Parameters Form. The time-out is administered between 6 and 25 seconds. No response was received from the remote destination. Check the status of the remote destination. This might also indicate possible synchronization problems. Network synchronization sources should be checked on all networked switches. Also see the SYNC Maintenance documentation.
32814	Call was answered but not by a remote data module. Check the remote destination extension and verify that this is a data module.
32841	Call went over the trunk and received ring back but did not receive modem answer tone. Check the remote destination for automatic answering.
65528	Administration problem; check all administration.
65532	Call setup timed out; retry, and check destination. If the destination is an adjunct (CMS, AUDIX, etc.), then check if the terminal ready light is lighted on the PDM. If not, then the adjunct is down. If the destination is another PBX, then the PBX might be restarting. Retry.
65535	Link specified is out-of-range (1 through 8).

- f. This error message indicates that the TN765 Processor Interface circuit pack could not transmit the message the software sent to it. See the "Link Recovery" section if the error continues. This is a normal error during "hot start" SPE-interchanges.
- g. Excessive resets on the link. Usually indicates that the remote end is down or the physical connection is broken. A warning alarm is raised initially, followed by a Major alarm if the problem is not cleared. See the "Link Recovery" section.
- h. Excessive I-frame retransmission. Could indicate a noisy link. Recover as in previous note. Aux values indicate the retransmission rate per minute. See the "Link Recovery" section.
- i. If the Aux Data value is 9, then the destination circuit pack (DIG-BD or DS1-BD) is not inserted. Otherwise, DS1 maintenance detected a hardware failure. (DS1 cable disconnected, loss of signal, DS1-BD problems.) Not a Processor Interface Link problem. Check DS1-BD maintenance. Only applicable to ISDN links. Aux value useless. Once the DS1 signal is restored, maintenance automatically restarts the Processor Interface Link. To hasten this process, test the appropriate DS1 Interface circuit pack via **test board PCS** command. When Test #138 (loss of signal) passes, the Processor Interface Link recovers shortly.

In addition to an indication that the link failed to establish the PI-LINK 2561 AUX\_Data, the hardware error log is also updated. This error may indicate two possible conditions:

1. A failure to detect the DTR from the peripheral.

When the DTR is not detected by the data module the AUX\_Data is set to 40. This indicates that the problem is most likely with the peripheral or the connection to the peripheral.

2. A time-out on the EIA interface query request to the data module.

When the data module fails to respond to the EIA interface (query request) the AUX\_Data is set to 41. This may indicate problems with the data module or connection to the data module. Other errors specific to the data module may also be logged if this is the case.

- j. TN765 PI-BD determined that the ISDN link went down. Check connectivity with the other end. Busyout and then release the link to recover. Occurs if DS1 maintenance detected a problem or the remote end is busied out or is down. This also occurs if the ISDN link is unstable or if there is excessive noise on the line. See the "Link Recovery" section.
- k. Excessive LAPD (link-access procedure on the D-channel) invalid frame errors. Could be a noisy line or problems with the TN765 Processor Interface circuit pack. Also check DS1-BD Maintenance documentation. See the "Link Recovery" section.
- l. Occurs 90 seconds after a 2817 Error Code if link does not recover. At this time, all ISDN trunks associated with this link are put into a maintenance far-end state (see ISDN-TRK for details). See the "Link Recovery" section.
- m. The application level process associated with the link has failed to establish a data connection with the far end. This problem prevents data from being processed. The condition may exist even if the link is in a data transfer state. Busyout, and release the link to restart it. This is not a Processor Interface hardware problem.

Aux values of concern; any others can be ignored.

433 OCM application did not start correctly. Reboot the OCM adjunct.

435 Application level process could not connect to session layer process.

- n. Excessive (over threshold) HDLC transmit or receive error rates were reported. Aux Data is the HDLC error rate reported. See the Link Recovery section for troubleshooting this problem

## Link Recovery

---

This section describes the general procedure to take to recover from link errors and alarms. Refer to the “Troubleshooting ISDN-PRI Problems” section in Chapter 5, “Routine Maintenance Procedures”, before proceeding with this “Link Recovery” strategy.

1. Determine the link status using the **status link** command. If the link status is “in-service” and (for X.25 links) all the pairs of processor channels are complete under “LOCAL/REMOTE PROCESSOR CHANNELS” (that is, every “/” is followed by a processor channel number, not a blank), then the link is operating correctly and no further action should be taken. If the link status is not “in-service,” then go to Step 2. If the link status is “in-service” and (for X.25) some of the processor channel pairs are incomplete (remote channel not specified, meaning that the processor channels are not connected), then look at the status of “status processor-channel” for the local processor channels that are not connected.
2. Look for active PI-SCI alarms and follow the procedure for those alarms if there are any. If there are no PI-SCI problems, go on to the next step.
3. If the link is still down, restart the link via the **busyout link lnk-no** system technician command followed by the **release link lnk-no** command. This sequence tears down the call and then tries to bring it back up. If the link is for DCS, it may speed the recovery of the link if **busyout link lnk-no** and **release link lnk-no** commands are executed on the switch that is establishing the connection (see Communication Link form). If the link does not recover, go on to the next step.
4. Check the status of the remote endpoint.
  - a. If the link is busied out, release it.
  - b. Is the switch down or restarting?
5. If link was never brought up:
  - a. Verify that the administration is correct as follows:
    - Enter the **display ds1 PCSS** command. Check the compatibility of the DS1 parameters with the far-end and the CSU.
    - Enter **display communication-interface links** command.
    - Enter the **display communication-interface processor-channels** command. Enter the **display communication-interface hop-channels** command (if hop-channels are being used).
    - Enter the **display trunk <grp>/<mbr>** command (if DS1 is being used for DCS).
    - Enter the **status sync** command (if DS1 is being used)—make sure the primary synchronization is administered.

6. If link is an EIA link:
  - Verify via the Communication-Interface Links form that the information for the EIA connection is correct on the local and remote PBXs.
7. Try to isolate the problem in the link if hardware is at fault. Test the link via the **test link lnk-no long** system technician command.
  - a. If Test #182 fails three times, replace the TN765 circuit pack. Refer to Chapter 6, "Reliability Systems: A Maintenance Aid".
  - b. If Test #182 passes and Test #183 fails, replace the TN754 or TN784 Digital Line or the TN722 or TN767 DS1 Interface circuit pack, whichever is used in the link. If Test #183 still fails, replace the TN765 PI-BD. Refer to Chapter 9, "Packet Bus Fault Isolation and Correction".
8. If the preceding tests pass:

Check the physical transmission link:

  - a. Are all the circuit packs physically installed?
  - b. Are the cables still connected throughout?
  - c. Check DS1-BD error section for possible connectivity problems if DS1-BD is used in link connection.
  - d. Check CSU options.
9. Finally, restart the Processor Interface circuit pack via **reset interface PCS**. This resets the circuit pack and restarts ALL the links on it.

## System Technician-Demanded Tests: Descriptions and Error Codes

Always investigate tests in the order presented in the table below when inspecting errors in the system. By clearing error codes associated with the *PI Loop Around Test*, for example, you may also clear errors generated from other tests in the testing sequence. REMINDER: The command line entry to test the PI-LINK MO is: **test link lnk-no (s or l)**.

Order of Investigation	Short Test Sequence	Long Test Sequence	D/ND <sup>1</sup>
Processor Interface Loop Around Test (#182)		X	D
TDM Loop Around Test (#183)		X	D
ISDN Hardware Test (#234)		X	ND
Link Quality Test (#233)	X	X	ND
Data Module Internal Loop Around Test (#175) <sup>2</sup>		X	ND
Digital Line NPE Crosstalk Test (#9) <sup>b</sup>		X	ND
Port Circuit Information Channel and Control Channel Loop Around Test (#13) <sup>b</sup>		X	ND
Data Module Audits Test (#17) <sup>b</sup>	X	X	ND

1. D = Destructive; ND = Nondestructive
2. If the PI-LINK under test is BX.25 and if there is an MPDM or an MTDM as part of the link, then the PI-LINK test sequence is expanded to include the tests on the data module. These tests are run via the PDMODULE or TDMODULE maintenance object. Refer to the PDMODULE TDMODULE (Data Module) Maintenance documentation for descriptions and details of these tests.

### Processor Interface Loop Around Test (#182)

**This test is destructive.**

The Processor Interface Loop Around Test is an on-board Loop Around Test. The test requires that the system technician issue a **busyout link lnk-no** command before this test is run. This means that the DCS, AUDIX, or ISDN link, for example, is torn down. It does not access the TDM Bus at all. When the circuit pack is put into local loop around mode, frames are looped internally on the circuit pack. If the test fails, the Processor Interface circuit pack reports the failure. It is a good check of most of the working hardware on the Processor Interface circuit pack.

Table 5-384. TEST #182 Processor Interface Loop Around Test

Error Code	Test Result	Description/Recommendation
1	ABORT	Link was not busied out via system technician. <ol style="list-style-type: none"> <li>1. Busyout the link via the <b>busyout link lnk-no</b> command.</li> <li>2. Retry the test command.</li> </ol>
2 4 9	ABORT	<ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
16 80 84 85 93 94 102	ABORT	Internal system error or possible TN765 PI-BD failure. <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> <li>2. If the test continues to abort, then reset the PI-BD via the <b>test interface PCS long</b> system technician command.</li> <li>3. If problem still exists, replace the TN765 PI-BD.</li> </ol>
12	FAIL	PI-BD reported that Loop Around Test failed. <ol style="list-style-type: none"> <li>1. Retry the test.</li> <li>2. If it continues to fail, try resetting the circuit pack by the <b>test interface PCS long</b> command. This TEARS down all other links on this circuit pack (DCS, AUDIX, ISDN, etc.).</li> <li>3. If the problem still exists, replace the TN765 circuit pack.</li> </ol>
	PASS	The on-board Loop Around Test on the TN765 circuit pack passed. Most of the hardware on the circuit pack was tested except for the TDM Bus buffers. If problem is isolated to TN765 and this test passes, then replace TN765 circuit pack since TDM Bus buffers could be at fault.
13	ABORT	The TN765 circuit pack has not been reset yet or is currently being reset. <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> <li>2. If test continues to abort with error code 13, then check status of all BX.25 and/or ISDN-PRI links on this TN765 via the <b>status link lnk-no</b> command. If all links are not in-service, then reset the TN765 using the <b>test interface PCS long</b> command.</li> <li>3. If the TN765 fails to reset, refer to the PI-SCI section of this manual.</li> <li>4. Retry the <b>test link lnk-no</b> command.</li> <li>5. If the test still aborts with error code 13 or from step 2, and some links are in-service and an error code is still present, escalate the problem.</li> </ol>

**TDM Loop Around Test (#183)****This test is destructive.**

This test requires that you enter the **busyout link lnk-no** command before running the test. This means that the DCS, AUDIX, or ISDN link, for example, are torn down. This test checks the health of the TN754 or TN784 DIG-LINE or the TN722 or TN767 DS1 Interface circuit pack. This depends on which circuit pack is used on the link. The TN754 or TN784 Digital Line or DS1 Interface circuit pack is put into loop around mode while the PI-BD is instructed to go into remote loop around. If this test fails, and the previous Test #182 passes, then the TN754 or TN784 Digital Line or the DS1 Interface circuit pack should be replaced. It is not run on ports administered as EIA.

Table 5-385. TEST #183 TDM Loop Around Test

Error Code	Test Result	Description/Recommendation
1	ABORT	Link was not busied out via system technician. <ol style="list-style-type: none"> <li>1. Busyout the link via the <b>busyout link lnk-no</b> command.</li> <li>2. Retry the test command.</li> </ol>
2 4 8	ABORT	Internal system error <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
6	ABORT	The system could not allocate time slots for the test. The system may be under heavy traffic conditions or it may have time slots out-of-service due to TDM-BUS errors. Refer to "TDM-BUS" to diagnose TDM-BUS errors. <ol style="list-style-type: none"> <li>1. If system has no TDM-BUS errors and is not handling heavy traffic, repeat test at 1-minute intervals a maximum of 5 times.</li> </ol>
9	ABORT	TN754 or TN784 Digital Line or TN722 or TN767 DS1 Interface circuit pack is not installed. <ol style="list-style-type: none"> <li>1. Install circuit pack and retry the test.</li> </ol>
13	ABORT	The TN765 circuit pack has not been reset yet or is currently being reset. <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> <li>2. If test continues to abort with error code 13, then check status of all BX.25 and/or ISDN-PRI links on this TN765 via the <b>status link lnk-no</b> command. If all links are not in-service, then reset the TN765 using the <b>test interface PCS long</b> command.</li> <li>3. If the TN765 fails to reset, refer to the PI-SCI section of this manual.</li> <li>4. Else, retry the <b>test link lnk-no</b> command.</li> <li>5. If the test still aborts with error code 13 or from step 2, and some links are in-service and a error code is still present, escalate the problem.</li> </ol>

*Continued on next page*

Table 5-385. TEST #183 TDM Loop Around Test — *Continued*

Error Code	Test Result	Description/Recommendation
16 80 84 85 93 94 102	ABORT	Internal system error <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li><li>2. If the test continues to abort, then reset the PI-BD via the <b>test interface PCS long</b> command.</li><li>3. If problem still exists, replace the TN765 circuit pack.</li></ol>
1005	ABORT	The test is not applicable if the EIA port is being used as part of the link.
12	FAIL	PI-BD reported that Loop Around Test failed. <ol style="list-style-type: none"><li>1. Retry the test.</li><li>2. If Test #182 fails, see section for Test #182 first.</li><li>3. If Test #182 passes and Test #183 continues to fail, replace either the TN754 or TN784 Digital Line or the TN722 or TN767 DS1 Interface circuit pack.</li><li>4. If Test #183 still fails, replace the TN765 PI-BD.</li></ol>
	PASS	The loop around from the TN765 PI-BD to the Digital Line or DS1 Interface circuit pack and then back to the PI-BD passed.

### Link Quality Test (#233)

This test queries the TN765 circuit pack for the latest error rates (number/minute) for certain counters that are kept by the TN765. The test passes if all the error rates are below a certain threshold. The counters that are queried are the Level 2 Reset SABM(E) [Set Asynchronous Balanced Mode (Extended)] counter, the Level 2 I-frame Retransmission counter, and the invalid LAPD frame counter.

Table 5-386. TEST #233 Link Quality Test

Error Code	Test Result	Description/Recommendation
3 11 24	ABORT	Internal system error 1. Retry the command at 1-minute intervals a maximum of 5 times.
13	ABORT	The TN765 circuit pack has not been reset yet or is currently being reset. 1. Retry the command at 1-minute intervals a maximum of 5 times. 2. If test continues to abort with error code 13, then check status of all BX.25 and/or ISDN-PRI links on this TN765 via the <b>status link lnk-no</b> command. If all links are not in-service, then reset the TN765 using the <b>test interface PCS long</b> command. 3. If the TN765 fails to reset, refer to the PI-SCI section of this manual. 4. Else, retry the <b>test link lnk-no</b> command. 5. If the test still aborts with error code 13 or from step 2, and some links are in-service and a error code is still present, escalate the problem.
4 16385 16386	FAIL	Excessive Level 2 resets (SABM) on link.  Excessive Level 2 I-frame retransmission. Possible noisy link. 1. See <a href="#">"PI-LINK (Processor Interface Link)" on page 5-934.</a>
16388	FAIL	Excessive LAPD invalid frame errors. Could be a noisy link or problems with the near-end Processor Interface circuit pack or with the far-end. 1. See <a href="#">"DS1-BD (DS1 Interface Circuit Pack)" on page 5-548</a> for DS1 interface circuit pack problems. 2. See "PI-LINK".
16387	FAIL	Excessive Level 2 resets and excessive Level 2 I-frame retransmission.
16389	FAIL	Excessive Level 2 resets and excessive LAPD invalid frame errors.
16390	FAIL	Excessive Level 2 I-frame retransmissions and excessive LAPD invalid frame errors.
16391	FAIL	Excessive Level 2 I-frame retransmissions, excessive LAPD invalid frame errors, and excessive Level 2 resets. 1. See PI-LINK ( Processor Interface Link) Maintenance documentation for this maintenance object.
16392	FAIL	HDLC receive rate exceeded the threshold.
16400	FAIL	HDLC transmit rate exceeded the threshold.

Continued on next page

Table 5-386. TEST #233 Link Quality Test — Continued

Error Code	Test Result	Description/Recommendation
16393-16425	FAIL	Other combinations of above individual failures can be calculated as follows: 16384 = 0X4000 16385 = 0X4001 16386 = 0X4002 16388 = 0X4004 16316 = 0X4010
	PASS	PI-LINK currently does not have any of the above errors.

### ISDN Hardware Check Test (#234)

This test checks the status of the ISDN hardware which is the DS1 Interface circuit pack and cabling. Status of the DS1 port is kept by the system. The state of the port can be in-service or out-of-service. This state is updated by DS1 Interface circuit pack maintenance. If DS1 maintenance detects a problem with the physical medium near-end or far-end, the Processor Interface Link maintenance is instructed to restart the link. Therefore, if this test fails, the port is considered out-of-service and the link cannot be brought up until DS1 maintenance changes the state to in-service. This is more of a status inquiry than a test. Thus, the only recovery procedure is to refer to [“DS1-BD \(DS1 Interface Circuit Pack\)” on page 5-548](#).

Table 5-387. TEST #234 ISDN Hardware Check Test

Error Code	Test Result	Description/Recommendation
	ABORT	Internal system error 1. Retry the test at 1-minute intervals a maximum of 5 times.
1005	ABORT	This test only runs for ISDN-PRI links. This link is a BX.25 link and, thus, aborts.
	FAIL	Indicates that there is a physical problem with the DS1 facility link. 1. Cross-reference DS1 Interface circuit pack errors for possible reason. Refer to <a href="#">“DS1-BD (DS1 Interface Circuit Pack)” on page 5-548</a> . 2. Retry the test. It continues to fail until the DS1 problem is cleared up.
	PASS	DS1 facility is functioning correctly.

## PKT-BUS (Packet Bus)

---

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run	Full Name of MO
PKT-BUS	MAJOR	test pkt port l r 2	Packet Bus
PKT-BUS	MINOR	test pkt port l	Packet Bus
PKT-BUS	WARNING	test pkt port l	Packet Bus

The Packet Bus consists of a single bus, and one such bus appears in the system. There is one instance of the Packet Bus maintenance object.

The Packet Bus is used to carry ISDN-BRI, ISDN-PRI, and ASAI signaling information. The SPE interface to the Packet Bus is the *second* Packet Interface instance (PKT-INT, instance1A2) on the TN795 Processor Circuit Pack, which works in concert with the Bus Bridge circuitry on the TN799 C-LAN circuit pack to provide Packet Bus access. Packet Bus maintenance is performed only when the `Packet Intf2?` field on the Maintenance-Related System Parameters form is set to `y`. Packet Bus testing is dependent on the following hardware components:

- TN795 Processor circuit pack, PKT-INT instance 1A2
- TN556 ISDN-BRI Line circuit pack

Packet Bus tests may abort if some of this hardware is not present in the system. Also, these tests may yield inconsistent results if some of this hardware is defective.

The interactions between the Packet Bus and the circuit packs that use the bus are complex. For this reason, the Packet Bus can be alarmed due to a circuit pack failure and, conversely, circuit packs can be alarmed due to a Packet Bus failure. This section on PKT-BUS is limited to a description of the Error and Alarm Log entries for the Packet Bus maintenance object and to a description of the Packet Bus test sequence.

### NOTE:

Refer to Chapter 9, “Packet Bus Fault Isolation and Correction”, in *DEFINITY® Enterprise Communications Server Release 8.2, Maintenance for R8si*, (555-233-123), Issue 1, April 2000, Comcode 108678715, for a complete discussion of Packet Bus maintenance and also the interactions of the bus with the Packet circuit packs. The chapter discusses fault isolation and correction procedures, and it should be referenced for all procedures and required decisions. The “Packet Bus Fault Isolation Flowchart” section of the chapter is the normal starting point for experienced technicians; however, technicians who are unfamiliar with the Packet Bus and its use should refer to the introductory material.

A failure of one or more circuit packs that use the Packet Bus can cause a Packet Bus alarm. In addition, a Packet Bus failure can cause loss of service to one or more such circuit packs, as well as to the ports and endpoints associated with the ISDN-BRI circuit pack (BRI-PORT, ABRI-PORT, BRI-SET, BRI-DAT, and ASAI-ADJ). These interactions are discussed in the “Circuit Packs That Use the Packet Bus” section of the chapter referenced in the note above.

The following list summarizes some of the important points to consider when working with the Packet Bus.

- Certain catastrophic failures of a Packet Bus can cause all the Packet circuit packs on that bus to report errors, thus generating a high volume of maintenance activity for maintenance objects that are healthy. In order to reduce this unnecessary activity, some maintenance for Packet circuit packs, ports, and endpoints is curtailed or disabled when such a catastrophic Packet Bus failure is suspected. The following list summarizes the error-logging and testing impact of this strategy:
  - e. In-line errors indicating possible Packet Bus failures are placed into the error log, but are *not* acted upon. *Circuit pack* maintenance objects thus affected include:
    - [“BRI-BD/LGATE-BD \(ISDN-BRI Line Circuit Pack\)” on page 5-305](#)
    - [“ASAI-BD \(Multi-Application Platform Board\)” on page 5-148](#)
    - [“BRI-BD/LGATE-BD \(ISDN-BRI Line Circuit Pack\)” on page 5-305](#)
    - PGATE-BD
    - [“CLAN-BD \(Control LAN Circuit Pack\)” on page 5-378](#)
    - [“UDS1-BD \(UDS1 Interface Circuit Pack\)” on page 5-1227](#)
    - [“MAPD-BD \(MAPD Interface Circuit Pack TN802\)” on page 5-752](#)
    - [“MEDPROPT \(TN802 MED PRO DSP PORT\)” on page 5-782](#)
  - f. In-line errors indicating possible Packet Bus failures **are neither placed into the error log nor acted upon**. *Circuit pack port* and *endpoint* maintenance objects thus affected include:
    - [“BRI-PORT \(ISDN-BRI Port\), ABRI-PORT \(ASAI ISDN-BRI Port\)” on page 5-312](#), [“BRI-SET, ASAI-ADJ, BRI-DAT” on page 5-334](#), [“TBRI-PT \(TN2185 ISDN Trunk-Side BRI Port\)” on page 5-1085](#)
    - ASAI-ADJ, [“ASAI-PT” on page 5-158](#), [“ASAI-EPT” on page 5-150](#)
    - ATT-PORT, ATT-ADJ, ATTE-PT, ATTE-AJ
    - [“LGATE-PT” on page 5-749](#)
    - [“LGATE-AJ” on page 5-749](#)

5 Maintenance Objects for DEFINITY ONE  
PKT-BUS (Packet Bus)

5-952

- PGATE-PT
  - [“ETH-PT \(Control LAN Ethernet\)” on page 5-645](#)
  - [“PPP-PT \(Control LAN Packet/Port\)” on page 5-980](#)
  - MEDPRO-RES
- g. Circuit pack and port in-line errors that are not relevant to the Packet Bus or that indicate a circuit pack failure are acted upon in the normal fashion.
- h. Normal background maintenance (periodic and scheduled) is not affected.
- i. Foreground maintenance (for example, commands executed on the Manager I terminal) is not affected.

The actions in the previous list serve to reduce the system load, which could become excessive if too many maintenance objects are affected by a Packet Bus failure. However, such an excessive load should in no way impede the isolation and the correction of the faults.

When the actions in the list are implemented, Error Type 3329 is logged against PKT-BUS, and a Warning alarm is raised (although other Packet Bus errors in many cases raise more severe alarms, thereby overriding the Warning alarm).

## Error Log Entries and Test to Clear Values

Table 5-388. PKT-BUS Error Log Entries

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
0 <sup>1</sup>	0	Any	Any	Any	test pkt l
1 (a)	1-2	Packet Circuit Pack Audit Test (#570)	MAJOR	ON	test pkt p l r 2
513 (b)	1-24	Maintenance/Test Circuit Pack Query Test (#572)	MAJOR	ON	test pkt p l r 2
1793 (c)	Any	none			
2305 (d)	1-24	Maintenance/Test Circuit Pack Query Test (#572)			test pkt p l
3329 (e)	1-7	none	WARNING	ON	test pkt p l
3585 (f)	Any	none	MINOR	ON	test pkt p l

1. Run the Long Test Sequence. Refer to the appropriate test description and follow the recommended procedures.

**NOTE:**

For PKT-BUS, an ON-BOARD alarm indicates a problem with the Packet Bus itself.

**Notes:**

- a. Within the last minute, packet circuit packs have reported errors that indicate a possible Packet Bus failure. The Aux Data value is 1 or 2, indicating that only one or more than one Packet circuit pack (respectively) have reported a possible Packet Bus failure.
- b. The Maintenance/Test Packet Bus port has determined that there are Packet Bus shorted-lead or stuck-lead faults. The Aux Data value indicates the number of faulty leads.
- c. Packet circuit packs have detected possible Packet Bus failures via in-line error or background test failure. Examine the Error and Alarm logs for more specific PKT-BUS errors.
- d. The Maintenance/Test Packet Bus port has detected open leads on the Packet Bus. The Aux Data value indicates the number of open leads.
- e. Packet circuit pack, port, and endpoint maintenance has been disabled due to a Packet Bus failure. The Aux Data value indicates which sources have reported errors that have caused maintenance to be disabled. These sources include the following:
  - In-line errors from Packet circuit packs.
  - Packet Bus fault report from the Maintenance/Test Packet Bus port.

The Aux Data values that indicate these sources are identified in the following table:

Aux Data	Packet Circuit Pack	Maint/Test Circuit Pack
1	X	
2		X
3	X	X
4		
5	X	
6		X
7	X	X

**NOTE:**

It is important to remember that problems reported by Packet circuit packs may be caused by **any** circuit pack. However, only Packet circuit packs can detect such problems (inasmuch as TDM-only circuit packs are not affected by these problems).

**5 Maintenance Objects for DEFINITY ONE**  
*PKT-BUS (Packet Bus)*

5-954

- f. Packet circuit pack, port, and endpoint maintenance has been disabled due to more than one circuit pack reporting in-line errors. If this occurs more than three times in 15 minutes (that is, if maintenance is disabled due to errors and then re-enabled because no more errors are reported), a Minor alarm is raised against the Packet Bus. Note that this error may still be present in the error log even if the "Circuit Pack Audit Test" reports that only one circuit pack has indicated a problem. This occurs if more than one circuit pack reported errors with in any one minute interval since the Packet Bus fault occurred.

---

**System Technician-Demanded Tests: Descriptions and Error Codes**

---

Always investigate tests in the order presented in the following tables when you are inspecting errors in the system. By clearing error codes associated with the *Packet Circuit Pack Audit Test*, for example, you may also clear errors generated from other tests in the testing sequence.

Order of Investigation	Short Test Sequence	Long Test Sequence	D/ND <sup>1</sup>
Packet Circuit Pack Audit Test (#573)	X	X	ND
Maintenance/Test Circuit Pack Query Test (#572)	X	X	ND

---

1. D = Destructive; ND = Nondestructive

**Maintenance/Test Circuit Pack Query Test (#572)**

This test queries the Maintenance/Test Packet Bus port about the state of health of the Packet Bus. If the Maintenance/Test circuit pack indicates that the Packet Bus has faults, the test fails. The corresponding failure code describes the severity, type, and number of faults. The test passes if the Packet Bus is fault-free.

**⇒ NOTE:**

A Maintenance/Test circuit pack is usually not present in the system unless the customer has purchased this circuit pack to use for ISDN-PRI test calls, or to enhance the system's ability to quickly recognize a Packet Bus failure.

Table 5-389. TEST #572 Maintenance/Test Circuit Pack Query Test

Error Code	Test Result	Description/ Recommendation
1006	ABORT	The Packet Bus port of the Maintenance/Test circuit pack is out of service. 1. Determine if the port is busied out. If so, release the port by entering the <a href="#">release port PCSS04</a> command on page. Re-enter the test command.
1142	ABORT	No Maintenance/Test circuit pack Packet Bus port is in service in this system. 1. The Maintenance/Test Packet Bus Port may not be present. If the port is present, and if it is busied out or has failed, release or replace the circuit pack. If there is no Maintenance/Test circuit pack, ignore the results of this test.
2000	ABORT	The test timed-out while waiting for an uplink CCMS response from the Maintenance/Test Packet Bus port. 1. Retry the command at 1-minute intervals a maximum of 5 times. 2. If the test continues to abort, check for problems with the Maintenance/Test Packet Bus port.
2059	ABORT	The Maintenance/Test Packet Bus port has reported a hardware failure. 1. Re-enter the test command.
2077	ABORT	The Maintenance/Test Circuit Pack Query located more than one Maintenance/Test Packet Bus port in the system.   <b>NOTE:</b> The software should not allow this to occur. This is an Internal system error. Attempt the following work-around steps.  1. Remove all Maintenance/Test circuit packs from the system. 2. Insert one Maintenance/Test circuit pack (there should not be more than one in a system). 3. Re-enter the test command.
2100	ABORT	Maintenance could not allocate all of the necessary system resources to perform this test.
2500	ABORT	An internal operation failed; the test could not be completed. 1. Retry the command at 1-minute intervals a maximum of 5 times.
XYZZ	FAIL	The Maintenance/Test Packet Bus port has detected faults on the Packet Bus. The error code is encoded as follows:
1xxx		The Maintenance/Test Packet Bus port has reconfigured the Packet Bus around the faulty leads. This action occurs only in high or critical reliability systems, and such a failure code should not appear in an R8csi system.

Continued on next page

5 Maintenance Objects for DEFINITY ONE  
PKT-BUS (Packet Bus)

5-956

Table 5-389. TEST #572 Maintenance/Test Circuit Pack Query Test — *Continued*

Error Code	Test Result	Description/ Recommendation
2xxx		The Maintenance/Test Packet Bus port is unable to correct all of the Packet Bus faults it has detected. This action occurs only in high or critical reliability systems, and such a failure code should not appear in an R8csi system.
x0xx		None of the Packet Bus faults are open faults.
x1xx		At least some of the Packet Bus faults are open faults. Look for Error Type 2305 in the Error Log. The Aux Data value indicates the number of open leads.
xxZZ		The last 2 digits of the error code indicate the total number of faulty Packet Bus leads detected by the Maintenance/Test Packet Bus port. <ol style="list-style-type: none"><li>1. Refer to the "Packet Bus Fault Isolation Flowchart" section in Chapter 9 of <i>DEFINITY Enterprise Communications Server Release 8.2 Maintenance for R8.2si</i> (555-233-123) to determine the cause of the failures.</li></ol>
	PASS	No faults have been detected on the Packet Bus by the Maintenance/Test circuit pack. This indicates that the Packet Bus is operating correctly.

**Packet Circuit Pack Audit Test (#573)**

This test determines whether Packet circuit packs have reported Packet Bus-related in-line errors within the last minute. If so, the failure code indicates whether one or more circuit packs have reported failures within the last minute.

Due to the one-minute time constraint included as part of this test, the test is designed to delay 15 seconds before returning a result in cases where the test has failed within the last five minutes. This procedure helps ensure that a repeated sequence of the test does not always yield the same result. If no failure has occurred in the last five minutes, a PASS is returned immediately.

**Table 5-390. Test #573 Packet Circuit Pack Audit Test**

Error Code	Test Result	Description/ Recommendation
2500	ABORT	An internal operation failed; the test could not be completed. 1. Retry the command at 1-minute intervals a maximum of 5 times.
1	FAIL	One Packet circuit pack has reported Packet Bus-related in-line errors within the last minute.
2	FAIL	More than one Packet circuit pack has reported Packet Bus-related in-line errors within that last minute. 1. Refer to the "Packet Bus Fault Isolation Flowchart" section in Chapter 9 of <i>DEFINITY Enterprise Communications Server Release 8.2 Maintenance for R8.2si</i> (555-233-123) to determine the cause of the error reports.
	PASS	No Packet circuit packs have reported Packet Bus-related in-line errors within the last minute. This indicates that the Packet Bus is healthy, or that a Packet Bus fault is transient or is being caused by a faulty Packet circuit pack. If this test passes while there are other signs of a Packet Bus failure (as indicated, for example, in the Error/Alarm Logs or by other test failures), refer to the "Packet Bus Fault Isolation Flowchart" section in Chapter 9 of <i>DEFINITY Enterprise Communications Server Release 8.2 Maintenance for R8.2si</i> (555-233-123) to isolate the problem.

## PKT-INT (Packet Interface)

---

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run	Full Name of MO
PKT-INT	MAJOR	reset packet-interface [1a l or 1a2]	Packet Interface
PKT-INT	MINOR	test packet-interface [1a l or 1a2]	Packet Interface
PKT-INT	WARNING	test packet-interface [1a l or 1a2]	Packet Interface

PKT-INT on the TN795 is implemented as a task-based module on the MPC860. The PKT-INT firmware module shares the processor with many other firmware modules.

The packet interface (PKT-INT) connected to the TDM bus provides the PRI interface to the SPE (Switch Processing Element) over the TDM bus. The PKT-INT connected to the packet bus provides the PRI interface and the TCP/IP interface from the C-LAN (TN799) to the SPE over the packet bus

The Packet Interface (PKT-INT) provides PRI link through the TDM bus. In addition to affecting telephone service, a failure of the Packet Interface affects service provided by the following circuit pack that connects to the TDM bus:

- TN767 — ISDN PRI service

The links that pass through the Packet Interface are identified as system links, and are defined as follows:

1. System links
  - ISDN PRI D channel signaling links
  - ISDN BRI D channel broadcast and point-to-point signaling links

## Packet Interface Service Operations

---

The following sections provides more background information about Packet Interface service operations.

### Administration

There are no **add** or **remove** commands associated with the Packet Interface. The Packet Interface is always present in the system, even if no ISDN application is administered.

## Packet Interface Replacement

When replacing the Packet Interface (as a part of the TN795 Processor circuit pack), follow the procedure used for replacing the TN795 Processor circuit pack. The carrier must be powered down before the TN795 is removed and then the carrier must be powered back up after the circuit pack is inserted.

### **WARNING:**

*When the disk is replaced on the TN795, a new license file must be downloaded to the system before the system will become operational. Refer to "Obtaining a License File" in Chapter 3 of DEFINITY ONE™ Communications System Release 2.0 Installation and Upgrades (555-233-109).*

### **CAUTION:**

*Replacing the TN 795 processor board can display the translation error message, "TRANS\_ID INTERVAL EXPIRATION:xx days when logging into the SAT window. If this occurs, immediately call a Lucent Technical Services Consultant (TSC) to remove the error message. While the switch is in the error condition, the save translations command is not available.*

## Error Log Entries and Test to Clear Values

Table 5-391. Packet Interface Error Log Entries

Error Type	Aux Data	Associated Test	Alarm Level	On/Of f Board	Test to Clear Value
0 <sup>1</sup>	0	Any	Any	ON	test packet-interface [1a1 or 1a2]   r 2
1(a)	Any	None	MAJOR	ON	
257 (b)		None			
513 (c)	0	None	MAJOR	OFF	
769 (d)	0	None			
1281(e)	0	Test #1356 Restart Failure	MAJOR	ON	
2305 (f)	0	None	WARNING	OFF	
3074 (g)	Any	None	MAJOR	ON	

*Continued on next page*

Table 5-391. Packet Interface Error Log Entries — *Continued*

Error Type	Aux Data	Associated Test	Alarm Level	On/Of f Board	Test to Clear Value
3585 (h)	0	None	WARNING	OFF	
3841 (i)	Any	None	MAJOR	ON	

- Indicates that an alarm was raised but an associated error was not entered into the hardware error log due to a momentary overload condition caused by a burst of hardware or software error reports. Run the long test sequence. Refer to the appropriate test descriptions for any failures and follow the recommended procedures.

Notes:

- Error Type:1 - This error occurs when background maintenance software has reset the Packet Interface as a fault recovery action. It is used to keep track of the number of times that the Packet Interface is reset, independent of whether or not the Reset test passed. Once three of these errors have occurred in the last 15 minutes, maintenance will place the Packet Interface into an out-of-service state, and a MAJOR on-board alarm will be raised on the Packet Interface.
  - Check to see if error codes 257, 513, 769, 1281, or 3841 are present in the hardware error log. If one or more of those error codes are present, refer to the information associated with those errors for the appropriate repair procedures.
  - If no other Packet Interface errors appear in the error log, and if the Packet Interface is not in a held reset state as indicated by the absence of a MAJOR alarm with a Service State of OUT, no action should be taken. If a Packet Interface MAJOR alarm is present and no other Packet Interface error codes are in the hardware error log, execute a demand reset by entering **reset packet-interface**.
  - if this fails execute **reset packet-interface [1a1 or 1a2] restart**.
- Error Type: 257 - Indicates that the PKT-INT detected a fatal failure. This error is a very serious and when it occurs, maintenance software immediately escalates testing to the destructive reset test (#882).

A fatal fault in-line error can be generated by the following failure conditions:

- In-line errors from PKT-INT firmware
  - Failure of the initialization tests during board reset
  - Failure of the Private LAPD or Broadcast Looparound Tests
  - When a LANHO critical error or LANHO over-length packet error occurs

5 Maintenance Objects for DEFINITY ONE  
PKT-INT (Packet Interface)

5-961

- When the values in the Configuration Control Area (CCA) are unacceptable
- When PKT-INT does not have enough memory to allocate the buffers and tables required by the CCA.
- 2. In-line errors from the Packet Control Driver (PCD) software
  - When the PCD does not agree with the state of the PKT-INT
  - Failure of the Sanity Handshake Test
  - When the PCD times out waiting for the PKT-INT to come into service during initialization
- c. Error Type: 513 - This error type indicates that a message protocol error (Handshake failure) between Packet Control Driver (PCD) and the Packet Interface was detected. These software/firmware modules are running on the MPC860 processor (part of the TN795 processor circuit pack).
  1. If the Packet Interface (PKT-INT) has a MAJOR alarm:
    - a. Reset the Packet Interface using the reset packet-int command or.
    - b. If the above step fails use restart packet-interface [1a1 or 1a2] [restart]
  2. If the test still fails, follow normal escalation procedures.
- d. Error 769 indicates that the maintenance-loop-around test failed. A maintenance loop around cannot be established or the packet interface circuit cannot send and receive data correctly as part of loop-around-test 886. If the number of errors exceeds a defined threshold, a major alarm will be raised. For more information, refer to the repair procedures for test 886. If handshake is up, execute a test long clear of the alarmed circuit pack and follow recommended procedures.
- e. Error Type: 1281 - This error type indicates that the Packet Interface has been restarted as a result of a fault recovery action. This action occurred due to error type 1 occurring three times within 15 minutes. As a result of this action the PKT-INT will be taken out of service.
- f. Error Type: 2305 - This error indicates that the Packet Bus Interface received packets with parity error from the Packet bus.
  1. Check for errors logged against the Packet bus. Refer to the appropriate repair procedures to clear those errors first.
  2. Check all other circuit packs connected to the Packet bus in the same cabinet. Packet Bus failures are likely to be caused by a faulty circuit pack connected to the backplane or bent pins on the back plane.
  3. If steps 1 and 2 above do not clear the problem, execute the **test packet-interface** command and follow repair procedures described for Test #887.

- g. Error Type: 3074 - indicates PKT-INT Transmit Buffer Overflow, which means that the number of transmit buffers required by software exceeded the number available. A 3074 error is generated when the PKINT sends an in-line hardware error to maintenance software indicating transmit buffer overflow. As part of the background recovery action for this error, maintenance software will automatically run the Maintenance Looparound test (#886). If that test fails, maintenance software requests a system WARM restart. If, after the WARM restart, transmit buffer overflow errors continue to be reported, maintenance software resets the PKT-INT.
1. Check for errors logged against the Packet Data Line circuit packs associated with the System Ports, BRI Line circuit packs and BRI endpoints, and the Universal DS1 circuit packs supporting PRI service. Errors against those components should be cleared first.
  2. Run Maintenance Looparound Test (#886). If test (#886) test passes, the alarm will clear. If the test fails, repeat the test 5 times. If it continues to fail, follow normal escalation procedures.
- h. Error Type: 3585 - This in-line error is generated when the PKT-INT has entered a "fatal fault" state due to the failure of the Packet Bus (see ["PKT-BUS \(Packet Bus\)" on page 5-950](#)).

 NOTE:

The PKT-INT is not taken out of service since it is used for running Packet Bus tests.

- i. Error Type: 3841 - This in-line error is generated when the PKT-INT enters its "fatal fault" state (the LANHO has gone insane). A PKT-INT fatal fault error and a Packet Bus LAN Critical error ("["PKT-BUS \(Packet Bus\)"](#)") are also reported at the same time. The PKT-INT reset test is run when a LAN Critical Fault is detected. However, before the PKT-INT is reset, a check is made to see if the PPN Packet Bus has a major alarm, indicating that the Packet Bus rather than the PKT-INT is the source of the failure (see ["PKT-BUS \(Packet Bus\)"](#)).
1. If error 3585 has also been reported, refer to ["PKT-BUS \(Packet Bus\)" on page 5-950](#). After the Packet Bus failure has been corrected, execute the **reset packet-interface** command to bring the Packet Interface circuit back into service.
  2. If the above step fails, enter `reset packet-interface [1a1 or 1a2]` restart.
  3. If error 3585 has not been reported, enter the **reset packet-interface** command and follow the repair steps associated with test #882.
  4. If the above step fails, enter `reset packet-interface [1a1 or 1a2]` restart.
  5. If the test still fails, follow normal escalation procedures.

## System Technician-Demanded Tests: Descriptions and Error Codes

---

Always investigate tests in the order presented in the table below. By clearing error codes associated with the *Packet Interface Private Looparound* test for example, you may also clear errors generated from other tests in the testing sequence.

Order of Investigation	Short Test Sequence	Long Test Sequence	Reset Board Sequence	D/ND <sup>1</sup>
Packet Interface Reset Test (#889)			X	D
Packet Interface Private Looparound Tests (#885)		X <sup>2</sup>		ND
Packet Interface Maintenance Looparound Test (#886)	X <sup>2</sup>	X <sup>2</sup>		ND
Packet Interface Restart Action (#1357)				X
Read and Clear Counters Test (#887)	X	X		ND

- 
1. D = Destructive; ND = Nondestructive
  2. This test is executed only for PKT 1a2

### Private Looparound Tests (#885)

This test requests the Packet Interface circuit pack to execute its three private looparound tests: Level 2 looparound, Broadcast path looparound, and Level 3 looparound. These tests verify the health of the circuit pack's Packet Bus interface, as well as the translation RAM, inward and outward bound data paths, parity indications and CRC calculations, and the Level 3 processing firmware.

- Level 2 (LAPD) Link Looparound

LAPD is a link level protocol that is used for all system links. This test verifies the health of the processing of these links.

- Broadcast Link Looparound

Each ISDN BRI port has two associated broadcast signaling links, one for call control and one for maintenance and management. Since these links have separate routing circuitry from the Level 2 Looparound, this test forces a CRC error to verify the CRC hardware associated with the broadcast data path.

These tests are also run as part of the reset tests. If the Level 2 looparound test fail as background tests, a "fatal error" message will be sent to the Packet Interface maintenance software and the Packet Interface will be put in the "out-of-service" state. Therefore, it is expected that the repair procedures associated with Abort Code 1137 (out-of-service) would normally be followed when failures with the Level 2 and Level 3 tests occur.

Table 5-392. TEST #885 Private Looparound Tests

Error Code	Test Result	Description/ Recommendation
1006 1137	ABORT	Packet Interface circuit pack is in the out-of-service state so normal maintenance tests will not run on that circuit pack.  1. Request a Packet Interface circuit pack reset using the <b>reset packet-interface CS</b> or <b>reset packet-interface [1a1 or 1a2]</b> restart command. Refer to " <a href="#">Packet Interface Reset Test (#889)</a> " on page 5-971 for repair procedures.
1334	ABORT	The Packet Interface circuit pack command queue is full. This should be a temporary condition caused by a high rate of commands being sent to a Packet Interface circuit pack. Continued operation with a full command queue will cause a system WARM restart that may escalate to more severe restart levels.  1. Retry the command at 10-second intervals, a maximum of 5 times.
2000	ABORT	Response to the test request was not received within the allowable time period.  1. Retry the command at 1-minute intervals, a maximum of 3 times.
2500	ABORT	Internal system error  1. Retry the command.
	NO BOARD	The Packet Interface circuit pack is administered and is present but it is not detected as being physically present.  1. If the Packet Interface circuit pack is present, replace it.

*Continued on next page*

Table 5-392. TEST #885 Private Looparound Tests — *Continued*

Error Code	Test Result	Description/ Recommendation
1	FAIL	<p>The Private Link Broadcast looparound test failed. The Packet Interface will enter a fatal fault state when this occurs and the Packet Interface Maintenance software should put the circuit in a out-of-service state. Therefore by the time further action is taken, it is expected that the test will abort with ABORT code 1137 and a demand reset or a demand restart should be used to test the circuit pack.</p> <ol style="list-style-type: none"><li>1. Reset the circuit pack using the <b>reset packet-interface CS</b> if this fails execute a reset packet-interface 1a1 or 1a2 restart command. Refer to the repair procedures in "<a href="#">Packet Interface Reset Test (#889)</a>" on page 5-971 for further action.</li></ol> <p> <b>CAUTION:</b> <i>Replacing the TN795 processor circuit pack will disrupt service, see the TN795 processor replacement procedures in this document before proceeding with step 2.</i></p> <p> <b>WARNING:</b> <i>When the disk is replaced on the TN795, a new license file must be downloaded to the system before the system will become operational. Refer to "Obtaining a License File" in Chapter 3 of DEFINITY ONE™ Communications System Release 2.0 Installation and Upgrades (555-233-109).</i></p> <p> <b>WARNING:</b> <i>If the test continues to fail, replace the TN795 processor circuit pack.</i></p>

*Continued on next page*

Table 5-392. TEST #885 Private Looparound Tests — *Continued*

Error Code	Test Result	Description/ Recommendation
2	FAIL	<p>The Private Level 2 looparound test failed. The Packet Interface will enter a fatal fault state when this occurs and the Packet Interface Maintenance software should put the circuit in a out-of-service state. Therefore by the time further action is taken, it is expected that the test will abort with ABORT code 1137 and a demand reset should be used to test the circuit pack.</p> <ol style="list-style-type: none"><li>1. Reset the circuit pack using the <b>reset packet-interface CS</b> if this fails execute a reset packet-interface 1a1 or 1a2 restart command. Refer to the repair procedures in <a href="#">“Packet Interface Reset Test (#889)” on page 5-971</a> for further action.</li></ol> <p> <b>CAUTION:</b> <i>Replacing the TN795 processor circuit pack will disrupt service, see the TN795 processor replacement procedures in this document before proceeding with step 2.</i></p> <p> <b>WARNING:</b> <i>When the disk is replaced on the TN795, a new license file must be downloaded to the system before the system will become operational. Refer to “Obtaining a License File” in Chapter 3 of DEFINITY ONE™ Communications System Release 2.0 Installation and Upgrades (555-233-109).</i></p> <ol style="list-style-type: none"><li>2. If the test continues to fail, replace the TN795 processor circuit pack.</li></ol>
	PASS	<p>All the private looparound tests passed. The circuit pack is functioning properly. If the system is still unable to place calls on cabinets other than the SPE cabinet, then:</p> <ol style="list-style-type: none"><li>1. Display the error log using the command <b>display errors</b> and check for errors on the Packet Bus and Maintenance/Test circuit pack. Clear those errors first.</li><li>2. Check all other circuit packs connected to the Packet Bus in the same cabinet. Packet Bus failures are likely to be caused by a faulty circuit pack connected to the backplane or bent pins on the back plane. Refer to the <a href="#">“PKT-BUS (Packet Bus)”</a> maintenance documentation for repair procedures.</li></ol>

**Maintenance Looparound Test (#886)**

This test checks whether the Packet Interface circuit pack can send and receive data correctly. It establishes a LAPD link from a Packet Interface circuit pack back to the same Packet Interface circuit pack and transmits and receives test data over that testing link. While timing signals from the Packet Bus are used for the data transfer, the data itself is looped around on the circuit pack at the interface to the Packet Bus and does not get sent over the Packet Bus.

**Table 5-393. TEST #886 Maintenance Looparound Test**

Error Code	Test Result	Description/ Recommendation
1006 1137	ABORT	Packet Interface circuit pack is in the out-of-service state so normal maintenance tests will not run on that circuit pack.  1. Reset the circuit pack using the <b>reset packet-interlace CS</b> if this fails execute a <b>reset packet-interface 1a1</b> or <b>1a2 restart</b> command. Refer to the repair procedures in " <a href="#">Packet Interface Reset Test (#889)</a> " on page 5-971 for further action.
1139	ABORT	The Packet Bus is alarmed  1. Try to retire the alarm associated with the Packet Bus. Refer to the Alarm Log via the <b>display alarms</b> command. Refer to the maintenance documentation for Packet Bus Maintenance for further action.  2. Retry the command when the alarm associated with the Packet Bus is retired.
1373	ABORT	Could not establish the link loop around link to run this test.  1. Retry the command at 1-minute intervals, a maximum of 3 times.
2060	ABORT	Packet link bus went down during maintenance looparound test.  1. Retry the command at 1-minute intervals, a maximum of 5 times.  2. If there are errors associated with the Packet Bus, refer to the maintenance information associated with the Packet Bus.
2100	ABORT	Could not allocate the necessary system resources to run this test.  1. Retry the command at 1-minute intervals, a maximum of 5 times.
2500	ABORT	Internal system error  1. Retry the command at 1-minute intervals, a maximum of 5 times.
	NO BOARD	The Packet Interface circuit pack present but it is not detected as being physically present.  1. If the Packet Interface circuit pack is present, replace it.

*Continued on next page*

Table 5-393. TEST #886 Maintenance Looparound Test — *Continued*

Error Code	Test Result	Description/ Recommendation
1-3	FAIL	<p>The test failed. Maintenance was unable to establish a looparound link from the Packet Interface circuit pack back to itself or was unable to receive data that was sent out over one side of the looparound link.</p> <ol style="list-style-type: none"> <li>Issue the <b>test packet-interface CS</b> command to retry the test. If the same error code is observed, background maintenance software will automatically attempt to reset the circuit pack and clear the problem.</li> </ol> <p> <b>CAUTION:</b> <i>Replacing the TN795 processor circuit pack will disrupt service, see the TN795 processor replacement procedures in this document before proceeding with step 2.</i></p> <p> <b>WARNING:</b> <i>When the disk is replaced on the TN795, a new license file must be downloaded to the system before the system will become operational. Refer to "Obtaining a License File" in Chapter 3 of DEFINITY ONE™ Communications System Release 2.0 Installation and Upgrades (555-233-109). Retry the command and if the test fails, replace the circuit pack.</i></p> <ol style="list-style-type: none"> <li>If the test continues to fail after replacing the circuit pack, run the <b>test packet P long</b> command. If any of the tests fail, the fault may be on the Packet Bus. Refer to the <a href="#">"PKT-BUS (Packet Bus)"</a> Maintenance documentation for recommended repair procedures.</li> <li>If the test continues to fail after the circuit pack is replaced and with no other alarms associated with the Packet Bus or circuit packs connected to the Packet Bus, follow normal escalation procedures.</li> </ol>
	PASS	<p>This test passed. The circuit pack and its interface with the SPE are functioning properly. If the system is unable to place calls on cabinets other than the SPE cabinet, then:</p> <ol style="list-style-type: none"> <li>Check for errors on the Packet Bus and Maintenance/Test circuit pack. Solve those errors first.</li> <li>Check all other circuit packs connected to the Packet Bus in the same cabinet. Packet Bus failures are likely to be caused by a faulty circuit pack connected to the backplane or bent pins on the back plane.</li> <li>Check the Packet Interface circuit pack connections to the Packet Bus.</li> </ol>

## Read and Clear Board Counters (#887)

This test involves sending commands to read on-circuit pack error counters on the Packet Interface. It also verifies the message interface between the SPE and the Packet Interface. This test reads and clears the Parity Error counter and FIFO Overflow counter. Information about the number of bad Translation location is sent to maintenance software as an in-line error from the circuit pack so it is not necessary to read a counter location.

Table 5-394. TEST #887 Read and Clear Board Counters

Error Code	Test Result	Description/ Recommendation
1006 1137	ABORT	Packet Interface is in the out-of-service state so normal maintenance tests will not run on that circuit pack.  1. Request a Packet Interface reset using the <b>reset packet-interface 1a1 or 1a2 restart</b> .
2000	ABORT	Response to the test request was not received within the allowable time period.  1. Retry the command at 1-minute intervals a maximum of 3 times.
2500	ABORT	Internal system error  1. Retry the command.

*Continued on next page*

Table 5-394. TEST #887 Read and Clear Board Counters — Continued

Error Code	Test Result	Description/ Recommendation
256 512 768	FAIL	<p>The Packet Interface on the active SPE has an error counter set. The following error codes are possible: 256: Parity error 512: FIFO overflow 768: Parity error and FIFO overflow error</p> <ol style="list-style-type: none"> <li>1. If error code 256 or 768 is reported, the Packet Interface received a parity error off the Packet Bus.               <ol style="list-style-type: none"> <li>a. Check for alarms and errors logged against other circuit packs connected to the Packet bus in the Processor Port Network cabinet. A list of packet circuit packs is presented in the first section of this repair procedure. Refer to the repair procedures for those circuit packs, in this manual, to clear those errors first.</li> </ol> <p><b>⚠ CAUTION:</b> <i>Replacing the TN795 processor circuit pack will disrupt service, see the TN795 processor replacement procedures in this document before proceeding with step b.</i></p> <p><b>⚠ WARNING:</b> <i>When the disk is replaced on the TN795, a new license file must be downloaded to the system before the system will become operational. Refer to "Obtaining a License File" in Chapter 3 of DEFINITY ONE™ Communications System Release 2.0 Installation and Upgrades (555-233-109). Retry the command and if the test fails, replace the circuit pack.</i></p> <ol style="list-style-type: none"> <li>b. Replace the TN795 Processor circuit pack at a time that would cause the least disruption of service. The circuit pack is still functional but should be replaced.</li> </ol> <p>If error code 512 is reported, the receive FIFO in the PKT-INT has overflowed. For the current hardware configuration, only one Packet Interface is allowed. Retry the command after a 1-minute delay and if the test continues to fail:</p> <ol style="list-style-type: none"> <li>2. ) Replace the circuit pack at a time that would cause the least service disruption.</li> </ol> </li> </ol>
PASS		The SPE is able to communicate with the Packet Interface.

**Packet Interface Reset Test (#889)**

This test is destructive.

This test resets the Packet Interface and causes the PKT-INT to run a set of initialization tests. If all initialization tests pass, the reset causes a complete initialization of the PKT-INT. This is equivalent to a hardware reset mode of the PKT-INT firmware. All links are lost, and all PKT-INT firmware counters are reset. Additionally, the LANHO will be reset.

If any of the initialization tests fail, the reset test fails, and the PKT-INT enters its fatal fault state. Otherwise, the reset test passes. This test is used when maintenance receives a fatal fault (counter 2) from the board.

This test is destructive. This test is run due to in-line errors, on demand, and as part of system restarts, cold 2 and above.

**Table 5-395. TEST #889 Packet Interface Reset Test**

Error Code	Test Result	Description/ Recommendation
1362	ABORT	The system was unable to run this test, the PK-INT to be tested [1a1 or 1a2] is in service and is not available for reset. <ol style="list-style-type: none"><li>1. Use the "status packet interface" command to determine the service state of the packet interface circuit pack.</li><li>2. If the circuit pack is "out-of-service", retry the reset command.</li><li>3. If the reset continues to abort with the same error code and the packet interface circuit is "out-of-service", follow the normal escalation procedure.</li></ol>
2500	ABORT	Internal system error <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>

*Continued on next page*

Table 5-395. TEST #889 Packet Interface Reset Test — *Continued*

Error Code	Test Result	Description/ Recommendation
257- 258, 263- 264	FAIL	<p>The reset test failed for that particular PKT-INT.</p> <ol style="list-style-type: none"><li>1. Retry the command at least 5 times.</li><li>2. If it still fails with the same error code, execute “reset packet-interface [1a1 or 1a2] restart.” command. Retry the command at least 5 times.</li></ol> <p> <b>CAUTION:</b> <i>Replacing/Re-seating the TN795 processor circuit pack will disrupt service, see the TN795 processor replacement procedures in this document before proceeding with step 3.</i></p> <p> <b>WARNING:</b> <i>When the disk is replaced on the TN795, a new license file must be downloaded to the system before the system will become operational. Refer to “Obtaining a License File” in Chapter 3 of DEFINITY ONE™ Communications System Release 2.0 Installation and Upgrades (555-233-109). Retry the command and if the test fails, replace the circuit pack.</i></p> <ol style="list-style-type: none"><li>3. If it still fails, <b>re-seat</b> the TN795 circuit pack.</li><li>4. Re-execute the test 5 times.</li><li>5. If it still fails, <b>replace</b> the TN795 circuit pack and re-run the “reset packet-interface [1a1 or 1a2] restart.” command.</li></ol>
	PASS	The reset command passed and the Packet Interface is operational.

**Switch Control Restart Action Test (#1357)**

This test is disruptive.

This test restarts the associated Packet Interface module and determines if it can successfully go through its initialization sequence. The test is disruptive since there is the possibility of losing some control messages to or from port circuit packs.

Existing calls are not disconnected.

**Table 5-396. TEST #1357 Switch Control Restart Test**

Error Code	Test Result	Description/ Recommendation
1362	ABORT	<p>The system was unable to run this test, the PK-INT to be tested [1a1 or 1a2] is in service and is not available for reset.</p> <ol style="list-style-type: none"> <li>1. Use the "status packet interface" command to determine the service state of the packet interface circuit pack.</li> <li>2. If the circuit pack is "out-of-service", retry the reset command.</li> <li>3. If the reset continues to abort with the same error code and the packet interface circuit is "out-of-service", follow the normal escalation procedure.</li> </ol>
2500	ABORT	<p>Internal system error</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
264	FAIL	<p>The restart test failed for that particular PKT-INT.</p> <ol style="list-style-type: none"> <li>1. Retry the command at least 5 times.</li> <li>2. If it still fails with the same error code, execute "reset packet-interface [1a1 or 1a2] restart." command. Retry the command at least 5 times.</li> </ol> <p> <b>CAUTION:</b> <i>Replacing/Re-seating the TN795 processor circuit pack will disrupt service, see the TN795 processor replacement procedures in this document before proceeding with step 3.</i></p> <ol style="list-style-type: none"> <li>3. See Caution: If it still fails, <b>re-seat</b> the TN795 circuit pack.</li> <li>4. Re-execute the test 5 times.</li> <li>5. If it still fails, <b>replace</b> the TN795 circuit pack and re-run the "reset packet-interface [1a1 or 1a2] restart." command.</li> </ol>
	PASS	<p>The restart command passed and the Packet Interface is operational.</p>

## PMS-PRNT/JNL-PRNT (PMS Printer Link)

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run	Full Name of MO
PMS-PRNT/JNL-PRNT	MINOR	test journal pms-log/wakeup-log l	PMS Printer/ Journal Printer
PMS-PRNT/JNL-PRNT	WARNING	test journal pms-log/wakeup-log	PMS Printer/ Journal Printer



### NOTE:

PMS-PRNT stands for the pms-log printer. JNL-PRNT stands for the wakeup-log printer. Since the maintenance strategy for the both the JNL-PRNT and PMS-PRNT MOs is the same, both of these MOs are described in this section.

In DEFINITY Generic 1 and Generic 3iV2, there are up to two journal printers. They are identified as the wakeup-log printer which is shared between the Automatic Wakeup feature and the Emergency Access to Attendant feature to print scheduled reports and log of events, and the pms-log printer which is used as a backup of the PMS output device to print the audit trail data of all PMS transactions executed by the system and the PMS Housekeeping Status Change events while the PMS Printer Link is not available. The journal printer link is administered to a data extension that provides a standard EIA 232C interface to the printer. The printer can be connected through a data module (PDM, MPDM, DTDM) and a port on the TN754 or TN754B Digital Line circuit pack, or through an ADU and a port on the TN726 Data Line circuit pack.

PMS Printer Link Maintenance provides a strategy in the system for maintaining the link between the system and a PMS device (an external Journal Printer device). The strategy includes a set of tests for periodic diagnosis, detection of errors during normal operation, actions for troubleshooting, and raising alarms for serious problems. PMS Printer Link Maintenance uses a try-and-wait mechanism for maintaining the PMS Printer Link. If a PMS Printer Link is torn down due to an error, PMS Printer Link Maintenance intends to bring the link up immediately. If the trial of Link Setup fails, PMS Link Maintenance waits for five minutes before the next retry. If the number of retries reaches the value of a threshold (15), a Minor alarm is raised for service attention.

PMS Printer Link Maintenance does not cover the maintenance of the elements composing the journal printer physical link, for instance, the external printer device, Data Module (PDM/MPDM/DTDM) and Digital Line Port of TN754 or TN754B Digital Line circuit pack, ADU and Data Line Port of TN726 Data Line circuit pack, and Data Channels on TN777 Network Control circuit pack. If PMS Printer Link Maintenance cannot restore the PMS Printer Link, then the maintenance tests of these individual components of the PMS Link must be executed to diagnose faults.

## Procedures for Restoring the PMS Printer Link

1. Determine the status of the PMS Printer Link.

Enter **status journal-printer wakeup-log|pms-log** command and make sure that the journal printer link is not busied out for maintenance. If the link is down, then continue to the next step.

2. Where does the journal printer link connect?

Enter **display system hospitality** and find out the destinations of the PMS Printer Link.

3. Determine the status of the data extension.

Enter **status data extension** command and verify whether the data extension is in the in-service/idle state. If the data extension is NOT available, then look for the extension number in Alt Name field of Hardware Error Log. Refer to XXX-BD (Common Port Circuit Pack) Maintenance documentation for resolutions.

4. Is a data channel on Network Control circuit pack in the in-service/idle state?

Enter **list data** command and find out the extension numbers of data channels on Network Control circuit pack. Enter **status data extension** command and make sure that at least one data channel is in the in-service/idle state. If no data channel is available, look for DATA-CHL/DATA-CON/DATA-BD errors in the Error Log. If present, refer to "DATA-BD".

5. Is the external printer device available?

Make sure that the printer device is ON-LINE and ready for service. Check the physical connectivity between Data Module and the printer device.

It is recommended that you busyout the PMS Printer Link before executing maintenance tests over objects composing the PMS Printer Link. If the PMS Printer Link is busied out, then all PMS Printer Link maintenance actions are deactivated. The interference to tests of other MOs is off.

## Error Log Entries and Test to Clear Values

Table 5-397. PMS-PRNT/JNL-PRNT Link Maintenance Error Log Entries

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
0 <sup>1</sup>	0	Any	Any	Any	test journal wakeup-log pms-log sh
18 (a)	0	busyout journal wakeup-log/ pms-log	WARNING	OFF	release journal wakeup-log pms-log
257 (b)	0, 3 to 6 255	Link Retry Test (#215)	MINOR/ WARNING <sup>2</sup>	OFF	test journal wakeup-log pms-log 1
513 (c)	0, 3 to 6 255				test journal wakeup-log pms-log
769 (d)					

1. Run the Short Test Sequence first. If all tests pass, run the Long Test Sequence. Refer to the appropriate test description and follow the recommended procedures.

Both PMS Printer and Journal Printer are administered to the same extension, and the printer is not connected. Refer to the ["Procedures for Restoring the PMS Printer Link"](#) section for resolution.

2. Minor alarms on this MO may be downgraded to Warning alarms based on the value used in the **set options** command.

### Notes:

- a. System Technician busied out the Journal Printer Link. The link is torn down. Enter **release** command to restore the link.
- b. Link Retry Test (#215) fails. Physical link cannot be set up, usually because of hardware problems such as power off or cable disconnect. The Aux Data field contains the Channel ID of Data Channels on Network Control circuit pack (that is, 3 for Channel 01, 4 for Channel 02, 5 for Channel 03, 6 for Channel 04), an Error Code 255 for the Internal system error, or 0 which indicates that the data module connected to the PMS Printer Link is out-of-service. Refer to ["Procedures for Restoring the PMS Printer Link" on page 5-975](#) for resolution.
- c. Physical link cannot be set up, usually because of hardware problems such as power off or cable disconnect. The PMS Printer Link physical link is down due to the following causes: cable to the printer device is disconnected, the printer device is powered off, or the data extension where the printer device connects to has been busied out. The Aux Data field contains the Channel ID of Data Channels on Network Control circuit pack (that is, 3 for Channel 01, 4 for Channel 02, 5 for Channel 03, 6 for Channel 04). Check the connectivity of wire and cable among wall jacket,

**5** Maintenance Objects for DEFINITY ONE  
PMS-PRNT/JNL-PRNT (PMS Printer Link)

5-977

data module, and the printer device. Enter **status data <extension>** and verify that the data extension of the printer device is in the in-service/idle state. If the data extension is not available, then refer to [“Procedures for Restoring the PMS Printer Link” on page 5-975](#) for resolution.

- d. Link idle timer; link comes down. This error indicates that the printer device is in an off-line state, for example, paper jam or paper out for a printer device. Check the printer device and act promptly to put it back to on-line state. Enter **test journal wakeup-log|pms-log** command to set up the printer link.

---

**System Technician-Demanded Tests: Descriptions and Error Codes**

---

Always investigate tests in the order presented in the table below when inspecting errors in the system. By clearing error codes associated with the *Link Retry Test*, for example, you may also clear errors generated from other tests in the testing sequence.

Order of Investigation	Short Test Sequence	Long Test Sequence	D/ND <sup>1</sup>
Link Tear Down Test (#213)		X	D
Link Retry Test (#215)	X	X	ND

---

1. D = Destructive; ND = Nondestructive

## Link Tear Down Test (#213)

**This test is destructive.**

This test disconnects the existing link between the system and the external printer device. If the link has been disconnected already, this test just returns PASS. All resources allocated for a PMS Printer Link are released after this test.

Table 5-398. TEST #213 Link Tear Down Test

Error Code	Test Result	Description/ Recommendation
40	ABORT	Internal system error
50	ABORT	Internal system error 1. Retry the command at 1minute intervals a maximum of 5 times.
1010	ABORT	The link has been busied out to out-of-service. 1. Enter <b>release journal wakeup-log pms-log</b> command to release the link from busyout state. 2. Retry <b>test journal wakeup-log pms-log l</b> command to execute the test.
	FAIL	Internal system error 1. Retry the command at 1-minute intervals a maximum of 5 times.
	PASS	The link is torn down.

## Link Retry Test (#215)

This test sends a message to the journal printer management software process to make a data call to the extension where the printer device connects to. If the journal printer link is already up, this test passes without making any data call.

Table 5-399. TEST #215 Link Retry Test

Error Code	Test Result	Description/ Recommendation
10	ABORT	Internal system error
20	ABORT	Internal system error 1. Retry the command at 1-minute intervals a maximum of 5 times.
30	ABORT	Internal system error 1. Refer to <a href="#">“Procedures for Restoring the PMS Printer Link” on page 5-975</a> for instructions.
1010	ABORT	The PMS Printer Link has been busied out to out-of-service. 1. Enter <b>release journal wakeup-log pms-log</b> command to release the link from busyout state. 2. Retry <b>test journal wakeup-log pms-log I</b> command to execute the test.
	FAIL	The link CANNOT be established. 1. Refer to <a href="#">“Procedures for Restoring the PMS Printer Link” on page 5-975</a> for instructions.
	PASS	The link is up.

## PPP-PT (Control LAN Packet/Port)

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run <sup>1</sup>	Full Name of MO
PPP-PT	MAJOR	<b>test port UUCSSpp long</b>	PPP Port Maintenance
PPP-PT	MINOR	<b>test port UUCSSpp long</b>	PPP Port Maintenance
PPP-PT	WARNING	<b>test port UUCSSpp</b>	PPP Port Maintenance

1. *UU* is the universal cabinet number (1 for PPN, 2 - 44 for EPNs). *C* is the carrier designation (A, B, C, D, or E). *SS* is the number of the slot in which the circuit pack resides (01 to 21). *pp* is the two digit port number (01, 02, ...).

The TN799 Control LAN (C-LAN) packet port circuit pack provides TCP/IP connection to adjuncts applications such as CMS, INTUITY, and DCS Networking. The C-LAN circuit pack has 1-10baseT Ethernet connection and up to 16 DS0 physical interfaces for PPP connections. Multiple C-LAN circuit packs in a system gives additional TCP/IP capacity.

A remote socket control link (RSCL) links the C-LAN and the SPE to pass call control and other management information. Since one link serves all the ports on the circuit pack, maintenance of the RSCL is part of the C-LAN circuit pack maintenance.

### NOTE:

The C-LAN TN799 circuit pack combines the functions of the PGATE and PI circuit packs into one circuit pack. The PGATE or PI can be used with the C-LAN to create an X.25 to TCP/IP bridge for adjunct and DCS connectivity.

## Control LAN Congestion Controls

The switch activates congestion controls on C-LAN when it detects buffers exceeding the threshold. The switch releases the congestion controls when the C-LAN reports that its buffer level has returned to normal levels.

If congestion:	Then the switch:
Persists for a 14-minute interval	Raises MINOR alarm
Exhausts buffers	Raises MINOR alarm
Ceases for 12 minutes	Retires MINOR alarm

## Error Log Entries and Test to Clear Value

Table 5-400. PPP-PT Error Log Entries

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
0 <sup>1</sup>	0	Any	Any	Any	test port UUCSSpp s
1 (a)	0	SCOTCH Sync Looparound Test (#1275)	MINOR	ON	test port UUCSSpp l r 3
257 (b)	0		WARNING	OFF	
513 (c)	0		MINOR	OFF	
769 (d)	0		WARNING	OFF	
1281 (e)	0				
1537, 1538 (f)	See note	Session Status Test (#1286)	MINOR	OFF	
1793-1920 (g)	See note				
2305-2560 (h)	See note				
2561-2816 (h)	See note				
3329 (i)	35768	TCP/IP Ping Test (#1281)	WARNING	OFF	
3585 (j)	0-1	TDM Looparound Test (#1285)	MAJOR	ON	test port UUCSSpp l r 3

- Run the Short Test Sequence first. If all tests pass, run the Long Test Sequence. Refer to the appropriate test description and follow the recommended procedures.

### Notes:

- Error Type 001:** SCOTCH Synchronous Looparound Test (#1275) failed.
  - Test the port (**test port UUCSSpp long**).
  - Refer to "[SCOTCH Synchronous Looparound Test \(#1275\)](#)" on [page 5-985](#) for repair procedures.
- Error Type 257:** C-LAN port detected overrun or underrun condition that may indicate a hardware problem.
  - Test for hardware problem (**test port UUCSSpp long**).
  - Refer to "[SCOTCH Synchronous Looparound Test \(#1275\)](#)" on [page 5-985](#) for repair procedures.
  - Clear the alarm (**test port UUCSSpp long clear**).

- c. **Error Type 513:** PPP link lost end-to-end connectivity.
  - 1. Test for hardware problem (**test port UUCSSpp long**).
  - 2. Run [“TDM Looparound Test \(#1285\)” on page 5-984](#) and refer to repair procedures if there is a hardware problem.  
  
If there is no hardware problem, the switch tries to re-establish PPP link.
- d. **Error Type 769:** Port received an invalid frame, which
  - is greater than the maximum length
  - contains CRC errors
  - violates the link level protocol.
  - 1. Test the port (**test port UUCSSpp long**).
  - 2. Refer to [“TDM Looparound Test \(#1285\)” on page 5-984](#) to verify repair.
  - 3. Clear the alarm (**test port UUCSSpp long clear**).
- e. **Error Type 1281:** System software received an indication that the far-end has requested a disconnect of a session on this link. This is a log-only error.
- f. **Error Type 1537, 1538:** Some or all port sessions (sockets) are down.

If the switch indicates that:	Then it:
Some of the sessions are down	Raises off-board WARNING
All of the sessions are down	Raises off-board MINOR alarm

- 1. Test the port (**test port UUCSSpp short**).
- 2. Refer to [“Session Status Test \(#1286\)” on page 5-989](#) to verify repair.
- g. **Error Type 1793-1920:** system software received an indication that a socket was closed due to an error. Error Type indicates the application associated with this socket.

Error Type	Application
1793	Unused
1794	DCS
1795	AUDIX
1796	CMS
1797	ISDN Gateway
1798-1920	Reserved for future

Aux Data indicates the internal application number.

- h. **Error Type 2305-2816:** System software detected a session is down. Aux Data indicates the session number. These are log only errors. Error types 2305-2560 are for session numbers 1-256. Error types 2561-2816 are for session numbers 257-512.
- i. **Error Type 3329:** TCP/IP Ping Test failed.
  - 1. Test the port (**test port UUCSSpp short**).
  - 2. Refer to [“TCP/IP Ping Test \(#1281\)” on page 5-987](#) for repair procedures.
- j. **Error Type 3585:** TDM Port Looparound Test (#1285) failed.
  - 1. Test the port (**test port UUCsspp long**).
  - 2. Refer to [“TDM Looparound Test \(#1285\)” on page 5-984](#) for repair procedures.

### System Technician-Demanded Tests: Descriptions and Error Codes

Investigate errors in the order they appear in the table below.

Table 5-401. System Technician-Demanded Tests: PPP-PT

Order of Investigation	Short Test Sequence	Long Test Sequence	D/ND <sup>1</sup>
TDM Looparound Test (#1285)		X	D
SCOTCH Synchronous Looparound Test (#1275)		X	D
TCP/IP Ping Test (#1281)	X	X	ND
Session Status Test (#1286)	X	X	ND
PPP Link Status Test (#1279)	X	X	ND

*Continued on next page*

1. D = Destructive, ND = Non-destructive

## TDM Looparound Test (#1285)

 **NOTE:**  
**This test is destructive.**

This test verifies whether the C-LAN PPP port can send and receive data on the TDM bus. This test has a tone generator send tones on a timeslot, and it has a tone receiver receive tones on another timeslot. The tones are looped through the ppp port.

If the received tones:	Then:
Match the tones sent	The test passes
Do not match the tones sent	The test fails

Test failure indicates failure of the

- C-LAN (TN799) circuit pack
- TDM Bus
- Tone generator / tone receiver circuit pack

Table 5-402. TEST #1285 TDM Looparound Test

Error Code	Test Result	Description/ Recommendation
1000	ABORT	<p>The port is in use.</p> <ol style="list-style-type: none"> <li>1. Determine port status (<b>status clan-port UUCSSpp</b>).</li> <li>2. Retry the command when the port is idle. The port may be forced to the idle state by executing a <b>busyout port UUCSS</b> command.</li> <li>3. Escalate if the problem persists.</li> </ol> <p> <b>NOTE:</b> The <b>busyout port</b> command is destructive, causing all calls and links associated with the port to be torn down.</p>
1002	ABORT	<p>No TDM bus timeslots available for the test.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals, up to 5 times.</li> <li>2. Escalate if the problem persists.</li> </ol>
1003	ABORT	<p>No more tone receivers idle for use in this test.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals, up to 5 times.</li> <li>2. Escalate if the problem persists.</li> </ol>

*Continued on next page*

Table 5-402. TEST #1285 TDM Looparound Test — *Continued*

Error Code	Test Result	Description/ Recommendation
2000	ABORT	Did not receive circuit pack test response within the allowable time period. <ol style="list-style-type: none"> <li>1. If this problem persists, reset the circuit pack (<b>busyout board UUCSS</b>, <b>reset board UUCSS</b>, and <b>release board UUCSS</b>).</li> <li>2. If the problem persists, replace the circuit pack.</li> </ol>
2012	ABORT	Internal system error. <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals, up to 3 times.</li> <li>2. Escalate if the problem persists.</li> </ol>
2100	ABORT	Could not allocate the necessary system resources to run test. <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals, up to 5 times.</li> <li>2. Escalate if the problem persists.</li> </ol>
	FAIL	Received tones do not match transmitted tones. <ol style="list-style-type: none"> <li>1. Retry command at 1-minute intervals, up to 3 times.</li> <li>2. If the problem persists, refer to <a href="#">“TDM-BUS (TDM Bus)” on page 5-1116</a>, <a href="#">“TONE-PT (Tone Generator)” on page 5-1204</a>, and Tone Receiver repair procedures.</li> <li>3. If the problem persists, reset the board (<b>busyout board UUCSS</b>, <b>reset board UUCSS</b>, and <b>release board UUCSS</b>). Repeat the test.</li> <li>4. If the problem persists, replace the circuit pack.</li> </ol>
	PASS	Port connections across the TDM bus function properly.

## SCOTCH Synchronous Looparound Test (#1275)

**NOTE:**

**This test is destructive.**

This test verifies the circuit in the datapath of a ppp call. This test fails if the data transmitted on the port does not match the data received in the looparound mode. Failure of this test indicates a port hardware fault on the circuit pack.

This test aborts if calls are using the port, or if the PPP link associated with the port is connected. To avoid this, first enter **busyout data-module extension**, or **busyout port UUCSSpp**, or **busyout link link#**, which will cause all calls and links using the port to be torn down.

Table 5-403. TEST #1275 SCOTCH Synchronous Looparound Test

Error Code	Test Result	Description/ Recommendation
1000	ABORT	<p>The port is in use or PPP link is connected.</p> <ol style="list-style-type: none"> <li>1. Determine when the port is available for testing (<b>status clan-port UUCSSpp</b>).</li> <li>2. The port may be forced to the idle state by executing a <b>busyout port UUCSSpp</b> command.</li> </ol> <p> <b>NOTE:</b> This command is destructive, causing all calls and links using the port to be torn down.</p>
1002	ABORT	<p>No TDM bus timeslots available for the test.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals, up to 5 times.</li> <li>2. Escalate if the problem persists.</li> </ol>
1963	ABORT	<p>Firmware indicates that the port is in use or ppp link is connected.</p> <ol style="list-style-type: none"> <li>1. Determine when the port is available for testing (<b>status clan-port UUCSSpp</b>).</li> <li>2. The port may be forced to the idle state by executing a <b>busyout port UUCSSpp</b> command.</li> </ol> <p> <b>NOTE:</b> This command is destructive, causing all calls and links using the port to be torn down.</p>
2000	ABORT	<p>Did not receive circuit pack test response within the allowable time period.</p> <ol style="list-style-type: none"> <li>1. If this problem persists, reset the circuit pack (<b>busyout board UUCSS</b>, <b>reset board UUCSS</b>, and <b>release board UUCSS</b>).</li> <li>2. If the problem persists, replace the circuit pack.</li> </ol>
2012	ABORT	<p>Internal system error.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals, up to 3 times.</li> <li>2. Escalate if the problem persists.</li> </ol>
2100	ABORT	<p>Could not allocate the necessary system resources to run test.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals, up to 5 times.</li> <li>2. Escalate if the problem persists.</li> </ol>
	FAIL	<p>C-LAN circuit pack detected test failure.</p> <ol style="list-style-type: none"> <li>1. If the problem persists, reset the circuit pack (<b>busyout board UUCSS</b>, <b>reset board UUCSS</b>, and <b>release board UUCSS</b>).</li> <li>2. If the problem persists, replace the circuit pack.</li> </ol>
	PASS	<p>Port circuitry functioning properly.</p>

## TCP/IP Ping Test (#1281)

This non-destructive test fails if the endpoint fails to respond. Use this test to check the circuitry in the data path for a peer-to-peer IP layer connection.

Table 5-404. TEST #1281 TCP/IP Ping Test

Error Code	Test Result	Description/ Recommendation
1, 2, 7, 11	ABORT	Internal error <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals up to 3 times</li> <li>2. Escalate if the problem persists.</li> </ol>
1005	ABORT	Test configuration is incorrect. <ol style="list-style-type: none"> <li>1. Verify PPP link is in-service (<b>status clan-port UUCSSpp</b> or <b>status link n</b>).</li> <li>2. Repeat the test.</li> <li>3. Escalate if the problem persists.</li> </ol>
1124	ABORT	ppp link is not enabled. <ol style="list-style-type: none"> <li>1. Verify that the ppp link is enabled (<b>status port UUCSSpp</b>, <b>status link n</b>, or <b>display data-module</b>).</li> <li>2. If the link is not enabled, enable the link (<b>change data-module</b>).</li> <li>3. Repeat the test.</li> <li>4. Escalate if the problem persists.</li> </ol>
1125	ABORT	PPP link not in service. <ol style="list-style-type: none"> <li>1. Verify whether ppp link is in service (<b>status port UUCSSpp</b> or <b>status link n</b>).</li> <li>2. If the ppp link is not in service, release the link (<b>release link n</b> or <b>release port UUCSSpp</b>).</li> <li>3. Repeat the test.</li> <li>4. Escalate if the problem persists.</li> </ol>
2000	ABORT	Response to the test was not received from the C-LAN circuit pack within the allowable time period. <ol style="list-style-type: none"> <li>1. If this result occurs repeatedly, attempt to reset the circuit pack if the other ports on the board are not in use (Yellow LED is off). Reset the circuit pack (<b>busyout board UUCSS</b>, <b>reset board UUCSS</b>, and <b>release board UUCSS</b>).</li> <li>2. If this result occurs again, replace the circuit pack.</li> </ol>

*Continued on next page*

Table 5-404. TEST #1281 TCP/IP Ping Test — Continued

Error Code	Test Result	Description/ Recommendation
2012	ABORT	Internal system error. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals, up to 3 times.</li><li>2. Escalate if the problem persists.</li></ol>
2100	ABORT	Could not allocate the necessary system resources to run test. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals, up to 5 times.</li><li>2. Escalate if the problem persists.</li></ol>
2500	ABORT	Internal system error. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals, up to 3 times.</li><li>2. Escalate if the problem persists.</li></ol>
1003	FAIL	Ping to the destination failed due to on-board problem. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals, up to 3 times.</li><li>2. If the problem persists, reset the circuit pack (<b>busyout board UUCSS</b>, <b>reset board UUCSS</b>, and <b>release board UUCSS</b>).</li><li>3. If the problem persists, re-administer the PPP connection through a different PPP port, if available.</li><li>4. If the problem still persists, or if there are no other available PPP ports, replace the circuit pack.</li></ol>
1007	FAIL	Ping to the destination failed due to the destination down. <ol style="list-style-type: none"><li>1. A PPP destination or a component in the path (e.g., DS1 trunk) may be down. Check the status of the destination or other components in the path.</li><li>2. If the destination and all components in the path are in-service, ping the PPP destinations (<b>ping ip-address xxx.xxx.xxx.xxx</b>).</li><li>3. Escalate if the problem persists.</li></ol>
	PASS	TCP/IP Ping Test (#1281) is successful.

### Session Status Test (#1286)

This non-destructive test determines the status of all PPP port sessions. This test queries the system software on port session status.

If the system software indicates that:	Then the switch:
All port sessions are up (ALL UP)	Raises no alarm, or retires alarm
Some port sessions are up (SOME UP)	Raises MINOR alarm
All port sessions are down (ALL DOWN)	Raises MINOR alarm

Table 5-405. TEST #1286 Session Status Test

Error Code	Test Result	Description/ Recommendation
1124	ABORT	<p>ppp link is not enabled.</p> <ol style="list-style-type: none"> <li>1. Verify that the ppp link is enabled (<b>status port UUCSSpp, status link n, or display data-module</b>).</li> <li>2. If the link is not enabled, enable the link (<b>change data-module</b>).</li> <li>3. Repeat the test.</li> <li>4. Escalate if the problem persists.</li> </ol>
1125	ABORT	<p>PPP link not in service.</p> <ol style="list-style-type: none"> <li>1. Verify whether PPP link is in service (<b>status port UUCSSpp or status link n</b>).</li> <li>2. If the PPP link is not in service, release the link (<b>release link n or release port UUCSSpp</b>).</li> <li>3. Repeat the test.</li> <li>4. Escalate if the problem persists.</li> </ol>
2000	ABORT	<p>Did not receive circuit pack test response within the allowable time period.</p> <ol style="list-style-type: none"> <li>1. If the problem persists, reset the circuit pack (<b>busyout port UUCSSpp, reset board UUCSS, and release board UUCSS</b>).</li> <li>2. If the problem persists, replace the circuit pack.</li> </ol>
2100	ABORT	<p>Could not locate the necessary system resources to run this test.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals, up to 5 times.</li> <li>2. Escalate if the problem persists.</li> </ol>
2500	ABORT	<p>Internal system error.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals, up to 3 times.</li> <li>2. Escalate if the problem persists.</li> </ol>

Continued on next page

Table 5-405. TEST #1286 Session Status Test — *Continued*

Error Code	Test Result	Description/ Recommendation
1	FAIL	System software indicates at least one PPP link session is down (SOME UP). 1. Isolate downed sessions ( <b>status port UUCSSpp</b> or <b>status link n</b> ). Follow actions based on session information.
2	FAIL	System software indicates all PPP sessions are down (ALL DOWN). 1. Test the port ( <b>test port UUCSSpp</b> ) to verify the SCOTCH Synchronous Looparound Test (#1275) result. 2. If test passes, wait for system software to indicate ALL UP. 3. If the test fails, check the destination and other components in the path. 4. If the destination and other components in the path are in-service, take action based on session information.
	PASS	All sessions up.

**PPP Link Status Inquiry Test (#1279)**

This non-destructive test determines the state of the PPP link. The test passes only if the link is up.

**Table 5-406. TEST #1279 PPP Link Status Inquiry Test**

Error Code	Test Result	Description/ Recommendation
1124	ABORT	ppp link is not enabled. <ol style="list-style-type: none"><li>1. Verify that the ppp link is enabled (<b>status port UUCSSpp</b>, <b>status link n</b>, or <b>display data-module</b>).</li><li>2. If the link is not enabled, enable the link (<b>change data-module</b>).</li><li>3. Repeat the test.</li><li>4. Escalate if the problem persists.</li></ol>
1125	ABORT	PPP Link is not in service. <ol style="list-style-type: none"><li>1. Verify whether PPP link is in-service (<b>status port UUCSSpp</b> or <b>status link n</b>).</li><li>2. If the PPP link is not in service, release the link (<b>release link n</b> or <b>release port UUCSSpp</b>).</li><li>3. Repeat the test.</li><li>4. Escalate if the problem persists.</li></ol>
2100	ABORT	Could not locate the necessary system resources to run this test. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals, up to 5 times.</li><li>2. Escalate if the problem persists.</li></ol>
2500	ABORT	Internal system error. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals, up to 3 times.</li><li>2. Escalate if the problem persists.</li></ol>

*Continued on next page*

Table 5-406. TEST #1279 PPP Link Status Inquiry Test — *Continued*

Error Code	Test Result	Description/ Recommendation
	FAIL	<p>PPP link is down.</p> <ol style="list-style-type: none"><li>1. Test the port (<b>test port UUCSSpp long</b>) to verify the SCOTCH Synchronous Local Loop Around Test (#1275) result.</li><li>2. If the test passes, wait for sessions to come up.</li><li>3. If the test fails, check the destination and other components in the path (e.g., DS1 trunks).</li><li>4. If the destination and other components in the path are in-service and the test still fails, execute <b>busyout port UUCSSpp</b> and <b>release port UUCSSpp</b>, and repeat the test.</li><li>5. If the test still fails, reset the circuit pack (<b>busyout board UUCSS</b>, <b>reset board UUCSS</b>, and <b>release board UUCSS</b>). Repeat the test.</li><li>6. If the problem persists, replace the circuit pack.</li></ol>
	PASS	<p>PPP link is up.</p>

## PR-ADX (Processor Board - AUDIX Port)

---

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run	Full Name of MO
PR-ADX	MINOR	test port long	Processor Board AUDIX Port

The SSP (Scalable Speech Processor) is located on a “mezzanine” card (CWY1) on the TN795. The SSP is connected to the Pentium Processor on the TN795 using a PMC connector. This card provides the signal processing hardware to perform AUDIX functions and integrate announcement functions. Messages are stored on the PC hard disk. No additional AUDIX hardware is required.

DEFINITY maintenance software supports the SSP by using a virtual board concept to allow for board insertion and maintenance testing.

By default, the CWY1 card is represented as a virtual board in slot 1A12 for AUDIX functions and in virtual slot 1A13 for announcement functions. It supports up to 8 ports that are administered for 2500 sets but used as AUDIX ports. The name of the Maintenance Object for these ports is PR-ADX.

The CWY1 is not a field replaceable unit. If it fails, the TN795 processor board must be replaced.

### WARNING:

*When the disk is replaced on the TN795, a new license file must be downloaded to the system before the system will become operational. Refer to “Obtaining a License File” in Chapter 3 of DEFINITY ONE™ Communications System Release 2.0 Installation and Upgrades (555-233-109). Retry the command and if the test fails, replace the circuit pack.*

## Error Log Entries and Test to Clear Values

Table 5-407. PR-ADX Error Log Entries

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
0 <sup>1</sup>	0	Any	Any	Any	test port PCSS
1(a)		SSP Port Loop-Around Test Failure (#1351)	MINOR	ON	test port PCSS
257(b)		SSP Port Loop-Around Test Failure (#1351)	MINOR	ON	test port PCSS

1. Run the Short Test sequence first. If all tests pass, run the Long Test Sequence. Refer to the appropriate test description and follow the recommended procedures.

### Notes:

- a. Error Type: 1 - Error Type 1 occurs when the SSP Loop-Around Test #1351 fails. This failure may be due to TDM-BUS errors. If TDM-BUS errors exist refer to [“TDM-BUS \(TDM Bus\)” on page 5-1116](#) to diagnose TDM-BUS errors.
- b. Error Type 257 - Error Type 257 occurs when the port looparound action requested by Test # 1351 fails. Run test 1351 and refer to the repair steps for that test. See [“SSP-Port Loop Around Test \(#1351\)” on page 5-995](#)

## System Technician-Demanded Tests: Descriptions and Error Codes

Always investigate tests in the order presented in the table below. By clearing error codes associated with the *SSP CMC Loop Around Test* for example, you may also clear errors generated from other tests in the testing sequence.

Order of Investigation	Short Test Sequence	Long Test Sequence	D/ND <sup>1</sup>
SSP CMC Loop Around Test (#1351)	X	X	ND

1. D = Destructive; ND = Nondestructive

**SSP-Port Loop Around Test (#1351)**

This is a non-destructive test

This test is designed to test all SSP port interface mechanisms. It is run in response to background maintenance tests and craft demanded tests for SSP ports. This test covers hardware/firmware/software for the Time Division Multiplex Bus (TDM), Network Computing Element (NCE), Concentration Highway Interface (CHI), Timeslot Manager (TSM), and the VFM/CornerStone Application Interface Software.

When DEFINITY makes a call to AUDIX, it sends a connection request telling the VFM which timeslots the virtual port should listen to and talk on. The VFM allocates (via its concentration highway (CHI) manager) available CHI timeslots and requests the MPC860 firmware to ask, in turn, the timeslot interchanger (TSI) to map the DEFINITY timeslots on the chosen CHI timeslots. The VFM then sends a response to the CornerStone telling it which CHI timeslots the voice for the answered call is on.

DEFINITY maintenance software sets up a loop around connection on the SSP-CMC. The assigned port will be told to transmit a test bit pattern (digital test count) on one TDM timeslot and listen for the same digital test count on another, verifying that the connection is looped and that the test bit pattern (digital test count) is correct.

**Table 5-408. TEST #1351 SSP Port Loop Around Test**

Error Code	Test Result	Description/Recommendation
	ABORT	Internal System Error (a)
1000	ABORT	System resources required to run this test are not available. The port may be in use. Use the <b>display port PCSSpp</b> command to determine the voice port extension of the port. Use the <b>status station</b> command to determine the service state of the port. If the port is in use, it is unavailable for certain tests. Refer to "status" commands in Chapter 4, "Maintenance Commands for DEFINITY ONE", for explanations of all possible states. Wait until the port is idle before retesting, then retry the command at one minute intervals a maximum of 5 times.
1001	ABORT	System resources required to run this test are not available; retry the command at one minute intervals a maximum of 5 times.
1002	ABORT	The system could not allocate time slots for the test. The system may be under heavy traffic conditions, or it may have time slots that are out-of-service due to TDM-BUS errors. Refer to <a href="#">"TDM-BUS (TDM Bus)" on page 5-1116</a> to diagnose TDM-BUS errors. <ol style="list-style-type: none"> <li>1. If the system has no TDM-BUS errors and if it is not handling heavy traffic, retry the command at one minute intervals a maximum of 5 times.</li> </ol>

*Continued on next page*

Table 5-408. TEST #1351 SSP Port Loop Around Test — *Continued*

Error Code	Test Result	Description/Recommendation
1003	ABORT	<p>The system could not allocate a tone receiver for the test. The system may be oversized for the number of tone detectors present, or some tone detectors may be out-of-service.</p> <ol style="list-style-type: none"> <li>1. Resolve any "TTR-LEV" errors.</li> <li>2. Resolve any "TONE-PT" errors. Retry the command at one minute intervals a maximum of 5 times.</li> </ol>
1004	ABORT	<p>The port was put in use during the test. The test has been aborted. Use the <b>display port PCSSpp</b> to determine the voice port extension of the port. Use the <b>status station</b> command to determine the service state of the port. If the port is in use, it is unavailable for certain tests. Wait until the port is idle before retesting. Retry the command at one minute intervals a maximum of 5 times.</p>
2000	ABORT	<p>Response to the test request was not received within the allowable time period. Retry the command at one minute intervals a maximum of 5 times.</p>
2100	ABORT	<p>Could not allocate the necessary system resources for this test. Retry the command at one minute intervals a maximum of 5 times.</p>
Any	FAIL	<p>The test failed.</p> <ol style="list-style-type: none"> <li>1 - On-board link to CWY1 firmware is not up</li> <li>2 - On-board link to CWY1 firmware failed</li> <li>3 - Loop around test failed</li> </ol> <p> <b>NOTE:</b> Retry the command at one minute intervals a maximum of 5 times.</p> <ol style="list-style-type: none"> <li>3. If all ports on the board fail, busy out the board and run the board test to see if the CWY1 card on the TN795 board has failed. Refer to the repair steps in "<a href="#">SSP-CMC Diagnostic/Initialization Test (#1350)</a>" on <a href="#">page 5-1019</a>.</li> <li>4. If the board tests passes and one or more port tests still fail, check for TDM-BUS problems, TONE-PT problems, or ETR-PORT problems.</li> <li>5. If the test continues to fail, replace the TN795.</li> </ol>
	PASS	<p>The SSP Port Loop Around test passed. All ports are transmitting properly.</p> <ol style="list-style-type: none"> <li>1. To be sure that this is not an intermittent problem, repeat this test up to 10 times and see if it continues to pass.</li> <li>2. If complaints still exist, check for TDM-BUS problems. Otherwise, escalate the problem.</li> </ol>

## PR-AL-BD (Processor Alarm Board)

### Error Log Entries and Test to Clear Values

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run	Full Name of MO
PR-AL-BD	None	test board	Processor Alarm Board

The Processor Alarm Board is a virtual board that is used by DEFINITY ONE to provide External Device Alarm contacts to indicate to DEFINITY maintenance software if there are any non-DEFINITY alarms such as an AUDIX alarm or PC (global) level alarm present. There is no hardware associated with the virtual board. By default, the board is administered in slot 1A11. The MO name for the External Device Alarms is EXT-DEV.

### Error Log Entries and Test to Clear Values

Table 5-409. ALARM-PT Error Log Entries

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
0 <sup>1</sup>		Any	Any	Any	test board PCSS
1(a)		None	Minor	ON	
257(b)		Control Channel Loop Around test (#52)	Major	OFF	test board PCSS

1. Run the Short Test sequence first. If all tests pass, run the Long Test Sequence. Refer to the appropriate test description and follow the recommended procedures.

#### Notes:

- a. Error Type: 1 - The circuit pack was removed by the VFM. This is a software problem. Follow normal escalation procedures
- b. Error Type: 257 - The code and vintage was not returned from the VFM. This is a software problem. Follow normal escalation procedures.

## System Technician-Demanded Tests: Descriptions and Error Codes

Always investigate tests in the order presented in the table below. By clearing error codes associated with the Control Channel Local Loop Around Test, for example, you may also clear errors generated from other tests in the testing sequence.

Order of Investigation	Short Test Sequence	Long Test Sequence	D/ND <sup>1</sup>
Control Channel Looparound Test (#52)	X	X	ND
NPE Audit Test (#50)		X	ND

1. D = Destructive, ND = Non-destructive

### NPE Test (#50)

This test is nondestructive

The system sends a message to the on-board microprocessor to update the network connectivity translation for all the Network Processing Elements (NPEs) on the circuit pack. This test always returns a PASS for PR-AL-BD since the virtual alarm board has no Network Processing Element. The NPE test is included for the virtual alarm board just to be consistent with standard port board tests.

Table 5-1. Test #52 Control Channel Looparound Test

Error Code	Test Result	Description/Recommendation
	PASS	Maintenance software always returns PASS since there is no NPE for the virtual alarm board.

### Control Channel Looparound Test (#52)

This test is nondestructive

This test queries the Virtual Fabric Manager for the circuit pack code and vintage of the Virtual Alarm Board and verifies its records.

**Table 5-410. Control Channel Looparound Test**

None 2100	Test Result	Description/Recommendation
None 2100	ABORT	System resources required for this test are not available. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
	FAIL	The test failed because the Virtual Manager software failed to return the circuit pack code or vintage. <ol style="list-style-type: none"><li>1. Retry the command for a maximum of 5 times.</li><li>2. If the error occurs again, there is a software problem. Follow normal escalation procedures.</li></ol>
	PASS	Communication with the Virtual Fabric Manager is successful.
	EXTRA BD	Follow normal escalation procedures
Any	NO BOARD	Follow normal escalation procedures.

## PR-MAINT (Maintenance Processor)

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run	Full Name of MO
PR-MAINT	MIN <sup>1</sup>	test pr-maint	Maintenance Processor

1. Alarms on the PROCR and PR-MAINT maintenance objects are indicated by the red LED on the Processor circuit pack.

The TN795 processor circuit pack combines three major processing functions: A PENTIUM processor executes “software” for co-resident applications such as voice mail, call accounting, and DEFINITY PBX features. The CWY1 DSP card is a second functional block, integrated with the main board, for speech processing. Finally, a MPC860 processor (supported by the PR-MAINT maintenance object) supports the following hardware/firmware components:

- Remote and Environment Maintenance Functions
- Packet Interfaces (one for TDM interface and one for the packet bus interface)
- Tone/clock Functions
- Archangel Functions

The TN795 processor includes the Pentium (SPE), memory, hard disk, PCMIA interface (for disk backup), environment maintenance, Archangel, clocking, and generation, packet interfaces to the TDM and packet busses, the standard DEFINITY bus interfaces, and PCI bus support.

The packet interface (PKTINT) connected to the TDM bus provides the PRI interface to the SPE (Switch Processing Element) over the TDM bus. The PKTINT connected to the packet bus provides the PRI interface and the TCP/IP interface from the C-LAN (TN795) to the SPE over the packet bus.

The RM (Remote Maintenance) firmware executing as a module on the MPC860 also serves as a maintenance processor and watchdog for the SPE by monitoring the SPE’s sanity, performing hardware and environment diagnostics, and providing a remote access port if the SPE is down.

The following environment and system functions will be supported by the MPC860 tasking system:

- Remote Maintenance Firmware - is a firmware module running on an MPC860 processor under the VxWorks real-time operating system.
- Sanity Timer - the RM firmware maintains sanity with the SPE (Pentium) using a socket connection on the IML. The SPE expects the RM firmware module to respond to a sanity byte. The SPE expects RM firmware to increment this byte and return it over the socket connection within a limited time.
- Emergency Transfer Switch - a manual or software controlled switch that transfers a set of analog telephones directly through to Central Office trunk lines.
- External Alarm Input Leads - 2 leads indicating a major or minor alarm condition on an external device (e.g., an Applications Processor or UPS (A UPS alarm is always a MAJOR alarm)).
- Customer Provided Equipment (CPE) Alarm Device Leads - a relay closure to a customer provided alarm device indicating a system fault condition.
- LEDs - the alarm panel LEDs for Major Alarm, Minor Alarm, and Emergency Transfer State (the Warning Alarm and Alarm Acknowledgment LEDs are removed) are controlled by RM firmware in response to DEFINITY software maintenance commands. There is the standard set of red (TN795 alarm), green (test-in-progress) and yellow (in use) LEDs for indicating the status of the processor board itself. Additional LEDs under firmware control are the green LED for OK-to-remove and clock status (the TN795 includes the tone/clock functions), and in addition the PCMIA LED for disk access.
- Power/Fan Status input - is an input monitored by RM firmware that indicates the CMC cabinet power supply or a cooling fan has failed. In a multiple cabinet system, this lead represents the logical OR'ing of all cabinet power supplies and fans.
- RS-232 external modem - (no internal modem is available on the TN795 circuit pack). In the event the SPE is down, the RM firmware will terminate the serial port/modem connection for maintenance activities. Another operating mode exists when the RM firmware watches the PC-terminated connection for escape sequences. The escape sequences will be used for BIOS operations such as setup, upgrade, or BIOS boot. An additional use is for running PC Doctor/DOS for diagnosing NT problems.
- Voltage and temperature monitoring - the RM firmware has access to a multi-channel ADC (Analog-to-Digital-Converter) for measuring all TN795 voltages and the temperature at two locations.

**Error Log Entries and Test to Clear Values**

Table 5-411. PR-MAINT Error Log Entries

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
1(a)	Any	MTP Reset Test (#101)	MINOR	ON	test pr-maint l
257(b)	Any	MTP Sanity Handshake Test (#106)	MINOR		test pr-maint s/l
1281(c)	Any	Flow Control l		ON	
2049(d)	Any	External Modem Present Test (#230)	MINOR	OFF	test pr-maint
3585(e)		Restart RM Firmware Test (#1354)		MINOR	
3841(f)		NT Reboot Test (#1355)		MAJOR	

## Notes:

- a. Error Type: 1 - The MTP Reset Test (#101) has failed. It is possible MPC860 real time limitations are keeping RM from performing diagnostics and communicating quickly enough. Therefore, the test should be attempted more than once. However, if this test does not pass within a few attempts a minor alarm occurs since RM is important for INADs call backup and environment monitoring.
- b. Error Type: 257 - The MTP Sanity Handshake Test (#106) has failed. RM firmware must be able to monitor the TN795 environment, make an INADs call if the SPE is down, and communicate alarm conditions to maintenance software.
- c. Error Type: 1281 - The TCD maintains a counter to control the number of messages it reports. When the counter reaches its threshold, it stops reporting until the counter is reset by maintenance. This ensures that other counters can reach threshold but that maintenance does not get flooded by errors from the drivers. This error counter is for internal software use and its value is not logged by maintenance.
- d. Error Type: 2049 - The External Modem Present Test (#230) has failed. If the external modem does not respond with a dial tone indication, the external modem test will fail. The external modem test will abort if the modem is busy with legitimate activity.

Since modem availability is critical for INADs, several failures will cause a minor alarm.

- e. Error Type: 3585 - The Restart RM Firmware Test (#1354) has failed. If the RM firmware module cannot be restarted by maintenance software, the RM restart test will fail. Repeating failures of this counter are serious. Maintenance software will make several attempts to bring RM firmware back before requesting a complete reboot.
- f. Error Type:3841 - The Restart RM Firmware Test (#1354) has failed several times and a reboot or restart of DEFINITY is requested.

## System Technician-Demanded Tests: Descriptions and Error Codes

Always investigate tests in the order presented in the table below. By clearing error codes associated with the *MTP Reset Test*, for example, you may also clear errors generated from other tests in the testing sequence.

Order of Investigation	Short Test Sequence	Long Test Sequence	D/ND <sup>1</sup>
External Modem Present Test (#230)(a)	X	X	ND
MTP Sanity Handshake Test (#106)	X	X	ND
MTP Reset Test (#101)		X	ND

1. D = Destructive; ND = Nondestructive

### Notes:

- a. This test aborts if an external modem is not administered.

## MTP Reset Test (#101)

### This test is Nondestructive.

This test sends a *RESET RM* message to cause the RM firmware module to reset itself. During the reset, the RM firmware will execute diagnostic tests. The result of the diagnostics will be sent upstream as PASS/FAIL indication.

The reset test will implicitly check the IML socket between the TCD and RM firmware. It will also verify that the mechanism RM firmware uses to handle MTP type messages is functional.

The reset test will fail if:

- The RM firmware fails its diagnostics.

The reset test will abort if:

- The IML link or MTP message handler fail to establish bidirectional communication (upstream and downstream).
- The test has been disabled.
- There are not enough software resources to support the test

Table 5-412. TEST #101 MTP Reset Test

Error Code	Test Result	Description/ Recommendation
100	ABORT	The requested test did not complete within the allowable time period. 1. Retry the command.
2500	ABORT	Internal system error 1. Retry at 1-minute intervals a maximum of 5 times.
1196	FAIL	The RM firmware did not respond to being reset. 1. Retry at 1-minute intervals a maximum of 5 times. 2. If the test continues to fail “reset pr-maint restart” to restart RM firmware. 3. If the test continues to fail, replace the Processor circuit pack.
1197	FAIL	The RM firmware was reset, but it responded with a NOT PASS status, indicating that it did not pass initialization correctly. The RM firmware is not functioning correctly. The system continues to function, but environmental monitoring is lost. 1. Retry at 1-minute intervals a maximum of 5 times. 2. If the test continues to fail “reset pr-maint restart” to restart RM firmware. 3. If test continues to fail, replace the Processor circuit pack.
	PASS	The RM firmware was reset, and it passed initialization correctly.

## MTP Sanity Handshake Test (#106)

This test is a nondestructive test.

The MTP Sanity Handshake Test is simply a query from a maintenance process to the RM Firmware. The TDC (Terminal Control Driver) must reply that RM Firmware is maintaining period sanity scans for this test to pass.

Table 5-413. TEST #106 MTP Sanity Handshake Test

Error Code	Test Result	Description/ Recommendation
100	ABORT	The test did not complete within the allowable time period. 1. Retry the command.
1000	ABORT	System software resources required for this test are not available. 1. Retry at 1-minute intervals a maximum of 5 times.
2000	ABORT	The response to the test request was not received within the allowable time period.
2033	ABORT	Internal system error. 1. Repeat the command at 1-minute intervals a maximum of 5 times.
	FAIL	The RM Firmware did not respond to the Sanity Handshake Query. 1. Re-enter command with the "long" option. 2. If the test continues to fail, replace the Processor circuit pack.
	PASS	The RM Firmware is maintaining Sanity with the TCD and the TCD is reporting that sanity is passing.

**MTP External Modem Present Test (#230)**

This test is a nondestructive

This test will test for the presence of an external modem, and runs only if the channel is idle. The test passes if the modem can detect dial tone and DEFINITY can Communicate with the modem.

**Table 5-414. TEST #230 External Modem Present Test**

Error Code	Test Result	Description/ Recommendation
100	ABORT	The test did not complete within the allowable time period. 1. Retry the command.
1018	ABORT	The test has been disabled via administration. 1. To enable the test, issue the <b>change system-parameters maintenance</b> command, and set the <code>Test Remote Access Port</code> field to <code>y</code> . 2. Rerun the test.
1131	ABORT	INADS port is busy because the system is reporting alarms to INADS, or because INADS is dialed into the system. 1. If INADS is communicating with the switch the INADS trunk is working. There is no need to run this test. 2. Or if required. Wait about ten minutes (until the INADS session is terminated) and then re-enter the command.
1000 2033	ABORT	System software resources required for this test are not available. Internal system error 1. Retry at 1-minute intervals a maximum of 5 times.
1050	ABORT	System could not determine if the testing of the INADS port is administered. 1. Enter the <b>change system-parameters maintenance</b> command, and verify the entry for the <code>Test Remote Access Port</code> field. 2. Retry at 1-minute intervals a maximum of 5 times.
2000	ABORT	MTP did not respond to the test request. 1. Repeat test at 1-minute intervals a maximum of 5 times. 2. Check modem connections, make sure the modem and the correct driver software are installed (within NT).
2500	ABORT	Internal System software Error 1. Retry at 1-minute intervals a maximum of 5 times.

*Continued on next page*

Table 5-414. TEST #230 External Modem Present Test — *Continued*

Error Code	Test Result	Description/ Recommendation
	FAIL	<p>Modem Test failure. The system is not able to reliably contact INADS with alarm data. However, the system can continue to provide call services.</p> <p> <b>NOTE:</b> The fault may be on the Processor circuit pack or the modem may not be installed correctly.</p> <ol style="list-style-type: none"><li>1. Check modem connections</li><li>2. Check the modem documentation and verify that the modem will pass self test.</li><li>3. Check that correct software driver is installed in NT OS</li><li>4. If the test still fails replace the TN795 circuit pack</li></ol>
	PASS	<p>The modem detected dial tone and was able to communicate with DEFINITY.</p> <ol style="list-style-type: none"><li>1. If the system cannot call INADS, or if INADS cannot contact the system, check with the local Central Office for problems with the INADS trunk, and verify that the INADS number is correct. Check the external modems and verify that it is a approved device. An approved modem with factory default settings is expected to work if correct software driver is installed in the NT OS</li></ol>

## PROCR (Processor Circuit Pack)

---

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run	Full Name of MO
PROCR	MAJOR	test processor a/b sh r/c	Processor Circuit Pack

**NOTE:**

For systems with a TN790 RISC Processor circuit pack see maintenance object "PROCR (TN790 RISC Processor Circuit Pack)".

**NOTE:**

Alarms on the MEM-BD [386 systems only], PROCR and PR-MAINT maintenance objects (MOs) are indicated by the red LED on the Processor circuit pack.

The TN786B has an 80386 processor that uses on-board flash ROM and DRAM memory. The TN786B Processor circuit pack is comprised of the 80386 Processor (PROCR), the Maintenance Processor (PR-MAINT) and Memory (MEM-BD).

The TN786B Processor circuit pack is responsible for the execution of the DEFINITY software. This includes all of the call processing, maintenance, and administration functions. The Processor circuit pack is the most critical component to proper operation of the system.

The PR-MAINT is responsible for monitoring the sanity of the Processor circuit pack as well as the environmental conditions. The PR-MAINT provides the serial interfaces for the administration terminal and for the Call Detail Recording (CDR) ports. The PR-MAINT also provides the communications interface to INADS for alarm reporting and remote maintenance capability.

In High and Critical Reliability systems, the PR-MAINT is part of the communications path between the Active Processor Element and the Standby Processor Element.

## Error Log Entries and Test to Clear Values

Table 5-415. 80286/386 Processor Circuit Pack Error Log Entries

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value <sup>1</sup>
0 <sup>2</sup>	0	Any	Any	Any	test processor a/b r 1
1 (a)	0	Software Initiated Interrupt Test (#77)	MAJOR	ON	test processor a/b r 3
769 (b)	0	ROM Checksum Test (#80)	MAJOR	ON	test processor a/b r 5
1025 (c)	0	Processor Non-maskable Interrupt Test (#82)	MAJOR	ON	test processor a/b r 2
1281 (d)	0	Processor Sanity Timer Test (#83)	MAJOR	ON	test processor a/b l r 2

- Software does not accept the repeat option on the TN773 circuit pack [G3iV1.1-286]. The repeat option is valid only on the TN786B circuit pack. You must manually repeat the command with the long option the designated number of times from the administration terminal and from a remote SAT because the Sanity Timer Test (#83) logs you off. In G3iV1.1-286, if the **test processor long** System Technician command is executed six times back-to-back, the system goes into SPE-DOWN mode.
- Run the Short Test Sequence first. If all tests pass, run the Long Test Sequence. Refer to the appropriate test description and follow the recommended procedures.

### Notes:

- The Software Initiated Interrupt Test (#77) failed. Refer to the FAIL condition of this test for further action.
- The ROM Checksum Test (#80) failed. Refer to the FAIL condition of this test for further action.
- The Processor Non-maskable Interrupt Test (#82) failed. Refer to the FAIL condition of this test for further action.
- The Processor Sanity Timer Test (#83) failed. Refer to the FAIL condition of this test for further action.

## System Technician-Demanded Tests: Descriptions and Error Codes

---

Always investigate tests in the order presented in the table below when you are inspecting errors in the system. By clearing error codes associated with the *Processor Non-maskable Interrupt Test*, for example, you may also clear errors generated from other tests in the testing sequence.

Order of Investigation	Short Test Sequence	Long Test Sequence	D/ND <sup>1</sup>
Processor Non-maskable Interrupt Test (#82)	X	X	ND
Processor ROM Checksum Test (#80)	X	X	ND
Processor Software Initiated Interrupt Test (#77)	X	X	ND
Processor Sanity Timer Test (#83)		X	D
MTP Outpulse Relay Test (#102) (a)	X	X	ND
MTP Analog Loop Around Test (#103) (a)	X	X	ND
MTP Sanity Handshake Test (#106) (a)	X	X	ND
MTPSAT Loop Around Test (#228) (a)	X	X	ND
MTP Aux Loop Around Test (#229) (a)	X	X	ND
MTP Reset Test (#101) (a)		X	D
MTP Dual Port Ram Test (#104) (a)		X	D
Read All Memory Test (#85)(b)		X	ND
Memory Error Detection Test (#87)(b)	X	X	ND
Text Checksum Test (#86)(b)		X	ND
Memory Functional Test (#332) (c)(b)		X	D
Memory Board Check Test (#631) (b)	X	X	ND

---

1. D = Destructive; ND = Nondestructive

### Notes:

- a. Refer to [“PR-MAINT \(Maintenance Processor\)” on page 5-1000](#) for a description of these tests.
  - b. Refer to [“MEMORY” on page 5-794](#) [386 systems only] for a description of these tests.
-

## Processor Software Initiated Interrupt Test (#77)

This test is a nondestructive test. The test verifies if the 80286/386 Processor can exercise the three types of software-initiated interrupts:

- Divide by zero
- Single step
- One byte interrupt instruction.

Table 5-416. TEST #77 Processor Software Initiated Interrupt Test

Error Code	Test Result	Description/ Recommendation
1029 2014 2015 2016 2017 2018 2020 2022 2024 2025 2051	ABORT	Refer to STBY-SPE Maintenance documentation for a description of these error codes.
	FAIL	<p>The processor did not detect the software interrupt condition. As a result, the processor executed the incorrect interrupt vector. The system may or may not continue to operate correctly.</p> <ol style="list-style-type: none"> <li>1. Repeat the command at 1-minute intervals a maximum of 5 times.</li> <li>2. If the test continues to fail, the Processor circuit pack should be replaced.</li> </ol> <p><b> WARNING:</b>  <i>If the TN786B circuit pack [386 systems only] must be replaced, and if there is a blank in the Expansion Memory circuit pack slot (that is, in the slot immediately to the right of the TN786B circuit pack), remove the blank before removing the circuit pack. Otherwise, the circuit pack and/or the two connectors that are used to connect the Expansion Memory circuit pack (if available) might become damaged.</i></p>
	PASS	The processor detected the software interrupt condition, and it executed the correct interrupt vector. The system continues to operate correctly.

## Processor ROM Checksum Test (#80)

This test is a nondestructive test. The test computes the checksum of the processor's bootstrap ROM, and it compares this checksum to a predetermined value stored within the ROM. A failure of this test indicates corruption of the ROM.

Table 5-417. TEST #80 Processor ROM Checksum Test

Error Code	Test Result	Description/ Recommendation
1029 2014 2015 2016 2017 2018 2020 2022 2024 2025 2051	ABORT	Refer to STBY-SPE Maintenance documentation for a description of these error codes.
	FAIL	<p>The computed checksum did not match the ROM checksum. The system may or may not continue to operate correctly. The system may fail later when some action requires access to the corrupted area of the bootstrap ROM.</p> <ol style="list-style-type: none"> <li data-bbox="272 924 803 951">1. The Processor circuit pack should be replaced.</li> </ol> <p><b>⚠ WARNING:</b></p> <p><i>If the TN786B circuit pack [386 systems only] must be replaced, and if there is a blank in the Expansion Memory circuit pack slot (that is, in the slot immediately to the right of the TN786B circuit pack), remove the blank before removing the circuit pack. Otherwise, the circuit pack and/or the two connectors that are used to connect the Expansion Memory circuit pack (if available) might become damaged.</i></p>
	PASS	The computed checksum matched the ROM checksum. The system continues to operate normally.

## Processor Non-maskable Interrupt Test (#82)

This test is a nondestructive test. The test is used to verify that the 80286/386 Processor can detect and respond to non-maskable interrupts. For example, the processor intentionally causes a BUS TIMEOUT EXCEPTION (BTE) and then verifies if it vectors to the correct interrupt routine. This is basically a test of the internal operation of the 80286/386 CPU chip.

Table 5-418. TEST #82 Processor Non-maskable Interrupt Test

Error Code	Test Result	Description/ Recommendation
1029 2014 2015 2016 2017 2018 2020 2022 2024 2025 2051	ABORT	Refer to STBY-SPE Maintenance documentation for a description of these error codes.
	FAIL	<p>The interrupt was not detected or acted upon.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> <li>2. If the test continues to fail, the Processor circuit pack should be replaced.</li> </ol> <p><b>⚠ WARNING:</b></p> <p><i>If the TN786B circuit pack [386 systems only] must be replaced, and if there is a blank in the Expansion Memory circuit pack slot (that is, in the slot immediately to the right of the TN786B circuit pack), remove the blank before removing the circuit pack. Otherwise, the circuit pack and/or the two connectors that are used to connect the Expansion Memory circuit pack (if available) might become damaged.</i></p> <ol style="list-style-type: none"> <li>3. If replacement of the Processor circuit pack still results in test failure, the following circuit packs should be replaced, one at a time in the order provided: TN770 Memory [G3iV1.1-286 only] Expansion Memory [G3iV2-386 only] TN765 Processor Interface, TN777B Network Control, TN778 Packet Control, and TN772 Duplication Interface circuit packs. The test should then be repeated.</li> <li>4. If the test still fails after you replace all the circuit packs discussed in the previous step, the problem must be in the control carrier, and the carrier should be replaced.</li> </ol>
	PASS	The interrupt was correctly detected. The 80286/386 CPU chip is functioning correctly.

**Processor Sanity Timer Test (#83)****This test is destructive.**

This test causes service to be disrupted for about seven seconds on the TN773 and for about one second on the TN786B. During this time, the system does not respond to any user action.

This test checks to see if the 80286/386 processor watch-dog sanity timer is functioning correctly. The processor intentionally allows the sanity timer to time out. If the processor detects itself being reset, the test passes, and the processor continues to execute normally. If the processor does not detect a reset, the test has failed. If this test continues to fail, the processor pack should be replaced as soon as possible. The sanity timer is not critical to system operation, but it is needed for processor recovery if the processor stops functioning.

**Table 5-419. TEST #83 Processor Sanity Timer Test**

Error Code	Test Result	Description/ Recommendation
1000	ABORT	System software resources required for this test are not available. 1. Retry the command at 1-minute intervals a maximum of 5 times.
1029 2014 2015 2016 2017 2018 2020 2022 2024 2025 2051	ABORT	Refer to STBY-SPE Maintenance documentation for a description of these error codes.
	FAIL	The sanity timer did not time out as expected. The system continues to function normally. If the processor gets into an infinite loop, the reset CANNOT be detected, and the system DOES NOT reboot itself to clear the problem. 1. Retry the command at 1-minute intervals a maximum of 5 times. 2. If test continues to fail, the Processor circuit pack should be replaced as soon as possible.
	PASS	The sanity timer went off as expected. The system continues to function normally. If the processor gets into an infinite loop, the reset IS detected, and the system reboots itself to clear the problem.

## PR-SSP (Processor Board - Scalable Speech Processor)

---

### Error Log Entries and Test to Clear Values

---

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run	Full Name of MO
PR-SSP	MAJOR	test board	Processor Board Scalable Speech Processor

The SSP (Scalable Speech Processor) is located on a “mezzanine” card (CWY1) on the TN795. The CWY1 is connected to the Pentium processor on the TN795 using a PMC connector. This card provides the signal processing hardware to perform AUDIX and integrated announcement functions. Voice messages and announcements are stored on the TN795 hard disk. No additional AUDIX hardware is required.

The MO name for the SSP card is PR-SSP. The MO name for the AUDIX ports on the SSP card is PR-ADX.

DEFINITY maintenance software supports the SSP by using a virtual board concept to allow for board insertion and maintenance testing. By default, the application dependent on the CWY1 card is located in virtual slot 1A12 for AUDIX functions and in virtual slot 1A13 for announcement functions.

#### **WARNING:**

*Slots 1A12 and 1A13 both use the CWY1 board connection. Running the test board long on Slot 1A12 will disrupt user AUDIX and announcement services on both A12 and 1A13 slots.*

Maintenance testing of the PR-SSP MO is handled by the SSP firmware which is managed by the CornerStone application software. DEFINITY maintenance software requests that the CornerStone application software run board related diagnostic and initialization tests. CornerStone passes the test result back to DEFINITY. Communication to/from CornerStone is via the Virtual Fabric Manager (VFM). DEFINITY uses the information to raise or retire alarms.

**5 Maintenance Objects for DEFINITY ONE**  
*PR-SSP (Processor Board - Scalable Speech Processor)*

5-1016

The CWY1 is not a field replaceable unit. If it fails, the TN795 processor board must be replaced.

The technician can fix the condition by logging in as init and issuing the following command: "reset translation-id". After this command executes, the "save translations" command is used and the system is rebooted to clear the error and reset the alarm condition.

**⚠ WARNING:**

*When the disk is replaced on the TN795, a new license file must be downloaded to the system before the system will become operational. Refer to "Obtaining a License File" in Chapter 3 of DEFINITY ONE™ Communications System Release 2.0 Installation and Upgrades (555-233-109). Retry the command and if the test fails, replace the circuit pack.*

**⇒ NOTE:**

Whenever a major alarm is raised on the board, all the ports will be put in the out-of-service state

**Error Log Entries and Test to Clear Values****Table 5-420. PR-SSP Error Log Entries**

<b>Error Type</b>	<b>Aux Data</b>	<b>Associated Test</b>	<b>Alarm Level</b>	<b>On/Off Board</b>	<b>Test to Clear Value</b>
0 <sup>1</sup>	0	Any	Any	Any	test board PCSS
1(a)	Any	SSP Board Diagnostic Test Failure (#1350)	MAJOR	ON	test board PCSS
257(b)	Any	SSP Board Diagnostic Test Failure (#1350)	MAJOR	ON	test board PCSS
513(c)		TSM Test (#1358)	MAJOR	OFF	test board PCSS
769(d)	Any	Control Channel Test (#52)	MAJOR	OFF	test board PCSS

*Continued on next page*

1. Run the Short Test sequence first. If all tests pass, run the Long Test Sequence. Refer to the appropriate test description and follow the recommended procedures.

Notes:

- a. Error Type: 1 - A hardware component on the board has failed to pass the on-board diagnostic test. This error occurs when any of the following conditions exist:
    - An in-line error of "SSP board diagnostic" was received.
    - Demand test of SSP diagnostic-initialization test fails, and the error code indicates a SSP diagnostic problem.
    - After the reset board command is entered, DEFINITY maintenance requests that CornerStone run the SSP diagnostic/initialization test. If the test result indicates a board diagnostic/initialization failure, this counter is increased by 1. This counter will be decreased by 1 when the test passes and the alarm will be retired.
  - b. Error Type: 257 - The board has failed to pass the initialization part of Test #1350. This error occurs when any of the following conditions exist:
    - An in-line error of "SSP board diagnostic/Initialization failure" is detected.
    - Demand test of SSP diagnostic-initialization test fails, and the error code indicates a SSP board Initialization problem.
    - After the reset board command is entered, DEFINITY maintenance requests that CornerStone run SSP diagnostic/initialization test. If the test result indicates a board diagnostic/initialization failure, this counter is increased by 1. This counter will be decreased by 1 when the test passes and the alarm will be retired.
  - c. Error Type: 513 - This error indicates a loss of communication between the VFM and the TSM. This error occurs when any of the following conditions exist:
    - An in-line error of "VFM and TSM loses communication" is detected.
    - Demand test of TSM test fails.
    - After the reset board command is executed, DEFINITY maintenance requests VFM to run the TSM test. If the test fails, this counter is increased by 1. This counter will be decreased by 1 to resolve the alarm when the test passes.
  - d. Error Type:769 - This error indicates that the Virtual Fabric Manager did not respond to a query for the circuit pack code and vintage of the virtual SSP board.
-

## System Technician-Demanded Tests: Descriptions and Error Codes

Always investigate tests in the order presented in the table below. By clearing error codes associated with the *Voice and Control Channel Local Loop Around Test* for example, you may also clear errors generated from other tests in the testing sequence.

Order of Investigation	Short Test Sequence	Long Test Sequence	D/ND <sup>1</sup>
Control Channel Looparound Test (#52)		X	D
TSM Test (#1358)	+	X	ND

1. D = Destructive; ND = Nondestructive

### Control Channel Looparound Test (#52)

This test is nondestructive

This test queries the Virtual Fabric Manager for the circuit pack code and vintage of the Virtual AUDIX Board and verifies its records.)

Table 5-421. Test #52 Control Channel Looparound Test

Error Code	Test Result	Description/Recommendation
None 2100	ABORT	System resources for this test are not available. 1. Retry the command at 1-minute intervals a maximum of 5 times.
	FAIL	The test failed because the Virtual Manager software failed to return the circuit pack code or vintage. 1. Retry the command for a maximum of 5 times. 2. If the error reoccurs, there is a software problem. Follow normal escalation procedures.
	PASS	Communication with the Virtual Fabric Manager software is successful.
	EXTRA BD	Follow normal escalation procedures
Any	NO Board	Follow normal escalation procedures

## SSP-CMC Diagnostic/Initialization Test (#1350)

This test is destructive



### NOTE:

Before running this test, busy out the SSP-CMC board. Otherwise, this test will abort. However, if this test is triggered by an inline error, maintenance software will busy out the board before running this test.



### WARNING:

*Slots 1A12 and 1A13 both use the CWY1 board connection. Running the test board long on Slot 1A12 will disrupt user AUDIX and announcement services on both A12 and 1A13 slots.*

This test runs the SSP-CMC diagnostic test and initialization tests.

This is a destructive test. This test is run in response to in-line errors, periodic maintenance, craft demand (test board & reset board command, etc.) and initialization testing for the SSP-CMC.

DEFINITY Maintenance sends a Run Diagnostic Request via the VFM to CornerStone software to run the SSP-CMC diagnostic test.

If CornerStone software detects an error during the diagnostic test, it will send an SSP-CMC diagnostic error message back to DEFINITY Maintenance software via the VFM (It performs no SSP-CMC initialization).

If the diagnostic test passes, CornerStone will automatically try to initialize the SSP-CMC. If CornerStone detects an error during initialization of the SSP-CMC, it will send an SSP-CMC initialization error message to DEFINITY Maintenance via the VFM. Otherwise, it will send a test pass message back to the DEFINITY Maintenance.

After testing the SSP-CMC board must be returned to service (When SSP-CMC board is busied out, all the ports on the board will be out-of-service). The only way to return the SSP-CMC board /ports back to the in-service state is to enter the "release board" command after the board test passes.

Table 5-422. TEST #1350 SSP Board Test

Error Code	Test Result	Description/Recommendation
1001	ABORT	System resources required to run this test are not available. Try (a)
1015	ABORT	The board is not busied out, the board must be busied out before running this test.
2000	ABORT	Response to the test request was not received within the allowable time period. Try (a).
1	FAIL	<p>A hardware component on the board has failed</p> <p><b>⚠ CAUTION:</b> <i>Resetting/replacing the TN795 processor pack will take the switch out of service. Follow the procedures for replacing the TN795 processor circuit pack listed in this document.</i></p> <p><b>⚠ WARNING:</b> <i>When the disk is replaced on the TN795, a new license file must be downloaded to the system before the system will become operational. Refer to "Obtaining a License File" in Chapter 3 of DEFINITY ONE™ Communications System Release 2.0 Installation and Upgrades (555-233-109). Retry the command and if the test fails, replace the circuit pack.</i></p> <ol style="list-style-type: none"> <li>1. Reset the board using the reset board 1a 12 command. Try (a).</li> <li>2. If the test still fails re-seat the TN795 processor circuit pack and retry step 1.</li> <li>3. If the test still fails replace the board and re-run all tests.</li> </ol>
2	FAIL	<p>The circuit pack has failed initialization</p> <ol style="list-style-type: none"> <li>1. (See recommendations for Error Code 1 Fail).</li> </ol>
	PASS	<ol style="list-style-type: none"> <li>2. All tests pass</li> </ol>

Note:

- a. Retry the command at 1-minute intervals a maximum of 5 times. Escalate if the problem persists.

**TSM Test (#1358)****This test is destructive.**

This test verifies that the Time Slot Manager (TSM) can communicate with the Virtual Fabric Manager (VFM). This verification is done by checking for time-outs and errors in the commutation's between the TSM and the VFM).

In this test, DEFINITY Maintenance sends a down link message to check the sanity of TSM. The VFM then checks to see whether the communications link between the VFM and TSM has been established.

If the communication link is established between VFM and the TSM firmware, the VFM informs DEFINITY Maintenance that the test passes.

If the communications link is not up, VFM restarts the TSM through the module manager and waits a time for it to come up. When VFM resets the TSM, all the existing phone calls will be torn down. If the TSM comes back then VFM sends a "pass" test result to DEFINITY Maintenance. DEFINITY Maintenance will restore all the administered port states back to whatever it was before the test, except those in-service ports, which will be put into idle state. If the TSM doesn't come back, then VFM sends a "failure" test result to DEFINITY Maintenance. DEFINITY Maintenance will put all the administered ports into out-of-service state

**Table 5-423. TEST #1358TSM Test**

Error Code	Test Result	Description/Recommendation
	ABORT	Internal System Error. Try (a)
1000	ABORT	System resources required to run this test are not available. The port may be in use. Use the <b>display port PCSSpp</b> command to determine the voice port extension of the port. Use the <b>status station</b> command to determine the service state of the port. If the port is in use, it is unavailable for certain tests. Refer to "Status" commands, in "Maintenance Commands and Trouble-Clearing Aids" for explanations of all possible states.
1001	ABORT	System resources required to run this test are not available; try (a).
2000	ABORT	Response to the test request was not received within the allowable time period.

*Continued on next page*

Table 5-423. TEST #1358TSM Test — Continued

Error Code	Test Result	Description/Recommendation
None	FAIL	<p>The TSM test failed and all ports are out of service.</p> <ol style="list-style-type: none"> <li>1. Test all associated ports using the <b>test port</b> command.</li> <li>2. Resolve any problems detected.</li> <li>3. Execute the <b>test port</b> command. If the test still fails wait 1 minute and re-test.</li> <li>4. If the board still fails run the status link command.</li> <li>5. Resolve any problems detected and re-test.</li> </ol> <p> <b>CAUTION:</b> <i>Resetting/replacing the TN795 processor circuit pack will disrupt service. See the TN795 processor re-placement procedures in this document before proceeding with step 6.</i></p> <p> <b>CAUTION:</b> <i>Replacing the TN 795 processor board can display the translation error message, "TRANS_ID INTERVAL EXPIRATION:xx days when logging into the SAT window. If this occurs, immediately call a Lucent Technical Services Consultant (TSC) to remove the error message. While the switch is in the error condition, the save translations command is not available.</i></p> <p> <b>WARNING:</b> <i>When the disk is replaced on the TN795, a new license file must be downloaded to the system before the system will become operational. Refer to "Obtaining a License File" in Chapter 3 of DEFINITY ONE™ Communications System Release 2.0 Installation and Upgrades (555-233-109). Retry the command and if the test fails, replace the circuit pack.</i></p> <ol style="list-style-type: none"> <li>6. Reset the board using the reset board command.</li> <li>7. If the board still fails replace the board and re-run all tests. See the above CAUTION.</li> </ol>
	PASS	<p>The TSM test has passed. To be sure that this is not an intermittent problem, repeat this test.</p>

Notes:

- a. Retry the command at 1-minute intervals a maximum of 5 times. Escalate if the problem persists.

## PR-TN-BD (TN795 Processor/Tone-Clock)

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run <sup>1</sup>	Full Name of MO
PR-TN-BD	MAJOR	test tone-clock PC	Processor/Tone-Clock
PR-TN-BD	MINOR	test tone-clock PC	Processor/Tone-Clock
PR-TN-BD	WARNING	release tone-clock PC	Processor/Tone-Clock

1. P is the port network number (1). C is the carrier designation (A, B, or C).

The tone-clock functions are located on the TN795 Processor/Tone-Clock circuit pack, and are implemented as a task-based module on the MPC860 processor chip. The tone/clock function shares the processor with many other firmware modules.

When resolving errors/alarms on the TN795 Processor/Tone-Clock circuit pack, the following should be used also:

- TONE-PT (Tone Generator) Maintenance documentation.
- TDM-CLK (TDM Bus Clock) Maintenance documentation.
- SYNC (Synchronization) Maintenance documentation.

When replacing the Tone Clock (as part of the TN795 Processor circuit pack), always follow procedures for replacing the TN795 Processor circuit pack.

### **WARNING:**

*When the disk is replaced on the TN795, a new license file must be downloaded to the system before the system will become operational. Refer to "Obtaining a License File" in Chapter 3 of DEFINITY ONE™ Communications System Release 2.0 Installation and Upgrades (555-233-109). Retry the command and if the test fails, replace the circuit pack.*

### **CAUTION:**

*Replacing the TN 795 processor board can display the translation error message, "TRANS\_ID INTERVAL EXPIRATION:xx days when logging into the SAT window. If this occurs, immediately call a Lucent Technical Services Consultant (TSC) to remove the error message. While the switch is in the error condition, the save translations command is not available.*

## Italian Tone Settings

---

Tone	Default	Old ISPT Value
Dial	Continuous	Cadenced
Confirmation	Cadenced	Continuous

The TN795 processor tone-clock circuit pack supports the same International changes as the TN780, and in addition allows the customization of up to 24 system tones in order to meet specific country needs. These changes are made via the **change system-parameters country-options** form.

## Tone-Clock Yellow LED Patterns

LED ACTION	BOARD STATE	EXPLANATION
flashing yellow 2.7 sec on 300 ms off	active	master, using off-board synchronization source
winking yellow 300 ms off 2.7 sec on	active	master, using its local reference source
steady yellow on	active	board has been reset and is providing clocks, but has not been told which synchronization source to use
double blink yellow 300 ms on, 300 ms off, 300 ms on, 2.1 s off,	active	TN795 has lost all external references and is in holdover mode

## Tone-Clock Replacement

---

When replacing a Tone Clock (as part of the TN795 Processor circuit pack), follow the procedures for replacing the TN795 Processor circuit pack. (See ["Replace the TN795 circuit pack" on page 2-8.](#)) The carrier must be powered down before the TN795 is removed and then the carrier must be powered back up after the circuit pack is inserted.

### WARNING:

*When the disk is replaced on the TN795, a new license file must be downloaded to the system before the system will become operational. Refer to "Obtaining a License File" in Chapter 3 of DEFINITY ONE™ Communications System Release 2.0 Installation and Upgrades (555-233-109). Retry the command and if the test fails, replace the circuit pack.*

### CAUTION:

*Replacing the TN 795 processor board can display the translation error message, "TRANS\_ID INTERVAL EXPIRATION:xx days when logging into the SAT window. If this occurs, immediately call a Lucent Technical Services Consultant (TSC) to remove the error message. While the switch is in the error condition, the save translations command is not available.*

## Hardware Error Log Entries and Test to Clear Values

---

Table 5-424. Tone-Clock Circuit Pack Error Log Entries

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
0 <sup>1</sup>	0	Any	Any	Any	test tone-clock PC sh
1(a)	0	Circuit pack removed or SAKI Sanity Test (#53)	MINOR	ON	
257	65535	Control Channel Test (#52)	MINOR	ON	test tone-clock PC r 20
257(b)	Any	None			
1538(c)	Any	None	MINOR	ON	
2049(d)	0	Clock Health Inquiry Test (#46)	MAJOR	ON	
2305(d)	0	Clock Health Inquiry Test (#46)	MAJOR	ON	

Continued on next page

Table 5-424. Tone-Clock Circuit Pack Error Log Entries — Continued

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
2561(e)	Any	None	MAJOR	ON	
3840(f)	Any	None			
3848(g)	0	Clock Health Inquiry Test (#46)			
3872(h)	0	None			
3999(i)	Any	None			

1. Run the Short Test Sequence first. If all tests pass, run the Long Test Sequence. Refer to the appropriate test description and follow the recommended procedures.

**Notes:**

- a. Error Type 1—This error indicates the circuit pack totally stopped functioning or it was physically removed from the system.
- b. Error Type 257—This error indicates transient communication problems with this circuit pack. This error is not service-affecting and no action is required.
- c. Error Type 1538— This error type may require a reset of the tone-clock component in the TN795; therefore, see caution before proceeding. The circuit pack was taken out of service because of an excessive rate of uplink messages. Use **test tone-clock 1a long** to reset the circuit pack and put it back into service. If the command is not successful, repeat the command 5 more times in 5 minutes increment. If the command failed all 5 times, perform the command reset tone-clock 1a. If the error occurs again within 15 minutes, follow normal escalation procedures.

**CAUTION:**

*Resetting the tone-clock module will disrupt service, e.g. no dial tone.*

- d. Error Type 2049 or 2305—These errors indicate the loss of clock signals from the Tone-Clock.
1. Examine the Hardware Error Log for errors reported against circuit packs especially the TDM-CLK. Follow the repair or replacement procedures indicated for any such errors found.
  2. This step may require a reset of the tone-clock; please see caution above before proceeding. If the error is not corrected by resolving errors found in step 1, perform the command reset tone-clock 1a. If the error occurs again within 15 minutes, follow normal escalation procedures.
  3. If error 2305 persists, all clock signals were lost.
  4. If the error has not been corrected at this point, there is a problem with the TDM Bus. This may include TDM Bus intercarrier cables, Bus terminators, bent pins on the backplane, and errors on any circuit pack. Refer to [“TDM-BUS \(TDM Bus\)” on page 5-1116](#).
- e. Error Type 2561—This error indicates that a Tone-Clock circuit pack, with a different circuit pack code than required for this system, has been inserted in the port slot as shown in the Hardware Error Log. To resolve this error, refer to the “How to Replace the Processor Circuit Pack” for an appropriate circuit pack code and replace the Tone-Clock circuit pack with a TN795 Processor/Tone-Clock circuit pack according to the procedures indicated for this system. The meaning of the aux data value is as follows:
- 1003     Either a TN741 or TN714 Tone-Clock circuit pack (instead of a TN795) is in the system.
- f. Error Type 3840—This error is not service-affecting and can be ignored. It indicates that the circuit pack has received a bad control message from the switch.
- g. Error Type 3848—This error indicates that the Tone/Clock module had a loss of clock. If error 2305 is also logged, see note (d).
- h. Error Type 3872—These errors indicate this Tone/Clock module had a loss of Data Clocks. This error will impact users on stations connected to Digital circuit packs. These users could be without service. If error 2049 is also logged, see note (d).
- i. Error Type 3999— indicates that the Tone/Clock module sent a large number of control channel messages to the switch within a short period of time. If error type 1538 is also present, the Tone/Clock module was taken out-of-service due to hyperactivity. If error type 1538 is not present, the Tone/Clock module has not been taken out-of-service, but it has generated 50% of the messages necessary to be considered hyperactive. This may be completely normal during heavy traffic periods. However, if this error type is logged when the circuit pack is being lightly used, it may indicate a problem with the circuit pack or the equipment attached to it.
-

## System Technician-Demanded Tests: Descriptions and Error Codes

---

Always investigate tests in the order presented in the following tables when inspecting errors in the system. By clearing error codes associated with the *SAKI Sanity Test*, for example, you may also clear errors generated from other tests in the testing sequence.

Table 5-425. System Technician-Demanded Tests: PR-TN-BD

Order of Investigation	Short Test Sequence	Long Test Sequence	D/ND <sup>1</sup>
SAKI Sanity Test (#53)		X	D
Clock Health Inquiry Test (#46)	X	X	ND
Control Channel Loop Around Test (#52)	X	X	ND
Tone Generator Crosstalk Test (#90) (b)		X	
Tone Generator Transmission Test (#40) (b)	X	X	
Tone Generator Audit/Update (#41) (b)	X	X	
TDM Bus Clock Circuit Status Inquiry Test (#148) (c)	X	X	
TDM Bus Clock Slip Inquiry (#149) (c)	X	X	
TDM Bus Clock PPM Inquiry Test (#150) (c)	X	X	
TDM Bus Clock Parameter Update Test (#151) (c)	X	X	
Board Type Check Test (#574) (c)	X	X	

---

1. D = Destructive, ND = Non-destructive

### Notes:

- a. Refer to [“XXX-BD \(Common Port Circuit Pack\)” on page 5-1343](#) for descriptions of these tests.
  - b. Refer to [“TONE-PT \(Tone Generator\)” on page 5-1204](#) for descriptions of these tests.
  - c. Refer to [“TDM-CLK \(TDM Bus Clock\)” on page 5-1132](#) for descriptions of these tests.
-

## Clock Health Inquiry Test (#46)

This test is nondestructive

This inquiry reads special data stored in memory to determine if the Tone-Clock had a loss of any of three clock types:

- SYSCLK
- SYSFM
- SYSDCLK

If this data indicates the Tone-Clock has had a loss of any of these clocks, the inquiry reports FAIL. In addition, if TDM-CLK error 1 is at threshold, this test will FAIL. TDM-CLK error 1 indicates a suspect clock is at the edge of its specified frequency. If the Tone-Clock did not have either a loss of clock or TDM-CLK error 1 at threshold, the inquiry reports PASS.

This is not really a test, in the sense that it simply reports status held by the system, and does not generate new information or raise alarms. If this test fails with no error code, there is at least one Major alarm against the Tone-Clock. If this test fails with an error code of 1, there is at least one Minor off-board alarm against TDM-CLK.

Table 5-426. TEST #46 Clock Health Inquiry Test

Error Code	Test Result	Description/ Recommendation
	ABORT	Internal System Error. 1. Retry the command at 1-minute intervals for a maximum of 5 times.
none	FAIL	The TN795 processor/Tone-Clock circuit pack had an apparent loss of clock. One or more of error types 2049, 2305, 3848, and 3872 will appear in the error log. Correct the problem according to the appropriate error log entries.

*Continued on next page*

Table 5-426. TEST #46 Clock Health Inquiry Test — *Continued*

Error Code	Test Result	Description/ Recommendation
1	FAIL	<p>The Tone-Clock is suspect of having a clock at the edge of its specified frequency.</p> <p><b>⚠ CAUTION:</b>  <i>Replacing/Reseating the TN795 Processor/Tone-Clock circuit pack will disrupt service. Please proceed this step with caution. Refer to <a href="#">“Replace the TN795 circuit pack” on page 2-8</a> and <a href="#">“Tone-Clock Replacement” on page 5-1025</a> for more information on replacing the TN795 Processor /Tone-Clock circuit pack.</i></p> <p><b>⚠ WARNING:</b>  <i>When the disk is replaced on the TN795, a new license file must be downloaded to the system before the system will become operational. Refer to “Obtaining a License File” in Chapter 3 of DEFINITY ONE™ Communications System Release 2.0 Installation and Upgrades (555-233-109).Retry the command and if the test fails, replace the circuit pack.</i></p> <p><b>⚠ CAUTION:</b>  <i>Replacing the TN 795 processor board can display the translation error message, “TRANS_ID INTERVAL EXPIRATION:xx days when logging into the SAT window. If this occurs, immediately call a Lucent Technical Services Consultant (TSC) to remove the error message. While the switch is in the error condition, the save translations command is not available.</i></p> <ol style="list-style-type: none"> <li>1. Read Caution above. Reseat the board.</li> <li>2. Run this test 5 more times in 5 minute increments.</li> <li>3. If the problem persists, replace the TN795 Processor/Tone-Clock circuit pack.</li> </ol>
	PASS	<p>This TN795 Processor/Tone-Clock circuit pack has not reported a loss of clock.</p>

## Control Channel Looparound Test (#52)

This test is nondestructive

This test queries the TN795 Processor/Tone-Clock circuit pack for its circuit pack code and vintage and verifies its records.

Table 5-427. TEST #52 Control Channel Looparound Test

Error Code	Test Result	Description/ Recommendation
None 2100	ABORT	System resources required for this test are not available. 1. Retry the command at 1-minute intervals a maximum of 5 times.
	FAIL	<p>The test failed because the circuit pack failed to return the circuit pack code or vintage.</p> <p>1. Retry the command for a maximum of 5 times.</p> <p>2. Note this step may require a reseal of the board; see caution below. If the problem continues, reseal the circuit pack.</p> <p><b>⚠ CAUTION:</b> <i>Reseating the TN795 Processor/Tone-Clock circuit pack will disrupt service. Please proceed with caution.</i></p> <p><b>⚠ WARNING:</b> <i>When the disk is replaced on the TN795, a new license file must be downloaded to the system before the system will become operational. Refer to "Obtaining a License File" in Chapter 3 of DEFINITY ONE™ Communications System Release 2.0 Installation and Upgrades (555-233-109). Retry the command and if the test fails, replace the circuit pack.</i></p> <p><b>⚠ CAUTION:</b> <i>Replacing the TN 795 processor board can display the translation error message, "TRANS_ID INTERVAL EXPIRATION:xx days when logging into the SAT window. If this occurs, immediately call a Lucent Technical Services Consultant (TSC) to remove the error message. While the switch is in the error condition, the save translations command is not available.</i></p> <p>3. Run the test again.</p> <p>4. If the error occurs again within 15 minutes, follow normal escalation procedures.</p>
	PASS	Communication with this circuit pack is successful.
	EXTRA BD	This result should only appear when more than one circuit pack has been installed. Remove this circuit pack.

*Continued on next page*

Table 5-427. TEST #52 Control Channel Looparound Test — *Continued*

Error Code	Test Result	Description/ Recommendation
Any	NO BOARD	<p>This is normal if the test is being done when the system is booting up. Otherwise, there is some inconsistency between the physical configuration and the data kept in the system.</p> <ol style="list-style-type: none"> <li>1. Verify that the system is not in a stage of booting up.</li> <li>2. Retry the command at 1-minute intervals for a maximum of 5 times.</li> <li>3. Note this step may require a reseal of the board; see caution below. If the problem continues, reseal the circuit pack.</li> </ol> <p> <b>CAUTION:</b> <i>Reseating the TN795 Processor/Tone-Clock circuit pack will disrupt service. Please proceed with caution.</i></p>

**SAKI Sanity Test (#53)**

This test is destructive

This test resets the Tone-Clock functions on the TN795 processor/Tone -Clock circuit pack. It is executed as part of the long test sequence only for the TN795 Processor/Tone-Clock circuit pack. This test can be executed by either a demand test tone-clock 1a long command or a demand **reset tone-clock 1a**.

Table 5-428. TEST #53 SAKI Sanity Test

Error Code	Test Result	Description/ Recommendation
None	ABORT	<p>System resources required for this test are not available.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
2100	ABORT	<p>System resources required for this test are not available.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
1	FAIL	The circuit pack failed to reset.

*Continued on next page*

Table 5-428. TEST #53 SAKI Sanity Test — *Continued*

Error Code	Test Result	Description/ Recommendation
2	FAIL	<p>The circuit pack failed to restart.</p> <ol style="list-style-type: none"> <li>1. Execute command again.</li> <li>2. Note this step may require a reset of the board; see caution below. If the problem persists, repeat the test 5 times in 5 minute increment. If problem continues, reseal the TN795 Processor/Tone-Clock circuit pack.</li> </ol> <p><b>⚠ CAUTION:</b>  <i>Reseating the TN795 Processor/Tone-Clock circuit pack will disrupt service. Please proceed this step with caution. Refer to <a href="#">“Replace the TN795 circuit pack” on page 2-8</a> and <a href="#">“Tone-Clock Replacement” on page 5-1025</a> for more information on replacing the TN795 Processor/Tone-Clock circuit pack.</i></p> <p><b>⚠ WARNING:</b>  <i>When the disk is replaced on the TN795, a new license file must be downloaded to the system before the system will become operational. Refer to “Obtaining a License File” in Chapter 3 of DEFINITY ONE™ Communications System Release 2.0 Installation and Upgrades (555-233-109). Retry the command and if the test fails, replace the circuit pack.</i></p> <p><b>⚠ CAUTION:</b>  <i>Replacing the TN 795 processor board can display the translation error message, “TRANS_ID INTERVAL EXPIRATION:xx days when logging into the SAT window. If this occurs, immediately call a Lucent Technical Services Consultant (TSC) to remove the error message. While the switch is in the error condition, the save translations command is not available.</i></p> <ol style="list-style-type: none"> <li>3. If the error occurs again within 15 minutes, follow normal escalation procedures.</li> </ol>

*Continued on next page*

Table 5-428. TEST #53 SAKI Sanity Test — *Continued*

Error Code	Test Result	Description/ Recommendation
	PASS	The circuit pack initializes correctly. <ol style="list-style-type: none"><li data-bbox="287 354 621 390">1. Run the short test sequence.</li></ol>
Any	NO BOARD	This is normal if the test is being done when (a) the board is not physically in the system or (b) the system is booting up. Otherwise, there is some inconsistency between the physical configuration and the data kept in the system. <ol style="list-style-type: none"><li data-bbox="287 534 816 569">1. Verify that the board is physically in the system.</li><li data-bbox="287 578 866 614">2. Verify that the system is not in a stage of booting up.</li><li data-bbox="287 623 1024 650">3. Retry the command at 1-minute intervals for a maximum of 5 times.</li></ol>

## PROC-SAN (Process Sanity Audits)

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run	Full Name of MO
PROC-SAN	none	none	Process Sanity Audits

The Process Sanity Audits MO is responsible for monitoring the sanity of software processes in the system. If the Process Sanity Audits MO detects that a process has gone insane (does not respond to a sanity message within an allotted time period), the process is restarted. If the Process Sanity Audits MO detects that multiple processes (or a single key process) do not respond to sanity messages within an allotted time period, a system recovery action is initiated.

The Process Sanity Audits MO has no alarms and no tests. Certain errors are logged to the Hardware Error Log for information purposes only.

### Error Log Entries and Test to Clear Values

Table 5-429. Process Sanity Audits Error Log Entries

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
0 <sup>1</sup>	0	Any	Any	Any	none
10 (a)	0	none	none	none	none
204 (a)	any	none	none	none	none

1. Look for other errors of the same type and deal with them accordingly.

Notes:

- a. These errors indicate that a system recovery action has been taken because one or more software processes failed to respond to a sanity audit in a timely fashion. As a result of the recovery action, the system may have temporarily suspended service for a period of time surrounding the error.

## **RING-GEN (Analog Ring Generator)**

<b>MO Name (in Alarm Log)</b>	<b>Alarm Level</b>	<b>Initial Command to Run<sup>1</sup></b>	<b>Full Name of MO</b>
RING-GEN	MAJOR	test environment P	Analog Ring Generator

- Where P is an appropriate port network number determined via the Port field from the Alarm or Error Log.

All analog phones must be provided with a ringing voltage. The Analog Ring Generator is part of the 650A AC Power Supply. A ringing voltage generator failure means that no ringing can occur on analog phones; however, ringing on digital and hybrid phones can still occur. The ringing voltage is monitored by the Tone-Clock circuit pack.

### **Hardware Error Log Entries and Test to Clear Values**

#### **Analog Ring Generator Error Log Entries**

<b>Error Type</b>	<b>Aux Data</b>	<b>Associated Test</b>	<b>Alarm Level</b>	<b>On/Off Board</b>	<b>Test to Clear Value</b>
0 <sup>1</sup>	0	Any	Any	Any	test environment PP
1		Analog Ring Generator Query Test (#118)	MAJOR	ON	test environment PP r 3

- Run the Short Test Sequence first. If all tests pass, run the Long Test Sequence. Refer to the appropriate test description and follow the recommended procedures.

## System Technician-Demanded Tests: Descriptions and Error Codes

---

Always investigate tests in the order presented in the following tables when inspecting errors in the system. By clearing error codes associated with the *Analog Ring Generator Initialization Test*, for example, you may also clear errors generated from other tests in the testing sequence.

Order of Investigation	Short Test Sequence	Long Test Sequence	D/ND <sup>1</sup>
Analog Ring Generator Initialization Test (#117)	X	X	ND
Analog Ring Generator Query Test (#118)	X	X	ND
Single-Carrier Power Query Test (#79)	X	X	ND
Emergency Transfer Query Test (#124) (a)	X	X	ND
External Alarm Lead Query Test (#120) (b)	X	X	ND

---

1. D = Destructive; ND = Nondestructive

### Notes:

- a. Refer to [“EMG-XFER” on page 5-641](#) for a description of this test.
  - b. Refer to EXT-DEV (External Alarm) Maintenance documentation for a description of this test.
-

## Analog Ring Generator Initialization Test (#117)

This test reports an error to the system software if the ringing voltage falls to low (only if system software has made a request to the tone clock to monitor the voltage). The Analog Ring Generator Initialization Test sends a request to the active tone/clock.

Table 5-430. TEST #117 Analog Ring Generator Initialization Test

Error Code	Test Result	Description/ Recommendation
1 1000 1001 1003 1115 2012 2100	ABORT	<p>The system software is unable to determine the active tone/clock circuit pack, unable to allocated the resources necessary to run the test, or unable to send a down link message.</p> <ol style="list-style-type: none"><li>1. Wait for the green LED on the active tone/clock to go out; use the <b>status port-network</b> command to determine the active Tone/Clock circuit pack.</li><li>2. Rerun the test. If the test aborts again, refer to <a href="#">“TDM-CLK (TDM Bus Clock)” on page 5-1132.</a></li></ol>
2000	ABORT	<p>Response to the request was not received within the allowable time period.</p> <ol style="list-style-type: none"><li>1. Look for TDM-CLK errors and alarms. Resolve all other Tone/Clock problems first.</li><li>2. Rerun the test.</li></ol>
1005	ABORT	<p>The tone/clock is unable to read the analog ringing voltage level when the tone/clock is in the Processor Interface slot. This test is not available for the Processor Port Network in this configuration.</p>
	PASS	<p>The active Tone/Clock has successfully been enabled to monitor the ringing voltage level.</p>

**Analog Ring Generator Query Test (#118)**

This test requests the Active Tone-Clock circuit pack to check the ringing voltage. The tone/clock circuit pack replies with PASS if the ringing voltage is adequate to ring the analog phones. If not, the active tone/clock circuit pack replies with a FAIL. The Analog Ring Generator Query Test then reports the result.

Table 5-431. TEST #118 Analog Ring Generator Query Test

Error Code	Test Result	Description/ Recommendation
1 1000 1001 1003 1115 2012 2100	ABORT	<p>Could not seize the resources to run the test. Other maintenance is running on the active tone/clock circuit pack.</p> <ol style="list-style-type: none"> <li>1. Wait for the green LED on the active tone/clock circuit pack to go out; (use the <b>status port-network</b> command to determine the Active tone/clock circuit pack).</li> <li>2. Rerun the test. If the test aborts again, refer to <a href="#">“TDM-CLK (TDM Bus Clock)” on page 5-1132</a>.</li> </ol>
2000	ABORT	<p>Response to the request was not received within the allowable time period.</p> <ol style="list-style-type: none"> <li>1. Look for TDM-CLK errors and alarms. Resolve all other tone/clock problems first.</li> <li>2. Rerun the test.</li> </ol>
1005	ABORT	<p>The tone/clock is unable to read the analog ringing voltage level when the tone/clock is in the Processor Interface slot. This test is not available for the Processor Port Network in this configuration.</p>
	FAIL	<p>This failure indicates that there is no ringing voltage in the carrier where the active tone/clock circuit pack resides. Other carriers may or may not have ringing voltage.</p> <ol style="list-style-type: none"> <li>1. Unseat all analog circuit packs in the cabinet that contains the Tone/Clock circuit pack and rerun the test.</li> <li>2. If the test passes, then the Ring Generator is healthy and one of the analog circuit packs is defective. Replace the analog circuit packs one at a time, and rerun the test to determine which circuit pack is causing the problem. When the defective analog circuit pack is found, replace it. Rerun the test.</li> <li>3. If the test still fails, go to Step 4.</li> <li>4. Replace the 650A power unit, and rerun the test.</li> </ol>
	PASS	<p>Ringing voltage is acceptable in the cabinet containing the tone/clock circuit pack.</p>

- 5 Maintenance Objects for DEFINITY ONE  
S-SYN-BD (Speech Synthesis Circuit Pack)

5-1040

## S-SYN-BD (Speech Synthesis Circuit Pack)

---

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run <sup>1</sup>	Full Name of MO
S-SYN-BD	MIN	test board PCSS sh	Speech Synthesis Circuit Pack
S-SYN-BD	WRN	test board PCSS sh	Speech Synthesis Circuit Pack

- 
1. Where P is the port network number (1); C is the carrier designation (for example, A, B, or C); and SS is the address of the slot in the carrier where the circuit pack is located (for example, 01, 02, ..., etc.).
- 

Refer to [“XXX-BD \(Common Port Circuit Pack\)” on page 5-1343](#) for circuit pack level errors. See also [“S-SYN-PT \(Speech Synthesis Port\)” on page 5-1041](#) for related port information.

## S-SYN-PT (Speech Synthesis Port)

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run <sup>1</sup>	Full Name of MO
S-SYN-PT	MAJOR	test port PCSSpp sh	Speech Synthesis Port
S-SYN-PT	MINOR	test port PCSSpp l	Speech Synthesis Port
S-SYN-PT	WARNING	test port PCSSpp sh	Speech Synthesis Port

1. Where P is the port network number (1); C is the carrier designation (for example, A, B, or C); and SS is the address of the slot in the carrier where the circuit pack is located (for example, 01, 02, ..., etc.).

The TN725 Speech Synthesis circuit pack provides four independent Speech Synthesis Ports which can be connected to any of the voice time slots on the TDM Bus. Each Speech Synthesis Port consists of a speech synthesizer device (SSD) and is managed by a custom-coded programmable speech synthesizer (PSS) controller. The PSS controller is, in turn, controlled by the on-board microprocessor via a command interface specifically designed for this application. The PSS controller's main function is the orderly transfer of encoded speech from the speech vocabulary read-only memory (ROM) to the SSDs. The SSDs decode it and produce 64 kb/s 5-255 PCM (Pulse Code Modulation) speech. The encoded speech is stored in up to 512K bytes of on-board read-only memory (ROM). In addition, each Speech Synthesis Port has an associated dual-tone multifrequency (DTMF) receiver to receive touch-tone digits from a station set connected to the port via a voice time slot. The station set may be connected to the Speech Synthesis Port through either a line or trunk circuit.

When there is an incoming call to a port, the "listen" network time slot is connected to the DTMF receiver input and the "talk" network time slot is connected to the SSD output. This enables the Speech Synthesis Port to support speech synthesis features or touch-tone input with voice response features. Some of the features that use the Speech Synthesis Port's capabilities include Leave Word Calling, Automatic Circuit Assurance, Automatic Wakeup (hotel-motel), and do Not Disturb (hotel-motel).

The Speech Synthesis circuit pack should not be confused with the Announcement circuit pack as different voice features are supported by each circuit pack.

5 Maintenance Objects for DEFINITY ONE  
S-SYN-PT (Speech Synthesis Port)

5-1042

**Hardware Error Log Entries and Test to Clear Values**

Speech Synthesis Port Error Log Entries

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
0 <sup>1</sup>	0	Any	Any	Any	test port PCSSpp sh r 1
1(a)	17672	None			
18	0	busyout port PCSSpp	WARNING	OFF	release port PCSSpp
130(b)		None	WARNING	ON	test port PCSSpp sh
257		Speech Synthesis PSS Handshake Test (#168)	MAJOR	ON	test port PCSSpp sh r 2
513	17922	Speech Synthesis Memory Test (#166)	MINOR	ON	test port PCSSpp sh r 2
769	17664	Speech Synthesis DTMF Receiver Inquiry Test (#164)	MINOR	ON	test port PCSSpp sh r 2
1025	17670	Speech Synthesis SSD Inquiry Test (#167)	MINOR	ON	test port PCSSpp sh r 2
1281		Speech Synthesis DSP Tone Test (#165)	MINOR	ON	test port PCSSpp sh r 2
1537		Speech Synthesis Memory Test (#166)	MINOR	ON	test port PCSSpp sh r 2
1793		Speech Synthesis DTMF Receiver Test (#163)	MINOR	ON	test port PCSSpp l r 2
2049(c)		Conference Circuit Test (#7)	MINOR	ON	test port PCSSpp l r 2
2305		NPE Crosstalk Test (#6)	MINOR	ON	test port PCSSpp l r 2
3840(d)	Any	None			

1. Run the Short Test Sequence first. If all tests pass, run the Long Test Sequence. Refer to the appropriate test description and follow the recommended procedures.

**Notes:**

- a. An in-line failure of the on-board microprocessor/PSS handshake has occurred. Refer to ["Speech Synthesis PSS Handshake Test \(#168\)" on page 5-1052](#) for repair procedures.

**5 Maintenance Objects for DEFINITY ONE**  
*S-SYN-PT (Speech Synthesis Port)*

5-1043

- b. This error type indicates that the circuit pack been removed or has been insane for more than 11 minutes. To clear the error, reinsert or replace the circuit pack.
- c. A transient error that does not cause an alarm can occasionally occur during a SPE, TDM BUS, or Tone Clock interchange. Test the port and follow the instructions for conference Test (#7).
- d. This error is not service-affecting and no action is required.

**System Technician-Demanded Tests: Descriptions  
and Error Codes**

Always investigate tests in the order presented in the table below when inspecting errors in the system. By clearing error codes associated with the *NPE Crosstalk Test*, for example, you may also clear errors generated from other tests in the testing sequence.

For example, you may also clear errors generated from other tests in the testing sequence.

Order of Investigation	Short Test Sequence	Long Test Sequence	D/ND <sup>1</sup>
Speech Synthesis PSS Handshake Test (#168)	X	X	ND
NPE Crosstalk Test (#6)		X	ND
Conference Circuit Test (#7)		X	ND
Speech Synthesis DTMF Receiver Test (#163)		X	ND
Speech Synthesis Memory Test (#166)	X	X	ND
Speech Synthesis DSP Tone Test (#165)	X	X	ND
Speech Synthesis SSD Inquiry Test (#167)	X	X	ND
Speech Synthesis DTMF Receiver Inquiry Test (#164)	X	X	ND
Speech Synthesis Parameter Update Test (#169)	X	X	ND

1. D = Destructive; ND = Nondestructive

## NPE Crosstalk Test (#6)

One or more NPEs reside on each circuit pack with a TDM Bus interface. The NPE controls port connectivity and gain, and provides conferencing functions on a per-port basis. The NPE Crosstalk Test verifies that this port's NPE channel talks on the selected time slot and never crosses over to time slots reserved for other connections. If the NPE is not working correctly, one-way and noisy connections may occur. This test is usually only part of a port's Long Test Sequence and takes about 20 to 30 seconds to complete.

Table 5-432. TEST #6 NPE Crosstalk Test

Error Code	Test Result	Description/ Recommendation
	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals a maximum of 5 times.
1000	ABORT	System resources required to run this test are not available. The port may be busy with a valid call and therefore unavailable for certain tests. You must wait until the port is idle (yellow LED if off) before retesting. 1. If the port is idle, retry the command at 1-minute intervals a maximum of 5 times.  (Refer to <a href="#">s"status station" on page 4-213</a> for a description of all possible states.)
1001	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals a maximum of 5 times.
1002	ABORT	The system could not allocate time slots for the test. The system may be under heavy traffic conditions or it may have time slots out-of-service due to TDM-BUS errors. Refer to <a href="#">"TDM-BUS (TDM Bus)" on page 5-1116</a> to diagnose any Active TDM-BUS errors. 1. If system has no TDM-BUS errors and is not handling heavy traffic, repeat test at 1-minute intervals a maximum of 5 times.
1003	ABORT	The system could not allocate a tone receiver for the test. The system may be oversized for the number of Tone Detectors present or some Tone Detectors may be out-of-service. 1. Look for TTR-LEV errors in the Error Log. If present, refer to <a href="#">"TTR-LEV (TTR Level)" on page 5-1223</a> . 2. Look for TONE-PT errors in the Error Log. If present, refer to <a href="#">"TONE-PT (Tone Generator)" on page 5-1204</a> . 3. If neither condition exists, retry the test at 1-minute intervals a maximum of 5 times.

*Continued on next page*

Table 5-432. TEST #6 NPE Crosstalk Test — *Continued*

Error Code	Test Result	Description/ Recommendation
1004	ABORT	The port was seized by a valid call during the test and the test has been aborted. You must wait until the port is idle (yellow LED if off) before retesting. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
1020	ABORT	The test did not run due to an already existing error on the specific port or a more general circuit pack error. <ol style="list-style-type: none"><li>1. Examine Error Log for existing errors against this port or the circuit pack and attempt to diagnose the already existing error.</li></ol>
2000	ABORT	Response to the test request was not received within the allowable time period.
2100	ABORT	Could not allocate the necessary system resources to run this test. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
Any	FAIL	The NPE of the tested port was found to be transmitting in error. This causes noisy and unreliable connections. <ol style="list-style-type: none"><li>1. Replace the circuit pack.</li></ol>
	PASS	The port is correctly using its allocated time slots. User-reported troubles on this port should be investigated using other port tests and examining the Error Log.

## Conference Circuit Test (#7)

One or more NPEs reside on each circuit pack with a TDM Bus interface. The NPE controls port connectivity and gain, and provides conferencing functions on a per-port basis. The Conference Circuit Test verifies that the NPE channel for the port being tested can correctly perform the conferencing function. The NPE is instructed to listen to several different tones and conference the tones together. The resulting signal is then measured by a Tone Detector port. If the level of the tone is within a certain range, the test passes.

Table 5-433. TEST #7 Conference Circuit Test

Error Code	Test Result	Description/ Recommendation
	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals a maximum of 5 times.
1000	ABORT	System resources required to run this test are not available. The port may be busy with a valid call and therefore unavailable for certain tests. You must wait until the port is idle (yellow LED if off) before retesting. 1. If the port is idle, retry the command at 1-minute intervals a maximum of 5 times.
1004	ABORT	The port was seized by a valid call during the test and the test has been aborted. You must wait until the port is idle (yellow LED if off) before retesting. 1. Retry the command at 1-minute intervals a maximum of 5 times.
1020	ABORT	The test did not run due to an already existing error on the specific port or a more general circuit pack error. 1. Examine Error Log for existing errors against this port or the circuit pack and attempt to diagnose the already existing error.
2000	ABORT	Response to the test request was not received within the allowable time period.
2100	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals a maximum of 5 times.
Any	FAIL	The NPE of the tested port did not conference the tones correctly. This causes noisy and unreliable connections. 1. Retry the test.
	PASS	The port can correctly conference multiple connections. User-reported troubles on this port should be investigated using other port tests and examining the Error Log.

## Speech Synthesis DTMF Receiver Test (#163)

A series of DTMF tones are conferenced from the TDM Bus into the port's DTMF receiver and checked to see if the correct tones have been detected during the correct intervals. If all the DTMF tones were detected correctly, the test passes. If any of the tones were not detected correctly, the test fails.

Table 5-434. TEST #163 Speech Synthesis DTMF Receiver

Error Code	Test Result	Description/ Recommendation
	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals a maximum of 5 times.
1000	ABORT	System resources required to run this test are not available. The port may be busy with a valid call and therefore unavailable for certain tests. You must wait until the port is idle (yellow LED if off) before retesting. 1. If the port is idle, retry the command at 1-minute intervals a maximum of 5 times.
2000	ABORT	Response to the test request was not received within the allowable time period.
2100	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals a maximum of 5 times.
Any	FAIL	DTMF tones were not detected. This type of failure may cause features using touch-tone input to the Speech Synthesis Port to malfunction. 1. Verify that the Tone-Clock circuit pack is functioning correctly by checking the Error Log and using the <b>test tone-clock long</b> command. 2. If the test fails again, replace the Speech Synthesis circuit pack.
	PASS	The port has detected all DTMF tones correctly. User-reported troubles should be investigated using other tests and verifying other ports on this circuit pack are working correctly.

## Speech Synthesis DTMF Receiver Inquiry Test (#164)

This test determines the sanity of the port's DTMF receiver. The on-board microprocessor tests the port's DTMF receiver and determines if it is in a sane (test passes) or insane (test fails) condition.

Table 5-435. TEST #164 Speech Synthesis DTMF Receiver Inquiry Test

Error Code	Test Result	Description/ Recommendation
	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals a maximum of 5 times.
1000	ABORT	System resources required to run this test are not available. The port may be busy with a valid call and therefore unavailable for certain tests. You must wait until the port is idle (yellow LED if off) before retesting. 1. If the port is idle, retry the command at 1-minute intervals a maximum of 5 times.
2000	ABORT	Response to the test request was not received within the allowable time period.
2100	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals a maximum of 5 times.
Any	FAIL	The DTMF receiver for this port is insane. 1. If the test fails again, replace the circuit pack.
	PASS	The DTMF receiver for this port is sane. User-reported troubles should be investigated using other tests and verifying other ports on this circuit pack are working correctly.

**Speech Synthesis DSP Tone Test (#165)**

The digital signal processor (DSP) associated with each port can generate a 440-Hz tone whose presence can be detected by TN748 General Purpose Tone Detector circuit packs. A 440-Hz tone is generated for 500 msec on a specified time slot which is being listened to by the detector circuit. If the detector determines the tone is present on the time slot, the test passes; otherwise, it fails.

**Table 5-436. TEST #165 Speech Synthesis DSP Tone Test**

Error Code	Test Result	Description/ Recommendation
	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals a maximum of 5 times.
1000	ABORT	System resources required to run this test are not available. The port may be busy with a valid call and therefore unavailable for certain tests. You must wait until the port is idle (yellow LED if off) before retesting. 1. If the port is idle retry the command at 1-minute intervals a maximum of 5 times.
1001 1002 1003	ABORT	System resources required to run this test are not available. 1. Retry the command at 1-minute intervals a maximum of 5 times.
1021	ABORT	The 440-Hz tone was not detected by the Tone Detector circuit and inter-digit time-out has occurred on the Tone Detector circuit. 1. Retry the command at 1-minute intervals a maximum of 5 times. 2. If the test continues to abort, verify all Tone Detector circuit packs in the system are functioning correctly by checking the Error Log and using the <b>test board PCSS long</b> command. Replace any faulty Tone Detector circuit packs and repeat the test. 3. If the test continues to abort, replace the Speech Synthesis circuit pack.
2000	ABORT	Response to the test request was not received within the allowable time period.
2100	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals a maximum of 5 times.
Any	FAIL	The 440-Hz tone was not detected by the Tone Detector circuits. 1. If the test fails again, verify all Tone Detector circuit packs in the system are functioning correctly by checking the Error Log and using the <b>test board PCSS long</b> command. Replace any faulty Tone Detector circuit packs and repeat the test. 2. If the test fails again, replace the Speech Synthesis circuit pack.
	PASS	The 440-Hz tone has been detected correctly. User-reported troubles should be investigated using other tests and verifying other ports on this circuit pack are working correctly.

## Speech Synthesis Memory Test (#166)

The encoded speech for the Speech Synthesis circuit pack is stored in on-board read-only memory. A checksum is computed for each 32K speech memory block and compared against a known checksum value. If all computed checksum values are successfully compared against the stored checksum values, the test passes. If, while testing the speech complex memory, the on-board microprocessor finds a memory error, the test is terminated and a failure is reported. This type of failure may affect other ports on the Speech Synthesis circuit pack, resulting in errors or alarms on each port.

Table 5-437. TEST #166 Speech Synthesis Memory Test

Error Code	Test Result	Description/ Recommendation
	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals a maximum of 5 times.
1000	ABORT	System resources required to run this test are not available. The port may be busy with a valid call and therefore unavailable for certain tests. You must wait until the port is idle (yellow LED if off) before retesting. 1. If the port is idle, retry the command at 1-minute intervals a maximum of 5 times.
1019	ABORT	Test is already running on a different port, possibly due to background maintenance activity. Only one of these tests may be active on a circuit pack at a time. 1. Retry the command at 1-minute intervals a maximum of 5 times.
2000	ABORT	Response to the test request was not received within the allowable time period.
2100	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals a maximum of 5 times.
Any	FAIL	The computed checksum from the speech vocabulary read-only memory did not compare correctly with the stored checksum. This type of failure may cause features using the Speech Synthesis Port's speech services to malfunction and result in degradation of synthesized speech quality ranging from insignificant to major. 1. Replace the circuit pack.
	PASS	The computed checksum values were successfully compared against the stored checksum values. User-reported troubles should be investigated using other tests and verifying other ports on this circuit pack are working correctly.

## Speech Synthesis SSD Inquiry Test (#167)

This test determines the sanity of the specified port's Speech Synthesis Device (SSD). The on-board microprocessor tests the port's SSD and determines if it is in a sane (test passes) or insane (test fails) condition. Other ports on the Speech Synthesis circuit pack continue to function correctly during this type of failure.

Table 5-438. TEST #167 Speech Synthesis SSD Inquiry Test

Error Code	Test Result	Description/ Recommendation
	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals a maximum of 5 times.
1000	ABORT	System resources required to run this test are not available. The port may be busy with a valid call and therefore unavailable for certain tests. You must wait until the port is idle (yellow LED if off) before retesting. 1. If the port is idle, retry the command at 1-minute intervals a maximum of 5 times.
2000	ABORT	Response to the test request was not received within the allowable time period.
2100	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals a maximum of 5 times.
Any	FAIL	The SSD is insane. 1. Replace the circuit pack.
	PASS	The SSD is sane. User-reported troubles should be investigated using other tests and verifying other ports on this circuit pack are working correctly.

## Speech Synthesis PSS Handshake Test (#168)

This test verifies control functionality between the on-board microprocessor and PSS controller. A failure occurs if either of the following events occur:

- The on-board microprocessor times out while waiting for the PSS controller to respond.
- An invalid command is received by the on-board microprocessor from the PSS controller.

This type of failure affects all four ports on the Speech Synthesis circuit pack, resulting in errors or alarms on each port.

Table 5-439. TEST #168 Speech Synthesis PSS Handshake Test

Error Code	Test Result	Description/ Recommendation
	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals a maximum of 5 times.
1000	ABORT	System resources required to run this test are not available. The port may be busy with a valid call and therefore unavailable for certain tests. You must wait until the port is idle (yellow LED if off) before retesting. 1. If the port is idle, retry the command at 1-minute intervals a maximum of 5 times.
2000	ABORT	Response to the test request was not received within the allowable time period.
2100	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals a maximum of 5 times.
Any	FAIL	The on-board microprocessor has timed out while waiting for the PSS controller to respond or an invalid command has been received by the on-board microprocessor from the PSS controller. This type of failure may cause features using the Speech Synthesis Port's speech services to malfunction. 1. Replace the circuit pack.
	PASS	The on-board microprocessor/PSS handshake is working correctly. User-reported troubles should be investigated using other tests and verifying other ports on this circuit pack are working correctly.

## Speech Synthesis Parameter Update Test (#169)

This test updates the DTMF interdigit time-out parameter used by the Speech Synthesis circuit pack to be consistent with that specified by the switch processing element (SPE).

Table 5-440. TEST #169 Speech Synthesis Parameter Update Test

Error Code	Test Result	Description/ Recommendation
	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals a maximum of 5 times.
1000	ABORT	System resources required to run this test are not available. The port may be busy with a valid call and therefore unavailable for certain tests. You must wait until the port is idle (yellow LED if off) before retesting. 1. If the port is idle, retry the command at 1-minute intervals a maximum of 5 times.
2100	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals a maximum of 5 times.
Any	FAIL	An internal system error has occurred.
	PASS	The DTMF interdigit time-out parameter has been updated. 1. User-reported troubles should be investigated using other tests and by verifying that other ports on this circuit pack are working correctly.

## SW-CTL (Switch Control)

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run	Full Name of MO
SW-CTL	MAJOR	test switch-control [1a] sh	Switch Control

The Switch Control (SW-CTL) Maintenance Object resides on the TN795 Processor board. It is used to send control information between port circuit packs and the system processor. This control information is sent via the Time Division Multiplex (TDM) Bus. The portion of the TDM Bus used to transmit control messages is called the control channel. The control channel can be on either TDM Bus A or TDM Bus B, but only one bus is used for the control channel at any given time.

The Switch Control is critical in the setup and take down of all calls but is not involved in the voice or data transmission that takes place during established calls. The Switch Control also detects which circuit packs are present in the system. This information is sent to the processor at system initialization time and when a circuit pack is plugged into the system or removed from the system.

The Switch Control also monitors the health of the control channel on the TDM Bus and informs the TDM-BUS Maintenance Object when errors occur. It also monitors critical system timing signals generated by the Tone Clock circuit on the TN795 circuit pack and informs the TDM-CLK Maintenance Object when a failure is detected.

### Error Log Entries and Test to Clear Values

Table 5-441. SW-CTL Error Log Entries

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
0 <sup>1</sup>	0	Any	Any	Any	test switch-control
1(a)	Any	Control Channel Test (#94)	MAJOR	ON	test switch-control r 3
2 (b)		Control Channel Test (#94)	MAJOR	ON	test switch-control r 3
769 (c)	Any	None			
1025		Switch Control Loop Around Test (#92)	MAJOR	ON	test switch-control r 2
1281 (d)	Any	None			

Continued on next page

5 Maintenance Objects for DEFINITY ONE  
SW-CTL (Switch Control)

5-1055

Table 5-441. SW-CTL Error Log Entries — Continued

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
1537 (e)		Switch Control Reset Action(#93)	MAJOR	ON	reset switch-control
3841 (f)		Switch Control Restart Action(#1357)	MAJOR	ON	reset switch-control restart

1. Indicates that an alarm was raised but that the associated error could not be entered into the hardware error log due to a momentary overload condition. Run the short test and refer to the appropriate test description for tests that fail.

## Notes:

- a. Error Type:1 - This error indicates that more than 8 circuit packs have been removed in the last 15 minutes. Generation of this error may indicate that there is a problem with the TN795 Processor circuit pack or with the TDM bus. The alarm caused by this condition can be resolved by 3 successful completions of the Control Channel test (#94).
- b. Error Type: 2 - The Switch Control Channel Transmission test failed. This error may not cause a Switch Control alarm if Error Type 769 is also present since this error may actually be caused by the loss of clock signals and not by a Switch Control failure.
- c. Error Type: 769 - This error occurs when the Switch Control reports a loss of timing signals to the processor. When this error is present, the Switch Control is usually not alarmed since any Switch Control test failures are actually the result of faulty signals from the Processor/Tone-Clock. See TDM-CLK (TDM Bus Clock) Maintenance documentation for the procedures needed to diagnose Tone-Clock circuit pack troubles.
- d. Error Type: 1281 - This error indicates a loss of handshake between the SW-CTL firmware and the system software. Look for and resolve all other SW-CTL errors. Normally this error causes Switch Control maintenance tests to run which will cause other errors to be generated. In the rare case where no other errors are logged, but Error Type 1281 is occurring at a high rate (more than 20 in the previous hour), escalate the problem.

A loss of handshake is caused by a failure of the hardware or firmware on the Processor circuit pack. Follow these repair steps:

1. Look for and resolve all other SW-CTL errors.
2. Look for and resolve all other PKT-CTRL errors.

3. Restart the Switch Control firmware on the Processor board by entering the *reset switch-control restart* command. If this test passes, the switch control firmware is operational. If the test fails, refer to the repair procedure for the Restart Test (#1357)
- e. Error Type: 1537 - This error indicates that the Switch Control Reset Action failed. This failure may be caused by a failure of the hardware or firmware on the Processor circuit pack. Refer to the repair procedures in [“Switch Control Reset Action\(#93\)” on page 5-1059](#).
- f. Error Type: 3841- This error indicates that the Switch Control Restart Action failed. This failure may be caused by a failure of the hardware or firmware on the Processor circuit pack. If this error counter reaches a count of 2, DEFINITY software is restarted in an attempt to correct the problem by downloading the Switch Control firmware to the MPC860 processor on the TN795 board. Refer to the repair procedures for the Restart Test (#1357)

**Recommended Repair Kits:** Processor circuit pack (TN795) with correct software release.

## System Technician-Demanded Tests: Descriptions and Error Codes

Always investigate tests in the order presented in the table below when inspecting errors in the system. By clearing error codes associated with the *Switch Control Restart Test*, for example, you may also clear errors generated from other tests in the testing sequence.

Order of Investigation	Short Test Sequence	Long Test Sequence	Reset Sequence	Restart Sequence	D/DR/ND <sup>1</sup>
Control Channel Interface Test (#92)	X	X			ND
Control Channel Transmission Test (#94)	X	X			ND
Switch Control Reset Action(#93)			X		DR
Switch Control Restart Action (#1357)				X	DR

1. D = Destructive; DR = Disruptive, ND = Nondestructive

**Control Channel Interface Test (#92)**

Loop back messages are sent to the Switch Control via the interface used for control channel messages. The messages are returned to the SPE for verification via the same interface.

**Table 5-442. TEST #92 Control Channel Interface Test**

Error Code	Test Result	Description/ Recommendation
2012	ABORT	Internal system error
2013	ABORT	Could not allocate the necessary system resources to run this test.
2100		1. Retry the command at 1-minute intervals a maximum of 5 times.
none		

*Continued on next page*

Table 5-442. TEST #92 Control Channel Interface Test — Continued

Error Code	Test Result	Description/ Recommendation
other	FAIL	<p>Messages could not be looped back through the control channel interface. The customer probably cannot make or receive calls.</p> <ol style="list-style-type: none"> <li>1. This failure could be due to either a Processor circuit pack failure or the loss of system timing signals. If the Switch Control is alarmed, then suspect a Processor circuit pack failure. If the Switch Control is not alarmed, investigate the possible loss of system timing signals before replacing the Processor circuit pack. Test #94 also fails if the system timing signals are lost. If Test #94 passes, do not suspect the loss of timing signals.</li> <li>2. Run the Short Test Sequence several times to make sure that this failure is occurring consistently. Run the Restart Test Sequence (<i>reset switch-control restart</i>) to reset the Switch Control. Sometimes restarting the Switch Control firmware may clear the problem. If the test is still failing, proceed to the next step.</li> <li>3. Shut down the processor and reboot it to cause the Switch Control firmware to be downloaded from the Pentium processor to the MPC860 processor on the TN795 circuit pack. If this does not correct the problem, go to Step 4 or Step 5.</li> <li>4. If the system can process calls but still fails the test, replace the Processor board at a time that will cause the least disruption to the customer.</li> <li>5. If calls cannot be made, replace the Processor board immediately.</li> </ol> <p><b>⚠ CAUTION:</b> <i>Reseating/Replacing the TN795 Processor/Tone -Clock circuit pack will disrupt service. Please perform the procedure with caution. Refer to <a href="#">"Replace the TN795 circuit pack" on page 2-8</a> and <a href="#">"Tone-Clock Replacement" on page 5-1025</a> for information on replacing the TN795 Processor/Tone-Clock circuit pack.</i></p> <p><b>⚠ WARNING:</b> <i>When the disk is replaced on the TN795, a new license file must be downloaded to the system before the system will become operational. Refer to "Obtaining a License File" in Chapter 3 of DEFINITY ONE™ Communications System Release 2.0 Installation and Upgrades (555-233-109). Retry the command and if the test fails, replace the circuit pack.</i></p>
	PASS	The control channel interface between the processor and the Switch Control is working correctly.

## Switch Control Reset Action(#93)

**This test is disruptive.**

This test resets the Switch Control and determines if it can successfully go through its initialization sequence. The test is disruptive since there is the possibility of losing some control messages to or from port circuit packs. Existing calls are not disconnected.

Table 5-443. TEST #93 Switch Control Reset Action

Error Code	Test Result	Description/ Recommendation
2012	ABORT	Internal system error
2013 2100 none	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals a maximum of 5 times.
2000 or None	FAIL	The Switch Control could not be successfully reset. If this is a standard system, the customer probably cannot make or receive calls. 1. This failure could be due to either a Processor circuit pack failure or the loss of system timing signals. If the Switch Control is alarmed, then suspect a Processor circuit pack failure. If the Switch Control is not alarmed, investigate the possible loss of system timing signals. See "TDM Bus Clock". If many port circuit pack LEDs are lit, suspect a TDM Bus Clock problem. If only the Processor circuit pack LED is lit, suspect the Processor circuit pack. If the Processor circuit pack is determined to be at fault, proceed to Step 2. 2. Restart the Switch Control firmware by running the Switch Control Restart action (See Test 1357). Follow the repair procedures for that test.
	PASS	The Switch Control has initialized correctly. Look at results of the other tests to see if the Switch Control is operating correctly.

## Control Channel Transmission Test (#94)

Control channel messages are sent from the SPE to selected port circuit packs and the response from the port circuit packs is checked. This tests the ability of the Switch Control to send and receive messages on the control channel of the TDM Bus.

Table 5-444. TEST #94 Control Channel Transmission Test

Error Code	Test Result	Description/ Recommendation
0	ABORT	<p>The port circuit packs necessary for this test are not available.</p> <ol style="list-style-type: none"> <li>1. For Release 1 of DEFINITY ONE, verify that a TN744 Call Classifier circuit pack is plugged into the system. For later releases, verify that at least one port circuit pack is plugged into the system.</li> <li>2. Retry the command at 1-minute intervals a maximum of 5 times.</li> <li>3. If the test continues to abort, run the Restart Action (<i>reset switch-control restart</i>) to see if the problem clears.</li> <li>4. If the test continues to abort, restart the system to see if the problem clears.</li> <li>5. Then replace the Processor circuit pack.</li> </ol> <p><b>⚠ CAUTION:</b> <i>Reseating/Replacing the TN795 Processor/Tone -Clock circuit pack will disrupt service. Please perform the procedure with caution. Refer to section on replacing the TN795 Processor/Tone-Clock circuit pack.</i></p> <p><b>⚠ WARNING:</b> <i>When the disk is replaced on the TN795, a new license file must be downloaded to the system before the system will become operational. Refer to "Obtaining a License File" in Chapter 3 of DEFINITY ONE™ Communications System Release 2.0 Installation and Upgrades (555-233-109). Retry the command and if the test fails, replace the circuit pack.</i></p>
2012	ABORT	Internal system error
2013	ABORT	Could not allocate the necessary system resources to run this test.
2100		
none		<ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>

*Continued on next page*

Table 5-444. TEST #94 Control Channel Transmission Test — Continued

Error Code	Test Result	Description/ Recommendation
0	FAIL	<p>The Switch Control cannot communicate on the TDM Bus control channel. The customer probably cannot make or receive calls.</p> <ol style="list-style-type: none"> <li>1. Run the Short Test Sequence several times to make sure this failure is occurring consistently</li> <li>2. If there are no TDM Bus alarms against the Standby TDM Bus, switch the control channel from its current bus to the Standby bus. If this test passes on the new bus, investigate the possibility of TDM Bus failures. If the test fails even after the control channel is switched to the standby TDM Bus, proceed to Step 3.</li> <li>3. Restart the Switch Control firmware by running the Restart Test (#1357) (<i>reset switch-control restart</i>)</li> <li>4. If the test continues to fail, shut down the processor and reboot it. This will cause the Switch Control firmware to be downloaded from the Pentium processor on the TN795 to the MPC860 processor on the TN795. If the test continues to fail, go to Step 5.</li> <li>5. If calls still cannot be made, replace the Processor board.</li> </ol>
	PASS	The Switch Control can communicate with the port circuit packs over the TDM Bus.

### Switch Control Restart Action(#1357)

**This test is disruptive.**

This test restarts the Switch Control firmware and determines if it can successfully go through its initialization sequence. The test is disruptive since there is the possibility of losing some control messages to or from port circuit packs. Existing calls are not disconnected.

Table 5-445. TEST #1357 Switch Control Restart Test

Error Code	Test Result	Description/ Recommendation
2012	ABORT	Internal system error
2013 2100 none	ABORT	<p>Could not allocate the necessary system resources to run this test.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>

Continued on next page

Table 5-445. TEST #1357 Switch Control Restart Test — *Continued*

Error Code	Test Result	Description/ Recommendation
2000 or None	FAIL	<p>The Switch Control could not be successfully restarted. The customer probably cannot make or receive calls.</p> <ol style="list-style-type: none"> <li>1. This failure is probably due to either a problem with the firmware that provides the Switch Control function on the Processor circuit pack or a failure of the hardware on the Processor circuit pack. If the Switch Control is alarmed, then proceed to Step 2.</li> <li>2. If calls cannot be made, shut down the processor and restart it to see if a download of the firmware from the Pentium processor on the TN795 to the MPC860 processor on the TN795 corrects the problem.</li> <li>3. If calls cannot be made after the system reboots, replace the Processor circuit pack.</li> </ol> <p><b>⚠ CAUTION:</b> <i>Reseating/Replacing the TN795 Processor/Tone -Clock circuit pack will disrupt service. Please perform the procedure with caution. Refer to section on replacing the TN795 Processor/Tone-Clock circuit pack.</i></p> <p><b>⚠ WARNING:</b> <i>When the disk is replaced on the TN795, a new license file must be downloaded to the system before the system will become operational. Refer to "Obtaining a License File" in Chapter 3 of DEFINITY ONE™ Communications System Release 2.0 Installation and Upgrades (555-233-109). Retry the command and if the test fails, replace the circuit pack.</i></p> <p>Note: If the 3841 error associated with the failure of this Restart test reaches a count of 2, DEFINITY software is restarted in an attempt to correct the problem.</p>
	PASS	<p>The Switch Control has restarted successfully. Look at results of the other tests to see if it is operating correctly.</p>

## SYNC (Synchronization)

---

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run	Full Name of MO
SYNC	MAJOR	display errors	Synchronization Maintenance
SYNC	MINOR	display errors	Synchronization Maintenance
SYNC	WARNING	test synchronization	Synchronization Maintenance

The Synchronization Maintenance is composed of both hardware and software components and its purpose is to provide a common reference frequency for reliable digital communication between systems and other PBXs, COs or CPE. Synchronization is achieved via the use of several system components which include the Tone-Clock and the DS1 Interface.

Depending on the network synchronization plan and the status of synchronization sources, the system timing reference may be a Tone-Clock circuit pack or DS1 interface circuit packs. Stratum 4 synchronization extracts timing information directly from a DS1 reference or from a Tone-Clock.

### Stratum 4 Synchronization

---

The system can be configured with primary and secondary synchronization references (DS1 interface circuit packs) when using Stratum 4 synchronization. Both references are optional (since the local oscillator can be used), and the secondary reference is optional if a primary is provided. If this system is the master for the network, then its local oscillator would be used and no DS1s would be used as references.

If the primary synchronization reference is not providing a valid timing signal, the system automatically switches to the secondary synchronization reference. If the secondary reference does not provide a valid timing signal or is not administered as a synchronization reference, a Tone-Clock circuit pack provides the system timing source. The system does not revert to the primary if the current reference is the secondary and is failing; however the system switches from the local oscillator to another reference when the new reference becomes available. **Both the primary and secondary references must reside in the PPN.**

There are two kinds of Stratum 4 synchronization that are supported: Type I and Type II. Stratum 4 type I is more stable than Type II and provides some switching capability at the hardware level. It is important to note that Stratum 4 Type I operation is not possible when one or both of the DS1 interface circuit packs providing the reference sources is a TN722. Both must be the TN767B (or higher) or TN464C (or higher).

## Synchronization Troubleshooting

---

For Stratum 4 operation, major and minor alarms indicate that there is a problem with the system synchronization references. These alarms are resolved when the alarmed synchronization reference is restored.

The **status synchronization** and **display synchronization** commands are used to determine the current system synchronization reference and the primary and secondary references that are administered respectively.

Other commands associated with Synchronization Maintenance are **disable synchronization-switch** and **enable synchronization-switch**. These commands are used to disable the ability of Synchronization Maintenance to switch between synchronization references and to enable this switching ability, respectively. The **set synchronization** command is executed only after synchronization has been disabled and is used to manually switch to a specific synchronization reference. This command is useful to diagnose synchronization problems by forcing a specific reference (DS1 or Tone-Clock) to be the system synchronization reference to determine if a specific reference is providing a valid timing signal. For Stratum 3 operation, only a TN780 Tone-Clock circuit pack may be specified. To switch synchronization to the Stratum 3 clock, use the **enable synchronization-switch** command after verifying that the Stratum 3 clock is wired correctly.

The system synchronization planner must avoid creating a *timing loop* when administering the primary and secondary synchronization references in a system. A timing loop exists whenever a system receives timing from another system whose timing reference is directly or indirectly derived from itself. Timing loops can lead to loss of digital data between systems that are exchanging data with any system within the loop. An invalid timing signal is also generated by any system within the loop, thus propagating the invalid timing signal to any system(s) using a system within the loop as a synchronization reference. [Figure 5-51](#) shows a timing loop and a correct distribution of timing between the systems.




Figure 5-51. Synchronization Timing Loop

A correctly designed network has no loops and each piece of equipment in the network is supplied by a clock of equal or lower stratum (that is, the inputs to a Stratum 3 clock should NEVER be from a Stratum 4 device). **It is strongly recommended that the network administrator be consulted before administering any synchronization changes.**

## Error Log Entries and Test to Clear Values

Table 5-446. Synchronization Error Log Entries

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
0 <sup>1</sup>	0	Any	Any	Any	test synchronization
1 (a) <sup>1</sup>	Any	None	WARNING/ MINOR(j) <sup>2</sup>	OFF	None
18 (b)	0	disable sync	WARNING	OFF	enable sync
257 (c) <sup>1</sup>	Any	None	WARNING/ MINOR(j) <sup>2</sup>	OFF	None
513 (d) <sup>1</sup>	Any	None	WARNING/ MAJOR(j) <sup>2</sup>	OFF	None

Continued on next page

5 Maintenance Objects for DEFINITY ONE  
SYNC (Synchronization)

5-1066

Table 5-446. Synchronization Error Log Entries — *Continued*

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
769 (e)		None	MAJOR/ WARNING <sup>3</sup>	OFF	None
1793 <sup>4</sup>	0-50	None	MAJOR/ WARNING	OFF	enable sync
2049 (f) (h) <sup>4</sup>	0	None	WARNING	OFF	None
2305 (g) (h) <sup>4</sup>	0	None	WARNING	OFF	None

1. Run the Short Test Sequence first. If all tests pass, run the Long Test Sequence. Refer to the appropriate test description and follow the recommended procedures.
2. This error type initially raises a Warning alarm. If this error type persists and alarms are not downgraded on this MO due to the value of **set options**, then, after a period of time, a Minor or Major alarm is raised.
3. Major alarms on this MO may be downgraded to Warning alarms based on the value used in the **set options** command.
4. It may take up to one hour for these SYNC alarms to clear due to "leaky bucket" strategy.

## Notes:

- a. This error indicates a problem with the primary DS1 reference. It is cleared when the primary reference is restored. The following steps should give an indication of the source of the problem:
  1. Check if the primary DS1 interface circuit pack is inserted in the carrier via the **list configuration board PCSS** command.
  2. Check the connection of the cable supplying the external timing source to the primary DS1 interface circuit pack.
  3. Test the primary DS1 interface circuit pack via the **test board PCSS long** command. Check the Error Log for DS1-BD errors and refer to the DS1-BD (DS1 Interface Circuit Pack) Maintenance documentation to resolve any errors associated with the primary DS1 interface circuit pack. If no errors are listed in the Error Log for the primary DS1 interface circuit pack, continue with the following steps.
  4. Test the active Tone-Clock circuit pack in the master port network via the **test tone/clock PC long** command. Check the Error Log for TDM-CLK errors and verify that TDM Bus Clock Test #148 passes successfully. If Test #148 fails with an Error Code 2 through 32, refer to ["TDM-CLK \(TDM Bus Clock\)"](#) to resolve the problem. If not, continue with the following steps.

5. Execute the **disable synchronization-switch** and the **enable synchronization-switch** commands. These two commands (when executed together) switch the system synchronization reference to the primary DS1 interface circuit pack. Check the Error Log and execute the **status synchronization** command to verify that the primary DS1 interface circuit pack is still the system synchronization reference. If the primary DS1 interface circuit pack is not the system synchronization reference, continue with the following step.
  - b. This error indicates that Synchronization Maintenance has been disabled via the **disable synchronization-switch** command. Execute the **enable synchronization-switch** command to enable Synchronization Maintenance reference switching and to resolve this alarm.
  - c. This error indicates a problem with the secondary DS1 reference. It is cleared when the secondary reference is restored. Refer to note (a) to resolve this error substituting **secondary** for **primary** in the preceding resolution steps.
  - d. This error indicates that the Tone-Clock circuit pack is providing the timing source for the system. The primary and secondary (if administered) are not providing a valid timing signal. Investigate errors 1 and 257 to resolve this error.
  - e. This error indicates excessive switching of system synchronization references has occurred. When this error occurs, synchronization is disabled and the Tone-Clock circuit pack (in the master port network) becomes the synchronization reference for the system. Execute the following steps to resolve this error:
    1. Check for timing loops and resolve any loops that exist.
    2. Test the active Tone-Clock circuit pack in the master port network via the **test tone/clock PC long** command. Check the Error Log for TDM-CLK errors and verify that TDM Bus Clock Test #148 passes successfully. If Test #148 fails with an Error Code 2 through 32, refer to the TDM-CLK (TDM Bus Clock) Maintenance documentation to resolve the problem. If not, continue with the following steps.
    3. Replace the primary and secondary (if administered) DS1 Interface circuit packs.
    4. Check for an error logged against the primary or secondary DS1 board. If there is an error, follow the DS1 section to resolve the errors. If there is not, enter **enable sync**, and wait for two to five minutes for the primary sync source to come on-line.
  - f. This error indicates that the slave Tone-Clock circuit pack is experiencing loss of signal. Refer to note (i) for error resolution steps.

g. The following steps should be executed to resolve error 2049 and 2305:

1. Check for timing loops, and resolve any loops that exist.

2. Error 2049:

- Test the Tone-Clock circuit packs in the master and slave port networks via the **test tone/clock PC long** command. Check the Error Log for TDM-CLK errors and verify that TDM Bus Clock Test #148 passes successfully. If Test #148 fails with an Error Code 2 through 32, refer to "TDM-CLK" to resolve the problem. If not, continue with the following steps.
- If the system synchronization reference is a Tone-Clock circuit pack and the master Tone-Clock circuit pack fails TDM Bus Clock Test #150, follow the steps listed in "TDM-CLK" to replace the master Tone-Clock circuit pack.
- If the system synchronization reference is a DS1 interface circuit pack and the master Tone-Clock circuit pack fails TDM Bus Clock Test #150, the primary or secondary (if administered) synchronization references are not providing valid timing signals for the system. Check the system synchronization references administered, and follow the steps outlined in note (a) if the primary synchronization reference is providing timing for the system or note (c) if the secondary synchronization reference is providing timing for the system.
- If the slave Tone-Clock circuit pack fails the TDM Bus Clock Test #150 but the master Tone-Clock **does not** fail this test, the master Tone-Clock circuit pack must be replaced. Follow the procedure in ["Tone-Clock Replacement" on page 5-1025](#).

If SLIP errors remain follow SLIP ANALYSIS.

3. Error 2305:

- If the problem persists, replace the Tone-Clock circuit pack in the slave port network. Follow the steps listed in "TDM-CLK" to replace the Tone-Clock circuit pack.

h. Noise on the DS1 line can cause transient alarms on synchronization.

Therefore, when a synchronization problem occurs causing error types 1, 257, or 513, a WARNING alarm is first raised for 15 to 20 minutes before the alarm is upgraded to a MAJOR or MINOR alarm.

---

## System Technician-Demanded Tests: Descriptions and Error Codes

---

Always investigate tests in the order presented in the table below. By clearing error codes associated with the *Test Synchronization Test*, for example, you may also clear errors generated from other tests in the testing sequence.

Order of Investigation	Short Test Sequence	Long Test Sequence	D/ND <sup>1</sup>
Test Synchronization Test (#417)	X	X	ND

- 
1. D = Destructive; ND = Nondestructive

### Test Synchronization Test (#417)

---

This test updates all the Synchronization Maintenance component circuit packs with the correct information regarding their role in providing synchronization for the system. All the Tone-Clock and DS1 Interface circuit packs in the system are updated via this test. This test will either pass or abort.

Table 5-447. TEST #417 Test Synchronization Test

---

Error Code	Test Result	Description/ Recommendation
	ABORT	Internal system error <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
	PASS	The Synchronization Maintenance component circuit pack parameters have been successfully updated. The system should be synchronized after successful execution of this test. If synchronization problems still exist, refer to the Error Log to obtain information regarding the source of the problem.

---

## SYS-LINK (System Links)

---

MO Name (in Alarm Log)	Alarm Level	Initial System Technician Command to Run	Full Name of MO
SYS-LINK	WARNING	test sys-link PCSSpp	SYSTEM LINKS

System Links are packet links that originate at the Packet Interface board and traverse various hardware components to specific endpoints. The hardware components involved on the forward and reverse routes can be different, depending upon the configuration and switch administration. This software release supports one type of link:

PRI ISDN PRI D-Channel Link terminating at a Universal DS1 board

### Recording System Link Events

---

The system links maintenance object is used to record all errors encountered on the links. Most of these events are not extra-ordinary, unless they occur with an alarming frequency. The events are logged as they occur, so as to leave a trail helping analyze abnormal behavior exhibited by the endpoints attached to the links or the links themselves.

When a link goes down, an alarm is raised immediately. A WARNING alarm is raised for the PRI link type. Other alarming conditions which do not cause the link to go down get a WARNING alarm regardless of the link type.

### Identifying a System Link

---

In order to trace problems associated with a system link, it is necessary to find its location. A PRI link can be uniquely identified by its endpoints.

### Display Errors/Alarms

The output of the **display errors** or **display alarm** commands shows the location of the system link for entries with a Maintenance Name of SYS-LINK. You can restrict the scope of the output of these commands by specifying category **sys-link** on the input form. The link type, if any, is listed under the Alt Name field.

### List sys-link

The command **list sys-link** lists all system links present in the system. The location of the system link and the link type are displayed for each link.

## Common Procedure for Repairing Link Problems

The state of a system link is dependent on the state of the various hardware components that it travels over. To resolve any problems associated with a system link, use the following procedure.

The switch maintains a list of hardware components over which the link travels called the hardware path. There are two hardware paths, the current hardware path and the faulted hardware path for each of the system links. The current hardware path is present only for those links that are currently up. When a link is down, the current hardware path is empty. The faulted hardware path, is always present once the link has gone down and is *not cleared when the link subsequently recovers*. The faulted path preserves the path that the link traversed when it last went down. The time at which the faulted path was last recorded is preserved and is accessible via the **status sys-link** location and **list sys-link** commands. Therefore, the focus of attention for problems which do not involve a link that is down, is the current hardware path. If the link is down, faulted hardware path is the focus of attention.

**The status sys-link location** command displays the state of both the hardware paths (current and faulted) along with the state of each of the components in the hardware path. When analyzing any system link problem

1. Look for alarms on the components listed under desired hardware path.
2. If any alarms are present, then follow the maintenance procedures for the alarmed components to clear those alarms first.
3. When all the components are alarm free, wait for 3 minutes to allow the links to recover.
4. Test the system link (**test sys-link PCSSpp long clear**) and notice any tests that fail.
5. If there are any failures, fix the problems indicated by the tests and repeat the procedure.

## Error Log Entries and Test to Clear Values

Table 5-448. SYS-LINK Error Log Entries

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
13 (a)		System Link Status (985)	WARNING	OFF	
257 (b)			WARNING	OFF	test sys-link PCSSpp l cl
513 (c)			WARNING	OFF	test sys-link PCSSpp l cl

*Continued on next page*

5 Maintenance Objects for DEFINITY ONE  
SYS-LINK (System Links)

5-1072

Table 5-448. SYS-LINK Error Log Entries — Continued

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
772 (d)			WARNING	OFF	test sys-link PCSSpp l cl
1025 (e)			WARNING	OFF	test sys-link PCSSpp l cl
1281 (f)			WARNING	OFF	test sys-link PCSSpp l cl
1537 (g)			WARNING	OFF	test sys-link PCSSpp l cl
1793 (h)			WARNING	OFF	test sys-link PCSSpp l cl
2049 (i)			WARNING	OFF	test sys-link PCSSpp l cl

## Notes:

- a. This error indicates that the link went down. The link may have gone down or never come up. Enter command **status sys-link location** and check the value of the field "Faulted Path." If the value is "default," then the link never came up. If the value is "present," then the link came up and went down.
  1. Follow the Common Procedure described above.
  2. Wait for 3 minutes before checking the link state.
  3. Repeat the procedure until there are no problems with the components.
- b. This error indicates that the link has experienced uplink flow control. Manifest effect of this error is that the end-point may be hyperactive. The system link is alarmed if 4 or more errors of this type are detected within 10 min.
  1. Follow the Common Procedure described above.
  2. Clear errors and wait for 10 min.
- c. This error indicates that the link has experienced downlink flow control. Manifest effect of this error is that some information packets from the packet interface board have been lost. The link is reset on first occurrence, hence, error 1025 will also be logged. The system link is alarmed if 2 or more errors of this type are detected within 10 min.
  1. Follow the Common Procedure described above.
  2. Clear errors and wait for 10 min.

- d. This error indicates that the link experienced a temporary disconnect due to excessive resets or state transitions. Manifest effect of this error is that the link is taken down and then brought up again. The system link is alarmed if 2 or more errors of this type are detected within 10 min.
    - 1. Follow the Common Procedure described above.
    - 2. Clear errors and wait for 10 min.
  - e. This error indicates that the link has been reset. Manifest effect of this error is that information packets queued at the time of reset are lost. The system link is alarmed if 20 or more errors of this type are detected within 10 min.
    - 1. Follow the Common Procedure described above.
    - 2. Clear errors and wait for 10 min.
  - f. This error indicates that the link has experienced slow transmit rate due to remote endpoint being busy. Manifest effect of this error is that the end-point location may experience slower throughput rate and/or noisy transmission. The system link is alarmed if 4 or more errors of this type are detected within 10 min.
    - 1. Ensure that the remote endpoint is functioning properly.
    - 2. If the problem persists, follow the Common Procedure described above.
    - 3. Clear errors and wait for 10 min.
  - g. This error indicates that the link has experienced slow transmit rate due to excessive retransmission. Possible causes for this error may be that the switch is overrunning the end-point or that the end-point is sick. Manifest effect of this error is that the end-point location may experience slower throughput rate. The system link is alarmed if 4 or more errors of this type are detected within 10 min.
    - 1. Follow the Common Procedure described above.
    - 2. Clear errors and wait for 10 min.
  - h. This error indicates that the link has experienced slow transmit rate due to unknown causes. Manifest effect of this error is that the end-point location may experience slower throughput rate and the Packet Interface may experience backup or congestion. The system link is alarmed if 4 or more errors of this type are detected within 10 min.
    - 1. Follow the Common Procedure described above.
    - 2. Clear errors and wait for 10 min.
  - i. This error indicates that the link has transmitted an excess amount of packets. The transmit buffers of this link have been purged. The system link is alarmed if 4 or more errors of this type are detected within 10 min.
    - 1. Follow the Common Procedure described above.
    - 2. Clear errors and wait for 10 min.
-

## System Technician-Demanded Tests: Descriptions and Error Codes

Testing for system links is different from the standard test procedures for maintenance objects. In addition to testing the system link maintenance object, the user is allowed to test all the components in the path of the system link. There are two paths preserved for the link. The current path, if present, represents the path traversed by the link currently. This path will not be present when the link is down. The other path, the faulted path is present if the link has ever gone down or never come up. If the link came up and went down, then the faulted path is marked "Present". If the link never came up, the faulted path is marked "Default". Either case, it represents the path on which the link was attempted or established unsuccessfully.

Test command for the system links, **test sys-link PCSSpp** can be specified with current or faulted as an optional argument if the user wishes to test all the components in the specified path. The tests executed will be the same if the user were to test each component manually. In the event that the user does not specify any path, then only the tests specified for the system links are executed.

Order of Investigation	Short Test Sequence	Long Test Sequence	D/ND <sup>1</sup>
System Link Status (#985)	X	X	N

1. D = Destructive, ND = Non-destructive

### System Link Status (#985)

This test is non-destructive.

This test queries the switch for the status of the system link and verifies that all switch components have the same view of the link state.

Table 5-449. TEST #985 System Link Status

Error Code	Test Result	Description/ Recommendation
1007	ABORT	Could not locate the system link associated with this location 1. Retry the command at 1-minute intervals for a maximum of 5 times.
2500	ABORT	Internal system error 1. Retry the command at 1-minute intervals for a maximum of 5 times.
6	FAIL	The system link is down. 1. Follow the procedure for error type 13.
	PASS	The system link is up.

## SYSTEM (System)

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run <sup>1</sup>	Full Name of MO
SYSTEM	None	None	SYSTEM

1. SYSTEM only has errors associated with it and thus only appears in the Error Log and not in the Alarm Log. There are no tests that can be run with SYSTEM.

SYSTEM is generally used when software encounters a problem with either hardware or itself and requests a restart to clear the problem. SYSTEM also logs errors that cannot be associated with any single process. This is not a problem. The initcauses log should also confirm that a software-requested restart was performed.

### Error Log Entries and Test to Clear Values

The Aux Data field may be 0 or the return code from a bad software call, and the following examples in no way exhaust the possibilities. Often, two errors are logged at the same time for each problem.

Table 5-450. System Error Log Entries

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
0 <sup>1</sup>	0	Any	Any	Any	None
8 (a)	0	None			
9 (b)	Any	None			
10 (c)	Any	None			
21 (d)		None			
355 (e)	Any	None			
356 (f)	Any	None			
601 (g)		None			
602 (h)		None			
603 (i)		None			

1. Run the Short Test Sequence first. If all tests pass, run the Long Test Sequence. Refer to the appropriate test description and follow the recommended procedures.

Notes:

- a. A System Restart Level 3 was requested.
  - b. A System Restart Level 2 was requested. This can happen due to a loss of tones (due to a faulty Tone-Clock circuit pack).
  - c. A System Restart Level 1 was requested.
  - d. A process trapped.
  - e. A Restart Level 2 occurred due to a power loss.
  - f. A Restart Level 2 occurred due to a tone clock loss.
  - g. An error occurred during initialization.
  - h. An error occurred while loading translations and the system requested a Restart Level 3.
  - i. A process was reset.
-

## TBRI-BD (TN2185 ISDN Trunk-Side BRI)

---


MO Name (in Alarm Log)	Alarm Level	Initial Command to Run <sup>1</sup>	Full Name of MO
TBRI-BD	MINOR	test board PCSS I r#	TBRI-BD

- 
1. Where P is the port network number (1), C is the carrier designation (A, B, or C), and SS is the carrier slot address where the circuit pack is located (1, 2, and so forth).
- 

The TN2185 circuit pack contains eight, 4-wire ports that interface to the network at the ISDN S/T reference point over two 64 Kb/s channels (B1 and B2) and over a 16Kb/s signaling (D) channel. The B1 and B2 channels can be simultaneously circuit switched, or individually packet switched. Only one channel per trunk can be packet switched due to Packet Processing Element (PPE) limitations. The D channel is either circuit switched or packet switched. Packet switching uses the PPE to combine all D channels into a single physical channel, which is then routed via the concentration highway to the Network Control Element (NCE) and then to the TDM bus. The circuit-switched connections have a Mu-law or A-law option for voice and operate as 64Kb/s clear data channels. The packet-switched channels support the LAPD protocol and conform with the CCITT Q.920 Recommendations for D-channel signaling.

### LEDs

The three LEDs on the circuit pack's faceplate indicate board status. When illuminated, the red LED indicates a board failure or a major or minor on-board alarm, the green LED indicates that testing is in progress, and the amber LED indicates that the board is in use.



ISDN Interface Reference Points

cydfisdn RPY 072397

Figure 5-52. Integrated Trunk-Side BRI, ISDN Interface Reference Points

ISDN Interface Reference Point definitions:

- LT Logical Terminal
- V Primary Rate user/network (asymmetrical) trunk interface. The ECS is capable of acting as the user or as the network side of this 1.544 - or 2.048-Mbps interface.
- R Interface between Terminal Equipment and Network Termination
- S Basic Rate network-side 4-wire line interface
- S/T 4-wire Basic Rate connection to a Network Termination<sup>1</sup>.
- T 4-wire Basic Rate interface to a Network Termination.<sup>2</sup>

5 Maintenance Objects for DEFINITY ONE  
TBRI-BD (TN2185 ISDN Trunk-Side BRI)

5-1079

- TE Terminal Equipment
- U Basic Rate network-side 2-wire line interface.
- 1 TN2185 ISDN-BRI 4-Wire S Interface (Trunk Side); Release 6.1 only
- 2 TN2185 ISDN-BRI 4-Wire S Interface (Trunk Side)
- 3 No 2-Wire ISDN-BRI circuit pack for Release 6.1
- 4 TN2185 ISDN-BRI 4-Wire S Interface (Trunk Side)
- 5 TN2185 ISDN-BRI 4-Wire S Interface (Trunk Side)

- 
1. Network Termination 2 (NT2), that terminates Layer 1 and higher layers. PBXs, LANs, and terminal controllers typically provide NT2 functionality including protocol handling and multiplexing for Layers 2 and 3.
  2. Network Termination 1 (NT1), that terminates Layer 1 and monitors maintenance, performance, timing, power transfer, multiplexing, and multi-drop termination with contention resolution.
- 

### Hardware Error Log Entries and Test to Clear Values

---

Table 5-451. TBRI-BD Error Log Entries

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
0 <sup>1</sup>	0	Any	Any	Any	test board PCSS sh r 1
1 (a)	Any	None	MINOR	ON	
257 (b)	65535	Control Channel Loop Test (#52)	MINOR	ON	test board PCSS r 20
513 (c)	4352 to 4357		None	ON	
769 (d)	4358				
1025 (e)	4363	NPE/NCE Audit Test (#50)	None	ON	
1291 (f)	4359	Clear Error Counters (#270)	MINOR	ON	
1294 (g)	46088 to 46096	SAKI Sanity Test (#53)	MINOR	ON	See (h)
1537 (h)	46082		MINOR	ON	
1793 (i)	46080		MINOR	ON	

Continued on next page

5 Maintenance Objects for DEFINITY ONE  
TBRI-BD (TN2185 ISDN Trunk-Side BRI)

5-1080

Table 5-451. TBRI-BD Error Log Entries — *Continued*

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
1794 (i)	46094		MINOR	ON	
1795 (i)	46085		MINOR	ON	
2305 (j)	46104		None	ON	
2306 (i)	46081		None	ON	
3330 (j)	46083		MINOR	OFF	
3586 (k)			MINOR	OFF	
3840(l)	4096 to 4101				
3842 (m)	46095				
3843 (n)	46097				

1. Run the Short Test Sequence first. If all tests pass, run the Long Test Sequence. Refer to the appropriate test description and follow the recommended procedures.

## Notes:

- a. The circuit pack stopped functioning or is physically removed from the system.

 **NOTE:**

This alarm logs approximately 11 minutes after removing the circuit pack and/or the SAKI Sanity Test (#53) fails.

If the circuit pack is not in the system, insert a circuit pack in the same slot as the error indicates. See note (g).

- b. Transient communication problems between the switch and this circuit pack. Execute the **test board PCSS** command and refer to the repair procedures for the Control Channel Loop Around Test (#52).
- c. On-board hardware failure. Aux data values correspond to the following detected errors:

4352	External RAM error
4353	Internal RAM error
4355	ROM Checksum error
4357	Instruction set error

Reset the circuit pack with the **busyout board PCSS** and **reset board PCSS** commands. When reset, the circuit pack executes a set of tests to detect the presence of any of the faults listed above. Detection of one of these errors during initialization causes the circuit pack to lock-up and appear insane to the system. See the repair procedure in Note (a).

- d. The circuit pack detects a program logic error. While no action is required, this error can lead to other errors against this circuit pack.
- e. The circuit pack cannot update and read back NPE/NCE memory. This error can be ignored, but may lead to other errors against this circuit pack.
- f. The TN2185 board notifies maintenance software that it has detected a parity error while accessing its dynamic RAM (that stores the board's translation information and downloadable application firmware). Maintenance software resets the circuit pack.
- g. Unable to write LAN Translation RAM Error (internal memory access error). Translation RAM locations for the call connection attempt are not available, and one or more RAM locations are bad due to a translation RAM read-back error. Reset the circuit pack with the **busyout board PCSS** and **reset board PCSS** commands. If the Circuit Pack Restart Test (#594) passes, then the on-board circuitry is healthy. Retire the alarm with the **test board PCSS long clear** command. If the Circuit Pack Restart Test (#594) fails, replace the circuit pack.
- h. Frame overrun at Packet Bus interface. Due to an on-board fault or by faulty data received on one of the circuit pack's external ports. If any of the ports on this circuit pack is alarmed, refer to the repair procedures for those maintenance objects. If this error persists, maintenance software removes the board from service; replace the circuit pack.
- i. The circuit pack is has problems transmitting/receiving data to/from the Packet Bus.

1793 Parity errors are detected when transmitting data to the Packet Bus.

1794 Packet Bus transmit buffers overflow.

1795 Circuit pack cannot find end of frame when transmitting to Packet Bus. Clear the alarm with: **busyout board PCSS**, **reset board PCSS**, **test board PCSS long clear**, **release board PCSS**. If the error recurs within 10 minutes, replace the circuit pack.

2306 Error in a received frame from the Packet Bus, most likely caused by a packet bus problem, but may be due to a circuit pack fault. An invalid Link Access Procedure Data (LAPD) frame error occurs if the frame contains a bad Cyclical Redundancy Check (CRC). If bus parity errors occur, run the LAN Receive Parity Error Counter Test (#595) to determine if the condition has cleared. Refer to the maintenance documentation to determine if the problem is isolated to this circuit pack or is caused by Packet Bus faults.

- j. Error Type (2305, 3330): A critical failure in the Circuit Pack's Packet Bus interface. Possible causes include either a Packet Bus fault or an on-board fault, for example, the board received a bad CRC or invalid DLCI. The number of ISDN circuit packs displaying this error increases the probability of errors due to Packet Bus problems.

If there are no Packet Bus alarms, reset the circuit pack with the **busyout board PCSS** and **reset board PCSS** commands. If the Circuit Pack Restart Test (#594) passes, then the on-board circuitry is healthy. Retire the alarm with the **test board PCSS long clear** command. If the Circuit Pack Restart Test (#594) fails, replace the circuit pack.

- k. The SPE software detects an excessive number of up-link messages from the TN2185 board within a certain time period. To prevent the faulty board from flooding the switch with data, the switch software takes the board out of service and alarms it. The switch software also tells the Archangel to ignore up-link messages from the board.

When the board is alarmed due to this error, the switch software periodically puts the board back in service and tells the Archangel to process up-link messages from the board. If the problem still exists, the software takes the circuit pack out of service again. If the circuit pack does not exhibit the problem for a certain time period, then maintenance software resolves the alarm and the circuit pack is left in service.

- l. The circuit pack received an inconsistent down-link message (a bad header, bad port number, bad data, bad subqualifier, or bad logical link) over the Control Channel.
- m. The board is receiving data from the bus faster than it can distribute the data to its endpoints, causing the FIFO RAM buffer to overflow. This error can occur occasionally due to the statistical sizing of the buffers. If it occurs frequently, it may indicate a LAPD parameter mismatch. LAPD should recover from this problem, but it may degrade the performance of the LAN bus.

When this error is reported, maintenance reads and clears the board counter and logs the problem in the maintenance error log.

- n. Bad translation RAM detected, but the call continues by using another translation location. The circuit pack reports this error when it cannot update NPE/NCE memory and read it back. This error is not service-affecting and can be ignored, but can lead to other types of errors against this circuit pack.
-

## System Technician-Demanded Tests: Descriptions and Error Codes

---

When inspecting errors in the system, always investigate tests in the order listed below. By clearing error codes associated with the *Control Channel Loop Around Test*, for example, you may also clear errors generated from other tests in the testing sequence.

Order of Investigation	Short Test Sequence	Long Test Sequence	D/ND <sup>1</sup>
Control Channel Loop-Around Test (#52)	X	X	ND
NPE/NCE Audit Test (#50)		X	ND
LAN Receive Parity Error Counter Test (#595)		X	ND

---

1. D = Destructive; ND = Nondestructive

---

### Control Channel Loop Around Test (#52)

Refer to the repair procedure described in the [“XXX-BD \(Common Port Circuit Pack\)”](#) section.

### NPE /NCE Audit Test (#50)

Refer to the repair procedure described in the [“XXX-BD \(Common Port Circuit Pack\)”](#) section.

### SAKI Sanity Test (#53)

**This test is destructive.**

Refer to the repair procedure described in the [“XXX-BD \(Common Port Circuit Pack\)”](#) section. This test is only run as a part of a reset board procedure.

### LAN Receive Parity Error Counter Test (#595)

This test is nondestructive. The test reads and clears the circuit pack's LAN Receive Parity Error Counter. This counter increments when it detects a parity error from the Packet Bus. These errors may indicate problems with a circuit pack, Packet Bus, or with another circuit pack on the bus. Use this test to verify the repair.

Table 5-452. TEST #595 LAN Receive Parity Error Counter Test

Error Code	Test Result	Description/ Recommendation
2000	ABORT	<p>Response to the test was not received from the circuit pack within the allowable time period.</p> <ol style="list-style-type: none"><li>1. If the test aborts repeatedly a maximum of 5 times, reset the circuit pack via the <b>busyout board PCSS</b> and <b>reset board PCSS</b> commands.</li><li>2. If the test aborts again, replace the circuit pack.</li></ol>
2100	ABORT	<p>Could not allocate the necessary system resources to run this test.</p>
2012	ABORT	<p>Internal system error.</p> <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
1-10	FAIL	<p>The circuit pack is still detecting errors of this type. The error code indicates the value of the on-board error counter.</p> <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li><li>2. If the test continues to fail, verify the validity of the Packet Bus. Run the Packet Bus maintenance test with the <b>test pkt P long</b> command.</li><li>3. If the Packet Bus test passes, check the validity of the circuit pack. Execute a test that involves data transmission onto the Packet Bus. For example, the <b>test port PCSSpp</b> command may use the connectivity tests of the BRI-PORT maintenance object. If the test fails, refer to the repair procedures; otherwise, proceed to the next step.</li><li>4. Other circuit packs on the Packet Bus may be causing of the parity error. Use the <b>display errors</b> command to check the Error Log for alarmed other circuit packs. Resolve any alarms for other circuit packs as well. Rerun the LAN Receive Parity Error Counter Test (#595).</li></ol>
	PASS	<p>No errors detected.</p>

## TBRI-PT (TN2185 ISDN Trunk-Side BRI Port)

---

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run <sup>1</sup>	Full Name of MO
TBRI-PT	MAJOR	test port PCSS l r#	TBRI-PT
TBRI-PT	MINOR	test port PCSS l r#	TBRI-PT
TBRI-PT	WARNING	test port PCSS s r#	TBRI-PT

- 
1. Where P is the port network number (1), C carrier designation (A, B, or C), and SS is the carrier slot address where the circuit pack is located (1, 2, and so forth).
- 

This document describes the port maintenance features of the DEFINITY ISDN Trunk-side BRI board (TN2185). The circuit pack provides 8 S/T ISDN 2B+D ports which interface to either the central office or another PBX.

The TN2185 circuit pack contains eight, 4-wire ports that interface to the network at the ISDN S/T reference point over two 64 Kb/s channels (B1 and B2) and over a 16Kb/s signaling (D) channel. The B1 and B2 channels can be simultaneously circuit switched, or individually packet switched. Only one channel per trunk can be packet switched due to Packet Processing Element (PPE) limitations. The D channel is either circuit switched or packet switched. Packet switching uses the PPE to combine all D channels into a single physical channel, which is then routed via the concentration highway to the Network Control Element (NCE) and then to the TDM bus. The circuit-switched connections have a Mu-law or A-law option for voice and operate as 64Kb/s clear data channels. The packet-switched channels support the LAPD protocol and conform with the CCITT Q.920 Recommendations for D-channel signaling.

### LEDs

The three LEDs on the circuit pack's faceplate indicate board status. When illuminated, the red LED indicates a board failure or a major or minor on-board alarm, the green LED indicates that testing is in progress, and the amber LED indicates that the board is in use.



5 Maintenance Objects for DEFINITY ONE  
TBRI-PT (TN2185 ISDN Trunk-Side BRI Port)

5-1087

- U Basic Rate network-side 2-wire line interface.
- 1 TN2185 ISDN-BRI 4-Wire S Interface (Trunk Side); Release 6.1 only
- 2 TN2185 ISDN-BRI 4-Wire S Interface (Trunk Side)
- 3 No 2-Wire ISDN-BRI circuit pack for Release 6.1
- 4 TN2185 ISDN-BRI 4-Wire S Interface (Trunk Side)
- 5 TN2185 ISDN-BRI 4-Wire S Interface (Trunk Side)

1. Network Termination 2 (NT2), that terminates Layer 1 and higher layers. PBXs, LANs, and terminal controllers typically provide NT2 functionality including protocol handling and multiplexing for Layers 2 and 3.
2. Network Termination 1 (NT1), that terminates Layer 1 and monitors maintenance, performance, timing, power transfer, multiplexing, and multi-drop termination with contention resolution.

**Hardware Error Log Entries and Test to Clear Values**

Table 5-453. TBRI-PT Error Log Entries

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
0 <sup>1</sup>	0	Any	Any	Any	test Port UCSSPP sh r 1
1 (a)		Level 1 Status Test (#1242)	MINOR	OFF	
129 <sup>2</sup>					
257(b)					
513 (c)	46222	XMIT FIFO Overflow	MINOR	ON	
514 (d)		XMIT FIFO Overflow (TDM)	MINOR	ON	
769 (e)		Traffic Hyperactivity	MINOR	OFF	
1025 (f)					
1281 (g)		NPE Crosstalk Test (#617)	MINOR	ON	
1537 (h)	46210	CRC error (D-Channel)	MINOR	OFF	
1538 (i)		CRC error (TDM D-Channel)	MINOR	OFF	

*Continued on next page*

Table 5-453. TBRI-PT Error Log Entries — *Continued*

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
1793 (j)		BRI Port Local TDM Looparound Test (#619)	MINOR	ON	
2049 (k)			MINOR	OFF	
2305 (l)		Layer 3 Query (#1243)	MINOR	OFF	
3073 (m)		Slip Query Test (#1244)	MINOR	OFF	
3585 (n)		Receive FIFO Overflow (TDM D-Channel)	Log Only	ON	
3586 (o)					
3587 (p)					
3588 (q)	46223				
3589 (r)					
3590 (s)	46211				
3591 (s)					
3592 (t)					
3841 to 3942 (u)					

1. Run the Short Test Sequence first. If all tests pass, run the Long Test Sequence. Refer to the appropriate test description and follow the recommended procedures.
2. The far-end switch changed the ISDN service state. This may be a temporary condition.

Notes:

- a. Loss of continuity of Layer 1 to the far-end. It is assumed that Layer 1 remains active, even when both B-Channels are idle.

This test determines whether Layer 1 is active or not. If Layer 1 is not active, the test attempts to activate it. If Layer 1 cannot be activated, the port is taken out of service, and the test fails.

- b. The D-Channel failed at Layer 2. Expiration of this timer indicates that attempts to bring the failed link back into service have not succeeded and some recovery actions should be taken on the associated B-Channels. Upon expiration, associated in-service B-channels are put in the out-of-service/far end state.

- c. Error Type (513): On-board hardware failure. The FIFO RAM buffers have overflowed, indicating a hardware problem.
- d. Error Type (514): Transmit FIFO Overflow - This error indicates that the circuit pack is having problems transmitting data to the TDM D-Channel. This error only occurs only a system that switches the packet implementation of the D-channel over the TDM Bus. This error indicates an on board problem related to the packet implementation of the D-Channel (R6.2 and higher).
- e. Error Type (769): The port is generating too many uplinks. The link is being suspended.
- f. Error Type (1025): An expired timer has created an unexpected event. The timer could be any of the following:

Timer	Event
T3031	ISDN T3031 timeout
T3032	ISDN T3032 timeout
T305	ISDN T305 timeout
T3081	ISDN T3081 timeout
T3082	ISDN T3082 timeout
TL3	Status Inquiry
T304	Setup ACK
T310	Call Proceeding Receive
T313	Connect SEND

- g. Error Type (1281): This error occurs when the NPE Crosstalk Test (#617) has failed. The test will be repeated every 15 minutes until it passes. Follow normal trouble shooting procedures for NPE Crosstalk Test (#617). If this does not fix the problem, follow normal escalation procedures.
- h. Error Type (1537): The board received a bad Cyclical Redundancy Check (CRC) over the D-Channel. This error is reported on a per-port basis. When the CRC errors exceed 5 within 15 minutes, the port is taken out of service for 5 seconds. If 5 more CRC errors are received within 15 minutes of the first set of 5 errors, the port is taken out of service for 1 minute. If 5 more CRC errors are received within 15 minutes of the previous 5, the port is taken out of service for 15 minutes.

This error is most likely due to a problem with backplane wiring, a noise source, or no termination (an open circuit). It usually does not indicate a problem with the circuit pack.

1. Check the backplane wiring.
2. If the problem persists escalate the problem.

5 Maintenance Objects for DEFINITY ONE  
TBRI-PT (TN2185 ISDN Trunk-Side BRI Port)

5-1090

- i. Error Type (1538): This error occurs when a frame with a bad CRC is received by the BRI trunk board. This error only occurs on a system that switches the packet implementation of the D-channel over the TDM bus. This error indicates an off board problem related to the packet implementation of the TDM D-Channel (R6.2 and later).
- j. Error Type (1793): The BRI Port Local TDM Loop Around Test (#619) failed. Run the Long Test Sequence paying particular attention to the results of the BRI TDM Port Loop Test (#619).
- k. Error Type (2049): The Layer 2 Link Query failed. The test is repeated every 15 minutes until it passes.
- l. Error Type (2305): The Remote Layer 3 Query failed. The test is repeated every 15 minutes until it passes.
- m. Error Type (3073): A frame of information had to be repeated or deleted. Slips usually occur when the received bit rate is not synchronized with the TDM Bus clock.
- n. Error Type (3585): The circuit pack detected an overflow of its receive buffers. This error occurs only a system that switches the packet implementation of the D-Channel over the TDM bus. This error indicates an on board problem related to the packet implementation of the TDM D-Channel (R6.2 and higher).
- o. Error Type (3586): Each port can support up to three Terminal Endpoint Identifiers (TEIs). Each channel on the port can request a TEI assignment from the switch if it supports ISDN-BRI TEI assignment procedures. If switch services gets a request for a fourth TEI on a port, it reports this event to maintenance software and initiates TEI check procedures on the port. Check to see if the correct number of channels are administered for this port.  

The user side supports automatic TEI assignment by the network. Both fixed and automatic TEI assignment are supported on the network side.
- p. Error Type (3587)Service Profiler Identifier (SPID) value is invalid or is a duplicate of another SPID that is already initialized at Layer 3 on the port. SPIDs are not used on the TN2185 circuit pack. However there will be related events.
- q. Error Type (3588): The board receives D-Channel data from the bus faster than it can process the data. The FIFO RAM buffers overflowed. This error occurs occasionally due to the statistical sizing of the buffers; however, frequent occurrences may indicate a LAPD parameter mismatch between the two endpoints of a packet-switched connection. Run the Long Test Sequence paying particular attention to the results of the Receive FIFO Overflow Test (#625).
- r. Error Type (3589): The BRI Port Local LAN Loop Around Test (#618) failed. Run the Long Test Sequence and pay particular attention to the results of Test #618.

- s. Error Type (3590): An activated BRI port receives a frame containing a DLCI over a D-Channel (on the packet bus) for which it does not have a translation. This error normally indicates an off-board problem related to a state mismatch between the far-end and the switch. This error is logged only.
- t. Error Type (3592): An activated BRI port receives a frame containing a DLCI over a D-Channel (on the TDM bus) for which it does not have a translation. This error normally indicates an off-board problem related to a state mismatch between the far-end and the switch. This error is logged only.
- u. Error Type (3592): The port is generating too many uplinks and is taken out of service.
- v. Error Types (3841-3942): [Table 5-454](#) contains the received ISDN cause values for Errors 3841-3942 that are recorded in the hardware error logs. Unless otherwise stated, the cause values are D-Channel events. The aux data field shows which port caused the error.
- w. Error Type (3591): An activated BRI port receives a frame containing a DLCI over a D-Channel (on the TDM bus) for which it does not have a translation. This error normally indicates an off-board problem related to a state mismatch between the far-end and the switch. This error is logged only.

---

**Table 5-454. Cause Values for Error 3841-3942**

---

Value	Type of Problem	Meaning
2	admin	No route to specific transit network
3	admin	No route to destination (or Germany bcap not imp)
6	admin	Channel unacceptable
18	switch problems	No user responding
38	switch problems	Network failure
50	subscription	Requested facility not subscribed
52	admin	Outgoing calls barred
54	admin	Incoming calls barred
62	subscription	Service not authorized
63	admin/sub	Service/option not available
65	admin/sub	Bearer capability not implemented

---

*Continued on next page*

Table 5-454. Cause Values for Error 3841-3942

Value	Type of Problem	Meaning
66	admin/sub	Channel type not implemented
69	admin/sub	Requested facility not implemented
70	admin/sub	Only restricted digital BC available
79	admin	Service/option not implemented
88	admin	Incompatible destination
102	switch problems	Recovery on timer expired

## System Technician-Demanded Tests: Descriptions and Error Codes

When inspecting errors in the system, always investigate tests in the order listed below. By clearing error codes associated with the *Control Channel Loop Around Test*, for example, you may also clear errors generated from other tests in the testing sequence.

Order of Investigation	Short Test Sequence	Long Test Sequence	D/ND <sup>1</sup>
BRI Local LAN Port Loop Around Test (#618)		X	ND
BRI TDM Port Loop Around Test (#619)		X	D
L1 State Query Test (#1242)	X	X	D
CRC Error Counter Test (#623)		X	ND
Receive FIFO Overflow Test (#625)		X	ND
Layer 3 Query Test (#1243)		X	ND
Slip Query Test (#1244)	X	X	ND
Clear Error Counters Test (#270)	X	X	ND
NPE Crosstalk Test (#617)		X	D

1. D = Destructive; ND = Nondestructive

## Clear Error Counters Test (#270)

This test is nondestructive. This test clears the various error counters associated with each TBRI-PT. This test passes if Maintenance is able to successfully send the downlink messages; otherwise, the test aborts.

Table 5-455. TEST #270 Clear Error Counters

Error Code	Test Result	Description/ Recommendation
Any	ABORT	Maintenance could not send the downlink message.
	PASS	The message to clear the error counters of the TBRI-PT maintenance object has been sent.

## NPE Crosstalk Test (#617)

**This test is conditionally destructive.**

One or more NPEs reside on each circuit pack with a TDM Bus interface. The NPE controls port connectivity and gain and provides conferencing functions on a per-port basis. The NPE Crosstalk Test verifies that this port's NPE channel talks on the selected time slot and never crosses over to time slots reserved for other connections. If the NPE is not working correctly, one-way and noisy connections may be observed. This test is part of a port's Long Test Sequence and takes approximately 20 to 30 seconds to complete. Crosstalk testing is performed on both B-channels (B1 and B2) associated with a BRI port. If this test fails on either channel, any channel connected to the port is taken out-of-service. The test aborts if the port and its associated channels are not in the idle state.

Table 5-456. TEST #617 NPE Crosstalk Test

Error Code	Test Result	Description/ Recommendation
1000	ABORT	System resources required to run this test are not available. The port may be busy with a valid call. Use the <b>display port PCSSpp</b> command to determine the station extension or trunk group/member number of the port. Use the <b>status bri-port PCSSpp</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. Wait until the port is idle before retesting. <ol style="list-style-type: none"><li>1. If the port status is idle, then retry the command at 1-minute intervals a maximum of 5 times.</li></ol>

*Continued on next page*

Table 5-456. TEST #617 NPE Crosstalk Test — Continued

Error Code	Test Result	Description/ Recommendation
1004	ABORT	The port has been seized by a user for a valid call. Use the <b>status bri-port</b> command to determine when the port is available for testing. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
1005	ABORT	This test is not valid for this type of translation. Ports administered as "ASAI" or "ADJK" cannot run this test, because the B channels associated with the port are not used by ASAI or Lucent Adjunct Links. This is a normal condition.
2012	ABORT	Internal system error
2100	ABORT	Could not allocate the necessary resources to run this test. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
1, 2	FAIL	The NPE of the tested port was found to be transmitting in error, causing noisy and unreliable connections. Error code 1 indicates that the NPE Crosstalk Test failed on Channel B1. Error code 2 indicates that the NPE Crosstalk Test failed on Channel B2. <ol style="list-style-type: none"><li>1. Replace circuit pack.</li></ol>
	PASS	The port is correctly using its allocated time slots. <ol style="list-style-type: none"><li>1. To be sure that this is not an intermittent problem, repeat this test a maximum of 10 times to ensure it continues to pass.</li><li>2. If complaints still exist, examine the connections and wiring.</li></ol>

## BRI Port Local LAN Looparound Test (#618)

### This test is destructive.

This test checks the connectivity of the BRI port across the LAN bus. Because this test is destructive, run this test only if the port is out-of-service.

Failures of this test indicate either on-board faults associated with the TBRI-PT hardware on the circuit pack or problems with the LAN Bus, which is used to form connectivity between the switch and the TBRI-PT.

If the port is in a state other than out-of-service, the BRI Port Local LAN Looparound Test will abort. If the port is out-of-service, then the port is put into a local looparound mode and the following test is executed.

A looparound test is performed across the bus for the D-Channel. The switch sends data over a packet connection, which is looped back by the BRI port (D-Channel) and received back by the switch. The test passes if the packet connection can be established and the transmitted data is received unaltered. The test aborts if the bus is alarmed in the Processor Port Network (or the port network in which that circuit pack resides) or if the Packet Interface is out-of-service. The test fails due to either on-board faults associated with the BRI port hardware on the circuit pack or problems with the bus.

Table 5-457. TEST #618 BRI Port Local LAN Loop Around

Error Code	Test Result	Description/ Recommendation
1015	ABORT	<p>The port is not out-of-service.</p> <ol style="list-style-type: none"> <li>1. Use the <b>status bri-port PCSSpp</b> command to determine the status of the port.</li> <li>2. If it is in use, wait until it is idle, and then use the <b>busyout port PCSSpp</b> command to place it in the out-of-service state and repeat this test.</li> </ol> <p> <b>CAUTION:</b> <i>Since the busyout command is destructive, execution of this command prior to the port being idle causes all calls associated with the BRI port to be torn down.</i></p>
1141	ABORT	<p>The PKT-INT is out-of-service.</p> <ol style="list-style-type: none"> <li>1. Follow the repair procedures for the PKT-INT.</li> <li>2. Run the <b>test port long PCSSpp</b> command and verify the repair by viewing the results of the BRI Port Local LAN Looparound Test (#618).</li> </ol>
2012 2100	ABORT	<p>Internal System Error. Could not allocate the necessary system resources to run this test.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
	FAIL	<p>The Looparound Test failed.</p> <ol style="list-style-type: none"> <li>1. If the test fails repeatedly, attempt to reset the circuit pack with the <b>busyout board PCSS</b> and the <b>reset board PCSS</b> commands if the other ports on the board are not in use.</li> <li>2. If the test fails again, execute <b>test pkt P</b>.</li> <li>3. If the tests in Step 2 pass, the problem is local to the BRI board. Replace the trunk circuit pack.</li> </ol>
	PASS	<p>The BRI Port Local LAN Looparound Test passed.</p>

## BRI Port Local TDM Looparound Test (#619)

**This test is conditionally destructive.**

This test verifies the connectivity of a BRI port across the TDM Bus. It aborts if calls associated with the port are in progress. Failure of this test indicates an on-board fault associated with the port hardware on the circuit pack.

This Looparound Test runs the following individual tests on the two B-channels (B1 and B2) associated with the port:

- A Looparound Test across the TDM Bus for B1.
- A Conference Circuit Test for B1.
- A Looparound Test across the TDM Bus for B2.
- A Conference Circuit Test for B2.

The tests are run in the above order. If one fails, the remaining tests in the sequence are not executed, and the maintenance software returns an error code.

Table 5-458. TEST #619 BRI Port Local TDM Loop Around

Error Code	Test Result	Description/ Recommendation
1000	ABORT	<p>The system resources required to run this test are not available. The port may be busy with a valid call. Use the <b>display port PCSSpp</b> command to determine the trunk group/member number of the port. Use the <b>status bri-port PCSSpp</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. Wait until the port is idle before retesting.</p> <ol style="list-style-type: none"> <li>1. If the port is idle, then retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
1002	ABORT	<p>The system could not allocate time slots for the test. The system may be under heavy traffic conditions or it may have time slots out-of-service due to TDM-BUS errors. Refer to <a href="#">"TDM-BUS (TDM Bus)" on page 5-1116</a> to diagnose any active TDM Bus errors.</p> <ol style="list-style-type: none"> <li>1. If the system has no TDM-BUS errors and is not handling heavy traffic, repeat test at 1-minute intervals a maximum of 5 times.</li> </ol>
1003	ABORT	<p>The system could not allocate a tone receiver for the test.</p> <ol style="list-style-type: none"> <li>1. Look for TTR-LEV errors in the Error Log and if present, refer to <a href="#">"TTR-LEV (TTR Level)" on page 5-1223</a>.</li> <li>2. Look for TONE-PT errors in the Error Log and if present, refer to <a href="#">"TONE-PT (Tone Generator)" on page 5-1204</a>.</li> <li>3. If neither condition exists, retry the test at 1-minute intervals a maximum of 5 times.</li> </ol>

Table 5-458. TEST #619 BRI Port Local TDM Loop Around — *Continued*

Error Code	Test Result	Description/ Recommendation
1004	ABORT	The port has been seized by a user for a valid call. Use the <b>status trunk</b> command for the trunks associated with this port and determine when the port is available for testing.  1. Retry the command at 1-minute intervals a maximum of 5 times.
1005	ABORT	This test is not valid for this type of translation. Ports administered as ASAI or ADJK cannot run this test because the B channels associated with the port are not used by ASAI or Lucent Adjunct Links. This is a normal condition.
2000	ABORT	Response to the test was not received from the BRI-LINE circuit pack within the allowable time period.  1. .If the test fails repeatedly, attempt to reset the circuit pack with the <b>busyout board PCSS</b> and the <b>reset board PCSS</b> commands if the other ports on the board are not in use.  2. If this result occurs again, replace the circuit pack.
2012	ABORT	Internal system error
2100	ABORT	Could not allocate the necessary resources to run this test.  1. Retry the command at 1-minute intervals a maximum of 5 times.
2103	ABORT	The system could not make the conference connection for the test.  1. Retry the command at 1-minute intervals a maximum of 5 times.
1, 2, 7, 8	FAIL	The TDM Looparound failed on one of the channels. <ul style="list-style-type: none"> <li>■ Error Code 1 — TDM Loop Around Test failed on B1.</li> <li>■ Error Code 2 — TDM Loop Around Test failed on B2.</li> </ul> The Conference Circuit Test failed on a B-channel. <ul style="list-style-type: none"> <li>■ Error Code 7 — test failed on B1</li> <li>■ Error Code 8 — test failed on B2.</li> </ul> 1. If the test fails repeatedly, attempt to reset the circuit pack with the <b>busyout board PCSS</b> and the <b>reset board PCSS</b> commands if the other ports on the board are not in use.  2. If the test fails again, replace the circuit pack.
	PASS	The BRI Port Local TDM Loop Around Test passed.

**CRC Error Counter Test (#623)**

This test is non-destructive. This test reads the BRI port's CRC error counters that are maintained on the BRI circuit pack. The Cyclic Redundancy Check (CRC) is a means of error detection used to determine the integrity of data frame contents. The CRC error counter is incremented by the circuit pack when it detects a CRC error. The test passes if the value of the counter is 0 (that is, the error is cleared). If the counter is non-zero, the test fails, and the value of the counter is displayed in the `Error Code` field.

**Table 5-459. TEST #623 CRC Error Counter Test**

<b>Error Code</b>	<b>Test Result</b>	<b>Description/ Recommendation</b>
ANY	FAIL	This error occurs when a frame with a bad CRC is received over the D-Channel by the BRI board. This error is reported on a per-port basis when the counter goes over the threshold. This error is most likely due to a problem with the wiring or interference on the wiring caused by a noise source or no termination. It usually does not indicate a problem with the circuit pack.
	PASS	The CRC error counter was read correctly and has a value of 0.

## Receive FIFO Overflow Error Counter Test (#625)

This test is nondestructive. This test reads and clears the BRI port's Receive FIFO Overflow error counter maintained on the TBRI-BD circuit pack. This counter is incremented by the circuit pack when it detects an overflow of its receive buffers. The test passes if the value of the counter is 0 (that is, the error is cleared). If the counter is non-zero, the test fails, and the value of the counter is displayed in the Error Code field.

This error can occur if signaling frames are being received from the Packet Bus at a rate sufficient to overflow the receive buffers on the circuit pack for a port OR if a hardware fault is causing the receive buffers not to be emptied properly by the circuit pack. This test is useful for verifying the repair of the problem.

Table 5-460. TEST #625 Receive FIFO Overflow  
Error Counter Test

Error Code	Test Result	Description/ Recommendation
2000	ABORT	Response to the test was not received from the circuit pack within the allowable time period. <ol style="list-style-type: none"> <li>1. If the test aborts repeatedly a maximum of 5 times, reset the circuit pack with the <b>busyout board PCSS</b> and <b>reset board PCSS</b> commands.</li> <li>2. If the test aborts again, replace the circuit pack.</li> </ol>
2012	ABORT	Internal system error
2100	ABORT	Could not allocate the necessary system resources to run this test. <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
value	FAIL	The TBRI-BD circuit pack is still detecting errors of this type. The Error Code field contains the value of this counter. <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> <li>2. If the test continues to fail, run the Long Test Sequence and pay particular attention to the Looparound Tests (#618 and #619). See the repair procedures for the executed test if it fails. Otherwise, go to the next step.</li> <li>3. Replace the circuit pack.</li> </ol>
	PASS	The Receive FIFO Overflow error counter was read correctly and has a value of 0.

## Level 1 Status Inquiry Test (#1242)

This test is nondestructive. This test determines the state of the transmission facility of a BRI port at the Level 1 (L1) physical layer: Activated, Pending Activation, or Deactivated.

The Activated state is the correct state for an ISDN-BRI port. In this state the L1 interface can send and receive synchronized signals. This test passes if the state of L1 is Activated. This test also passes if software has taken this port out of service. See the description of the L1 "Deactivated State" below for more details.

The Pending Activation state indicates a problem with the channels, the wiring, or the TBRI-BD circuit pack. When in this state, the Level 1 interface is either not receiving any L1 framing from the channel, or it is communicating with the channel or adjunct but cannot transition to the Activated state.

The Deactivated state indicates a problem with the TBRI-BD circuit pack. When in this state, the Level 1 interface is not active, and an idle signal is transmitted to the channels or that Layer 1 was deactivated by the switch. When an TBRI-PT port is placed in the out-of-service state, Level 1 is also put into the Deactivated state. This could be due either to the system detecting a fault with the port or to a **busyout port PCSSpp** request.

Table 5-461. TEST #1242 Level 1 Status Inquiry

Error Code	Test Result	Description/ Recommendation
1187	ABORT	<p>The board or port may have been busied out.</p> <ol style="list-style-type: none"> <li>1. Look in the Error Log for Error Type 18 (port busied out) for this port and TBRI-BD (board busied out). If this error type is present for TBRI-PT only, then release the port with the <b>release port pp</b> command and run the test again. If the error is present for both TBRI-BD and TBRI-PORT, then release the board with the <b>release board PCSS</b> command and run the test again.</li> </ol> <p> <b>NOTE:</b> When you release a board, you release all ports associated with it. If certain ports still need to be busied out, use the <b>release port PCSSpp</b> command to busy out each port.</p> <ol style="list-style-type: none"> <li>2. Make sure the end point is connected.// What terminal, connected to what//</li> <li>3. Retry the command at 1-minute intervals a maximum of 5 times // Then what?.</li> </ol>

*Continued on next page*

Table 5-461. TEST #1242 Level 1 Status Inquiry — Continued

Error Code	Test Result	Description/ Recommendation
2000	ABORT	Response to the test was not received from the circuit pack within the allowable time period. <ol style="list-style-type: none"><li>1. If the test aborts repeatedly a maximum of 5 times, reset the circuit pack with the <b>busyout board PCSS</b> and <b>reset board PCSS</b> commands.</li><li>2. If the test aborts again, replace the circuit pack.</li></ol>
2012	ABORT	Internal system error
2100	ABORT	Could not allocate the necessary system resources to run this test. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
1	FAIL	Received a status of Level 1 Pending Activation. U interface down indicating a problem with a connection between the switch and the NT1, a 2- to 4-wire converter that is used to connect 4-wire terminals to a 2-wire TN2198 or TN2185 circuit pack. <ol style="list-style-type: none"><li>1. Verify that the connections between the switch and the NT1 are good. Verify that the NT1 has power.</li><li>2. Execute the <b>test port PCSSpp</b> command and review the results of the Level 1 Status Inquiry Test to verify the repair. If this test still fails, proceed to Step 3.</li><li>3. Follow the manufacturers repair procedures for the NT1. Then execute the <b>test port PCSSpp</b> command and review the results of the Level 1 Status Inquiry Test to verify repair.</li></ol>
2	FAIL	Received a status of Level 1 Pending Activation. U interface up, S/T interface down, which indicates a problem with the NT1 or the wiring between the NT1 and the BRI endpoint (S/T interface). <ol style="list-style-type: none"><li>1. Execute the <b>test port PCSSpp</b> command and review the results of the Level 1 Status Inquiry test to verify the repair. If this test still fails, proceed to Step 2.</li><li>2. Follow the manufacturer-recommended repair procedures for the NT1. Then execute the <b>test port PCSSpp</b> command and review the results of the Level 1 Status Inquiry test to verify repair.</li></ol>

*Continued on next page*

Table 5-461. TEST #1242 Level 1 Status Inquiry — Continued

Error Code	Test Result	Description/ Recommendation
3	FAIL	<p>Received a status of Level 1 Deactivated; the port is out-of-service.</p> <ol style="list-style-type: none"><li>1. Issue the <b>status bri-port PCSSpp</b> command to verify that the service state of the port is out-of-service. If the service state of the port is not out-of-service, proceed to Step 2.</li><li>2. If the port has been placed out-of-service with the <b>busyout port PCSSpp</b> command, try releasing the port by executing the <b>release port PCSSpp</b> command. Then issue the <b>test port long PCSSpp</b> command and review the results of Level 1 Status Inquiry test. If this test still fails, proceed to Step 3.</li><li>3. After executing the <b>test port long PCSSpp</b> command, review the results of all the tests. Follow the repair procedures for any tests that fail. Verify repair of the problem by executing the <b>test port PCSSpp</b> command and by determining that the Level 1 Status test passes.</li></ol>
4	FAIL	<p>Received a status of Level 1 Pending Activation, the NT1 has a loss of power indicating a problem with the NT1.</p> <ol style="list-style-type: none"><li>1. Follow the manufacturer-recommended repair procedures for the NT1.</li><li>2. Execute the <b>test port PCSSpp</b> command and review the results of the Level 1 Status Inquiry test to verify the repair.</li></ol>
	PASS	<p>This test indicates that Level 1 is activated or that software has taken the port out of service.</p>

### Layer 3 Query Test (#1243)

This test is nondestructive. This test is used to check the application layer communications across the in-service ISDN D-Channel. The test passes if a status enquiry message was successfully sent, fails if the signaling link is down, and aborts if a query is already running or there is an internal error.

Table 5-462. TEST #1243 Layer 3 Query

Error Code	Test Result	Description/ Recommendation
1019	ABORT	Test is already running.
1113	ABORT	<p>The signaling link is down.</p> <ol style="list-style-type: none"> <li>1. Use the <b>test port PCSSpp long</b> command to clear any errors which prevent establishment of the signaling link.</li> <li>2. Examine the results of Test #626, which is executed with the command. If this test aborts or fails, follow the repair procedure for the Signaling Link Status Test.</li> </ol>
1141	ABORT	<p>The PKT-INT is out-of-service.</p> <ol style="list-style-type: none"> <li>1. Consult the repair procedure for PKT-INT.</li> </ol>
1187	ABORT	<p>The circuit pack or port may have been busied out by a technician.</p> <ol style="list-style-type: none"> <li>1. Look in the Error Log for Error Type 18 (busied out) for TBRI-BD or TBRI-PT. <ol style="list-style-type: none"> <li>a. If this error type is present for TBRI-PT, then release the port with the <b>release port PCSSpp</b> command, and run the test again.</li> <li>b. If the error is present for both TBRI-BD and TBRI-PT, then release the circuit pack with the <b>release board PPCSS</b> command and run the test again.</li> </ol> </li> </ol> <p> <b>NOTE:</b> When you release the circuit pack, you release all ports associated with it. If certain ports still need to be busied out, use the <b>release port PCSSpp</b> command to busy them out.</p> <ol style="list-style-type: none"> <li>2. Make sure the endpoint is connected.</li> <li>3. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
2012	ABORT	Internal system error
2100	ABORT	<p>Could not allocate the necessary system resources to run this test.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
	PASS	The switch has successfully sent a Status Enquiry message.

## Slip Query Test (#1244)

This test is non-destructive. Slips occur when the transmitter and receiver are not running at precisely the same clock rate. The Slip Alarm Inquiry Test polls the total number of slips that have occurred on a link.

When the TN2185 circuit pack detects a slip condition, maintenance software initiates the Slip Alarm Inquiry Test to query the slip counters on the TN2185 circuit pack and total the slip counts in the maintenance software.

If the slip count is over the threshold, a Minor alarm is raised against the TN2185 circuit pack, leaving all ports of the TN2185 circuit pack in the in-service state. If the TN2185 circuit pack is used to supply the system synchronization source, the MINOR alarm will initiate a synchronization source switch. See TDM-BUS and SYNC for additional information.

Table 5-463. TEST #1244 Slip Alarm Inquiry Test

Error Code	Test Result	Description/ Recommendation
2000	ABORT	Internal System Error
	ABORT	Response to the test request was not received within the allowable time period. If Error Type 1538 is present in the Error Log, follow the maintenance strategy recommended for this error type.
2100	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals for a maximum of 5 times.
1 to 88	FAIL	The circuit pack and the remote endpoint are not synchronized to the same clock rate, which has generated the Slip alarm. The error code equals the number of slips detected by the TN2185 circuit pack since the last Slip Alarm Inquiry Test. 1. Retry the command at 1-minute intervals a maximum of 5 times. 2. If the circuit pack is a TN2185, enter the <b>list measurement ds1-log PCSS</b> command to read the error seconds measurement. 3. Verify that both endpoints of the DS1 link are administered using the same signaling mode, framing mode, and line coding. 4. Check the physical connections of DS1 Interface circuit packs and cable. 5. Replace the local DS1 Interface circuit pack and repeat the test. 6. Contact T1 Network Service to diagnose the remote DS1 endpoint.
	PASS	No Slip alarm is detected on the DS1 Interface circuit pack.
0	NO BOARD	The DS1 Interface circuit pack is not administered. 1. Administer the DS1 Interface circuit pack by issuing the <b>add ds1 PCSS</b> command. 2. Run the test again.

## TBRI-TRK (TN2185 ISDN Trunk-Side BRI)

---

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run <sup>1</sup>	Full Name of MO
TBRI-TRK <sup>2</sup>	MAJOR <sup>3</sup>	test trunk PCSSpp l	MO_TBRI_TRK
TBRI-TRK	MINOR	test trunk PCSSpp l	MO_TBRI_TRK
TBRI-TRK	WARNING	test trunk PCSSpp sh	MO_TBRI_TRK

1. Where P is the port network number (1); C is the carrier designation (for example, A, B, or C); and SS is the address of the slot in the carrier where the circuit pack is located (for example, 01, 02, and so forth).
2. For additional repair information, also see TBRI-BD and TBRI-PT Maintenance Object documentation.
3. A MAJOR alarm on a trunk indicates that alarms on these trunks are not downgraded by the **set options** command and that at least 75 percent of the trunks in this trunk group are alarmed.

The TN2185 circuit pack contains eight, 4-wire ports that interface to the network at the ISDN S/T reference point over two 64 Kb/s channels (B1 and B2) and over a 16Kb/s signaling (D) channel. The B1 and B2 channels can be simultaneously circuit switched, or individually packet switched. Only one channel per trunk can be packet switched due to Packet Processing Element (PPE) limitations. The D channel is either circuit switched or packet switched. Packet switching uses the PPE to combine all D channels into a single physical channel, which is then routed via the concentration highway to the Network Control Element (NCE) and then to the TDM bus. The circuit-switched connections have a Mu-law or A-law option for voice and operate as 64Kb/s clear data channels. The packet-switched channels support the LAPD protocol and conform with the CCITT Q.920 Recommendations for D-channel signaling.

### LEDs

The three LEDs on the circuit pack's faceplate indicate board status. When illuminated, the red LED indicates a board failure or a major or minor on-board alarm, the green LED indicates that testing is in progress, and the amber LED indicates that the board is in use.

## Hardware Error Log Entries and Test to Clear Values

---

Table 5-464. TBRI-TRK Error Log Entries

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
0 <sup>1</sup>	0	Any	Any	Any	test Port UCSSPP sh r 1
513 (a)		Service State Audit (Test #256)	WARNING	OFF	
1793 (b)	8, 9		WARNING	OFF	
3073 (c)		Service State Audit (Test #256)			
3585 (d)					
3841 (e)			WARNING	OFF	

---

1. Run the Short Test Sequence first. If all tests pass, run the Long Test Sequence. Refer to the appropriate test description and follow the recommended procedures.

### Notes:

- a. The far-end has reported that this channel is not administered. The trunks are placed in the out-of-service state.
  - b. The Signaling link is down. See the following Aux Data explanation:
    - Aux data 8 indicates the Signaling Link is down.
    - Aux data 9 indicates the Port is out of service.
  - c. The Service State Audit failed. The test will be run every 15 minutes until it passes.
  - d. Unexpected Restart message; this error causes no action and is logged only.
  - e. B-Channel Rejection Event; this action causes the Service State Audit, the Call State Audit, and the Test Call Audit to be executed.
-

## System Technician-Demanded Tests: Descriptions and Error Codes

---

Always investigate tests in the order presented in the table below when inspecting errors in the system. By clearing error codes associated with the *Services State Test*, for example, you may also clear errors generated from other tests in the testing sequence.

Order of Investigation	Short Test Sequence	Long Test Sequence	D/ND <sup>1</sup>
Signaling Link State Check Test (#1251)	X	X	ND
Service State Audit Test (#256)	X	X	ND
Call State Audit Test (#257)	X	X	ND
ISDN Test Call Test (#258)		X	ND

---

1. Destructive; ND = Nondestructive

### Signaling Link State (#1251)

---

This test is nondestructive. This test checks the current state of the signaling link. The test looks at the board-level translations, checks that the board is physically inserted, gets the state of the D-Channel and service state of the port.

The test passes if the signaling link (D-Channel) is connected and operating normally. The test fails if the board is not installed, the signaling link is disconnected, or if the port is out of service. The test aborts otherwise.

Table 5-465. TEST #1251 Signaling Link State Test

Error Code	Test Result	Description/ Recommendation
	ABORT	Internal system error
1018	ABORT	The test is disabled. 1. Enable the test by entering <b>enable test #1251</b> .
1114	ABORT	The signaling link is in a transitional state. 1. Retry the command at 1-minute intervals a maximum of 5 times.
8	FAIL	The signaling link is down. 1. Consult the procedures for the TBRI-PT maintenance object.

---

Continued on next page

Table 5-465. TEST #1251 Signaling Link State Test — *Continued*

Error Code	Test Result	Description/ Recommendation
9	FAIL	The port is out of service. 1. Return the port too an in service state.
	PASS	The signaling link is connected and operating normally.

### Service State Audit (#256)

This test is nondestructive. This test performs a service state audit on an ISDN B-Channel. The test passes if Call Processing informs Maintenance that the Restart message was transmitted successfully, or if the B-Channel was busy and could not send the message.

The test fails if the board is not inserted or translated properly, or if a reply is not received within a certain amount of time.

The test aborts if the signaling link is disconnected, if a message is already outstanding, or if the necessary resources could not be allocated. Maintenance will take no action if the test aborts.

To investigate the service state of the TN2185 ISDN Trunk-Side BRI Channel, issue the **status trunk trunk-group/trunk-member** command.

Table 5-466. TEST #256 Service State Audit Test

Error Code	Test Result	Description/ Recommendation
1000	ABORT	System resources required to run this test are not available. The port may be on a valid call. Use <b>status trunk</b> to determine when the trunk is available for testing. 1. Check the results of Test #1251 (Signaling Link State Check).
1018	ABORT	The test is disabled. 1. Enable maintenance by entering <b>y</b> in the Maintenance Tests? field on page 2 of the <b>change trunk-group</b> form.
1113	ABORT	The signaling link has failed, so the system cannot send any messages on behalf of this trunk. 1. Check the results of Test #1251 (Signaling Link State Test).

*Continued on next page*

Table 5-466. TEST #256 Service State Audit Test — *Continued*

Error Code	Test Result	Description/ Recommendation
1114	ABORT	The signaling link is in a transitional state. 1. Retry the command at 1-minute intervals a maximum of 5 times.
1116	ABORT	The trunk is not in a service state which is appropriate for running the test. This test is only performed in the OOS/FE state.
1117	ABORT	A service state audit message is outstanding. 1. Wait two minutes and then try again.
2100	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals a maximum of 5 times.
	FAIL	Internal System Error. 1. Retry the command at 1-minute intervals a maximum of 5 times.
	PASS	Wait 4 minutes and then check the Error Log for any new errors of type 3073. If there are none, then both sides of the ISDN connection agree on the service state; the negotiation succeeded. If there is a new 3073 error, then the negotiation failed (the far-end switch twice failed to respond within 2 minutes). The switch automatically retries every 15 minutes. If the trunk was initially in-service, it is now placed in the maintenance/far-end state. Incoming calls will be accepted, but no outgoing calls can be originated. If an incoming call is presented, another Service State Audit is immediately performed in an attempt to put the TN2185 ISDN Trunk-Side BRI Channel in the proper state.

## Call State Audit Test (#257)

---

This test is nondestructive. This test performs a call state audit on an ISDN B-Channel, and upon successful completion, guarantees that both sides of the interface are in a consistent call state for connections using the B-Channel. The test can be helpful when trying to clear a hung call. If the internal call state data to the near-end switch is different from that of the far-end switch, *the call will be torn down.*

The test passes if the audit is successful.

The test fails if the board is not inserted, there is an internal system error, or if a reply was not received within a certain amount of time.

The test aborts if the signaling link is disconnected, the request is already active, or if the B-Channel is in an Out-Of-Service state.

Table 5-467. TEST #257 Call State Audit Test

Error Code	Test Result	Description/ Recommendation
1018	ABORT	The test is disabled. 1. Enable the test by entering <b>y</b> in the <code>Maintenance Tests?</code> field on page 2 of the <b>change trunk-group</b> form.
1019	ABORT	An audit is already in progress. 1. Wait two minutes and try again.
1113	ABORT	The signaling link has failed, so the system cannot send any messages on behalf of this trunk. 1. Check the results of Test #1251 (Signaling Link State Check).
1114	ABORT	The signaling link is in a transitional state. 1. Retry the command at 1-minute intervals a maximum of 5 times.
1116	ABORT	The trunk is in an out-of-service ISDN service state. 1. A call cannot be present if the trunk is in an ISDN out-of-service state, so a call state audit would be inappropriate. No action necessary. (Use the <b>status trunk</b> command.)
2100	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals a maximum of 5 times.
	FAIL	Internal system error 1. Retry the command at 1-minute intervals a maximum of 5 times.
	PASS	The audit passed successfully.

---

## ISDN Test Call Test (#258)

This test performs a far-end loop around to a far-end switch over an ISDN trunk. The trunk's service state must be in-service, maint-NE, or out-of-service/NE, and no call can be active on the trunk.

A test call connection is established to a far-end switch over the ISDN trunk to be tested. The digital port on a TN711D Maintenance/Test circuit pack generates a test-pattern bit stream which is sent to the far-end switch and echoed back. The received pattern is then compared to the sent pattern and checked for errors that indicate a loss of integrity on the communications path.

If a test call is running when scheduled maintenance starts, the green LED is turned off. To determine if a test call is still running, use the **list isdn-testcall** and **status isdn-testcall** commands. A lit yellow LED on the Maintenance/Test circuit pack also indicates that a test call is running.

There are two methods available to place an outgoing ISDN Trunk-side BRI trunk test call:

1. The test call connection is established over the TDM Bus of the transmit and receive sides of the ISDN Trunk-side BRI trunk to a data channel.
2. The test call connection is established over the TDM Bus of the transmit and receive sides of the ISDN Trunk-side BRI trunk to a digital trunk testing port on the Processor circuit pack. The Processor Digital Port generates a pseudo bit stream.

A test is run periodically to check if the call is hung. If so, it gracefully tears down the call to release the resources.

### Synchronous Commands

You can demand a synchronous outgoing test call by using the following maintenance commands:

- **test trunk trunk-group-no/member-no long [repeat number]**
- **test board board-location long [repeat number]**
- **test port port-location long [repeat number]**

Whenever a circuit translates to an ISDN Trunk-side BRI trunk during a Long Test Sequence, an outgoing test call is invoked, and the duration of the test call is 8.6 seconds. The outgoing ISDN Trunk-side BRI trunk test call is established over a high speed data channel on the Processor circuit pack (DATA-BD). A bit error rate greater than zero is reported as a failure to the Manager I terminal (MGRI). A failure indicates the need to run further diagnostics.

## Asynchronous Commands



## NOTE:

Only one trunk can be tested in a given port network, until the test call is canceled or completes.

Table 5-468. TEST #258 ISDN TEST Call

Error Code	Test Result	Description/ Recommendation
4	ABORT	There is a problem with the Processor Interface Link. 1. Refer to <a href="#">“PKT-INT (Packet Interface)” on page 5-958</a> .
1004	ABORT	B channel in use. 1. Determine if a call is active on this ISDN Trunk-side BRI trunk with the <b>status trunk</b> command. 2. When the service state indicates in-service/idle, retry the test.
1005	ABORT	Bad Configuration (that is, no Maintenance/Test circuit pack) Issue the <b>test trunk trunk group/trunk member</b> command and make sure there is a DATA-CHL administered.
1018	ABORT	Test call is disabled. 1. Enable Maintenance on the Trunk Group form.
1024	ABORT	(M/T-DIG) Maintenance/Test Digital Port in use. 1. Wait until yellow and green LEDs are turned off on the M/T-BD (Maintenance/Test circuit pack). 2. Retry the test. If problem persists, refer to M/T-DIG (Maintenance/Test Digital Port) Maintenance documentation.
1113	ABORT	The signaling link has failed. Therefore, the system cannot send any messages on behalf of this trunk. 1. Check the results of Test #1251 (Signaling Link State Check Test).
1114	ABORT	The signaling link is in a transitional state. 1. Retry the command at 1-minute intervals a maximum of 5 times.
1116	ABORT	The switch could not appropriately change the ISDN service state. 1. Determine if a call is active on this ISDN Trunk-side BRI trunk (use the <b>status trunk</b> ) 2. If not, check the Error and Alarm Logs for problems with this TBRI-TRK MO.
1117	ABORT	ISDN B-channel maintenance message is already outstanding. 1. Wait two minutes. Then try again.

*Continued on next page*

Table 5-468. TEST #258 ISDN TEST Call — *Continued*

Error Code	Test Result	Description/ Recommendation
1118	ABORT	Far-end of ISDN trunk is not administered. <ol style="list-style-type: none"> <li>1. Check the administration of the far-end ISDN trunk.</li> <li>2. Issue the <b>status trunk</b> command.</li> <li>3. Try the test again.</li> </ol>
1119	ABORT	The test call was aborted due to a normal call attempt on this trunk. The test call is performed only if the trunk is idle. <ol style="list-style-type: none"> <li>1. Either wait for the normal call to terminate normally, or force it to be dropped by using the <b>busyout trunk</b> command.</li> </ol>
1120	ABORT	The ISDN Trunk-side BRI trunk is in the ISDN out-of-service/far-end state. <ol style="list-style-type: none"> <li>1. Try to change the service state via Test #256 (Service State Audit Test). Then retry this test. <b>However, the trunk may be in the out-of-service/far-end state due to problems at the far-end switch. If that is the case, no remedial action can be taken at this end.</b></li> </ol>
1122	ABORT	There is no test line number for the far-end switch. <ol style="list-style-type: none"> <li>1. Check the Trunk Group Administration form.</li> </ol>
1123	ABORT	There is no Feature Access Code administration for this Facility Test. <ol style="list-style-type: none"> <li>1. Check the Dial Plan and Feature Administration forms.</li> </ol>
2012 None 2000	ABORT	Internal System Error. <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
2035	ABORT	The call has timed out, perhaps because of a lack of system resources. <ol style="list-style-type: none"> <li>1. Wait 1 minute and try again.</li> </ol>
2036 2037	ABORT	Internal System Error. <ol style="list-style-type: none"> <li>1. Follow the recommendation for ABORT code 2012.</li> </ol>
2038 2039	ABORT	A problem occurred while trying to read the test data. <ol style="list-style-type: none"> <li>1. Wait one minute and then try again.</li> <li>2. If the test aborts again in the same manner, there is a serious internal problem.</li> </ol>
2040	ABORT	Internal System Error. <ol style="list-style-type: none"> <li>1. Follow the recommendations for ABORT code 2012.</li> </ol>
2041	ABORT	The call has timed out, perhaps because of a lack of system resources. <ol style="list-style-type: none"> <li>1. Follow the recommendations for ABORT code 2035.</li> </ol>
2066	ABORT	Could not establish test call. <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>

*Continued on next page*

Table 5-468. TEST #258 ISDN TEST Call — *Continued*

Error Code	Test Result	Description/ Recommendation
2067	ABORT	The call has timed out, perhaps because of a lack of system resources. 1. Follow the recommendations for ABORT code 2035.
2074	ABORT	Bit and Block Error query failed. 1. Retry the command at 1-minute intervals a maximum of 5 times. 2. If the test continues to abort, there may be a serious internal problem with M/T-DIG (Maintenance/Test Digital Port). If this is the case, refer to the M/T-DIG (Maintenance/Test Digital Port) Maintenance documentation.
2075	ABORT	Internal System Error. 1. Follow the recommendations for ABORT code 2012.
2100	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals a maximum of 5 times.
2104	ABORT	Call dropped or could not be originated. 1. Make sure service is provisioned by the network. 2. Check the administration of the far-end test line extension on the trunk group administration form. 3. Check the administration of the test call BCC (Bearer Capability Class) on the trunk group administration form. 4. Try the test again.
2201 2202 2203 2204 2205	ABORT	Internal System Error. 1. Follow the recommendations for ABORT code 2012.
2206	ABORT	Could not allocate the necessary system resources to run this test. 1. Follow the recommendations for ABORT code 2100.
2208	ABORT	Internal System Error. 1. Follow the recommendations for ABORT code 2012.
2209 2210	ABORT	Could not allocate the necessary system resources to run this test. 1. Follow the recommendations for ABORT code 2100.
2211	ABORT	Internal System Error. 1. Follow the recommendations for ABORT code 2012.
2212	ABORT	Call terminated by unexpected disconnect. 1. Wait one minute and then try again.

*Continued on next page*

5 Maintenance Objects for DEFINITY ONE  
TBRI-TRK (TN2185 ISDN Trunk-Side BRI)

5-1115

Table 5-468. TEST #258 ISDN TEST Call — *Continued*

Error Code	Test Result	Description/ Recommendation
2213	ABORT	The call has timed-out, perhaps because of a lack of system resources. 1. Follow the recommendations for ABORT code 2035.
2214	ABORT	Call terminated by unexpected disconnect. 1. Wait one minute and then try again.
2215 2216 2217 2218 2219	ABORT	Internal System Error. 1. Follow recommendations for ABORT code 2012.
2220	ABORT	Call terminated prematurely. 1. Wait one minute and try again.
2221 2222 2223 2224 2225 2226	ABORT	Internal System Error. 1. Follow recommendations for ABORT code 2012.
2227	ABORT	Could not allocate the necessary system resources to run this test. 1. Follow the recommendations for ABORT code 2100.
2042	FAIL	<b>This is the main purpose of the test.</b> The comparison of the data sent with the data received indicates a loss of integrity on the communications path.  1. The trunk should be taken out-of-service and the quality of the ISDN Trunk-side BRI line should be investigated. The investigation should include an in-depth analysis of the facility including the transmission facility and any external equipment such as DACs, CSUs, etc.
	PASS	The call worked. A test pattern was sent and received properly; the communications path is OK if the synchronous test call command was issued. An in-depth analysis of the ISDN Trunk-side BRI trunk facility including the transmission facility and any external equipment such as DACs, CSUs, and others should take place if the bit and block error rates are not acceptable.

## TDM-BUS (TDM Bus)

---

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run	Full Name of MO
TDM-BUS	MAJOR	test tdm P	TDM Bus
TDM-BUS	MINOR	test tdm P	TDM Bus
TDM-BUS	WARNING	test tdm P	TDM Bus

The TDM Bus consists of a duplicated TDM Bus on each port network: TDM Bus A and TDM Bus B. Each TDM Bus consists of 256 time slots. The first five time slots on each bus are called the Control Channel. The Control Channel is active on only one bus at a time in each Port Network. The next 17 time slots are reserved for dedicated tones (that is, dial tone). These time slots are called the dedicated tone time slots and only one bus at a time carries the dedicated tones. The rest of the time slots on each bus are for general system use (that is, phone call).

On system initialization, the Control Channel is on TDM Bus A and the dedicated tones on TDM Bus B in each Port Network.

Terminology:

- Control Channel Bus - The TDM Bus control channel is on.
- Non-Control Channel Bus - The TDM Bus control channel is NOT on.
- Tone Bus - The TDM Bus dedicated tone time slots are on.
- Non-Tone Bus - The TDM Bus dedicated tone time slots are NOT on.

### TDM Bus Fault Detection and Isolation Procedure

---

TDM Bus faults are most likely caused by a defective circuit pack connected to the backplane or bent pins on the backplane. It is possible that a circuit pack can cause a TDM Bus fault but still exhibit trouble-free operation. For example, the insertion of an MBUS (Memory Bus) only circuit pack can bend the TDM Bus pins on the backplane and short two leads together. Since the TDM Bus is a shared resource, automatic identification of the cause of a TDM Bus fault is difficult. If a TDM Bus problem is suspected, the system technician should run the **test tdm P** system technician command. If any of the resulting tests fail, then the system technician must manually perform a TDM Bus isolation procedure to identify the cause of the problem.

#### **WARNING:**

*Since the TDM Bus fault isolation procedure involves removing circuit packs and possibly disconnecting entire carriers, the procedure is extremely destructive to the port network that contains the TDM Bus being tested. If possible, this procedure should be used after hours or during hours with minimum system use.*

**5** Maintenance Objects for DEFINITY ONE  
TDM-BUS (TDM Bus)

5-1117

As circuit packs are removed or entire carriers are disconnected, any active calls terminating on those circuit packs or carriers are dropped. If the system technician has any hints about a particular circuit pack that may be causing the TDM Bus problem (for example, a new circuit pack was inserted into the Port Network just before the TDM Bus problem appeared), then those hints should be investigated before performing this procedure.

For this procedure, make sure at least one Tone Detector circuit pack is in the same Port Network in which the TDM Bus fault is being isolated. The Tone Detector circuit pack is needed by maintenance to test the TDM Bus.

**Procedure 1**

This procedure is an attempt to isolate the TDM Bus fault to circuit packs that are essential to the system operation. For each of the following circuit packs, perform Procedure 1.

<b>Circuit Pack</b>	<b>Error Log Names</b>
Tone-Clock	TONE-BD, TONE-PT, and TDM-CLK
Network Control	SW-CTL
Tone Detector	DETR-BD, GPTD-PT, and DTMR-PT

1. Display the Hardware Error and Alarm Logs for the circuit pack via the **display errors** and **display alarms** commands.
2. If there are errors for the circuit pack, refer to its Maintenance documentation and try to resolve the errors.
3. Whether or not all the errors can be cleared, test the TDM Bus again via the **test tdm P** command.
4. If some TDM Bus tests fail, continue with the next circuit pack.
5. If there are no more circuit packs in the list, go to Procedure 2.
6. If all the TDM Bus tests pass, the problem has been fixed.

## Procedure 2

This procedure removes and re-inserts port circuit packs; one or several at a time.

If all of the TDM Bus tests pass when the circuit pack is removed, but some of the tests fail when the circuit pack is inserted, the circuit pack is the cause of the problem and should be replaced. If some of the tests fail regardless of whether the circuit pack is inserted or removed, the circuit pack is not the cause of the problem (see Note). Repeat this procedure for each purple slot circuit pack in the Port Network.

### NOTE:

Of course, in a multiple failure situation, the circuit pack may be one cause of the TDM Bus problem and there may be other failures that are causing TDM Bus faults. Also, the circuit pack itself may not be the cause of the problem, but the backplane pins may have been bent when the circuit pack was inserted.

1. Remove port circuit packs which have failed the NPE Crosstalk Test (#6) first. To find which circuit packs failed this test, display the Hardware Error Log via the **display errors** command. Refer to the Maintenance documentation of each port circuit pack that has port errors to check if any error indicates the failure of the NPE Crosstalk Test.
2. If no circuit pack failed the NPE Crosstalk Test (#6), remove one or several purple slot circuit packs.
3. Run the **test tdm P** command.
4. If any of the TDM Bus tests fail:
  - Check if the backplane pins in the removed circuit pack's slot appear to be bent.
  - If the backplane pins are bent, straighten or replace the pins, re-insert the circuit pack, and do this procedure again for the same circuit pack.
  - If the backplane pins are not bent, re-insert the circuit pack and do this procedure for the next set of circuit packs.
5. If none of the TDM Bus tests fail:
  - Re-insert the circuit pack.
  - Run the **test tdm** system technician command.
  - If any of the TDM Bus tests fail, the re-inserted circuit pack is faulty. Replace the circuit pack and do this procedure again for the new circuit pack.
  - If none of the TDM Bus tests fail, then the problem has been fixed.

### Procedure 3

Procedure 3 attempts to isolate the failure to a particular set of carriers, and then checks only the circuit packs in those carriers. This procedure involves terminating the TDM Bus so that certain carriers are disconnected from the TDM Bus. This is done by moving the TDM Bus terminators (AHF1) on the carrier backplane. To terminate a TDM Bus at the end of a particular carrier, the TDM Bus cable that connects the carrier to the next carrier should be unplugged and replaced with the TDM Bus terminator. The TDM Bus terminators can be taken from one carrier to the other. To get to the TDM Bus cables, remove the back cover of the cabinet. When the length of the TDM Bus is modified via this procedure, the circuit packs that are essential to system operation and TDM Bus maintenance (for example, Network Control circuit pack, Tone-Clock circuit pack, Tone Detector circuit pack) must still be connected to the new *shortened* TDM Bus.

### For the Processor Port Network (PPN)

1. Terminate the TDM Bus so that it extends within the control carrier.
2. Run the **test tdm** system technician command. If any of the TDM Bus tests fail, perform Procedure 2 and/or Procedure 3 for only the circuit packs in those carriers connected to the *shortened* TDM Bus. Procedure 2 is performed for port circuit packs (purple slots) and Procedure 3 for control carrier circuit packs.
3. If none of the TDM Bus tests fail, extend the TDM Bus to another carrier and repeat this procedure. When a carrier is added that causes some of the TDM Bus tests to fail, perform Procedure 2 and/or Procedure 3 for only the circuit packs in that carrier.

### Restarting Nonfunctioning Port Circuit Packs

A defective TDM Bus Control Channel or system timing reference on one of the networks can result in port circuit packs (that is non-control carrier circuit packs) on this defective network entering the reset state. When this situation occurs, the circuit pack stops functioning and its red LED lights. The system does not detect the presence of a circuit pack when the circuit pack is in the reset state. Hence, executing the **list config board PCSS** command indicates that the circuit pack is not present.

If a circuit pack enters the reset state when the control channel is on TDM Bus PT (where network P contains the circuit pack), this circuit pack stops functioning until it receives a restart message when the control channel is on the same TDM Bus PT or when this circuit pack is powered up again.

To force the system to send a restart message to all circuit packs on a network, try one of the following methods depending on the circumstances:



#### NOTE:

A circuit pack functioning normally (that is, not in the reset state) ignores the restart message.

### Procedure 1 (Nondestructive)

Execute the Idle Time Slot Test (#294) by issuing the command **test tdm P** when the control channel is on the same TDM Bus as it was when the circuit pack entered the reset state. If using this method is not feasible, try the other procedures in this section.

### Procedure 2 (Nondestructive)

**if you are at the site:** Reseat the circuit pack. This action causes the circuit pack that was in the reset state to begin functioning on the *current* Control Channel bus.

### Procedure 2 (Nondestructive)

Execute the Idle Time Slot Test (#294) by issuing the command **test tdm P** when the control channel is on the same TDM Bus as it was when the circuit pack entered the reset state. If using this method is not feasible, try the other procedures in the section.

### Procedure 3 (Destructive)

Reset the port network that contains the circuit pack that is in the reset state. When a network is reset, two restart messages, one on the control channel of each TDM Bus, are sent to each circuit pack on the network. Executing the **reset system L** command (where L=2, 3, 4, or 5) resets all networks in the system.



**WARNING:**

*The **reset system** command disrupts all calls in the system.*

### Procedure 4 (Destructive)

Execute the **recycle carrier PC** command where P is the Port Network Number of the network containing the circuit pack and C is the designation of the carrier containing the circuit pack.



**WARNING:**

*This command removes power and returns power to the designated Medium cabinet port carrier. Thus, any other circuit packs on this carrier is also temporarily taken out-of-service.*

## Error Log Entries and Test to Clear Values

Table 5-469. TDM Bus Error Log Entries

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
0 <sup>1</sup>	0	Any	Any	Any	test tdm
1	0	Control Channel Test (#296)	MINOR	ON	test tdm P r 3
18 (a)	0	busyout tdm PC	WARNING	ON	release tdm PC
35 (b)	0-1	TDM Bus Corruption	MINOR	ON	set tdm PC
257 (c)	0	none	MAJOR	ON	
513 (d)	Any	Idle Time Slot Test (#294)	MINOR	ON	test tdm P r 3
769 (e)	Any	Idle Time Slot Test (#294)	WARNING	ON	test tdm P r 3
769 (f)	Any	Idle Time Slot Test (#294)			(see Notes)
1025	Any				
3872 (g)	Any	none			
3873 (g)	Any	none			
3874 (g)	Any	none			
3877 (g)	Any	none			

1. Run the Short Test Sequence first. If all tests pass, run the Long Test Sequence. Refer to the appropriate test description and follow the recommended procedures.

**NOTE:**

For TDM-BUS, an ON-BOARD alarm refers to a problem with the TDM-BUS itself.

**Notes:**

- a. The TDM Bus has been busied out by the technician. The error retires when the technician releases the TDM Bus.
- b. This error indicates the TDM Bus is corrupted.

An Aux Data value of 0 indicates the last reported TDM Bus corruption was on the Control channel bus.

An Aux Data value of 1 indicates the last reported TDM Bus corruption was on the Non-Control channel bus.

If this error is logged on both TDM Buses (A and B) within two or three minutes, the red LED of several circuit packs may or may not be lit and there could be Switch Control errors. Under these circumstances do the following:

- Display the Hardware Error Log via the **display errors** command and look for SW-CTL (Switch Control) errors.
  - If there are any errors logged against the Switch Control, try to resolve them.
  - Test the TDM Bus via the **test tdm P** command.
  - If all the TDM Bus tests pass, the problem has been fixed.
  - Test the TDM Bus via the **test tdm P** command.
  - If all the TDM Bus tests pass, the problem has been fixed.
- c. This error indicates the TDM Bus was switched to the other bus due to TDM Bus corruption. The aux data value is not meaningful and no action is required.
- d. This error indicates that some time slots are corrupted in the specified TDM Bus. The Minor alarm is raised when there are more than 50 bad time slots in the bus. The aux data indicates the number of bad time slots found by the test.
- e. This error indicates that some time slots are corrupted in the specified TDM Bus. The Warning alarm is raised when there are more than 10 bad time slots but less than or up to 50 bad ones in the bus. The aux data value indicates the number of bad time slots found by the test.
- f. This error indicates the idle time slot test found less than 10 bad time slots in the TDM Bus. The aux data value indicates the number of bad time slots found by the test. There is no alarm associated with this error.
- g. These errors indicate communication problems. Test the TDM Bus via the **test tdm P** command and follow the procedures according to the error codes reported from the test.

The aux data value shows the Angel ID number for which a downlink message was lost.

---

## System Technician-Demanded Tests: Descriptions and Error Codes

Always investigate tests in the order presented in the table below when inspecting errors in the system. By clearing error codes associated with the *Control Channel Test*, for example, you may also clear errors generated from other tests in the testing sequence.

Order of Investigation	Short Test Sequence	Long Test Sequence	D/ND <sup>1</sup>
Control Channel Test on the Control Channel Bus (#296)	X	X	ND
Digit Detection Test on the Non-Control Channel Bus (#297)	X	X	ND
Idle Time Slot Test on TDM Bus A (#294)	X	X	ND

1. D = Destructive; ND = Nondestructive

### Idle Time Slot Test on TDM Bus A or B (#294)

The Idle Time Slot Test detects noisy time slots on the bus and takes them out-of-service. The Tone Detector circuit pack is told to listen to idle time slots and if it detects any noise on a time slot, it returns a failure. At the end of the test, any out-of-service time slots are retested to see if they are still noisy and restored to service if they are idle. After all the time slots have been tested, maintenance counts the number of bad time slots and reports the number to the technician in the error code field. No more than 220 time slots are taken out-of-service on one bus, and no more than 300 are taken out-of-service on both buses at one time.

Table 5-470. TEST #294 or #295 Idle Time Slot Test on TDM Bus A or TDM Bus B

Error Code	Test Result	Description/ Recommendation
none	ABORT	Could not allocate the necessary system resources to run this test. For example, maintenance could be running on the Tone Detector circuit pack and it is using the CPTRs.
1115	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals a maximum of 5 times.

*Continued on next page*

Table 5-470. TEST #294 or #295 Idle Time Slot Test on TDM Bus A or TDM Bus B — *Continued*

Error Code	Test Result	Description/ Recommendation
number	FAIL	<p>The error code indicates the number of bad time slots that were detected. The cause of this failure is most likely due to a bad port circuit pack and not the TDM Bus itself.</p> <ol style="list-style-type: none"><li>1. Execute the command again.</li><li>2. If the error persists, check the Error and Alarm Logs for alarms on port circuit packs from the NPE Crosstalk Test.</li><li>3. Refer to the appropriate circuit pack's documentation to clear the circuit pack's problem.</li><li>4. Test the TDM Bus again. If the error continues, refer to the <a href="#">"TDM Bus Fault Detection and Isolation Procedure"</a> described earlier.</li></ol>
	PASS	<p>The success of this test indicates all the idle time slots that are supposed to be idle are indeed idle. There is no noise on any of the idle time slots.</p>

## Control Channel Test (#296)

This test tests the integrity of the Control Channel bus. It ensures that communication through the TDM Bus is operational.

Table 5-471. TEST #296 Control Channel Test

Error Code	Test Result	Description/ Recommendation
any code other than 1005	ABORT	Internal system error  1. Retry the command at 1-minute intervals a maximum of 5 times.
1005	ABORT	Since this test is valid only on the control channel bus, it aborts execution when run on the non-control channel bus. This is a valid response. Use the <b>status system</b> command to verify which bus is the control channel bus.
none	FAIL	Communication through the Control Channel is not working. The problem is not necessarily the TDM Bus itself.  1. Display the hardware error and alarm log for the Tone-Clock circuit pack. Refer to TONE-BD (Tone-Clock Circuit Pack) Maintenance documentation.  2. Resolve the errors for the Tone-Clock circuit pack.  3. Display the hardware error and alarm log for the Network Control circuit pack. Refer to DATA-BD (Network Control Circuit Pack) Maintenance documentation.  4. Execute the <b>test tdm P</b> command again.  5. If the test still fails, refer to the <a href="#">"TDM Bus Fault Detection and Isolation Procedure"</a> described earlier.
	PASS	Communication through the TDM Bus is operational.

**Digit Detection Test (#297)**

This test is executed on the Non-Control Channel bus. The Tone-Clock circuit pack is told to put a tone on the Non-Control Channel bus and the Tone Detector circuit pack is told to listen to it. The test passes if the tone is successfully transmitted on the Non-Control Channel bus.

Table 5-472. TEST #297 Digit Detection Test

Error Code	Test Result	Description/ Recommendation
none, 1001 2100	ABORT	Could not allocate the necessary system resources to run this test.
1005	ABORT	Since this test is valid only on the non-control channel bus, it aborts execution when run on the control channel bus. This is a valid response. Use the <b>status system</b> command to verify which bus is the control channel bus.
2000	ABORT	Response to the test request was not received within the allowable time period. <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
none	FAIL	This failure indicates that communication on the Non-Control Channel is not reliable. <ol style="list-style-type: none"> <li>1. Execute the command again.</li> <li>2. If the problem persists, test the Tone-Clock circuit pack and Tone Detector circuit pack to make sure they are healthy. Refer to TONE-BD (Tone-Clock Circuit Pack), <a href="#">“TONE-PT (Tone Generator)” on page 5-1204</a>, <a href="#">“GPTD-PT [General Purpose Tone Detector Port (CPTR)]” on page 5-667</a>, and <a href="#">“DTMR-PT [Dual Tone Multifrequency Port (TTR)]” on page 5-624</a>.</li> <li>3. Execute the command again.</li> <li>4. If the problems persists, refer to the <a href="#">“TDM Bus Fault Detection and Isolation Procedure” on page 5-1116</a>.</li> </ol>
	PASS	The non-control channel bus is operational.

## System Technician-Demanded Tests: Descriptions and Error Codes

Use the **list configuration control** command to find the Tone-Clock circuit pack code of the system, and then proceed to look for the Short and Long Test Sequences according to the Tone-Clock circuit pack code.

Always investigate tests in the order presented in the following tables when inspecting errors in the system. By clearing error codes associated with the *SAKI Reset Test*, for example, you may also clear errors generated from other tests in the testing sequence.

Table 5-473. System Technician-Demanded Tests: TDM-BUS with the TN795Tone-Clock Circuit Pack

Order of Investigation	Short Test Sequence	Long Test Sequence	D/ND <sup>1</sup>
SAKI Reset Test (#53) (a)		X	D
Clock Health Test (#46) (b)	X	X	ND
Control Channel Loop Around Test (#52) (a)	X	X	ND
Tone Generator Crosstalk Test (#90) (c)		X	ND
Tone Generator Transmission Test (#40) (c)	X	X	ND
Tone Generator Audit/Update Test (#41) (c)	X	X	ND
TDM Bus Clock Circuit Status Inquiry Test (#148)	X	X	ND
TDM Bus Clock PPM Inquiry Test (#150)	X	X	ND
TDM Bus Clock Parameter Update Test (#151)	X	X	ND
Standby Reference Health Check Test (#651) (d)		X	ND

1. D = Destructive, ND = Non-destructive

### Notes:

- a. Refer to [“XXX-BD \(Common Port Circuit Pack\)” on page 5-1343](#) for descriptions of these tests.
- b. Refer to TONE-BD (Tone-Clock Circuit Pack) documentation for a description of this test.
- c. Refer to [“TONE-PT \(Tone Generator\)” on page 5-1204](#) for descriptions of these tests.
- d. This test only runs on the Standby Tone-Clock circuit pack in a Port Network with more than one Tone-Clock circuit pack. The circuit pack must be a TN795.

**TDM Bus Clock PPM Inquiry Test (#150)**

This test evaluates the quality of the synchronization source for the Tone-Clock circuit pack.

**Table 5-474. TEST #150 TDM Bus Clock PPM Inquiry Test**

Error Code	Test Result	Description/ Recommendation
1001	ABORT	The system could not allocate the necessary resources for the test.
	ABORT	The system could not allocate the necessary resources for the test. 1. Wait 1 minute, and retry the test.
2000	ABORT	Response to the test request was not received within the allowable time period.
2100	ABORT	System resources required to run this test are not available. 1. Retry the command at 1-minute intervals a maximum of 5 times.
255	ABORT	The test was not executed because the Tone-Clock circuit pack was using its local oscillator rather than synchronizing to an external source. 1. Verify that this Tone-Clock circuit pack is expected to be the synchronization source. If not, correct the synchronization information and re-execute the test.

*Continued on next page*

Table 5-474. TEST #150 TDM Bus Clock PPM Inquiry Test — *Continued*

Error Code	Test Result	Description/ Recommendation
ANY	FAIL	<p>This error represents the number of PPM errors detected on the external synchronization source since the last PPM inquiry was sent to the Tone-Clock circuit pack. A failure of this test indicates that we are outside of Stratum 4 timing specifications on the external timing source. This error produces an invalid timing signal for any system that uses this source for a synchronization reference. The error code is a variable amount ranging from 1 to 254.</p> <ol style="list-style-type: none"> <li>1. If there are errors against SYNC (Synchronization), refer to <a href="#">“SYNC (Synchronization)” on page 5-1063</a> to change the system synchronization reference, OR</li> <li>2. If there are errors against STRAT-3 (Stratum 3 Clock), refer to the STRAT-3 (Stratum 3 Clock) Maintenance documentation to resolve the errors, OR</li> <li>3. If there are errors against DS1-BD (DS1 Interface circuit pack), refer to the <a href="#">“DS1-BD (DS1 Interface Circuit Pack)” on page 5-548</a> to resolve the errors, OR</li> <li>4. If there are no other errors besides Error Type 1537 against TDM-CLK and if this error was logged against the Tone-Clock circuit pack that provided the current system synchronization reference (use the <b>status synchronization</b> command to determine this), replace the defective Tone-Clock circuit pack.</li> </ol> <p> <b>WARNING:</b></p> <p><i>Since service may be disrupted when the following procedures are carried out, try to perform the following steps when it is convenient for the customer.</i></p> <ol style="list-style-type: none"> <li>5. If the Tone-Clock circuit pack under test is in the Active mode but is not providing the current system synchronization reference, switch the synchronization reference to the Tone-Clock circuit pack under test using the <b>set synchronization PC</b> command. Rerun the test. If the test still fails, replace the defective Tone-Clock circuit pack.</li> <li>6. If the Tone-Clock circuit pack under test is in the Standby mode place it in the Active mode via the command <b>set tone-clock PC</b>. Switch the synchronization reference to the Tone-Clock circuit pack under test using the <b>set synchronization PC</b> command. Rerun the test. If the test still fails, replace the defective Tone-Clock circuit pack.</li> </ol>
	PASS	<p>The Tone-Clock circuit pack does not detect timing any PPM errors. This indicates that the external synchronization timing source is valid or that the system synchronization reference is a Tone-Clock circuit pack. The <b>status synchronization</b> command should be used to verify that the desired synchronization reference is providing timing for the system.</p>

## TDM Bus Clock Parameter Update Test (#151)

This action updates the Tone-Clock internal circuit pack parameters. Tone-Clock circuit pack:

- Disable in-line duplication status messages.
- Set the PPM threshold at 85 PPM for TN795.
- Enable PPM threshold switching
- Set the number of slips to trigger *loss of signal* - currently 30 per 5 millisecond period
- Enable the on-board synchronization switching algorithm (see above)
- Enable holdover operation (TN795 only).

This is not a test and will always pass without identifying or reporting any Tone-Clock circuit pack errors.

Table 5-475. TEST #151 TDM Bus Clock Parameter Update Test

Error Code	Test Result	Description/ Recommendation
	ABORT	Internal system error
	FAIL	Internal system error 1. Retry the command at 1-minute intervals a maximum of 5 times.
	PASS	The Tone-Clock circuit pack parameters have been successfully updated.

**Standby Reference Health Check Test (#651)**

This test evaluates the quality of the external synchronization timing source for the Standby Tone-Clock circuit pack.

**Table 5-476. TEST #651 Standby Reference Health Check Test**

Error Code	Test Result	Description/ Recommendation
	ABORT	This test may already be running due to a tone-clock installation, scheduled maintenance, alarm activity, or a technician-demand test from another terminal. This abort can also occur due to an internal system error.  1. Try the command again at 1-minute intervals up to 5 times.
1184	ABORT	This test requires an external synchronization source to be administered (DS1 primary, DS1 primary and secondary, or Stratum 3 Clock).  1. Administer the external synchronization source and retry the test.
2500	ABORT	Internal system error  1. Try the command again at 1-minute intervals up to 5 times.
0	FAIL	<b>If the Tone-Clock circuit pack is in the PPN</b> , the external synchronization timing source for side A of the Stratum 3 clock, or for the Primary DS1 reference is either absent or invalid. <b>If the Tone-Clock circuit pack is in an EPN</b> , the synchronization reference from the active EI circuit pack is either absent or invalid.
1	FAIL	<b>If the Tone-Clock circuit pack is in the PPN</b> , both external synchronization timing sources are either absent or invalid. <b>If the Tone-Clock circuit pack is in an EPN</b> , the synchronization references from both EI circuit packs are either absent or invalid.  1. Correct the synchronization source problem. Refer to the <a href="#">“SYNC (Synchronization)” on page 5-1063</a> .  2. If the error still exists, replace the Tone-Clock circuit pack reported in the error log.
	PASS	The external synchronization timing source is valid.

## TDM-CLK (TDM Bus Clock)

---

MO Name (in Alarm Log)	Alarm Level	Initial Command To Run <sup>1</sup>	Full Name of MO
TDM-CLK	MAJOR	test tone-clock PC short	TDM Bus Clock
TDM-CLK	MINOR	test tone-clock PC short	TDM Bus Clock
TDM-CLK	WARNING	release tone-clock PC	TDM Bus Clock

1. P is the cabinet number (1). C is the carrier designation (A, B, or C).

### NOTE:

Replacing the TN795 Processor/Tone-Clock circuit pack requires a special procedure described in the documentation for PR-TN-BD. That section also describes the LED displays for this board.

### WARNING:

*When the disk is replaced on the TN795, a new license file must be downloaded to the system before the system will become operational. Refer to "Obtaining a License File" in Chapter 3 of DEFINITY ONE™ Communications System Release 2.0 Installation and Upgrades (555-233-109). Retry the command and if the test fails, replace the circuit pack.*

The Time Division Multiplex (TDM) Bus Clock resides on the TN795 Processor/Tone-Clock circuit pack, providing clocking signals both for the TDM Bus and the LAN Bus. The Tone-Clock is a critical component in the system and is necessary to ensure the operation of all port circuit packs in the system. The TDM buses are synchronized together. The system timing reference can be derived internally from the Tone-Clock, or from an external (off-board) timing reference. Currently, the TDM Bus Clock supports synchronizing the TDM Bus with interface rates from Digital Signal 1 (DS1) facilities as primary and secondary references.

Moreover, the TN795 Processor/Tone-Clock circuit pack aids in monitoring and selecting synchronization references. The TN795 Processor/Tone-Clock circuit pack, after detecting that the external source of timing is not valid, will automatically begin its escalation procedure, according to the facilities administered.

### NOTE:

Switching back to a DS1 source is handled by synchronization maintenance, once any problems with it have been corrected and tested.

5 Maintenance Objects for DEFINITY ONE  
TDM-CLK (TDM Bus Clock)

5-1133

Tone-Clock Role	Synchronization Facilities	Initial External Synchronization Source	Backup External Synchronization Source	Internal Source
MASTER	DS1 Primary and Secondary	DS1 Primary	DS1 Secondary	Local oscillator
	DS1 Primary Only	DS1 Primary	None	
	No External Source	None	None	

See [“SYNC \(Synchronization\)” on page 5-1063](#) for more details of the escalation plan. *There exists a strong interdependency among the DS1 Interface circuit pack Maintenance, Synchronization Maintenance, and TDM Bus Clock Maintenance MOs.*

**Error Log Entries and Test to Clear Values**

Table 5-477. TDM Bus Clock Error Log Entries

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board <sup>1</sup>	Test to Clear Value
0 <sup>2</sup>	0	Any	Any	Any	test tone-clock PC sh r 1
130(a)		None			
257(b)		None	WARNING	OFF	
513(c)	Any	Clock Circuit Status Inquiry (#148)	MINOR <sup>3</sup>	OFF	test tone-clock PC
769(d)	Any	Clock Circuit Status Inquiry (#148)	MAJOR‡	ON	test tone-clock PC sh r 10
1025(e)	Any	Clock Slip Inquiry(#149)			test tone-clock PC sh
1281(f) 1282(f)	Any	None	MINOR	OFF	
1537	Any	Clock PPM Inquiry(#150)			test tone-clock PC sh

*Continued on next page*

5 Maintenance Objects for DEFINITY ONE  
TDM-CLK (TDM Bus Clock)

5-1134

Table 5-477. TDM Bus Clock Error Log Entries — *Continued*

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board <sup>1</sup>	Test to Clear Value
2049(g)	Any	Standby Reference Health Check Test(#651)	MAJOR <sup>3</sup>	ON	test tone-clock PC
2305(h)	0	None	WARNING	OFF	

- As a general rule, any *on board* errors against the TDM Bus Clock should be resolved before pursuing any other errors against SPE. *Off board* clock errors may be caused by other board errors, and should usually be addressed once any on board errors have been resolved.
- Run the Short Test Sequence first. If all tests pass, run the Long Test Sequence. Refer to the appropriate test description and follow the recommended procedures.
- Major or Minor alarms on this MO may have been downgraded to Warning alarms based on the values used in the **set options** command.

## Notes:

- Error Type 130: - This error type indicates that the circuit pack has been removed or has been insane for more than 11 minutes. To clear the error, reinsert or reset the tone clock module with the command **reset tone-clock 1a**.
- Error Type 257: - The Processor/Tone-Clock circuit pack is not a TN780 and will not administer as a Stratum 3 synchronization. Replace the Tone-Clock in the PPN with a TN780, or change synchronization administration to Stratum 4 if a Stratum 3 clock is not being used.
- Error Type 513: - The Processor/Tone-Clock has reported an out-of-lock condition. An aux value of 1 indicates this error is an out-of-lock with the primary reference. An aux value of 2 indicates this error is an out-of-lock with the secondary reference. It could not lock onto the frequency of that synchronization reference. This will lead to a change in the synchronization reference if the condition continues.
- Error Type 769: - The Processor/Tone-Clock module may be defective.
  - Execute the **test tone-clock 1a**. If there are error codes from any tests, follow the recommended maintenance procedures for the error code(s) to resolve the problem(s). If all tests pass, consider the 769 error type to have been a transient problem, and clear the error log entry with **test tone-clock 1a long clear**.

5 Maintenance Objects for DEFINITY ONE  
TDM-CLK (TDM Bus Clock)

5-1135

- e. Error Type 1025: -The Processor/Tone-Clock circuit pack on-board maintenance has detected one or more *clock slips*, timing differences between its internal reference source and the synchronization signal provided by the master Reference-Clock. Although no clock slip errors are expected during normal operation, an interchange of synchronization references may result in clock slip counts.

If error 1281 also is logged for the Processor/Tone-Clock module, it is related to this problem, and should be corrected first. Otherwise, continue with the procedure below.

1. Use **test tone-clock 1a**, and examine the results of test #149 to see if slip errors are still occurring. If no new slip errors are reported, and if these errors are not causing a TDM-CLK alarm, they may be ignored. Use **test tone-clock 1a long clear** to clear the errors.
2. Otherwise, enter the **display errors** command, and follow corrective procedures for any other TDM-CLK, PR-TN-BD, SYNC, DS1C-BD, and errors logged, except for those in the following table.

**Error Log Entries for Slip Errors**

Circuit Pack Name	Error Log Name	Error Log Entry for Slips
DS1 Interface	DS1-BD	3073 to 3160
Tone-Clock	TDM-CLK	1025
UDS1 Interface	UDS1-BD	3073 to 3160

3. If 1025 errors persist, refer to [“SYNC \(Synchronization\)” on page 5-1063](#).
- f. Error Type 1281—This error is an indication that the Processor Tone-Clock module has detected a loss of timing signal from the system synchronization reference. The Processor Tone-Clock module has switched synchronization references.
1. Resolve any errors logged against the SYNC maintenance objects.
  2. Refer to [“SYNC \(Synchronization\)” on page 5-1063](#) if the error is not resolved by step 1

Error Type 1282—Indicates that the TN795 Processor/Tone-Clock was synchronized to a DS1 facility and that the reference frequency provided by the DS1 drifted beyond a range that could be tracked by the TN795. Therefore the TN795 is no longer synchronized to that DS1 reference. If a second DS1 is available, the tone-clock may be synchronized to that reference. If no secondary DS1 reference is available, the tone-clock will run off of its internal clock. This may result in slips being reported by the tone-clock and all DS1 facilities.

- g. Error Type 2049: - The Processor/Tone-Clock module was unable to detect the incoming synchronization signal. If the aux data is 0, the problem is with the signal on the primary. If the aux data is 1, the problem is with the signal on the secondary.
1. If Error 1281 is also logged, it is related to this problem and should be corrected first.
  2. Clear all other errors before replacing the Processor/Tone-Clock circuit pack.
  3. See the Caution below. Replace the Processor/Tone-Clock circuit pack.



**CAUTION:**

*Reseating/Replacing the TN795 Processor/Tone-Clock circuit pack will disrupt service. Please perform the procedure with caution. Refer to ["Replace the TN795 circuit pack" on page 2-8](#) and ["Tone-Clock Replacement" on page 5-1025](#).*



**WARNING:**

*When the disk is replaced on the TN795, a new license file must be downloaded to the system before the system will become operational. Refer to ["Obtaining a License File" in Chapter 3 of DEFINITY ONE™ Communications System Release 2.0 Installation and Upgrades \(555-233-109\)](#). Retry the command and if the test fails, replace the circuit pack.*

- h. Error Type 2305: - The indicated Processor/Tone-Clock circuit pack has detected a loss of timing signal.
1. Enter **display errors** and **display alarms**, and follow the associated repair procedures for TDM-CLK error log entries that have on-board alarms.
  2. If Error 1281 is also logged, it is related to this problem and should be corrected first.
  3. If the 2305 errors persist:
    - a. Execute the **test synchronization r 10** command and check to see if new 2305 errors were reported.  
  
If no new instances of the 2305 errors were logged for either test, then enter **test tone-clock 1a long clear** to clear the TDM-CLK errors and the procedure is complete.
  4. If the problem is still not cleared, and the Processor Tone-Clock circuit pack reported in the error log has not been replaced up to now, replace it. See the Caution above.

**System Technician-Demanded Tests:  
Descriptions and Error Codes**

Always investigate tests in the order presented in the table below. By clearing error codes associated with the *SAKI Reset Test* for example, you may also clear errors generated from other tests in the testing sequence.

Order of Investigation	Short Test Sequence	Long Test Sequence	Reset Board Sequence	D/ND <sup>1</sup>
TDM Bus Clock Circuit Status Inquiry Test (#148)	X	X		ND
TDM Bus Clock PPM Inquiry Test (#150)	X	X		ND
TDM Bus Clock Parameter Update Test (#151)	X	X		ND
Board Type Check Test (#574)	X	X		ND

1. D = Destructive; ND = Nondestructive

**TDM Bus Clock Circuit Status Inquiry Test (#148)**

This test is Nondestructive.

The TDM Bus Clock circuitry is checked for sanity. Any problems that are found are reported via error codes

Table 5-478. TEST #148 TDM Bus Clock Circuit Status Inquiry Test

Error Code	Test Result	Description/ Recommendation
1001	ABORT	The system could not allocate the necessary resources for the test. 1. Wait 1 minute, and retry the test.
2000	ABORT	Response to the test request was not received within the allowable time period.
2100	ABORT	System resources required to run this test are not available. 1. Retry the command at 1-minute intervals a maximum of 5 times.

*Continued on next page*

Table 5-478. TEST #148 TDM Bus Clock Circuit Status Inquiry Test — *Continued*

Error Code	Test Result	Description/ Recommendation
1	FAIL	<p>This error means the Processor Tone-Clock circuit pack framing verification firmware reports an error in the clock synchronization signal coming in.</p> <ol style="list-style-type: none"> <li>1. If the Processor Tone-Clock circuit module reporting the problem, then the system synchronization reference is providing a bad timing source. Refer to <a href="#">“SYNC (Synchronization)” on page 5-1063</a> to change the system synchronization reference.</li> <li>2. If the Processor Tone-Clock circuit pack is a slave clock follow the diagnostic procedures specified for TDM-CLK Error Code 2305.</li> <li>3. If no problem can be found with the incoming synchronization signal, reset the tone-clock module with the command <code>reset tone-clock 1a</code>.</li> <li>4. See Caution below: If reset tone-clock command does not clear the problem, replace the TN795 Processor/Tone-Clock board.</li> </ol> <p><b>⚠ CAUTION:</b> <i>Reseating/Replacing the TN795 Processor/Tone-Clock circuit pack will disrupt service. Please perform the procedure with caution. Refer to <a href="#">“Replace the TN795 circuit pack” on page 2-8</a> and <a href="#">“Tone-Clock Replacement” on page 5-1025</a> for information on replacing the TN795 Processor/Tone-Clock circuit pack.</i></p> <p><b>⚠ WARNING:</b> <i>When the disk is replaced on the TN795, a new license file must be downloaded to the system before the system will become operational. Refer to “Obtaining a License File” in Chapter 3 of DEFINITY ONE™ Communications System Release 2.0 Installation and Upgrades (555-233-109). Retry the command and if the test fails, replace the circuit pack.</i></p>
2	FAIL	<p>This error indicates that the Processor Tone-Clock module has inaccurately detected loss of signal on the incoming synchronization timing source.</p>
4 or 8	FAIL	<p>The local oscillator on the Tone-Clock module has failed.</p>
16 or 32	FAIL	<p>The circuitry on the Processor Tone-Clock module used to detect synchronization timing errors has failed.</p> <ol style="list-style-type: none"> <li>1. Errors 2, 4, 8, 16, and 32 indicate that there is poor synchronization external facilities. It may be noticeable to the customer in the form of errors in data communications. The Tone-Clock module is defective.</li> </ol>

*Continued on next page*

Table 5-478. TEST #148 TDM Bus Clock Circuit Status Inquiry Test — Continued

Error Code	Test Result	Description/ Recommendation
64	FAIL	<p>This message is only sent when an uplink message has reported the loss of valid synchronization timing information coming in. It has been reported in TDM-CLK Error Log entries; one or more of 1025, 1281, 1537, 2049 and 2305.</p> <ol style="list-style-type: none"> <li>1. Resolve the errors indicated. No separate corrective action is required.</li> </ol>
65	FAIL	<p>The Processor Tone-Clock is currently not able to lock on to the current synchronization reference.</p> <ol style="list-style-type: none"> <li>1. Examine the error log for any DS1-BD, SYNC or other TDM-CLK errors and resolve as applicable.</li> <li>2. Run this test again via the <b>test tone-clock 1a</b> command.</li> <li>3. Examine the DS1 measurements to determine if the facility is healthy.</li> <li>4. Administer a new synchronization reference.</li> <li>5. Replace the DS1 board currently supplying the reference.</li> </ol> <p>If this tone-clock is the slave</p> <ol style="list-style-type: none"> <li>1. Examine the error log for any SYNC or other TDM-CLK errors.</li> <li>2. Run this test again via the <b>test tone-clock 1a</b> command.</li> </ol>
66	FAIL	<p>There is an on-board failure of TDM clock hardware.</p> <ol style="list-style-type: none"> <li>1. Execute the command reset tone-clock 1a.</li> <li>2. See Caution below: If reset tone-clock command does not clear the problem, replace the TN795 Processor/Tone-Clock board.</li> </ol> <p><b>⚠ CAUTION:</b> <i>Reseating/Replacing the TN795 Processor/Tone-Clock circuit pack will disrupt service. Please perform the procedure with caution. Refer to <a href="#">“Replace the TN795 circuit pack” on page 2-8</a> and <a href="#">“Tone-Clock Replacement” on page 5-1025</a> for information on replacing the TN795 Processor/Tone-Clock circuit pack.</i></p> <p><b>⚠ WARNING:</b> <i>When the disk is replaced on the TN795, a new license file must be downloaded to the system before the system will become operational. Refer to “Obtaining a License File” in Chapter 3 of DEFINITY ONE™ Communications System Release 2.0 Installation and Upgrades (555-233-109).Retry the command and if the test fails, replace the circuit pack.</i></p>
	PASS	<p>TDM Bus Clock Circuit Status is sane. There are no clock-detection circuit problems on the Tone-Clock circuit pack.</p>

## TDM Bus Clock PPM Inquiry Test (#150)

This test is Nondestructive.

This test evaluates the quality of the synchronization source for the Processor Tone-Clock circuit pack

Table 5-479. TEST #150 TDM Bus Clock PPM Inquiry Test

Error Code	Test Result	Description/ Recommendation
1001	ABORT	The system could not allocate the necessary resources for the test.
	ABORT	The system could not allocate the necessary resources for the test. 1. Wait 1 minute and retry the test.
255	ABORT	The Processor Tone-Clock module was using its local oscillator rather than synchronizing to an external source. 1. Verify that this Processor Tone-Clock module is expected to be the synchronization source. If not, correct the synchronization information and re-execute the test.
2000	ABORT	Response to the test request was not received within the allowable time period.
2100	ABORT	System resources required to run this test are not available. 1. Retry the command at 1-minute intervals a maximum of 5 times.
Any	FAIL	The error code represents the rate (in Parts Per Million, or PPM) at which clock slip errors have been detected on the incoming synchronization source since the last PPM inquiry was sent to the Tone-Clock module. A failure of this test indicates that we are outside of Stratum 4 timing specifications on the incoming timing source.  The error code is a variable amount ranging from 1 to 254. 1. If error 1537 is entered in the hardware error log against TDM-CLK, then the board has switched timing sources. Follow the procedures associated with hardware log error code 1537. 2. Otherwise, refer to <a href="#">“Synchronization Troubleshooting” on page 5-1064.</a>
	PASS	The Processor Tone-Clock module does not detect timing any PPM errors. This indicates that the external synchronization timing source is valid or that the system synchronization reference is a Tone-Clock module. The <b>status synchronization</b> command should be used to verify that the desired synchronization reference is providing timing for the system.

## TDM Bus Clock Parameter Update Test (#151)

This test is Nondestructive.

This test updates the following internal parameters on the TN795 Processor/Tone-Clock circuit pack:

- Set the PPM threshold at 85 PPM for the TN795.
- Enable PPM threshold switching
- Set the number of slips to trigger *loss of signal* - currently 30 per 5 millisecond period
- Enable the on-board synchronization switching algorithm (see above)
- Enable holdover operation (TN795 only).

This is not a test and will always pass without identifying or reporting any Tone-Clock circuit pack errors

Table 5-480. TEST #151 TDM Bus Clock Parameter Update Test

Error Code	Test Result	Description/ Recommendation
	ABORT	Internal System Error
	FAIL	Internal System Error 1. Retry the command at 1-minute intervals a maximum of 5 times.
	PASS	The Tone-Clock circuit pack parameters have been successfully updated.

## **TDMODULE (Trunk Data Module)**

---

<b>MO Name (in Alarm Log)</b>	<b>Alarm Level</b>	<b>Initial Command to Run</b>	<b>Full Name of MO</b>
TDMODULE <sup>1</sup>	MINOR	test port PCSSpp I	Trunk Data Module
TDMODULE (a)	WARNING	test port PCSSpp I	Trunk Data Module

- 
1. Where P is the port network number (1); C is the carrier designation (for example, A, B, or C); SS is the address of the slot in the carrier where the circuit pack is located (for example, 01, 02, ...,etc.); and pp is the 2-digit port number (for example, 01).
- 

The TDMODULE (Trunk Data Module) Maintenance documentation is covered in the PDMODULE (Processor Data Module) Maintenance documentation.

**5** Maintenance Objects for DEFINITY ONE  
*TIE-BD (Tie Trunk Circuit Pack)*

5-1143

**TIE-BD (Tie Trunk Circuit Pack)**

---

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run <sup>1</sup>	Full Name of MO
TIE-BD	MIN	test board PCSS sh	Tie Trunk Circuit Pack
TIE-BD	WRN	test board PCSS sh	Tie Trunk Circuit Pack

- 
1. Where P is the port network number (1); C is the carrier designation (for example, A, B, or C); and SS is the address of the slot in the carrier where the circuit pack is located (for example, 01, 02, ..., etc.).
- 

Refer to [“XXX-BD \(Common Port Circuit Pack\)” on page 5-1343](#) for circuit pack level errors. See also [“TIE-TRK \(Tie Trunk\)” on page 5-1161](#).

## TIE-DS1 (DS1 Tie Trunk)

---

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run	Full Name of MO
TIE-DS1 <sup>1</sup>	MAJOR <sup>2</sup>	test trunk <grp/mbr> l	DS1 Tie Trunk
TIE-DS1	MINOR	test trunk <grp/mbr> l	DS1 Tie Trunk
TIE-DS1	WARNING	test trunk <grp/mbr>	DS1 Tie Trunk

1. For additional repair information, see also DS1-BD (DS1 Interface Circuit Pack) Maintenance documentation.
  2. A MAJOR alarm on a trunk indicates that alarms on these trunks are not downgraded by the **set options** command and that at least 75 percent of the trunks in this trunk group are alarmed.
- 

The DS1 tie trunk provides both voice and data inter-PBX communication. A 24 channel DS1 Interface circuit pack can support up to 24 digital tie trunks through a 1.544 Mbps DS1 link. A 32 channel DS1 Interface circuit pack can support up to 30 digital tie trunks through a 2.048 Mbps DS1 link. DS1 Interface circuit packs are described in DS1-BD. DS1 Tie Trunks are used widely in the DCS and Central Attendant Service (CAS) features of the system.

A DS1 tie trunk can also be used as an access endpoint which is a non-signaling channel with a bandwidth of voice-grade-data, 56K-data or 64K-data.

DS1 tie trunk maintenance provides a strategy to maintain a DS1 tie trunk via a port on the DS1 Interface circuit pack. The maintenance strategy covers logging DS1 tie trunk hardware errors, running tests for trunk initialization, periodic and scheduled maintenance, system technician-demanded tests, and alarm escalation and resolution. Three different trunk service states are specified in the DS1 tie trunk maintenance. They are: *out-of-service* in which the trunk is in a deactivated state and cannot be used for either incoming or outgoing calls; *in-service* in which the trunk is in an activated state and can be used for both incoming and outgoing calls; *disconnect* (ready-for-service) in which the trunk is in an activated state but can only be used for an incoming call. If the DS1 Interface circuit pack is out-of-service, all trunks on the DS1 Interface circuit pack are placed into out-of-service state, and a Warning alarm is raised.

## Hardware Error Log Entries and Test to Clear Values

Table 5-481. DS1 Tie Trunk Error Log Entries

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
0 <sup>1</sup>	0	Any	Any	Any	test trunk <grp>/<mbr> sh r 1>
1 (a)	57476 57477 57485 57487				
15 (b)	Any	Port Audit and Update Test (#36)			
18 (c)	0	busyout trunk <grp>/<mbr>	WARNING	OFF	release trunk <grp>/<mbr>
130 (d)		None	WARNING	ON	test trunk <grp>/<mbr>
257 (e)	57473 57474				
513(f)	57392	DS1 Tie Trunk Seizure Test (#136)	MIN/MAJ <sup>2</sup>		
769(g)	57393	DS1 Tie Trunk Seizure Test (#136)	MIN/MAJ <sup>2</sup>		
1025		DS1 Tie Trunk Seizure (Test #136)	MAJ/MIN/ WRN <sup>3</sup>	OFF	test trunk <grp>/<mbr> r 2
1281		Conference Circuit (Test #7)	MAJ/MIN/ WRN <sup>3</sup>	ON	test trunk <grp>/<mbr> l r 4
1537		NPE Crosstalk Test (#6)	MAJ/MIN/ WRN <sup>3</sup>	ON	test trunk <grp>/<mbr> l r 3
1793 (h)					test board PCSS long
2305(i)	50944	DS1 Tie Trunk Seizure Test (#136)	MIN/MAJ <sup>3</sup>	OFF	

1. Run the Short Test Sequence first. If all tests pass, run the Long Test Sequence. Refer to the appropriate test description and follow the recommended procedures.

**5** Maintenance Objects for DEFINITY ONE  
*TIE-DS1 (DS1 Tie Trunk)*

5-1146

2. This alarm will only be raised when the System-Parameter Country form has the Base Tone Generator field set to 4 (Italy). This alarm will be a MINOR alarm unless 75% or more trunks in this trunk group are out of service, then the alarm will be upgraded to a MAJOR alarm.
3. Minor alarms on this MO may be downgraded to Warning alarms based on the values used in the **set options** command. If the MINOR alarm is not downgraded by the **set options** values, the MINOR alarm is upgraded to a MAJOR alarm if 75 percent of the trunks in this trunk group are alarmed.

## Notes:

- a. Error Type 1—The DS1 Interface circuit pack detects a hardware error on the DS1 tie trunk. This error can be caused by incompatible translations. Make sure the parameters administered on the DS1 circuit pack form match those administered on the far-end switch.

The Aux Data field indicates the following hardware error types:

57476	On-hook before wink
57477	On-hook before ready to receive digits
57485	Wink too short for valid signal
57487	The timer expired while waiting for an off-hook signal from the far end as a response at end of digits dialing. Check the far-end switch for related problems.

If all administration errors between the switch and the far-end match, and these errors continue to recur, follow normal escalation procedures.

- b. Error Type 15—This is a software audit error that does not indicate any hardware malfunction. Run Short Test Sequence and investigate associated errors (if any).
- c. Error Type 18—The DS1 tie trunk has been busied out by a **busyout trunk grp/mbr** command. No calls can be made on this trunk except for the Facility Access Test Call.
- d. Error Type 130—This error type indicates that the circuit pack has been removed or has been insane for more than 11 minutes. To clear the error, reinsert or replace the circuit pack.
- e. Error Type 257—The DS1 Interface circuit pack detects a hardware error on the DS1 tie trunk. The trunk cannot communicate with the far end because it is unable to interpret digits sent from the far-end switch. The Aux Data field indicates the following:

57473	The rotary dial rate is below 8 pulses per second.
57474	The rotary dial rate is above 12 pulses per second.

Check with the far-end switch or operating company for proper trunk connection.

5 Maintenance Objects for DEFINITY ONE  
TIE-DS1 (DS1 Tie Trunk)

5-1147

- f. Error Type 513—DS1 Interface circuit pack detects a hardware error on the DS1 tie trunk. The trunk is in-service/active and waiting for an “on-hook” from the far-end switch. No calls can be routed over the trunk while it is in this state. Aux Data 57392 indicates no external release on PBX disconnect. Check with the far-end switch or operating company for proper trunk connection.
  - g. Error Type 769—The DS1 Interface circuit pack detects a hardware error on the DS1 tie trunk. This error usually occurs after one or more occurrences of error type 513. The trunk has received the belated “on-hook” that it has been waiting for from the far-end switch. The trunk is restored to in-service/idle and can be used for calls. Aux Data 57393 indicates delayed external release on PBX disconnect. This error can be ignored.
  - h. Error Type 1793—The DS1 Interface circuit pack is out-of-service. See the appropriate DS1-BD/UDS1-BD (DS1/UDS1 Interface Circuit Pack) Maintenance documentation for details.
  - i. Error Type 2305—Reorder message. The trunk could not be seized. This error will cause the Trunk Seizure Test (#136) to run and is only considered a problem if the Seizure Test fails (in which case Error Type 1025 will also show up). In this case, the trunk may be put in “Ready-for-Service” state (shown as “disconnected” by the status command), which allows only incoming calls. Run the Trunk Seizure Test (#136) and follow its outlined procedures.
  - j. Error Type 2562—Retry Failure error. This error is logged only. It is not a hardware failure and hence does not start any testing or generate any alarms. This error comes from call processing and is generated when a second attempt (retry) to seize an outgoing trunk fails.
  - k. Error Type 2817—Glare error. This error is logged only. It is not a hardware failure and hence does not start any testing or generate any alarms. This error is the result of a simultaneous seizure of a two-way trunk from both the near-end and the far-end. Attempt to place the call again. If the error persists, execute the DS1 Tie Trunk Seizure Test (#136) and follow its outlined procedures.
  - l. Error Type 3840—Port Audit and Update Test (#36) failed due to an internal system error. Enter **status trunk** command and verify the status of the trunk. If the trunk is out-of-service, then enter **release trunk** command to put it back to in-service. Retry the test command.
-

## System Technician-Demanded Tests: Descriptions and Error Codes

---

Always investigate tests in the order presented in [Table 5-482](#) when inspecting errors in the system. By clearing error codes associated with the *NPE Crosstalk Test*, for example, you may also clear errors generated from other tests in the testing sequence.

Table 5-482. System Technician-Demanded Tests: TIE-DS1

---

Order of Investigation	Short Test Sequence	Long Test Sequence	D/ND <sup>1</sup>
NPE Crosstalk Test (#6)		X	ND
Conference Circuit Test (#7)		X	ND
DS1 Tie Trunk Seizure Test (#136)	X	X	ND
Port Audit and Update Test (#36)	X	X	ND

---

---

1. D = Destructive; ND = Nondestructive

---

**NPE Crosstalk Test (#6)**

One or more NPEs reside on each circuit pack with a TDM Bus interface. The NPE controls port connectivity and gain, and provides conferencing functions on a per port basis. The NPE Crosstalk Test verifies that this port's NPE channel talks on the selected time slot and never crosses over to time slots reserved for other connections. If the NPE is not working correctly, one-way and noisy connections may be observed. This test is usually only part of a port's Long Test Sequence and takes on the order of 20 to 30 seconds to complete.

Table 5-483. TEST #6 NPE Crosstalk Test

Error Code	Test Result	Description/ Recommendation
	ABORT	System resources required for this test are not available.  1. Retry the command at 1-minute intervals a maximum of 5 times.
1000	ABORT	System resources required to run this test were not available. The port may be busy with a valid call. Use the <b>display port PCSSpp</b> command to determine the trunk group/member number of the port. Use the <b>status trunk</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. (Refer to " <a href="#">status station</a> " on page 4-213 for a description of all possible states.) You must wait until the port is idle before retesting.  1. If the port status is active but the port is not in use (no calls), check the error log for error type 1025 (see the error log table for a description of this error and required actions). The port may be locked up.  2. If the port status is idle, retry the command at 1-minute intervals for a maximum of 5 times.
1001	ABORT	System resources required to run this test are not available.  1. Retry the command at 1-minute intervals for a maximum of 5 times.
1002	ABORT	The system could not allocate time slots for the test. The system may be under heavy traffic conditions, or it may have time slots out of service due to TDM-BUS errors. Refer to the " <a href="#">TDM-BUS (TDM Bus)</a> " on page 5-1116 to diagnose any active TDM-BUS errors.  1. If the system has no TDM-BUS errors and is not handling heavy traffic and the port status is idle, retry the command at 1-minute intervals for a maximum of 5 times.

*Continued on next page*

5 Maintenance Objects for DEFINITY ONE  
TIE-DS1 (DS1 Tie Trunk)

5-1150

Table 5-483. TEST #6 NPE Crosstalk Test — *Continued*

Error Code	Test Result	Description/ Recommendation
1003	ABORT	<p>The system could not allocate a tone receiver for the test. The system may be oversized for the number of tone detectors present or some of the tone detectors may be out of service. Issue the <b>list measurements tone-receiver</b> command to display basic information about the system's tone receivers.</p> <ol style="list-style-type: none"> <li>1. Look for TTR-LEV errors in the error log. If present, refer to <a href="#">“TTR-LEV (TTR Level)” on page 5-1223</a>.</li> <li>2. Look for TONE-PT errors in the error log. If present, refer to <a href="#">“TONE-PT (Tone Generator)” on page 5-1204</a>.</li> <li>3. If neither condition exists, retry the test at 1-minute intervals for a maximum of 5 times.</li> </ol>
1004	ABORT	<p>The port was seized by a user for a valid call. Use the <b>display port PCSSpp</b> command to determine the trunk group/member number of the port. Use the <b>status trunk</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. You must wait until the port is idle before retesting.</p> <ol style="list-style-type: none"> <li>1. If the port status is idle, retry the command at 1-minute intervals for a maximum of 5 times.</li> </ol>
1020	ABORT	<p>The test did not run because of a previously existing error on the specific port or a more general circuit pack error.</p> <ol style="list-style-type: none"> <li>1. Examine the Error Log for existing errors against this port or the circuit pack and attempt to diagnose the already existing error.</li> </ol>
2000	ABORT	Response to the test request was not received within the allowable time period.
2100	ABORT	<p>System resources required for this test are not available.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
2053	ABORT	<p>At least one of the following errors is found on the DS1 circuit pack: 1281—Loss of signal, 1793—Blue Alarm, 2049—Red Alarm, 2305—Yellow Alarm, 1537—Hyperactivity.</p> <p>Look for the above error types in the Hardware Error Log and follow the procedures given in the appropriate DS1-BD or UDS1-BD maintenance documentation for the listed error types.</p>

*Continued on next page*

Table 5-483. TEST #6 NPE Crosstalk Test — *Continued*

Error Code	Test Result	Description/ Recommendation
	FAIL	<p>This can be due to on-board or off-board problems. Off-board problems of concern include EXP-PN and EXP-INTF faults, TDM-BUS faults, and faults associated with the tone detectors/tone generators. Clear all off-board problems before replacing the board. Keep in mind that a TDM-BUS problem is usually the result of a faulty board connected to the backplane or bent pins on the backplane.</p> <ol style="list-style-type: none"><li>1. Look for EXP-PN and/or EXP-INTF errors in the error log. If present, refer to the EXP-PN Maintenance documentation and the EXP-INTF Maintenance documentation.</li><li>2. Look for TDM-BUS errors in the error log. If present, refer to the <a href="#">“TDM-BUS (TDM Bus)” on page 5-1116</a>.</li><li>3. Look for TONE-BD and/or TONE-PT errors in the error log. If present, refer to the TONE-BD Maintenance documentation and the <a href="#">“TONE-PT (Tone Generator)” on page 5-1204</a>.</li><li>4. Retest when the faults from steps 1, 2, and 3 are cleared. Replace the board only if the test fails.</li></ol>
	PASS	<p>The port is correctly using its allocated time slots. User-reported troubles on this port should be investigated using other port tests and by examining station, trunk, or external wiring.</p>
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board). This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"><li>1. Check to ensure that the board translations are correct. Use the <b>list config</b> command, and resolve any problems that are found.</li><li>2. If the board was found to be correctly inserted in step 1, issue the <b>busyout board</b> command.</li><li>3. Issue the <b>reset board</b> command.</li><li>4. Issue the <b>release busy board</b> command.</li><li>5. Issue the <b>test board long</b> command. This should re-establish the linkage between the internal ID and the port. If this is not the case, check to see that there is a valid board inserted.</li></ol>

## Conference Circuit Test (#7)

One or more NPEs reside on each circuit pack with a TDM Bus interface. The NPE controls port connectivity and gain, and provides conferencing functions on a per-port basis. The Conference Circuit Test verifies that the NPE channel for the port being tested can correctly perform the conferencing function. The NPE is instructed to listen to several different tones and conference the tones together. The resulting signal is then measured by a Tone Detector port. If the level of the tone is within a certain range, the test passes.

Table 5-484. TEST #7 Conference Circuit Test

Error Code	Test Result	Description/ Recommendation
	ABORT	System resources required for this test are not available. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
1000	ABORT	System resources required to run this test were not available. The port may be busy with a valid call. Use the <b>display port PCSSpp</b> command to determine the trunk group/member number of the port. Use the <b>status trunk</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. You must wait until the port is idle before retesting. <ol style="list-style-type: none"><li>1. If the port status is active but the port is not in use (no calls), check the error log for error type 1025 (see the error log table for a description of this error and required actions). The port may be locked up.</li><li>2. If the port status is idle, retry the command at 1-minute intervals for a maximum of 5 times.</li></ol>
1002	ABORT	The system could not allocate time slots for the test. The system may be under heavy traffic conditions, or it may have time slots out of service due to TDM-BUS errors. The <b>status health</b> command can be used to determine if the system is experiencing heavy traffic. Refer to the <a href="#">"TDM-BUS (TDM Bus)" on page 5-1116</a> to diagnose any active TDM-BUS errors. <ol style="list-style-type: none"><li>1. If the system has no TDM-BUS errors and is not handling heavy traffic and the port status is idle, retry the command at 1-minute intervals for a maximum of 5 times.</li></ol>

*Continued on next page*

Table 5-484. TEST #7 Conference Circuit Test — *Continued*

Error Code	Test Result	Description/ Recommendation
1003	ABORT	<p>The system could not allocate a tone receiver for the test. The system may be oversized for the number of tone detectors present or some of the tone detectors may be out of service. Issue the <b>list measurements tone-receiver</b> command to display basic information about the system's tone receivers.</p> <ol style="list-style-type: none"> <li>1. Look for TTR-LEV errors in the error log. If present, refer to <a href="#">"TTR-LEV (TTR Level)" on page 5-1223</a>.</li> <li>2. Look for TONE-PT errors in the error log. If present, refer to <a href="#">"TONE-PT (Tone Generator)" on page 5-1204</a>.</li> <li>3. If neither condition exists, retry the test at 1-minute intervals for a maximum of 5 times.</li> </ol>
1004	ABORT	<p>The port was seized by a user for a valid call. Use the <b>display port PCSSpp</b> command to determine the trunk group/member number of the port. Use the <b>status trunk</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. You must wait until the port is idle before retesting.</p> <ol style="list-style-type: none"> <li>1. If the port status is idle, retry the command at 1-minute intervals for a maximum of 5 times.</li> </ol>
1018	ABORT	<p>Test disabled via administration. This only applies to analog stations.</p> <ol style="list-style-type: none"> <li>1. To enable test, set the Test field on the station administration screen for the particular analog station being tested to "y." Use the <b>change station &lt;extension&gt;</b> command.</li> </ol>
1020	ABORT	<p>The test did not run due to a previously existing error on the specific port or because of a more general circuit pack error.</p> <ol style="list-style-type: none"> <li>1. Examine the Error Log for existing errors against this port or circuit pack, and attempt to diagnose the previously existing error.</li> </ol>
2000	ABORT	Response to the test request was not received within the allowable time period.
2100	ABORT	<p>System resources required to run this test are not available.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
2053	ABORT	<p>At least one of the following errors is found on the DS1 circuit pack: 1281—Loss of signal, 1793—Blue Alarm, 2049—Red Alarm, 2305—Yellow Alarm, 1537—Hyperactivity.</p> <p>Look for the above error types in the Hardware Error Log and follow the procedures given in the appropriate DS1-BD or UDS1-BD maintenance documentation for the listed error types.</p>

*Continued on next page*

Table 5-484. TEST #7 Conference Circuit Test — *Continued*

Error Code	Test Result	Description/ Recommendation
	FAIL	<p>The NPE of the tested port did not conference the tones correctly. This can cause noisy and unreliable connections.</p> <ol style="list-style-type: none"> <li>1. Enter the <b>list configuration board PCSS</b> command. If the circuit pack is a TN767B vintage 8 or 9, replace the circuit pack with a TN767C V3 or later. The error log may have error type 1281 entries.</li> <li>2. Test all administered trunks on the board. If one fails, this could be an off-board problem (such as an incoming seizure or an off-hook port seizure during the test). Retest the board.</li> <li>3. If all of the ports fail, check the CARR-POW (see note below).</li> <li>4. If several ports fail, check the error log for TONE-BD or TONE-PT errors. If there are such errors, take the appropriate action. When the TONE errors have cleared, rerun the test.</li> <li>5. If the retry passes and troubles have been reported, coordinate isolation with the far-end PBX. Make sure that the near-end and far-end switches and any NTCE equipment (the CSU's) have the correct administration.</li> </ol>
	FAIL (con't.)	<ol style="list-style-type: none"> <li>6. Replace the circuit pack.</li> </ol> <p> <b>NOTE:</b> If the conference circuit test fails for all ports on a circuit pack, a -5 volt power problem is indicated.</p>
	PASS	<p>The port can correctly conference multiple connections. User-reported troubles on this port should be investigated using other port tests and by examining station, trunk, or external wiring.</p>
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board). This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"> <li>1. Check to ensure that the board translations are correct. Use the <b>list config</b> command, and resolve any problems that are found.</li> <li>2. If the board was found to be correctly inserted in step 1, issue the <b>busyout board</b> command.</li> <li>3. Issue the <b>reset board</b> command.</li> <li>4. Issue the <b>release busy board</b> command.</li> <li>5. Issue the <b>test board long</b> command. This should re-establish the linkage between the internal ID and the port. If this is not the case, check to see that there is a valid board inserted.</li> </ol>

## Port Audit and Update Test (#36)

This test sends port level translation data from switch processor to the DS1 Interface circuit pack to ensure that the trunk's translation is correct. Translation updates include the following data: trunk type (in/out), dial type, timing parameters, and signaling bits enabled. The port audit operation verifies the consistency of the current state of the trunk kept by the DS1 Interface circuit pack and the switch software.

Table 5-485. TEST #36 Audit and Update Test

Error Code	Test Result	Description/ Recommendation
	ABORT	Internal System Error.  1. Retry the command at 1-minute intervals a maximum of 5 times.
1000	ABORT	System resources required to run this test were not available. The port may be busy with a valid call. Use the <b>display port PCSSpp</b> command to determine the trunk group/member number of the port. Use the <b>status trunk</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. You must wait until the port is idle before retesting.  1. If the port status is active but the port is not in use (no calls), check the error log for error type 1025 (see the error log table for a description of this error and required actions). The port may be locked up.  2. If the port status is idle, retry the command at 1-minute intervals for a maximum of 5 times.
1006	ABORT	The test was aborted because the trunk is out of service.  1. Use the <b>status trunk</b> command to verify that the trunk is out of service.  2. If the trunk is out of service, determine why.  3. If it is OK to put the trunk back in service, issue the <b>release trunk</b> command to put the trunk back in service, and then retry the test.
2000	ABORT	Response to the test request was not received within the allowable time period.
2100	ABORT	Could not allocate the necessary system resources to run this test.  1. Retry the command at 1-minute intervals a maximum of 5 times.

*Continued on next page*

Table 5-485. TEST #36 Audit and Update Test — *Continued*

Error Code	Test Result	Description/ Recommendation
	FAIL	Internal System Error. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
	PASS	Trunk translation has been updated successfully. The current trunk states kept in the DS1 Interface circuit pack and switch software are consistent. If the trunk is busied out, the test does not run, but it does return PASS. To verify that the trunk is in-service: <ol style="list-style-type: none"><li>1. Enter <b>status trunk</b> command to verify that the trunk is in-service. If the trunk is in-service, no further action is necessary. If the trunk is out-of-service, continue to Step 2.</li><li>2. Enter <b>release trunk</b> command to put trunk back into in-service.</li><li>3. Retry the test command.</li></ol>
0	NO BOARD	The test could not relate the internal ID to the port (no board). This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted. <ol style="list-style-type: none"><li>1. Check to ensure that the board translations are correct. Use the <b>list config</b> command, and resolve any problems that are found.</li><li>2. If the board was found to be correctly inserted in step 1, issue the <b>busyout board</b> command.</li><li>3. Issue the <b>reset board</b> command.</li><li>4. Issue the <b>release busy board</b> command.</li><li>5. Issue the <b>test board long</b> command. This should re-establish the linkage between the internal ID and the port. If this is not the case, check to see that there is a valid board inserted.</li></ol>

### DS1 Tie Trunk Seizure Test (#136)

The DS1 Tie Trunk Seizure Test is run to verify the trunk's signaling capability. The test is composed of two parts. The first part queries the circuit pack for the following errors: Loss of Signal, Red Alarm, Blue Alarm, Yellow Alarm, and Hyperactivity Alarm. The second part of the test is performed by sending a seizure message to the DS1 Interface circuit pack and expecting an active reply by the DS1 Interface circuit pack. If maintenance software does not receive any reply and the timer expires, the test is aborted. Once the active message is received, a dial pause message is sent to the DS1 Interface circuit pack. If the DS1 Interface circuit pack replies with a dial pulse tone message when the far end responds to the seizure, then the DS1 tie trunk Seizure Test passes. If the far end does not respond to the seizure and the timer expires, and the DS1 Interface circuit pack sends a reorder message back to the maintenance software, then the test fails.

This second part of this test **CANNOT** be run on a trunk if one of the following cases is true:

1. The trunk direction is administered as an incoming only trunk.
2. The trunk is the 24th port on a DS1 Interface circuit pack which is administered using 24th Common Channel Signaling.
3. The trunk has been seized by a normal trunk call.
4. The trunk is administered with maintenance test disabled.
5. The outgoing signal type of the trunk is either automatic or immediate-start.

Table 5-486. TEST #136 DS1 Tie Trunk Seizure Test

Error Code	Test Result	Description/ Recommendation
1000	ABORT	Internal System Error.
	ABORT	<p>System resources required to run this test were not available. The port may be busy with a valid call. Use the <b>display port PCSSpp</b> command to determine the trunk group/member number of the port. Use the <b>status trunk</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. You must wait until the port is idle before retesting.</p> <ol style="list-style-type: none"> <li>1. If the port status is active but the port is not in use (no calls), check the error log for error type 1025 (see the error log table for a description of this error and required actions). The port may be locked up.</li> <li>2. If the port status is idle, retry the command at 1-minute intervals for a maximum of 5 times.</li> </ol>

*Continued on next page*

Table 5-486. TEST #136 DS1 Tie Trunk Seizure Test — *Continued*

Error Code	Test Result	Description/ Recommendation
1004	ABORT	<p>Far end is seizing the trunk while the test is ongoing. A glare situation is detected. Current test is designed to be aborted. Use the <b>display port PCSSpp</b> command to determine the trunk group/member number of the port. Use the <b>status trunk</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. You must wait until the port is idle before retesting.</p> <ol style="list-style-type: none"><li>1. If the port status is idle, retry the command at 1-minute intervals for a maximum of 5 times.</li></ol>
1005	ABORT	<p>Test failed due to incompatible configuration administered in trunk group form.</p> <ol style="list-style-type: none"><li>1. Verify the following fields on the trunk group administration screen:<ol style="list-style-type: none"><li>a. Is trunk direction incoming only?</li><li>b. Is trunk outgoing type either automatic or immediate-start?</li><li>c. Is trunk the 24th port of the DS1 Interface circuit pack while common control channel signaling is specified?</li></ol></li><li>2. If the trunk has been administered using the above information, then this test should abort.</li></ol>
1018	ABORT	<p>The test was disabled via translation. You may want to determine why the test has been disabled before you enable it.</p> <ol style="list-style-type: none"><li>1. Verify that the <code>Maintenance Test</code> field on the Trunk Administration screen is set to <b>n</b>. To enable the test, change the trunk administration and enter <b>y</b> into the <code>Maintenance Test</code> field.</li><li>2. Repeat the test.</li></ol>
1020	ABORT	<p>The test did not run due to an already existing error on the specific port or due to a more general circuit pack error.</p> <ol style="list-style-type: none"><li>1. Examine the error log for existing errors against this port or the circuit pack and attempt to diagnose the already existing error.</li><li>2. Retry the test.</li></ol>
1040	ABORT	<p>This test is not performed for trunk ports administered as access endpoints.</p> <ol style="list-style-type: none"><li>1. Verify this port is an access endpoint by using the <b>display port</b> command.</li><li>2. If the port has been administered as an access endpoint, this test should abort.</li></ol>

*Continued on next page*

5 Maintenance Objects for DEFINITY ONE  
TIE-DS1 (DS1 Tie Trunk)

5-1159

Table 5-486. TEST #136 DS1 Tie Trunk Seizure Test — *Continued*

Error Code	Test Result	Description/ Recommendation
2000	ABORT	Response to the test request was not received within the allowable time period.
2100	ABORT	<p>Could not allocate the necessary system resources to run this test.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals for a maximum of 5 times.</li> </ol>
2053	ABORT/ FAIL <sup>1</sup>	<p>At least one of the following errors is found on the circuit pack: 1281: Loss of Signal, 1793: Blue Alarm, 2049: Red Alarm, 2305: Yellow Alarm, 1537: Hyperactivity.</p> <ol style="list-style-type: none"> <li>1. Look for the above error types in the Hardware Error Log and follow the procedures given in the DS1-BD tests for the listed error types.</li> </ol>
	FAIL	<p>The far-end trunk did not respond to the seizure of the near-end trunk within the allowable time period. This test could have associated in-line errors in the error log.</p> <ol style="list-style-type: none"> <li>1. 1) Enter the <b>list configuration board PCSS</b> command. If the circuit pack is a TN767B vintage 8 or 9, a failure of test 136 causes a subsequent failure of test 7 due to a firmware bug. Eventually, the board and all of its ports will be taken out of service and extraneous on-board alarms will be generated. Replace the circuit pack with a TN767C V3 or later.</li> <li>2. Verify that the 'Trunk Type' field on the 'Trunk Administration' screen matches the trunk type administered on far-end switch.</li> <li>3. Look for DS1-BD or UDS1-BD errors in the hardware error log. If present, refer to <a href="#">"DS1-BD (DS1 Interface Circuit Pack)" on page 5-548</a> or to <a href="#">"UDS1-BD (UDS1 Interface Circuit Pack)" on page 5-1227</a>.</li> <li>4. Retry the test at 1-minute intervals for a maximum of 5 times.</li> </ol>
2000	FAIL	<p>Response to the seizure message was not received within the allowable time period.</p> <ol style="list-style-type: none"> <li>1. Enter the <b>list configuration board PCSS</b> command. If the circuit pack is a TN767B vintage 8 or 9, a failure of test 136 causes a subsequent failure of test 7 due to a firmware bug. Eventually, the board and all of its ports will be taken out of service and extraneous on-board alarms will be generated. Replace the circuit pack with a TN767C V3 or later.</li> <li>2. Verify that the <code>Trunk Type</code> field on the Trunk Administration screen matches the trunk type administered on far-end switch.</li> <li>3. Look for DS1-BD or UDS1-BD errors in the hardware error log. If present, refer to <a href="#">"DS1-BD (DS1 Interface Circuit Pack)" on page 5-548</a> or to <a href="#">"UDS1-BD (UDS1 Interface Circuit Pack)" on page 5-1227</a>.</li> <li>4. Retry the test at 1-minute intervals for a maximum of 5 times.</li> </ol>
	PASS	The trunk can be seized for an outgoing call.

*Continued on next page*

Table 5-486. TEST #136 DS1 Tie Trunk Seizure Test — *Continued*

---

Error Code	Test Result	Description/ Recommendation
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board). This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"><li>1. Check to ensure that the board translations are correct. Use the <b>list config</b> command, and resolve any problems that are found.</li><li>2. If the board was found to be correctly inserted in step 1, issue the <b>busyout board</b> command.</li><li>3. Issue the <b>reset board</b> command.</li><li>4. Issue the <b>release busy board</b> command.</li><li>5. Issue the <b>test board long</b> command. This should re-establish the linkage between the internal ID and the port. If this is not the case, check to see that there is a valid board inserted.</li></ol>

---

1. Earlier G1 Software Versions reported Error Code 2053's Test Result as FAIL.

## TIE-TRK (Tie Trunk)

---

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run <sup>1</sup>	Full Name of MO
TIE-TRK <sup>2</sup>	MAJOR <sup>3</sup>	test port PCSSpp l	Tie Trunk
TIE-TRK	MINOR	test port PCSSpp l	Tie Trunk
TIE-TRK	WARNING	test port PCSSpp sh	Tie Trunk

1. Where P is the port network number (1); C is the carrier designation (for example, A, B, or C); SS is the address of the slot in the carrier where the circuit pack is located (for example, 01, 02, ..., etc.); and pp is the 2-digit port number (for example, 01).
  2. Not relevant to the TN497 circuit pack.
  3. A Major alarm on a trunk indicates that alarms on these trunks are not downgraded by the **set options** command and that at least 75 percent of the trunks in this trunk group are alarmed. (This is not relevant to the TN497 circuit pack.)
- 

### NOTE:


If ATMS testing is enabled, check the error log for ATMS Errors #3840 and #3841. If the error log indicates that measurements exceeded acceptable thresholds, and if no other trouble is found with the **test trunk** command, run the ATMS test call with the **test analog-testcall port PCSSpp full** command.

The following circuit packs are covered by this section of TIE-TRK (Tie Trunk):

- TN497
- TN2140B

The Tie Trunk circuit pack fits into a port slot and contains four trunk circuits (see [Figure 5-54](#)). Each tie trunk for the TN497 circuit packs has 2-wire audio connection/signal leads (A and B).

A tie trunk port can also be administered as an access endpoint, which is a non-signaling channel with a voice-grade data bandwidth.



**Figure 5-54. Tie Trunk Interactions**

The number of tests to be implemented for Tie Trunk maintenance depends upon the TIE-TRK circuit packs involved. The test are as follows:

1. NPE Crosstalk Test—Verifies the switch connection operation of the circuit pack. It verifies that the trunk circuitry talks only on the selected time slot on the TDM Bus and that it never crosses over to time slots reserved for other connections.
2. Loop Around and Conference Circuit Test—Verifies the transmission operation of the circuit pack. It verifies that signals are transmitted to and from each port (Loop Around within the port), and it tests the conference capabilities of all ports.

This test may fail due to noise induced by adjacent electric power lines. Customers having this problem should resolve it with their local power company. To temporarily alleviate the alarm caused by the failure of this test, the test may be disabled from trunk administration test field.

3. Several seizure tests, including the following:
  - Tie Trunk Seizure Test verifies the seizure capabilities of the circuit pack. For the TN2140B circuit pack, this test activates the M lead and checks for a response from the distant end within 10 seconds. This test ABORTS on trunk ports administered as access endpoints.
  - Seizure Test (for TN497 circuit packs only)—Verifies the seizure capabilities of the circuit pack. This test seizes the trunk and outputs a “pause.” The port reports the result of the seizure attempt uplink. The test can be disabled via Trunk Group Administration.

4. EPF, M, and E Lead Test ABORTS on trunk ports administered as access endpoints. This test consists of two parts:
  - E lead test—Checks for the proper activation and deactivation of the port's E lead.
  - M lead test—Checks the M lead EPF current flow. The results of this test allow for distinguishing between circuit pack and external facility failures.
5. Port Audit Update Test (Audit & Update Test for the TN497 circuit pack)—Sends non-disruptive administrative updates to the circuit pack with no expected response. The test updates the translation information on individual ports of the Tie Trunk. Except for the TN497 circuit pack, these updates include:
  - Immediate, automatic, wink start, or delay dial; for the TN2140B, continuous-seize-ack
  - For the TN2140B, continuous or discontinuous.
  - Rotary or DTMF senderization in or out
  - Disconnect timing
  - DMTF time slot

Additional in-line testing is performed while a call is in progress. Thus, many in-line errors may occur during operation. See the Error Log table for a description of these errors. These errors may be reproduced by using the trunk (making a call), and checking their occurrence in the Hardware Error Log.

Before a maintenance test can be run on a port, the port is required to be idle. Except for a TN497 circuit pack, if an incoming call seizes the port which is being tested by maintenance, the test is aborted, and the incoming call proceeds.

Non-TN497 circuit packs can be configured for back-to-back testing (also known as connectivity testing) by making translation and cross-connect changes. This testing configuration allows for the connection of Tie Trunks back-to-back in the same switch to verify the operation of Tie Trunk ports. The tests can be performed in either the E&M or simplex modes.

5 Maintenance Objects for DEFINITY ONE  
TIE-TRK (Tie Trunk)

5-1164

**Hardware Error Log Entries and Test to Clear Values**

Table 5-487. TIE Trunk Error Log Entries

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
0 <sup>1</sup>	0	Any	Any	Any	test port PCSSpp s r 1
1 (a) <sup>2</sup>	16384 <sup>2</sup>	None <sup>2</sup>	WARNING <sup>2</sup>	OFF <sup>2</sup>	
1 (b) <sup>2</sup>	57476 <sup>2</sup>	None <sup>2</sup>	WARNING <sup>2</sup>	OFF <sup>2</sup>	
1 (c) <sup>2</sup>	57477 <sup>2</sup>	None <sup>2</sup>	WARNING <sup>2</sup>	OFF <sup>2</sup>	
1 (d)	57483	None <sup>3</sup>	WARNING	OFF	
1 (e) <sup>2</sup>	57485 <sup>2</sup>	None <sup>2</sup>	WARNING <sup>2</sup>	OFF <sup>2</sup>	
15 (f)	Any	Port Audit Update (#36); Audit and Update (#36)			
18 (g)	0	busyout trunk <grp/mbr>	WARNING	OFF	release trunk <grp/mbr>
130 (h) <sup>2</sup>		None <sup>2</sup>	WARNING	ON	test trunk <grp>/<mbr>
257 (i)	57473	None	WARNING	OFF	
257 (j)	57474	None	WARNING	OFF	
257 (k)	57475	None	WARNING	OFF	
513	Any	EPF M and E Lead (#74)	MAJ/MIN/ WRN <sup>1</sup>	OFF	test port PCSSpp sh r 3
769	57481	EPF M and E Lead (#74)	MAJ/MIN/ WRN <sup>1</sup>	ON	test port PCSSpp sh r 3
1025 (l)	Any <sup>2</sup> 57392 <sup>3</sup>	None	MAJ/MIN/ WRN <sup>1,2</sup> MINOR <sup>3</sup>	OFF	
1281	Any	EPF M and E Lead (#74)	MAJ/MIN/ WRN <sup>1</sup>	ON	test port PCSSpp sh r 3
1537		Loop Around and Conference (#33)	MAJ/MIN/ WRN <sup>1</sup> , MINOR	ON	test port PCSSpp l r 3
1793		Tie Trunk Seizure (#73); Seizure (#73) <sup>3</sup> ; Tie Trunk Dial (#747)	MAJ/MIN/ WRN; MINOR	OFF	test port PCSSpp sh r 2; test port PCSSpp s r 2
2049		NPE Crosstalk (#6)	MAJ/MIN/ WRN <sup>1</sup> , MINOR	ON	test port PCSSpp l r 3 <sup>2</sup>

Continued on next page

5 Maintenance Objects for DEFINITY ONE  
TIE-TRK (Tie Trunk)

5-1165

Table 5-487. TIE Trunk Error Log Entries — *Continued*

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
2305 (m)	50944	None; Seizure (#73) <sup>3</sup> ; Tie Trunk Dial (#747)			
2305 (m)	57424	Tie Trunk Dial (#747)			
2561 <sup>3</sup>	0 <sup>3</sup>	None <sup>3v</sup>	WARNING <sup>3</sup>	OFF <sup>3</sup>	
2817 <sup>3</sup>	0 <sup>3</sup>	None <sup>3</sup>	MINOR <sup>3</sup>	OFF <sup>3</sup>	
3073 <sup>3</sup>	0 <sup>3</sup>	None <sup>3</sup>			
3840 (n)	8000	Analog Transmission (#844-848)		OFF	
3841 (n)		Analog Transmission (#844-848)	MINOR	OFF	test analog testcall PCSS pp r 2

1. Minor alarms on this MO may be downgraded to Warning alarms based on the values used in the **set options** command. If the MINOR alarm is not downgraded by the **set options** values, the MINOR alarm is upgraded to a MAJOR alarm if 75 percent of the trunks in this trunk group are alarmed.
2. Non-TN497 circuit packs only.
3. TN497 circuit packs only.

## Notes:

- a. Digit time-out. This occurs when the far-end PBX begins transmitting digits too late (10 seconds) after receiving the signal indicating ready to receive digits (if any). This can occur on an incoming immediate, wink, or delay dial line. Check the far-end PBX to ensure a translation match at both ends.
- b. Rotary dial before wink. This occurs when the far-end PBX starts dialing before the PBX sends the wink on a wink-start or (for non-TN439 circuit packs) on a delay-dial line. Check the far-end PBX to ensure a translation match at both ends.
- c. Rotary dial too early. This occurs when the far-end PBX starts dialing too soon (about 50ms) after seizure on a wink start or (for non-TN439 circuit packs) on a delay-dial line. Check the far-end PBX to ensure a translation match at both ends.
- d. On hook before wink. This occurs when the far end goes on hook before a wink. Check the far-end PBX to ensure a translation match at both ends.
- e. On an outgoing wink-start or delay-dial trunk, the wink time was too short (less than 80ms) for a valid signal. Check the far-end PBX to ensure a translation match at both ends.

5 Maintenance Objects for DEFINITY ONE  
TIE-TRK (Tie Trunk)

5-1166

- f. This is a software audit error that does not indicate any hardware malfunction. Run the Short Test Sequence and investigate associated errors (if any).
- g. This indicates that the trunk in question has been busied-out by maintenance personnel.
- h. This indicates that the circuit pack has been removed or has been insane for more than 11 minutes. To clear the error, reinsert or replace the circuit pack.
- i. The rotary dial rate was too slow (less than eight pulses per second.) Check the far-end PBX to ensure a translation match at both ends.
- j. The rotary dial rate was too fast (more than 12 pulses per second.) Check the far-end PBX to ensure a translation match at both ends.
- k. The time between digits was too short (less than 300ms). Check the far-end PBX to ensure a translation match at both ends.
- l. This indicates that the trunk is still seized with an incoming call. The far-end PBX is not releasing the trunk after the call is dropped. A Minor alarm is generated every four minutes until the far-end PBX releases the trunk. Check the far-end PBX for problems.

Once the trunk is released from the call, the severity of this problem is decreased. If Error Type 1025 does not appear again, this means that the problem has been corrected. Verify that Error Type 1025 does not reappear in the Error Log.

- m. Reorder message. Trunk could not be seized. This error causes the Tie Trunk Seizure Test (#73) to run, and it is considered a problem only if the Seizure Test fails (in which case Error Type 1793 also shows up). In this case, the trunk may be placed in the "Ready-for-Service" state (shown as "disconnected" by the status command), which allows only incoming calls. Run the Tie Trunk Seizure Test and follow its outlined procedures.
  - n. Test calls made by the Automatic Transmission Measurement System (ATMS) returned measurements that were outside the acceptable limits. Use the **list testcall detail** command to examine specific transmission parameters that are out of spec, and investigate the trunk for that kind of noise. If the noise is acceptable, the limits administered on the "change trunk" screen should be changed.
-

## System Technician-Demanded Tests: Descriptions and Error Codes

---

Always investigate tests in the order presented in the table below when inspecting errors in the system. By clearing error codes associated with the *Loop Around and Conference Circuit Test*, for example, you may also clear errors generated from other tests in the testing sequence.

Order of Investigation	Short Test Sequence	Long Test Sequence	D/ND <sup>1</sup>
NPE Crosstalk Test (#6)		X	ND
Loop Around and Conference Circuit Test (#33)		X	ND
Tie Trunk Seizure Test (#73) <sup>2</sup> , Tie Trunk Dial Test (#747) <sup>3</sup> , Seizure Test (#73) <sup>4</sup>	X	X	ND
Tie Trunk EPF Test (#74) <sup>5</sup>	X	X	ND
Port Audit and Update Test (#36) <sup>6</sup> , Audit and Update Test (#36) <sup>4</sup>	X	X	ND
Analog Transmission Test (#844-848)	(a)	(a)	

- 
1. D = Destructive; ND = Nondestructive
  2. Non-TN439 and non-TN497 circuit packs only
  3. TN439 circuit pack only
  4. TN497 circuit pack only
  5. G3iV1.1-286 and G3iV2-386 only
  6. Non-TN497 circuit packs only

### Notes:

- a. ATMS test are not part of either sequence. They are run either on demand with the **test analog-testcall** command or via the ATMS schedule.
- 

## NPE Crosstalk Test (#6)

One or more NPE reside on each circuit pack with a TDM Bus interface. The NPE controls port connectivity and gain, and provides conferencing functions on a per port basis. The NPE Crosstalk Test verifies that this port's NPE channel talks on the selected time slot and never crosses over to time slots reserved for other connections. If the NPE is not working correctly, one-way and noisy connections may be observed. This test is usually only part of a port's Long Test Sequence and takes 20 to 30 seconds to complete.

5 Maintenance Objects for DEFINITY ONE  
TIE-TRK (Tie Trunk)

5-1168

Table 5-488. TEST #6 NPE Crosstalk Test

Error Code	Test Result	Description/ Recommendation
	ABORT	<p>Could not allocate the necessary system resources to run this test.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
1000	ABORT	<p>System resources required to run this test are not available. The trunk may be busy with a valid call. Use the <b>display trunk xx</b> command to determine the trunk group/member number of the port. Use the <b>status trunk</b> command to determine the service state of the port. If the service state indicates that the port is in use, the port is unavailable for certain tests. (Refer to <a href="#">"status station" on page 4-213</a> for a description of all possible states.) You must wait until the port is idle before retesting.</p> <ol style="list-style-type: none"> <li>1. If the port status is active, but the port is not in use (no connected ports), check the Error Log for Error Type 1025 (see Error Log table for description of this error and required actions). The port may be locked up.</li> <li>2. If the port status is idle, retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
1001	ABORT	<p>System resources required to run this test are not available. This could be due to a failure to seize the port.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
1002	ABORT	<p>The system could not allocate time slots for the test. The system may be under heavy traffic conditions or it may have time slots out-of-service due to TDM-BUS errors. Refer to <a href="#">"TDM-BUS (TDM Bus)" on page 5-1116</a> to diagnose any active TDM-BUS errors.</p> <ol style="list-style-type: none"> <li>1. If the system has no TDM-BUS errors and is not handling heavy traffic, repeat test at 1-minute intervals a maximum of 5 times.</li> </ol>
1003	ABORT	<p>The system could not allocate a tone receiver for the test. The system may be oversized for the number of Tone Detectors present or some Tone Detectors may be out-of-service.</p> <ol style="list-style-type: none"> <li>1. Look for TTR-LEV errors in the Error Log. If present, refer to <a href="#">"TTR-LEV (TTR Level)" on page 5-1223</a>.</li> <li>2. Look for TONE-PT errors in the Error Log. If present, refer to <a href="#">"TONE-PT (Tone Generator)" on page 5-1204</a>.</li> <li>3. If neither condition exists, retry the test at 1-minute intervals a maximum of 5 times.</li> </ol>
1004	ABORT	<p>(Non-TN497 circuit packs only) The port was seized by a valid call during the test. The test has been aborted. Use the <b>display trunk xx</b> command to determine the trunk group/member number of the port. Use the <b>status trunk</b> command to determine the service state of the port. If the service state indicates that the port is in use, the port is unavailable for certain tests. You must wait until the port is idle before retesting.</p>

Continued on next page

5 Maintenance Objects for DEFINITY ONE  
TIE-TRK (Tie Trunk)

5-1169

Table 5-488. TEST #6 NPE Crosstalk Test — *Continued*

Error Code	Test Result	Description/ Recommendation
2000	ABORT	Response to the test request was not received within the allowable time period.
2100	ABORT	Could not allocate the necessary system resources to run this test. This could be due to a failure to seize the port.  1. Retry the command at 1-minute intervals a maximum of 5 times.
Any	FAIL	This test can fail due to on-board or off-board problems. Off-board problems of concern include TDM-BUS faults and faults associated with the tone detectors/tone generators. Clear all off-board problems before replacing the board. Keep in mind that a TDM-BUS problem is usually the result of a faulty board connected to the backplane or bent pins on the backplane.  1. Look for TDM-BUS errors in the error log. If present, refer to the <a href="#">“TDM-BUS (TDM Bus)” on page 5-1116</a> .  2. Look for TONE-BD and/or TONE-PT errors in the error log. If present, refer to the TONE-BD Maintenance documentation and <a href="#">“TONE-PT (Tone Generator)” on page 5-1204</a> .  3. Test the board when the faults from steps 1 and 2 are cleared. Replace the board only if the test fails.
	PASS	The port is correctly using its allocated time slots. User-reported troubles on this port should be investigated using other port tests and examining station, trunk or external wiring.
0	NO BOARD	The test could not relate the internal ID to the port (no board).  1. Check to ensure that the board translations are correct. Translate the board, if necessary.  2. Issue the <b>busyout board</b> command.  3. Issue the <b>reset board</b> command.  4. Issue the <b>release busy board</b> command.  5. Issue the <b>test board</b> command. This should re-establish the linkage between the internal ID and the port.

## Loop Around and Conference Circuit Test (#33)

This test checks the reflective loop around, and conference capabilities of a tie trunk port circuit. The test uses 404-Hz, 1004-Hz, and 2804-Hz tones. This is an on-board test only, and each tone is transmitted through the loop and checked upon return.

This test may fail due to noise induced by adjacent electric power lines. Customers having this problem should resolve it with their local power company. To temporarily alleviate the alarm caused by the failure of this test, the test may be disabled from the trunk administration Test field.

Table 5-489. TEST #33 Loop Around and Conference Circuit Test

Error Code	Test Result	Description/ Recommendation
	ABORT	Could not allocate the necessary system resources to run this test. This could be due to a failure to seize the port.  1. Retry the command at 1-minute intervals a maximum of 5 times.
7	ABORT	The conference circuit test was aborted.  1. Retry the command at 1-minute intervals a maximum of 5 times.
129	ABORT	The 404-Hz reflective loop around test aborted. Response to the test request was not received within the allowable time period.
131		The 1004-Hz reflective loop around test aborted. Response to the test request was not received within the allowable time period.
133		The 2804-Hz reflective loop around test aborted. Response to the test request was not received within the allowable time period.  1. Retry the command at 1-minute intervals for a maximum of 5 times.
1000	ABORT	System resources required to run this test are not available. The trunk may be busy with a valid call. Use the <b>display trunk xx</b> command to determine the trunk group/member number of the port. Use the <b>status trunk</b> command to determine the service state of the port. If the service state indicates that the port is in use, the port is unavailable for certain tests. You must wait until the port is idle before retesting.  1. If the port status is active, but the port is not in use (no calls), check the Error Log for Error Type 1025 (see Error Log table for a description of this error and required actions). The port may be locked up.  2. If the port status is idle, retry the command at 1-minute intervals a maximum of 5 times.

*Continued on next page*

5 Maintenance Objects for DEFINITY ONE  
TIE-TRK (Tie Trunk)

5-1171

Table 5-489. TEST #33 Loop Around and Conference Circuit Test — *Continued*

Error Code	Test Result	Description/ Recommendation
1002	ABORT	<p>The system could not allocate time slots for the test. The system may be under heavy traffic conditions or it may have time slots out-of-service due to TDM-BUS errors. Refer to <a href="#">“TDM-BUS (TDM Bus)” on page 5-1116</a> to diagnose any active TDM-BUS errors.</p> <ol style="list-style-type: none"> <li>1. If system has no TDM-BUS errors and is not handling heavy traffic, repeat test at 1-minute intervals a maximum of 5 times.</li> </ol>
1003	ABORT	<p>The system could not allocate a tone receiver for the test. The system may be oversized for the number of Tone Detectors present, or some Tone Detectors may be out-of-service.</p> <ol style="list-style-type: none"> <li>1. Look for TTR-LEV errors in the Error Log. If present, refer to <a href="#">“TTR-LEV (TTR Level)” on page 5-1223</a>.</li> <li>2. Look for TONE-PT errors in the Error Log. If present, refer to <a href="#">“TONE-PT (Tone Generator)” on page 5-1204</a>.</li> <li>3. If neither condition exists, retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
1004	ABORT	<p>(Non-TN497 circuit packs only.) The port was seized by a valid call during the test. The test has been aborted. Use the <b>display trunk xx</b> command to determine the trunk group/member number of the port. Use the <b>status trunk</b> command to determine the service state of the port. If the service state indicates that the port is in use, the port is unavailable for certain tests. You must wait until the port is idle before retesting.</p>
1018	ABORT	<p>The test has been disabled via administration.</p> <p>Verify that the 'Maintenance Test' field on the 'Trunk Group' form is set to 'n'. To enable the test, issue the <b>change trunk-group x</b> command (x equals the number of the trunk group to be tested). Then, change the entry in the <code>Maintenance Test</code> field on the form to <b>y</b>.</p>
2000	ABORT	<p>Response to the test request was not received within the allowable time period.</p>
2100	ABORT	<p>Could not allocate the necessary system resources to run this test. This could be due to a failure to seize the port.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>

*Continued on next page*

Table 5-489. TEST #33 Loop Around and Conference Circuit Test — *Continued*

Error Code	Test Result	Description/ Recommendation
7, 129, 131, or 133	FAIL	<p>The conference capabilities of the port failed (Error Code 7).</p> <p>The reflective 404-Hz Tone Test failed. No transmission was detected to or from the port (Error Code 129).</p> <p>The reflective 1004-Hz Tone Test failed. No transmission was detected to or from the port (Error Code 131).</p> <p>The reflective 2804-Hz Tone Test failed. No transmission was detected to or from the port (Error Code 133).</p> <p>Proceed as follows unless power or tone problems are suspected (see notes on the next page).</p> <ol style="list-style-type: none"> <li>1. To make sure the problem is on-board, disconnect the port from the CO and retry the test. Coordinate this with the CO, or do it after busy hours; otherwise, the CO may put the connection out of service.</li> <li>2. If the retry fails, replace the circuit pack.</li> <li>3. If the retry passes and no troubles have been reported, disable the test. If the retry passes and troubles have been reported, refer the problem to the CO.</li> </ol> <p><b>⇒ NOTE:</b> If the looparound and conference circuit test fails for all ports on a circuit pack, a -5 volt power problem is indicated.</p> <p>If the test fails on more than 1 port, check for errors on the TONE-BD or the TONE-PT. If errors, take appropriate actions. When the tone errors are cleared, rerun the test. If the test fails again, see FAULT ISOLATION above.</p>
	PASS	<p>Tie trunk Loop Around and Conference Test is successful. This port is functioning properly.</p> <ol style="list-style-type: none"> <li>1. If users are reporting troubles, examine loop connections to the port.</li> </ol>
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board).</p> <ol style="list-style-type: none"> <li>1. Check to ensure that the board translations are correct. Translate the board, if necessary.</li> <li>2. Issue the <b>busyout board</b> command.</li> <li>3. Issue the <b>reset board</b> command.</li> <li>4. Issue the <b>release busy board</b> command.</li> <li>5. Issue the <b>test board</b> command. This should re-establish the linkage between the internal ID and the port.</li> </ol>

**Audit Update Test (#36)**

This test sends updates of the Tie Trunk port translation for all ports on the circuit pack that have been translated. The update is non-disruptive and guards against possible corruption of translation data contained on the board. No response message is expected from the circuit pack once it receives translation updates. The port translation data for non-TN497 circuit packs includes the following: Immediate, automatic, wink-start or delay dial trunk, rotary or DTMF senderization in or out, disconnect timing from 10 to 2550ms in 10ms increments, and DMTF time slot. (Continuous-seize-ack is also included for the TN2140B circuit pack.)

Table 5-490. TEST #36 Audit Update Test

Error Code	Test Result	Description/ Recommendation
	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals a maximum of 5 times.
1006	ABORT	(TN497 circuit pack only.) The port is in the out-of-service state. The test cannot be run. 1. Retry the command once the port is in service.
2100	ABORT	Could not allocate the necessary system resources to run the test. This could be due to a failure to seize the port. 1. Retry the command at 1-minute intervals a maximum of 5 times.
	FAIL	Internal System Error. 1. Retry the command at 1-minute intervals a maximum of 5 times.
	PASS	This test passed. Translation information was successfully updated on the circuit pack. 1. If signaling troubles are reported, verify translation information for this port.  (Non-TN497 circuit packs only.) If the trunk is busied out, the test does not run, but it does return PASS.  To verify that the trunk is in-service: 1. Enter <b>status trunk</b> command to verify that the trunk is in-service.  If the trunk is in-service, no further action is necessary. If the trunk is out-of-service, continue to Step 2. 2. Enter <b>release trunk</b> command to put trunk back into in-service. 3. Retry the test command.

Continued on next page

Table 5-490. TEST #36 Audit Update Test — *Continued*

Error Code	Test Result	Description/ Recommendation
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board).</p> <ol style="list-style-type: none"><li>1. Check to ensure that the board translations are correct. Translate the board, if necessary.</li><li>2. Issue the <b>busyout board</b> command.</li><li>3. Issue the <b>reset board</b> command.</li><li>4. Issue the <b>release busy board</b> command.</li><li>5. Issue the <b>test board</b> command. This should re-establish the linkage between the internal ID and the port.</li></ol>

### Tie Trunk Seizure Test (#73), Tie Trunk Dial Test (#747). Seizure Test(#73)

The Tie Trunk Seizure Test activates the M lead and checks for a response from the external end within 10 seconds. This test is applicable only to wink start and delay dial outgoing trunks. (For the TN2140B circuit pack, the trunk must also be continuous-seize-ack and discontinuous-seize-ack).

The Tie Trunk Dial Test seizes the trunk and output pulses a pause digit.

For a port administered as TGU or a TGE, the Seizure Test internally seizes the trunk and output pulses a "pause." The report reports the result of the seizure attempt uplink.

5 Maintenance Objects for DEFINITY ONE  
TIE-TRK (Tie Trunk)

5-1175

Table 5-491. Seizure Tests (#73, #747, #73)

Error Code	Test Result	Description/ Recommendation
	ABORT	Could not allocate the necessary system resources to run this test.  1. Retry the command at 1-minute intervals a maximum of 5 times.
1000	ABORT	System resources required to run this test are not available. The trunk may be busy with a valid call. Use the <b>display trunk xx</b> to determine the trunk group/member number of the port. Use the <b>status trunk</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. You must wait until the port is idle before retesting.  1. If the port status is active, but the port is not in use (no calls), then check the Error Log for Error Type 1025 (see Error Log table for description of this error and required actions). The port may be locked up. The far-end PBX may not be releasing.  2. If the port status is idle, then retry the command at 1-minute intervals a maximum of 5 times.
1004	ABORT	(Non-TN497 circuit packs only.) The port was seized by a valid call during the test. The test has been aborted. Use the <b>display trunk xx</b> to determine the trunk group/member number of the port. Use the <b>status trunk</b> command to determine the service state of the port. If the service state indicates that the port is in use, the port is unavailable for certain tests. You must wait until the port is idle before retesting.  1. Retry the command at 1-minute intervals a maximum of 5 times.
1005	ABORT	This test is not valid for this trunk translation. For this test to run, a delay dial trunk (or, for non-TN497 circuit packs, a wink-start trunk) must be in effect, and the trunk must be outgoing or two-way. Also, for the TN2140B, the trunk must be continuous-seize-ack or discontinuous-seize-ack.  1. Check trunk translation. If it is not a wink-start or delay dial trunk, this abort message should be ignored. (For the TN2140B, disregard this abort on a trunk that is not continuous-seize-ack or discontinuous-seize-ack.)

*Continued on next page*

Table 5-491. Seizure Tests (#73, #747, #73) — Continued

Error Code	Test Result	Description/ Recommendation
1018	ABORT	Test disabled via administration.  1. Verify that the <code>Maintenance Tests?</code> field on the Trunk Group Form is set to <b>n</b> . To enable the test, issue the <b>change trunk-group x</b> command where "x" equals the number of the trunk group to be tested. Then change the entry in the <code>Maintenance Tests?</code> field on the form to <b>y</b> .
1040	ABORT	(Non-TN497 circuit packs only.) This test is not performed for trunk ports administered as access endpoints.  1. Verify this port is an access endpoint by using the <b>display port</b> command.  2. If the port has been administered as an access endpoint, this test should abort.
2000	ABORT	Seizure message is not received back within 10 seconds.  1. Retry the command at 1-minute intervals a maximum of 5 times.  2. If the test continues to fail, check the far-end PBX to ensure a translation match at both ends.  3. Check the facility.
2100	ABORT	Could not allocate the necessary system resources to run the test. This could be due to a failure to seize the port.  1. Retry the command at 1-minute intervals a maximum of 5 times.
3	FAIL	(TN439 circuit packs only.) No dial tone detected from the other end.  1. Retry the command at 1-minute intervals a maximum of 5 times.  2. If the test continues to fail, check the far-end PBX to ensure a translation match at both ends.  3. Check the facility.

*Continued on next page*

Table 5-491. Seizure Tests (#73, #747, #73) — *Continued*

Error Code	Test Result	Description/ Recommendation
	PASS	The relevant seizure test passes. This port is functioning properly. <ol style="list-style-type: none"> <li>1. If users are reporting troubles, examine loop connections to the port, wiring, and stations.</li> </ol>
0	NO BOARD	The test could not relate the internal ID to the port (no board). <ol style="list-style-type: none"> <li>1. Check to ensure that the board translations are correct. Translate the board, if necessary.</li> <li>2. Issue the <b>busyout board</b> command.</li> <li>3. Issue the <b>reset board</b> command.</li> <li>4. Issue the <b>release busy board</b> command.</li> <li>5. Issue the <b>test board</b> command. This should re-establish the linkage between the internal ID and the port.</li> </ol>

### Tie Trunk EPF Test (#74)

This test consists of an E lead and M lead test. The E lead test checks for the proper activation and deactivation of the port's E lead. The M lead test checks the M lead EPF current flow. The processor sends an M lead test request to the circuit pack and receives the results. The returned results are measured to see if a port or external tie trunk line fails.

Table 5-492. TEST #74 Tie Trunk EPF Test

Error Code	Test Result	Description/ Recommendation
	ABORT	Could not allocate the necessary system resources to run the test. This could be due to a failure to seize the port. <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
1	ABORT	Internal System Error. <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>

*Continued on next page*

5 Maintenance Objects for DEFINITY ONE  
TIE-TRK (Tie Trunk)

5-1178

Table 5-492. TEST #74 Tie Trunk EPF Test — *Continued*

Error Code	Test Result	Description/ Recommendation
1000	ABORT	<p>System resources required to run this test are not available. The trunk may be busy with a valid call. Use the <b>display trunk xx</b> to determine trunk group/member number of the port. Use the <b>status trunk</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. You must wait until the port is idle before retesting.</p> <ol style="list-style-type: none"><li>1. If the port status is active, but the port is not in use (no calls), then check the Error Log for Error Type 1025 (see Error Log table for description of this error and required actions). The port may be locked up. The far-end PBX may not be releasing.</li><li>2. If the port status is idle, then retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
1004	ABORT	<p>The port was seized by a valid call during the test. The test has been aborted. Use the <b>display trunk xx</b> to determine the trunk group/member number of the port. Use the <b>status trunk</b> command to determine the service state of the port. If the service state indicates that the port is in use, the port is unavailable for certain tests. You must wait until the port is idle before retesting.</p> <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
1005	ABORT	<p>This test is not valid for this trunk translation. Must be a Type-1 standard trunk for this test to run.</p> <ol style="list-style-type: none"><li>1. Check trunk configuration. If it is not a Type-1 standard trunk, this abort message should be ignored.</li></ol>
1014	ABORT	<p>The test was aborted because the circuit pack has not been inserted into the system.</p> <ol style="list-style-type: none"><li>1. Use the <b>list configuration board</b> command to make sure the circuit pack is inserted in the carrier.</li><li>2. If the board is not inserted, make sure the circuit pack is inserted in the carrier and fully seated.</li></ol>
1040	ABORT	<p>This test is not performed for trunk ports administered as "access endpoints."</p> <ol style="list-style-type: none"><li>1. Verify this port is an access endpoint by using the <b>display port</b> command.</li><li>2. If the port has been administered as an access endpoint, this test should abort.</li></ol>

*Continued on next page*

5 Maintenance Objects for DEFINITY ONE  
TIE-TRK (Tie Trunk)

5-1179

Table 5-492. TEST #74 Tie Trunk EPF Test — *Continued*

Error Code	Test Result	Description/ Recommendation
2000	ABORT	Response to the test request was not received within the allowable time period.
2100	ABORT	Could not allocate the necessary system resources to run the test. This could be due to a failure to seize the port. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
1	FAIL	The E lead test failed due to an on-board port problem. <ol style="list-style-type: none"><li>1. Replace the circuit pack.</li></ol>
2	FAIL	The M lead test failed. The EPF has experienced an overcurrent condition, perhaps due to the external M lead. <ol style="list-style-type: none"><li>1. To make sure the problem is on-board, disconnect the facility from the pack and retry the test.</li><li>2. If the test fails, replace the circuit pack. Otherwise, check the external wiring toward the far-end PBX.</li></ol>
	PASS	Tie Trunk EPF test is successful. This port is functioning properly. <ol style="list-style-type: none"><li>1. If users are reporting troubles, examine loop connections to the port.</li></ol>
0	NO BOARD	The test could not relate the internal ID to the port (no board). <ol style="list-style-type: none"><li>1. Check to ensure that the board translations are correct. Translate the board, if necessary.</li><li>2. Issue the <b>busyout board</b> command.</li><li>3. Issue the <b>reset board</b> command.</li><li>4. Issue the <b>release busy board</b> command.</li><li>5. Issue the <b>test board</b> command. This should re-establish the linkage between the internal ID and the port.</li></ol>

**Transmission Test (#844-848)**

This test is non-destructive.

**NOTE:**

Tests #844-848 are not supported on an International switch.

These tests are run by the Automatic Transmission Measurement System (ATMS). They are not part of the long or short trunk test sequences. Instead, they are run on demand with the **test analog-testcall** command or as part of ATMS scheduled testing.

The test call is run from an analog port on a TN795 Processor circuit pack. It attempts to seize a port and make a call to a terminating test line (TTL) on the trunk's far end. Transmission performance measurements are made and compared to administered thresholds. Errors are generated when results fall outside of "marginal" or "unacceptable" thresholds. Detail and summary measurement reports are obtainable via the **list testcalls** command.

**Table 5-493. TEST #844-848 Transmission Test**

Error Code	Test Result	Description/ Recommendation
1000	ABORT	System resources required to run this test are not available. The port may be busy with a valid call. Use <b>display port PCSSpp</b> to determine the trunk group/member number of the port. Use the <b>status trunk</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port unavailable for this test. You must wait until the port is idle before retesting.  1. If the port status is idle, then retry the command at 1-minute intervals for a maximum of 5 retries.
1001	ABORT	Could not allocate the necessary system resources to run this test.  1. Retry the command at 1-minute intervals for a maximum of 5 retries.
1002	ABORT	The system could not allocate timeslots for the test. The system may be under heavy traffic conditions or it may have timeslots out of service due to TDM bus errors. Refer to <a href="#">"TDM-BUS (TDM Bus)" on page 5-1116</a> to diagnose any active TDM bus errors.  1. If system has no TDM bus errors and is not handling heavy traffic, repeat test at 1-minute intervals for a maximum of 5 retries.
1004	ABORT	The port has been seized by a user for a valid call. Use status trunk to determine when the port is available for testing.  1. Retry the command at 1-minute intervals for a maximum of 5 retries.
1005	ABORT	Trunk has been administered as incoming-only; transmission tests can only be run on outgoing trunks.

*Continued on next page*

Table 5-493. TEST #844-848 Transmission Test — Continued

Error Code	Test Result	Description/ Recommendation
1115	ABORT	The near end test line on the circuit pack could not be allocated. <ol style="list-style-type: none"> <li>1. Verify that the circuit pack is in service and that port 1 is administered and in service with the <b>status port</b> command.</li> <li>2. retry the command at 1-minute intervals for a maximum of 5 retries.</li> </ol>
1900	ABORT	The test completion message was not received from the circuit pack. <ol style="list-style-type: none"> <li>1. Test the TN795 circuit packs.</li> </ol>
1901	ABORT	This error occurs when the TN795 circuit pack uplinks a message that is not the proper response for this test. The anticipated uplink messages are seize, ring or answer. <ol style="list-style-type: none"> <li>1. Verify that the Trunk is administered properly.</li> </ol>
1905	ABORT	Intercept tone detected from far end. <ol style="list-style-type: none"> <li>1. Get the test line data from theand verify it with the far end. Dial the test number manually to see if the TTL is reached. If it is not, then either the number is wrong, or the far end is administered incorrectly.</li> </ol>
1906	ABORT	Reorder tone detected from far end. <ol style="list-style-type: none"> <li>1. See actions for error code 1905.</li> </ol>
1907	ABORT	Other unexpected tone detected from far end. <ol style="list-style-type: none"> <li>1. See actions for error code 1905.</li> </ol>
1913	ABORT	Audible Ring detected from far end. <ol style="list-style-type: none"> <li>1. See actions for error code 1905.</li> </ol>
1914	ABORT	Unidentified interrupted tone detected from far end. <ol style="list-style-type: none"> <li>1. See actions for error code 1905</li> </ol>
1915	ABORT	Busy tone detected from far end. <ol style="list-style-type: none"> <li>1. Since the test line at the far end was busy. Try the test again.</li> <li>2. If the test continues to abort, the problem is with the far end system.</li> </ol>
1918	ABORT	Test progress tone not removed from far end (type 105 test line only). <ol style="list-style-type: none"> <li>1. The problem is with the far end system; a technician at the far end should test the test line (TN795).</li> </ol>
1919	ABORT	Unexpected far end release <ol style="list-style-type: none"> <li>1. The problem is with the far end system; a technician at the far end should test the test line (TN795).</li> </ol>
1920	ABORT	No response from far end. <ol style="list-style-type: none"> <li>1. The problem is with the far end system; a technician at the far end should test the test line (TN795).</li> </ol>

5 Maintenance Objects for DEFINITY ONE  
TIE-TRK (Tie Trunk)

5-1182

Table 5-493. TEST #844-848 Transmission Test — *Continued*

Error Code	Test Result	Description/ Recommendation
1921	ABORT	No data returned from far end. 1. The problem is with the far end system; a technician at the far end should test the test line (TN795).
1922	ABORT	Steady, unidentifiable tone from far end 1. See actions for error code 1905.
1923	ABORT	Broadband energy detected from far end (such as voice or announcement). 1. See actions for error code 1905.
1924	ABORT	No test tone from far end 1. See actions for error code 1905.
1938	ABORT	Near-end self test failed. 1. Test the TN795 circuit pack.
1939	ABORT	Loss self check at 0dBm at 1004 Hz failed. 1. Test the TN795 circuit packs.
1940	ABORT	Far end noise self check failed. 1. The problem is with the far end system; a technician at the far end should test the test line (TN795).
1941	ABORT	High frequency singing return loss self check failed. 1. Test the TN795 circuit pack.
1942	ABORT	Echo return loss self check failed. 1. Test the TN795 circuit pack.
1943	ABORT	Singing return loss self check failed. 1. Test the TN795 circuit pack.
1944	ABORT	Loss self check at -16 dBm at 1004 Hz failed. 1. Test the TN795 circuit pack.
1945	ABORT	Loss self check at -16 dBm at 404 Hz failed. 1. Test the TN795 circuit pack.
1946	ABORT	Loss self check at -16 dBm at 2804 Hz failed. 1. Test the TN795 circuit pack.
1947	ABORT	Noise with tone self check failed. 1. Test the TN795 circuit pack.

*Continued on next page*

5 Maintenance Objects for DEFINITY ONE  
TIE-TRK (Tie Trunk)

5-1183

Table 5-493. TEST #844-848 Transmission Test — *Continued*

Error Code	Test Result	Description/ Recommendation
2000	ABORT	The test timed out while waiting for a response from the TN795 circuit pack. 1. Retry the command at 1-minute intervals for a maximum of 5 retries.
2012	ABORT	An internal software error occurred. 1. Retry the command at 1-minute intervals for a maximum of 5 retries.
2053	ABORT	The test call could not be established, but no information on why is available. 1. Retry the command at 1-minute intervals for a maximum of 5 retries.
2056	ABORT	
	FAIL	Measured transmission performance was in the unacceptable range as administered on the trunk group form. Retrieve a measurement report via the <b>list testcalls</b> command. Make sure that ATMS thresholds are set properly on page 4 of the Trunk Group form. Besides the facility, test failures can be caused by faulty test lines or switch paths. If the measurements point to a facility problem, report the results to the trunk vendor.
8000	FAIL	Measured transmission performance was in the marginal range as administered on the trunk group form. This generally means that the trunk is usable but has an undesirable amount of noise or loss. If the user does not report unacceptable effects, it may not be necessary to take any action. Retrieve a measurement report via the <b>list testcalls</b> command. Make sure that ATMS thresholds are set properly on page 4 of the Trunk Group form.

## TONE-BD (Tone-Clock Circuit Pack)

---

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run <sup>1</sup>	Full Name of MO
	MAJOR	test tone-clock PC	Tone-Clock Circuit Pack
TONE-BD	MINOR	test tone-clock PC	Tone-Clock Circuit Pack
TONE-BD	WARNING	release tone-clock PC	Tone-Clock Circuit Pack

1. P is the port network number (1 for PPN, 2-3 for EPNs). C is the carrier designation (A, B, C, D, or E).

The Tone-Clock circuit pack functionality is provided by two independent objects in the same circuit pack. The tone generator provides all the tones needed by the system and the clock generates the system clocks for the Time Division Multiplex (TDM) Bus and aids in monitoring and selecting internal synchronization references.

When resolving errors/alarms on the Tone-Clock circuit pack, the following should be used also:

- Use the **set tone-clock PC** command to establish the tone and synchronization resources for the system.
- TONE-PT (Tone Generator) Maintenance documentation.
- TDM-CLK (TDM Bus Clock) Maintenance documentation.
- SYNC (Synchronization) Maintenance documentation.

The TN2182 is a combined Tone-Clock-Detector circuit pack which contains a third independent function not available on the TN768 or TN780. The TN2182 contains 8 ports used for all-purpose tone detection. These ports are called Enhanced Tone Receiver ports (ETR-PT) and are described in the documentation for ETR-PT.

## Tone-Clock Circuit Packs and System Reliability Options

---

The following sections describe the relationship between the various System Reliability Options and Tone-Clock circuit pack configurations.

### Standard Reliability Option

---

Systems with the Standard Reliability Option (no duplication options) have one Tone-Clock circuit pack in each port network (PPN and EPN). For the PPN or the EPN this is in the A carrier. This Tone-Clock circuit pack generates clocks and provides system tones for all carriers of the port network it resides on.

## High Reliability Option

---

Systems with the High Reliability Option (duplicated SPE, simplex PNC) have one Tone-Clock circuit pack in each PPN control carrier, A and B. One Tone-Clock circuit pack will be actively generating system clock signals for PPN components, while the other will be in standby mode, ready to take over in the event of a Tone-Clock interchange. Similarly, one Tone-Clock circuit pack will be actively providing system tones for the PPN, while the other will be in standby mode. Normally, the same Tone-Clock circuit pack will be active for both tones and clock signals, but these responsibilities may be divided if neither circuit pack is able to perform both functions. The **status port-network** command will indicate which Tone-Clock circuit pack is actively performing each function.

For systems using the TN2182 Tone-Clock-Detector circuit pack, tone generation and clock generation behaves the same as other clock boards with one being active and one being standby. But the tone detector ports (ETR-PTs) of the TN2182 are always considered available and in-service regardless of the active/standby state of the tones or clock for a specific circuit pack.

EPN Tone-Clock circuit pack configuration is the same as for the Standard Reliability Option. Each EPN Tone-Clock circuit pack will be active for both tones and clock signals for its port network.

## Critical Reliability Option

---

Systems with the Critical Reliability Option (SPE duplication and PNC duplication) have two Tone-Clock circuit packs associated with the PPN, as in the High Reliability Option case, and two more Tone-Clock circuit packs for each EPN. For the EPN, these are in carriers A and B. As in the previous case, one Tone-Clock in each Port Network is active, supplying system clocks and tones, and the other is in standby mode.

## Tone-Clock Interchange Strategy

---

The Tone-Clock circuit pack interchanges are controlled both by manual intervention and by maintenance software strategies.

The manual interchange strategy for Tone-Clock circuit packs differs slightly between the PPN and any EPNs on a system.

## Manual PPN Tone-Clock Interchange

---

In a PPN with more than one Tone-Clock circuit pack, the intention is to assure that the one considered most healthy is active at any given time. *This is independent of the SPE Duplication strategy*, in the sense that the active Tone-Clock circuit pack need not change with an interchange of SPE carriers. Rather, except for the effect of the manual intervention discussed earlier, Tone-Clock interchanges occur only as a result of changes in the health of Tone-Clock circuit packs, as perceived by maintenance software. When both Tone-Clock circuit packs are equally healthy, no preference is given to one over the other, regardless of which SPE carrier is active.

It is possible to manually control Tone-Clock interchanges in three ways.

1. The **standby** Tone-Clock circuit pack may be made unavailable for most purposes by using the **busyout tone-clock PC** command. Such a Tone-Clock may not be selected with console commands, nor with normal maintenance software activities, until it has been made available again with the **restore tone-clock PC** command.



### NOTE:

**busyout tone-clock** is not allowed for active Tone-Clock circuit packs.

2. The SPE processor lock switches may be used to force a particular SPE to be active. *This method overrides all other Tone-Clock interchange controls*. If there is a Tone-Clock circuit pack in the same carrier as the active SPE, it will become active, regardless of its health. If the Tone-Clock circuit pack in the selected SPE was in the *busyout* state (see item 1 above), it will automatically be released and made active. While the lock switches are set for a particular carrier, *no manual intervention or software error detection* will cause an interchange of Tone-Clocks; the Tone-Clock circuit pack in the standby SPE carrier can never become active. If there is no Tone-Clock circuit pack in the selected SPE at the time the switches are set, but one is later installed, the system will interchange to it regardless of its health. If the Tone-Clock circuit pack is removed from an SPE while the switches are set, *no interchange will occur*; the system will have no active tone-clock. When the lock switches are restored to the neutral position, a tone clock interchange will occur only if the standby Tone-Clock circuit pack is healthier than the active one.
3. A particular Tone-Clock circuit pack can be made active by issuing the **set tone-clock PC [override]** command. If the Tone-Clock to be made active is less healthy than the currently active one, no interchange will occur unless the **override** option is specified; without it a message will inform the user that it is required.

Once a Tone-Clock circuit pack is made active by the **set tone-clock PC** command, it will stay active until either the **set tone-clock PC** command is issued again to make the other circuit pack active, or until a fault occurs in the active Tone-Clock circuit pack, which causes the system to interchange Tone-Clocks.

## Manual EPN Tone-Clock Interchange

In an EPN with duplicated Tone-Clock circuit packs, one circuit pack is always *preferred* over the other. This is the Tone-Clock circuit pack in carrier **A**. The intention is that the preferred circuit pack be active whenever it is healthy. Once a failing preferred Tone-Clock circuit pack has been replaced or repaired, the system will make it active as soon as possible.

Control over interchanges for an EPN is accomplished in essentially the same ways as items 1 and 3 in the PPN case above. In addition, when the non-preferred Tone-Clock circuit pack in an EPN is active, and the preferred circuit pack is repaired and proven capable of filling its roles, the system will automatically interchange back to it as soon as possible.

## Software Maintenance Interchange

Interchanges may be instigated by software Tone-Clock maintenance in two ways.

1. A scheduled Tone-Clock circuit pack interchange occurs according to the parameters set by the **change system-parameters maintenance** command. This can be disabled or set to run weekly, but the standard (default) situation is for it to occur daily, at the time specified in the system-parameters list for scheduled maintenance to begin. This interchange will be blocked if the lock switches are set, if the non-preferred Tone-Clock circuit pack in an EPN has been selected with the **set tone-clock** command, if the standby Tone-Clock has been set to the busyout state, or if the clock generation capability of the standby Tone-Clock circuit pack is known to be impaired. When this scheduled interchange occurs, the standby Tone-Clock circuit pack becomes active for a period of 20 seconds to test its ability to generate clock signals, and then is returned to standby mode.
2. Unscheduled interchanges occur when on-board Tone-Clock circuit pack maintenance, or ongoing switch maintenance tests of **TONE-BD**, **TONE-PT**, or **TDM-CLK** uncover failures serious enough to raise any MAJOR or MINOR alarm against the active Tone-Clock circuit pack.

## International Settings [G3i V2]

---

The TN780 Tone-Clock circuit pack uses three firmware configuration parameters for international support [G3i V2]. The following two are automatically set by the software load for the targeted country:

- The circuit pack's country-code (USA, ITALY, AUSTRALIA, etc.)
- The circuit pack's companding mode (mu-Law or A-Law)

The third configuration parameter is used only for Italy (country code: ITALY), and selects whether *new* versus *old* ISPT (Istituto Superiore Poste Telegrafi) tones will be used for dial and confirmation tones. Values for dial confirmation tone can be set independently on the **change system-parameters miscellaneous** form.

Whenever such changes are made, the effects are immediately enforced on all TN780 Tone-Clock circuit packs without disrupting tone or timing services.

## Italian Tone Settings (New ISPT Value)

---

Tone	Default	Old ISPT Value
Dial	Continuous	Cadenced
Confirmation	Cadenced	Continuous

In addition the TN780 allows customization of up to six system tones in order to meet specific country needs. These changes are made via the **change system-parameters country-options** form.

The TN2182 allows the same International changes as the TN780 but allows the customization of up to 24 system tones in order to meet specific country needs. These changes are made via the **change system-parameters country-options** form.

## How to Replace a Tone-Clock Circuit Pack

Replacing the Tone-Clock circuit pack is a service-disrupting procedure on Port Networks with a single Tone-Clock, because the Tone-Clock circuit pack is always needed to generate clocks for its network. For EPN Tone-Clock replacement where no second Tone-Clock circuit pack exists, only that EPN is affected. When the circuit pack is removed, all calls are dropped immediately, the EPN enters emergency transfer within one minute, and no calls can be set up from or to that EPN. However, if the PPN Tone-Clock is removed for replacement in a Standard Reliability Option system, the System Emergency Transfer feature is activated within milliseconds, and the entire system is disrupted; no calls can be placed, and existing calls are dropped.

When replacing the Tone-Clock circuit pack, always replace it with a comparable Tone-Clock circuit pack for the system. See the following table:

System Type	Tone-Clock Circuit Pack Code
One-port network single-carrier cabinet system without High or Critical Reliability.	TN756, TN768, TN780 TN2182 [G3iV4-386]
One-port network system without High or Critical Reliability (multicarrier cabinet).	TN768, TN780
Two-port network single-carrier cabinet system without High or Critical Reliability.	TN768, TN780 TN2182 [G3iV4-386]
One- or two-port network without High or Critical Reliability.	TN768, TN780 TN2182 [G3iV4-386]

- **TN768**—This is the general purpose Tone-Clock circuit pack for port networks on a G3i switch. It can be used in every situation except as the Master Tone-Clock circuit pack when a Stratum 3 Clock is administered.
- **TN780**—The Stratum 3 Clock feature requires the use of this circuit pack code for the PPN (in both carriers of High and Critical Reliability systems). The Stratum 3 Clock will operate only with this code as the Master Tone-Clock circuit pack. The TN780 circuit pack is upward compatible with the TN768 code, and can be used in any place a TN768 would be allowed. The TN780 is used in many countries outside the U.S. where the TN768 does not provide local tones.
- **TN2182**—This Tone-Clock-Detector may be used anywhere a TN768 or TN780 is used with the exception of configurations requiring Stratum 3 Clock. The TN2182 may be used in all country configurations.

## Port Networks with a Single Tone-Clock Circuit Pack

### This procedure is destructive.

1. Pull out the defective Tone-Clock circuit pack. This will remove the clocks and cause the system to activate emergency measures:
  - For the PPN Tone-Clock, the system will immediately go into the Emergency Transfer state.
  - For an EPN Tone-Clock, all calls to and from the EPN will drop and the EPN will activate Emergency Transfer within about one minute, but the rest of the system should operate normally.
2. Insert a new Tone-Clock circuit pack. The system will detect the return of the clocks and will automatically recover as follows:
  - If the Tone-Clock circuit pack being replaced is in the Processor Port Network, the system will perform a **reset system 2 (system cold 2 restart)** automatically. First, all red LEDs of the PPN will come on and off within 30 seconds. Then, all red LEDs of any Expansion Port Networks will come on and go off within the next 30 seconds.
  - If the Tone-Clock circuit pack being replaced is in an Expansion Port Network, the system will reset the EPN (**EPN cold restart**) and all the red LEDs of the EPN will come on and go off within 30 seconds.
3. If the red LEDs come on but do not go off within 30 seconds, pull the circuit pack out and reseat it. If the LEDs perform as expected this time, continue with step 6. Otherwise, there may be a problem with the TDM Bus; possibly a bent pin in the Tone-Clock circuit pack slot. Follow the directions in the TDM-BUS maintenance section.
4. If the red LEDs did light, as explained above, then go to Step 6. If the red LEDs do NOT light, as explained above, then go on to Step 5.
5. Restart the affected Port Network:
  - In the PPN, restart the system via the **reset system 2** command.
  - In an EPN, restart the EPN by resetting its Expansion Interface circuit pack via the **reset board** command, using the board address 1a01 for EPN1 and 1a02 for EPN2.

If this step should fail, follow normal escalation procedures.

6. Test the new Tone-Clock circuit pack to verify that it is functioning properly, using the **test tone-clock PC long** command, and verify that the system is operational by placing several phone calls. Where possible, try calls into, out from, and within the affected Port Network.

If the system is not operating properly, follow normal escalation procedures.

## Port Networks with Two Tone-Clock Circuit Packs:

1. If both Tone-Clock circuit packs in a Port Network need to be replaced, first replace and test the one that is in standby mode. Make sure that it is healthy and active before replacing the second one. Make sure the Tone-Clock circuit pack to be replaced is in Standby Mode by displaying its status via the **status port-network** command or making sure its yellow LED is off.

The active/standby state of a Tone-Clock circuit pack may also be determined by looking at its LED. A continuously lit red LED on the Tone-Clock circuit pack indicates a reported fault on one or more of the maintenance objects on the circuit pack. Flashing patterns of the yellow and green LEDs correspond to the following service states: **Tone-Clock LED Flashing Codes**

Condition	Tone-Clock Circuit State	Explanation
"flashing yellow" 2.7 seconds on,.3 seconds off	active	An external timing source is being used as a synchronization reference. <sup>1</sup>
"flashing yellow".3 seconds on, 2.7 seconds off	active	The local oscillator on the Tone-Clock circuit pack is being used as a synchronization reference.
"yellow" on continuously	active	The circuit pack has been reset but has not been told which synchronization source to use.
"yellow" LED off	standby	The circuit pack is in standby mode, (neither generating tones nor supplying clocks).
"jingle bells" green and yellow.1 sec on,.2 sec off,.1 sec on,.4 sec off,.4 sec on,.4 sec off	standby	Maintenance software is testing the standby circuit pack (the standby Tone-Clock is providing tones).
"double blink yellow".3 sec on,.3 sec off,.3 sec on, 2.4 sec off	active	TN2182 has lost all external references and is in holdover mode.
"other green and yellow patterns"	active	Maintenance software is testing the active circuit pack.
random yellow	standby	If the circuit pack is a TN2182, the yellow LED may come on and off intermittently as ETR-PTs on the board are used for tone detection services.

1. For a Tone-Clock in the master port network, the external source is the primary or secondary DS1 source, or a Stratum 3 clock. For a Tone-Clock in a slave port network, the external source is the Expansion Interface circuit pack.

2. If the Tone-Clock circuit pack to be replaced is active, then switch to the other Tone-Clock circuit pack by doing the following:
  - **set tone-clock PC**—where PC is the Standby Tone-Clock circuit pack. Since the system is designed to operate primarily on the preferred tone clock, the set tone-clock PC command should be used to make the preferred tone board active when maintenance activity is completed. There is no preferred tone clock for the PPN, but carrier A is preferred for EPNs.
  - **status system**—verify the Tone-Clock circuit pack switched to the other Tone-Clock circuit pack or check the LEDs. The yellow LED of the new Standby Tone-Clock circuit pack should be off (provided maintenance is not running on it) and the yellow LED of the active Tone-Clock circuit pack should be blinking.
  - If the interchange was not successful, the standby Tone-Clock circuit pack may be defective. In particular, if the error message “must use override” is displayed, fix the standby Tone-Clock circuit pack before attempting to replace the active one.
3. If the Tone-Clock circuit pack to be replaced is in the PPN, it is recommended, but not required, that the SPE carrier containing it be locked in standby mode by executing an interchange if necessary, and locking the SPE-Select switches. This protects you from disrupting service in case of inadvertent errors in replacing the circuit pack.

 **NOTE:**

If the SPE-Select switches are locked, be sure to release them at the conclusion of the replacement procedure.

4. Pull out the defective Tone-Clock circuit pack. No calls should be affected. If this is a TN2182 circuit pack, some ETR-PTs may be in use and removal of the pack will affect some individual users. It may be less disruptive to busyout the standby TN2182 before removing it.
5. Insert a new Tone-Clock circuit pack of the appropriate code in the same slot where the defective Tone-Clock circuit pack was removed.
6. Test the new Tone-Clock circuit pack via the **test tone-clock PC** command to make sure it is functioning properly. If the Tone-Clock circuit pack is being replaced due to loss of clocks, the Clock Health Inquiry (#46) will still report a failure, proceed with the next step.

7. To verify that the new Tone-Clock circuit pack is able to generate clocks for the system, switch to the new Tone-Clock circuit pack via the **set tone-clock PC override** command, and execute **test tone-clock PC**. (In a PPN, the SPE-Select switches must be in the auto position.)



**CAUTION:**

*If the new Tone-Clock circuit pack is not able to generate system clocks, this procedure becomes destructive. The system will detect a loss of clock and recover accordingly.*

In this case if the Tone-Clock circuit pack being replaced is in the PPN the system will perform a reset system 2 (cold 2 restart) automatically. If the Tone-Clock circuit pack being replaced is in an EPN, the system will reset the EPN (EPN cold restart). After either type of restart, the faulty Tone-Clock circuit pack will be in standby mode. Since the replacement procedure was not successful, follow normal escalation procedures. **If the new Tone-Clock circuit pack is able to generate system clocks, there will be no system disruption.**

8. Place several phone calls.
9. After replacing a Tone-Clock circuit pack in an SPE, if the SPE lock switches were set during the procedure, they should be released. Additionally, after repairs in an EPN, the **set tone-clock PC** command should be used if required to make the preferred Tone-Clock circuit pack active.

**Hardware Error Log Entries and Test to Clear Values**

---

Tone-Clock Circuit Pack Error Log Entries

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
0 <sup>1</sup>	0	Any	Any	Any	test tone-clock PC sh
1(a)	0	Circuit pack removed or SAKI Sanity Test (#53)	MINOR	ON	
18(b)	0	busyout tone-clock PC	WARNING	OFF	release tone-clock PC
23(c)	0	None	WARNING	OFF	
125(d)		None	MINOR	ON	
126(e)		None	MINOR	ON	
257	65535	Control Channel Test (#52)	MINOR	ON	test tone-clock PC r 20
257(f)	Any	None			

5 Maintenance Objects for DEFINITY ONE  
TONE-BD (Tone-Clock Circuit Pack)

5-1194

## Tone-Clock Circuit Pack Error Log Entries

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
513(g)	Any	None			
769(h)	4358	None			
1025(i)	4363	NPE Audit Test (50)			test tone-clock PC sh
1538(j)	Any	None	MINOR	ON	
2049(k)	0	Clock Health Inquiry Test (#46)	MAJOR	ON	set tone-clock PC override
2305(k)	0	Clock Health Inquiry Test (#46)	MAJOR	ON	set tone-clock PC override
2561(l)	Any	None	MAJOR	ON	
3329(m)	0	None	MINOR/ WARNING <sup>2</sup>	OFF	set tone-clock PC
3840(n)	Any	None			
3848(o)	0	Clock Health Inquiry Test (#46)			set tone-clock PC override
3872(p)	0	None			set tone-clock PC override
3999 (q)	Any	None			

1. Run the Short Test Sequence first. If all tests pass, run the Long Test Sequence. Refer to the appropriate test description and follow the recommended procedures.
2. Minor alarms on this MO may be downgraded to Warning alarms based on the value used in the **set options** command.

## Notes:

- a. Error Type 1—This error indicates the circuit pack totally stopped functioning or it was physically removed from the system.

 **NOTE:**

The alarm is logged approximately 11 minutes after the circuit pack is removed/SAKI Sanity Test (#53) fails.

If the circuit pack is not present in the system, insert a circuit pack in the slot indicated by the error to resolve the error.

If the circuit pack is present in the system, it is faulty and must be replaced. See [“How to Replace a Tone-Clock Circuit Pack” on page 5-1189](#).

If the faulty circuit pack is in standby mode, a MINOR alarm is raised, but no other system action is taken. If the circuit pack is the active Tone-Clock, further effects of this error depend on the Reliability Option for the switch.

Table 5-494. Effect of Error Type 1 on an Active Tone-Clock Circuit Pack

Reliability Option	Location of Tone-Clock Circuit Pack	
	PPN	EPN
Standard	System Emergency Transfer (entire system affected)	Emergency Transfer in the affected EPN
High	Interchange to standby Tone-Clock in the PPN	Emergency Transfer in the affected EPN
Critical	Interchange to standby Tone-Clock in the PPN	Interchange to standby Tone-Clock in the affected EPN

If an interchange is attempted and the system is unable to activate the standby Tone-Clock, Emergency Transfer is activated. If the problem is in the PPN the entire system is affected. Otherwise only the EPN in question is affected. When this happens, both circuit packs are faulty and must be replaced. See the preceding section, [“How to Replace a Tone-Clock Circuit Pack”](#).

If a successful interchange occurs in response to a failure of the active Tone-Clock, or if a standby Tone-Clock fails, the faulty Tone-Clock should be replaced.

- b. Error Type 18—The indicated Tone-Clock circuit pack has been made unavailable via the **busyout tone-clock PC** command. This error applies only to High or Critical Reliability systems (an active Tone-Clock may not be busied out). To resolve this error, execute **release tone-clock PC**.
- c. Error Type 23—The circuit pack has been logically administered but not physically installed. Installing the circuit pack will resolve the alarm.
- d. Error Type 125—A wrong circuit pack is inserted in the slot where this circuit pack is logically administered. To resolve this problem, either remove the wrong circuit pack and insert the logically administered circuit pack OR use the **change circuit-pack** command to readminister this slot to match the circuit pack inserted.
- e. Error Type 126—The port network specified in the PORT field of the error log entry booted up without a Tone-Clock circuit pack, or with a one that cannot communicate at all with the system. The error is logged five minutes after the port network is restarted. If no circuit pack is present, install one of the proper code. If there is a circuit pack present, replace it. See [“How to Replace a Tone-Clock Circuit Pack” on page 5-1189](#). If replacement does not solve the problem, follow normal escalation procedures.

5 Maintenance Objects for DEFINITY ONE  
TONE-BD (Tone-Clock Circuit Pack)

5-1196

- f. Error Type 257—This error indicates transient communication problems with this circuit pack. This error is not service-affecting and no action is required.
- g. Error Type 513—This circuit pack has an on-board hardware failure. Replace the circuit pack using the procedure described in p [“How to Replace a Tone-Clock Circuit Pack” on page 5-1189](#).
- h. Error Type 769—This error can be ignored, but look for other errors on this circuit pack.
- i. Error Type 1025—This error is not service-affecting and no action is required.
- j. Error Type 1538—The circuit pack was taken out of service because of an excessive rate of uplink messages. Use **test tone-clock PC long** to reset the circuit pack and put it back into service. If the command is not successful, replace the circuit pack using the procedure described in [“How to Replace a Tone-Clock Circuit Pack” on page 5-1189](#). If the alarmed circuit pack is the active Tone-Clock of a duplicated pair, first interchange Tone-Clocks via the **set tone-clock PC** command to avoid a service outage. If the error occurs again within 15 minutes, follow normal escalation procedures.
- k. Error Type 2049 or 2305—These errors indicate the loss of one or more clock signals from the reported Tone-Clock circuit pack, which was active at the time of the error. The effect of any of these errors is described in the table for error type 1. Diagnosis of the problem is the same for all four error types, with the exception noted below.
  - 1. Examine the Hardware Error Log for errors reported against circuit packs in the same Port Network, especially TDM-CLK, TONE-BD, DUPINT, SW-CTL, and EXP-INTF. Follow the repair or replacement procedures indicated for any such errors found.
  - 2. If the error is not corrected by resolving errors found in step 1, the Tone-Clock circuit pack should be replaced. See [“How to Replace a Tone-Clock Circuit Pack” on page 5-1189](#).

**NOTE:**

Replacing the circuit pack and retesting it with the **test tone-clock** command is not adequate to retire this alarm and return the Tone-Clock Circuit Pack to full service; the Clock Health Inquiry test (#46) will continue to fail. Because the ability to generate clocks was considered lost, once any repairs have been made it is necessary to execute the **set tone-clock PC override** command, forcing the circuit pack to become active. If the problem has not actually been corrected, this action may cause a disruption in service for active digital facilities users.

3. If error 2305 or 3848 persists, all clock signals from the indicated board were lost. If the reported Tone-Clock circuit pack is in a Port Network with duplicated Tone-Clocks, the problem may lie with the circuit pack responsible for selecting the active Tone-Clock circuit pack (the *t/c selector*).
  - For a PPN, the *t/c selector* is the DUPINT circuit pack on carrier A.
  - For an EPN, the *t/c selector* is the active EXP-INTF circuit pack that is connected to the PPN. This is EXP-INTF 2A01 or 2B02 for EPN1 and 3A01 or 3B02 for EPN2.

The *t/c selector* circuit pack of interest is the one which was active at the time the error was logged. This is the currently active *t/c selector* unless there has been an SPE interchange for PPN problem, or an EXP-INTF link switch for EPN problem, In order to determine whether an interchange has occurred since the TONE-BD error, examine the **display initcauses** log for SPE interchanges, and EXP-LNK entries in the hardware error log for expansion link interchanges.

If the *t/c selector* circuit pack was not replaced as part of the previous step, replace it now. Follow procedures described in “Replacing Defective SPE Circuit Packs” in Chapter 6, “Reliability Systems: A Maintenance Aid” for the DUPINT circuit pack, or in the EXP-INTF section of this chapter for the Expansion Interface.

4. If the error has not been corrected at this point, there is a problem with the TDM Bus within the Port Network containing the reported Tone-Clock circuit pack. This may include TDM Bus intercarrier cables, Bus terminators, bent pins on the backplane, and errors on any circuit pack plugged into the same Port Network. Refer to the TDM-BUS section.
  5. If the problem persists, follow normal escalation procedures.
- I. Error Type 2561—This error indicates that a Tone-Clock circuit pack, with a different circuit pack code as required for this system, has been inserted in the port slot as shown in the Hardware Error Log. To resolve this error, refer to [“How to Replace a Tone-Clock Circuit Pack” on page 5-1189](#) for an appropriate circuit pack code and replace the Tone-Clock circuit pack according to the procedures indicated for this system. The meanings of the aux data values are as follows:

1001	A TN756 Tone-Clock circuit pack is in the PPN of a one port network system without High or Critical Reliability (Multicarrier Cabinet).
1002	A TN756 Tone-Clock circuit pack is in the EPN of a one port network system without High or Critical Reliability (Multicarrier Cabinet).

5 Maintenance Objects for DEFINITY ONE  
TONE-BD (Tone-Clock Circuit Pack)

5-1198

1001	A TN756 Tone-Clock circuit pack is in the PPN of a one port network system without High or Critical Reliability (Multicarrier Cabinet).
1003	Either a TN741 or TN714 Tone-Clock circuit pack (instead of a TN768, TN780 or TN2182) is in a one port network system without High or Critical Reliability (Multicarrier Cabinet).
1004	Either a TN741 or TN714 Tone-Clock circuit pack (instead of a TN768, TN780 or TN2182) is in a High or Critical Reliability system.
1005	Same as for aux value 1004.

- m. Error Type 3329—The system attempted but failed to interchange Tone-Clock circuit packs. (This error occurs only in Port Networks with duplicated Tone-Clocks.) The fault may lie in the standby Tone-Clock or in the circuit pack that controls selection of the active Tone-Clock (the *t/c selector*). The goal of the following procedure is to ensure that both Tone-Clocks can be interchanged into while either *t/c-selector* circuit pack is active.
1. Examine the Error Log for errors reported against circuit packs in the same Port Network, paying special attention to TDM-CLK, TONE-BD, DUPINT, SW-CTL, and EXP-INTF. Follow the procedures indicated for any such errors found. After eliminating the above potential problem sources, proceed with the following steps.
  2. Determine which circuit pack was controlling the choice of Tone-Clock at the time the error occurred.
    - For a PPN, the *t/c selector* is the DUPINT circuit pack on the A-carrier.
    - For an EPN, the *t/c selector* is the active EXP-INTF circuit pack that is connected to the PPN. This is EXP-INTF 2A01 or 2B02 for EPN1 and 3A01 or 3B02 for EPN2.

The *t/c-selector* circuit pack of interest is the one which was active at the time the error was logged. An EXP-LNK interchange since the time of the error may have made that circuit pack the current standby. Determine whether an interchange affecting the *t/c selector* has occurred since the TONE-BD error. When investigating an EPN Tone-Clock, look for EXP-LNK entries in the hardware error log for PNC interchanges, which would affect the EXP-INTF.

3. If the *t/c selector* has not undergone an interchange since the error occurred, go to the next step. If such an interchange has taken place, interchange back to the formerly active *t/c selector*. Use the **set expansion-interface** command when investigating an EPN Tone-Clock.) If the interchange attempt fails due to other errors, resolve those problems first.

4. Interchange the Tone-Clock circuit packs using the **set tone-clock PC** command. If the command succeeds, the interchange which previously failed has been accomplished and the problem has been satisfactorily resolved. If it fails, proceed to the next step. (You may want to proceed in any case to definitively test all relevant components.)
5. Interchange the t/c selector using **set expansion-interface** if investigating an EPN. If errors prevent this interchange, resolve them first.
6. Attempt again to interchange Tone-Clocks with the **set tone-clock PC** command.
  - If the Tone-Clock interchange failed for both t/c selectors:

Replace the standby Tone-Clock circuit pack which could not be interchanged into and return to this step. (See [“How to Replace a Tone-Clock Circuit Pack” on page 5-1189](#).) Test the new circuit pack as follows:

    - a. Execute the set tone-clock PC command.
    - b. Execute a set expansion-interface, if this is an EPN Tone-Clock.
    - c. Execute the set tone-clock PC command again.

If these commands successfully complete, the problem has been resolved.
  - If these commands successfully complete, the problem has been resolved.
  - If the Tone-Clock circuit packs successfully interchange when one EXP-INTF is active, but not when the other one is:

The t/c-selector circuit pack on the failing side is suspect.

    - a. Replace the A carrier DUPINT or EXP-INTF board that is active when the Tone-Clock interchange fails. (Follow procedures in “Replacing Defective SPE Circuit Packs” in Chapter 6, “Reliability Systems: A Maintenance Aid” for the DUPINT circuit pack; for the Expansion Interface, see EXP-INTF.)
    - b. Make sure the new t/c selector is active and execute the set tone-clock PC command.
  - If both Tone-Clocks can be interchanged into, and interchanges succeed when either t/c selector is active, the problem has been resolved. If the problem persists after following the above steps, follow normal escalation procedures.

5 Maintenance Objects for DEFINITY ONE  
TONE-BD (Tone-Clock Circuit Pack)

5-1200

- n. Error Type 3840—This error is not service-affecting and can be ignored. It indicates that the circuit pack has received a bad control message from the switch.
  - o. Error Type 3848—This error indicates that the Tone/Clock circuit pack had a loss of clock. If error 2305 is also logged, see note (j).
  - p. Error Type 3872—These errors indicate this Tone/Clock circuit pack had a loss of Data Clocks. This error will impact mainly users on station connected to Digital circuit packs. These users could be with out service. If error 2049 is also logged see note (i).
  - q. Error type 3999 indicates that the circuit pack sent a large number of control channel messages to the switch within a short period of time. If error type 1538 is also present, then the circuit pack was taken out-of-service due to hyperactivity. If error type 1538 is not present, then the circuit pack has not been taken out-of-service, but it has generated 50% of the messages necessary to be considered hyperactive. This may be completely normal during heavy traffic periods. However, if this error type is logged when the circuit pack is being lightly used, it may indicate a problem with the circuit pack or the equipment attached to it.
-

## System Technician-Demanded Tests: Descriptions and Error Codes

---

Always investigate tests in the order presented in the following tables when inspecting errors in the system. By clearing error codes associated with the *SAKI Sanity Test*, for example, you may also clear errors generated from other tests in the testing sequence.

Use the **list configuration control** command to find the Tone-Clock Circuit Pack Code of the system. Look for the Short and Long Test Sequences according to the Tone-Clock Circuit Pack Code.

### **For a system with a TN756 Tone-Clock Circuit Pack:**

Order of Investigation	Short Test Sequence	Long Test Sequence	D/ND <sup>1</sup>
SAKI Sanity Test (#53) (a)		X	D
Clock Health Inquiry Test (#46)	X	X	ND
Control Channel Loop Around Test (#52) (a)	X	X	ND
Tone Detection Verification Test (#42) (b)	X	X	ND
Tone Detection Audit/Update Test (#43) (b)	X	X	ND
Tone Generator Crosstalk Test (#90) (b)		X	ND
Tone Generator Transmission Test (#40) (b)	X	X	ND
Tone Generator Audit/Update (#41) (b)	X	X	ND

1. D = Destructive; ND = Nondestructive

- a. Refer to [“XXX-BD \(Common Port Circuit Pack\)” on page 5-1343](#) for descriptions of these tests.
- b. Refer to [“TONE-PT \(Tone Generator\)” on page 5-1204](#) for descriptions of these tests.

**For a system with a TN768, TN780 or TN2182 Tone-Clock Circuit Pack.**

Order of Investigation	Short Test Sequence	Long Test Sequence	D/ND <sup>1</sup>
SAKI Reset Test (#53) (a)		X	
Clock Health Inquiry Test (#46)	X	X	
Control Channel Loop Around Test (#52) (a)	X	X	
Tone Generator Crosstalk Test (#90) (b)		X	
Tone Generator Transmission Test (#40) (b)	X	X	
Tone Generator Audit/Update (#41) (b)	X	X	
TDM Bus Clock Circuit Status Inquiry Test (#148) (c)	X	X	
TDM Bus Clock Slip Inquiry (#149) (c) (e)	X	X	
TDM Bus Clock PPM Inquiry Test (#150) (c)	X	X	
TDM Bus Clock Parameter Update Test (#151) (c)	X	X	
Board Type Check Test (#574) (c)	X	X	
Standby Reference Health Check Test (#651) (c,d)		X	

1. D = Destructive; ND = Nondestructive

**Notes:**

- a. Refer to [“XXX-BD \(Common Port Circuit Pack\)”](#) on page 5-1343 for descriptions of these tests.
- b. Refer to [“TONE-PT \(Tone Generator\)”](#) on page 5-1204 for descriptions of these tests.
- c. Refer to [“TDM-CLK \(TDM Bus Clock\)”](#) on page 5-1132 for descriptions of these tests.
- d. This test runs only on the standby Tone-Clock circuit pack in a Port Network with duplicated Tone-Clocks (High or Critical Reliability systems). The circuit pack must be a TN780 with firmware version 2 or above or a TN2182.

**Clock Health Inquiry Test (#46)**

This inquiry reads special data stored in memory to determine if this Tone-Clock circuit pack had a loss of any of three clock types:

- SYSCLK
- SYSFM
- SYSDCLK

If this data indicates this Tone-Clock circuit pack had a loss of any of these clocks, the inquiry reports FAIL. In addition, if TDM-CLK error 1 is at threshold, this test will FAIL. TDM-CLK error 1 indicates a suspect clock is at the edge of its specified frequency. If the circuit pack did not have a loss of clock or TDM-CLK error 1 at threshold, the inquiry reports PASS.

This is not really a test, in the sense that it simply reports status held by the system, and does not generate new information or raise alarms. If this test fails with no error code, there is at least one Major alarm against a Tone-Clock circuit pack. If this test fails with an error code of 1, there is at least one Minor off-board alarm against a TDM-CLK.

Table 5-495. TEST #46 Clock Health Inquiry Test

Error Code	Test Result	Description/ Recommendation
	ABORT	Internal System Error. <ol style="list-style-type: none"> <li>1. Retry the command at 11-minute intervals for a maximum of 5 times.</li> <li>2. If the test continues to abort, follow normal escalation procedures.</li> </ol>
none	FAIL	This Tone-Clock circuit pack had an apparent loss of clock. One or more of error types 2049, 2305, 3834, and 3872 will appear in the error log. Correct the problem according to the appropriate error log entries. Once this test fails, the only way to make it pass, and to retire the associated alarm, is to repair the problem and to execute the <b>set tone-clock PC override</b> command against the indicated Tone-Clock circuit pack.  <b>⇒ NOTE:</b> If power is removed from a carrier in a duplicated system, and that SPE has the active TONE-CLK, a MAJOR alarm is raised for the TONE-BD. The TONE-BD will be out of service and when running Test 46 (Clock Health Test) it will fail, indicating a loss of any of these three clocks, SYSCLK, SYSFM, and SYSDCLK.  To restore the TONE-BD to service you must execute the <b>set tone spe health-override</b> command.
1	FAIL	This Tone-Clock circuit pack is suspect of having a clock at the edge of its specified frequency. A Tone-Clock circuit pack with this problem can cause Expansion Interface circuit packs to go out-of-frame or report no neighbor conditions, thus causing EPNs to go down <ol style="list-style-type: none"> <li>1. Replace the Tone-Clock circuit pack identified in the error log. Refer to <a href="#">"How to Replace a Tone-Clock Circuit Pack" on page 5-1189</a>.</li> <li>2. If the error persists, follow normal escalation procedures.</li> </ol>
	PASS	This Tone-Clock circuit pack has not reported a loss of clock.

## TONE-PT (Tone Generator)

---

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run	Full Name of MO
TONE-PT	MAJOR	test tone-clock PC sh	Tone Generator
TONE-PT	MINOR	test tone-clock PC sh	Tone Generator
TONE-PT	WARNING	release tone-clock PC sh	Tone Generator

The tone generator resides on the TN795 Processor/Tone-Clock circuit pack and provides all system tones such as dial tone, busy tone, and so on. If a tone generator fails, system may not have tones (see the Tone Generator Transmission Test #40). For instance, a user may go off-hook and hear no dial tone. The system will be able to process certain type of calls (that is, internal calls will succeed while outgoing calls will not).

The TN795 Processor/Tone-Clock circuit pack also provides the clocks for the system and can serve as the synchronization reference. Therefore, when resolving alarms on the Processor/Tone-Clock circuit pack, refer to [“TDM-CLK \(TDM Bus Clock\)” on page 5-1132](#) and [“SYNC \(Synchronization\)” on page 5-1063](#) as well as to [“PR-TN-BD \(TN795 Processor/Tone-Clock\)” on page 5-1023](#).

When replacing the Tone Clock (as part of the TN795 Processor circuit pack), always follow the procedures for replacing the TN795 Processor circuit pack.

### **WARNING:**

*When the disk is replaced on the TN795, a new license file must be downloaded to the system before the system will become operational. Refer to “Obtaining a License File” in Chapter 3 of DEFINITY ONE™ Communications System Release 2.0 Installation and Upgrades (555-233-109). Retry the command and if the test fails, replace the circuit pack.*

## Hardware Error Log Entries and Test to Clear Values

Table 5-496. Tone Generator Error Log Entries

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
0 <sup>1</sup>	0	Any	Any	Any	test tone-clock PC r 1
1(a)	17664	Tone Generator Audit/ Update Test (#41)	MAJOR	ON	test tone-clock PC r 2
769(b)	Any	Transmission Test (#40)	MAJOR	ON	test tone-clock PC r 3
1025(c)		Crosstalk Test (#90)	MAJOR	ON	test tone-clock PC l r 2
1281(d)	Any	Tone Generator Audit/ Update Test (#41)	MINOR	OFF	test tone-clock PC r 3

1. Run the Short Test Sequence first. If all tests pass, run the Long Test Sequence. Refer to the appropriate test description and follow the recommended procedures.

### Notes:

- a. Error Type: 1 - A failure in the tone generation facility on the TN795 circuit pack has been detected. Replace the TN795 Processor/Tone-Clock circuit pack.



### WARNING:

*When the disk is replaced on the TN795, a new license file must be downloaded to the system before the system will become operational. Refer to "Obtaining a License File" in Chapter 3 of DEFINITY ONE™ Communications System Release 2.0 Installation and Upgrades (555-233-109). Retry the command and if the test fails, replace the circuit pack.*

- b. Error Type: 769 - Infrequent errors, at a rate which does not bring up an alarm, probably do not affect service, unless there are customer complaints of no tones, or incorrect tones which cannot be explained in any other way. However, if an alarm is raised because this error is being repeatedly logged, then the circuit pack should be replaced.
- c. Error Type: 1025 - Timeslot Crosstalk Test failure. If a tone applied to one timeslot is inaudible, or is audible on another, it is reported by incrementing this counter and a MAJOR alarm is raised. Replace the TN795 Processor/Tone-Clock circuit pack.

- d. Error Type: 1281 - If the system-parameters country-options translation requires a TN795 and the circuit pack is not a TN795 this counter is incremented. Install the correct circuit pack.
- 

## System Technician-Demanded Tests: Descriptions and Error Codes

---

Always investigate tests in the order presented in the following tables when inspecting errors in the system. By clearing error codes associated with the *SAKI Sanity Test*, for example, you may also clear errors generated from other tests in the testing sequence.

Use the **list configuration control** command to find the Tone-Clock Circuit Pack Code of the system. Then look for the Short and Long Test Sequences according to the Tone-Clock Circuit Pack Code.

### **For a system with a TN795 Processor/Tone-Clock Circuit Pack:**

Order of Investigation	Short Test Sequence	Long Test Sequence	D/ND <sup>1</sup>
Tone Generator Crosstalk Test (#90)		X	ND
Tone Generator Transmission Test (#40)	X	X	ND
Tone Generator Audit/Update Test (#41)	X	X	ND

---

1. D = Destructive; ND = Nondestructive

### **Tone Generator Transmission Test (#40)**

The purpose of this test is to verify that the tone generation hardware on the tone-clock circuit pack is capable of generating a subset of system tones and a set of test tones. This test does not verify all system tones the tone generator produces during normal system operation.

The test is performed in two parts. For the first part, the Tone Generator is told to generate the touch-tone digits. The digits are received and checked by a Tone Detector touch-tone detector. If any of the digits fail, the test is repeated using a touch-tone detector in another Tone Detector circuit pack if available.

For the second part, the Tone Generator is told to generate call progress tones that are detected and identified by a tone detector. These tones are:

- 440 Hz
- 2225 Hz
- Digital Count

**5** Maintenance Objects for DEFINITY ONE  
TONE-PT (Tone Generator)

5-1207

The tone generator is then told to generate a sequence of test tones whose output levels are measured by a tone detector. These tones are:

- 404 Hz at 0 dB
- 1004 Hz at -16 dB
- 1004 Hz at 0 dB
- 2804 Hz at 0 dB

A Tone Detector general purpose tone detector listens for the tones and measures the quality of the tone. If any of the measured values are not within limits, the test is repeated using a general purpose tone detector in a different Tone Detector circuit pack. If the values are still out of the limits, the test will fail.

For all the failure cases of Test #40, do the following:

1. Check that all Tone Detector circuit packs have the same companding mode as that administered for the system. Correct the situation if there is a mismatch.
2. Run the long test sequence: **test tone-clock PC long repeat 1**.
3. If the problem persists, replace the TN795 Processor/Tone-Clock circuit pack by following the steps for replacing the TN795 Processor circuit pack.

 **WARNING:**

*When the disk is replaced on the TN795, a new license file must be downloaded to the system before the system will become operational. Refer to "Obtaining a License File" in Chapter 3 of DEFINITY ONE™ Communications System Release 2.0 Installation and Upgrades (555-233-109). Retry the command and if the test fails, replace the circuit pack.*

Table 5-497. TEST #40 Tone Generator Transmission Test

Error Code	Test Result	Description/ Recommendation
None	ABORT	The system was not able to allocate all the resources needed for this test or there was an Internal System Error.
1	ABORT	The system could not allocate all the resources needed to test the DTMF tones.
1001	ABORT	The system was not able to put the tone generation facility in the appropriate mode to test it.
1002	ABORT	The system could not allocate time slots for the test connection. This can happen when the system is heavily loaded. If the system is not heavily loaded, then test the TDM Bus via the <b>test tdm port-network PN#</b> command. Refer to <a href="#">“TDM-BUS (TDM Bus)” on page 5-1116</a> for details. <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
1003	ABORT	The system could not allocate a tone receiver for the test connection. This can happen when the system is heavily loaded or there is not a Tone Detector circuit pack in the port network where this test is being executed. <ol style="list-style-type: none"> <li>1. Make sure there is a Tone Detector circuit pack installed.</li> <li>2. Allow approximately 1 minute for Tone Detector maintenance to run on the newly inserted Tone Detector circuit pack.</li> <li>3. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
1022	ABORT	Tone detection for the system is administered as wide broadband (tone detection mode 5), and the Tone Detector used for this test was not a TN744. GPTD ports on other types of Tone Detector circuit packs are taken out of service since they cannot provide the administered function. <ol style="list-style-type: none"> <li>1. Change the tone-detection mode administered on the system-parameters country-options form.</li> </ol> <p>Or</p> <ol style="list-style-type: none"> <li>2. Remove all non-TN744 circuit packs from the system.</li> </ol>
2000	ABORT	Response to the test request was not received within the allowable time period. System resources required for this test are not available. <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>

*Continued on next page*

Table 5-497. TEST #40 Tone Generator Transmission Test — *Continued*

Error Code	Test Result	Description/ Recommendation
2100	ABORT	System resources required for this test are not available. 1. Retry the command at 1-minute intervals a maximum of 5 times.
1 (a)	FAIL	DTMF generation failed for the tone generator.
105 (a)	FAIL	Generation of 440-Hz failed.
109 (a)	FAIL	Generation of 2225-Hz failed.
110 (b)	FAIL	Generation of 404-Hz level invalid.
111 (b)	FAIL	Generation of 1004-Hz low level invalid.
112 (b)	FAIL	Generation of 1004-Hz high level invalid.
113 (b)	FAIL	Generation of 2804-Hz level invalid.
115 (b,c)	FAIL	Generation of digital count sequence invalid.
120 (a)	FAIL	Generation of quiet tone failed.
1044 (a)	FAIL	DTMF generation failed to generate Digit 1 for the standby tone generator.
1045 (a)	FAIL	DTMF generation failed to generate Digit 5 for the standby tone generator.
1046 (a)	FAIL	DTMF generation failed to generate Digit 9 for the standby tone generator.
1047 (a)	FAIL	DTMF generation failed to generate Digit D for the standby tone generator.
	PASS	The tone generation facility is able to generate and transmit all the tones.

Notes:

Replacing the circuit pack is a service disrupting procedure. The test should be run several times with more than one failure before the replacement policy specified in the following notes is executed.

- a. All the failure error codes marked with (a) will affect users. When the tone generation facility fails, replace the faulty Tone-Clock promptly. See warning below

5 Maintenance Objects for DEFINITY ONE  
TONE-PT (Tone Generator)

5-1210

- b. All the failure error codes marked with (b) are almost transparent to the user. Users may or may not hear any noisy tones. This type of failure affects other MOs. Maintenance may not be able to run on other objects which use the tone generation facility (that is, Tone Detector Circuit Pack maintenance). In this case, the Tone-Clock circuit pack can be replaced as suitable to the customer.
- c. Error code 115 may also be caused by TDM Bus corruption. This normally means a physical problem with bent backplane pins, TDM/LAN Bus cabling, or TDM/LAN Bus terminators. Such physical problems should especially be suspected if board replacement or other physical activity has occurred just before this error is observed.

Use **display errors** to look for errors on other circuit packs in the carriers of the same Port Network as the Tone-Clock. If any are found, they should be resolved if possible, and the Tone-Clock retested. If this does not clear the problem, the TN795 Processor/Tone-Clock circuit pack should be replaced and the new one tested. If the problem persists, follow instructions for TDM Bus maintenance in this manual.



**WARNING:**

*When the disk is replaced on the TN795, a new license file must be downloaded to the system before the system will become operational. Refer to "Obtaining a License File" in Chapter 3 of DEFINITY ONE™ Communications System Release 2.0 Installation and Upgrades (555-233-109). Retry the command and if the test fails, replace the circuit pack.*

---

## Tone Generator Update/Audit Test (#41)

The tone generation facility is refreshed with all the time slot tone information. This test also triggers in-line error messages the TN795 Processor/Tone-Clock circuit pack generates when it detects problems by itself.

A check is also made between the type of tone-clock being tested and the type of tone-clock needed based on system administration. The administration on the system-parameters country-options form requires a TN795 circuit pack.

Table 5-498. TEST #41 Tone Generator Update/Audit Test

Error Code	Test Result	Description/ Recommendation
none	ABORT	The system was not able to allocate all the resources needed for this test.
2100	ABORT	System resources required for this test are not available. Retry the command at 1 minute intervals a maximum of 5 times.
1	FAIL	<p>The system requires a TN795 processor/tone-clock to support the currently administered country-options tone generation parameters.</p> <ol style="list-style-type: none"> <li>1. Check the administration on the system-parameters country-option form. Specifically, the Base Tone Generation Set on page 1 and any custom tone administration beginning on page 2.</li> <li>2. Replace existing tone-clock circuit packs with a TN795 processor/tone-clock.</li> </ol> <p><b>⚠ WARNING:</b>  <i>When the disk is replaced on the TN795, a new license file must be downloaded to the system before the system will become operational. Refer to "Obtaining a License File" in Chapter 3 of DEFINITY ONE™ Communications System Release 2.0 Installation and Upgrades (555-233-109). Retry the command and if the test fails, replace the circuit pack.</i></p>

*Continued on next page*

Table 5-498. TEST #41 Tone Generator Update/Audit Test — *Continued*

Error Code	Test Result	Description/ Recommendation
2	FAIL	<p>The system requires TN795 processor/tone-clock to support the currently administered country-options tone generation parameters.</p> <ol style="list-style-type: none"><li>1. Check the administration on the system-parameters country-option form. Specifically, the Base Tone Generation Set on page 1 and any custom tone administration beginning on page 2.</li><li>2. Replace existing tone-clock circuit pack with a TN795 processor/tone-clock.</li></ol> <p> <b>WARNING:</b> <i>When the disk is replaced on the TN795, a new license file must be downloaded to the system before the system will become operational. Refer to "Obtaining a License File" in Chapter 3 of DEFINITY ONE™ Communications System Release 2.0 Installation and Upgrades (555-233-109). Retry the command and if the test fails, replace the circuit pack.</i></p>
	PASS	<p>The tone generation facility has been successfully refreshed with its time-slot translation and system administration is consistent with this type of tone-clock.</p> <ol style="list-style-type: none"><li>1. Display the Hardware Error Log via the <b>display errors</b> command to make sure this circuit pack did not generate new errors.</li></ol>

### Tone Generator Crosstalk Test (#90)

This test checks the ability of the Tone Generator to talk on a specific time slot. The other idle time slots are checked to make sure the Tone Generator put the tone on only the specified time slot.

Table 5-499. TEST #90 Tone Generator Crosstalk Test

Error Code	Test Result	Description/ Recommendation
None	ABORT	Internal System Error
1001	ABORT	The system was not able to put the tone generation facility in the appropriate mode to test it. Retry the command at 1 minute intervals a maximum of 5 times.
1002	ABORT	The system could not allocate time slots for the test connection. This can happen when the system is heavily loaded. If the system is not heavily loaded, then test the TDM-BUS via the <b>test tdm port-network PN#</b> command. Refer to <a href="#">“TDM-BUS (TDM Bus)” on page 5-1116</a> for details.
2000	ABORT	Response to the test request was not received within the allowable time period.
2100	ABORT	Could not allocate the necessary system resources to run this test. <ul style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ul>
	FAIL	<p>The Tone Generator could be defective.</p> <ol style="list-style-type: none"> <li>1. Test the Tone-Clock again via the <b>test tone-clock PC</b> command</li> <li>2. If the test fails again, look at the Hardware Error Log for Tone Detector circuit pack errors.</li> <li>3. If there are Tone Detector circuit pack errors, refer to Tone Detector Maintenance documentation (<a href="#">“DTMR-PT [Dual Tone Multifrequency Port (TTR)]” on page 5-624</a>, <a href="#">“GPTD-PT [General Purpose Tone Detector Port (CPTR)]” on page 5-667</a>, CLAS-PT, and <a href="#">“ETR-PT (Enhanced Tone Receiver Port)” on page 5-655</a>) to resolve these errors first.</li> <li>4. If there are no Tone Detector circuit pack errors, then the TN795 processor/Tone-Clock pack should be replaced.</li> </ol> <p style="text-align: center;"><b>⚠ WARNING:</b></p> <p style="text-align: center;"><i>When the disk is replaced on the TN795, a new license file must be downloaded to the system before the system will become operational. Refer to “Obtaining a License File” in Chapter 3 of DEFINITY ONE™ Communications System Release 2.0 Installation and Upgrades (555-233-109). Retry the command and if the test fails, replace the circuit pack.</i></p>
	PASS	The tone generation facility is able to put tones out.

## TRANS-STO (Translation Storage)

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run	Full Name of MO
TRAN-STO	MAJOR <sup>1</sup>	test translation-store	Translation Store
TRAN-STO	MINOR	test translation-store long	Translation Store
TRAN-STO	WARNING	test translation-store short	Translation Store

1. The "MAJOR" alarm occurs only at power-up time or on a Reset System 3 or 5 when the switch cannot load any translations.

This maintenance object, Translation-Store (TRANS-STO) supports maintenance testing of translation files stored on the hard disk. Maintenance actions concerning (TRANS-STO) are associated with maintaining translation file integrity and checking for translation read and write (save) errors.

### Error Log Entries and Test to Clear Values

Table 5-500. TRAN-STO Error Log Entries

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
0 <sup>1</sup>	0	Any	Any	Any	test translation-store
1281(a)	Any	Translation File Data Integrity Test (#694)	MINOR	OFF	test translation-store long
3329(b)	any	None	MINOR/ MAJOR (SUPER)	OFF	
3841(c)	Any	Save Translation	MINOR	OFF	save translation
3842(d)	Any	Save Translation	MINOR	OFF	save translation

1. Indicates that an alarm was raised but that the associated error could not be entered into the hardware error log due to a momentary overload condition. Run the short test and refer to the appropriate test description for tests that fail.

Notes:

- a. Error-Type:1281. Translation file data integrity test. The translations file test detected a checksum error on the translation file during the read operation. The hard drive can no longer hold the written data. Enter the save translation command to restore the translations. Then, run the test translation-store long command to clear the alarm. If the error occurs repeatedly, restore the translation file and then do a warm reset on the system.
- b. Error-Type 3329. There was an error while translations were being loaded. The relevant alarm occurs at power-up or on a Reset System 3 or 5 if the switch cannot load translations.

In a standard system, the alarm invokes Emergency Transfer.

- c. Error-Type 3841. Save Translation. The error indicates that the translation file cannot be saved to the hard disk. This indicates that the file is possibly being accessed by another application. Allow between 30 seconds to a minute before attempting to save translation again. If the error continues, perform a warm restart on the system.
- d. Error-Type 3842. Save Translation error. This error indicates a system error when saving translation. Attempt to save translation again after a 30 second to 1 minute interval. Enter test trans store clear to clear the alarm. If error continues, perform a warm restart.

**System Technician-Demanded Tests: Descriptions and Error Codes**

Always investigate tests in the order presented in the table below. By clearing error codes associated with the *Translation File Data Integrity Test* for example, you may also clear errors generated from other tests in the testing sequence.

Table 5-501. System Technician-Demanded Tests: TRANS-STO

Order of Investigation	Short Test Sequence	Long Test Sequence	Reset Board Sequence	D/ND <sup>1</sup>
Translation File Data Integrity Test (#694)	X	X		ND

1. D = Destructive; ND = Nondestructive

## Translation File Data Integrity Test (#694)

This test is nondestructive.

This test, verifies the integrity of the translation file stored on the hard drive by reading the translation file stored on disk and then performing checksum error checking. The calculated checksum value is compared with the recorded checksum value in the translation file. If these two values are different, this indicates that the translation file is corrupted.

Note: This file data integrity test consists of two copies of the translation file. It performs a checksum on each copy of the translation file and returns the good copy of the file to be accessed. If and only if both copies of translation files have detected an error during the translation test will it generate an alarm and error.

When restoring or backing up translation files, both copies of the translation must be backed up.

Table 5-502. TEST #694 Translation File Data Integrity Test

Error Code	Test Result	Description/ Recommendation
2012 2106 2114	ABORT	Internal system error <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
2013 2100 none	ABORT	Could not allocate the necessary system resources to run this test. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
Any	FAIL	A checksum error is detected in the translation file. <ol style="list-style-type: none"><li>1. Enter the <b>save translation</b> command, and verify that translations can be successfully saved onto the hard disk.</li><li>2. Rerun the test.</li><li>3. If the test fails again, restore the translation file, and repeat Steps 1 and 2. [See Installation Manual, Chapter 3, "Backup and Restore".</li></ol>
	PASS	No checksum error is found in the translation file.

## TSC-ADM (Administered Temporary Signaling Connections)

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run	Full Name of MO
TSC-ADM	none	none	Administered Temporary Signaling Connections
TSC-ADM	none	none	Administered Temporary Signaling Connections

No alarms are generated for the TSC-ADM (Administered Temporary Signaling Connections) MO. Due to the unusual length of the full name of this MO (that is, Administered Temporary Signaling Connections), the abbreviation Administered TSC is used often in this Maintenance documentation.

In general, administered temporary signaling connections provide a path through ISDN-PRI switches for supplementary D-channel messages. ISDN-PRI applications [that is, Distributed Communications System (DCS)] use temporary signaling connections to exchange user information across an ISDN-PRI network. What makes Administered Temporary Signaling Connection unique is that these particular Temporary Signaling Connections stay active for an extended period time (that is, similar to a permanent data connection). These ADM Temporary Signaling Connections are used for DCS features that require a NCATSC, and the ADM TSC serves as the logical channel function in a DCS network.

A Non-Call Associated Temporary Signaling Connection (NCATSC) is a virtual connection established within a D-channel. The NCATSC connection provides user to user service by exchanging USER INFORMATION messages through the virtual connection in a D-channel without associating any B-channel connections.

An *Administered TSC* is a special NCA Administered TSC defined for the DCS over the ISDN-PRI D-channel application of G3iV1.1-286 or G3iV2-386. The Administered TSC connection is a special type of NCATSC that has an administratively defined endpoint and is established for an extended period of time.

There are two types of ADMTSCs:

- Permanent

TSCs are established by the originating PBX (that is *Near-end* ADM TSC) or by the terminating PBX (that is, *Far-end* ADM TSC). Once these ADMTSCs are established, they remain active.

- As-Needed

TSCs are established on an as-needed basis. In this case, the ADMTSC is established whenever it is needed, and not before.

ADMTSC maintenance provides a strategy to verify that a far-end can respond to an ISDN-PRI USER INFORMATION TSC heartbeat message, thereby indicating that user to user signaling is functioning. In addition, maintenance can retrieve the status of the ADMTSC's connection state.

Since ADMTSCs are administered on a per signaling group basis, the health of an ADMTSC also depends on the state of the D-channel or D-channel pair administered per signaling group. Refer to ["ISDN-SGR \(ISDN-PRI Signaling Group\)" on page 5-705](#) for details on ISDN-PRI NFAS and D-channel Backup maintenance. The two administration commands for ADMTSCs are as follows:

- **add signaling group #**
- **change signaling group #**

The two maintenance commands for ADMTSCs are as follows:

- **test tsc-administered signaling group #[/tsc index]**
- **status tsc-administered signaling group #/tsc index**

## Hardware Error Log Entries and Test to Clear Values

ADM TSC Error Log Entries

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
3840-3967(a)	tsc index #	test tsc-administered			

### Notes:

- a. There is no Test to Clear Value for error types 3840-3967. The error types provide the following additional data that may prove useful when tracking down problems.

This error indicates that a TSC Heartbeat Inquiry Test was run on an Active far-end Administered TSC from the switch. Upon receiving the heartbeat message, the network communicated to the switch that the call reference value is not currently in use on the ISDN interface. As a result, the error was logged. Check the signaling group status of the D-channel or D-channel pair via the **status signaling-group <group>** command for the Administered TSC. Check the status of the Administered TSC via the **status tsc-administered** command. Also check the administration of the Administered TSC on the switch.

This error may only be affecting service for some DCS customers. Upon receipt of this error condition, the switch tears down and re-establishes the ADMTSC within 20 minutes.

- b. The port field in the error log contains the signaling group number for TSC-ADM errors.

## System Technician-Demanded Tests: Descriptions and Error Codes

Always investigate tests in the order presented in the following tables when inspecting errors in the system. By clearing error codes associated with the *TSC Heartbeat Inquiry Test*, for example, you may also clear errors generated from other tests in the testing sequence.

Order of Investigation	Short Test Sequence	Long Test Sequence	D/ND <sup>1</sup>
TSC Heartbeat Inquiry Test (#604)			ND

1. D = Destructive; ND = Nondestructive

### TSC Heartbeat Inquiry Test(#604)

This test can be invoked by system technician personnel for any ADMTSC administered in the switch. The following table indicates the possible error conditions that might be encountered when the test is invoked. Most of the error conditions do not log an error, but switched services may take some type of recovery action in certain instances.

This test sends a USER INFORMATION TSC heartbeat message inquiry across an Administered TSC to determine if the far-end can respond to a USER INFORMATION TSC heartbeat message.

Table 5-503. TEST #604 TSC Heartbeat Inquiry Test

Error Code	Test Result	Description/ Recommendation
2100	ABORT	Could not allocate the necessary system resources to run this test. 1. Reissue the <b>test tsc-administered</b> command at 1-minute intervals a maximum of 5 times.
1005	ABORT	The Administered TSC does not exist. 1. Display the administration for the Administered TSC. 2. If an Administered TSC is exists, reissue the <b>test tsc-administered</b> command.
1113	ABORT	The D-channel is out-of-service. 1. Refer to the ISDN-LNK (ISDN-PRI Signaling Link Port) Maintenance documentation.

*Continued on next page*

5 Maintenance Objects for DEFINITY ONE  
TSC-ADM (Administered Temporary Signaling Connections)

5-1220

Table 5-503. TEST #604 TSC Heartbeat Inquiry Test — Continued

Error Code	Test Result	Description/ Recommendation
1145	ABORT	<p>There is congestion in the network.</p> <ol style="list-style-type: none"> <li>1. Issue the <b>status tsc-administered</b> command at 1-minute intervals a maximum of 5 times.</li> <li>2. If the congestion does not clear, disable and enable the Administered TSC via the <b>change sig-group &lt;group&gt;</b> command. To disable the Administered TSC, display the (administration) Signaling Group Form via the <b>change sig-group &lt;group&gt;</b> command where <b>&lt;group&gt;</b> refers to the number of the signaling group under which the suspect TSC is administered. Change the <code>Enable</code> field to <b>n</b>. To enable the ADMTSC, change the <code>Enable</code> field to <b>y</b>.</li> <li>3. If the congestion still does not clear, check other nodes in the network.</li> </ol>
1146	ABORT	<p>The congestion just occurred in the network.</p> <ol style="list-style-type: none"> <li>1. Issue the <b>status tsc-administered</b> command at 1-minute intervals a maximum of 3 times.</li> <li>2. If congestion does not clear, disable and enable the Administered TSC via the <b>change sig-group &lt;group&gt;</b> command. To disable the Administered TSC, display the (administration) Signaling Group Form via the <b>change sig-group &lt;group&gt;</b> command where <b>&lt;group&gt;</b> refers to the number of the signaling group under which the suspect TSC is administered. Change the <code>Enable</code> field to <b>n</b>. To enable the ADMTSC, change the <code>Enable</code> field to <b>y</b>.</li> <li>3. If congestion still does not clear, check the other nodes in the network.</li> </ol>
1147	ABORT	<p>The ADMTSC is being torn down.</p> <ol style="list-style-type: none"> <li>1. Issue the <b>status tsc-administered</b> command at 1-minute intervals a maximum of 3 times.</li> <li>2. If ADMTSC is still down, disable and enable the ADM TSC via the <b>change sig-group &lt;group&gt;</b> command. <b>NOTE:</b> To disable the ADMTSC, display the (administration) Signaling Group Form via the <b>change sig-group &lt;group&gt;</b> command where <b>&lt;group&gt;</b> refers to the number of the signaling group under which the suspect TSC is administered. Change the <code>Enable</code> field to <b>n</b>. To enable the ADMTSC, change the <code>Enable</code> field to <b>y</b>.</li> <li>3. If the ADMTSC is still down, check the other nodes in the network.</li> </ol>
1148	ABORT	<p>The ADMTSC is enabled, but inactive (near-end).</p> <ol style="list-style-type: none"> <li>1. Disable and enable the ADMTSC.</li> <li>2. Reissue the <b>test tsc-administered</b> command.</li> <li>3. If the ADMTSC is still inactive, check the other nodes in the network.</li> </ol>

Continued on next page

5 Maintenance Objects for DEFINITY ONE  
TSC-ADM (Administered Temporary Signaling Connections)

5-1221

Table 5-503. TEST #604 TSC Heartbeat Inquiry Test — *Continued*

Error Code	Test Result	Description/ Recommendation
1149	ABORT	The ADMTSC is disabled. <ol style="list-style-type: none"> <li>1. Enable the TSC, and see if the status indicates "active."</li> <li>2. Reissue the <b>test tsc-administered</b> command.</li> <li>3. If the TSC still disabled, remove the ADMTSC from the system.</li> </ol>
1181	ABORT	Ran out of ADMTSC resources. <ol style="list-style-type: none"> <li>1. Reissue the <b>test tsc-administered</b> command at 1-minute intervals a maximum of 3 times.</li> </ol>
1182	ABORT	The BX.25 link is down at the gateway. <ol style="list-style-type: none"> <li>1. Disable the ADMTSC.</li> <li>2. Check the status of the gateway link via the <b>status link link-no</b> command.</li> <li>3. Once the gateway link indicates an "in-service" state, enable the Administered TSC.</li> <li>4. Reissue the <b>test tsc-administered</b> command.</li> </ol>
2000	ABORT	The Administered TSC is not responding to a TSC heartbeat inquiry. <ol style="list-style-type: none"> <li>1. Retry the <b>test tsc-administered</b> command at 1-minute intervals a maximum of 3 times.</li> <li>2. If the problem continues to fail, obtain the status of the D-channel or D-channel pair associated with the ADMTSC via the <b>status sig-group &lt;group&gt;</b> command. If the D-channel is INS (that is, in-service) and the status of the ADMTSC appears to be active, disable and enable the ADMTSC through administration. <b>NOTE:</b> To disable the ADMTSC, display the (administration) Signaling Group Form via the <b>change sig-group &lt;group&gt;</b> command where <b>&lt;group&gt;</b> refers to the number of the signaling group under which the suspect TSC is administered. Change the <code>Enable</code> field to <b>n</b>. To enable the ADMTSC, change the <code>Enable</code> field to <b>y</b>.</li> <li>3. Reissue the <b>test tsc-administered</b> command.</li> <li>4. If the test fails, check the ADMTSC node on the other side of the network to verify that the ADM TSC is indeed active.</li> </ol>
2012	ABORT	Internal System Error. <ol style="list-style-type: none"> <li>1. Reissue the <b>test tsc-administered</b> command at 1-minute intervals a maximum of 5 times.</li> </ol>

*Continued on next page*

5 Maintenance Objects for DEFINITY ONE  
TSC-ADM (Administered Temporary Signaling Connections)

5-1222

Table 5-503. TEST #604 TSC Heartbeat Inquiry Test — *Continued*

Error Code	Test Result	Description/ Recommendation
1	FAIL	The Administered TSC is not active (far-end). <ol style="list-style-type: none"><li>1. Reissue the <b>test tsc-administered</b> command.</li><li>2. Verify that the Administered TSC node on the other side of the network is active.</li><li>3. Disable and enable the Administered TSC.</li><li>4. Retry the <b>test tsc-administered</b> command.</li></ol>
2	FAIL	Facility IE (Information Element) reject. <ol style="list-style-type: none"><li>1. Check all other nodes in the network, and make sure Administered TSC is active.</li></ol>
	PASS	The Administered TSC responded to a heartbeat.

## TTR-LEV (TTR Level)

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run	Full Name of MO
TTR-LEV	WARNING	See Note <sup>1</sup>	TTR Level

1. See the "Repair Procedure for the TTR Level Maintenance Object" section.

A TN795 Tone-Clock/Detector/Call Classifier and the TN744D Call Classifier circuit packs provide touch tone receivers (TTRs or DTMR-PTs) that are devices used to interpret touch tone calling signals and to translate the dual tones into the following valid digits: 0 through 9, \*, and #. A Tone Detector circuit pack is a resource shared by all PBX users and also has general purpose tone detector ports (GPTD-PTs) to detect call progress tones, modem answer tones, and transmission test tones. Call Classifier Ports (CLSFY-PTs) have also been added to detect voice or network intercept tones. A Call Classifier Port (CLSFY-PT) can function as either a DTMR-PT or as a GPTD-PT.

When a user places a call from a digital or analog voice terminal on the switch, a TTR is needed to interpret the dual tone multifrequency signals sent from the voice terminal. The TTR is in use until the total number of digits needed is collected or until a time-out occurs. Dial tone is supplied to a user after receipt of an off-hook signal which signifies that a TTR is connected and ready to receive digits. For example, if there are 20 TTRs in the system being used simultaneously by 20 users at a given time, then the 21st user would not receive dial tone until a TTR becomes available. It is for this reason that it is necessary to have sufficient tone detectors in the system to prevent delay in receiving dial tone. The TTR-LEV errors can be used to determine a shortage of tone detectors. Use the **list measurements tone-receiver** command to determine tone detector usage. The minimum threshold values assigned on the Maintenance-Related System Parameters Form for TTRs (DTMR-PTs), CPTRs (GPTD-PTs), and CCRs (CLSFY-PTs) should match the number of touch tone receivers (TTR) and tone detectors (GPTD-PT) in the system. The numbers are 8 CCRs for each Call Classifier Port (TN744D) circuit pack. The threshold values are administered via the **change system-parameters maintenance** command on the Maintenance-Related System Parameters Form. The desired numbers are entered in the "TTR" (DTMR-PT), "CPTR" (GPTD-PT), and "Call Classifier" (CLSFY-PT) fields, respectively.

The TTR Level (Touch Tone Receiver Level) MO is used to represent the following possible events:

1. The total number of General Purpose Tone Detector Ports (GPTD-PTs), [also known as Call Progress Tone Receivers (CPTRs)], currently in service is less than the administered threshold number.
2. The total number of Dual Tone Multifrequency Receiver Ports (DTMR-PTs) [(also known as Touch Tone Receiver (TTRs)], currently in service is less than the administered threshold number.

**5 Maintenance Objects for DEFINITY ONE**  
*TTR-LEV (TTR Level)*

5-1224

The TTR Level maintenance performs a monitoring function. When one of the above events occurs, the switch reports it. At this point, the system is still operating properly, but the system capacity is reduced.

The above events can occur if:

1. The threshold number of General Purpose Tone Detector Ports (GPTD-PTs) for service or the threshold number of Dual Tone Multifrequency Receiver Ports (DTMR-PTs) for service is administered incorrectly on a Tone Detector circuit pack.
2. Too many General Purpose Tone Detector Ports (GPTD-PTs) or Dual Tone Multifrequency Receiver Ports (DTMR-PTs) have been taken out-of-service for a Tone Detector circuit pack (that is, the ports have been either busied-out by system technician or maintenance has taken them out-of-service).
3. Too many ports have been taken out-of-service for a Call Classifier circuit pack (that is, the ports have been busied-out by system technician or maintenance has taken them out-of-service).
4. There is an insufficient number of General Purpose Tone Detector Ports (GPTD-PTs) or Dual Tone Multifrequency Receiver Ports (DTMR-PTs) in the system for a Tone Detector circuit pack. Or there is an insufficient number of ports in the system for a Call Classifier circuit pack.

**Repair Procedure for the TTR Level Maintenance Object**

The following is a step-by-step approach to resolve the TTR Level maintenance alarm.

1. Execute the **display error** command. Determine if the TTR-LEV warning alarm is raised against the GPTD-PT level, the DTMR-PT level, or the CLSFY-PT level. In the Hardware Error Log Table, the error type field of the TTR-LEV MO has a value of 2 for DTMR-PT level, a value of 4 for GPTD-PT level, or a value of 6 for CLSFY-PT level.

Perform the actions described in Step 2 for the DTMR-PT, the GPTD-PT, or the CLSFY-PT.

2. Issue the **change system-parameters maintenance** command. Check the administered value(s) for TTRs and CPTRs for service on the Tone Detector circuit packs or for CCRs on the Call Classifier Port (CLSFY-PT) circuit pack. If a threshold value is set too high, change it to a lower value via the **change system-parameters maintenance** command and wait one minute for the alarm to clear.
3. Execute the **display error** command. Look for a GPTD-PT, DTMR-PT, or CLSFY-PT that has been busied out. A port that has been busied out has a value of 18 in the error type field of the Hardware Error Log.

5 Maintenance Objects for DEFINITY ONE  
TTR-LEV (TTR Level)

5-1225

For each of the busied-out ports, use the following procedure:

- Determine why the port was busied out.
- If the port can be placed back into service, test the port via the **test port PCSSpp** command.
- If all the tests pass, release the port via the **release port PCSSpp** command. Then wait one minute for the TTR Level alarm to clear.

If this does not clear the TTR Level alarm, proceed to Step 4.

4. Execute the **display alarm** command. Determine the address of the Tone Detector circuit pack which contains the defective (alarmed) GPTD-PT or DTMR-PT.

Execute the **test board PCSS long rep 3** command where PCSS is the address (that is, port network number, carrier designation, and slot address) of the Tone Detector circuit pack or Call Classifier circuit pack containing the defective (alarmed) GPTD-PT or DTMR-PT.

If this does not clear the TTR Level alarm, proceed to Step 5.

5. At this point, the only way to clear the alarm is to replace the Tone Detector circuit pack or Call Classifier circuit pack containing the defective (alarmed) GPTD-PT, DTMR-PT or CLSFY-PT.

## Hardware Error Log Entries and Test to Clear Values

Table 5-504. TTR Level Error Log Entries

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
1 (a)	1	None			
2 (b)	2		WARNING (See the WARNING message below)	OFF	
3 (c)	3	None			
4 (d)	4		WARNING	OFF	
5 (e)	5	None			
6 (f)	6		WARNING	OFF	
7 (g)	7		MAJOR	OFF	
8 (h)	8		MINOR	OFF	
9 (i)	9		MINOR	OFF	



### WARNING:

The Alarm is upgraded to MAJOR if the Base Tone Generator is set to 12 (France).

Notes:

- a. Error code 1 does not indicate a current error condition. It indicates that the number of DTMR ports in service was below the administered threshold, but is now equal to or greater than the threshold. These errors are typically generated during boot time or other transitional states when the ports are being brought into service.
  - b. The total number of DTMR ports currently in service is below the administered threshold. To clear the alarm, refer to the repair procedure described above.
  - c. Error code 3 does not indicate a current error condition. It indicates that the number of GPTD ports in service was below the administered threshold, but is now equal to or greater than the threshold. These errors are typically generated during boot time or other transitional states when the ports are being brought into service.
  - d. The total number of GPTD ports currently in service is below the administered threshold. To clear the alarm, refer to the repair procedure describe above.
  - e. Error code 5 does not indicate a current error condition. It indicates that the number of Call Classifier ports (CLSFY-PT) in service was below the administered threshold, but is now equal to or greater than the threshold. These errors are typically generated during boot time or other transitional states when the ports are being brought into service.
  - f. The total number of Call Classifier ports currently in service is below the administered threshold. To clear the alarm, refer to the repair procedure described above.
  - g. There are currently no DTMR ports in service. To clear the alarm, refer to the repair procedure described above.
  - h. There are currently no GPTD ports in service. To clear the alarm, refer to the repair procedure described above.
  - i. There are currently no Call Classifier ports in service. To clear the alarm, refer to the repair procedure described above.
-

## UDS1-BD (UDS1 Interface Circuit Pack)

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run	Full Name of MO
UDS1-BD	MAJOR	test board PCSSpp sh	UDS1 Interface Circuit Pack
UDS1-BD	MINOR	test board PCSSpp l	UDS1 Interface Circuit Pack
UDS1-BD	WARNING	test board PCSSpp sh	UDS1 Interface Circuit Pack

The UDS1 Interface circuit pack provides an interface to the DS1 facility. UDS1 Interface circuit packs include the TN464B circuit pack and the TN464C circuit pack.

The TN464B circuit pack is designed to support 32 DS0 channels on a 2.048 Mbps DS1 link, and the TN464C (or greater vintage) circuit pack is designed to support either 24 DS0 channels on a 1.544 Mbps DS1 link or 32 DS0 channels on a 2.048 Mbps DS1 link. The TN464C (or greater vintage) circuit pack is optioned via a removable strap on the circuit pack. The 2 strap positions are labeled "24CHNL" or "32CHNL."

The DS0 channels can be administered either as trunks to other switches, lines to off-premises stations, ports to line-side PRI terminating devices, or as ports to other line-side non-PRI terminating devices.

### NOTE:

DS0 channels on the TN464B circuit pack can be administered only as trunks to other switches.

UDS1 Interface Circuit Pack Maintenance documentation provides a strategy for maintaining the UDS1 Interface circuit pack. The maintenance strategy deals with logging the in-line errors reported by the UDS1 Interface circuit pack, running tests for error diagnosis and recovery, and raising or clearing maintenance alarms.

The TN464B and TN464C circuit packs support Tie trunks, CO trunks, DID trunks, OPS lines, narrowband access endpoint ports, the ISDN-PRI signaling channel (D-channel), and ISDN-PRI trunks (B-channels). The TN464C circuit pack can also support wideband access endpoint ports and PRI endpoint ports (B-channels).

The signaling (that is, the call setup) for the Tie trunks, CO trunks, DID trunks and OPS lines is done on the circuit pack by the UDS1 firmware. Signaling for the B-channels (ISDN-PRI trunks and PRI endpoint ports) is routed over the D-channel. ISDN-PRI Trunk and PRI endpoint port signaling (Q.921, Q.931), however, is not provided by the UDS1 Interface circuit pack. The signaling over the DS1 link must be synchronized between the transmitting end and the receiving end to ensure error-free communication. Refer to ["SYNC \(Synchronization\)" on page 5-1063](#) for details.

Each trunk, line, and port has its own maintenance strategy. However, each trunk, line, or port is dependent upon the health of the UDS1 Interface circuit pack. Refer to the following sections for details:

- [“TIE-DS1 \(DS1 Tie Trunk\)” on page 5-1144](#) for a DS1 Tie Trunk
- [“CO-DS1 \(DS1 CO Trunk\)” on page 5-402](#) for a DS1 CO Trunk
- [“DID-DS1 \(DS1 DID Trunk\)” on page 5-475](#) for a DS1 DID Trunk
- [“OPS-LINE \(DS1 OPS Line\)” on page 5-882](#) for a DS1 OPS Line
- [“WAE-PORT \(Wideband Access Endpoint Port\)” on page 5-1336](#) for a Wideband Access Endpoint
- [“ISDN-TRK \(DS1 ISDN Trunk\)” on page 5-722](#) for a DS1 ISDN Trunk
- [“PE-BCHL \(PRI Endpoint Port\)” on page 5-913](#) for a PRI Endpoint Port
- ISDN-LNK documentation for an ISDN-PRI Signaling Link Port

The TN464F (or later suffix) circuit pack combined with Lucent's new 120A1 CSU Module forms an Enhanced Integrated CSU. The new 120A1 CSU Module, when combined with the functionality provided by the TN464F hardware and firmware, and new switch software, provides functionality equivalent to an external stand-alone ESF T1 CSU. The 120A1 CSU Module connects to the TN464F circuit pack on the I/O connector panel on the back of the port carrier. The new CSU Module, thus becomes an integrated part of the DEFINITY. system. Throughout the document, the term 120A1 will mean a 120A1 or later suffix CSU Module.

The Enhanced Integrated CSU is for use in the United States of America with 1.544 Mbps DS1 service. For further details on the 120A1 CSU Module see *DEFINITY. Communications System Generic 1, Generic 2, and Generic 3 V1 and V2 - Integrated CSU Module Installation and Operation*, 555-230-193, Issue 1, December 1993.

The TN464F and 120A1 CSU Module support on-demand loopback tests that assist in the detection of faults between the TN464F circuit pack and the CSU Module, between the Integrated CSU and the optional Customer Premises Loopback Jack, or between the Integrated CSU and remote CSU. These loopback tests are explained in detail later in this UDS1-BD section, but [Figure 5-55](#) gives a high level overview of the loopback points.

5 Maintenance Objects for DEFINITY ONE  
UDS1-BD (UDS1 Interface Circuit Pack)

5-1229




Figure 5-55. High Level Overview Of Loopback Points

## Circuit Pack Administration and Options

The DS1 configuration for each circuit pack is administered on the DS1 Circuit Pack form. *Bit Rate* is set to 1.544 Mbps for 24-channel systems, and 2.048 Mbps for 32-channel systems. *Country Protocol* is used to drive layer 3 protocol decisions based on PRI specifications specific to a given country (not those related to specific features). This Country Protocol is independent of the *Country* parameter administered on the country-options system-parameters form. Different UDS1 circuit packs may be administered with different Country Protocols, allowing the switch to act as a gateway between two incompatible ISDN-PRI implementations (for example, between two different countries). US systems use country protocol 1. *Near-End CSU Type* is set to *other* for no CSU installed, *or* for an external CSU such as an ESF T1 CSU, *or integrated* for the 120A1 CSU Module. Answering *integrated* will cause additional fields to be displayed for administering the Enhanced Integrated CSU Module. In addition to the above there are numerous other fields defining such parameters as framing modes, line coding companding mode and so on. For details, see *DEFINITY Communications System Generic 3 V2 Implementation*, 555-230-653, and *DEFINITY Communications System Generic 2.2 and Generic 3 V2 DS1/CEPT/ISDN-PRI Reference*, 555-025-107.

[Figure 5-56](#) through [Figure 5-58](#) show how to configure the circuit pack for 24-channel or 32-channel DS1. The channel selection must match the parameters administered on the corresponding DS1 Circuit Pack Form. (US applications use 24 Channels.)

The channel selection must match the parameters administered on the corresponding DS1 Circuit Pack Form. (US applications use 24 Channels.)




Figure 5-56. TN464C/D DS1 Option Jumpers




Figure 5-57. TN464C/D DS1 Option Jumpers

The option switch located on the component side of the TN464E/F circuit pack must be set correctly. [Figure 5-58](#) shows how to configure the circuit pack for 24-channel or 32-channel DS1. The channel selection must match the parameters administered on the corresponding DS1 Circuit Pack Form. (US applications use 24 Channels.)




Figure 5-58. TN464E/F DS1 Option switches

## Hardware Error Log Entries and Test to Clear Values

Table 5-505. DS1 Interface Circuit Pack Maintenance Error Log Entries

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
0 <sup>1</sup>	0	Any	Any	Any	test board PCSS
1(a)	0	Circuit pack removed or SAKI Test (#53)	MIN/ WRN <sup>2</sup>	ON	
18(b)	0	busyout board PCSS	WARNING	OFF	release board PCSS
23(c)	0		WARNING	OFF	add ds1 PCSS
125(d)	none	None	MIN/ WRN <sup>3</sup>	ON	
257	65535	Control Channel Loop Test (#52)	MINOR	ON	test board PCSS l r 20
257(e)	Any	None			
513(f)	Any		MIN/ WRN <sup>3</sup>	ON	
514(g)	46086		MIN/ WRN <sup>3</sup>	ON	
769(h)	46085		MIN/ WRN <sup>3</sup>	ON	
770(i)	46096		MIN/ WRN <sup>3</sup>	ON	
1025(e)	4363	NPE Audit Test (#50)			
1281	Any	Loss of Signal Alarm Inquiry Test (#138)	MIN /WRN <sup>3</sup>	OFF	test board PCSS
1300(j)	Any	Loss Of Signal Alarm Inquiry Test (#138)	WARNING	OFF	test board PCSS
1301(k)	Any	Loss Of Signal Alarm Inquiry Test (#138)	WARNING	OFF	test board PCSS
1302(l)	Any	Loss Of Signal Alarm Inquiry Test (#138)	MIN/ WRN <sup>3</sup>	OFF	test board PCSS
1303(m)	Any	Loss Of Signal Alarm Inquiry Test (#138)	MIN/ WRN <sup>3</sup>	ON	test board PCSS

Continued on next page

5 Maintenance Objects for DEFINITY ONE  
UDS1-BD (UDS1 Interface Circuit Pack)

5-1233

Table 5-505. DS1 Interface Circuit Pack Maintenance Error Log Entries — *Continued*

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
1310(n)	Any	Board Loopback Test (#1209)	MINOR	ON	test ds1-loop PCSS ds1/csu-loopback-tests
1311(o)	Any	Equipment Loopback Test (#1210)	MIN/ WRN <sup>3</sup>	OFF	test ds1-loop PCSS ds1/csu-loopback-tests
1312(p)	Any	Repeater Loopback Test (#1211)	MIN/ WRN <sup>3</sup>	OFF	test ds1-loop PCSS ds1/csu-loopback-tests
1313(q)	Any	CPE Loopback Jack Test (#1212)	MIN/ WRN <sup>3</sup>	OFF	test ds1-loop PCSS end-loopback/span-test
1314(r)	Any	Far CSU Loopback Test (#1213)	MIN/ WRN <sup>3</sup>	OFF	test ds1-loop PCSS end-loopback/span-
1320	Any	Loss of Signal Alarm Inquiry Test (#138)	MIN/ WRN <sup>3</sup>	OFF	test board PCSS
1321	Any	Loss of Signal Alarm Inquiry Test (#138)	MIN/ WRN <sup>3</sup>	OFF	test board PCSS
1322	Any	Loss of Signal Alarm Inquiry Test (#138)	MINOR	ON	test board PCSS
1323	Any	Loss of Signal Alarm Inquiry Test (#138)	MIN/ WRN <sup>3</sup>	OFF	test board PCSS
1324	Any	Loss of Signal Alarm Inquiry Test (#138)	WARNING	OFF	test board PCSS
1537(s)	46082		MIN/ WRN <sup>3</sup>	ON	
1538(t)	Any		MIN/ WRN <sup>3</sup>	ON	
1793	Any	Blue Alarm Inquiry Test (#139)	MAJ/MIN/W RN <sup>4</sup>	OFF	test board PCSS
1794	Any	Blue Alarm Inquiry Test (#139)	MAJ/MIN/W RN <sup>4</sup>	OFF	test board PCSS
1795	Any	Blue Alarm Inquiry Test (#139)	MAJ/MIN/W RN <sup>4</sup>	OFF	test board PCSS
2049	Any	Red Alarm Inquiry Test (#140)	MIN/ WRN <sup>3</sup>	OFF	test board PCSS

*Continued on next page*

5 Maintenance Objects for DEFINITY ONE  
UDS1-BD (UDS1 Interface Circuit Pack)

5-1234

Table 5-505. DS1 Interface Circuit Pack Maintenance Error Log Entries — *Continued*

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
2305	Any	Yellow Alarm Inquiry Test (#141)	MIN/ WRN <sup>3</sup>	OFF	test board PCSS
2306	Any	Yellow Alarm Inquiry Test (#141)	MIN /WRN <sup>3</sup>	OFF	test Board PCSS
2561	Any	Major Alarm Inquiry Test (#142)	MIN /WRN <sup>3</sup>	OFF	test board PCSS
2817		Minor Alarm Inquiry Test (#143)	MIN/ WRN <sup>3</sup>	OFF	test board PCSS
3073 to 3160 (u)	Any	Slip Alarm Inquiry Test (#144)	MIN/ WRN <sup>3</sup>	OFF	test board PCSS r 6
3330(v)	46083		MIN/ WRN <sup>3</sup>	ON	
3585 to 3601 (w)	Any	Misframe Alarm Inquiry Test (#145)	MIN/ WRN <sup>3</sup>	OFF	test board PCSS r 6
3840(x)	Any	None			
3841(y)	4358				
3842(z)	46097				
3843	46081				
3900(aa)	Any	CPE Loopback Jack Test (#1212)			
3901(ab)	Any	Far CSU Loopback Test (#1213)			
3902(ac)	Any	One-Way Span Test (#1214)			
3999(ad)	Any	None			

1. Run the Short Test Sequence first. If all tests pass, run the Long Test Sequence. Refer to the appropriate test description and follow the recommended procedures.
2. If ports are assigned to the circuit pack, then a minor alarm is raised. If no ports are assigned to the circuit pack, then a warning alarm is raised. The alarm is raised after the circuit pack has been missing for a period of 15 minutes. Warning alarms are also raised against any ports administered on the circuit pack.
3. Minor alarms on this MO may be downgraded to warning alarms based on values set in the **set options** command.
4. Major alarms on this MO may be downgraded to minor or warning alarms based on values set in the **set options** command.

## Notes:

- a. Error 1 indicates that the circuit pack has totally stopped functioning or is not fully administered. The alarm is logged about 15 minutes after the circuit pack has been removed or 11 minutes after the SAKI Test (#53) fails.

To be fully administered, a UDS1 circuit pack must meet all of these 3 conditions:

1. Have an entry in the circuit plan via the **change circuit pack** command
2. Be administered via the **add ds1** PCSS command
3. Be physically inserted into the correct slot

If the circuit pack has an entry in the circuit plan and either of the other two conditions are *not* met, a MINOR alarm is logged. To resolve the error either

1. Make sure all conditions for administration are met and that a functioning UDS1 circuit pack is inserted in the correct slot, or
2. Completely remove the UDS1-BD from the system using the following steps:
  - a. Remove any administered DS1 trunks, access endpoints or PRI endpoints associated with the circuit pack from their trunk groups.
  - b. Execute the **remove ds1** PCSS and **change circuit pack** PCSS commands.

If all the administration conditions are met for this circuit pack and the red LED is still on, follow the instructions for LED Alarms with Error Type 1.

- b. The UDS1 Interface circuit pack has been busied out by a **busyout board PCSS** command.
- c. The UDS1-BD circuit pack is not completely administered. To be fully administered, the UDS1 circuit pack must:
  1. Have an entry in the circuit plan via the **change circuit pack** command,
  2. Be administered via the **add ds1** PCSS command, and
  3. Be physically inserted into the correct slot.

A DS1 (UDS1-BD and DS1-BD) differs from most circuit packs in that inserting the circuit pack into the switch is not enough to make the board usable. It must also be administered with the **add ds1** command.

5 Maintenance Objects for DEFINITY ONE  
UDS1-BD (UDS1 Interface Circuit Pack)

5-1236

- d. No Aux Data: A wrong circuit pack is inserted in the slot where this circuit pack is logically administered. To resolve this problem, either remove the wrong circuit pack and insert the logically administered circuit pack OR use the **change circuit-pack** command to readminister this slot to match the circuit pack inserted.

Aux Data 3: The 24/32-channel option jumper setting on the circuit pack does not match the option set on the DS1 circuit pack administration form. The circuit pack must be physically removed to see the setting of the jumper.

- e. This error is associated with the Common Port Circuit Pack Maintenance Test. Refer to [“XXX-BD \(Common Port Circuit Pack\)” on page 5-1343](#) for details.
- f. The UDS1 Interface circuit pack has detected a transient hardware problem. The value in the Aux Data field indicates the type of hardware problem.

4352 External RAM failure

4353 Internal RAM failure

4355 Internal ROM failure

If the UDS1 board detects only one of these hardware problems, then the error will disappear when none of these faults are detected for 10 minutes. If the same Aux Data value is logged more than once in a 24 hour period, the circuit pack should be replaced.

- g. LAN External RAM Error. This error occurs when there is a hardware fault in the PPE external RAM. The RAM is used for message buffering to and from the Packet Bus. This error should not occur regularly. If this error is seen quite frequently (10 times within 30 minutes), the circuit pack should be replaced.
- h. Transmit FIFO Underflow Error. This error occurs when the circuit pack cannot find the "end of frame" bit when transmitting a frame to Packet Bus. An alarm will be raised if this error occurs 3 times within 10 minutes. Clear the alarm via the following commands: **busyout board PCSS, reset board PCSS, test board PCSS long, release board PCSS**. If the error recurs within 10 minutes, then replace the circuit pack.
- i. Unable to Write LAN Translation RAM Error. This error occurs when a call is aborted because there are no available translation RAM locations for the call connection attempt. An alarm will be raised if this error occurs two times within 10 minutes. Clear the alarm via the following commands: **busyout board PCSS, reset board PCSS, test board PCSS long, release board PCSS**. If the error recurs within 10 minutes, then replace the circuit pack.

5 Maintenance Objects for DEFINITY ONE  
UDS1-BD (UDS1 Interface Circuit Pack)

5-1237

- j. CSU Module missing. The *Near-End CSU Type* field on the *add ds1* form has been administered as *integrated* but the 120A CSU Module is not physically connected (or is improperly connected) to the TN464F board on the back of the port carrier.

If using the 120A CSU Module, plug (or replug) the CSU Module into the TN464F circuit pack's connector on the I/O connector panel on back of the carrier. Otherwise, change the *Near-End CSU Type* field using the *change ds1* form to *other*.

If this error remains after plugging the CSU Module into the board's connector, there could be a problem with the I/O connector panel.

- k. CSU Module not expected. The 120A CSU Module is physically connected to the TN464F board on the back of the port carrier but the *Near-End CSU Type* field on the *add ds1* form has not been administered as *integrated*.

If the 120A CSU Module is to be used, use the *change ds1* command to change the *Near-End CSU Type* field to *integrated*. Otherwise, physically remove the 120A CSU Module from the back of the port carrier.

- l. DS1 configuration error. Attempting to use the 120A CSU Module with a TN464F circuit pack that is configured for 32-channel (2.048 Mbps) operation. The CSU Module only works with a DS1 board configured for 24-channel (1.544 Mbps) operation in the United States.
- m. DS1 circuit pack suffix incorrect for CSU Module. The *Near-End CSU Type* field on the *add ds1* form has been administered as *integrated* but the DS1 circuit pack is not a TN464F or later suffix UDS1 board.
- If the 120A CSU Module is to be used, remove the circuit pack and replace it with a TN464F or later suffix board. Otherwise, use the ***change ds1*** command to change the *Near-End CSU Type* field to *other*.
- n. BLB failure. This error occurs when the DS1 Board Loopback (BLB) demand test fails. Repeat the test using the following commands: ***busyout board PCSS, test ds1-loop PCSS ds1/csu-loopback-tests, release board PCSS***. If the BLB test continues to fail, then the TN464F circuit pack needs to be replaced.
- o. ELB failure. This error occurs when the Integrated CSU (I-CSU) Module Equipment Loopback (ELB) test fails. This test is executed by the I-CSU during I-CSU power-up/reset (i.e.- TN464F board physically inserted and 120A CSU Module already installed) or when the 120A CSU Module is plugged on to an already initialized DS1 board. The ELB test is also executed as part of the command ***test ds1-loop PCSS ds1/csu-loopback-tests***.

Attempt to clear the alarm via the following commands: ***busyout board PCSS, test ds1-loop PCSS ds1/csu-loopback-tests, release board PCSS***. If the ELB test continues to fail, then either the TN464F board, the CSU Module, or the I/O cable between the backplane and the CSU module (or any combination thereof) has failed. Attempt to isolate where the failure is occurring by reexecuting the test by replacing one piece of hardware at a time.

5 Maintenance Objects for DEFINITY ONE  
UDS1-BD (UDS1 Interface Circuit Pack)

5-1238

- p. RLB failure. This error occurs when the Integrated CSU (I-CSU) Module Repeater Loopback (RLB) test fails. This test is executed by the I-CSU during I-CSU power-up/reset (i.e.- TN464F board physically inserted and 120A1 CSU Module already installed) or when the 120A CSU Module is plugged on to an already initialized DS1 board. The RLB test is also executed as part of the command *test ds1-loop PCSS ds1/csu-loopback-tests*.

Attempt to clear the alarm via the following commands: *busyout board PCSS, test ds1-loop PCSS ds1/csu-loopback-tests, release board PCSS*. If the RLB test continues to fail, then the CSU Module needs to be replaced.

- q. CPE Loopback Jack deactivation error. This error occurs when the TN464F circuit pack could not deactivate a CPE Loopback Jack loopback on power-up/reset or upon software request.

Attempt to clear the alarm via the following commands: *busyout board PCSS, test ds1-loop PCSS end-loopback/span-test, release board PCSS*. If the attempt to deactivate the CPE Loopback Jack loopback continues to fail, other steps must be taken to deactivate the loopback.

- r. Far CSU Loopback deactivation error. This error occurs when the TN464F circuit pack could not deactivate a far-end CSU loopback on power-up/reset or upon software request.

Attempt to clear the alarm via the following commands: *busyout board PCSS, test ds1-loop PCSS end-loopback/span-test, release board PCSS*. If the attempt to deactivate the Far CSU loopback continues to fail, then escalate the problem.

- s. If the error occurs 3 times within 10 minutes, the board will be isolated from the Packet Bus and the board will be alarmed. To clear the alarm and restore the board to the Packet Bus, use the following commands: **busyout board PCSS, reset board PCSS, test board PCSS long, release board PCSS**.

If the problem persists, and there are no PKT-BUS alarms or port alarms, then replace the circuit pack.

- t. The hyperactive circuit pack is out-of-service and may exhibit one or more of the following symptoms:
1. The common circuit pack level tests such as Test #50 and/or Test #52 are aborting with error code 2000.
  2. The tests run on the ports of this circuit pack are returning with a NO-BOARD.
  3. A busyout/release of the circuit pack has no affect on test results.
  4. A **list configuration** command shows that the circuit pack and ports are properly installed.

5 Maintenance Objects for DEFINITY ONE  
UDS1-BD (UDS1 Interface Circuit Pack)

5-1239

The circuit pack is isolated from the system and all trunks or ports on this circuit pack are placed into the out-of-service state. The system will try to restore the circuit pack within 20-30 minutes. When no faults are detected for 20-30 minutes, the UDS1 Interface circuit pack is restored to normal operation. All trunks or ports of the UDS1 Interface circuit pack are then returned to the in-service state. If the board is not restored to normal operation, or the error recurs after the board was restored to normal operation, escalate the problem.

- u. Only error 3073 will show that this board is receiving slips and the AUX data shows the last slip count that was reported.
- v. These errors are not service-affecting. No action is required. These errors are reported by the circuit pack when it receives a bad control channel message from the switch. The auxiliary data identifies the following error events:
  - 4096 Bad major heading
  - 4097 Bad port number
  - 4098 Bad data
  - 4099 Bad sub-qualifier
  - 4100 State inconsistency
  - 4101 Bad logical link
- w. Only error 3585 will show that this board is receiving misframes and the AUX data shows the last misframe count that was reported.
- x. The UDS1 Interface circuit pack has detected a transient hardware logic error (for example, program logic inconsistency). This error will disappear when no faults are detected for 100 minutes. The value in Aux Data field indicates the type of hardware problem.
- y. Bad Translation RAM Location Found Error. This error is not service-affecting. No action is required. A Bad Translation RAM is detected, but the call continues by using another translation location.
- z. LAN Receive Parity Error. This error occurs when the circuit pack detects an error in a received frame from the TDM Bus. These errors are most likely caused by a TDM Bus problem, but may be due to a circuit pack fault.
- aa. Error 3900 is used to give status information on a CPE Loopback Jack Test. The value in the Aux Data field indicates the status of the loopback test.
  - 1 — Test is currently running.
  - 2 — Test failed because loopback could not be activated.
  - 3 — Test failed because test pattern could not be detected.
  - 4 — Test has been terminated.

5 Maintenance Objects for DEFINITY ONE  
UDS1-BD (UDS1 Interface Circuit Pack)

5-1240

- ab. Error 3901 is used to give status information on a Far CSU Loopback Test. The value in the Aux Data field indicates the status of the loopback test.
    - 1 — Test is currently running.
    - 2 — Test failed because loopback could not be activated.
    - 3 — Test failed because test pattern could not be detected.
    - 4 — Test has been terminated.
  
  - ac. Error 3902 is used to give status information on a One-Way Span Test. The value in the Aux Data field indicates the status of the span test.
    - 1 — Test is currently running.
    - 2 — Test has failed because test could not be activated.
    - 3 — Test pattern was not received from the far end.
    - 4 — Test has been terminated.
  
  - ad. Error type 3999 indicates that the circuit pack sent a large number of control channel messages to the switch within a short period of time. If error type 1538 is also present, then the circuit pack was taken out-of-service due to hyperactivity. If error type 1538 is not present, then the circuit pack has not been taken out-of-service, but it has generated 50% of the messages necessary to be considered hyperactive. This may be completely normal during heavy traffic periods. However, if this error type is logged when the circuit pack is being lightly used, it may indicate a problem with the circuit pack or the equipment attached to it.
-

5 Maintenance Objects for DEFINITY ONE  
UDS1-BD (UDS1 Interface Circuit Pack)

5-1241

**System Technician-Demanded Tests: Descriptions  
and Error Codes**

Always investigate tests in the order they are presented in the table below when inspecting errors in the system. By clearing error codes associated with the *NPE Connection Audit Test*, for example, you may also clear errors generated from other tests in the testing sequence.

Table 5-506. System Technician-Demanded Tests: UDS1-BD

Order of Investigation	Short Test Sequence	Long Test Sequence	Reset Board Sequence	test ds1-loop Command	D/ND <sup>1</sup>
NPE Connection Audit Test (#50)		X			ND
Control Channel Loop Test (#52)		X			ND
Loss of Signal Alarm Inquiry Test (#138)	X	X			ND
Blue Alarm Inquiry Test (#139)	X	X			ND
Red Alarm Inquiry Test (#140)	X	X			ND
Yellow Alarm Inquiry Test (#141)	X	X			ND
Major Alarm Inquiry Test (#142)	X	X			ND
Minor Alarm Inquiry Test (#143)	X	X			ND
Slip Alarm Inquiry Test (#144)	X	X			ND
Misframe Alarm Inquiry Test (#145)	X	X			ND
Translation Update Test (#146)	X	X			ND
ICSU Status LEDs Test (#1227)	X	X			ND
SAKI Sanity Test (#53)			X		D
Internal Loop Around Test (#135)			X		D
DS1/CSU Loopback Tests					

Continued on next page

5 Maintenance Objects for DEFINITY ONE  
UDS1-BD (UDS1 Interface Circuit Pack)

5-1242

Table 5-506. System Technician-Demanded Tests: UDS1-BD — *Continued*

Order of Investigation	Short Test Sequence	Long Test Sequence	Reset Board Sequence	test ds1-loop Command	D/ND <sup>1</sup>
DS1 Board Loopback Test (#1209)				X	D
CSU Equipment Loopback Test (#1210)				X	D
CSU Repeater Loopback Test (#1211)				X	D
CPE Loopback Jack Test (#1212)				X	D
Far CSU Loopback Test (#1213)				X	D
One-Way Span Test (#1214)				X	D
Inject Single Bit Error (#1215)				X	D
End Loopback/Span Test (#1216)				X	D

---

1. D = Destructive; ND = Nondestructive

---

## NPE Connection Audit Test (#50)

The system sends a message to the on-board microprocessor to update the network connectivity translation for the SCOTCH-NPE chip on the circuit pack.

Table 5-507. TEST #50 NPE Connection Audit Test

Error Code	Test Result	Description/ Recommendation
None 2100	ABORT	System resources required for this test are not available. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
1019	ABORT	The test aborted because a test was already running on the port. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals for a maximum of 5 times.</li></ol>
	FAIL	Internal System Error <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
	PASS	The circuit pack's SCOTCH-NPE chip have been updated with its translation.
0	NO BOARD	The test could not relate the internal ID to the port (no board). This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted. <ol style="list-style-type: none"><li>1. Ensure that the board translations are correct. Execute the <b>add ds1 PCSS</b> command to administer the UDS1 interface if it is not already administered.</li><li>2. If the board was already administered correctly, check the error log to determine whether the board is hyperactive. If this is the case, the board is shut down. Reseating the board will re-initialize the board.</li><li>3. If the board was found to be correctly inserted in step 1, then issue the <b>busyout board</b> command.</li><li>4. Issue the <b>reset board</b> command.</li><li>5. Issue the <b>release busy board</b> command.</li><li>6. Issue the <b>test board long</b> command.</li></ol> <p>This should re-establish the linkage between the internal ID and the port.</p>

## Control Channel Loop Around Test (#52)

This test queries the circuit pack for its circuit pack code and vintage and verifies its records.

Table 5-508. TEST #52 Control Channel Loop Around Test

Error Code	Test Result	Description/ Recommendation
None 2100	ABORT	System resources required for this test are not available.  1. Retry the command at 1-minute intervals a maximum of 5 times.
	FAIL	The circuit pack failed to return the circuit pack code or vintage.  1. Retry the command a maximum of 5 times.  2. If the problem continues, and if the circuit pack is one of the Port circuit packs, replace the circuit pack.  3. Retry the command a few times a maximum of 5 times.
	PASS	Communication with this circuit pack is successful.
0	NO BOARD	The test could not relate the internal ID to the port (no board). This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.  1. Ensure that the board translations are correct. Execute the <b>add ds1 PCSS</b> command to administer the UDS1 interface if it is not already administered.  2. If the board was already administered correctly, check the error log to determine whether the board is hyperactive. If this is the case, the board is shut down. Reseating the board will re-initialize the board.  3. If the board was found to be correctly inserted in step 1, then issue the <b>busyout board</b> command.  4. Issue the <b>reset board</b> command.  5. Issue the <b>release busy board</b> command.  6. Issue the <b>test board long</b> command.  This should re-establish the linkage between the internal ID and the port.

## SAKI Sanity Test (#53)

**This test is destructive.**

This test resets the circuit pack. The test is highly destructive and can only be initiated by a system technician-demanded **reset board PCSS** command.

Table 5-509. TEST #53 SAKI Sanity Test

Error Code	Test Result	Description/ Recommendation
None	ABORT	System resources required for this test are not available.  1. Retry the <b>reset board</b> command at 1-minute intervals a maximum of 5 times.
1005	ABORT	Wrong circuit pack configuration to run this test. This error applies only to DS1 Interface circuit packs. It means the DS1 Interface circuit pack is providing timing for the system and, therefore, it cannot be reset without major system disruptions.  1. If the circuit pack needs to be reset, then set synchronization to another DS1 Interface circuit pack or to the Tone-Clock circuit pack and try again. Refer to " <a href="#">SYNC (Synchronization)</a> " on page 5-1063.
1015	ABORT	Port is not out-of-service.  1. Busyout the circuit pack. 2. Execute the <b>reset board</b> command again.
2100	ABORT	System resources required for this test are not available.  1. Retry the <b>reset board</b> command at 1-minute intervals a maximum of 5 times.
1	FAIL	The circuit pack failed to reset.
2	FAIL	The circuit pack failed to restart.  1. Execute the <b>reset board</b> command again. 2. If the problem persists, replace the circuit pack.
	PASS	The circuit pack initializes correctly.  1. Run the Short Test Sequence.

*Continued on next page*

Table 5-509. TEST #53 SAKI Sanity Test — *Continued*

Error Code	Test Result	Description/ Recommendation
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board). This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"><li>1. Ensure that the board translations are correct. Execute the <b>add ds1 PCSS</b> command to administer the UDS1 interface if it is not already administered.</li><li>2. If the board was already administered correctly, check the error log to determine whether the board is hyperactive. If this is the case, the board is shut down. Reseating the board will re-initialize the board.</li><li>3. If the board was found to be correctly inserted in step 1, then issue the <b>busyout board</b> command.</li><li>4. Issue the <b>reset board</b> command.</li><li>5. Issue the <b>release busy board</b> command.</li><li>6. Issue the <b>test board long</b> command.</li></ol> <p>This should re-establish the linkage between the internal ID and the port.</p>

## Internal Loop Around Test (#135)

### This test is destructive.

The Internal Loop Around Test is run by looping the transmitted DS1 bit stream back into the UDS1's board receiver. The loop occurs just before the DS1 facility interface. The test is highly destructive and can only be initiated by a system technician-demanded **reset board PCSS** command.

All trunks or ports on the UDS1 Interface circuit pack must be busied out via the system technician **busyout board** command before running the Internal Loop Around Test. When the Internal Loop Around Test is initiated, maintenance software sends appropriate messages to the UDS1 Interface circuit pack to start the test. The test uses the Tone Generator and Tone Detector to exercise a bit pattern consistency test for all ports. If the transmitted and received bit patterns on a trunk or port are different, the test fails.

When the test is complete, the maintenance software sends a stop loop around message to the UDS1 Interface circuit pack to put the circuit pack back into the normal operation mode. All trunks or ports of the UDS1 Interface circuit pack are restored to the in-service state after the **release board** command is entered.

Table 5-510. TEST #135 Internal Loop Around Test

Error Code	Test Result	Description/ Recommendation
2012	ABORT	Internal System Error <ol style="list-style-type: none"><li>1. Retry the <b>reset board</b> command at 1-minute intervals a maximum of 5 times.</li></ol>
1002	ABORT	The system could not allocate time slots for the test. The system may be under heavy traffic conditions or it may have time slots out-of-service due to TDM-BUS errors. Refer to " <a href="#">TDM-BUS (TDM Bus)</a> " on page 5-1116 to diagnose any active TDM-BUS errors. <ol style="list-style-type: none"><li>1. If system has no TDM-BUS errors and is not handling heavy traffic, repeat test at 1-minute intervals a maximum of 5 times.</li></ol>
1003	ABORT	The system could not allocate a tone receiver for the test. The system may be oversized for the number of Tone Detectors present or some Tone Detectors may be out-of-service. <ol style="list-style-type: none"><li>1. Look for TTR-LEV errors in the Error Log. If present, refer to "<a href="#">TTR-LEV (TTR Level)</a>" on page 5-1223.</li><li>2. Look for TONE-PT errors in the Error Log. If present, refer to "<a href="#">TONE-PT (Tone Generator)</a>" on page 5-1204.</li><li>3. If neither condition exists, retry the <b>reset board</b> command at 1-minute intervals a maximum of 5 times.</li></ol>
1004	ABORT	Received an incoming call on a port of the UDS1 circuit pack during the test. <ol style="list-style-type: none"><li>1. Enter the <b>busyout board PCSS</b> command to put all trunks or ports of the UDS1 Interface circuit pack to out-of-service state.</li><li>2. Retry the <b>reset board</b> command at 1-minute intervals a maximum of 5 times.</li></ol>
1015	ABORT	Ports on the UDS1 Interface circuit pack have not been busied out to out-of-service. <ol style="list-style-type: none"><li>1. Enter the <b>busyout board PCSS</b> command to put all trunks or ports of the UDS1 Interface circuit pack into the out-of-service state.</li><li>2. Retry the <b>reset board</b> command.</li></ol>

---

*Continued on next page*

Table 5-510. TEST #135 Internal Loop Around Test — *Continued*

Error Code	Test Result	Description/ Recommendation
1039	ABORT	<p>The UDS1 Interface circuit pack is providing timing for the system. Executing this test could cause major system disruption. If the UDS1 Interface circuit pack needs to be tested, set the synchronization reference to another DS1 Interface circuit pack or to the Tone-Clock circuit pack via the following command sequence:</p> <ol style="list-style-type: none"><li>1. Issue the <b>disable synchronization-switch</b> command.</li><li>2. Next, issue the <b>set synchronization PCSS</b> command.</li><li>3. Issue the <b>enable synchronization-switch</b> command. Then rerun the test. If the test aborts again, a different ABORT error code will be generated. Follow the recommended maintenance procedures for that error code.</li></ol>
2000	ABORT	<p>Response to the test request was not received within the allowable time period. If Error Type 1538 is present in the Error Log, follow the maintenance strategy recommended for this error type.</p>
2100	ABORT	<p>Could not allocate the necessary system resources to run this test.</p> <ol style="list-style-type: none"><li>1. Retry the <b>reset board</b> command at 1-minute intervals for a maximum of 5 times.</li></ol>
	FAIL	<p>The UDS1 Interface circuit pack failed in the Internal Loop Around Test. If the UDS1 connects to a T1 network facility or another switch:</p> <ol style="list-style-type: none"><li>1. Retry the <b>reset board</b> command at 1-minute intervals a maximum of 5 times.</li><li>2. Enter the <b>list measurement ds1-log PCSS</b> command to read the error seconds measurement.</li><li>3. Verify that both endpoints of the DS1 link are administered using the same signaling mode, framing mode, and line coding.</li><li>4. Check the physical connectivity of DS1 Interface circuit packs and cable.</li><li>5. Replace the local UDS1 Interface circuit pack and repeat the test.</li><li>6. Contact T1 Network Service to diagnose the remote DS1 endpoint. <i>More information continues on the next page.</i></li></ol>

*Continued on next page*

5 Maintenance Objects for DEFINITY ONE  
UDS1-BD (UDS1 Interface Circuit Pack)

5-1249

Table 5-510. TEST #135 Internal Loop Around Test — *Continued*

Error Code	Test Result	Description/ Recommendation
	FAIL ( <i>cont'd.</i> )	<p>If the UDS1 connects to a line-side terminating device such as a PRI terminal adapter:</p> <ol style="list-style-type: none"><li>1. Retry the <b>reset board</b> command at 1-minute intervals a maximum of 5 times.</li><li>2. Enter the <b>list measurement ds1-log PCSS</b> command to read the error seconds measurement.</li><li>3. Verify that the switch DS1 and the line-side terminating device are administered using the same signaling mode, framing mode, and line coding.</li><li>4. Investigate the maintenance status of the line-side terminating device. Obtain the error seconds measurement on the terminating device (if possible). Refer to the line-side terminating device operating manual for information.</li><li>5. Check the physical connection of the UDS1 Interface circuit pack to the terminating device. Check premise distribution system (or intra-premise wiring) for physical connection failures. If the error seconds measurement is severe, investigate premise distribution system wiring for noise and distance limitation.</li><li>6. Replace the local UDS1 Interface circuit pack and repeat the test.</li><li>7. Contact the vendor of the line-side terminating device to diagnose the equipment.</li></ol>
	PASS	<p>All administered trunks or ports of the UDS1 Interface circuit pack pass the Internal Loop Around Test. The bit pattern consistency test is executed successfully over the path that covers a DS1 port, cable, and the external NCTE device.</p>

*Continued on next page*

Table 5-510. TEST #135 Internal Loop Around Test — *Continued*

Error Code	Test Result	Description/ Recommendation
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board). This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"> <li>1. Ensure that the board translations are correct. Execute the <b>add ds1 PCSS</b> command to administer the UDS1 interface if it is not already administered.</li> <li>2. If the board was already administered correctly, check the error log to determine whether the board is hyperactive. If this is the case, the board is shut down. Reseating the board will re-initialize the board.</li> <li>3. If the board was found to be correctly inserted in step 1, then issue the <b>busyout board</b> command.</li> <li>4. Issue the <b>reset board</b> command.</li> <li>5. Issue the <b>release busy board</b> command.</li> <li>6. Issue the <b>test board long</b> command.</li> </ol> <p>This should re-establish the linkage between the internal ID and the port.</p>

### Loss of Signal Alarm Inquiry Test (#138)

This test verifies the synchronization status and continuity of the DS1 link. The Loss of Signal alarm indicates that the UDS1 Interface circuit pack is unable to derive the synchronization clock from the DS1 facility. When the UDS1 Interface circuit pack detects a Loss of Signal alarm, it stops providing the synchronization clock for the system if it is administered as a timing source and transmits a Yellow alarm to the remote DS1 endpoint.

When the Loss of Signal alarm is confirmed, the maintenance software places all trunks or ports of the UDS1 Interface circuit pack into the out-of-service state. The inquiry test will run every 10 minutes until the loss of signal has been restored.

The UDS1 Interface circuit pack raises a Loss of Signal alarm after the signal has been lost for about 3 seconds. It will not retire the alarm until the signal has returned for about 10 seconds.

This test is also used to maintain the 120A CSU Module. This CSU Module, when combined with the functionality provided by the TN464F circuit pack, provides functionality equivalent to an external stand-alone ESF T1 CSU. The 120A2 CSU Module is known as an Enhanced Integrated CSU (I-CSU).

5 Maintenance Objects for DEFINITY ONE  
UDS1-BD (UDS1 Interface Circuit Pack)

5-1251

If a TN464F circuit pack detects certain I-CSU hardware errors, it will notify maintenance. When the maintenance subsystem receives notification of the I-CSU error, it will execute this Loss of Signal Inquiry test. The test, in addition to querying for a Loss Of Signal alarm condition, will also query the TN464F board to confirm the I-CSU error. A Minor or Warning alarm will be raised depending on the severity of the I-CSU error. The trunks on the board may be taken out of service if the I-CSU error is deemed serious.

If a Loss Of Signal alarm and an I-CSU error co-exist, the Loss Of Signal alarm condition will take priority and the board and all trunks on the board will be put in the out-of-service state. Errors will be logged, however, for both.

When the maintenance subsystem receives notification that the I-CSU hardware error condition no longer exists, maintenance will restore the board and all trunks to their previous service state if the alarm can be cleared (no other I-CSU errors or Loss Of Signal alarm exist).

Table 5-511. TEST #138 Loss of Signal Alarm Inquiry Test

Error Code	Test Result	Description/ Recommendation
	ABORT	Internal System Error 1. Retry the command at 1-minute intervals a maximum of 5 times.
2000	ABORT	Response to the test was not received within the allowable time period. This may be due to hyperactivity. Error type 1538 in the error log indicates hyperactivity. The hyperactive circuit pack is out of service and one or more of the following symptoms may be exhibited. <ol style="list-style-type: none"> <li>1. The UDS1-BD tests (such as test 138 and test 139) are aborting with error code 2000.</li> <li>2. The tests run on the ports of this circuit pack are returning a no board result.</li> <li>3. A <b>busyout</b> or a <b>release</b> command has no affect on the test results.</li> <li>4. A <b>list config</b> command shows that the circuit pack and the ports are properly installed.</li> </ol> When hyperactivity occurs, the circuit pack is isolated from the system, and all of the trunks for this circuit pack are placed into the out of service state. The system will try to restore the circuit pack within 15 minutes. When no faults are detected for 15 minutes, the UDS1 interface circuit pack is restored to normal operation. All of the trunks for the UDS1 interface circuit pack are then returned to the in service state. Hyperactivity is often caused by the associated facility. In such a case, faults (such as slips, misframes, or blue alarms) would be entered in the error log. In addition, many hardware errors would be logged against the associated trunk circuits. If the facility is OK and the error occurs again after 15 minutes, replace the circuit pack.

Table 5-511. TEST #138 Loss of Signal Alarm Inquiry Test — Continued

Error Code	Test Result	Description/ Recommendation
2100	ABORT	<p>Could not allocate the necessary system resources to run this test.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals for a maximum of 5 times.</li> </ol>
	FAIL	<p>UDS1 Interface circuit pack detects a Loss of Signal alarm. The physical link is broken or the remote DS1 endpoint is down. All trunks or ports of this UDS1 interface circuit pack are out-of-service. If the UDS1 Interface circuit pack is designated as the supplier of the system synchronization source, then the system synchronization maintenance will adopt a source elsewhere. Refer to <a href="#">“SYNC (Synchronization)” on page 5-1063</a> for details. If the UDS1 connects to a T1 network facility:</p> <ol style="list-style-type: none"> <li>1. Check the physical connection of the UDS1 Interface circuit pack and the cable. If a 120A1 CSU Module is physically connected to a TN464F board on the back of the port carrier, check the physical connection of the CSU Module and make sure the Network Interface cable is plugged into the CSU Module's NETWORK jack.</li> <li>2. If the UDS1 Interface circuit pack connects to a T1 facility, call the vendor of the T1 carrier to diagnose the remote DS1 endpoint.</li> </ol> <p>If the UDS1 Interface circuit pack connects directly to a switch, call the system technician of the remote switch to diagnose the DS1 endpoint. If the UDS1 connects to a line-side terminating device such as a PRI terminal adapter:</p> <ol style="list-style-type: none"> <li>1. Check the physical connection of the UDS1 Interface circuit pack to the terminating device. Check premise distribution system (or intra-premise wiring) for physical connection failures. If a 120A1 CSU Module is physically connected to a TN464F board on the back of the port carrier, check the physical connection of the CSU Module and make sure the Network Interface cable is plugged into the CSU Module's NETWORK jack.</li> <li>2. Contact the vendor of the line-side terminating device to diagnose the equipment.</li> </ol>
1300		<p>The CSU Module is missing. The <i>Near-End CSU Type</i> field on the <b>add ds1</b> form has been administered as <b>integrated</b> but the 120A1 CSU Module is not physically connected to the TN464F board on the back of the port carrier.</p> <ol style="list-style-type: none"> <li>1. If using the 120A1 CSU Module, plug the CSU Module into the TN464F circuit pack's connector on the I/O connector panel on back of the carrier. Otherwise, change the <i>Near-End CSU Type</i> field using the <b>change ds1</b> form to <b>other</b>.</li> <li>2. Run the test again.</li> </ol>

Continued on next page

Table 5-511. TEST #138 Loss of Signal Alarm Inquiry Test — Continued

Error Code	Test Result	Description/ Recommendation
1301	FAIL	<p>The 120A1 CSU Module is physically connected to the TN464F board on the back of the port carrier but the Near-End CSU Type field on the <b>add ds1</b> form has not been administered as <b>integrated</b>.</p> <ol style="list-style-type: none"><li>1. If the 120A1 CSU Module is to be used, use the <b>change ds1</b> command to change the Near-End CSU Type field to <b>integrated</b>. Otherwise, physically remove the 120A1 CSU Module from the back of the port carrier.</li><li>2. Run the test again.</li></ol>
1302	FAIL	<p>Attempting to use the 120A1 CSU Module with a TN464F circuit pack that is configured for 32-channel (2.048 Mbps) operation. The CSU Module only works with a DS1 board configured for 24-channel (1.544 Mbps) operation in the United States of America.</p> <ol style="list-style-type: none"><li>1. If the 120A1 CSU Module is to be used, physically remove the TN464F circuit pack and reconfigure for 24-channel (1.544 Mbps) operation.</li><li>2. Reinsert the circuit pack and run the test again.</li></ol>
1303	FAIL	<p>The DS1 circuit pack Suffix is incorrect for CSU Module administration. The Near-End CSU Type field on the <b>add ds1</b> form has been administered as <b>integrated</b>, but the DS1 circuit pack is not a TN464F or later suffix UDS1 board.</p> <ol style="list-style-type: none"><li>1. If the CSU Module is to be used, and the Near-End CSU Type field is set to <b>integrated</b> to allow for CSU Module administration, remove the circuit pack and replace with a TN464F or later suffix board. Otherwise, use the <b>change ds1</b> command to change the Near-End CSU Type field to <b>other</b>.</li></ol>
1310	FAIL	<p>The DS1 Board Loopback (BLB) demand test (#1209) failed.</p> <ol style="list-style-type: none"><li>1. Repeat the test using the <b>test ds1-loop PCSS ds1/csu-loopback-tests</b> command.</li><li>2. If the BLB test continues to fail, then replace the TN464F circuit pack.</li><li>3. Run this test again.</li></ol>

*Continued on next page*

Table 5-511. TEST #138 Loss of Signal Alarm Inquiry Test — Continued

Error Code	Test Result	Description/ Recommendation
1311	FAIL	<p>The Integrated CSU (I-CSU) Module Equipment Loopback (ELB) test (#1210) failed. This test is executed by the I-CSU during I-CSU power-up/reset (i.e.- TN464F board physically inserted and 120A1 CSU Module already installed) or when the 120A1 CSU Module is plugged on to an already initialized DS1 board. The ELB test is also executed as part of the command <b>test ds1-loop PCSS ds1/csu-loopback-tests</b>.</p> <ol style="list-style-type: none"> <li>1. Execute the <b>test ds1-loop PCSS ds1/csu-loopback-tests</b> command.</li> <li>2. If the ELB test continues to fail, then either the TN464F board, the CSU Module, or the I/O cable between the backplane and the CSU module (or any combination thereof) has failed. Attempt to isolate the problem to one of these areas. Begin by replacing the CSU Module and running the <b>test ds1-loop PCSS ds1/csu-loopback-tests</b> command again.</li> <li>3. If the ELB test continues to fail, then replace the TN464F board and run the <b>test ds1-loop PCSS ds1/csu-loopback-tests</b> command again.</li> <li>4. If the ELB test continues to fail, the problem could be in the I/O cable between the backplane and the CSU module.</li> </ol>
1312	FAIL	<p>The Integrated CSU (I-CSU) Module Repeater Loopback (RLB) test (#1211) failed. This test is executed by the I-CSU during I-CSU power-up/reset (i.e.- TN464F board physically inserted and 120A1 CSU Module already installed) or when the 120A1 CSU Module is plugged on to an already initialized DS1 board. The RLB test is also executed as part of the command <b>test ds1-loop PCSS ds1/csu-loopback-tests</b>.</p> <ol style="list-style-type: none"> <li>1. Execute the <b>test ds1-loop PCSS ds1/csu-loopback-tests</b> command.</li> <li>2. If the RLB test continues to fail, then replace the CSU Module.</li> <li>3. Run this test again.</li> </ol>
1313	FAIL	<p>The TN464F circuit pack could not deactivate a CPE Loopback Jack loopback.</p> <ol style="list-style-type: none"> <li>1. Execute the <b>test ds1-loop PCSS end-loopback/span-test</b> command.</li> <li>2. If the attempt to deactivate the CPE Loopback Jack loopback is not successful, check the cabling and investigate the problem at the CPE Loopback Jack.</li> <li>3. Run the test again.</li> </ol>
1314	FAIL	<p>The TN464F circuit pack could not deactivate a far-end CSU loopback.</p> <ol style="list-style-type: none"> <li>1. Execute the <b>test ds1-loop PCSS end-loopback/span-test</b> command.</li> <li>2. If the attempt to deactivate the far-end CSU loopback continues to fail, then escalate the problem.</li> </ol>

Continued on next page

5 Maintenance Objects for DEFINITY ONE  
UDS1-BD (UDS1 Interface Circuit Pack)

5-1255

Table 5-511. TEST #138 Loss of Signal Alarm Inquiry Test — *Continued*

Error Code	Test Result	Description/ Recommendation
1320	FAIL	<p>A 120A1 CSU module hardware failure or an ICSU serial interface audit failure was detected by the TN464F UDS1 circuit pack.</p> <ol style="list-style-type: none"><li>1. Replace the CSU module, and then run the test again.</li><li>2. If the test continues to fail with this error code, replace the TN464F and run the test again.</li><li>3. If the test continues to fail with this error code, then the problem could be in the I/O cable between the backplane and the CSU module.</li></ol>
1321	FAIL	<p>DTE LOS (loss of signal) was detected between the TN464F UDS1 board and the 120A1 CSU Module. Either the TN464F board, the 120A1 CSU Module, or the I/O cable between the backplane and the CSU module (or any combination thereof) has failed. Attempt to isolate the problem to one of these areas.</p> <ol style="list-style-type: none"><li>1. Replace the CSU Module and run the test again.</li><li>2. If the test continues to fail with this error code, then replace the TN464F board and run the test again.</li><li>3. If the test continues to fail with this error code, the problem could be in the I/O cable between the backplane and the CSU module.</li></ol>
1322	FAIL	<p>No 5 volts power detected from the TN464F circuit pack to the 120A1 CSU Module. Problem probably due to an open fuse on the DS1 board or a faulty ICSU.</p> <p> <b>NOTE:</b> Do not immediately swap DS1 boards as this may blow the fuse on the new board.</p> <ol style="list-style-type: none"><li>1. If the test continues to fail with this error code, then replace the CSU Module and run the test again.</li><li>2. Remove the TN464F from the system and reinsert.</li><li>3. Run the test again once the board has finished its reset.</li><li>4. If the test continues to fail with this error code, then replace the TN464F board and run the test again.</li><li>5. If the test continues to fail with this error code, the problem could be in the I/O cable between the backplane and the CSU module.</li></ol>
1323	FAIL	<p>A service affecting CSU Module audit failure was detected by the TN464F UDS1 circuit pack. All administered ports on the UDS1 circuit pack are affected and maintenance software will place the ports into the out-of-service state.</p> <ol style="list-style-type: none"><li>1. Replace the 120A1 CSU Module.</li></ol>

*Continued on next page*

Table 5-511. TEST #138 Loss of Signal Alarm Inquiry Test — *Continued*

Error Code	Test Result	Description/ Recommendation
1324	FAIL	A non-service affecting CSU Module audit failure was detected by the TN464F UDS1 circuit pack. No ports should be affected. No immediate action is required. These errors indicate that the CSU Module hardware may have a problem, and that it should be replaced when practical to avoid further deterioration.
	PASS	DS1 signal is present and the physical link is healthy. In addition, no Integrated CSU errors are detected.
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board). This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"><li>1. Ensure that the board translations are correct. Execute the <b>add ds1 PCSS</b> command to administer the UDS1 interface if it is not already administered.</li><li>2. If the board was already administered correctly, check the error log to determine whether the board is hyperactive. If this is the case, the board is shut down. Reseating the board will re-initialize the board.</li><li>3. If the board was found to be correctly inserted in step 1, then issue the <b>busyout board</b> command.</li><li>4. Issue the <b>reset board</b> command.</li><li>5. Issue the <b>release busy board</b> command.</li><li>6. Issue the <b>test board long</b> command.</li></ol> <p>This should re-establish the linkage between the internal ID and the port.</p>

## Blue Alarm Inquiry Test (#139)

The Blue Alarm is a signal sent by the remote DS1 endpoint when it is out-of-service. The Blue Alarm Inquiry Test checks the blue alarm status of the remote DS1 endpoint.

When the UDS1 Interface circuit pack detects a Blue Alarm signal from the remote DS1 endpoint, the circuit pack will transmit a Yellow alarm to the remote DS1 endpoint and send a BLUE ALARM message to the maintenance software. When the Blue alarm is confirmed, the maintenance software places all trunks or ports of the UDS1 Interface circuit pack into the out-of-service state. The inquiry test will be run every 10 minutes until the Blue alarm is cleared.

The UDS1 Interface circuit pack takes 3 seconds to recognize and report a Blue alarm and 16 seconds to recognize and report the resolution of a Blue alarm. When the Blue alarm is cleared, the UDS1 Interface circuit pack stops transmitting the Yellow alarm and places the trunks or ports back into the service state before the Blue alarm occurs.

## Line Loopback Alarm

The Line Loopback (LLB) is used by the remote DS1 endpoint to put the switch DS1 into a loopback mode. When the switch DS1 is in the LLB mode, the arriving bit pattern is regenerated and sent back. Line Loopback (LLB) Alarm is activated when the in-band activate LLB bit pattern has been arriving continuously for 5 seconds on the DS1 line. LLB is deactivated when the in-band deactivate LLB bit pattern has been arriving continuously for 5 seconds on the DS1 line.

Since LLB is a maintenance condition rendering all DS0 channels unavailable for signaling or bearer traffic, maintenance software treats this the same as a Blue Alarm.

## Payload Loopback Alarm

The Payload Loopback (PLB) is used by the remote DS1 endpoint to put the switch DS1 into a loopback mode. PLB Alarm is activated when a network protocol activate bit pattern arrives over the 4Kbps ESF data link on the DS1 line. PLB is deactivated when a network protocol deactivate bit pattern arrives over the 4Kbps ESF data link on the DS1 line.

Since PLB is a maintenance condition rendering all DS0 channels unavailable for signaling or bearer traffic, maintenance software treats this the same as a Blue Alarm.

Table 5-512. TEST #139 Blue Alarm Inquiry Test

Error Code	Test Result	Description/ Recommendation
	ABORT	Internal System Error 1. Retry the command at 1-minute intervals a maximum of 5 times.
2000	ABORT	Response to the test was not received within the allowable time period. This may be due to hyperactivity. Error type 1538 in the error log indicates hyperactivity. The hyperactive circuit pack is out of service and one or more of the following symptoms may be exhibited. 1. The UDS1-BD tests (such as test 138 and test 139) are aborting with error code 2000. 2. The tests run on the ports of this circuit pack are returning a no board result. 3. A <b>busyout</b> or a <b>release</b> command has no affect on the test results. 4. A <b>list config</b> command shows that the circuit pack and the ports are properly installed. When hyperactivity occurs, the circuit pack is isolated from the system, and all of the trunks for this circuit pack are placed into the out of service state. The system will try to restore the circuit pack within 15 minutes. When no faults are detected for 15 minutes, the UDS1 interface circuit pack is restored to normal operation. All of the trunks for the UDS1 interface circuit pack are then returned to the in service state. Hyperactivity is often caused by the associated facility. In such a case, faults (such as slips, misframes, or blue alarms) would be entered in the error log. In addition, many hardware errors would be logged against the associated trunk circuits. If the facility is OK and the error occurs again after 15 minutes, replace the circuit pack.
2100	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals for a maximum of 5 times.
1 1794	FAIL FAIL	The remote DS1 endpoint is out-of-service. The UDS1 Interface circuit pack detects a Line Loopback Alarm (LLB). If the UDS1 interface circuit pack connects to a T1 facility, call the vendor of the T1 carrier to diagnose the remote DS1 endpoint. If the UDS1 interface circuit pack connects directly to a switch, call the system technician of the remote switch to diagnose the DS1 endpoint. If the UDS1 interface circuit pack connects directly to a line-side terminating device (for example, a PRI terminal adapter), call the vendor of the terminating device to diagnose the equipment.

Continued on next page

Table 5-512. TEST #139 Blue Alarm Inquiry Test — *Continued*

Error Code	Test Result	Description/ Recommendation
1795	FAIL	<p>The UDS1 Interface circuit pack detects a Payload Loopback Alarm (PLB).</p> <p>If the UDS1 Interface circuit pack connects to a leased T1 facility, call the vendor of the T1 carrier to diagnose the remote DS1 endpoint. If the UDS1 Interface circuit pack connects directly to another DS1 board, call the system technician of the remote switch to diagnose the DS1 endpoint.</p> <p>If the UDS1 Interface circuit pack connects directly to a line-side terminating device such as a PRI terminal adapter contact the vendor of the terminating device to diagnose the equipment.</p>
	PASS	<p>Remote DS1 endpoint is in-service. Neither a Blue alarm nor a Line Loopback alarm nor a Payload Loopback alarm is detected by the UDS1 Interface circuit pack.</p>
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board). This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"><li>1. Ensure that the board translations are correct. Execute the <b>add ds1 PCSS</b> command to administer the UDS1 interface if it is not already administered.</li><li>2. If the board was already administered correctly, check the error log to determine whether the board is hyperactive. If this is the case, the board is shut down. Reseating the board will re-initialize the board.</li><li>3. If the board was found to be correctly inserted in step 1, then issue the <b>busyout board</b> command.</li><li>4. Issue the <b>reset board</b> command.</li><li>5. Issue the <b>release busy board</b> command.</li><li>6. Issue the <b>test board long</b> command.</li></ol> <p>This should re-establish the linkage between the internal ID and the port.</p>

## Red Alarm Inquiry Test (#140)

A UDS1 Interface circuit pack raises a Red alarm when the framing pattern of the incoming DS1 bit stream has been lost. The Red Alarm Inquiry Test checks the framing status of a UDS1 Interface circuit pack. A UDS1 Interface circuit pack takes 3 seconds to recognize and report a Red alarm and 10 seconds to recognize and report the resolution of a Red alarm.

When the UDS1 Interface circuit pack detects a Red alarm, the circuit pack will transmit a Yellow alarm to the remote DS1 endpoint and send a RED ALARM message to the maintenance software. After the Red alarm is confirmed, the maintenance software places all trunks or ports of the circuit pack into the out-of-service state. The inquiry test will be run every 10 minutes until the Red alarm is cleared.

When the Red alarm is cleared, the UDS1 Interface circuit pack will stop transmitting the Yellow alarm to the remote DS1 endpoint. The maintenance software restores all trunks or ports of the UDS1 Interface circuit pack to the service state before the Red alarm occurs.

## Loss of Multiframe Alarm

If the UDS1 Interface circuit pack is administered using DMI-BOS signaling, the UDS1 Interface circuit pack raises a Loss of Multiframe Alarm (LMA) when it cannot interpret the incoming signaling bits to synchronize to the multiframe pattern received in the 24th channel. Once the UDS1 Interface circuit pack detects an LMA, the circuit pack will transmit a Remote Multiframe Alarm (RMA) to the remote DS1 endpoint. Maintenance software handles both Red alarm and LMA alarm(s) using the same mechanism.

Table 5-513. TEST #140 Red Alarm Inquiry Test

Error Code	Test Result	Description/ Recommendation
	ABORT	Internal System Error <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
2000	ABORT	<p>Response to the test was not received within the allowable time period. This may be due to hyperactivity. Error type 1538 in the error log indicates hyperactivity. The hyperactive circuit pack is out of service and one or more of the following symptoms may be exhibited.</p> <ol style="list-style-type: none"><li>1. The UDS1-BD tests (such as test 138 and test 139) are aborting with error code 2000.</li><li>2. The tests run on the ports of this circuit pack are returning a no board result.</li><li>3. A <b>busyout</b> or a <b>release</b> command has no affect on the test results.</li><li>4. A <b>list config</b> command shows that the circuit pack and the ports are properly installed.</li></ol> <p> <b>NOTE:</b> When hyperactivity occurs, the circuit pack is isolated from the system, and all of the trunks for this circuit pack are placed into the out of service state. The system will try to restore the circuit pack within 15 minutes. When no faults are detected for 15 minutes, the UDS1 interface circuit pack is restored to normal operation. All of the trunks for the UDS1 interface circuit pack are then returned to the in service state. Hyperactivity is often caused by the associated facility. In such a case, faults (such as slips, misframes, or blue alarms) would be entered in the error log. In addition, many hardware errors would be logged against the associated trunk circuits. If the facility is OK and the error occurs again after 15 minutes, replace the circuit pack.</p>

*Continued on next page*

Table 5-513. TEST #140 Red Alarm Inquiry Test — *Continued*

Error Code	Test Result	Description/ Recommendation
	FAIL	<p>The UDS1 interface circuit pack detected a red alarm. An out of frame condition occurred on the UDS1 interface circuit pack. The UDS1 interface circuit pack will transmit a yellow alarm to the remote UDS1 endpoint until the red alarm is retired.</p> <p>If the UDS1 connects to a T1 network facility or to another switch, do the following.</p> <ol style="list-style-type: none"> <li>1. Verify that both endpoints of the DS1 link are administered using the same signaling mode, framing mode, and line coding.</li> <li>2. Contact T1 Network Service or a technician at the far-end switch to diagnose the remote DS1 endpoint.</li> <li>3. Check the physical connectivity of the UDS1 packs and of the cable.</li> <li>4. Replace the local UDS1 interface circuit pack, and repeat the test.</li> </ol> <p>If the UDS1 connects to a line-side terminating device (for example, a PRI terminal adapter), do the following.</p> <ol style="list-style-type: none"> <li>1. Verify that the switch DS1 and the line-side terminating device are administered using the same signaling mode, framing mode, and line coding.</li> <li>2. Investigate the maintenance status of the line-side terminating device. Refer to the 'Line-Side Terminating Device Operating Manual' for information.</li> <li>3. Contact the vendor of the line-side terminating device to diagnose the equipment.</li> <li>4. Check the physical connection of the UDS1 interface circuit pack to the terminating device, and check the premise distribution system (or the intra-premise wiring) for physical connection failures.</li> <li>5. Replace the local UDS1 interface circuit pack and repeat the test.</li> </ol>

*Continued on next page*

Table 5-513. TEST #140 Red Alarm Inquiry Test — *Continued*

Error Code	Test Result	Description/ Recommendation
1	FAIL	<p>The UDS1 interface circuit pack detected a loss of multiframe alarm (LMA). An out of frame condition occurred on the UDS1 interface circuit pack. The UDS1 interface circuit pack will transmit a remote multiframe alarm (RMA) to the remote UDS1 endpoint until the LMA is retired.</p> <p>If the UDS1 connects to a T1 network facility or to another switch, do the following:</p> <ol style="list-style-type: none"> <li>1. Verify that both endpoints of the DS1 link are administered using the same signaling mode, framing mode, and line coding.</li> <li>2. Contact T1 Network Service or a technician at the far-end switch to diagnose the remote DS1 endpoint.</li> <li>3. Check the physical connectivity of the UDS1 packs and of the cable.</li> <li>4. Replace the local UDS1 interface circuit pack, and repeat the test.</li> </ol> <p>If the UDS1 connects to a line-side terminating device (for example, a PRI terminal adapter), do the following.</p> <ol style="list-style-type: none"> <li>1. Verify that the switch DS1 and the line-side terminating device are administered using the same signaling mode, framing mode, and line coding.</li> <li>2. Investigate the maintenance status of the line-side terminating device. Refer to the 'Line-Side Terminating Device Operating Manual' for information.</li> <li>3. Contact the vendor of the line-side terminating device to diagnose the equipment.</li> <li>4. Check the physical connection of the UDS1 interface circuit pack to the terminating device, and check the premise distribution system (or the intra-premise wiring) for physical connection failures.</li> <li>5. Replace the local UDS1 interface circuit pack and repeat the test.</li> </ol>

*Continued on next page*

Table 5-513. TEST #140 Red Alarm Inquiry Test — *Continued*

Error Code	Test Result	Description/ Recommendation
	PASS	No Red alarm is detected on the UDS1 Interface circuit pack.
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board). This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"><li>1. Ensure that the board translations are correct. Execute the <b>add ds1 PCSS</b> command to administer the UDS1 interface if it is not already administered.</li><li>2. If the board was already administered correctly, check the error log to determine whether the board is hyperactive. If this is the case, the board is shut down. Reseating the board will re-initialize the board.</li><li>3. If the board was found to be correctly inserted in step 1, then issue the <b>busyout board</b> command.</li><li>4. Issue the <b>reset board</b> command.</li><li>5. Issue the <b>release busy board</b> command.</li><li>6. Issue the <b>test board long</b> command.</li></ol> <p>This should re-establish the linkage between the internal ID and the port.</p>

## Yellow Alarm Inquiry Test (#141)

Receiving a Yellow alarm from remote DS1 endpoint indicates that the remote DS1 endpoint has an out-of-frame condition. The Yellow Alarm Inquiry Test is used to determine whether the remote DS1 endpoint is transmitting a Yellow alarm. The UDS1 Interface circuit pack takes 500 msec to recognize and report a Yellow alarm and 500 msec to recognize and report that a Yellow alarm condition is cleared.

When the UDS1 Interface circuit pack detects a Yellow alarm from the remote DS1 endpoint, it will send a YELLOW-ALARM uplink message to the maintenance software. After the maintenance software receives the YELLOW-ALARM message, the Yellow Alarm Inquiry Test is run to confirm the Yellow alarm. Once the Yellow alarm is confirmed, the maintenance software places all trunks or ports on the circuit pack into the out-of-service state. The Inquiry Test will be run every 10 minutes until the Yellow alarm is cleared.

When the Yellow alarm is cleared, the maintenance software restores all trunks or ports on the UDS1 Interface circuit pack back to their previous service state before the Yellow alarm was raised.

This Yellow alarm corresponds to the yellow F2 state documented in CCITT Recommendation I.431.

## Remote Multiframe Alarm

Remote Multiframe Alarm (RMA) indicates that the remote DS1 endpoint is in a Loss of Multiframe Alarm condition while the UDS1 Interface circuit pack is administered using the DMI-BOS common channel signaling. The RMA is handled as a Yellow alarm.

## Yellow F5 Fault Alarm

For 32-channel E1 operation with CRC4 on, the F5 fault state is defined as a fault in the user-network interface, specifically in the direction from the user (PBX) to the network. Refer to CCITT recommendation I.431.

Table 5-514. TEST #141 Yellow Alarm Inquiry Test

Error Code	Test Result	Description/ Recommendation
	ABORT	Internal System Error <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
2000	ABORT	<p>Response to the test was not received within the allowable time period. This may be due to hyperactivity. Error type 1538 in the error log indicates hyperactivity. The hyperactive circuit pack is out of service and one or more of the following symptoms may be exhibited.</p> <ol style="list-style-type: none"><li>1. The UDS1-BD tests (such as test 138 and test 139) are aborting with error code 2000.</li><li>2. The tests run on the ports of this circuit pack are returning a no board result.</li><li>3. A <b>busyout</b> or a <b>release</b> command has no affect on the test results.</li><li>4. A <b>list config</b> command shows that the circuit pack and the ports are properly installed.</li></ol> <p>When hyperactivity occurs, the circuit pack is isolated from the system, and all of the trunks for this circuit pack are placed into the out of service state. The system will try to restore the circuit pack within 15 minutes. When no faults are detected for 15 minutes, the UDS1 interface circuit pack is restored to normal operation. All of the trunks for the UDS1 interface circuit pack are then returned to the in service state. Hyperactivity is often caused by the associated facility. In such a case, faults (such as slips, misframes, or blue alarms) would be entered in the error log. In addition, many hardware errors would be logged against the associated trunk circuits. If the facility is OK and the error occurs again after 15 minutes, replace the circuit pack.</p>

*Continued on next page*

Table 5-514. TEST #141 Yellow Alarm Inquiry Test — *Continued*

Error Code	Test Result	Description/ Recommendation
	FAIL	<p>The UDS1 interface circuit pack detected a yellow alarm sent by the remote DS1 endpoint. An out of frame condition occurred at the DS1 endpoint. If the UDS1 connects to a T1 network facility or to another switch, do the following:</p> <ol style="list-style-type: none"><li>1. Verify that both endpoints of the DS1 link are administered using the same signaling mode, framing mode, and line coding.</li><li>2. Contact T1 Network Service or a technician at the far-end switch to diagnose the remote DS1 endpoint.</li><li>3. Check the physical connectivity of the UDS1 packs and of the cable.</li><li>4. Replace the local UDS1 interface circuit pack, and repeat the test.</li></ol> <p>If the UDS1 connects to a line-side terminating device (for example, a PRI terminal adapter), do the following:</p> <ol style="list-style-type: none"><li>1. Verify that the switch DS1 and the line-side terminating device are administered using the same signaling mode, framing mode, and line coding.</li><li>2. Investigate the maintenance status of the line-side terminating device. Refer to the 'Line-Side Terminating Device Operating Manual' for information.</li><li>3. Contact the vendor of the line-side terminating device to diagnose the equipment.</li><li>4. Check the physical connection of the UDS1 interface circuit pack to the terminating device, and check the premise distribution system (or the intra-premise wiring) for physical connection failures.</li><li>5. Replace the local UDS1 interface circuit pack and repeat the test.</li></ol>

*Continued on next page*

Table 5-514. TEST #141 Yellow Alarm Inquiry Test — *Continued*

Error Code	Test Result	Description/ Recommendation
1	FAIL	<p>The UDS1 interface circuit pack detected a remote multiframe alarm (RMA) sent by the remote DS1 endpoint. An out of frame condition occurred at the DS1 endpoint.</p> <p>If the UDS1 connects to a T1 network facility or to another switch, do the following:</p> <ol style="list-style-type: none"> <li>1. Verify that both endpoints of the DS1 link are administered using the same signaling mode, framing mode, and line coding.</li> <li>2. Contact T1 Network Service or a technician at the far-end switch to diagnose the remote DS1 endpoint.</li> <li>3. Check the physical connectivity of the UDS1 packs and of the cable.</li> <li>4. Replace the local UDS1 interface circuit pack, and repeat the test.</li> </ol> <p>If the UDS1 connects to a line-side terminating device (for example, a PRI terminal adapter), do the following:</p> <ol style="list-style-type: none"> <li>1. Verify that the switch DS1 and the line-side terminating device are administered using the same signaling mode, framing mode, and line coding.</li> <li>2. Investigate the maintenance status of the line-side terminating device. Refer to the 'Line-Side Terminating Device Operating Manual' for information.</li> <li>3. Contact the vendor of the line-side terminating device to diagnose the equipment.</li> <li>4. Check the physical connection of the UDS1 interface circuit pack to the terminating device, and check the premise distribution system (or the intra-premise wiring) for physical connection failures.</li> <li>5. Replace the local UDS1 interface circuit pack and repeat the test.</li> </ol>

*Continued on next page*

Table 5-514. TEST #141 Yellow Alarm Inquiry Test — *Continued*

Error Code	Test Result	Description/ Recommendation
2	FAIL	<p>The UDS1 interface circuit pack is reporting a Yellow F5 fault alarm. There is a fault in the User-Network interface from the user (PBX) to the network. An out-of-frame condition occurs on the remote DS1 endpoint.</p> <p>If the UDS1 connects to a T1 network facility:</p> <ol style="list-style-type: none"> <li>1. Verify that both endpoints of the DS1 link are administered using the same signaling mode, framing mode, and line coding.</li> <li>2. Contact T1 Network Service to diagnose the remote DS1 endpoint.</li> <li>3. Check the physical connectivity of the DS1 Interface circuit packs and cable.</li> <li>4. Replace the local UDS1 Interface circuit pack and repeat the test.</li> </ol> <p>If the UDS1 connects to a line-side terminating device such as a PRI terminal adapter:</p> <ol style="list-style-type: none"> <li>1. Verify that the switch DS1 and the line-side terminating device are administered using the same signaling mode, framing mode, and line coding.</li> <li>2. Investigate the maintenance status of the line-side terminating device. Refer to the 'Line-Side Terminating Device Operating Manual' for information.</li> <li>3. Contact the vendor of the line-side terminating device to diagnose the equipment.</li> <li>4. Check the physical connection of the UDS1 Interface circuit pack to the terminating device. Check premise distribution system (or intra-premise wiring) for physical connection failures.</li> <li>5. Replace the local UDS1 Interface circuit pack and repeat the test.</li> </ol>
	PASS	<p>Neither a Yellow alarm nor a Remote Multiframe Alarm nor a F5 state alarm is being received from the remote DS1 endpoint.</p>

*Continued on next page*

Table 5-514. TEST #141 Yellow Alarm Inquiry Test — *Continued*

Error Code	Test Result	Description/ Recommendation
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board). This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"> <li>1. Ensure that the board translations are correct. Execute the <b>add ds1 PCSS</b> command to administer the UDS1 interface if it is not already administered.</li> <li>2. If the board was already administered correctly, check the error log to determine whether the board is hyperactive. If this is the case, the board is shut down. Reseating the board will re-initialize the board.</li> <li>3. If the board was found to be correctly inserted in step 1, then issue the <b>busyout board</b> command.</li> <li>4. Issue the <b>reset board</b> command.</li> <li>5. Issue the <b>release busy board</b> command.</li> <li>6. Issue the <b>test board long</b> command.</li> </ol> <p>This should re-establish the linkage between the internal ID and the port.</p>

### Major Alarm Inquiry Test (#142)

The Major alarm raised by a UDS1 Interface circuit pack indicates that the average bit error rate on the DS1 facility is greater than 1/1000. The Major Alarm Inquiry Test is used to determine that the received DS1 bit error rate is greater than 1/1000. The UDS1 Interface circuit pack takes 10 seconds to recognize and report a Major alarm and 10 seconds to recognize and report that a Major alarm condition is cleared.

When the UDS1 Interface circuit pack detects a Major alarm, it will send a MAJOR-ALARM message to the maintenance software. (32-channel interfaces send a YELLOW alarm to the far end). After the maintenance software receives a MAJOR-ALARM message, the Major Alarm Inquiry Test is initiated to confirm the Major alarm on the UDS1 Interface circuit pack. The Inquiry Test will be run every 10 minutes until the Major alarm is cleared. The maintenance software places all trunks or ports on the circuit pack in the out-of-service state if the Major alarm persists for more than 20 minutes.

When the Major alarm is cleared, the maintenance software restores all trunks or ports on the circuit pack to their previous service state before a Major alarm occurs.

Table 5-515. TEST #142 Major Alarm Inquiry Test

Error Code	Test Result	Description/ Recommendation
	ABORT	Internal System Error 1. Retry the command at 1-minute intervals for a maximum of 5 times.
2000	ABORT	Response to the test was not received within the allowable time period. This may be due to hyperactivity. Error type 1538 in the error log indicates hyperactivity. The hyperactive circuit pack is out of service and one or more of the following symptoms may be exhibited. 1. The UDS1-BD tests (such as test 138 and test 139) are aborting with error code 2000. 2. The tests run on the ports of this circuit pack are returning a no board result. 3. A <b>busyout</b> or a <b>release</b> command has no affect on the test results. 4. A <b>list config</b> command shows that the circuit pack and the ports are properly installed. When hyperactivity occurs, the circuit pack is isolated from the system, and all of the trunks for this circuit pack are placed into the out of service state. The system will try to restore the circuit pack within 15 minutes. When no faults are detected for 15 minutes, the UDS1 interface circuit pack is restored to normal operation. All of the trunks for the UDS1 interface circuit pack are then returned to the in service state. Hyperactivity is often caused by the associated facility. In such a case, faults (such as slips, misframes, or blue alarms) would be entered in the error log. In addition, many hardware errors would be logged against the associated trunk circuits. If the facility is OK and the error occurs again after 15 minutes, replace the circuit pack.
2100	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals for a maximum of 5 times.

*Continued on next page*

Table 5-515. TEST #142 Major Alarm Inquiry Test — *Continued*

Error Code	Test Result	Description/ Recommendation
	FAIL	<p>The performance of the DS1 link between the UDS1 interface circuit pack and the remote DS1 endpoint is very poor.</p> <p>If the UDS1 connects to a T1 network facility or to another switch, do the following:</p> <ol style="list-style-type: none"> <li>1. Enter the <b>list measurement ds1-log PCSS</b> command to read the error seconds measurement.</li> <li>2. Verify that both endpoints of the DS1 link are administered using the same signaling mode, framing mode, and line coding.</li> <li>3. Contact T1 Network Service or the technician at the remote switch to diagnose the equipment.</li> <li>4. Check the physical connectivity of the UDS1 interface circuit packs and the cable.</li> <li>5. Replace the local UDS1 interface circuit pack, and repeat the test.</li> </ol> <p>If the UDS1 connects to a line-side terminating device (for example, a PRI terminal adapter), do the following:</p> <ol style="list-style-type: none"> <li>1. The performance of the DS1 link between the UDS1 interface circuit pack and the line-side terminating device is very poor. Enter the <b>list measurement ds1-log PCSS</b> command to read the error seconds measurement.</li> <li>2. Verify that the switch DS1 and the line-side terminating device are administered using the same signaling mode, framing mode, and line coding.</li> <li>3. Investigate the maintenance status of the line-side terminating device. Refer to the 'Line-Side Terminating Device Operating Manual' for information.</li> <li>4. Contact the vendor of the line-side terminating device to diagnose the equipment.</li> <li>5. Check the physical connection of the UDS1 interface circuit pack to the terminating device, and check the premise distribution system (or the intra-premise wiring) for physical connection failures.</li> <li>6. Replace the local UDS1 interface circuit pack and repeat the test.</li> </ol>
	PASS	No Major alarm is detected in the UDS1 Interface circuit pack.

*Continued on next page*

Table 5-515. TEST #142 Major Alarm Inquiry Test — *Continued*

Error Code	Test Result	Description/ Recommendation
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board). This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"><li>1. Ensure that the board translations are correct. Execute the <b>add ds1 PCSS</b> command to administer the UDS1 interface if it is not already administered.</li><li>2. If the board was already administered correctly, check the error log to determine whether the board is hyperactive. If this is the case, the board is shut down. Reseating the board will re-initialize the board.</li><li>3. If the board was found to be correctly inserted in step 1, then issue the <b>busyout board</b> command.</li><li>4. Issue the <b>reset board</b> command.</li><li>5. Issue the <b>release busy board</b> command.</li><li>6. Issue the <b>test board long</b> command.</li></ol> <p>This should re-establish the linkage between the internal ID and the port.</p>

### Minor Alarm Inquiry Test (#143)

The Minor alarm raised by a UDS1 Interface circuit pack indicates that the average bit error rate on the DS1 facility is greater than 1/1,000,000, but less than 1/1000. The Minor Alarm Inquiry Test is used to determine that the received DS1 bit error rate is greater than 1/1,000,000 and less than 1/1000. When D4 framing mode is selected, the UDS1 Interface circuit pack takes 41 minutes to recognize and report a Minor alarm and 41 minutes to recognize and report that a Minor alarm condition has cleared. If ESF framing mode is selected, the UDS1 Interface circuit pack takes 10 minutes to recognize and report a Minor alarm and 10 minutes to recognize and report that a Minor alarm condition has cleared.

When the UDS1 Interface circuit pack detects a Minor alarm condition, it will send a MINOR-ALARM message to the maintenance software. After the maintenance software receives a MINOR-ALARM message, the Minor Alarm Inquiry Test is initiated to confirm the Minor alarm. All trunks or ports on the circuit pack are kept in the in-service state after the Minor alarm is confirmed. The Minor Alarm Inquiry Test is run every 10 minutes until the Minor alarm is cleared.

Table 5-516. TEST #143 Minor Alarm Inquiry Test

Error Code	Test Result	Description/ Recommendation
	ABORT	Internal System Error 1. Retry the command at 1-minute intervals a maximum of 5 times.
2000	ABORT	Response to the test was not received within the allowable time period. This may be due to hyperactivity. Error type 1538 in the error log indicates hyperactivity. The hyperactive circuit pack is out of service and one or more of the following symptoms may be exhibited. 1. The UDS1-BD tests (such as test 138 and test 139) are aborting with error code 2000. 2. The tests run on the ports of this circuit pack are returning a no board result. 3. A <b>busyout</b> or a <b>release</b> command has no affect on the test results. 4. A <b>list config</b> command shows that the circuit pack and the ports are properly installed. When hyperactivity occurs, the circuit pack is isolated from the system, and all of the trunks for this circuit pack are placed into the out of service state. The system will try to restore the circuit pack within 15 minutes. When no faults are detected for 15 minutes, the UDS1 interface circuit pack is restored to normal operation. All of the trunks for the UDS1 interface circuit pack are then returned to the in service state. Hyperactivity is often caused by the associated facility. In such a case, faults (such as slips, misframes, or blue alarms) would be entered in the error log. In addition, many hardware errors would be logged against the associated trunk circuits. If the facility is OK and the error occurs again after 15 minutes, replace the circuit pack.
2100	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals for a maximum of 5 times.

*Continued on next page*

Table 5-516. TEST #143 Minor Alarm Inquiry Test — *Continued*

Error Code	Test Result	Description/ Recommendation
	FAIL	<p>If the UDS1 connects to a T1 network facility or to another switch, do the following:</p> <ol style="list-style-type: none"> <li>1. The performance of the DS1 link between the UDS1 interface circuit pack and the remote DS1 endpoint is poor. Enter the <b>list measurement ds1-log PCSS</b> command to read the error seconds measurement.</li> <li>2. Verify that both endpoints of the DS1 link are administered using the same signaling mode, framing mode, and line coding.</li> <li>3. Contact T1 Network Service or the technician at the remote switch to diagnose the equipment.</li> <li>4. Check the physical connectivity of the UDS1 interface circuit packs and the cable.</li> <li>5. Replace the local UDS1 interface circuit pack, and repeat the test.</li> </ol> <p>If the UDS1 connects to a line-side terminating device (for example, a PRI terminal adapter), do the following:</p> <ol style="list-style-type: none"> <li>1. The performance of the DS1 link between the UDS1 interface circuit pack and the line-side terminating device is poor. Enter the <b>list measurement ds1-log PCSS</b> command to read the error seconds measurement.</li> <li>2. Verify that the switch DS1 and the line-side terminating device are administered using the same signaling mode, framing mode, and line coding.</li> <li>3. Investigate the maintenance status of the line-side terminating device. Obtain the error seconds measurement on the terminating device (if possible). Refer to the 'Line-Side Terminating Device Operating Manual' for information.</li> <li>4. Contact the vendor of the line-side terminating device to diagnose the equipment.</li> <li>5. Check the physical connection of the UDS1 interface circuit pack to the terminating device, and check the premise distribution system (or the intra-premise wiring) for physical connection failures.</li> <li>6. Replace the local UDS1 interface circuit pack and repeat the test.</li> </ol>
	PASS	No Minor alarm is detected in the UDS1 Interface circuit pack.

*Continued on next page*

Table 5-516. TEST #143 Minor Alarm Inquiry Test — *Continued*

Error Code	Test Result	Description/ Recommendation
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board). This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"> <li>1. Ensure that the board translations are correct. Execute the <b>add ds1 PCSS</b> command to administer the UDS1 interface if it is not already administered.</li> <li>2. If the board was already administered correctly, check the error log to determine whether the board is hyperactive. If this is the case, the board is shut down. Reseating the board will re-initialize the board.</li> <li>3. If the board was found to be correctly inserted in step 1, then issue the <b>busyout board</b> command.</li> <li>4. Issue the <b>reset board</b> command.</li> <li>5. Issue the <b>release busy board</b> command.</li> <li>6. Issue the <b>test board long</b> command.</li> </ol> <p>This should re-establish the linkage between the internal ID and the port.</p>

### Slip Alarm Inquiry Test (#144)

Slips occur when transmitter and receiver are not running at precisely the same clock rate. The UDS1 Interface circuit pack can detect both positive and negative slips on the DS1 facility. The Slip Alarm Inquiry Test is used to acquire the total number of slips that have occurred on a DS1 link.

When the UDS1 Interface circuit pack detects a slip condition, the circuit pack will increase the on-board slip counter by 1. A SLIP-COUNT message is spontaneously sent to the system software after the counter reaches a threshold (for example, 88). When the maintenance software receives the SLIP-COUNT message, the Slip Alarm Inquiry Test is initiated to query the slip counters on a UDS1 Interface circuit pack and total the slip counts in the maintenance software.

If the count of slips is over the threshold, a Minor alarm is raised against the UDS1 Interface circuit pack. All trunks or ports of the UDS1 Interface circuit pack remain in the in-service state. If the UDS1 Interface circuit pack is used to supply the system synchronization source, the MINOR alarm will initiate a synchronization source switch. See TDM-BUS (TDM Bus) and SYNC (Synchronization) Maintenance documentation for details.

5 Maintenance Objects for DEFINITY ONE  
UDS1-BD (UDS1 Interface Circuit Pack)

5-1277

Table 5-517. TEST #144 Slip Alarm Inquiry Test

Error Code	Test Result	Description/ Recommendation
	ABORT	Internal System Error <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
2000	ABORT	<p>Response to the test was not received within the allowable time period. This may be due to hyperactivity. Error type 1538 in the error log indicates hyperactivity. The hyperactive circuit pack is out of service and one or more of the following symptoms may be exhibited.</p> <ol style="list-style-type: none"><li>1. The UDS1-BD tests (such as test 138 and test 139) are aborting with error code 2000.</li><li>2. The tests run on the ports of this circuit pack are returning a no board result.</li><li>3. A <b>busyout</b> or a <b>release</b> command has no affect on the test results.</li><li>4. A <b>list config</b> command shows that the circuit pack and the ports are properly installed.</li></ol> <p>When hyperactivity occurs, the circuit pack is isolated from the system, and all of the trunks for this circuit pack are placed into the out of service state. The system will try to restore the circuit pack within 15 minutes. When no faults are detected for 15 minutes, the UDS1 interface circuit pack is restored to normal operation. All of the trunks for the UDS1 interface circuit pack are then returned to the in service state. Hyperactivity is often caused by the associated facility. In such a case, faults (such as slips, misframes, or blue alarms) would be entered in the error log. In addition, many hardware errors would be logged against the associated trunk circuits. If the facility is OK and the error occurs again after 15 minutes, replace the circuit pack.</p>
2100	ABORT	Could not allocate the necessary system resources to run this test. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals for a maximum of 5 times.</li></ol>

*Continued on next page*

Table 5-517. TEST #144 Slip Alarm Inquiry Test — *Continued*

Error Code	Test Result	Description/ Recommendation
1 to 88	FAIL	<p>The test failed because the UDS1 interface circuit pack and the remote DS1 endpoint are not synchronized to the same clock rate. The UDS1 interface circuit pack detected a slip alarm. The error code equals the number of slips detected by the UDS1 interface circuit pack since the last slip alarm inquiry test.</p> <p>If the UDS1 connects to a T1 network facility or to another switch, do the following:</p> <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals for a maximum of 5 times.</li><li>2. If the DS1 interface circuit pack is a TN464C, enter the <b>list measurement ds1-log PCSS</b> command to read the error seconds measurement.</li><li>3. Verify that both endpoints of the DS1 link are administered using the same signaling mode, framing mode, and line coding.</li><li>4. Check the active alarm and error logs for recent alarms and errors against the synchronization (SYNC). Follow the suggested repair procedure for these errors.</li><li>5. Contact T1 Network Service or the technician at the remote switch to diagnose the remote DS1 endpoint.</li><li>6. Check the physical connectivity of the UDS1 interface circuit packs and the cable.</li><li>7. Replace the local UDS1 interface circuit pack, and repeat the test.</li></ol> <p><i>Information continues.</i></p>

*Continued on next page*

Table 5-517. TEST #144 Slip Alarm Inquiry Test — *Continued*

Error Code	Test Result	Description/ Recommendation
1 to 88 <i>(cont'd.)</i>	FAIL <i>(cont'd.)</i>	<p>If the UDS1 connects to a line-side terminating device (for example, a PRI terminal adapter), do the following:</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals for a maximum of 5 times.</li> <li>2. Enter the <b>list measurement ds1-log PCSS</b> command to read the error seconds measurement.</li> <li>3. Verify that the switch DS1 and the line-side terminating device are administered using the same signaling mode, framing mode, and line coding.</li> <li>4. Investigate the maintenance status of the line-side terminating device. Refer to the 'Line-Side Terminating Device Operating Manual' for information.</li> <li>5. Contact the vendor of the line-side terminating device to diagnose the equipment.</li> <li>6. Check the physical connection of the UDS1 interface circuit pack to the terminating device, and check the premise distribution system (or the intra-premise wiring) for physical connection failures.</li> <li>7) Replace the local UDS1 interface circuit pack and repeat the test.</li> </ol>
	PASS	No Slip alarm is detected on the UDS1 Interface circuit pack.
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board). This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"> <li>1. Ensure that the board translations are correct. Execute the <b>add ds1 PCSS</b> command to administer the UDS1 interface if it is not already administered.</li> <li>2. If the board was already administered correctly, check the error log to determine whether the board is hyperactive. If this is the case, the board is shut down. Reseating the board will re-initialize the board.</li> <li>3. If the board was found to be correctly inserted in step 1, then issue the <b>busyout board</b> command.</li> <li>4. Issue the <b>reset board</b> command.</li> <li>5. Issue the <b>release busy board</b> command.</li> <li>6. Issue the <b>test board long</b> command.</li> </ol> <p>This should re-establish the linkage between the internal ID and the port.</p>

## Misframe Alarm Inquiry Test (#145)

Misframe Alarm indicates that framing bits observed on a UDS1 Interface circuit pack are in error. The Misframe Alarm Inquiry Test queries the total number of misframes that have occurred on a DS1 Interface circuit pack since the last inquiry.

When the DS1 Interface circuit pack detects a misframe error, it will increase its misframe counter by 1. If the counter reaches a specified threshold (i.e.- 17), a MISFRAME-COUNT message is automatically sent to the switch maintenance software. After the maintenance software receives the MISFRAME-COUNT message, the Misframe Alarm Inquiry Test is initiated to collect the misframe counts from the UDS1 Interface circuit pack.

When the threshold of misframes is reached, if the UDS1 Interface circuit pack is supplying the system synchronization source, then a switching synchronization source message is sent to the TDM Bus Clock. See TDM-BUS (TDM Bus) Maintenance documentation for details. A Minor alarm against the UDS1 Interface circuit pack is raised, but all trunks or ports of the UDS1 Interface circuit pack remain in the in-service state.

Table 5-518. TEST #145 Misframe Alarm Inquiry Test

Error Code	Test Result	Description/ Recommendation
	ABORT	Internal System Error 1. Retry the command at 1-minute intervals a maximum of 5 times.
2000	ABORT	Response to the test was not received within the allowable time period. This may be due to hyperactivity. Error type 1538 in the error log indicates hyperactivity. The hyperactive circuit pack is out of service and one or more of the following symptoms may be exhibited. <ol style="list-style-type: none"> <li>1. The UDS1-BD tests (such as test 138 and test 139) are aborting with error code 2000.</li> <li>2. The tests run on the ports of this circuit pack are returning a no board result.</li> <li>3. A <b>busyout</b> or a <b>release</b> command has no affect on the test results.</li> <li>4. A <b>list config</b> command shows that the circuit pack and the ports are properly installed.</li> </ol> When hyperactivity occurs, the circuit pack is isolated from the system, and all of the trunks for this circuit pack are placed into the out of service state. The system will try to restore the circuit pack within 15 minutes. When no faults are detected for 15 minutes, the UDS1 interface circuit pack is restored to normal operation. All of the trunks for the UDS1 interface circuit pack are then returned to the in service state. Hyperactivity is often caused by the associated facility. In such a case, faults (such as slips, misframes, or blue alarms) would be entered in the error log. In addition, many hardware errors would be logged against the associated trunk circuits. If the facility is OK and the error occurs again after 15 minutes, replace the circuit pack.
2100	ABORT	Could not allocate the necessary system resources to run this test. <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals for a maximum of 5 times.</li> </ol>

*Continued on next page*

Table 5-518. TEST #145 Misframe Alarm Inquiry Test — *Continued*

Error Code	Test Result	Description/ Recommendation
1 to 17	FAIL	<p>The test failed because the UDS1 interface circuit pack detected errors in the received framing bits pattern. The error code equals the number of misframes detected by the UDS1 interface circuit pack since the last misframe alarm inquiry test. Major bit and minor bit error rate (error types 2561 and 2817) error logs often accompany misframe alarms. Clearing the cause of these error logs may clear the misframes which are occurring.</p> <p>If the UDS1 connects to a T1 network facility or to another switch, do the following:</p> <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals for a maximum of 5 times.</li><li>2. If the DS1 interface circuit pack is a TN464C, enter the <b>list measurement ds1-log PCSS</b> command to read the error seconds measurement.</li><li>3. Verify that both endpoints of the DS1 link are administered using the same signaling mode, framing mode, and line coding.</li><li>4. Check the active alarm and error logs for recent alarms and errors against the synchronization (SYNC). Follow the suggested repair procedure for these errors.</li><li>5. Contact T1 Network Service or the technician at the remote switch to diagnose the remote DS1 endpoint.</li><li>6. Check the physical connectivity of the UDS1 interface circuit packs and the cable.</li><li>7. Replace the local UDS1 interface circuit pack, and repeat the test.</li></ol> <p><i>More information continues.</i></p>

*Continued on next page*

Table 5-518. TEST #145 Misframe Alarm Inquiry Test — *Continued*

Error Code	Test Result	Description/ Recommendation
1 to 17 <i>(cont'd.)</i>	FAIL <i>(cont'd.)</i>	<p>If the UDS1 connects to a line-side terminating device such as a PRI terminal adapter:</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals for a maximum of 5 times.</li> <li>2. Enter the <b>list measurement ds1-log PCSS</b> command to read the error seconds measurement.</li> <li>3. Verify that the switch DS1 and the line-side terminating device are administered using the same signaling mode, framing mode, and line coding.</li> <li>4. Investigate the maintenance status of the line-side terminating device. Refer to the 'Line-Side Terminating Device Operating Manual' for information.</li> <li>5. Contact the vendor of the line-side terminating device to diagnose the equipment.</li> <li>6. Check the physical connection of the UDS1 interface circuit pack to the terminating device, and check the premise distribution system (or the intra-premise wiring) for physical connection failures.</li> <li>7. Replace the local UDS1 interface circuit pack and repeat the test.</li> </ol>
	PASS	No Misframe alarm is detected on the UDS1 Interface circuit pack.
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board). This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"> <li>1. Ensure that the board translations are correct. Execute the <b>add ds1 PCSS</b> command to administer the UDS1 interface if it is not already administered.</li> <li>2. If the board was already administered correctly, check the error log to determine whether the board is hyperactive. If this is the case, the board is shut down. Reseating the board will re-initialize the board.</li> <li>3. If the board was found to be correctly inserted in step 1, then issue the <b>busyout board</b> command.</li> <li>4. Issue the <b>reset board</b> command.</li> <li>5. Issue the <b>release busy board</b> command.</li> <li>6. Issue the <b>test board long</b> command.</li> </ol> <p>This should re-establish the linkage between the internal ID and the port.</p>

## Translation Update Test (#146)

The Translation Update Test sends the circuit-pack-level information specified by System Administration to the UDS1 Interface circuit pack. Translation includes the following data administered for a UDS1 Interface circuit pack (see output of **display ds1 PCSS** command): DS1 Link Length between two DS1 endpoints, Synchronization Source Control, All Zero Suppression, Framing Mode, Signaling Mode, Time Slot Number of 697-Hz Tone, Time Slot Number of 700-Hz Tone, etc.

Table 5-519. TEST #146 Translation Update Test

Error Code	Test Result	Description/ Recommendation
	ABORT	Internal System Error  1. Retry the command at 1-minute intervals a maximum of 5 times.
	FAIL	Internal system software error.  1. Enter the <b>display ds1 PCSS</b> command to verify the UDS1 Interface circuit pack translation.
	PASS	Translation data has been downloaded to the UDS1 Interface circuit pack successfully.
0	NO BOARD	The test could not relate the internal ID to the port (no board). This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.  1. Ensure that the board translations are correct. Execute the <b>add ds1 PCSS</b> command to administer the UDS1 interface if it is not already administered.  2. If the board was already administered correctly, check the error log to determine whether the board is hyperactive. If this is the case, the board is shut down. Reseating the board will re-initialize the board.  3. If the board was found to be correctly inserted in step 1, then issue the <b>busyout board</b> command.  4. Issue the <b>reset board</b> command.  5. Issue the <b>release busy board</b> command.  6. Issue the <b>test board long</b> command.  This should re-establish the linkage between the internal ID and the port.

## DS1 Board Loopback Test (#1209)

**This test is destructive.**

The DS1 Board Loopback (BLB) Test causes a loopback at the TN464F DS1 board edge and tests DS1 board internal circuitry.

The test is destructive and can only be initiated by a system technician demanded *test ds1-loop PCSS ds1/csu-loopback-tests* command.

All trunks or ports on the UDS1 Interface circuit pack must be busied out via the system technician **busyout board** command before running the BLB Test.

When the BLB Test is initiated, maintenance software sends an appropriate message to the TN464F UDS1 Interface circuit pack to start the test. The board will set up the BLB loopback, transmit a test pattern, and verify that the pattern is received unaltered through the loopback. If the transmitted and received pattern is different, the test fails.

When the test is complete, all trunks or ports on the TN464F UDS1 Interface circuit pack are restored to the in-service state after the **release board** command is entered.

Table 5-520. TEST #1209 DS1 Board Loopback Test

Error Code	Test Result	Description/ Recommendation
	ABORT	Internal System Error  1. Retry the <i>test ds1-loop PCSS ds1/csu-loopback-tests</i> command at 1-minute intervals a maximum of 5 times.
1005	ABORT	DS1 Board Loopback Test cannot be executed in the current configuration. To run this, the TN464F or later suffix UDS1 must be administered for 24-channel operation. The "Bit Rate" field on the DS1 circuit pack administration form must be set to "1.544" for 24-channel operation.
1015	ABORT	Ports on the UDS1 Interface circuit pack have not been busied out to out-of-service.  1. Enter the <b>busyout board PCSS</b> command to put all trunks or ports of the UDS1 Interface circuit pack into the out-of-service state.  2. Retry the command.

*Continued on next page*

Table 5-520. TEST #1209 DS1 Board Loopback Test — *Continued*

Error Code	Test Result	Description/ Recommendation
1039	ABORT	<p>The UDS1 Interface circuit pack is providing timing for the system. Executing this test could cause major system disruption. If the UDS1 Interface circuit pack needs to be tested, set the synchronization reference to another DS1 Interface circuit pack or to the Tone-Clock circuit pack via the following command sequence:</p> <ol style="list-style-type: none"><li>1. Issue the <b>disable synchronization-switch</b> command.</li><li>2. Next, issue the <b>set synchronization PCSS</b> command.</li><li>3. Lastly, issue the <b>enable synchronization-switch</b> command. Then rerun the test. If the test aborts again, a different ABORT error code will be generated. Follow the recommended maintenance procedures for that error code.</li></ol>
1950	ABORT	<p>Another loopback/span test is already executing on the DS1 board or the board is in a network requested loopback mode (Line loopback or Payload loopback). The hardware error log will indicate whether a Customer Loopback Jack Test, Far CSU Loopback Test, or the One-Way Span Test is executing or if the board is in line loopback or payload loopback mode. Only one long-duration loopback/span test can be active at a given time. Thus, if a loopback/span test is already active, that test must be terminated via the <b>test ds1-loop PCSS end-loopback/span-test</b> command in order to execute this test.</p>

*Continued on next page*

Table 5-520. TEST #1209 DS1 Board Loopback Test — *Continued*

Error Code	Test Result	Description/ Recommendation
2000	ABORT	<p>Response to the test was not received within the allowable time period. This may be due to hyperactivity. Error type 1538 in the error log indicates hyperactivity. The hyperactive circuit pack is out of service and one or more of the following symptoms may be exhibited.</p> <ol style="list-style-type: none"> <li>1. The UDS1-BD tests (such as test 138 and test 139) are aborting with error code 2000.</li> <li>2. The tests run on the ports of this circuit pack are returning a no board result.</li> <li>3. A <b>busyout</b> or a <b>release</b> command has no affect on the test results.</li> <li>4. A <b>list config</b> command shows that the circuit pack and the ports are properly installed.</li> </ol> <p>When hyperactivity occurs, the circuit pack is isolated from the system, and all of the trunks for this circuit pack are placed into the out of service state. The system will try to restore the circuit pack within 15 minutes. When no faults are detected for 15 minutes, the UDS1 interface circuit pack is restored to normal operation. All of the trunks for the UDS1 interface circuit pack are then returned to the in service state. Hyperactivity is often caused by the associated facility. In such a case, faults (such as slips, misframes, or blue alarms) would be entered in the error log. In addition, many hardware errors would be logged against the associated trunk circuits. If the facility is OK and the error occurs again after 15 minutes, replace the circuit pack.</p>
2100	ABORT	<p>Could not allocate the necessary system resources to run this test.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals for a maximum of 5 times.</li> </ol>
	FAIL	<p>UDS1 Interface circuit pack failed the DS1 Board Loopback Test.</p> <ol style="list-style-type: none"> <li>1. Retry the <b>test ds1-loop PCSS ds1/csu-loopback-tests</b> command.</li> <li>2. If the BLB test continues to fail, then replace the UDS1 circuit pack.</li> </ol>
	PASS	<p>The BLB test executed successfully. The test pattern was transmitted and received successfully up to the TN464F DS1 board edge.</p>

*Continued on next page*

Table 5-520. TEST #1209 DS1 Board Loopback Test — *Continued*

Error Code	Test Result	Description/ Recommendation
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board). This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"> <li>1. Ensure that the board translations are correct. Execute the <b>add ds1 PCSS</b> command to administer the UDS1 interface if it is not already administered.</li> <li>2. If the board was already administered correctly, check the error log to determine whether the board is hyperactive. If this is the case, the board is shut down. Reseating the board will re-initialize the board.</li> <li>3. If the board was found to be correctly inserted in step 1, then issue the <b>busyout board</b> command.</li> <li>4. Issue the <b>reset board</b> command.</li> <li>5. Issue the <b>release busy board</b> command.</li> <li>6. Issue the <b>test board long</b> command.</li> </ol> <p>This should re-establish the linkage between the internal ID and the port.</p>

## CSU Equipment Loopback Test (#1210)

**This test is destructive.**

The CSU Equipment Loopback (ELB) Test causes a loopback at the near-edge of the local 120A1 CSU Module and tests the connection from the TN464F DS1 board to the CSU Module (DS1 board edge, connection, and CSU Module edge). This test will only be performed if the 120A1 CSU Module is present, administered, and connected to a 1.544 Mbps TN464F DS1 circuit pack on the back of the port carrier.

The test is destructive and can only be initiated by a system technician demanded `test ds1-loop PCSS ds1/csu-loopback-tests` command.

All trunks or ports on the UDS1 Interface circuit pack must be busied out via the system technician **busyout board** command before running the ELB Test.

When the ELB Test is initiated, maintenance software sends an appropriate message to the TN464F UDS1 Interface circuit pack to start the test. The board will set up the ELB loopback, transmit a test pattern, and verify that the pattern is received unaltered through the loopback. If the transmitted and received pattern is different, the test fails.

In addition, the DS1 circuit pack hardware applies a DC current while the test is running in order to detect any broken wires which may not be detected by the loopback pattern itself.

When the test is complete, all trunks or ports on the TN464F UDS1 Interface circuit pack are restored to the in-service state after the **release board** command is entered.

Table 5-521. TEST #1210 CSU Equipment Loopback Test

Error Code	Test Result	Description/ Recommendation
	ABORT	Internal System Error 1. Retry the <b>test ds1-loop PCSS ds1/csu-loopback-tests</b> command at 1-minute intervals a maximum of 5 times.
1005	ABORT	CSU Equipment Loopback Test cannot be executed in the current configuration. To run this test, the <i>Near-End CSU Type</i> field on the DS1 circuit pack administration form must be set to <i>integrated</i> and the "Bit Rate" field must be set to "1.544" (24-channel operation). 1. Use the <b>change ds1 PCSS</b> command to set the <i>Near-End CSU Type</i> field on the DS1 circuit pack administration form to <i>integrated</i> , and/or change the "Bit Rate" field to "1.544" if the board is to be used in 24-channel configuration. 2. Retry the <b>test ds1-loop PCSS ds1/csu-loopback-tests</b> command.
1015	ABORT	Ports on the UDS1 Interface circuit pack have not been busied out to out-of-service. 1. Enter the <b>busyout board PCSS</b> command to put all trunks or ports of the UDS1 Interface circuit pack into the out-of-service state. 2. Retry the command.
1039	ABORT	The UDS1 Interface circuit pack is providing timing for the system. Executing this test could cause major system disruption. 1. If the UDS1 Interface circuit pack needs to be tested, set the synchronization reference to another DS1 Interface circuit pack or to the Tone-Clock circuit pack via the following command sequence: ■ Issue the <b>disable synchronization-switch</b> command. ■ Next, issue the <b>set synchronization PCSS</b> command. ■ Lastly, issue the <b>enable synchronization-switch</b> command. Then rerun the test. 2. If the test aborts again, a different ABORT error code will be generated. Follow the recommended maintenance procedures for that error code.

Continued on next page

Table 5-521. TEST #1210 CSU Equipment Loopback Test — *Continued*

Error Code	Test Result	Description/ Recommendation
1950	ABORT	Another loopback/span test is already executing on the DS1 board or the board is in a network requested loopback mode (Line loopback or Payload loopback). The hardware error log will indicate whether a Customer Loopback Jack Test, Far CSU Loopback Test, or the One-Way Span Test is executing or if the board is in line loopback or payload loopback mode. Only one long-duration loopback/span tests can be active at a given time. Thus, if a loopback/span test is already active, that test must be terminated via the <b>test ds1-loop PCSS end-loopback/span-test</b> command in order to execute this test.
1951	ABORT	The CSU Equipment Loopback Test could not be executed because the 120A1 CSU Module was not physically installed. Physically connect the 120A1 CSU Module to the TN464F board on the back of the port carrier.
2000	ABORT	<p>Response to the test was not received within the allowable time period. This may be due to hyperactivity. Error type 1538 in the error log indicates hyperactivity. The hyperactive circuit pack is out of service and one or more of the following symptoms may be exhibited.</p> <ol style="list-style-type: none"> <li>1. The UDS1-BD tests (such as test 138 and test 139) are aborting with error code 2000.</li> <li>2. The tests run on the ports of this circuit pack are returning a no board result.</li> <li>3. A <b>busyout</b> or a <b>release</b> command has no affect on the test results.</li> <li>4. A <b>list config</b> command shows that the circuit pack and the ports are properly installed.</li> </ol> <p>When hyperactivity occurs, the circuit pack is isolated from the system, and all of the trunks for this circuit pack are placed into the out of service state. The system will try to restore the circuit pack within 15 minutes. When no faults are detected for 15 minutes, the UDS1 interface circuit pack is restored to normal operation. All of the trunks for the UDS1 interface circuit pack are then returned to the in service state. Hyperactivity is often caused by the associated facility. In such a case, faults (such as slips, misframes, or blue alarms) would be entered in the error log. In addition, many hardware errors would be logged against the associated trunk circuits. If the facility is OK and the error occurs again after 15 minutes, replace the circuit pack.</p>
2100	ABORT	<p>Could not allocate the necessary system resources to run this test.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals for a maximum of 5 times.</li> </ol>

*Continued on next page*

5 Maintenance Objects for DEFINITY ONE  
UDS1-BD (UDS1 Interface Circuit Pack)

5-1291

Table 5-521. TEST #1210 CSU Equipment Loopback Test — *Continued*

Error Code	Test Result	Description/ Recommendation
	FAIL	<p>UDS1 Interface circuit pack failed the CSU Equipment Loopback Test.</p> <ol style="list-style-type: none"> <li>1. Retry the <b>test ds1-loop PCSS ds1/csu-loopback-tests</b> command.</li> <li>2. If the ELB test continues to fail, then either the TN464F board, the CSU Module, or the I/O cable between the backplane and the CSU module (or any combination thereof) has failed. Attempt to isolate the problem to one of these areas. Begin by replacing the CSU Module and running the <b>test ds1-loop PCSS ds1/csu-loopback-tests</b> command again.</li> <li>3. If the ELB test continues to fail, then replace the TN464F board and run the <b>test ds1-loop PCSS ds1/csu-loopback-tests</b> command again.</li> <li>4. If the ELB test continues to fail, the problem could be in the I/O cable between the backplane and the CSU module.</li> </ol>
	PASS	<p>The ELB test executed successfully. The test pattern was transmitted and received successfully over the connection from the TN464F DS1 board to the near-edge of the 120A1 CSU Module.</p>
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board). This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"> <li>1. Ensure that the board translations are correct. Execute the <b>add ds1 PCSS</b> command to administer the UDS1 interface if it is not already administered.</li> <li>2. If the board was already administered correctly, check the error log to determine whether the board is hyperactive. If this is the case, the board is shut down. Reseating the board will re-initialize the board.</li> <li>3. If the board was found to be correctly inserted in step 1, then issue the <b>busyout board</b> command.</li> <li>4. Issue the <b>reset board</b> command.</li> <li>5. Issue the <b>release busy board</b> command.</li> <li>6. Issue the <b>test board long</b> command.</li> </ol> <p>This should re-establish the linkage between the internal ID and the port.</p>

## CSU Repeater Loopback Test (#1211)

**This test is destructive.**

The CSU Repeater Loopback (RLB) Test causes a loopback at the far-edge of the local 120A1 CSU Module and tests the connection from the TN464F DS1 board to and including the CSU Module circuitry. This test will only be performed if the 120A1 CSU Module is present, administered, and connected to a 1.544 Mbps TN464F DS1 circuit pack on the back of the port carrier.

The test is destructive and can only be initiated by a system technician demanded `test ds1-loop PCSS ds1/csu-loopback-tests` command.

All trunks or ports on the UDS1 Interface circuit pack must be busied out via the system technician **busyout board** command before running the RLB Test.

When the RLB Test is initiated, maintenance software sends an appropriate message to the TN464F UDS1 Interface circuit pack to start the test. The board will set up the RLB loopback, transmit a test pattern, and verify that the pattern is received unaltered through the loopback. If the transmitted and received pattern is different, the test fails.

In addition, the DS1 circuit pack hardware applies a DC current while the test is running in order to detect any broken wires which may not be detected by the loopback pattern itself.

When the test is complete, all trunks or ports on the TN464F UDS1 Interface circuit pack are restored to the in-service state after the **release board** command is entered.

Table 5-522. TEST #1211 CSU Repeater Loopback Test

Error Code	Test Result	Description/ Recommendation
	ABORT	Internal System Error  1. Retry the <b>test ds1-loop PCSS ds1/csu-loopback-tests</b> command at 1-minute intervals a maximum of 5 times.
1005	ABORT	CSU Repeater Loopback Test cannot be executed in the current configuration. To run this test, the <i>Near-End CSU Type</i> field on the DS1 circuit pack administration form must be set to <b>integrated</b> , and the <i>Bit Rate</i> field must be set to <b>1.544</b> (24-channel operation).  1. Use the <b>change ds1 PCSS</b> command to set the <i>Near-End CSU Type</i> field on the DS1 circuit pack administration form to <b>integrated</b> , and/or change the <i>Bit Rate</i> field must be set to <b>1.544</b> if the board is to be used in 24-channel configuration.  2. Retry the <b>test ds1-loop PCSS ds1/csu-loopback-tests</b> command.

Table 5-522. TEST #1211 CSU Repeater Loopback Test — *Continued*

Error Code	Test Result	Description/ Recommendation
1015	ABORT	Ports on the UDS1 Interface circuit pack have not been busied out to out-of-service. <ol style="list-style-type: none"><li>1. Enter the <b>busyout board PCSS</b> command to put all trunks or ports of the UDS1 Interface circuit pack into the out-of-service state.</li><li>2. Retry the command.</li></ol>
1039	ABORT	The UDS1 Interface circuit pack is providing timing for the system. Executing this test could cause major system disruption. If the UDS1 Interface circuit pack needs to be tested, set the synchronization reference to another DS1 Interface circuit pack or to the Tone-Clock circuit pack via the following command sequence: <ol style="list-style-type: none"><li>1. Issue the <b>disable synchronization-switch</b> command.</li><li>2. Issue the <b>set synchronization PCSS</b> command.</li><li>3. Issue the <b>enable synchronization-switch</b> command. Then rerun the test. If the test aborts again, a different ABORT error code will be generated. Follow the recommended maintenance procedures for that error code.</li></ol>
1950	ABORT	Another loopback/span test is already executing on the DS1 board or the board is in a network requested loopback mode (Line loopback or Payload loopback). The hardware error log will indicate whether a Customer Loopback Jack Test, Far CSU Loopback Test, or the One-Way Span Test is executing or if the board is in line loopback or payload loopback mode. Only one long-duration loopback/span test can be active at a given time. Thus, if a loopback/span test is already active, that test must be terminated via the <b>test ds1-loop PCSS end-loopback/span-test</b> command in order to execute this test.
1951	ABORT	The CSU Repeater Loopback Test could not be executed because the 120A1 CSU Module was not physically installed. Physically connect the 120A1 CSU Module to the TN464F board on the back of the port carrier.

*Continued on next page*

Table 5-522. TEST #1211 CSU Repeater Loopback Test — *Continued*

Error Code	Test Result	Description/ Recommendation
2000	ABORT	<p>Response to the test was not received within the allowable time period. This may be due to hyperactivity. Error type 1538 in the error log indicates hyperactivity. The hyperactive circuit pack is out of service and one or more of the following symptoms may be exhibited.</p> <ol style="list-style-type: none"> <li>1. The UDS1-BD tests (such as test 138 and test 139) are aborting with error code 2000.</li> <li>2. The tests run on the ports of this circuit pack are returning a no board result.</li> <li>3. A <b>busyout</b> or a <b>release</b> command has no affect on the test results.</li> <li>4. A <b>list config</b> command shows that the circuit pack and the ports are properly installed.</li> </ol> <p>When hyperactivity occurs, the circuit pack is isolated from the system, and all of the trunks for this circuit pack are placed into the out of service state. The system will try to restore the circuit pack within 15 minutes. When no faults are detected for 15 minutes, the UDS1 interface circuit pack is restored to normal operation. All of the trunks for the UDS1 interface circuit pack are then returned to the in service state. Hyperactivity is often caused by the associated facility. In such a case, faults (such as slips, misframes, or blue alarms) would be entered in the error log. In addition, many hardware errors would be logged against the associated trunk circuits. If the facility is OK and the error occurs again after 15 minutes, replace the circuit pack.</p>
2100	ABORT	<p>Could not allocate the necessary system resources to run this test.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals for a maximum of 5 times.</li> </ol>
	FAIL	<p>UDS1 Interface circuit pack failed the CSU Repeater Loopback Test.</p> <ol style="list-style-type: none"> <li>1. Retry the <i>test ds1-loop PCSS ds1/csu-loopback-tests</i> command.</li> <li>2. If the RLB test continues to fail, and the CSU Equipment Loopback Test (#1210) passed, then replace the CSU Module.</li> </ol>
	PASS	<p>The RLB test executed successfully. The test pattern was transmitted and received successfully over the connection from the TN464F DS1 board to the far-edge of the 120A1 CSU Module.</p>

*Continued on next page*

Table 5-522. TEST #1211 CSU Repeater Loopback Test — *Continued*

Error Code	Test Result	Description/ Recommendation
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board). This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"><li>1. Ensure that the board translations are correct. Execute the <b>add ds1 PCSS</b> command to administer the UDS1 interface if it is not already administered.</li><li>2. If the board was already administered correctly, check the error log to determine whether the board is hyperactive. If this is the case, the board is shut down. Reseating the board will re-initialize the board.</li><li>3. If the board was found to be correctly inserted in step 1, then issue the <b>busyout board</b> command.</li><li>4. Issue the <b>reset board</b> command.</li><li>5. Issue the <b>release busy board</b> command.</li><li>6. Issue the <b>test board long</b> command.</li></ol> <p>This should re-establish the linkage between the internal ID and the port.</p>

## CPE Loopback Jack Test (#1212)

**This test is destructive.**

The CPE Loopback Jack (CLJ-LB) Test causes a loopback at the CPE Loopback Jack and tests the building wiring connection between the TN464F DS1 board and the CPE Loopback Jack.

The test is highly destructive and can only be initiated by a system technician demanded ***test ds1-loop PCSS cpe-loopback-jack-test-begin [number-of-bits bit-pattern]*** command. The system technician has the choice of entering a loopback activation code on the command line or using the default code (0x47F).

All trunks or ports on the UDS1 Interface circuit pack must be busied out via the system technician **busyout board** command before running the CSJ Loopback Test.

The CPE Loopback Test has the TN464F UDS1 Interface circuit pack transmit a loopback activation code to the CPE Loopback Jack, waits up to 10 seconds for return of the code to verify the loopback has been established, transmits a framed 3-in-24 test pattern, begins counting bit errors in the received test pattern, and returns a PASS result to indicate that the pattern was successfully sent. If the loopback is not established within the 10 seconds, the test returns FAIL.

The status of the CPE Loopback test will be available in the hardware error log via error type 3900. Several distinct aux values will be used to give the user information of the status of the test.

The *list measurements ds1 summary* command will display the length of time the test has been running (*Test Duration* field) and number of bit errors detected (*Loopback/Span Test Bit-Error Count* field). If the test pattern is being passed through the loopback cleanly, the number of bit errors should be very low. The command will also display the type of Loopback/Span test executing (*Test* field), the type of pattern generated for the Loopback/Span test (*Pattern* field), and whether the pattern (*i.e.* 3-in-24 *Pattern*) is synchronized (*Synchronized* field).

To terminate the test, enter the *test ds1-loop PCSS end-loopback/span-test* command or the **release board** command. Using the **release board** command will restore all trunks or ports on the TN464F UDS1 Interface circuit pack to the in-service state.

5 Maintenance Objects for DEFINITY ONE  
UDS1-BD (UDS1 Interface Circuit Pack)

5-1297

Table 5-523. TEST #1212 CPE Loopback Jack Test

Error Code	Test Result	Description/ Recommendation
	ABORT	Internal System Error  1. Retry the <b>test ds1-loop PCSS cpe-loopback-jack-test-begin</b> command at 1-minute intervals a maximum of 5 times.
1005	ABORT	CPE Loopback Jack Test cannot be executed in the current configuration. To run this test, the TN464F or later suffix UDS1 must be administered for 24-channel operation. The <code>Bit Rate</code> field on the DS1 circuit pack administration form must be set to <b>1.544</b> for 24-channel operation.
1015	ABORT	Ports on the UDS1 Interface circuit pack have not been busied out to out-of-service.  1. Enter the <b>busyout board PCSS</b> command to put all trunks or ports of the UDS1 Interface circuit pack into the out-of-service state.  2. Retry the command.
1039	ABORT	The UDS1 Interface circuit pack is providing timing for the system. Executing this test could cause major system disruption. If the UDS1 Interface circuit pack needs to be tested, set the synchronization reference to another DS1 Interface circuit pack or to the Tone-Clock circuit pack via the following command sequence:  1. Issue the <b>disable synchronization-switch</b> command.  2. Issue the <b>set synchronization PCSS</b> command.  3. Issue the <b>enable synchronization-switch</b> command. Then rerun the test. If the test aborts again, a different ABORT error code will be generated. Follow the recommended maintenance procedures for that error code.
1950	ABORT	Another loopback/span test is already executing on the DS1 board or the board is in a network requested loopback mode (Line loopback or Payload loopback). The hardware error log will indicate whether a Customer Loopback Jack Test, Far CSU Loopback Test, or the One-Way Span Test is executing or if the board is in line loopback or payload loopback mode. Only one long-duration loopback/span test can be active at a given time. Thus, if a loopback/span test is already active, that test must be terminated via the <b>test ds1-loop PCSS end-loopback/span-test</b> command in order to execute this test.

*Continued on next page*

Table 5-523. TEST #1212 CPE Loopback Jack Test — *Continued*

Error Code	Test Result	Description/ Recommendation
2000	ABORT	<p>Response to the test was not received within the allowable time period. This may be due to hyperactivity. Error type 1538 in the error log indicates hyperactivity. The hyperactive circuit pack is out of service and one or more of the following symptoms may be exhibited.</p> <ol style="list-style-type: none"> <li>1. The UDS1-BD tests (such as test 138 and test 139) are aborting with error code 2000.</li> <li>2. The tests run on the ports of this circuit pack are returning a no board result.</li> <li>3. A <b>busyout</b> or a <b>release</b> command has no affect on the test results.</li> <li>4. A <b>list config</b> command shows that the circuit pack and the ports are properly installed.</li> </ol> <p>When hyperactivity occurs, the circuit pack is isolated from the system, and all of the trunks for this circuit pack are placed into the out of service state. The system will try to restore the circuit pack within 15 minutes. When no faults are detected for 15 minutes, the UDS1 interface circuit pack is restored to normal operation. All of the trunks for the UDS1 interface circuit pack are then returned to the in service state. Hyperactivity is often caused by the associated facility. In such a case, faults (such as slips, misframes, or blue alarms) would be entered in the error log. In addition, many hardware errors would be logged against the associated trunk circuits. If the facility is OK and the error occurs again after 15 minutes, replace the circuit pack.</p>
2100	ABORT	<p>Could not allocate the necessary system resources to run this test.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals for a maximum of 5 times.</li> </ol>
2	FAIL	<p>The CLJ-LB test failed because it was not set up properly. The UDS1 interface pack could not successfully put the CPE loopback jack into loopback mode.</p> <ol style="list-style-type: none"> <li>1. Rerun the <b>test ds1-loop PCSS cpe-loopback-jack-test-begin</b> command.</li> <li>2. If the test continues to fail, the problem could be with the TN464F board, the CPE loopback jack equipment, or somewhere between. Run the <b>test ds1-loop PCSS ds1/csu-loopback-tests</b> command to determine if the loopback tests that are closer to the TN464F board are successful. If any of these tests fail, follow the maintenance strategy that is associated with the test that fails.</li> </ol>

*Continued on next page*

5 Maintenance Objects for DEFINITY ONE  
UDS1-BD (UDS1 Interface Circuit Pack)

5-1299

Table 5-523. TEST #1212 CPE Loopback Jack Test — Continued

Error Code	Test Result	Description/ Recommendation
3	FAIL	<p>The CPE Loopback Jack Test was not set up properly. The framed 3-in-24 test pattern, generated by the UDS1 Interface circuit pack and looped back through the CPE Loopback Jack, could not be detected properly by the UDS1 circuit pack.</p> <ol style="list-style-type: none"><li>1. Retry the <b>test ds1-loop PCSS cpe-loopback-jack-test-begin</b> command.</li><li>2. If the CPE Loopback test continues to fail, the problem could be with the TN464F board, the CPE Loopback Jack equipment, or somewhere in between. Run the <b>test ds1-loop PCSS ds1/csu-loopback-tests</b> command to see if the loopback tests closer to the TN464F board are successful. If any of those loopback tests fail, follow the maintenance strategy associated with those loopbacks.</li></ol>
	PASS	<p>The CSJ Loopback test has successfully began executing. The test will continue to run until the system technician enters the <b>test ds1-loop PCSS end-loopback/span-test</b> command or the <b>release board PCSS</b> command.</p>
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board). This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"><li>1. Ensure that the board translations are correct. Execute the <b>add ds1 PCSS</b> command to administer the UDS1 interface if it is not already administered.</li><li>2. If the board was already administered correctly, check the error log to determine whether the board is hyperactive. If this is the case, the board is shut down. Reseating the board will re-initialize the board.</li><li>3. If the board was found to be correctly inserted in step 1, then issue the <b>busyout board</b> command.</li><li>4. Issue the <b>reset board</b> command.</li><li>5. Issue the <b>release busy board</b> command.</li><li>6. Issue the <b>test board long</b> command.</li></ol> <p>This should re-establish the linkage between the internal ID and the port.</p>

## Far CSU Loopback Test (#1213)

**This test is destructive.**

The Far CSU Loopback (R-LLB) Test causes a loopback at the far-end CSU and tests all circuitry and facilities from the local TN464F DS1 board to the far-end CSU.

The test is destructive and can only be initiated by a system technician demanded *test ds1-loop PCSS far-csu-loopback-test-begin* command.

All trunks or ports on the UDS1 Interface circuit pack must be busied out via the system technician **busyout board** command before running the Far CSU Loopback Test.

If the far-end CSU is not a 120A1 CSU Module, and the UDS1 is administered for ami-zcs line coding, one's density protection must be disabled on the CSU during the test due to the large number of zero's in the 3-in-24 test pattern.

The Far CSU Loopback Test has the TN464F UDS1 Interface circuit pack transmit a loopback activation code to the remote CSU, waits up to 15 seconds for return of the code to verify the loopback has been established, transmits a framed 3-in-24 test pattern, begins counting bit errors in the received test pattern, and returns a PASS result. If the loopback is not established within the 15 seconds, the test fails.

The status of the Far CSU Loopback test will be available in the hardware error log via error type 3901. Several distinct aux values will be used to give the user information of the status of the test.

The **list measurements ds1 summary** command will display the length of time the test has been running (*Test Duration* field) and number of bit errors detected (*Loopback/Span Test Bit-Error Count* field). If the test pattern is being passed through the loopback cleanly, the number of bit errors should be very low. The command will also display the type of Loopback/Span test executing (*Test* field), the type of pattern generated for the Loopback/Span test (*Pattern* field), and whether the pattern (*i.e.* 3-in-24 *Pattern*) is synchronized (*Synchronized* field).

To terminate the test, enter the **test ds1-loop PCSS end-loopback/span-test** command or the **release board** command. Using the **release board** command will restore all trunks or ports on the TN464F UDS1 Interface circuit pack to the in-service state.

Table 5-524. TEST #1213 Far CSU Loopback Test

Error Code	Test Result	Description/ Recommendation
	ABORT	Internal System Error  1. Retry the <b>test ds1-loop PCSS far-csu-loopback-test-begin</b> command at 1-minute intervals a maximum of 5 times.
1005	ABORT	Far CSU Loopback Test cannot be executed in the current configuration. To run this, the TN464F or later suffix UDS1 must be administered for 24-channel operation. The "Bit Rate" field on the DS1 circuit pack administration form must be set to "1.544" for 24-channel operation.
1015	ABORT	Ports on the UDS1 Interface circuit pack have not been busied out to out-of-service.  1. Enter the <b>busyout board PCSS</b> command to put all trunks or ports of the UDS1 Interface circuit pack into the out-of-service state.  2. Retry the command.
1039	ABORT	The UDS1 Interface circuit pack is providing timing for the system. Executing this test could cause major system disruption. If the UDS1 Interface circuit pack needs to be tested, set the synchronization reference to another DS1 Interface circuit pack or to the Tone-Clock circuit pack via the following command sequence:  1. Issue the <b>disable synchronization-switch</b> command.  2. Issue the <b>set synchronization PCSS</b> command.  3. Issue the <b>enable synchronization-switch</b> command. Then rerun the test. If the test aborts again, a different ABORT error code will be generated. Follow the recommended maintenance procedures for that error code.
1950	ABORT	Another loopback/span test is already executing on the DS1 board or the board is in a network requested loopback mode (Line loopback or Payload loopback). The hardware error log will indicate whether a Customer Loopback Jack Test, Far CSU Loopback Test, or the One-Way Span Test is executing or if the board is in line loopback or payload loopback mode. Only one long-duration loopback/span test can be active at a given time. Thus, if a loopback/span test is already active, that test must be terminated via the <b>test ds1-loop PCSS end-loopback/span-test</b> command in order to execute this test.

*Continued on next page*

5 Maintenance Objects for DEFINITY ONE  
UDS1-BD (UDS1 Interface Circuit Pack)

5-1302

Table 5-524. TEST #1213 Far CSU Loopback Test — *Continued*

Error Code	Test Result	Description/ Recommendation
2000	ABORT	<p>Response to the test was not received within the allowable time period. This may be due to hyperactivity. Error type 1538 in the error log indicates hyperactivity. The hyperactive circuit pack is out of service and one or more of the following symptoms may be exhibited.</p> <ol style="list-style-type: none"> <li>1. The UDS1-BD tests (such as test 138 and test 139) are aborting with error code 2000.</li> <li>2. The tests run on the ports of this circuit pack are returning a no board result.</li> <li>3. A <b>busyout</b> or a <b>release</b> command has no affect on the test results.</li> <li>4. A <b>list config</b> command shows that the circuit pack and the ports are properly installed.</li> </ol> <p>When hyperactivity occurs, the circuit pack is isolated from the system, and all of the trunks for this circuit pack are placed into the out of service state. The system will try to restore the circuit pack within 15 minutes. When no faults are detected for 15 minutes, the UDS1 interface circuit pack is restored to normal operation. All of the trunks for the UDS1 interface circuit pack are then returned to the in service state. Hyperactivity is often caused by the associated facility. In such a case, faults (such as slips, misframes, or blue alarms) would be entered in the error log. In addition, many hardware errors would be logged against the associated trunk circuits. If the facility is OK and the error occurs again after 15 minutes, replace the circuit pack.</p>
2100	ABORT	<p>Could not allocate the necessary system resources to run this test.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals for a maximum of 5 times.</li> </ol>
2	FAIL	<p>The test failed because it was not set up properly. The UDS1 pack could not successfully put the far-end CSU into loopback mode.</p> <ol style="list-style-type: none"> <li>1. Rerun the <b>test ds1-loop PCSS far-csu-loopback-test-begin</b> command.</li> <li>2. If the test continues to fail, the problem could be with the TN464F board, the CPE loopback jack equipment, or somewhere between. Run the <b>test ds1-loop PCSS cpe-loopback-jack-test-begin</b> command to determine if the CPE loopback jack loopback test is successful. If a CPE loopback jack device is not being used, issue the <b>test ds1-loop PCSS ds1/csu-loopback-tests</b> command instead. If the closer loopback test fails, follow the maintenance strategy that is associated with that test; otherwise, escalate the problem.</li> </ol>

*Continued on next page*

Table 5-524. TEST #1213 Far CSU Loopback Test — *Continued*

Error Code	Test Result	Description/ Recommendation
3	FAIL	<p>The Far CSU Loopback Test was not set up properly. The framed 3-in-24 test pattern, generated by the UDS1 Interface circuit pack and looped back through the far-end CSU, could not be detected properly by the UDS1 circuit pack.</p> <ol style="list-style-type: none"> <li>1. Retry the <b>test ds1-loop PCSS far-csu-loopback-test-begin</b> command.</li> <li>2. If the Far CSU Loopback test continues to fail with this error code, the problem could be with the TN464F board, the far-end CSU equipment, or somewhere in between. Run the <b>test ds1-loop PCSS cpe-loopback-jack-test-begin</b> command to see if the CPE Loopback Jack test which is closer to the TN464F board is successful. (If a CPE Loopback Jack device is not being used, then run the <b>test ds1-loop PCSS ds1/csu-loopback-tests</b> command to see if these even closer loopback tests succeed). If the closer loopback test fails, follow the maintenance strategy associated with that loopback. Otherwise, escalate the problem.</li> </ol>
	PASS	<p>The Far CSU Loopback test has successfully began executing. The test will continue to run until the system technician enters the <b>test ds1-loop PCSS end-loopback/span-test</b> command or the <b>release board PCSS</b> command.</p>
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board). This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"> <li>1. Ensure that the board translations are correct. Execute the <b>add ds1 PCSS</b> command to administer the UDS1 interface if it is not already administered.</li> <li>2. If the board was already administered correctly, check the error log to determine whether the board is hyperactive. If this is the case, the board is shut down. Reseating the board will re-initialize the board.</li> <li>3. If the board was found to be correctly inserted in step 1, then issue the <b>busyout board</b> command.</li> <li>4. Issue the <b>reset board</b> command.</li> <li>5. Issue the <b>release busy board</b> command.</li> <li>6. Issue the <b>test board long</b> command.</li> </ol> <p>This should re-establish the linkage between the internal ID and the port.</p>

## One-Way Span Test (#1214)

**This test is destructive.**

The One-Way Span Test allows one-way span testing to and from remote test equipment or another DEFINITY communications system. This will test all circuitry and facilities from the local TN464F DS1 board to the remote test equipment or other DEFINITY communications system.

The test is destructive and can only be initiated by a system technician demanded **test ds1-loop PCSS one-way-span-test-begin** command.

All trunks or ports on the UDS1 Interface circuit pack must be busied out via the system technician **busyout board** command before running the One-Way Span Test.

The One-Way Span Test has the TN464F UDS1 Interface circuit pack transmit a framed 3-in-24 test pattern and attempt to receive and verify the pattern. If the TN464F board receives a framed 3-in-24 test pattern sent from another DEFINITY G3V3 or test equipment at the far-end of the DS1, it will begin counting bit errors within the received pattern.

The status of the One-Way Span test will be available in the hardware error log via error type 3902. Several distinct aux values will be used to give the user information of the status of the test.

The **list measurements ds1 summary** command will display the length of time the test has been running (*Test Duration* field) and number of bit errors detected (*Loopback/Span Test Bit-Error Count* field). If the test pattern is being sent cleanly over the span from the far-end, the number of bit errors should be very low. The *Test Duration* field will show 0 until the test pattern is received from the far-end. Upon receiving the test pattern, the board will begin calculating the test duration and number of bit errors. The command will also display the type of Loopback/Span test executing (*Test Field*), the type of pattern generated for the Loopback/Span test (*Pattern Field*), and whether the 3-in-24 pattern is synchronized (*Synchronized Field*).

To terminate the test, enter the **test ds1-loop PCSS end-loopback/span-test** command or the **release board** command. Using the **release board** command will restore all trunks or ports on the TN464F UDS1 Interface circuit pack to the in-service state.

5 Maintenance Objects for DEFINITY ONE  
UDS1-BD (UDS1 Interface Circuit Pack)

5-1305

Table 5-525. TEST #1214 One-Way Span Test

Error Code	Test Result	Description/ Recommendation
	ABORT	Internal System Error <ol style="list-style-type: none"><li>1. Retry the <b>test ds1-loop PCSS one-way-span-test-begin</b> command at 1-minute intervals a maximum of 5 times.</li></ol>
1005	ABORT	One-Way Span Test cannot be executed in the current configuration. To run this, the TN464F or later suffix UDS1 must be administered for 24-channel operation. The <code>Bit Rate</code> field on the DS1 circuit pack administration form must be set to <b>1.544</b> for 24-channel operation.
1015	ABORT	Ports on the UDS1 Interface circuit pack have not been busied out to out-of-service. <ol style="list-style-type: none"><li>1. Enter the <b>busyout board PCSS</b> command to put all trunks or ports of the UDS1 Interface circuit pack into the out-of-service state.</li><li>2. Retry the command.</li></ol>
1039	ABORT	The UDS1 Interface circuit pack is providing timing for the system. Executing this test could cause major system disruption. If the UDS1 Interface circuit pack needs to be tested, set the synchronization reference to another DS1 Interface circuit pack or to the Tone-Clock circuit pack via the following command sequence: <ol style="list-style-type: none"><li>1. Issue the <b>disable synchronization-switch</b> command.</li><li>2. Issue the <b>set synchronization PCSS</b> command.</li><li>3. Issue the <b>enable synchronization-switch</b> command. Then rerun the test. If the test aborts again, a different ABORT error code will be generated. Follow the recommended maintenance procedures for that error code.</li></ol>
1950	ABORT	Another loopback/span test is already executing on the DS1 board or the board is in a network requested loopback mode (Line loopback or Payload loopback). The hardware error log will indicate whether a Customer Loopback Jack Test, Far CSU Loopback Test, or the One-Way Span Test is executing or if the board is in line loopback or payload loopback mode. Only one long-duration loopback/span test can be active at a given time. Thus, if a loopback/span test is already active, that test must be terminated via the <b>test ds1-loop PCSS end-loopback/span-test</b> command in order to execute this test.

*Continued on next page*

Table 5-525. TEST #1214 One-Way Span Test — *Continued*

Error Code	Test Result	Description/ Recommendation
2000	ABORT	<p>Response to the test was not received within the allowable time period. This may be due to hyperactivity. Error type 1538 in the error log indicates hyperactivity. The hyperactive circuit pack is out of service and one or more of the following symptoms may be exhibited.</p> <ol style="list-style-type: none"> <li>1. The UDS1-BD tests (such as test 138 and test 139) are aborting with error code 2000.</li> <li>2. The tests run on the ports of this circuit pack are returning a no board result.</li> <li>3. A <b>busyout</b> or a <b>release</b> command has no affect on the test results.</li> <li>4. A <b>list config</b> command shows that the circuit pack and the ports are properly installed.</li> </ol> <p>When hyperactivity occurs, the circuit pack is isolated from the system, and all of the trunks for this circuit pack are placed into the out of service state. The system will try to restore the circuit pack within 15 minutes. When no faults are detected for 15 minutes, the UDS1 interface circuit pack is restored to normal operation. All of the trunks for the UDS1 interface circuit pack are then returned to the in service state. Hyperactivity is often caused by the associated facility. In such a case, faults (such as slips, misframes, or blue alarms) would be entered in the error log. In addition, many hardware errors would be logged against the associated trunk circuits. If the facility is OK and the error occurs again after 15 minutes, replace the circuit pack.</p>
2100	ABORT	<p>Could not allocate the necessary system resources to run this test.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals for a maximum of 5 times.</li> </ol>
	PASS	<p>The One-Way Span test has successfully began transmitting a framed 3-in-24 test pattern. The test will continue to run until the system technician enters the <b>test ds1-loop PCSS end-loopback/span-test</b> command or the <b>release board PCSS</b> command.</p>

*Continued on next page*

Table 5-525. TEST #1214 One-Way Span Test — *Continued*

Error Code	Test Result	Description/ Recommendation
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board). This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"> <li>1. Ensure that the board translations are correct. Execute the <b>add ds1 PCSS</b> command to administer the UDS1 interface if it is not already administered.</li> <li>2. If the board was already administered correctly, check the error log to determine whether the board is hyperactive. If this is the case, the board is shut down. Reseating the board will re-initialize the board.</li> <li>3. If the board was found to be correctly inserted in step 1, then issue the <b>busyout board</b> command.</li> <li>4. Issue the <b>reset board</b> command.</li> <li>5. Issue the <b>release busy board</b> command.</li> <li>6. Issue the <b>test board long</b> command.</li> </ol> <p>This should re-establish the linkage between the internal ID and the port.</p>

## Inject Single Bit Error Test (#1215)

**This test is destructive.**

The Inject Single Bit Error Test will cause a single bit error to be sent within an active framed 3-in-24 test pattern.

The test is highly destructive and can only be initiated by a system technician demanded **test ds1-loop PCSS inject-single-bit-error** command. An attempt to use this command will be rejected if none of the three long-duration DS1 loopback/span tests (CPE Loopback Jack Test, Far CSU Loopback Test, One-Way Span Test) are active on a TN464F circuit pack.

All trunks or ports on the UDS1 Interface circuit pack must be busied out via the system technician **busyout board** command before running the Inject Single Bit Error Test.

The **list measurements ds1 summary** command displays the number of bit errors detected (Loopback/Span Test Bit-Error Count field). Injecting this single bit error should increment the bit error count of the loopback/span test by one.

5 Maintenance Objects for DEFINITY ONE  
UDS1-BD (UDS1 Interface Circuit Pack)

5-1308

Table 5-526. TEST #1215 Inject Single Bit Error Test

Error Code	Test Result	Description/ Recommendation
	ABORT	Internal System Error 1. Retry the <b>test ds1-loop PCSS inject-single-bit-error</b> command at 1-minute intervals a maximum of 5 times.
1015	ABORT	Ports on the UDS1 Interface circuit pack have not been busied out to out-of-service. 1. Enter the <b>busyout board PCSS</b> command to put all trunks or ports of the UDS1 Interface circuit pack into the out-of-service state. 2. Retry the command.
2000	ABORT	Response to the test was not received within the allowable time period. This may be due to hyperactivity. Error type 1538 in the error log indicates hyperactivity. The hyperactive circuit pack is out of service and one or more of the following symptoms may be exhibited. 1. The UDS1-BD tests (such as test 138 and test 139) are aborting with error code 2000. 2. The tests run on the ports of this circuit pack are returning a no board result. 3. A <b>busyout</b> or a <b>release</b> command has no affect on the test results. 4. A <b>list config</b> command shows that the circuit pack and the ports are properly installed.  When hyperactivity occurs, the circuit pack is isolated from the system, and all of the trunks for this circuit pack are placed into the out of service state. The system will try to restore the circuit pack within 15 minutes. When no faults are detected for 15 minutes, the UDS1 interface circuit pack is restored to normal operation. All of the trunks for the UDS1 interface circuit pack are then returned to the in service state. Hyperactivity is often caused by the associated facility. In such a case, faults (such as slips, misframes, or blue alarms) would be entered in the error log. In addition, many hardware errors would be logged against the associated trunk circuits. If the facility is OK and the error occurs again after 15 minutes, replace the circuit pack.
2100	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals for a maximum of 5 times.
	PASS	A single bit error has been successfully injected into an active framed 3-in-24 test pattern.

*Continued on next page*

Table 5-526. TEST #1215 Inject Single Bit Error Test — *Continued*

Error Code	Test Result	Description/ Recommendation
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board). This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"><li>1. Ensure that the board translations are correct. Execute the <b>add ds1 PCSS</b> command to administer the UDS1 interface if it is not already administered.</li><li>2. If the board was already administered correctly, check the error log to determine whether the board is hyperactive. If this is the case, the board is shut down. Reseating the board will re-initialize the board.</li><li>3. If the board was found to be correctly inserted in step 1, then issue the <b>busyout board</b> command.</li><li>4. Issue the <b>reset board</b> command.</li><li>5. Issue the <b>release busy board</b> command.</li><li>6. Issue the <b>test board long</b> command.</li></ol> <p>This should re-establish the linkage between the internal ID and the port.</p>

## End Loopback/Span Test (#1216)

**This test is destructive.**

The End Loopback/Span Test will terminate an active loopback or span test on a TN464F UDS1 circuit pack. Bit error counting against the received test pattern stream is terminated and sending of the framed 3-in-24 test pattern is halted. If either the CPE Loopback Jack or the far-end CSU is looped, the appropriate loopback deactivate code is sent. If the loopback could not be deactivated, then the test will FAIL and a MINOR alarm will be noted in the alarm log until the loopback is cleared.

The test is highly destructive and can only be initiated by a system technician demanded. Since only one of these three different long-duration loopback/span tests can be active at a time, the TN464F circuit pack knows which loopback/span test to terminate.

All trunks or ports on the UDS1 Interface circuit pack must be busied out via the system technician **busyout board** command before running this End Loopback/Span Test.

The **list measurements ds1 summary** command will display the length of time the test ran (Test Duration field) and number of bit errors detected (Loopback/Span Test Bit-Error Count field).

To restore the trunks or ports on the TN464F UDS1 Interface circuit pack to the in-service state, execute the **release board** command.

Table 5-527. TEST #1216 End Loopback/Span Test

Error Code	Test Result	Description/ Recommendation
	ABORT	Internal System Error  1. Retry the <b>test ds1-loop PCSS end-loopback/span-test</b> command at 1-minute intervals a maximum of 5 times.
1005	ABORT	End Loopback/Span Test cannot be executed in the current configuration. To run this, the TN464F or later suffix UDS1 must be administered for 24-channel operation. The Bit Rate field on the DS1 circuit pack administration form must be set to <b>1.544</b> for 24-channel operation.
1015	ABORT	Ports on the UDS1 Interface circuit pack have not been busied out to out-of-service.  1. Enter the <b>busyout board PCSS</b> command to put all trunks or ports of the UDS1 Interface circuit pack into the out-of-service state.  2. Retry the command.

*Continued on next page*

Table 5-527. TEST #1216 End Loopback/Span Test — *Continued*

Error Code	Test Result	Description/ Recommendation
2000	ABORT	<p>Response to the test was not received within the allowable time period. This may be due to hyperactivity. Error type 1538 in the error log indicates hyperactivity. The hyperactive circuit pack is out of service and one or more of the following symptoms may be exhibited.</p> <ol style="list-style-type: none"> <li>1. The UDS1-BD tests (such as test 138 and test 139) are aborting with error code 2000.</li> <li>2. The tests run on the ports of this circuit pack are returning a no board result.</li> <li>3. A <b>busyout</b> or a <b>release</b> command has no affect on the test results.</li> <li>4. A <b>list config</b> command shows that the circuit pack and the ports are properly installed.</li> </ol> <p>When hyperactivity occurs, the circuit pack is isolated from the system, and all of the trunks for this circuit pack are placed into the out of service state. The system will try to restore the circuit pack within 15 minutes. When no faults are detected for 15 minutes, the UDS1 interface circuit pack is restored to normal operation. All of the trunks for the UDS1 interface circuit pack are then returned to the in service state. Hyperactivity is often caused by the associated facility. In such a case, faults (such as slips, misframes, or blue alarms) would be entered in the error log. In addition, many hardware errors would be logged against the associated trunk circuits. If the facility is OK and the error occurs again after 15 minutes, replace the circuit pack.</p>
2100	ABORT	<p>Could not allocate the necessary system resources to run this test.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals for a maximum of 5 times.</li> </ol>
1313	FAIL	<p>The TN464F UDS1 circuit pack could not deactivate the loopback through the Customer Loopback Jack.</p> <ol style="list-style-type: none"> <li>1. Retry the <b>test ds1-loop PCSS end-loopback/span-test</b> command at 1-minute intervals for a maximum of 5 times.</li> </ol>
1314	FAIL	<p>The TN464F UDS1 circuit pack could not deactivate the loopback through the far-end CSU.</p> <ol style="list-style-type: none"> <li>1. Make sure that the far-end DS1 is installed if the far-end CSU is a 120A Lucent CSU Module.</li> <li>2. Retry the <b>test ds1-loop PCSS end-loopback/span-test</b> command at 1-minute intervals for a maximum of 5 times.</li> </ol>
	PASS	<p>The active long-duration loopback or span test on the TN464F circuit pack was successfully terminated.</p>

*Continued on next page*

Table 5-527. TEST #1216 End Loopback/Span Test — *Continued*

Error Code	Test Result	Description/ Recommendation
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board). This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"><li>1. Ensure that the board translations are correct. Execute the <b>add ds1 PCSS</b> command to administer the UDS1 interface if it is not already administered.</li><li>2. If the board was already administered correctly, check the error log to determine whether the board is hyperactive. If this is the case, the board is shut down. Reseating the board will re-initialize the board.</li><li>3. If the board was found to be correctly inserted in step 1, then issue the <b>busyout board</b> command.</li><li>4. Issue the <b>reset board</b> command.</li><li>5. Issue the <b>release busy board</b> command.</li><li>6. Issue the <b>test board long</b> command.</li></ol> <p>This should re-establish the linkage between the internal ID and the port.</p>

### ICSU Status LEDs Test (#1227)

The TN464F UDS1 circuit pack has four status LEDs on the faceplate in addition to the three standard faceplate LEDs. These four status LEDs are associated with the 120A1 Channel Service Unit (CSU) Module that can be connected to the TN464F board via the I/O connector panel on the back of the port carrier. The TN464F circuit pack combined with Lucent's new 120A1 CSU Module forms an Integrated CSU (ICSU).

This test is a visual test. It will light the four status LEDs red for 5 seconds, then light them green for 5 seconds, then light them yellow for 5 seconds, then turn the LEDs off and returns control of the status LEDs to the circuit pack.

This test will only be executed on a TN464F or later suffix UDS1 circuit packs administered for 24-channel operation (1.544 bit rate).

If the 120A1 CSU Module is not physically installed, the status LEDs are always off and this test will abort.

Table 5-528. TEST #1227 ICUSU Status LEDs Test

Error Code	Test Result	Description/ Recommendation
	ABORT	Internal System Error 1. Retry the command at 1-minute intervals a maximum of 5 times.
1005	ABORT	The ICUSU Status LEDs test can not be executed for the current configuration. The test applies only to TN464F or later UDS1 circuit packs administered for 24-channel operation (1.544 bit rate). 1. If the circuit pack is a TN464F or later suffix UDS1 circuit pack, then retry the command. 2. If the test continues to abort, escalate the problem.
1951	ABORT	The ICUSU Status LEDs Test can not be executed because a 120A1 or later suffix CSU Module is not physically installed. If using a 120A1 CSU Module, physically connect it to the TN464F board on the back of the port carrier. Otherwise, ignore this abort.
2100	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals for a maximum of 5 times.
2500	ABORT	Internal System Error 1. Retry the command.

*Continued on next page*

Table 5-528. TEST #1227 ICSU Status LEDs Test — *Continued*

Error Code	Test Result	Description/ Recommendation
	PASS	<p>The ICSU Status LEDs test executed successfully. A PASS result, however, does not necessarily mean that the status LEDs behaved properly. It only means that the software successfully attempted to light the status LEDs. This is a visual test. The service technician must visually exam the behavior of the LEDs while the test is running. The LEDs are functioning properly if the four status LEDs are lit red for 5 seconds, then lit green for 5 seconds, then lit yellow for 5 seconds. If the LEDs behave differently, the board should be replaced at the customer's convenience.</p>
0	NO BOARD	<p>The test could not relate the internal ID to the port (no board). This could be due to incorrect translations, no board is inserted, an incorrect board is inserted, or an insane board is inserted.</p> <ol style="list-style-type: none"><li>1. Ensure that the board translations are correct. Execute the <b>add ds1 PCSS</b> command to administer the UDS1 interface if it is not already administered.</li><li>2. If the board was already administered correctly, check the error log to determine whether the board is hyperactive. If this is the case, the board is shut down. Reseating the board will re-initialize the board.</li><li>3. If the board was found to be correctly inserted in step 1, then issue the <b>busyout board</b> command.</li><li>4. Issue the <b>reset board</b> command.</li><li>5. Issue the <b>release busy board</b> command.</li><li>6. Issue the <b>test board long</b> command.</li></ol> <p>This should re-establish the linkage between the internal ID and the port.</p>

## VC-BD

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run <sup>1</sup>	Full Name of MO
VC-BD	MAJOR	test board PCSS l r#	Voice Conditioner Circuit Pack
VC-BD	MINOR	test board PCSS l r#	Voice Conditioner Circuit Pack
VC-BD	WARNING <sup>2</sup>	test board PCSS s r#	Voice Conditioner Circuit Pack

- Where P is the port network number (1 for PPN and 2 or 3 for EPN); C is the carrier designation (for example, A, B, C, or D); and SS is the address of the slot in the carrier where the circuit pack is located (for example, 01, 02, ...).
- Refer to ["XXX-BD \(Common Port Circuit Pack\)" on page 5-1343](#).

### CAUTION:

*If the TN788 Voice Conditioner Circuit Pack (VC-BD) is not Vintage 2 or later, it must be replaced.*

The TN788 Voice Conditioner Circuit Pack (VC-BD) is a service circuit pack that provides conditioning for the audio signals from multimedia equipment based on the CCITT H.221 standard. The TN788 transcodes, gain adjusts, and bridges the audio bit streams demultiplexed by the TN787 (MMI) circuit pack and transmits encoded, exclusive audio conference sums onto the TDM bus so that the MMI can multiplex the audio, video, and data streams for the H.221 endpoints.

## Error Log Entries and Test to Clear Values

Table 5-529. VC-BD Error Log Entries

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
0 <sup>1</sup>	0	Any	Any	Any	test board PCSS sh r 1
1 (a)	Any	None	MIN	ON	
18 (b)	0	busyout board PCSS	WNG	OFF	release board PCSS
257 (c)	Any	Control Channel Loop Test (#52)	MIN	ON	test board PCSS r 20
513 (d)	4352 to 4357				
769 (e)	4358				

*Continued on next page*

Table 5-529. VC-BD Error Log Entries — *Continued*

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
1025 (f)	4363	NPE Audit Test (#50)			
1281 (g)	Any	SAKI Sanity Test (#53)	MAJ	ON	
1293 to 1294 (h)	46088 to 46096	SAKI Sanity Test (#53)	MIN	ON	See note (g)
1538 (i)	46082		MIN	ON	

1. Run the short test sequence first. If all tests pass, run the long test sequence. Refer to the appropriate test description and follow the recommended procedures.

**Notes:**

- a. The circuit pack stopped functioning or it was removed from the system. This alarm is logged approximately 11 minutes after the circuit pack is removed and/or the SAKI Sanity Test (#53) fails.

To resolve this error, insert a circuit pack in the same slot as the error indicates, if the circuit pack is not already in the system. Or, if the circuit pack is in the system and the red LED is on, then follow instructions for Red alarms.

**CAUTION:**

*If the TN788 Voice Conditioner Circuit Pack (VC-BD) is not Vintage 2 or later, it must be replaced.*

- b. This circuit pack is busied out by the [busyout board](#) **PCSS** command on page [4-6](#).
- c. Transient communication problems exist between the switch and this circuit pack. Execute the [test board](#) **PCSS** command on page [4-237](#) and refer to the repair procedures for the Control Channel Loop Around Test (#52).

- d. The circuit pack detected an on-board hardware failure. The reported aux data values correspond to the following detected errors:

Error	Description
4352	External RAM error
4353	Internal RAM error
4355	ROM Checksum error
4357	Instruction set error

Reset the circuit pack by executing the [busyout board PCSS](#) on page [4-6](#), [reset board PCSS](#) on page [4-123](#), and [release board PCSS](#) on page [4-112](#) commands. When it is reset, the circuit pack executes a set of tests to detect the presence of any of the above faults. The detection of one these errors during initialization causes the circuit pack to lock-up and appear insane to the system. See the repair procedures in footnote (a) for error type 1.

- e. The circuit pack detects a program logic error. While no action is required, this error may lead to errors of other types being reported against this circuit pack.
- f. The circuit pack cannot update NPE memory and read it back. This error type can be ignored, but it may lead to other error types being reported against this circuit pack.
- g. A critical hardware failure has been detected on the circuit pack. Use [busyout board PCSS](#) on page [4-6](#), [reset board PCSS](#) on page [4-123](#), followed by [release board PCSS](#) on page [4-112](#). If test #53 passes, the on-board circuitry is healthy. Use [test board PCSS long clear](#) on page [4-237](#) to retire the alarm. If test #53 fails, replace the circuit pack.
- h. The circuit pack detected a critical hardware failure. Reset the circuit pack by issuing [busyout board PCSS](#) on page [4-6](#), [reset board PCSS](#) on page [4-123](#), and [release board PCSS](#) on page [4-112](#). If the Circuit Pack Restart Test (#594) passes, then the on-board circuitry is healthy. Retire the alarm by issuing the [test board PCSS long clear](#) command on page [4-237](#). If the Circuit Pack Restart Rest (#594) fails, replace the circuit pack.

The reported error types correspond to the following detected errors:

Error	Description
1293	On-board auxiliary processor insane
1294	Internal memory access error

- i. The circuit pack is hyperactive — it is flooding the switch with messages sent over the control channel. The circuit pack is taken out of service when a threshold number of these errors is reported to the switch. Clear the alarm by using [busyout board PCSS](#) on page [4-6](#), [reset board PCSS](#) on page [4-123](#), [test board PCSS long clear](#) on page [4-237](#), and [release board PCSS](#) on page [4-112](#). If the error recurs within 10 minutes, then replace the circuit pack.

## System Technician-Demanded Tests: Descriptions and Error Code

---

Order of Investigation	Short Test Sequence	Long Test Sequence	D/ND <sup>1</sup>
Control Channel Loop-Around Test (#52) (a)	X	X	ND

- 
1. D = Destructive; ND = Nondestructive

### CAUTION:

*If the TN788 Voice Conditioner Circuit Pack (VC-BD) is not Vintage 2 or later, it must be replaced.*

#### Note:

- a. Refer to the repair procedure described in the [“XXX-BD \(Common Port Circuit Pack\)” on page 5-1343](#) for a description of this test.
- 

## Control Channel Loop Around Test (#52)

Refer to the repair procedure described in the [“XXX-BD \(Common Port Circuit Pack\)” on page 5-1343](#) as Control Channel Loop Around Test (#52).

## VC-DSPPT

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run <sup>1</sup>	Full Name of MO
VC-DSPPT	MAJOR	test port PCSSpp l r#	Voice Conditioner DSP Port
VC-DSPPT	MINOR	test port PCSSpp l r#	Voice Conditioner DSP Port
VC-DSPPT	WARNING	test port PCSSpp l r#	Voice Conditioner DSP Port

- Where P is the port network number (1 for PPN and 2 or 3 for EPN); C is the carrier designation (for example, A, B, C, or D); and SS is the address of the slot in the carrier where the circuit pack is located (for example, 01, 02, ...).

Each Voice Conditioner Circuit Pack (VC-BD) provides two types of resources:

- Transcoder Resources used for encoding and decoding audio formats
- Summer Resources used for summing audio from different sources

The eight Voice Conditioner DSP ports are the transcoder resources on the VC-BD.

## Error Log Entries and Test to Clear Values

Table 5-530. VC-DSPPT Error Log Entries

Error Type	Aux Data	Associated Test	Alarm Level	On/ Off Board	Test to Clear Value
0 <sup>1</sup>	0	Any	Any	Any	test port PCSSpp sh r 1
18 (a)	0	busyout port PCSSpp	WNG	OFF	release port PCSSpp
257 (b)	Any	NPE Crosstalk Test (#6)	MIN	ON	test port PCSSpp 1 r 3
513 (c)	Any	VC DSP Port Local TDM Loopback Test (#1104)	MIN	ON	test port PCSSpp sh r 3
778 to 781 (d)	Any	VC Port Reset DSP Test (#1106)	MAJ	ON	See note (d)
1025 (e)			WNG	ON	
1281 (f)	Any	VC DSP Port DSP Loopback Test #(1105)	MIN	ON	test port PCSSpp sh r 3
3840 (g)					

- Run the short test sequence first. If all test pass, run the long test sequence. Refer to the appropriate test description and follow the recommended procedures.

## Notes:

- a. This port has been busied out by the [busyout port PCSSpp](#) command on page [4-12](#).
- b. The VC DSP Port NPE Crosstalk Test(#1103) failed.
- c. The VC DSP Port Local TDM Loopback Test(#1104) failed. Run the Long Test Sequence.
- d. A critical hardware failure has been detected on the circuit pack. Reset the port by the [busyout port PCSSpp](#) and [reset port PCSSpp](#) commands. If the VC Reset DSP Test (#1106) passes, then the on-board circuitry is healthy. Retire the alarm with the [test port PCSSpp long clear](#) command on page [4-264](#).
- e. The VC DSP port reported loss of framing on the Service Channel between the VC and MMI circuit packs.
- f. The VC DSP Port DSP Loopback Test (#1105) failed.
- g. The DSP corresponding to this port on the VC circuit pack reported a firmware error. No action is required.

---

**System Technician-Demanded Tests:  
Descriptions and Error Codes**

---

Always investigate tests in the order presented in the table below. By clearing error codes associated with the DSP NPE Crosstalk Test, for example, you may also clear errors generated from other tests in the testing sequence.

Order of Investigation	Short Test Sequence	Long Test Sequence	D/ND <sup>1</sup>
DSP NPE Crosstalk Test (#1103)		X	D
TDM Loopback Test (#1104)	X	X	D
DSP Loopback Test (#1105)	X	X	D

---

1. D = Destructive; ND = Nondestructive

**VC DSP Port NPE Crosstalk Test (#1103)****This test is destructive.**

The NPE controls port connectivity and gain and provides conferencing functions. The NPE Crosstalk test verifies that this port's NPE channel talks on the selected time slot and never crosses over to time slots reserved for other connections. If the NPE is not working correctly, one-way and noisy connections may be observed. This test is part of the port's long test sequence and takes approximately 20 to 30 seconds to complete.

Table 5-531. TEST #1103 VC DSP Port NPE Crosstalk Test

Error Code	Test Result	Description/ Recommendation
1000 1001	ABORT	System resources required to run this test are not available. The port may be busy with a valid call.  1. Retry the command at 1-minute intervals a maximum of 5 times.
2012 2100	ABORT ABORT	Internal system error  Could not allocate the necessary resources to run this test.  1. Retry the command at 1-minute intervals a maximum of 5 times.
0-3	FAIL	The NPE of the tested port was transmitting in error. This causes noisy and unreliable connections.  1. Replace circuit pack.
	PASS	The port is correctly using its allocated time slots.  1. To be sure that this is not an intermittent problem, repeat this test a maximum of 10 times to make sure that it continues to pass.  2. If complaints still persist, examine the station, connections, and wiring.


### VC DSP Port Local TDM Loopback Test (#1104)

**This test is destructive.**

This test verifies the connectivity of a VC DSP Port across the TDM bus. It aborts if calls associated with the port are in progress. Failure of this test indicates an on-board fault associated with the port hardware on the circuit pack. The Loopback Test runs the following tests:

1. A Looparound test across the TDM bus.
2. A conference Circuit Test.

The tests are run in the above order; if one test fails, an error code is returned and the remaining tests in the sequence are not executed.



cydf1q2 PDH 121296

Figure 5-59. VC Circuit Pack DSP Port Local TDM Loopback Test

Table 5-532. TEST #1104 VC DSPPT Local  
TDM Loopback Test

Error Code	Test Result	Description/Recommendation
1000 1001	ABORT	System resources required to run this test are not available, or the port is busy with a valid call.  1. Retry the command at 1-minute intervals a maximum of 5 times.
1002	ABORT	The system could not allocate time slots for the test. The traffic load on the system is very high, or time slots may be out-of-service due to TDM-BUS errors. Refer to <a href="#">"TDM-BUS (TDM Bus)" on page 5-1116</a> to diagnose TDM Bus errors.  1. If the system has no TDM-BUS errors and is not handling heavy traffic, repeat the test at 1-minute intervals a maximum of 5 times.
1003	ABORT	The system could not allocate a Tone Detector for the test. The system is oversized for the number of Tone Detectors present, or some Tone Detectors are out-of-service.  1. Resolve any "TTR-LEV" errors. Refer to <a href="#">"TTR-LEV (TTR Level)" on page 5-1223</a> .  2. Resolve any "TONE-PT" errors. Refer to <a href="#">"TONE-PT (Tone Generator)" on page 5-1204</a> .  3. If neither condition exists, retry the test at 1-minute intervals.
1004	ABORT	The port is seized by a user for a valid call. Use the <a href="#">status station</a> command on page <a href="#">4-213</a> for the station associated with this port and determine if the port is available for testing.  1. Retry the command at 1-minute intervals a maximum of 5 times.
2000	ABORT	Response to the test was not received from the VC-BD circuit pack within the allowable time period.  1. If this result occurs repeatedly, attempt to reset the port by using the <a href="#">busyout port PCSSpp</a> command on page <a href="#">4-12</a> and <b>reset port PCSSpp</b> command.  2. If this result occurs again, replace the circuit pack.
2012	ABORT	Internal system error  1. Retry the command at 1-minute intervals a maximum of 5 times.
2100	ABORT	Could not allocate the necessary resources to run this test.  1. Retry the command at 1-minute intervals a maximum of 5 times.
2103	ABORT	The system could not make the conference connection for the test.  1. Retry the command at 1-minute intervals a maximum of 5 times.
0-3	FAIL	The TDM Loop Around Test failed.  1. Replace circuit pack.


Table 5-532. TEST #1104 VC DSPPT Local  
 TDM Loopback Test — *Continued*

Error Code	Test Result	Description/Recommendation
4-7	FAIL	The Conference Circuit Test failed. 1. Replace circuit pack.
	PASS	The VC DSP Port Local TDM Loop Around Test passed.

### VC-DSP Port DSP Loopback Test (#1105)

**This test is destructive.**

This test verifies the connectivity of a VC-DSPPT across the TDM bus. It aborts if calls associated with the port are in progress. Failure of this test indicates an on-board fault associated with the port hardware on the circuit pack.



cydfkq3 PDH 121296

Figure 5-60. VC Circuit pack DSP Port DSP Looparound Test

Table 5-533. TEST #1105 VC-DSP Port DSP Loopback Test

Error Code	Test Result	Description/Recommendation
1000	ABORT	System resources required to run this test are not available, or the port is busy with a valid call.  1. Retry the command at 1-minute intervals a maximum of 5 times.
1002	ABORT	The system could not allocate time slots for the test, the traffic load on the system is very high, or time slots are out-of-service due to TDM-BUS errors. Refer to <a href="#">"TDM-BUS (TDM Bus)" on page 5-1116</a> to diagnose TDM Bus errors.  1. If the system has no TDM-BUS errors and is not handling heavy traffic, repeat the test at 1-minute intervals a maximum of 5 times.
1003	ABORT	The system could not allocate a Tone Detector for the test, the system is oversized for the number of Tone Detectors present, or some Tone Detectors are out-of-service.  1. Resolve any "TTR-LEV" errors. Refer to <a href="#">"TTR-LEV (TTR Level)" on page 5-1223</a> .  2. Resolve any "TONE-PT" errors. Refer to <a href="#">"TONE-PT (Tone Generator)" on page 5-1204</a> .  3. If neither condition exists, retry the test at 1-minute intervals a maximum of 5 times.
1004	ABORT	The port has been seized by a user for a valid call. Use the <a href="#">status station</a> command on page <a href="#">4-213</a> for the station associated with this port and determine if the port is available for testing  1. Retry the command at 1-minute intervals a maximum of 5 times.
2000	ABORT	Response to the test request was not received from the VC-BD circuit pack within the allowable time period.  1. If this result occurs repeatedly, reset the circuit pack if the other ports are not in use by using the <a href="#">busyout port PCSSpp</a> command on page <a href="#">4-12</a> and <a href="#">reset port PCSSpp</a> command.  2. If this result occurs again, replace the circuit pack.
2012	ABORT	Internal system error  1. Retry the command at 1-minute intervals a maximum of 5 times.
2100	ABORT	Could not allocate the necessary system resources to run this test.  1. Rerun the test at 1-minute intervals a maximum of 5 times.
0, 1	FAIL	The VC-DSPPT DSP Loopback Test failed.  1. Replace the circuit pack.
	PASS	The VC DSPPT DSP Loopback Test passed

**VC Port Reset DSP Test (#1106)****This test is destructive.**

This test resets the VC-DSPPT and the DSP associated with it. As part of the reset procedure, the VC-DSPPT will execute a series of self- tests on the hardware. If these self- tests fail, the test will fail; otherwise the test will pass.

Before executing the test, the VC-DSPPT must be busied out by executing the [busyout port PCSSpp](#) command on page [4-12](#). After the completion of the test, the VC-DSPPT must be released by executing the [release port PCSSpp](#) command on page [4-117](#).

Table 5-534. TEST #1106 VC Port Reset DSP Test

Error Code	Test Result	Description/Recommendation
1000	ABORT	System resources required to run this test are not available, or the port may be busy with a call.  1. Retry the command at 1-minute intervals a maximum of 5 times.
1015	ABORT	The VC-DSPPT is not busied out.  1. Busy out the VC-DSPPT by executing the <a href="#">busyout port PCSSpp</a> command and then retry the test.
2000	ABORT	Response to the test was not received from the VC-DSPPT within the allowable time period.  1. Retry the command at 1-minute intervals a maximum of 5 times. 2. If this result occurs again, replace the circuit pack.
2012	ABORT	Internal system error  1. Retry the command at 1-minute intervals a maximum of 5 times.
2100	ABORT	Could not allocate the necessary resources for this test.  1. Retry the command at 1-minute intervals a maximum of 5 times.
	FAIL	The reset of the VC-DSPPT was unsuccessful.  1. Replace circuit pack.
	PASS	The VC-DSPPT was successfully reset.  1. Release the VC-DSPPT by executing the <b>reset port PCSSpp</b> command.

## VC-LEV (Voice Conditioner DSP Port Level)

---

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run	Full Name of MO
VC-LEV	MAJOR	See <a href="#">"Resolving VC-LEV Errors/Alarms"</a>	VC-LEV

Enable the MMCH feature on the System-Parameters Customer-Options form before changing the fields.

The Voice Conditioner (VC) Port Level MO monitors VC efficiency by tracking the number of VC ports that are in-service, and then comparing that number with the value entered in the VC field on the System-Parameters Maintenance form. This  $VC_S$  field is located under the Minimum Maintenance Thresholds section. The  $VC_S$  field contains the minimum number of VC ports needed for the Multimedia Call Handling (MMCH) feature, and is an administrable field. The  $VC_S$  field must contain a number between 0 and 126, and is entered by the system administrator. The MMCH feature must be enabled on the System-Parameters Customer-Options form before the  $VC_S$  field can be changed to a number greater than 0. For example, administering 8 in that field means 1 circuit pack. The algorithm for determining that a low level of VC resources exists uses the number entered in the  $VC_S$  field, and the number of VCs that are in-service in the system.

Each VC circuit pack contains 16 physical ports: 8 ports are reserved for VC-DSPPT ports, and the remaining 8 ports are designated as VC-SUMPT ports. The 8 DSP ports are made up of 4 encoder and 4 decoder resources that encode and decode audio formats. Thus, *one VC circuit pack is required for every 8 ports of MMCH port capacity*. If the number of in-service VC ports falls below the MMCH port capacity (value entered on the System-Parameters Maintenance form under the Minimum Maintenance Thresholds section and in the  $VC_S$  field), a VEC-LEV error is logged. If this outage continues for 15 minutes a MAJOR alarm is raised.

## Resolving VC-LEV Errors/Alarms

---

VC ports are a key part of the MMCH feature, any loss in the number of ports available for use degrades the MMCH customer defined service level.

If a VC circuit pack or port is busied out using the [busyout board](#) command on page [4-6](#) or [busyout port](#) command on page [4-12](#), these out-of-service ports are not included in the VC level calculation, thus allowing a technician to busy out a VC circuit pack for maintenance reasons without causing a MAJOR alarm to be raised.

### NOTE:

When diagnosing a VC-LEV problem, resolve any alarms raised against VC-BD or VC-DSPPT maintenance objects. Clearing VC-BD or VC-DSPPT alarms may clear the VC-LEV alarm.

The VC circuit pack is maintained by the software similarly to the Tone Detector circuit pack. Tone Detector circuit packs may be removed and reinserted in any port board slot without administration. The same rule applies to VC circuit packs. If a VC circuit pack is removed from service logically (by failing the Archangel sanity scan test) or is removed from service physically (by physically removing the circuit pack from the carrier), no error/alarm is raised against VC-BD or VC-DSPPT maintenance objects. Therefore, if a VC-LEV error/alarm exists, and none has been raised against VC-BD or VC-DSPPT maintenance objects, a VC circuit pack may have been removed from service causing the VC-LEV error/alarm. To resolve a VC-LEV MAJOR alarm, restore the number of VC ports available for service to be equal to or more than the calculated port capacity (value entered in the `VCs` field).

To determine how many VC circuit packs are needed for the MMCH feature:

1. Display the System-Parameters Maintenance form by executing the [display system-parameters maintenance](#) command on page [4-61](#).
2. Locate the number listed in the Minimum Maintenance Threshold (`VCs`) field. The MMCH feature requires one VC circuit pack for each four ports listed in the Minimum Maintenance Threshold (`VCs`) field.
3. Divide the Minimum Maintenance Threshold value by 8 to determine the number of VC circuit packs needed. For example, a port capacity of 12 listed in the Minimum Maintenance Threshold (`VCs`) field would require 2 VC circuit packs.
4. Use the [list configuration](#) command on page [4-72](#) to verify that the number of VC circuit packs listed agrees with the required number of VC circuit packs (determined in step 3). If the number of VC circuit packs listed in the step 3 differs from the calculated number, restore the number of VC circuit packs to the correct value, in order to resolve the VC-LEV alarm.

**5** Maintenance Objects for DEFINITY ONE  
VC-LEV (Voice Conditioner DSP Port Level)

5-1330

**Error Log Entries and Test to Clear Values**

---

**Table 5-535. VC-LEV Error Log Entries**

---

Error Type	Aux Data	Associated Test	Alarm Level	On/ Off Board	Test to Clear Value
1 (a)	Any	None	MAJOR	OFF	

---

**Notes:**

- a. The number of VC resources in the system that are in service has fallen below the calculated minimum value. If the number of in-service VC ports falls below the MMCH port capacity (value entered in the Minimum Maintenance Threshold  $VC_S$  field on the system parameters maintenance form), a VEC-LEV error is logged. If this outage continues for 15 minutes a MAJOR alarm is raised. To resolve this alarm, correct the out-of-service problem by following the procedures below:
    1. See [“VC-DSPPT” on page 5-1319](#) and [“VC-BD” on page 5-1315](#) and resolve any associated alarms.
    2. If a VC-LEV error/alarm exist and none has been raised against VC-BD or VC-DSPPT maintenance objects, a VC circuit pack may have been removed from service causing the VC-LEV error/alarm. To resolve a VC-LEV MAJOR alarm, restore the number of VC ports available for service to be equal to or more than the calculated port capacity. See [“Resolving VC-LEV Errors/Alarms” on page 5-1329](#) for details.
- 

**System Technician-Demanded Tests:  
Descriptions and Error Code**

---

There are no System Technician-Demanded test for VC-LEV.

## VC-SUMPT

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run <sup>1</sup>	Full Name of MO
VC-SUMPT	MAJ	test port PCSS l r#	Voice Conditioner Summer Port
VC-SUMPT	MIN	test port PCSS l r#	Voice Conditioner Summer Port
VC-SUMPT	WNG	test port PCSS s r#	Voice Conditioner Summer Port

- Where UU is the universal cabinet number (1 for PPN and 2-44 for EPN); C is the carrier designation (for example, A, B, C, D, or E); SS is the address of the slot in the carrier where the circuit pack is located (for example, 01, 02, ...); and pp is the two digit port number (01, 02, 03, ...).

Each Voice Conditioner Circuit Pack (VC-BD) provides two types of resources:

- Transcoder Resources that are used for encoding and decoding audio formats
- Summer Resources that are used for summing audio formats from different sources.

The Voice Conditioner Summer ports (VC-SUMPT) are the summer resources on the VC-BD. There are 8 such ports on a VC-BD.

## Error Log Entries and Test to Clear Values

Table 5-536. VC-SUMPT Error Log Entries

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
0 <sup>1</sup>	0	Any	Any	Any	test port PCSSpp sh r 1
18 (a)	0	busyout port PCSS	WNG	OFF	release port PCSSpp
130 (b)			WNG	ON	test port PCSSpp sh
257 (c)	Any	Control Channel Loop Test (#52)	MIN	ON	test board PCSSpp 1 r 3
513 (d)	Any	VC Summer Port Local Loopback Test #(1100)	MIN	ON	test board PCSSpp sh r 3

- Run the short test sequence first. If all test pass, run the long test sequence. Refer to the appropriate test description and follow the recommended procedures.

## Notes:

- a. This port has been busied out with the [busyout port](#) **PCSSpp** command.
  - b. The circuit pack has been removed or has been insane for more than 11 minutes. To clear the error, replace or reinsert the circuit pack.
  - c. The NPE Crosstalk Test(#1103) failed.
  - d. The VC Summer Port Local TDM Loopback Test(#1100) failed.
- 

## System Technician-Demanded Tests: Descriptions and Error Codes

---

Always investigate tests in the order presented in the table below. By clearing error codes associated with the Voice and Control Channel Local Loop Around Test, for example, you may also clear errors generated from other tests in the testing sequence.

Order of Investigation	Short Test Sequence	Long Test Sequence	D/ND <sup>1</sup>
NPE Crosstalk Test (#6) (a)		X	D
TDM Loopback Test (#1100)	X	X	D

- 
1. D = Destructive; ND = Nondestructive

### NPE Crosstalk Test (#6)

**This test is destructive.**

The NPE Crosstalk test verifies that this port's NPE channel talks on the selected time slot and never crosses over to time slots reserved for other connections. If the NPE is not working correctly, one-way and noisy connections may be observed. This test is part of the port's long test sequence and takes approximately 20 to 30 seconds to complete.

Table 5-537. TEST #6 NPE Crosstalk Test

Error Code	Test Result	Description/Recommendation
1000	ABORT	System resources required to run this test are not available. The port may be busy with a valid call. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
2012	ABORT	Internal system error
2100	ABORT	Could not allocate the necessary resources to run this test. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
	FAIL	The NPE of the tested port was transmitting in error, causing noisy and unreliable connections. <ol style="list-style-type: none"><li>1. Replace the circuit pack.</li></ol>
	PASS	The port is correctly using its allocated time slots. <ol style="list-style-type: none"><li>1. To be sure that this is not an intermittent problem, repeat this test a maximum of 10 times.</li><li>2. If complaints still persist, examine the station, connections, and wiring.</li></ol>


## VC Summer Port Local TDM Loopback Test (#1100)

### **This test is destructive.**

This test verifies the connectivity of a VC Summer Port across the TDM bus. It aborts if calls associated with the port are in progress. Failure of this test indicates an on-board fault associated with the port hardware on the circuit pack. The Loopback Test runs the following tests:

- A Looparound test across the TDM bus.
- A conference circuit test.

The tests are run in the above order. If the first test fails, the switch returns an error code, and the second test is not executed.



cydfflq1 PDH 121296

Figure 5-61. VC Circuit Pack Summer Port Loopback Test

Table 5-538. TEST #1100 VC Summer Port  
Local TDM Loopback Test

Error Code	Test Result	Description/Recommendation
1000	ABORT	System resources required to run this test are not available, or the port may be busy with a valid call.  1. Retry the command at 1-minute intervals a maximum of 5 times.
1002	ABORT	The system could not allocate time slots for the test. The traffic load on the system is very high or time slots are out-of-service due to TDM-BUS errors. Refer to <a href="#">"TDM-BUS (TDM Bus)" on page 5-1116</a> to diagnose any active TDM Bus errors.  1. If the system has no TDM-BUS errors and is not handling heavy traffic, repeat the test at 1-minute intervals a maximum of 5 times.
1003	ABORT	The system could not allocate a Tone Detector for the test, the system is oversized for the number of Tone Detectors present, or some Tone Detectors are out-of-service.  1. Resolve any "TTR-LEV" errors. Refer to <a href="#">"TTR-LEV (TTR Level)" on page 5-1223</a> .  2. Resolve any "TONE-PT" errors. Refer to <a href="#">"TONE-PT (Tone Generator)" on page 5-1204</a> .  3. If neither condition exists, retry the test at 1-minute intervals a maximum of 5 times.
1004	ABORT	The port has been seized by a user for a valid call. Use the <a href="#">status station</a> command on page <a href="#">4-213</a> for the station associated with this port to determine whether the port is available for testing.  1. Retry the command at 1-minute intervals a maximum of 5 times.
2000	ABORT	Response to the test request was not received from the VC-BD circuit pack within the allowable time period.  1. If this result occurs repeatedly, reset the circuit pack if the other ports are not in use. Reset the circuit pack by issuing the <a href="#">busyout board PCSS</a> command on page <a href="#">4-6</a> and the <a href="#">reset board PCSS</a> command on page <a href="#">4-123</a> .  2. If this result occurs again, replace the circuit pack.
2012	ABORT	Internal system error
2100	ABORT	Could not allocate the necessary system resources to run this test.
2103	ABORT	The system could not make the conference connection for the test.  1. Retry the command at 1-minute intervals a maximum of 5 times.
0	FAIL	The TDM Loop Around Test failed.
1	FAIL	The Conference Circuit Test failed.  1. Replace circuit pack.
	PASS	The VC Summer Port Local TDM Loopback Test passed.

## WAE-PORT (Wideband Access Endpoint Port)

---

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run	Full Name of MO
WAE-PORT <sup>1</sup>	MINOR	test access-endpoint <extension> I	Wideband Access Endpoint Port
WAE-PORT	WARNING	test access-endpoint <extension>	Wideband Access Endpoint Port

- 
1. For additional repair information, see also [“UDS1-BD \(UDS1 Interface Circuit Pack\)” on page 5-1227](#).
- 

The Wideband Switching capability supports end-to-end connectivity between customer endpoints at data rates from 128 to 1536 kbps over T1 facilities and to 1984 kbps over E1 facilities. DEFINITY switching capabilities are extended to support wideband calls comprised of multiple DS0s that are switched end-to-end as a single entity.

The Wideband Switching capability extends the Administered Connections feature to include non-signaling Wideband Access Endpoints. Endpoint application equipment with direct T1 or E1 interfaces may connect directly to the switch's line-side facilities. Application equipment without T1 or E1 interfaces requires a Terminal Adapter, such as a DSU/CSU. The terminal adapter or endpoint application equipment is connected to the Universal DS1 circuit pack (TN464C). These endpoints are administered as Access Endpoints, and they have no signaling interface to the switch. Instead, they simply transmit and receive data. (Some applications detect and respond to the presence or absence of data.) Calls are initiated from these endpoints using the Administered Connections feature.

Multiple Access Endpoints on one line-side UDS1 circuit pack (TN464C) facility are separate and distinct within the facility, and the endpoint application equipment must be administered to send and receive the correct data rate over the correct DS0s. All Administered Connections originating from Access Endpoints use the entire bandwidth administered for the Access Endpoint. An incoming call of a different data rate than that administered for the Access Endpoint cannot be routed to the Access Endpoint.

## 5 Maintenance Objects for DEFINITY ONE

### WAE-PORT (Wideband Access Endpoint Port)

5-1337

Although Wideband Access Endpoints are used primarily for line-side facilities, these endpoints can also be administered on network DS1 facilities to connect DEFINITY to non-switched network services, such as the AT&T fractional T-1 service. An example of this is the AT&T Static Integrated Network Access, where a trunk group to AT&T 4ESS Switched Services shares an access T-1 facility with a Wideband Access Endpoint. In this case, the Wideband Access Endpoint is connected to the AT&T fractional T-1 service, and it does not terminate on local endpoint equipment but is connected to a far-end CPE (for example, another DEFINITY PBX) via the dedicated fractional T-1. All Wideband Access Endpoint functionality and operation is identical on both line-side and network facilities. However, because maintenance capabilities are limited to the Wideband Access Endpoint interface, and because faults can occur end-to-end, troubleshooting procedures based on an end-to-end view of the network is required.

Wideband Access Endpoint Port maintenance provides a strategy for maintaining a Wideband Access Endpoint Port via a port on the Universal DS1 interface circuit pack hardware. The maintenance strategy involves logging Wideband Access Endpoint Port hardware errors, running tests for port initialization, periodic and scheduled maintenance, system technician-demanded tests, and alarm escalation and resolution. Two different port service states are specified in the Wideband Access Endpoint Port maintenance. These states include *out-of-service*, where the port is in a deactivated state and cannot be used for calls, and *in-service*, where the port is in an activated state and can be used for calls. If the Universal DS1 Interface circuit pack (TN464C) is out-of-service, all ports on the Universal DS1 Interface circuit pack (TN464C) are placed into the out-of-service state.

## Hardware Error Log Entries and Test to Clear Values

---

### Wideband Access Endpoint Maintenance Error Log Entries

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
0 <sup>1</sup>	0	Any	Any	Any	test access-endpoint <extension> sh r 1
18 (a)	0	busyout access-endpoint	WARNING	OFF	release access-endpoint <extension>
130 (b)		None	WARNING	ON	test access-endpoint <extension>
1281 (c)		Conference Circuit (Test #7)	MINOR	ON	test access-endpoint <extension> l r 4
1537 (d)		NPE Crosstalk Test (#6)	MINOR	ON	test access-endpoint <extension> l r 3
1793 (e)		None			test board PCSS long
3840 (f)	Any	Port Audit and Update (Test #36)			

1. Run the Short Test Sequence first. If all tests pass, run the Long Test Sequence. Refer to the appropriate test description and follow the recommended procedures.

#### Notes:

- a. The wideband access endpoint has been busied out by a **busyout access-endpoint <extension>** command. No calls can be made to this extension.
- b. The circuit pack has been removed, or it has been insane for more than 11 minutes. To clear the error, reinsert or replace the circuit pack.
- c. The Conference Circuit Test (#7) failed on this port. See Test #7 for repair procedures.
- d. The NPE Crosstalk Test (#6) failed on this port. See Test #6 for repair procedures.
- e. There was a failure of the TN464C UDS1 Interface circuit pack. See UDS1-BD Maintenance documentation for details.
- f. The Port Audit and Update Test (#36) failed due to an internal system error. Enter the **status access-endpoint <extension>** command and verify the status of the port. If the wideband access endpoint is out-of-service, enter the **release access-endpoint <extension>** command to put it back to in-service. Retry the test command. If the test continues to fail, escalate the problem.

## System Technician-Demanded Tests: Descriptions and Error Codes

Always investigate tests in the order presented in the table below when inspecting errors in the system. By clearing error codes associated with the *NPE Crosstalk Test*, for example, you may also clear errors generated from other tests in the testing sequence.

Order of Investigation	Short Test Sequence	Long Test Sequence	D/ND <sup>1</sup>
NPE Crosstalk Test (#6)		X	ND
Conference Circuit Test (#7)		X	ND
Port Audit and Update Test (#36)	X	X	ND

1. D = Destructive; ND = Nondestructive

### NPE Crosstalk Test (#6)

One or more Network Processing Elements (NPEs) reside on each circuit pack with a TDM Bus interface. (The TN464C UDS1 circuit pack has one SCOTCH-NPE chip instead of several NPE chips). The NPE controls port connectivity and gain, and it provides conferencing functions on a per-port basis. The NPE Crosstalk Test verifies that this port's NPE channel talks on the selected time slot and that it never crosses over to time slots reserved for other connections. If the NPE is not working correctly, one-way and noisy connections may be observed. This test is usually only part of a port's Long Test Sequence, and it takes between 20 and 30 seconds to complete.

Table 5-539. TEST #6 NPE Crosstalk Test

Error Code	Test Result	Description/ Recommendation
	ABORT	System resources required for this test are not available. 1. Retry the command at 1-minute intervals a maximum of 5 times.
1000	ABORT	System resources required to run this test are not available. The port may be in use on a valid call. Use the <b>status access-endpoint &lt;extension&gt;</b> command to determine when the port is available for testing. (Refer to <a href="#">"status station" on page 4-213</a> for a description of all possible states.) 1. Retry the command at 1-minute intervals a maximum of 5 times.
1001	ABORT	System resources required for this test are not available. 1. Retry the command at 1-minute intervals a maximum of 5 times.

Continued on next page

5 Maintenance Objects for DEFINITY ONE  
WAE-PORT (Wideband Access Endpoint Port)

5-1340

Table 5-539. TEST #6 NPE Crosstalk Test — Continued

Error Code	Test Result	Description/ Recommendation
1002	ABORT	<p>The system could not allocate time slots for the test. The system may be under heavy traffic conditions, or it may have time slots that are out-of-service due to TDM-BUS errors. The <b>status health</b> command can be used to determine if the system is experiencing heavy traffic. Refer to <a href="#">“TDM-BUS (TDM Bus)” on page 5-1116</a> to diagnose any active TDM-BUS errors.</p> <ol style="list-style-type: none"> <li>1. If system has no TDM-BUS errors, and if it is not handling heavy traffic, repeat the test at 1-minute intervals a maximum of 5 times.</li> </ol>
1003	ABORT	<p>The system could not allocate a tone receiver for the test. The system may be oversized for the number of Tone Detectors present, or some Tone Detectors may be out-of-service. The <b>list measurement tone-receiver</b> command displays information on the system's tone receivers.</p> <ol style="list-style-type: none"> <li>1. Look for TTR-LEV errors in the Error Log. If errors are present, refer to <a href="#">“TTR-LEV (TTR Level)” on page 5-1223</a>.</li> <li>2. Look for TONE-PT errors in the Error Log. If errors are present, refer to <a href="#">“TONE-PT (Tone Generator)” on page 5-1204</a>.</li> <li>3. If neither condition exists, retry the test at 1-minute intervals a maximum of 5 times.</li> </ol>
1004	ABORT	<p>The port has been seized by a user for a valid call. Use the <b>status access-endpoint &lt;extension&gt;</b> command to determine when the port is available for testing. The port is available when it is in the <b>in-service/idle</b> state.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
1020	ABORT	<p>The test did not run due either to a previously existing error on the specific port or to a more general circuit pack error.</p> <ol style="list-style-type: none"> <li>1. Examine the Error Log for existing errors against this port or the circuit pack, and attempt to diagnose the already existing error.</li> </ol>
2000	ABORT	Response to the test request was not received within the allowable time period.
2100	ABORT	<p>System resources required for this test are not available.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
	FAIL	<p>The NPE of the tested port was found to be transmitting in error. This causes noisy and unreliable connections.</p> <ol style="list-style-type: none"> <li>1. Replace the circuit pack.</li> </ol>
	PASS	<p>The port is correctly using its allocated time slots.</p> <ol style="list-style-type: none"> <li>1. User-reported troubles on this port should be investigated by using other port tests and by examining the terminal adapter or the external wiring.</li> </ol>

**Conference Circuit Test (#7)**

One or more Network Processing Elements (NPEs) reside on each circuit pack with a TDM Bus interface. (The TN464C UDS1 circuit pack has one SCOTCH-NPE chip instead of several NPE chips). The NPE controls port connectivity and gain, and it provides conferencing functions on a per-port basis. The Conference Circuit Test verifies that the NPE channel for the port being tested can correctly perform the conferencing function. The NPE is instructed to listen to several different tones and to conference the tones together. The resulting signal is then measured by a Tone Detector port. If the level of the tone is within a certain range, the test passes.

**Table 5-540. TEST #7 Conference Circuit Test**

Error Code	Test Result	Description/ Recommendation
	ABORT	System resources required for this test are not available. 1. Retry the command at 1-minute intervals a maximum of 5 times.
1000	ABORT	System resources required to run this test are not available. The port may be in use on a valid call. Use the <b>status access-endpoint &lt;extension&gt;</b> command to determine when the port is available for testing.
1004	ABORT	The port has been seized by a user for a valid call. Use the <b>status access-endpoint &lt;extension&gt;</b> command to determine when the port is available for testing. The port is available when it is in the <b>in-service/idle</b> state. 1. Retry the command at 1-minute intervals a maximum of 5 times.
1020	ABORT	The test did not run due either to a previously existing error on the specific port or to a more general circuit pack error. 1. Examine the Error Log for existing errors against this port or circuit pack, and attempt to diagnose the previously existing error.
2000	ABORT	Response to the test request was not received within the allowable time period.
2100	ABORT	System resources required for this test are not available. 1. Retry the command at 1-minute intervals a maximum of 5 times.
	FAIL	The NPE of the tested port did not conference the tones correctly. This causes noisy and unreliable connections. Although wideband calls do not use the conferencing feature on the NPE, this failure indicates problems with the circuit pack hardware. 1. Replace the circuit pack.
	PASS	The port can correctly conference multiple connections. 1. User-reported troubles on this port should be investigated by using other port tests and by examining the terminal adapter or the external wiring.

### Port Audit and Update Test (#36)

This test sends port level translation data from switch processor to the UDS1 Interface circuit pack to ensure that the wideband access endpoint port's translation is correct.

Table 5-541. TEST #36 Audit and Update Test

Error Code	Test Result	Description/ Recommendation
	ABORT	Internal System Error. 1. Retry the command at 1-minute intervals a maximum of 5 times.
1006	ABORT	The port is out-of-service. If the port is busied out: 1. Issue <b>release access-endpoint &lt;extension&gt;</b> command to put the port back into in-service. 2. Retry the test command. If the port is not busied out: 1. Check the error and alarm logs for WAE-PORT and UDS1-BD errors and alarms. Follow the recommended repair procedures.
2000	ABORT	Response to the test request was not received within the allowable time period.
2100	ABORT	Could not allocate the necessary system resources to run this test. 1. Retry the command at 1-minute intervals a maximum of 5 times.
	FAIL	Internal system error. 1. Retry the command at 1-minute intervals a maximum of 5 times.
	PASS	Port translation has been updated successfully.

## XXX-BD (Common Port Circuit Pack)

---

The Common Port Circuit Pack Maintenance is a set of common tests used by all the circuit packs with the generic hardware that interfaces with the TDM bus. Circuit packs included in this category are listed on the following pages.

MO Name (in Alarm Log)	Alarm Level	Initial Command to Run <sup>1</sup>	Full Name of MO
XXX-BD <sup>2</sup>	MAJOR	test board PCSS	Common Port Circuit Pack Maintenance
XXX-BD <sup>2</sup>	MINOR	test board PCSS	Common Port Circuit Pack Maintenance
XXX-BD <sup>2</sup>	WARNING	test board PCSS	Common Port Circuit Pack Maintenance

1. Where P is the port network number (1); C is the carrier designation (for example, A, B, or C); and SS is the address of the slot in the carrier where the circuit pack is located (for example, 01, 02,...etc.)
2. Refer to the appropriate circuit pack documentation to get the correct MO name displayed in this field. It usually ends with BD.

### Notes:

- a. All circuit pack suffixes (B,C, D, etc.) are also supported by the XXX-BD (Common Port Circuit Pack) Maintenance documentation.
  - b. The XXX-BD designation is also used in the SAT display in the case where a **reset board command** is issued to a circuit pack type which is in conflict to the actual circuit pack type administered for that slot or when a **reset board** command is issued to an empty circuit pack slot.
-

5 Maintenance Objects for DEFINITY ONE  
XXX-BD (Common Port Circuit Pack)

5-1344

When any of the Common Port Circuit Packs (except the TN754 Digital Line and TN758 Pooled Modem circuit packs) are physically removed from the backplane, no alarm is logged for approximately 11 minutes. In the case of the Digital Line and Pooled Modem circuit packs, approximately 21 minutes elapse before an alarm is logged. When a circuit pack that has been removed is alarmed, the alarm type is minor and is classified as an on-board alarm. The time delay permits maintenance activity to be performed without triggering an additional alarm. **An alarm is logged only against a Common Port Circuit Pack on which ports have been administered.** See the next Note.

 NOTE:

In a heavily loaded system, the interval between the removal of a Common Port Circuit Pack and the logging of the alarm may be several minutes longer.

**XXX-BD Common Circuit Packs**

The following list of circuit packs are listed by apparatus code, including circuit packs used in non-United States installations.

Table 5-542. XXX-BD Common Circuit Packs

Apparatus Code	Name	Type
(TN566) (TN567)	DEFINITY AUDIX R3 System	Port Assembly
(TN2208)	Call Visor ASAI over the DEFINITY (LAN) Gateway R1	Port Assembly
TN417	Auxiliary Trunk	Port
TN429	Direct Inward/Outward Dialing (DIOD) Trunk	Port
TN433	Speech Synthesizer	Service
TN436B	Direct Inward Dialing Trunk	Port
TN437	Tie Trunk	Port
TN438B	Central Office Trunk	Port
TN439	Tie Trunk	Port
TN447	Central Office Trunk	Port
TN457	Speech Synthesizer	Service
TN458	Tie Trunk	Port
TN459B	Direct Inward Dialing Trunk	Port
TN464C/ D/E/ F	DS1/E1 Interface - T1, 24 Channel - E1, 32 Channel	Port
TN465/B/C	Central Office Trunk	Port
TN467	Analog Line	Port
TN468B	Analog Line	Port

Continued on next page

5 Maintenance Objects for DEFINITY ONE  
XXX-BD (Common Port Circuit Pack)

5-1345

Table 5-542. XXX-BD Common Circuit Packs — *Continued*

Apparatus Code	Name	Type
TN479	Analog Line	Port
TN497	Tie Trunk	Port
TN722B	Digital Signal Level 1 Tie Trunk	Port
TN725B	Speech Synthesizer	Service
TN726/B	Data Line	Port
TN735	MET Line	Port
TN742	Analog Line	Port
TN744/B/C	Call Classifier - Detector	Service
TN744D	Call Classifier - Detector - Multi-Country	Service
TN746/B	Analog Line	Port
TN747B	Central Office Trunk	Port
TN750/B/C	Announcement	Service
TN753	Direct Inward Dialing Trunk	Port
TN754/B	Digital Line 4-Wire DCP	Port
TN758	Pooled Modem	Port
TN760B/C/D	Tie Trunk	Port
TN762B	Hybrid Line	Port
TN763B/C/D	Auxiliary Trunk	Port
TN767B/C/D/E	DS1 Interface - T1, 24 Channel	Port
TN769	Analog Line	Port
TN795	Processor	Control
TN2135	Analog Line	Port
TN2136	Digital Line 2-Wire DCP	Port
TN2138	Central Office Trunk	Port
TN2139	Direct Inward Dialing Trunk	Port
TN2140/B	Tie Trunk	Port
TN2144	Analog Line	Port
TN2146	Direct Inward Dialing Trunk	Port
TN2147/C	Central Office Trunk	Port
TN2149	Analog Line	Port
TN2180	Analog Line	Port
TN2181	Digital Line 2-wire DCP	Port
TN2182/B	Tone-Clock - Tone Detector and Call Classifier	Control

*Continued on next page*

Table 5-542. XXX-BD Common Circuit Packs — *Continued*

Apparatus Code	Name	Type
TN2183	Analog Line	Port
TN2184	DIOD Trunk	Port
TN2199	Central Office Trunk	Port
TN2224	Digital Line, 24-Port, 2-Wire DCP	Control

### Hardware Error Log Entries and Test to Clear Values

#### Common Port Circuit Pack Maintenance Error Log Entries

Error Type	Aux Data	Associated Test	Alarm Level	On/Off Board	Test to Clear Value
0 <sup>1</sup>	0	Any	Any	Any	test board PCSS sh r 1
1(a)	0	Circuit pack removed or SAKI Sanity Test (#53)	MINOR	ON	
18(b)	0	busyout board PCSS	WARNING	OFF	release board PCSS
23(c)	0	None	WARNING	OFF	
125 (d)		None	MINOR	ON	
257	65535	Control Channel Test (#52)	MINOR	ON	test board PCSS sh r 20
257 (e)	Any	None			
267 (d)	0	None	WARNING	ON	
513 (f)	Any	None	MINOR	ON	test board PCSS sh
769 (g)	4358	None			
1025 (h)	4363	NPE Audit Test (#50)			test board PCSS l r 20
1281 (i)		Ringing Application Test (#51)	MINOR	ON	test board PCSS r 2
1538 (j)	Any	None	WARNING/ MINOR	ON	
1793 (k)		Neon Test (#220)	MINOR	ON	test board PCSS r 2
3840 (l)	Any	None			
3999 (m)	Any	None			

1. Run the Short Test Sequence first. If all tests pass, run the Long Test Sequence. Refer to the appropriate test description and follow the recommended procedures.

## Notes:

- a. This error indicates the circuit pack totally stopped functioning or it was physically removed from the system. This error type is not applicable to ANN-BD, DETR-BD, S-SYN-BD, M/T-BD, or CLSFY-BD.

 **NOTE:**

The alarm is logged approximately 11 minutes after the circuit pack has been removed and/or SAKI Sanity Test (#53) fails.

If the circuit pack is not in the system, insert a circuit pack (in the same slot as the error indicates) to resolve this error. Or, if the circuit pack is in the system and the red LED is on, follow the instructions for "Red (alarm)" in the ["Circuit pack status LEDs"](#) section in [Chapter 1, "Maintenance Concepts for DEFINITY ONE"](#)

- b. This error indicates the circuit pack has been busied out. Release the circuit pack via **release board PCSS**.
- c. The circuit pack has been logically administered but not physically installed. The alarm should clear when the circuit pack is installed.

If the circuit pack is already installed:

1. Run **test board PCSS long** and look at any test failures or error codes generated.
  2. If the test does not clear error 23, then execute **reset board PCSS** and run the long test again.
  3. If the reset/test does not clear error 23, replace the circuit pack.
- d. A wrong circuit pack is inserted in the slot where this circuit pack is logically administered. To resolve this problem, either remove the wrong circuit pack and insert the logically administered circuit pack OR use the **change circuit-pack** command to readminister this slot to match the circuit pack inserted.
  - e. This error indicates transient communication problems with this circuit pack. This error is not service-affecting and no action is required.
  - f. This error, when reported with Aux data in the range of 4352 to 4358, indicates that the circuit pack has reported an on-board hardware failure. The circuit pack continuously tests the hardware and report the results approximately every 10 minutes. If the hardware problem is resolved, the "leaky bucket" strategy should clear the alarm in approximately 30 minutes. However, if the alarm does NOT clear in 30 minutes, the circuit pack should be replaced.
  - g. This error can be ignored, but look for other errors on this circuit pack.
  - h. This error is not service-affecting and no action is required.
  - i. This error indicates that no ringing current is detected. Run Test #51, Ringing Application Test, and follow the procedures for Test #51. This error is only applicable to Analog Line circuit packs.

- j. The hyperactive circuit pack is out-of-service and may exhibit one or more of the following symptoms:
1. The common circuit pack level tests such as Test #51 and/or Test #220 are aborting with error code 2000.
  2. The tests run on the ports of this circuit pack are returning with a NO-BOARD.
  3. A busyout/release of the circuit pack has no affect on test results.
  4. A **list configuration** command shows that the circuit pack and ports are properly installed.

If the XXX-BD is not a TN754 Digital Line Circuit Pack (DIG-BD), and if this error happens again within 15 minutes, replace the circuit pack. If the XXX-BD is a TN754 Digital Line Circuit Pack (DIG-BD), check the alarm level. If the alarm level is a WARNING, this indicates that users are probably causing the hyperactivity by playing with their digital stations. If the circuit pack is really hyperactive, this alarm is upgraded to a MINOR alarm within one hour. If the alarm level is a MINOR alarm, replace the circuit pack.

- k. This error indicates that no neon current is detected. Run Test #220, Neon Test, and follow the procedures for Test #220. This error is applicable only to TN769 and TN746 Analog Line circuit packs.
- l. This error is not service-affecting and no action is required.
- m. Error type 3999 indicates that the circuit pack sent a large number of control channel messages to the switch within a short period of time. If error type 1538 is also present, then the circuit pack was taken out-of-service due to hyperactivity. If error type 1538 is not present, then the circuit pack has not been taken out-of-service, but it has generated 50% of the messages necessary to be considered hyperactive. This may be completely normal during heavy traffic periods. However, if this error type is logged when the circuit pack is being lightly used, it may indicate a problem with the circuit pack or the equipment attached to it.
-

## System Technician-Demanded Tests: Descriptions and Error Codes

---

Always investigate tests in the order presented in [Table 5-543](#) when inspecting errors in the system. By clearing error codes associated with the *Control Channel Loop Around Test*, for example, you may also clear errors generated from other tests in the testing sequence.

Table 5-543. System Technician-Demanded Tests: XXX-BD

Order of Investigation	Short Test Sequence	Long Test Sequence	Reset Board Sequence	D/ND <sup>1</sup>
NPE Audit Test (#50)		X		ND
Ringing Application Test (#51) (a)	X	X		ND
Control Channel Loop Around Test (#52)	X	X		ND
SAKI Sanity Test (#53)		X	D	
Neon Test (#220) (b)	X	X		ND

---

1. D = Destructive; ND = Nondestructive

### Notes:

- a. Only applicable to Analog Line circuit packs.
  - b. Only applicable to TN746 and TN769 Analog Line circuit packs.
-

**NPE Audit Test (#50)**

The system sends a message to the on-board microprocessor to update the network connectivity translation for all the Network Processing Elements (NPEs) on the circuit pack.

**Table 5-544. TEST #50 NPE Audit Test**

Error Code	Test Result	Description/ Recommendation
none or 2100	ABORT	System resources required for this test are not available.
1019	ABORT	Test already in progress.
	FAIL	Internal System Error. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
	PASS	The circuit pack's NPEs have been updated with their translation.
	EXTRA BD	Certain circuit packs have limitations on how many circuit packs can be in the system such as the Call Classifier (TN744). The Call Classifier allow only 10 circuit packs in each system. All additional circuit packs return EXTRA-BD and should be removed.
any	NO BOARD	This is normal if the test is being done when (a) the circuit pack is not physically in the system or (b) the system is booting up. Otherwise, there is some inconsistency between the physical configuration and the data kept in the system. <ol style="list-style-type: none"><li>1. Verify that the circuit pack is physically in the system.</li><li>2. Verify that the system is not in a stage of booting up.</li><li>3. Retry the command at 1-minute intervals for a maximum of 5 times.</li></ol>

## Ringling Application Test (#51)

This test checks the ringling application circuitry common to all ports on an Analog Line circuit pack.

Table 5-545. TEST #51 Ringling Application Circuit Test

Error Code	Test Result	Description/ Recommendation
1000 or 2100	ABORT	Could not allocate the necessary system resources to run test.
	ABORT	Could not allocate the necessary system resources to run test. The circuit pack is not installed. Internal System Error.
2000	ABORT	<p>There was no response from the board.</p> <ol style="list-style-type: none"> <li>1. If error type 1538 (hyperactivity) is present in the error log, follow the maintenance strategy that is recommended for this error type.</li> <li>2. Run the <b>busyout board</b>, <b>reset board</b>, and <b>release busy board</b> commands, and then retest.</li> <li>3. If the test still aborts, dispatch with the circuit pack.</li> <li>4. Check the off-board wiring and the terminal, and, if there are no problems found, replace the circuit pack.</li> </ol>
1004	ABORT	<p>The port was seized by a valid call during the test. The test has been aborted. Use the <b>display port PCSSpp</b> command to determine the station extension. Use the <b>status station</b> command to determine the service state of the port. If the service state indicates that the port is in use, the port is unavailable for certain tests. You must wait until the port is idle before retesting.</p> <ol style="list-style-type: none"> <li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li> </ol>
1008	ABORT	<p>Could not allocate a ringling circuit for one of the following reasons: all the ringling circuits are in use; the ringling generator is defective; ringling generator is not wired correctly.</p> <ol style="list-style-type: none"> <li>1. If the test continues to abort, look for RING-GEN error in Error Log. <ol style="list-style-type: none"> <li>a. If there are RING-GEN errors, refer to <a href="#">"RING-GEN (Analog Ring Generator)" on page 5-1036</a> and try to resolve any problem(s). Go to Step 2.</li> <li>b. If there are no RING-GEN errors, and the test continues to abort, issue the <b>test board PCSS</b> command on other TN742, TN769, or TN746 Analog circuit packs. If an ABORT with error code 1008 occurs for this test on other circuit packs as well, the ringling generator may be defective or may not be wired properly. Refer to RING-GEN Maintenance documentation for details. If an ABORT with error code 1008 does NOT occur on the other ports, then all four ring generators are in use. Exit from this documentation.</li> </ol> </li> <li>2. Retry the command.</li> </ol>

Table 5-545. TEST #51 Ringing Application Circuit Test — *Continued*

Error Code	Test Result	Description/ Recommendation
	FAIL	<p>No ringing current is detected. The ringing application circuitry on this circuit pack probably is not healthy.</p> <ol style="list-style-type: none"> <li>1. Retry the command again.</li> <li>2. If the test continues to fail, look for RING-GEN error in Error Log.                             <ol style="list-style-type: none"> <li>a. If there are RING-GEN errors, refer to the <a href="#">"RING-GEN (Analog Ring Generator)" on page 5-1036</a> and try to resolve any problem(s).</li> <li>b. If there are no RING-GEN errors, replace the circuit pack.</li> </ol> </li> <li>3. Retry the command again.</li> </ol>
	PASS	<p>Ringing current is detected or this vintage of the Analog Line circuit pack does not support the Ringing Application Circuit Test. Analog Line circuit packs that DO NOT support Test #51 include TN742 Vintage 3 and earlier.</p>
any	NO BOARD	<p>This is normal if the test is being done when (a) the circuit pack is not physically in the system or (b) the system is booting up. Otherwise, there is some inconsistency between the physical configuration and the data kept in the system.</p> <ol style="list-style-type: none"> <li>1. Verify that the circuit pack is physically in the system. Verify that the system is not in a stage of booting up. Retry the command at 1-minute intervals for a maximum of 5 times.</li> </ol>

## Control Channel Loop Around Test (#52)

This test queries the circuit pack for its circuit pack code and vintage and verifies its records.

Table 5-546. TEST #52 Control Channel Loop Around Test

Error Code	Test Result	Description/ Recommendation
none or 2100	ABORT	System resources required for this test are not available. <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
	FAIL	The test failed because the circuit pack failed to return the circuit pack code or vintage. <ol style="list-style-type: none"><li>1. Retry the command for a maximum of 5 times.</li><li>2. If the test still fails, issue the <b>busyout board</b>, <b>reset board</b>, and <b>release busy board</b> commands, and then retest.</li><li>3. If the problem continues, replace the circuit pack.</li><li>4. Run the test again.</li></ol>
	PASS	Communication with this circuit pack is successful.
any	NO BOARD	This is normal if the test is being done when (a) the circuit pack is not physically in the system or (b) the system is booting up. Otherwise, there is some inconsistency between the physical configuration and the data kept in the system. <ol style="list-style-type: none"><li>1. Verify that the circuit pack is physically in the system.</li><li>2. Verify that the system is not in a stage of booting up.</li><li>3. ) Retry the command at 1-minute intervals for a maximum of 5 times.</li></ol>

## SAKI Sanity Test (#53)

**This test is destructive.**

This test resets the circuit pack and is executed as part of the long test sequence only for the Tone-Clock circuit pack and DS1 interface circuit packs. All other common circuit packs can be reset with the **reset board PCSS** command.

Table 5-547. TEST #53 SAKI Sanity Test

Error Code	Test Result	Description/ Recommendation
none	ABORT	System resources required for this test are not available. 1. Retry the command at 1-minute intervals a maximum of 5 times.
1005	ABORT	Wrong circuit pack configuration to run this test. This error applies only to DS1 interface circuit packs. It means the DS1 interface circuit pack is providing timing for the system and, therefore, it cannot be reset without major system disruptions. 1. If the circuit pack needs to be reset, set synchronization to another DS1 interface circuit pack or the Tone-Clock circuit pack and try again. Refer to <a href="#">"SYNC (Synchronization)" on page 5-1063</a> .
1015	ABORT	Port is not out-of-service. 1. Busy out the circuit pack. 2. Execute command again.
2100	ABORT	System resources required for this test are not available. 1. Retry the command at 1-minute intervals a maximum of 5 times.
1	FAIL	The circuit pack failed to reset.
2	FAIL	The circuit pack failed to restart. 1. Execute command again. 2. If the problem persists, replace the circuit pack.
	PASS	The circuit pack initializes correctly. 1. Run the Short Test Sequence.
any	NO BOARD	This is normal if the test is being done when (a) the circuit pack is not physically in the system or (b) the system is booting up. Otherwise, there is some inconsistency between the physical configuration and the data kept in the system. 1. Verify that the circuit pack is physically in the system. 2. Verify that the system is not in a stage of booting up. 3. Retry the command at 1-minute intervals for a maximum of 5 times.

## Neon Test (#220)

This test checks the voltage required to light the neon lamp on an analog terminal. A relay connects a 120V DC source from the backplane of the circuit pack onto the voltage bus, and another relay connects a 2K shunt from the bus to ground. Current in the line is then monitored to determine if the voltage is present.

The neon test runs only for TN746 and TN769 Analog circuit packs. If the circuit pack is not a TN746 or TN769, the test returns PASS, but there is no testing done to the circuit pack.

Table 5-548. TEST #220 Neon Test

Error Code	Test Result	Description/ Recommendation
1004	ABORT	<p>The port was seized by a valid call during the test. The test has been aborted. Use the <b>display port PCSSpp</b> command to determine the station extension. Use the <b>status station</b> command to determine the service state of the port. If the service state indicates that the port is in use, then the port is unavailable for certain tests. You must wait until the port is idle before retesting.</p> <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li></ol>
1008	ABORT	<p>Could not allocate a ringing circuit. Either all the ringing circuits are in use, or the ringing generator is defective or is not wired correctly.</p> <ol style="list-style-type: none"><li>1. Retry the command at 1-minute intervals a maximum of 5 times.</li><li>2. If the test continues to abort, look for RING-GEN errors in the Error Log. If an ABORT 1008 occurs for this test on other circuit packs as well, then the ringing generator may be defective or is not wired correctly. If it doesn't occur on port test 48 for ANL-16-L, then all four ring phases are in use.</li></ol>

*Continued on next page*

Table 5-548. TEST #220 Neon Test — Continued

Error Code	Test Result	Description/ Recommendation
1018	ABORT	<p>There are not any translated ports on the circuit pack, or if there are ports, then none are administered to have "neon."</p> <ol style="list-style-type: none"> <li>1. Verify that there are ports administered on the circuit pack. If no ports are administered, no further action is required.</li> <li>2. Verify that you have neon sets connected (Lucent sets that may be neon sets are 500 and 2500 series, also some non-Lucent may also be neon sets). If no neon sets are connected to the circuit pack, the test continues to abort, but no further action is required.</li> <li>3. If there are no neon sets connected to the circuit pack, at least one port needs to be translated with neon. To check if a port is translated with neon, use the <b>display port PCSSpp</b> command to determine the station extension of any station on this circuit pack. Use the <b>display station &lt;extension&gt;</b> to determine if the port is administered with neon. The field "Message Waiting Indicator:" must be set to "neon" for at least one of the administered ports. If this field is not administered to "neon" the test continues to abort. This is acceptable because not all stations have neon lamps on their analog terminals. If none of the terminals have neon lamps, the test continues to abort, but no further action is required.</li> <li>4. Retry the command again.</li> <li>5. Retry the command at 1-minute intervals a maximum of 5 times.</li> <li>6. If the test continues to abort, look for RING-GEN errors in the Error Log. If an ABORT 1008 occurs for this test on other circuit packs as well, then the ringing generator may be defective. If it does not occur on port test 48 for ANL-16-L, all four ring phases are in use.</li> <li>7. Retry the command again.</li> </ol>
2000	ABORT	Response to the request was not received within the allowable time period.
2100	ABORT	Could not allocate the necessary system resources to run this test.
	ABORT	<p>Could not allocate the necessary system resources to run this test. Internal System Error.</p> <ol style="list-style-type: none"> <li>1. If Error Type 1538 is present in the Error Log, follow the recommended maintenance strategy.</li> </ol>
	FAIL	<p>The test failed because no neon current was detected.</p> <ol style="list-style-type: none"> <li>1. Look for the failure of test 220. If test 220 fails, replace the 650A power supply.</li> <li>2. Retry the command again.</li> </ol>

Continued on next page

5 Maintenance Objects for DEFINITY ONE  
XXX-BD (Common Port Circuit Pack)

5-1357

Table 5-548. TEST #220 Neon Test — *Continued*

Error Code	Test Result	Description/ Recommendation
	PASS	This circuit pack is a TN746 or TN769 Analog Line circuit pack and the neon current is detected. This test also returns PASS for circuit packs that are not TN746 or TN769 circuit packs, but the test is not run on the circuit pack and the results of this test can be ignored.
any	NO BOARD	<p>This is normal if the test is being done when (a) the circuit pack is not physically in the system or (b) the system is booting up. Otherwise, there is some inconsistency between the physical configuration and the data kept in the system.</p> <ol style="list-style-type: none"><li data-bbox="303 580 895 607">1. Verify that the circuit pack is physically in the system.</li><li data-bbox="303 623 887 650">2. Verify that the system is not in a stage of booting up.</li><li data-bbox="303 666 1043 693">3. Retry the command at 1-minute intervals for a maximum of 5 times.</li></ol>

- 5** Maintenance Objects for DEFINITY ONE  
*XXX-BD (Common Port Circuit Pack)*

5-1358

# DEFINITY ONE NT Log Events and Alarms

# 6

## Introduction

---

Alarms and NT log events generated by the DEFINITY ONE system software are stored in the Application Log. This chapter describes the alarms that can be generated by the co-resident services running on the TN795 Processor circuit pack, along with advice on how to resolve the alarms.

See [“Resolving alarms” on page 2-5](#) for information about how to view and respond to alarms that occur.

## Co-Resident Services

---

This section describes the co-resident services.

**Table 6-1. Co-Resident Services**

---

Acronym	Description
GAM	The <i>global alarm module</i> (GAM) coordinates alarm reporting for the DEFINITY ONE™ system. Its primary functions are to: <ul style="list-style-type: none"><li>■ Accept and forward alarms from other applications.</li><li>■ Generate alarms for Windows NT.</li><li>■ Manage communication links to the Operations Support System (OSS).</li></ul>

See [Table 6-3](#).

---

*Continued on next page*

Table 6-1. Co-Resident Services — *Continued*

Acronym	Description
GAS	<p>The <i>global administration subsystem</i> (GAS) provides</p> <ul style="list-style-type: none"><li>■ Command line access to administration and maintenance functions.</li><li>■ Administration support for parameters in the DEFINITY ONE system that are not provided elsewhere.</li></ul> <p>See <a href="#">Table 6-4</a>.</p>
GSK	<p>The <i>global sanity keeper</i> (GSK) ensures that all authorized Lucent Technologies applications are executing on a DEFINITY ONE server. Its major component is the Watchdog process.</p> <p>See <a href="#">Table 6-7</a>.</p>
LAC	<p>The <i>Lucent access control</i> software module (LAC) governs maintenance access to the Lucent application software.</p> <p>See <a href="#">Table 6-13</a>.</p>
LIC	<p>The <i>license server</i> (LIC) governs permission to execute software applications.</p> <p>See <a href="#">Table 6-14</a>.</p>
NT	<p>Microsoft Windows NT operating system.</p> <p>See <a href="#">Table 6-15</a>.</p>
VFM	<p>The <i>virtual fabric manager</i> (VFM) translates DEFINITY ECS protocols into DEFINITY ONE methods and messages.</p> <p>See <a href="#">Table 6-14</a>.</p>

## Alarms for DEFINITY ONE Co-Resident Services

---

All Co-Resident Services alarms reside in the Application Log (except for one in the GSK, see that section). All alarms are listed by their Event Source.

Table 6-2. GAM Events

Event ID	Alarm Severity	Description	Resolution
2	Minor	Modem failure. Either the modem is not working or is not connected.	<ol style="list-style-type: none"><li>1. Verify modem is connected.</li><li>2. run prmaint add link to command test #</li><li>3. If problem persists, escalate.</li></ol>

---

Table 6-3. GAS Events

Event ID	Alarm severity	Description	Displayed error message	Resolution	Next Step
2	Minor	During backup, command cannot write to the destination add link in the PCMCIA card, or to a network disk.	Cannot write to <i>destination</i>	For PCMCIA:  Check that PCMCIA card is plugged in and sane.  Check permissions on PCMCIA (e: drive)  For network disk: Check that f: is mapped to network.  Check permissions on mapped network drive (f: drive).	
3	Minor	Archive command failed" gasp" under d1 backup.	Archive command failed.	Escalate. Possible causes: internal software error, software version mismatch, possible disk corruption.	

*Continued on next page*

Table 6-3. GAS Events — *Continued*

Event ID	Alarm severity	Description	Displayed error message	Resolution	Next Step
12	Minor	"gasp" under d1backup command cannot write to destination.	Cannot write to destination.	For PCMCIA: Check that PCMCIA card is plugged in and sane.  Check permissions on PCMCIA (e: drive)  For network disk: Check that f:drive is mapped to network.  Check permissions on mapped network drive (f: drive).	
13	None	cp command under d1restore attempted to restore nonexistent file.  The file: contrybackup/backup_ident on destination is missing.	<i>Filename</i> does not exist	locate correct file and reexecute command.	

*Continued on next page*

Table 6-3. GAS Events — *Continued*

Event ID	Alarm severity	Description	Displayed error message	Resolution	Next Step
15	none	D1 Restore command failed (caused by either gzip, cp permissions access contention, or hard drive space).  Otherwise, one of the archive files in destination/countrybackup directory is corrupted.	Restore failed ( <i>reason code</i> )	Escalate	
21	None	Bad or missing installation file	Bad or missing installation file	Re-install DEFINITY ONE. If problem persists, escalate to INADS to acquire new license file.	Install new license file. add link
22	None	Bad password file	Bad password file.	Re-install DEFINITY ONE. If problem persists, escalate to INADS to acquire new password file.	Install new password file. add link
23	None	Failed to add or delete a user in the system	Failed to add or delete a user in the system	Login ID does not have permission to perform operation.	

*Continued on next page*

Table 6-3. GAS Events — *Continued*

Event ID	Alarm severity	Description	Displayed error message	Resolution	Next Step
24	Major	Password file expired	Password file expired	Informed customer escalate to INADS	Escalate to INADS for new installation file.
25	Minor	Failed to retrieve serial number from firmware.	Failed to retrieve serial number from firmware.	Re-install DEFINITY ONE. If problem persists, escalate.	Replace firmware. (link TBA)

Table 6-4. GSK Events

Event ID	Alarm Severity	Description	Resolution	Next Steps
1	None	Watchdog started (Both System and Application logs)		N/A
2	None	Application <i>application_name</i> started		N/A
3	None	Application failed unexpectedly and has restarted.  Application <i>application_name</i> terminated. Executing recovery script (if any) and restarting. Retry Count = <i>nn</i> .  Could not start application <i>application_name</i> . Retrying (retry count = <i>nn</i> ).		Examine log files for failure reasons. Escalate to Tier 4 or report to development.

*Continued on next page*

Table 6-4. GSK Events — *Continued*

Event ID	Alarm Severity	Description	Resolution	Next Steps
4	Major	Watchdog Initiated Reboot.  Sanity Timeout to Firmware. System will reboot.	Escalate	Record external activity prior to reboot. Provide system log files to development.
5	Major	Application Total Failure  1. Application <i>application_name</i> totally failed.  2. Executable <i>filename</i> of application <i>application_name</i> not found	Restart DEFINITY ONE. If problem persists, escalate.	<ol style="list-style-type: none"><li>1. Restart application with "start" command. Examine log files for failure reason. Report to development.</li><li>2. Restart application using correct executable.</li></ol>
6	Minor	Cannot open log file <i>watchdog_log_file_name</i> .	Escalate	<ol style="list-style-type: none"><li>1. Copy corrupted watchdog log file to another location, then remove it from the original location.  When the system is restarted, a new log file will be created.</li><li>2. Provide copy of corrupt log file to development.</li></ol>

*Continued on next page*

Table 6-4. GSK Events — *Continued*

Event ID	Alarm Severity	Description	Resolution	Next Steps
7	Minor	Internal Software Error <ol style="list-style-type: none"><li>1. Internal Software Error. Clean Shutdown not possible for application <i>application_name</i>.</li><li>2. Internal Software Error. Orderly System Shutdowns Affected</li><li>3. Cannot access registry. No protection against continuous reboots.</li></ol>	Restart DEFINITY ONE at a convenient time. If problem persists, escalate.	<ol style="list-style-type: none"><li>1. Provide log files to development. Arrange a planned system restart at a time when system is the least busy.</li><li>2. Provide log files to development.</li></ol>
8	Major	Watchdog Failure: <ol style="list-style-type: none"><li>1. Watchdog initialization failed. Internal Software Error. Applications will not start.</li><li>2. Watchdog initialization failed. Cannot read configuration file <i>filename</i>. Applications will not start.</li><li>3. Watchdog failed. Internal Software Error. System may reboot.</li></ol>	Escalate	<ol style="list-style-type: none"><li>1. Contact development. Provide watchdog log file.</li><li>2. Replace watchdog configuration file.</li><li>3. Contact development. Provide log files.</li></ol>

---

*Continued on next page*

Table 6-4. GSK Events — *Continued*

Event ID	Alarm Severity	Description	Resolution	Next Steps
9	None	Watchdog Request: <ol style="list-style-type: none"><li>1. Addproc request received for application <i>application_name</i>.</li><li>2. Addwatch (registration) request received for application <i>application_name</i>.</li><li>3. Delwatch (un-registration) request received for application <i>application_name</i>.</li></ol>		Information event only. No action required.
10	None	Process <i>process_name</i> missed a heart beat.		Examine log files for failure reasons. Escalate to Tier 4 or report to development.
11	Minor	Recovery script not found <ol style="list-style-type: none"><li>1. Recovery script <i>filename</i> for application <i>application_name</i> not found</li><li>2. Fail script <i>filename</i> for application <i>application_name</i> not found</li></ol>	Escalate	<ol style="list-style-type: none"><li>1. Arrange a planned application or system restart at a time when system is the least busy.</li><li>2. Ensure correct script name is used on restart.</li></ol>

---

*Continued on next page*

Table 6-4. GSK Events — *Continued*

Event ID	Alarm Severity	Description	Resolution	Next Steps
12	None	Watchdog cannot start. Another watchdog may be running or another application has opened watchdog log file. Cannot rename file from <i>old_filename</i> to <i>new_filename</i> .		If another watchdog is running, do not attempt to start watchdog without first shutting it down in an orderly manner (for example, via the <b>shutdownproc</b> command.) If the watchdog log file is open (for example, is being viewed), close it and then attempt to start watchdog again. Otherwise, contact development and provide watchdog log file.
13	None	Application <i>application_name</i> has been shut down		N/A
14	Major	System continuously rebooting  Exceeded the maximum allowable number of system reboots. Watchdog exited	Escalate	Contact development. Provide log files.

*Continued on next page*

Table 6-4. GSK Events — *Continued*

Event ID	Alarm Severity	Description	Resolution	Next Steps
15	None	All applications have been shut down		N/A
50	Major	Firmware download failure	Firmware download program could not talk to watchdog. Applications will not start.	Contact development. Provide Lucent log file.
51	Minor	Firmware download failure (Bad boot)	Downloadable boot firmware is invalid. Firmware is running in permanent boot code because all previous attempts to download application firmware using downloadable boot firmware failed.	Contact development. Provide Lucent log file.

Table 6-5. LAC Events

Event ID	Alarm Severity	Displayed Error Message	Resolution
1	None	User attempting login	Informational
2	None	User has been locked out	Informational
5	None	Unable to open lac file or invalid lac file	Reinstall license file using siteconfig
6	None	Lac Login file not available	Reinstall license file using siteconfig
7	None	Password file expired	Reinstall license file using siteconfig
8	Minor	Failed to get firmware serial number	<p>Replace TN795 Processor Board.</p> <p><b>⚠ WARNING:</b></p> <p><i>When the disk is replaced on the TN795, a new license file must be downloaded to the system before the system will become operational. Refer to "Obtaining a License File" in Chapter 3 of DEFINITY ONE™ Communications System Release 2.0 Installation and Upgrades (555-233-109). Retry the command and if the test fails, replace the circuit pack.</i></p>
9	None	Sanity event not opened	Informational - escalate
11	None	Error cannot connect to DEFINITY	escalate
12	None	Error cannot connect to AUDIX	escalate

6 DEFINITY ONE NT Log Events and Alarms  
Alarms for DEFINITY ONE Co-Resident Services

6-14

Table 6-6. LIC Events

Event ID	Alarm Severity	Description	Resolution	Next Step
1	Major	Corrupted or missing license file	Re-install DEFINITY ONE. If problem persists, escalate.	Copy in a valid license file.
2	Major	License file expired.	Escalate	Replace licence file.
3	Major	Failed to retrieve serial number from firmware	Escalate	Check firmware
5	None	License denied	Check serial number. Add link	

Table 6-7. VFM Events

Event ID	Alarm Severity	Description	Resolution	Next Step
1	Minor	Unable to start timer  The system will still operate with this alarm. Scheduled maintenance will not run	Restart DEFINITY ONE at your convenience. If step one does not resolve the problem, see step 2 link to procedure for restarting.	1. Restart VFM add link to procedure). 2. Restart system
3	Minor	VFM unable to open configuration file	The system will operate with the following restrictions: <ul style="list-style-type: none"> <li>■ AUDIX is down</li> <li>■ ISDN cards are down</li> </ul> Re-install DEFINITY ONE at your convenience. If problem persists, see add link.	1. Check config file in C:\LucentSoftware\Definity\vfm.cfg. 2. Verify config file entries are correct. 3. Restart VFM. 4. Restart system.

## NT Generated Alarm Information

All NT Generated alarms reside in the System Log.

Table 6-8. NT Alarms

Event Source	Event ID	Alarm Severity	Description	Resolution	Next Steps
Srv	2001	Major	The server was unable to perform an operation due to a shortage of available resources.	Escalate	Look for a vagrant application in task manager.  The page file has reached the maximum page file size and there are no more pages available, either in main memory or in the page file. This generally indicates a memory leak in a another process.
Srv	2002	Major	The server could not create its device. The server could not be started.	Escalate	The server was started on a computer that does not have any memory free.
Srv	2003	Major	The server could not create a process. The server could not be started.	Escalate	The server was started on a computer that does not have any memory free.
Srv	2004	Major	The server could not create a startup thread. The server could not be started.	Escalate	The server was started on a computer that does not have any memory free.

*Continued on next page*

Table 6-8. NT Alarms — *Continued*

Event Source	Event ID	Alarm Severity	Description	Resolution	Next Steps
Srv	2010	Major	The server could not start the scavenger thread. The server could not be started.	Escalate	The server was started on a computer that does not have any memory free.
Srv	2012	Major	The server has encountered a network error.	Escalate	If you see many errors of this type in the event log in Event Viewer, they indicate a network hardware or software problem.
Srv	2020	Major	The server was unable to allocate from the system paged pool because the pool was empty.	Escalate	The page file has reached the maximum page file size and there are no more pages available, either in main memory or in the page file. This generally indicates a memory leak in a another process.
Srv	2013	Major	The <i>disk_name</i> disk is at or near capacity.	Escalate	You may need to delete some files.  Look for oversized log files.  Look for unusually large AUDIX mailboxes (If necessary send broadcasters delete messages)
Srv	2501	Minor	The server's Registry key %1 was not present. The server could not start.	Escalate	The Registry is corrupted.

*Continued on next page*

Table 6-8. NT Alarms — *Continued*

Event Source	Event ID	Alarm Severity	Description	Resolution	Next Steps
Srv	2502	Minor	The server's Registry key <i>key_name</i> was not present and could not be created. The server could not start.	Escalate	The Registry is corrupted.
ndis	5000	Minor	<i>Driver_name</i> : Has encountered a conflict in resources and could not load.	Escalate	The network driver failed to initialize due to an apparent conflict between the adapter card and some other hardware.
ndis	5006	Minor	<i>Driver</i> : The version number is incorrect for this driver.	Escalate	The network driver version number is incompatible with this operating system.
Qic117	151	Minor	The driver could not allocate memory for data transfer buffers. Try restarting the system. If this error persists, more system RAM may be required. From device: <i>device_name</i> .	Escalate	

*Continued on next page*

Table 6-8. NT Alarms — *Continued*

Event Source	Event ID	Alarm Severity	Description	Resolution	Next Steps
RAS PPTP	1	Minor	Unable to open registry key path for the RAS PPTP driver.	Escalate	
serial	8	Minor	Not enough resources were available for the driver.	Escalate	
Various	41	Major	The file system structure on the disk is corrupt and unusable. Please run the chkdsk utility on the device <i>device_name</i> with label " <i>label</i> ".	Escalate	

# Summary of DEFINITY ONE Commands

**NOTE:**

Most of the commands listed below are INTUITY AUDIX COMMANDS.

This appendix provides brief descriptions for the commands you will encounter in using the DEFINITY ONE system.

This chapter is organized in alphabetical order by command name. These commands include INTUITY AUDIX and DEFINITY ONE.

Command	Description
Alogdump	Dumps contents of VM activity log in ASCII format DEFINITY ONE: Same as Intuity
Assign	Assign a group number to a card/channel or service to channel DEFINITY ONE: NA
Audit	Voice mail audits DEFINITY ONE: AUDIX screens: audit or Command line: Use runmp - i.e. runmp <AUD_NIGHTLY, AUD_WEEKLY> No platform audit
audit_nwdb	Runs audits on the networking databases DEFINITY ONE: Same as Intuity

Command	Description
busy_nwchan	<p>Busy a networking channel</p> <p>DEFINITY ONE: Use Web page screens only</p>
cat	<p>DEFINITY ONE: Reads a file in sequence and writes it to standard output</p> <p>i.e. cat [filename] (Ctrl C to stop a long cat)</p>
cleardb, clean_sys, (M4)	<p>Removes all data files from AUDIX filesystems. Must be done before installing the VM-dfltdb (voice mail default databases)</p> <p>DEFINITY ONE: Use/LucentSoftware/Audix/tools/postinstall.sh -Tt -d all</p> <p><b>⇒ NOTE:</b> The “-d all option” says clear all AUDIX databases</p>
crtindexed	<p>Creates an empty indexed VM database file</p> <p>DEFINITY ONE: NA</p>
clearlog	<p>DEFINITY ONE: Used to clear the logs maint, res, alarm, &amp; fax</p> <p>i.e. clearlog -i maint</p>
d1backup	<p>DEFINITY ONE: Backup of DEFINITY, INTUITY and the registry</p> <p>Where dataset = deftran, vmnamtran, vmmsgtran, vmannounce, vmnammsgtran, registry the destination would be PCMCIA unless you have a mapped network drive</p> <p>d1backup [datasets] [destination_path] [-c][[/c] [-?][/?][-v][/v]</p> <p>i.e. d1backup deftran registry pcmcia</p>
d1restore	<p>DEFINITY ONE: Restore of DEFINITY, INTUITY and the registry</p> <p>Where dataset = deftran, vmnamtran, vmmsgtran, vmannounce, vmnammsgtran, registry the destination would be PCMCIA unless you have a mapped network drive</p> <p>d1restore [source_path datasets] [-c][[/c] [-?][/?][-v][/v]</p> <p>i.e. d1restore deftran registry pcmcia</p>

Command	Description
dconstruct	Create/populate VM database file by reading an ASCII file and converting it into a binary database file DEFINITY ONE: Same as INTUITY i.e. deconstruct -C -f syp < syp.out
delete	Removes a card/channel from a service group DEFINITY ONE: NA
dflt_annc	Checks /VM/audix/sd/sdata/annc.name for current permissions and corrects them if need be DEFINITY ONE: Use /LucentSoftware/Audix/tools/postinstall.sh -Tt
dformat	Converts a binary database file into ASCII readable form DEFINITY ONE: Same as INTUITY i.e. dformat -f syp > syp.out
diagnose	Test a card while it is in service DEFINITY ONE: use DEFINITY screen: test board 1A12
diskok	Checks to see if all hard disks are working properly DEFINITY ONE: diskok is not available on DEFINITY ONE. The NT diskeeper command is available. From NT start button -> programs -> executive software -> diskeeper
disp_nwstat	Display networking channel status DEFINITY ONE: Same as INTUITY
display card	Displays information about given card(s) DEFINITY ONE: DEFINITY screen: list config all
display chan	Displays information about given channel(s) DEFINITY ONE: DEFINITY screen: display station
displot	Displays administration, maintenance, active/resolved alarms DEFINITY ONE: Same as INTUITY
dx	Converts a decimal integer into it's hexadecimal equivalent DEFINITY ONE: Same as INTUITY
ftp	DEFINITY ONE: Use to transfer files to another machine on the LAN

Command	Description
hostname	DEFINITY ONE: Displays the name of the DEFINITY ONE machine
init_nwdb	Initializes the networking database DEFINITY ONE: Same as INTUITY
ipconfig	DEFINITY ONE: Displays Windows NT IP Configuration
kill_vm	Sends a kill signal to all voice mail processes DEFINITY ONE: Do Not Use
ksh -o vi	DEFINITY ONE: Invokes k-shell so you don't have re-type commands. After typing ksh -o vi press Esc key, then - key to find a previously used command. Commands are buffered so you step through the list by pressing the "-" key.
less	DEFINITY ONE: A filter that displays the contents of a text file on the terminal, one screen at a time. Example: ps -ef   less
load_nwdb	Loads the networking databases from ASCII data files that were previously generated with the unload_nwdb command DEFINITY ONE: Same as INTUITY Use load_nwdb -init to clear the networking database.
logsend	Generate event to be logged. This command is used to resolve active alarms by generating a resolved alarm event. Located in /mtce/tools/bin DEFINITY ONE: Same as INTUITY Located /LucentSoftware/CornerStone/bin
lucent help	DEFINITY ONE: Displays a list of commands that can be run from the lucent1 login
mkindexed	Will expand a flat file copy of an indexed file into an indexed file DEFINITY ONE: NA
midlands	Test for the presence of a symbolic link between /VM/audix/[nm/annc] and /voiceX/[nm/annc] DEFINITY ONE: Use /LucentSoftware/Audix/tools/postinstall.sh -Tt

Command	Description
more	A filter that displays the contents of a text file on the terminal, one screen at a time  DEFINITY ONE: No "more" on DEFINITY ONE see "less" command
net	DEFINITY ONE: To share a drive from the command line. net share CDR=D:\LucentData\CDR
netstat	DEFINITY ONE: Use to get general route information
ping	DEFINITY ONE: Use to test IP configuration
ps	DEFINITY ONE: Prints information about active processes. The most common use of this command is "ps -ef" to see a list if all active processes on the system  ps -ef   grep audix/ to view all actively running Audix processes  ps -ef   grep audixN/ to view all actively running Networking processes
pstat	Displays current status of voice port  DEFINITY ONE: Use DEFINITY screen: status station
pulist	DEFINITY ONE: Process User list. Details all the processes running in the system and who is using the process
rel_nwchan	Release a networking channel  DEFINITY ONE: Use web screen
remove	Places card/channel in the manual-out-of-service (MANOOS) state  DEFINITY ONE: Use DEFINITY Screen: busy board1A12 or busy station x
reset_nw	Resets the networking module in background by executing stop_nw and start_nw  DEFINITY ONE: a two step operation:  shutdown AudixNetw  start AudixNetw
reset_nwbrd	Reset networking ACCX board  DEFINITY ONE: NA
restore	Places a card/channel in-service (INSERV) state  DEFINITY ONE: NA

Command	Description
rstfiles	Restores from backup tape the Datatype (e.g. System Data, Voice Names) and one or more pathnames to get a specific file(s); this is very useful when less than an entire Datatype is needed from the backup tape  DEFINITY ONE: NA
rtname	Translates resource types to numeric resources and vice versa  DEFINITY ONE: Same as INTUITY
serial_diag	This command executes the Equinox diagnostic command /mtce/bin/megadiag  DEFINITY ONE: NA
setip	display and change TCIP network properties  DEFINITY ONE: setip with no arguments displays current network properties on the system. Valid datatypes are: name, cust, dns, wins, ras
softboot	Executes an init 6 reboot of the system after stopping VS  DEFINITY ONE: reboot nice
ss	Displays system status. For each module (Maintenance, Platform, Voice Mail and Networking) a count of the number of processes and a list of all significant processes that are running  DEFINITY ONE: d1stat gives the number of processes active  For actual process names: AUDIX: ps -ef   grep audix/ AudixNetworking: ps -ef   grep AudixN
start_nw	Start networking  DEFINITY ONE: start AudixNetw

Command	Description
start_vs	<p>Start voice system up to a fully operational state</p> <p>DEFINITY ONE: start CornerStone   Audix   AudixNetw</p> <p>Start Cornerstone starts Cornerstone, AUDIX and AUDIX Networking</p> <p>Start AUDIX starts AUDIX and AUDIX Networking</p> <p>Start AUDIXNetw starts AUDIX Networking</p> <p> <b>NOTE:</b> To stop applications: shutdown AudixNetw   Audix   CornerStone</p>
startvm	<p>Starts up the voice mail application</p> <p>DEFINITY ONE: Start Audix</p>
status	<p>Displays the status line that appears on the AUDIX screens</p> <p>DEFINITY ONE: same as INTUITY</p>
stop_nw	<p>Stop networking</p> <p>DEFINITY ONE: stop AudixNetw</p>
stop_vm	<p>Shuts down the voice mail system in a 'synchronous' mode (same as vmshut -s)\</p> <p>DEFINITY ONE: shutdown Audix</p>
stop_vs	<p>Stops the voice system software</p> <p>DEFINITY ONE: shutdown CornerStone</p>
sys_software	<p>Creates a list of installed software by doing a pkginfo -l, and puts the output into /mtce/text/soft_inst</p> <p>DEFINITY ONE: Use sw_version command</p>
sysmon	<p>Displays system monitor which allows user to see incoming activity on voice channels dynamically</p> <p>DEFINITY ONE:</p> <p>From NT Explorer: /LucentSoftware/CornerStone/mtce/sysmon/sysmon.exe (double click)</p> <p>From Command line: /LucentSoftware/CornerStone/mtce/sysmon/sysmon.exe</p>

Command	Description
tail	DEFINITY ONE: Copies a file to standard output beginning at a designated place  i.e. tail -f /vm/misc/tracelog.a   <b>NOTE:</b> Don't leave the system with an active tail running Ctrl-c to quit the tail
telnet	DEFINITY ONE: Use to connect to another machine on the LAN
test_nwconn	Test remote machine connectivity on optionally specified channel  DEFINITY ONE: Same as INTUITY
test_nwloop	Run loop around test on a networking channel  DEFINITY ONE: NA
toggle	Toggles the function keys on the AUDIX terminal  DEFINITY ONE: Same as INTUITY Example:  term type: vt131  from command line: toggle f (to better position the function keys)  useful keystrokes: <ul style="list-style-type: none"> <li>■ F1 enter</li> <li>■ F2 choices</li> <li>■ ctrl x cancel</li> <li>■ ctrl p prev page</li> <li>■ ctrl n next page</li> <li>■ ctrl l refresh</li> <li>■ ctrl c choices</li> <li>■ ctrl e enter</li> </ul>
trace	Modifies trace levels of selected voice mail modules. The trace output is in /VM/misc/tracelog.a  DEFINITY ONE: use /vm/bin/vmtrace
trace_nw	turn networking trace on/off and display current trace levels, initialize tracing, get list of valid trace levels  DEFINITY ONE: same as INTUITY AUDIX

Command	Description
unload_nwdb	<p>Unloads networking database into ASCII readable files. By default the entire database is unloaded</p> <p>DEFINITY ONE: same as INTUITY</p>
vdf	<p>Displays the hours-of-speech information (purchased, used, potential)</p> <p>DEFINITY ONE: audix screen: list measurements load day</p>
ve_backup	<p>With no Datatype(s) given, an unattended backup (nightly - System-Data only) will be done, otherwise a restore of the given Datatypes will be done</p> <p>DEFINITY ONE: Use the DEFINITY ONE Web screens for Backup</p> <p>or</p> <p>Use d1backup (See d1backup)</p>
ve_restore	<p>With no Datatype(s) given, the whole set of Datatypes on the tape will be restored, otherwise a restore of the given Datatypes will be done</p> <p>DEFINITY ONE:</p> <ol style="list-style-type: none"> <li>1. Use the DEFINITY ONE Web screens for Restore</li> </ol> <p>or</p> <ol style="list-style-type: none"> <li>2. Use d1restore</li> </ol>
Vex	<p>Displays the INTUITY AUDIX Administration Menu</p> <p>DEFINITY ONE: use Fc for Audix Screens</p> <p> <b>NOTE:</b> Note CornerStone does not have any screens and the Audix Networking screens are web accessible.</p>
vmrestart	<p>Stops and starts the voice mail system</p> <p>DEFINITY ONE: a two step operation: "shutdown Audix" followed by "start Audix"</p>
vmshut	<p>Graceful shutdown of the voice mail system in a camp-on manner. Use '-f' to force-busy the voice ports which will drop all current calls. (Recommend vmshut -f &amp; to put into background)</p> <p>DEFINITY ONE: shutdown Audix campon. To force a shutdown after the campon has been started, do a "shutdown Audix"</p>

Command	Description
vprmdchk	Checks permissions of all /voiceX directories and corrects them as required  DEFINITY ONE: Use /LucentSoftware/Audix/tools/postinstall.sh -Tt
vs_status	Displays voice system information  DEFINITY ONE: use d1stat
vscstat	Displays the number of VSC's (Voice Sessions Controller) running  DEFINITY ONE: same as INTUITY AUDIX
vsdisable	Disables the automatic restarting of the voice system after a reboot  DEFINITY ONE: manually edit the /LucentSoftware/ECSplatform/watchdog/watchd.ini file
vsenable	Enables the automatic restarting of the voice system after a reboot  DEFINITY ONE: manually edit the /LucentSoftware/ECSplatform/watchdog/watchd.ini file
who -b	Used to figure out when the INTUITY AUDIX last completed a restart  DEFINITY ONE: Use command "restartcause"
xd	Converts 32-bit hexadecimal number to it's decimal equivalent  DEFINITY ONE: same as INTUITY AUDIX
Sw, Hw, Fw Version	INTUITY AUDIX: various ways  DEFINITY ONE: Hardware and Firmware: fwversionSoftware: swversion

## LAC GAS Commands

---

(Lucent Access Controller - Global Administration System)

Command Name	Description
oss	Set or display OSS Parameters
siteconfig	Set passwords for NT Administrator and Guest logins (Ntadmin, user)
productid	Set product IDs for DEFINITY, INTUITY AUDIX and DEFINITY ONE
swversion	Display product version numbers for DEFINITY, INTUITY AUDIX, CornerStone, DragonFly and DEFINITY ONE
serialnumber	Display serial number of the RYON board
alarmstat	Display Alarm Status
gamalarmstat	Display GAM alarms
cleargam	Manually resolve GAM alarms
alarmorig	Display the status of alarm origination to the OSS Enable/disable alarm origination
DEFINITY	Connect to SAT
AUDIX	Connect to INTUITY AUDIX SAT
pcAnywhere	Activate pcAnywhere on the DEFINITY ONE Type pcanywhere to start pcAnywhere Type pcanywhere -c to stop pcAnywhere
logoff or exit	Logoff from the LAC
reboot	Reboot the DEFINITY ONE. Options: reboot nice and reboot immediate
shutdown	Stop Applications gracefully. Options: shutdown Audixnetw, shutdown Audix, shutdown CornerStone, shutdown all
start	Restart Applications. Options: start CornerStone, start Audix, start AudixNetw
restartcause	Display DEFINITY ONE restart causes
fwversion	Display RYON firmware version

Command Name	Description
environment	Display RYON temperature Display RYON voltages Display power/fan input lead
installconfig	Install configuration
autobackup	Display automatic backup status (enabled/disabled) Enable/Disable automatic backup
backupsources	Display data sets to be auto-backed up Set data sets to be auto-backed up
backupparms	Display time and destination for auto-backup Set time and destination for auto-backup
identbackup	Display identification information for an existing backup set
help	GNU bash commands, these shell commands are defined internally. Type 'help' to see this list  Type 'help name' to find out more about the function 'name'  Use 'info bash' to find out more about the shell in general  A star (*) next to a name means that the command is disabled
downloadboot	Download firmware image

## Access Security Gateway

# B

---

This appendix provides information on how to administer Access Security Gateway (ASG). ASG employs a challenge/response protocol to confirm the validity of a user and reduce the opportunity for unauthorized access. ASG authentication will be imposed for Lucent Services logins as indicated below.

- lucent1 — all types of access require ASG authentication
- lucent2 — all types of access require ASG authentication
- lucent3 — all types of access require ASG authentication

 **NOTE:**  
init, inads, and craft are NOT supported on this platform.

### Using the ASG Mobile

1. On your desktop, double-click ASG Mobile V1.1.  
The ASG Mobile V1.1 window appears.
2. In the `Tech ID` field, type your login ID, which is the name of the attached file (without the .asg extension). Your login ID is the same as your Lucent login or an abbreviated part of it.

 **NOTE:**  
Your new password will be sent to you in a separate e-mail. The password is case sensitive.

3. Type the password twice.
4. Click **OK**.  
The ASG Mobile V1.1 window appears.

5. Use your communications package (for example, DSA, ProComm, or TerraNova), to dial the switch you need to contact.
6. In the communications package window, login as **lucent1**, **lucent2** or **lucent3**.  
  
Instead of a password prompt, a 7-digit challenge numbers appears.
7. Move to the ASG Mobile V1.1 window.
8. In the `Equipment ID` field, type the 10-digit Product ID.  
  
The default ID is 10 zeros (0000000000).
9. In the `Equipment Login` field, type **lucent1**, **lucent2** or **lucent3**.
10. In the `Challenge` field, type the 7-digit challenge number from step [6](#). Do not use the "-" character.  
  
DEFINITY ECS verifies the response. If correct, DEFINITY logs you on.
11. If the response is incorrect, return to step [1](#).
12. If this is the third rejection, see the *DEFINITY Enterprise Communications Server Release 8.2 Maintenance for R7csi*.

# Index

---

## Numerics

120A ICSU, [2-44](#)

---

## A

ACA, see Automatic Circuit Assurance

Access Security Gateway, [B-1](#)

Accessing DEFINITY ONE for

  maintenance, [1-26](#)

administration

  logins, [1-53](#)

air filters, [2-2](#)

alarm logs, [1-14](#)

Alarm Origination to OSS Numbers, [4-25](#)

alarm-related commands

  alarmorig, [3-5](#)

  alarmstat, [3-6](#)

  cleargamalarm, [3-7](#)

  gamalarmstat, [3-19](#)

alarms

  classifications, [1-15](#)

  error reporting, [1-14](#)

  logs, [1-14](#)

  major, [1-15](#)

  minor, [1-15](#)

  off-board, [1-15](#)

  on-board, [1-15](#)

  resolving, [2-5](#)

  warning, [1-15](#)

Alogdump command, [A-1](#)

Analog Tie Trunk Back-to-Back testing, [2-24](#)

AN-LN-PT, [5-187](#)

ATM (Asynchronous Transfer Mode)

  B-channel, [5-251](#)

  circuit emulation service (CES), [5-251](#)

  D-channel, [5-251](#)

  signaling group, [5-251](#)

  trunking, [5-251](#)

attendant consoles, LEDs, [1-38](#)

Automatic Circuit Assurance (ACA), [2-15](#)

---

## B

background tests, [1-15](#)

  fixed interval, [1-15](#)

  scheduled, [1-15](#)

backup commands

  autobackup, [3-6](#)

  identbackup, [3-20](#)

  schedbackup, [3-26](#)

bash commands, [3-2](#)

bit rate

  setting, [2-62](#)

Busy Verification of Terminals and Trunks, [2-15](#)

busyout commands

  busyout access-endpoint, [4-2](#)

  busyout adjunct-ip-link, [4-4](#)

  busyout board, [4-6](#)

  busyout cdr-link, [4-7](#)

---

## C

cabinets

  configurations, [2-2](#)

carrier lead appearances

  110 cross-connect field, [2-26](#)

change commands

  change circuit-packs, [4-19](#)

  change synchronization, [4-21](#)

  change system-parameters

    maintenance, [4-22](#)

circuit packs

  replacing TN795, [2-8](#)

  replacing/reseating, [2-7](#)

  status LEDs, [1-40](#)

  TN2305, [5-251](#)

  TN2306, [5-251](#)

  TN464, [5-548](#)

  TN722, [5-548](#)

  TN767, [5-548](#)

  TN768, [5-1132](#)

  TN780, [5-1132](#)

  TN790 Processor, [1-9](#)

  TN802 MAPD, [5-752](#)

  universal DS1 (UDS1) interface, [5-548](#), [5-752](#)

CLAN, [5-378](#)

clear commands

  clear audits, [4-30](#)

  clear errors, [4-30](#)

  cleargamalarm, [3-7](#)

clearlog command, [A-2](#)

clocks, system, [5-1132](#)

cold starts

  with translations loading, [1-33](#)

  without translations loading, [1-32](#)

commands

  categories, [1-51](#)

  DEFINITY for user, [1-51](#)

companding, [5-1188](#)

configurations

  cabinets, [2-2](#)

control and port circuit pack status LEDs, [1-39](#)

control circuit packs

  replacing, [2-7](#)

  reseating, [2-7](#)

  unseating, [2-7](#)

country codes, [5-1188](#)

---

**D**

data-link layer, OSI, [1-17](#)  
DC power  
    signaling leads, [2-60](#)  
DEFINITY logins, [1-49](#)  
DEFINITY reboot, [1-33](#)  
demand tests, [1-16](#)  
disable commands  
    disable synchronization-switch, [4-33](#)  
    disable test-number, [4-33](#)  
diskok, [A-3](#)  
display alarms commands  
    display alarms, [4-33](#)  
    display errors, [4-49](#)  
display commands  
    autobackup, [A-12](#)  
    backuppargs, [A-12](#)  
    backupsources, [A-12](#)  
    environment, [A-12](#)  
    fwversion, [A-11](#)  
    identbackup, [A-12](#)  
    restartcause, [A-11](#)  
display commands, see also list commands  
dislog command, [A-3](#)  
DLG maintenance, [1-19](#)  
downloadboot command, [3-3](#)  
DS1, [2-40](#)  
    CO trunk (CO-DS1), [5-526](#)  
    interface circuit packs, [5-548](#), [5-752](#)  
    option jumpers, [5-1230](#)  
    signaling, [5-548](#)  
    trunks, [5-752](#)  
DS1 Circuit Pack form, [5-1230](#)  
DS1 loopback, [2-39](#)  
DS1 span, [2-40](#)  
    T1, [2-39](#)  
DS1 span test, [2-40](#)  
DTMF, see Touch-tone (DTMF) Receiver Test Call  
DTMR port, [5-624](#)

---

**E**

E&M mode tests, [2-24](#)  
electromagnetic compatibility standards, [xxii](#)  
Emergency Transfer, [5-641](#)  
enable commands  
    enable mst, [4-70](#)  
    enable suspend-alm-orig, [4-70](#)  
    enable synchronization -switch, [4-71](#)  
    enable test-number, [4-72](#)  
environment commands  
    test environment, [4-249](#)  
error logs, [1-14](#)

error reporting, [1-14](#)  
errors  
    control, [1-17](#)  
    logs, [1-14](#)  
    reporting, [1-14](#)  
European Union Standards, [xxiii](#)  
exit command, [3-17](#)

---

**F**

Facility Test Calls, [2-16](#)  
    System Tone Test Call, [2-21](#)  
    Time Slot Test Call, [2-19](#)  
    Touch-Tone (DTMF) Receiver Test Call, [2-18](#)  
    Trunk Test Call, [2-17](#)  
fatal errors  
    recovery, [2-4](#)  
fileversion command, [3-17](#)  
First OSS Telephone Number, [4-24](#), [4-63](#)  
flow control, [1-17](#)  
Forced Password Aging, [1-53](#)  
ftpserv commands, [3-17](#)  
fwversion command, [3-18](#)

---

**G**

GAM events, [6-3](#)  
GAS commands, [3-1](#), [A-11](#)  
GAS events, [6-4](#)  
GSK events, [6-7](#)

---

**H**

H.323 Signaling Group, [5-668](#)  
Hard disk, replacing, [2-9](#)  
    diskok, [A-3](#)  
help, see lucent help

---

**I**

impedance, setting, [2-62](#)  
INADS Link, [5-696](#)  
Internet Telephony Server (ITS-E), [5-752](#)  
ISDN-PRI  
    DS0 channels, [5-752](#)  
    troubleshooting, [2-32](#)  
    troubleshooting test call problems, [2-35](#)

---

**L**

LAC events, [6-13](#)

LAC GAS commands, [A-11](#)

**LEDs**

attendant consoles, [1-38](#)

control and port circuit pack status, [1-39](#)

definition, [1-33](#)

maintenance circuit pack, [1-34](#)

processor circuit pack, [1-34](#)

LGATE-BD, [5-298](#), [5-305](#)

LIC events, [6-14](#)

**list commands**

list configuration, [4-72](#)

list disabled-mos, [4-76](#)

list history, [4-77](#)

list isdn-testcall, [4-79](#)

list measurements, [4-81](#)

list suspend-alm-orig, [4-84](#)

list sys-link, [4-85](#)

list testcalls, [4-86](#)

login groups, [1-43](#)

login names, [1-43](#)

**logins**

administering command permissions, [1-51](#)

AUDIX commands, [1-44](#)

customer AUDIX, [1-44](#)

customer DEFINITY, [1-49](#)

customer Web access, [1-45](#)

customer Windows NT, [1-43](#), [1-48](#)

security, [1-53](#)

logsend command, [A-4](#)

loopback jack, [2-39](#)

lucent help, [3-21](#)

---

**M****maintenance**

background testing, [1-15](#)

preventative procedures, [2-1](#)

subsystem, [1-1](#)

system's overall functions, [1-1](#)

testing, [1-15](#)

**maintenance object repair procedures**

BRI-PORT (ISDN-BRI Port), ABRI-PORT  
(ASAI ISDN-BRI Port), [5-312](#)

BRI-SET, ASAI-ADJ, BRI-DAT, [5-334](#)

DID-BD (Direct Inward Dial Trunk Circuit  
Pack), [5-474](#)

DID-DS1 (DS1 DID Trunk), [5-475](#)

DID-TRK (DID Trunk), [5-486](#)

maintenance object repair procedures,  
(continued)

DIG-BD (Digital Line Circuit Pack), [5-501](#)

DIG-LINE (Digital Line), [5-502](#)

DIOD-TRK (DIOD Trunk) [G1.2SE], [5-537](#)

DTMR-PT [Dual Tone Multifrequency Port  
(TTR)], [5-624](#)

M/T-BD (Maintenance-Test Circuit Pack)  
[G3iV1.1-286, G3iV2-386], [5-864](#)

M/T-DIG (Maintenance-Test Digital Port)  
[G3iV1-1.286, G3iV2-386], [5-865](#)

M/T-PKT (Maintenance-Test Packet Bus Port)  
[G3iV1.1-286, G3iV2-386], [5-877](#)

PDMODULE, TDMODULE (Data  
Module), [5-894](#)

S-SYN-PT (Speech Synthesis Port), [5-1041](#)

TIE-TRK (Tie Trunk), [5-1161](#)

TSC-ADM (Administered Temporary Signal-  
ing Connections) [G3iV1.1-286,  
G3iV2-386], [5-1217](#)

TTR-LEV (TTR Level), [5-1223](#)

UDS1-BD (UDS1 Interface Circuit  
Pack), [5-1227](#)

XXX-BD (Common Port Circuit Pack), [5-1343](#)

**maintenance objects (MOs)**

definition, [1-14](#)

maintenance/test analog port (M/T-ANL), [5-854](#)

Maintenance/Test Circuit Pack Query Test  
(#572), [5-954](#)

MAPD, [5-782](#)

mark port command, [4-90](#)

**measurements**

security, [1-50](#)

Media Processor, [5-668](#), [5-782](#)

MedPro, [5-668](#)

**MEDPROPT**

TN802B MAPD, [5-782](#)

**monitor commands**

monitor bcms, [4-90](#)

monitor health, [4-95](#)

monitor security-violations, [4-98](#)

monitor system, [4-99](#)

monitor traffic, [4-105](#)

monitor trunk, [4-107](#)

---

**N**

Neon voltage, [2-13](#)

network interface, [2-44](#)

NT alarms, [6-15](#)

## O

- Open System Interconnect model, [1-16](#)
  - data-link layer, [1-17](#)
  - physical layer, [1-16](#)
- option jumpers
  - TN464, [5-1230](#)
  - universal DS1 (UDS1) circuit packs, [5-1230](#)
- OSI, see Open System Interconnect model
- OSS Numbers field, [4-22](#)

## P

- Packet Bus, [5-950](#)
- Packet Circuit Pack Audit Test (#573), [5-957](#)
- Password Expiration screen, [1-52](#)
- passwords
  - security, [1-53](#)
- pcAnywhere, [5-758](#)
- physical
  - layer, OSI, [1-16](#)
- PKT-BUS, [5-882](#), [5-950](#)
- PKT-BUS Error Log Entries, [5-952](#)
- Power
  - controls, [2-2](#)
  - options available, [2-2](#)
  - removing, [2-11](#)
  - restoring, [2-12](#)
- preventative maintenance
  - procedures, [2-1](#)
- PRI endpoint problems
  - troubleshooting, [2-33](#)
- PSTN fallback, [5-756](#)

## R

- reboots, [1-29](#)
- recycle carrier command, [4-108](#)
- release commands
  - release access-endpoint, [4-109](#)
  - release adjunct-ip-link, [4-110](#)
  - release board, [4-112](#)
  - release cdr-link, [4-113](#)
  - release data-module, [4-114](#)
  - release mis, [4-115](#)
  - release modem-pool, [4-116](#)
  - release port, [4-117](#)
  - release pri-endpoint, [4-118](#)
  - release station, [4-119](#)
  - release tdm, [4-120](#)
  - release tone-clock, [4-121](#)
  - release trunk, [4-122](#)
- reseating/replacing circuit packs, [2-7](#)

- reset commands
  - reset board, [4-123](#)
  - reset packet-interface, [4-124](#)
  - reset switch-control, [4-125](#)
  - reset system, [4-125](#)
  - reset system 1
    - warm start, [1-32](#)
  - reset system 2
    - cold start, [1-32](#)
  - reset system 3
    - cold starts, [1-33](#)
  - reset system 4, [1-33](#)
  - reset system 5
    - DEFINITY extended reboot, [1-33](#)
- Reset system 4
  - DEFINITY reboot, [1-33](#)
- reset system 5, [1-33](#)
- resolving alarms, [2-5](#)
- restart commands
  - restartcause, [A-11](#)
  - start, [A-11](#)
  - vmrestart, [A-9](#)
- Restoring power, [2-12](#)
- resume hardware command, [4-128](#)
- ring ping, [2-13](#)

## S

- safety precautions, [xix](#)
- save translation command, [4-129](#)
- Second OSS Telephone Number, [4-24](#), [4-63](#)
- security
  - logins, [1-53](#)
  - measurements, [1-50](#)
  - passwords, [1-53](#)
- set commands
  - set options, [4-130](#)
  - set synchronization, [4-135](#)
  - set tdm, [4-136](#)
- setting
  - bit rate, [2-62](#)
  - line impedance, [2-62](#)
  - neon voltage, [2-13](#)
- shut-down commands
  - shutdown, [3-30](#)
  - vmshut, [A-9](#)
- shutting down NT on TN802, [5-773](#)
- signaling leads, DC power, [2-60](#)
- simplex mode tests, [2-29](#)
- status commands
  - status administered-connection, [4-138](#)
  - status asai/adjunct tcp/ip link, [4-140](#)
  - status attendant, [4-142](#)
  - status audits, [4-143](#)
  - status bri-port, [4-151](#)
  - status cdr-link, [4-158](#)
  - status cleared-alarm-notif, [4-159](#)

status commands, (continued)  
 status conference, [4-159](#)  
 status data-module, [4-195](#)  
 status hardware-group, [4-197](#)  
 status health, [4-199](#)  
 status isdn-testcall, [4-202](#)  
 status link, [4-204](#)  
 status packet-interface, [4-204](#)  
 status periodic-scheduled, [4-205](#)  
 status pri-endpoint, [4-206](#)  
 status processor-channel, [4-208](#)  
 status remote-access, [4-210](#)  
 status signaling group, [4-211](#)  
 status synchronization, [4-216](#)  
 status sys-link, [4-217](#)  
 status system, [4-219](#)  
 status trunk, [4-223](#)  
 status tsc-administered, [4-225](#)  
 status tti, [4-226](#)  
 status vs\_status, [A-10](#)  
 status vscstat, [A-10](#)  
 Super\_User, [1-51](#)  
 switch settings  
     TN464 circuit pack, [2-62](#)  
     TN760 tie trunk, [2-60](#)  
 synchronization, [1-17](#)  
 sysmon command, [A-7](#)  
 system features  
     troubleshooting system resources, [2-14](#)  
 system reboots, [1-33](#)  
 system resets  
     reasons for, [1-32](#)  
 System Tone Test Call, [2-21](#)

## T

T1 DS1 span, [2-39](#)  
 TDM bus  
     clocks, [5-1132](#)  
 TDM bus clock (TDM-CLK), [5-1132](#)  
 Temporary Signaling Connections, [5-1217](#)  
 Terminating Trunk Transmission (TT)  
     tests, [2-31](#)  
 test commands  
     test access-endpoint, [4-228](#)  
     test alarms, [4-230](#)  
     test analog-testcall, [4-235](#)  
     test board, [4-237](#)  
     test customer-alarm, [4-241](#)  
     test data-module, [4-243](#)  
     test ds1-loop, [4-244](#)  
     test eda-external-device-alm, [4-247](#)  
     test hardware-group, [4-251](#)  
     test inads-link, [4-256](#)  
     test isdnpri-testcall, [4-258](#)  
     test led, [4-260](#)  
     test modem-pool, [4-260](#)

test commands, (continued)  
     test packet-interface, [4-261](#)  
     test pkt, [4-262](#)  
     test port, [4-264](#)  
     test pri-endpoint, [4-266](#)  
     test pr-maintenance, [4-268](#)  
     test signaling-group, [4-269](#)  
     test station, [4-271](#)  
     test switch-control, [4-273](#)  
     test synchronization, [4-274](#)  
     test sys-link, [4-276](#)  
     test tdm, [4-278](#)  
     test tone-clock, [4-280](#)  
     test translation-store, [4-281](#)  
     test trunk, [4-283](#)  
     test tsc-administered, [4-285](#)  
 testing  
     background, [1-15](#)  
     demand, [1-16](#)  
     maintenance, [1-15](#)  
     system technician-demanded, [5-280](#), [5-784](#)  
 tests  
     analog tie trunk back-to-back, [2-24](#)  
     E&M mode, [2-24](#)  
     simplex mode, [2-29](#)  
     Terminating Trunk Transmission (TTT), [2-31](#)  
 tests and audits  
     #11 Digital Line Electronic Power Feed  
         Test, [5-519](#)  
     #1201 Digital Terminal Remote Loop Around  
         Test, [5-514](#)  
     #1209 Board Loopback Test, [5-593](#)  
     #1210 CSU Equipment Loopback  
         Test, [5-596](#)  
     #1211 CSU Repeater Loopback Test, [5-600](#)  
     #1212 CPE Loopback Jack Test, [5-604](#)  
     #1213 Far CSU Loopback Test, [5-608](#)  
     #1214 One-Way Span Test, [5-612](#)  
     #1215 Inject Single Bit Error Test, [5-616](#)  
     #1216 End Loopback/Span Test, [5-619](#)  
     #122 Cabinet Temperature Query Test  
         [Non-Variable Speed Fans], [5-367](#)  
     #1227 ICSU Status LEDs Test, [5-622](#)  
     #13 Voice and Control Channel Local Loop  
         Test, [5-520](#)  
     #135 Internal Loop Around Test, [5-563](#),  
         [5-1246](#)  
     #138 Loss of Signal Alarm Inquiry  
         Test, [5-567](#), [5-1250](#)  
     #139 Blue Alarm Inquiry Test, [5-573](#)  
     #139 Red Alarm Inquiry Test, [5-576](#)  
     #140 Red Alarm Inquiry Test, [5-575](#)  
     #140AY Loop Around Test, [5-125](#)  
     #141 Yellow Alarm Inquiry Test, [5-578](#), [5-579](#)  
     #142 Major Alarm Inquiry Test, [5-581](#),  
         [5-1270](#)  
     #143 Minor Alarm Inquiry Test, [5-583](#),  
         [5-1273](#)  
     #144 Slip Alarm Inquiry Test, [5-586](#), [5-1104](#)  
     #145 Misframe Alarm Inquiry Test, [5-589](#)

tests and audits, (continued)

- #146 Translation Update Test, [5-592](#), [5-781](#)
- #148 TDM Bus Clock Circuit Status Inquiry Test, [5-1137](#)
- #150 TDM Bus Clock PPM Inquiry Test, [5-1140](#)
- #151 TDM Bus Clock Parameter Update Test, [5-1141](#)
- #16 DIG-LINE Station Lamp Updates Test, [5-523](#)
- #161 Loop Around Test, [5-41](#), [5-319](#), [5-1093](#)
- #17 Station (Digital) Audits Test, [5-524](#)
- #205 Channel Administration Memory Array (CAMA) Test, [5-137](#)
- #206 Playback Speech Memory Array (PSMA) Test, [5-139](#)
- #208 Angel-Speech Processor (SP) Handshake Test, [5-121](#)
- #209 Announcement Checksum Test, [5-122](#)
- #211 Super Frame Match Inquiry Test, [5-130](#)
- #222 140AY Channel Sanity Inquiry Test, [5-143](#)
- #240 Expansion Interface Local Looparound, [5-237](#), [5-259](#), [5-295](#)
- #241 Expansion Interface 2-way Transmission Test, [5-210](#)
- #242 Expansion Interface Lightwave Transceiver Looparound, [5-226](#), [5-290](#), [5-786](#)
- #252 Circuit Pack Restart Test, [5-386](#), [5-387](#)
- #255 Signaling Link State Check Test, [5-176](#)
- #256 Service State Audit Test, [5-177](#)
- #257 Call State Audit Test, [5-179](#)
- #258 ISDN Test Call, [5-180](#)
- #270 Clear Error Counters, [5-167](#), [5-333](#), [5-1093](#)
- #314 DS1 CO Dial Tone Seizure Test, [5-535](#)
- #314 DS1CO Dial Tone Seizure Test, [5-415](#)
- #316 Expansion Interface Control Channel Test, [5-217](#), [5-218](#), [5-283](#)
- #35 Battery Feed Test, [5-34](#), [5-72](#)
- #36 Port Audit and Update Test, [5-413](#), [5-534](#)
- #36 Station Status and Translation Audits and Updates, [5-56](#)
- #36 Station Status and Translation Audits and Updates Test, [5-75](#)
- #36 Station Status and Translation Audits and Updates Test (#36), [5-36](#)
- #40 Tone Generator Transmission Test, [5-1206](#)
- #42 Tone Detection Verification Test, [5-397](#)
- #46 Clock Health Inquiry Test, [5-1029](#), [5-1202](#)
- #47 Loop Around and Conference Test, [5-78](#)
- #48 Station Present Test, [5-38](#), [5-58](#), [5-83](#)
- #50 NPE Connection Audit Test, [5-281](#), [5-559](#), [5-775](#), [5-1243](#)
- #52 Control Channel Loop Around Test, [5-10](#), [5-12](#), [5-560](#), [5-776](#), [5-1031](#)

tests and audits, (continued)

- #52 Control Channel Loop-Around Test, [5-241](#), [5-386](#)
  - #53 SAKI Sanity Test, [5-561](#), [5-777](#), [5-1032](#), [5-1245](#)
  - #595 LANBIC Receive Parity Error Counter Test, [5-304](#), [5-311](#), [5-388](#), [5-1084](#)
  - #596 Receive FIFO Overflow Error Counter Test, [5-389](#)
  - #597 Invalid LAPD Frame Error Counter Test, [5-390](#)
  - #598 Packet Interface Test, [5-391](#)
  - #599 Packet Gateway Switched Port Loop-Around Test, [5-984](#)
  - #6 NPE Crosstalk Test, [5-29](#), [5-405](#), [5-530](#)
  - #600 Congestion Query Test, [5-392](#)
  - #601 Link Status Test, [5-393](#), [5-991](#)
  - #610 Packet Gateway Port Local Loop-Around Test, [5-648](#), [5-649](#), [5-986](#)
  - #613 Level 1 State Inquiry Test, [5-652](#), [5-653](#), [5-671](#), [5-673](#), [5-989](#)
  - #618 BRI Port Local LAN Loop Around, [5-162](#), [5-321](#), [5-1095](#)
  - #619 BRI Port Local TDM Loop Around, [5-324](#), [5-1096](#)
  - #620 Electronic Power Feed Restoral, [5-326](#)
  - #621 Level 1 Status Inquiry, [5-164](#), [5-327](#), [5-1100](#)
  - #622 Electronic Power Feed Inquiry, [5-330](#)
  - #624 Layer 1 Transmission Error Counter Test, [5-165](#), [5-166](#), [5-331](#)
  - #625 Receive FIFO Overflow Error Counter Test, [5-332](#), [5-1098](#), [5-1099](#)
  - #626 Signaling Link Status Test, [5-157](#), [5-348](#)
  - #627 BRI Remote Loop Back, [5-351](#)
  - #628 BRI XID, [5-354](#)
  - #629 BRI Layer 3 Query, [5-356](#), [5-1103](#)
  - #630 BRI Set Audits, [5-359](#)
  - #637 Remote Layer 3 Query, [5-262](#), [5-671](#)
  - #643 Signaling Link Board Check, [5-186](#)
  - #7 Conference Circuit Test, [5-32](#), [5-51](#), [5-409](#), [5-532](#)
  - #844-848 Transmission Test, [5-440](#), [5-1180](#)
  - #885 Private Loop Around Tests, [5-964](#)
  - #886 Maintenance Loop Around Test, [5-967](#)
  - #887 Read and Clear Board Counters, [5-969](#)
  - #9 Digital Line NPE Crosstalk Test, [5-517](#)
  - #976 Session Status Query Test, [5-672](#), [5-987](#)
  - #985 System Link Status, [5-1074](#)
- tie trunk
- circuit pack option settings, [2-60](#)
  - Time Slot Test Call, [2-19](#)
- TN1655 circuit packs, [5-220](#)
- TN2182 circuit packs
- international settings, [5-1188](#)
  - time division multiplex (TDM) bus clocks, [5-1132](#)
- TN2793B, [5-88](#)

TN464 circuit pack  
  option settings, [2-62](#)

TN464 circuit packs  
  DS1 interface, [5-548](#), [5-752](#)  
  option jumpers, [5-1230](#)

TN722 circuit packs, [5-548](#)

TN760 circuit pack  
  option settings, [2-60](#)

TN767 circuit packs, [5-548](#)

TN768 circuit packs  
  international settings, [5-1188](#)  
  time division multiplex (TDM) bus  
  clocks, [5-1132](#)

TN780 circuit packs  
  international settings, [5-1188](#)  
  time division multiplex (TDM) bus  
  clocks, [5-1132](#)

TN790 Processor, [1-9](#)

TN793B, [5-88](#)

TN795 circuit pack  
  replacing, [2-8](#)

TN797, [5-88](#)

TN799 C-LAN, [5-378](#)

TN802B, [5-668](#), [5-782](#)

tone-clock circuit packs  
  international settings, [5-1188](#)  
  time division multiplex (TDM) bus  
  clocks, [5-1132](#)

tones  
  Italian, [5-1188](#)

Touch-Tone (DTMF) Receiver Test Call, [2-18](#)

transmission  
  errors, [1-17](#)  
  stream, [1-17](#)

troubleshooting  
  features, [2-14](#)  
  ISDN-PRI problems, [2-32](#)  
  ISDN-PRI test call problems, [2-35](#)  
  MMCH, [2-63](#)  
  PRI endpoint problems, [2-33](#)

Trunk Group Busy/Warning Indicators to  
  Attendant, [2-16](#)

Trunk Group form, [2-25](#)

Trunk Identification by Attendant, [2-16](#)

Trunk Test Call, [2-17](#)

trunks, DS1, [5-752](#)

TTT, see Terminating Trunk Transmission (TTT)

---

## U

universal DS1 (UDS1) circuit packs  
  option jumpers, [5-1230](#)

universal DS1 (UDS1) interface circuit  
  packs, [5-548](#), [5-752](#)

---

## V

version-related commands  
  fileversion, [3-17](#)  
  fwversion, [3-18](#)  
  swversion, [3-34](#)  
  versiondiff, [3-36](#)

VFM events, [6-14](#)

---

## W

warm start  
  reset system 1, [1-32](#)

Wideband Access Endpoint, [5-1336](#)

Windows NT logins, [1-48](#)

