



WL Wireless - Frequency Changes

Sony can modify select WL Series "B" models to 30/32 or 42/44

Contact Sony Service in Teaneck NJ 201-833-5300

Service Manager: Dominick Esolda

Refer to "UPG-324" / "Frequency change service program"

Model	Style	Modification
Transmitter		
WRT-8B	Bodypack	\$300.00
WRT-822B	Bodypack	\$300.00
WRT-807B	Handheld	\$300.00
WRT-847B	Handheld	\$300.00
Tuner / Receiver		
WRR-855B	Portable	\$400.00
WRR-861B	Portable	\$400.00
WRR-862B	Portable	\$400.00
MB-8N	Rackmount	TBD
Antenna		
WD-850A	Distributor	TBD

*Other existing WL-800 Series models (ones not included in the list above) can't be modified. This is because the unique parts needed are discontinued and no longer available.