# TRANSMISSION SERVICING - M/T

#### 1990 Nissan 240SX

1990 Manual Transmission Servicing

Axxess, Maxima, Pathfinder, Pickup, Pulsar NX, Sentra, Stanza, 240SX, 300ZX

#### IDENTIFICATION

#### MANUAL TRANSMISSION APPLICATIONS

| Model   | Transmission   |
|---|--|
| Axxess & Maxima Pathfinder & Pickup (3.0L) Pickup (2.4L) Pulsar NX Sentra | 5-Speed RS5F50A<br>5-Speed FS5R30A<br>5-Speed FS5W71C<br>5-Speed RS5F31A                                       |
| Sedan Coupe & 4WD Stanza  240SX 300ZX                                     | 4-Speed RN4F31A<br>5-Speed RS5F31A<br>5-Speed RS5F50A<br>5-Speed RS5F50V<br>5-Speed FS5W71C<br>5-Speed FS5R30A |

### **LUBRICATION SERVICE INTERVALS**

Inspect fluid level every 15,000 miles or 12 months. If under severe usage, change every 30,000 miles or 24 months.

# **CHECKING FLUID LEVEL**

## TRANSMISSION & TRANSAXLE

Fill plug is located on side of transmission or transaxle case. Lubricant level should be to bottom of fill hole. Add fluid if necessary.

# TRANSFER CASE

Fill plug is located on side of transfer case. Lubricant level should be to bottom of fill hole. Add fluid if necessary.

# **RECOMMENDED FLUID**

Use Hypoid SAE 75W-90 (API GL-4) gear oil for all transmissions, transaxles and transfer cases.

NOTE: Pathfinder and Pickup transfer cases come with Dexron-II ATF fluid from factory. It can be replaced with Hypoid SAE 75W-90 (API GL-4) gear oil. DO NOT mix Dexron-II and gear oil.

#### **FLUID CAPACITY TABLE**

TRANSMISSION REFILL CAPACITIES

| Transmission                    | Pts. (L)   |
|---------------------------------|--|
| Axxess, Maxima & Stanza         | 10 (4.7)   |
| 2WD                             | 5.1 (2.4)<br>7.6 (3.6)                           |
| 2WD                             | 4.3 (2.0)<br>8.5 (4.0)<br>8.2 (3.9)              |
| Sedan) Coupe & 4WD 240SX 300ZX  | 5.8 (2.7)<br>5.9 (2.8)<br>5.1 (2.4)<br>5.9 (2.8) |
| TRANSFER CASE REFILL CAPACITIES |  |
| Application                     | Pts. (L)   |
| Axxess                          | 3.8 (1.6)<br>4.6 (2.2)<br>2.3 (1.1)              |

# **LINKAGE ADJUST**

NOTE: All models have floor shift mechanisms without external linkage and require no adjustment.