

1/22/01

Horn/Driver Compatibility Matrix

	Horns																			
	HPT42	HPT64	HPT94	HP42S	HP64	HP64S	HPS64	HP64M	HP66	HP66S	HP85	HP85P	HP94	HP94S	HP99	HP99P	HP420	HP640	HP940	HP1240
DH1A				X	X	X			X	X			X	X			X	X	X	X
DH1A-16				X	X	X			X	X			X	X			X	X	X	X
DH1Amt							X				X				X	X				
DH1Amt-16							X				X				X	X				
DH2A				X	X	X			X	X			X	X			X	X	X	X
DH2A-16				X	X	X			X	X			X	X			X	X	X	X
DH2As1							X				X				X	X				
DH2As1-16							X				X				X	X				
DH2As2							X				X				X	X				
DH2As2-16							X				X				X	X				
DH2Amt*	X	X	X	**	**	**	*	X	**	**	*	X	**	**	*	*	**	**	**	**
DH2Amt-16*	X	X	X	**	**	**	*	X	**	**	*	X	**	**	*	*	**	**	**	**
DH2T*	X	X	X	**	**	**	*	X	**	**	*	X	**	**	*	*	**	**	**	**
DH2T-16*	X	X	X	**	**	**	*	X	**	**	*	X	**	**	*	*	**	**	**	**
DH2010A*	X	X	X	**	**	**	*	X	**	**	*	X	**	**	*	*	**	**	**	**
DH5-8							X				X				X	X				
DH5-16							X				X				X	X				
DH5-8/2				X	X	X			X	X			X	X			X	X	X	X
DH5-16/2				X	X	X			X	X			X	X			X	X	X	X
DH6-8							X				X				X	X				
DH6-16							X				X				X	X				
DH6-8/2				X	X	X			X	X			X	X			X	X	X	X
DH6-16/2				X	X	X			X	X			X	X			X	X	X	X
N/Dym1				X	X	X			X	X			X	X			X	X	X	X
N/Dym1-16				X	X	X			X	X			X	X			X	X	X	X
ND5-8							X				X				X	X				
ND5-16							X				X				X	X				
ND5-8/2				X	X	X			X	X			X	X			X	X	X	X
ND5-16/2				X	X	X			X	X			X	X			X	X	X	X

Drivers

*Note: The ADH3 adaptor (P/N 70108 A HV) is available to allow 1" throat opening, screw on driver to be attached to a 1.4" throat opening bolt-on horn. Drivers affected are the DH2Amt, DH2Amt-16, DH2T, DH2T-16, and DH2010A. Horns affected are the HPS64, HP85, and HP99P.

**Note: The ADH5 adaptor (P/N 73327 A HV) is available to allow 1" throat opening, screw on driver to be attached to a 2.0" throat opening bolt-on horn. Drivers affected are the DH2Amt, DH2Amt-16, DH2T, DH2T-16, and DH2010A. Horns affected are the HP64, HP64S, HP66, HP66S, HP94, HP94S, HP99, HP420, HP640, HP940, and HP1240.