## Service Bulletin

EVI AUDIO 600 Cecil Street Buchanan, MI 49107 Phone: 616.695.6831 Fax: 616.695.4743





July 8, 1999

SUBJECT: DL18MT, EVX180, EVX180A and EVX180B Cone Changes

Engineering has changed the cones used in the DL18MT and the EVX180B as part of our efforts for continuous improvements. With these changes, we have made these speakers even more reliable than they have been in the past. The recone kit numbers will remain the same and the new cones will be shipped in place of the old cone. The old cones can be used until you receive the new cones. The price will also remain the same.

DL18MT

RECONE KIT 81386XX

NEW CONE 74186 (Still has the pre-damped surround)

OLD CONE 73154 (Obsolete)

EVX180, EVX180A and EVX180B

RECONE KITS 82835XX, 83417XX, 83523XX,84590XX, 84591XX and

84592XX

NEW CONE 74189 (Obsolete)

OLD CONE 71442

We have addressed the problems some have experienced with the cone surround splitting with these changes. If you have any questions, please contact either myself or Janice Stanfield in Buchanan.

Sincerely,

Frank Spain

Frank Spain

National Service Manager