

This VTR has playback compatibility of consumer DV (both SP and LP recorded tapes), DVCPRO (25 Mbps) as well as DVCAM™. In addition, The DSR-2000 also has the ability to perform Double-Scan Playback, helping to restore both video and audio off track tape information. The DSR-2000 also includes an internal signal generator, a wider digital slow play range (-x1 to x1), excellent jog audio, built-in video control, RS-422A interface, and a built-in timecode generator. Analog interfaces (component, S-Video, composite video, and four balanced audio channels), SDI, SDTI (QSDI™) and AES/EBU interfaces are standard. Optional i.LINK®\* IEEE 1394 DV I/O interface board (DSBK-190) and an SDTI-CP interface board (DSBK-210) are also available.

SONY®

# Sony's DSR-2000 DVCAM Studio Editing Recorder with Double-Scan Playback Capability

DSR-2000 • Suggested List Price \$14,750.00 ▼

## Key Features

- DVCAM Digital Component Recording Format
- Playback Compatibility with All DV (25 Mbps) Formats
- Pre-Read Editing Capability
- DMC (Dynamic Motion Control)
- Functionally Designed Operating Panel
- Excellent Editing Performance

## Key Applications

- Server Ingest of all DV (25 mbps) formats
- On Air Playback
- Feed Recording
- Linear Editing

## Key Competitors and Pricing

N/A



For further information about the DSR-2000, please contact your Sony Account Manager or download a more detailed spec sheet from the Sony website.

[www.sony.com/professional](http://www.sony.com/professional)  
Business Solutions & Systems Company

©2003 Sony Electronics Inc. All rights reserved. Reproduction in whole or in part without written permission is prohibited. Features and specifications are subject to change without notice. All non-metric weights and measures are approximate. Sony, DVCAM, and QSDI are trademarks of Sony.

\*i.LINK is a trademark of Sony used only to designate that a product contains an IEEE1394 connection. The i.LINK connection may vary depending on the software applications, operating system and compatible i.LINK devices. All products with an i.LINK connection may not communicate with each other. Please refer to the documentation that comes with any device having an i.LINK connection for information on compatibility, operating conditions and proper connection. For information on any Sony device having an i.LINK connection, contact Sony at 1-800-686-7669.

Created 5/12/03

Sony Electronics Inc.  
1 Sony Drive  
Park Ridge, NJ 07656