

# PVM to LUMA Replacement Chart

| CRT Model | CRT List   | LCD Replacement | Description            | LCD List   | Notes  |
|-----------|------------|-----------------|------------------------|------------|--|
| PVM20L5/1 | \$3,980.00 | LMD230WS/2      | 23" 16:9 HD/SD Monitor | \$3,950.00 |  |
|           |            | LMD210S         | 21" 4:3 HD/SD Monitor  | \$3,700.00 |  |
| PVM20L2   | \$2,943.00 | LMD2020         | 20" 4:3 SD Monitor     | \$2,995.00 |  |
| PVM20L1   | \$1,334.00 | LMD2010         | 20" 4:3 SD Monitor     | \$1,465.00 | Analog Component/RGB Input is standard in LMD2010 and not in the PVM20L1 |
| PVM14L5/1 | \$2,295.00 | LMD171WS        | 17" 16:9 HD/SD Monitor | \$3,425.00 |  |
|           |            | LMD150S         | 15" 4:3 HD/SD Monitor  | \$2,900.00 |  |
| PVM14L2   | \$1,469.00 | LMD1420         | 14" 4:3 SD Monitor     | \$1,495.00 |  |
| PVM14L1   | \$697.00   | LMD1410         | 14" 4:3 SD Monitor     | \$770.00   | Analog Component/RGB Input is standard in LMD1410 and not in the PVM14L1 |
| PVM9L3    | \$1,512.00 | LMD9050         | 9" 4:3 HD/SD Monitor   | \$4,800.00 | LMD9050 comes with built in HDSDI. PVM9L3 w/SDI board is \$2,407         |
| BVMD9H1U  | \$4,660.00 |                 |                        |            | LMD9050 comes with bulit in HDSDI BVM cost with HDSDI Card is \$8,565.00 |
| BVMD9H5U  | \$5,195.00 |                 |                        |            | LMD9050 comes with built in HDSDI BVM cost with HDSDI Card is \$9,100.00 |
| PVM9L2    | \$1,100.00 | Not yet avail   |                        |            |  |
| PVM9L1    | \$885.00   | Not yet avail   |                        |            |  |

**Note: PVM96, PVM97, PVM136, PVM137 are discontinued and not being replaced with LCD**